

From: Official Information
Sent: Friday, 9 March 2018 4:54 p.m.
To: '██████████@fairfaxmedia.co.nz'
Subject: LGOIMA 18/029 response - wellheads material

Dear ██████████,

Thank you for your email, received on 24 January. You requested the following information, under the Local Government Official Information and Meetings Act 1987 (LGOIMA):

"- Can we please get copies of the report(s) / communication from the engineers who carried out the Christchurch well assessments, resulting in Canterbury Water Assessor removing the city's secure status. The report was delivered, according to Mayor Lianne Dalziel in yesterday's media briefing, on December 22. I understand they were City Care contractors.

- Can we please get copies of all correspondence relating to the city's drinking water (including the aforementioned report) on December 22, 2017 involving Mayor Lianne Dalziel, the mayor's office, CEO Karleen Edwards, any members of the communication team, John Mackie and city councillors. This would include any emails, documents, text messages and any other methods of communication.

- All correspondence involving the same individuals regarding or relating to the water status between December 22 and January 23.

- The Canterbury Water Assessor's correspondence about the engineer's well assessments and decision to remove the city's secure water status.

- When were city councillors advised of the results of the engineers' well assessments / the city's loss of secure water status? Please provide information in relation to that."

You subsequently expanded your request as follows:

"Can we please make a tiny amendment to the below LGOIMA/OIA, to extend the request in question three to include all correspondence up to and including the council meeting on January 25."

Refinement sought

On 2 February we asked that you refine your request, if possible, due to the extremely large amount of information involved, and the lack of due particularity inherent in parts of your request:

"Regarding point 3, I wonder if you are able to refine your request? As it stands this encompasses a very large amount of information, which will take quite some time to find and collate. For example, it would be helpful if you could specify a more particular topic (i.e. not only 'water status' or 'drinking water'), or limiting the individuals and groups included in the request. It would be very helpful for us to understand the particular information it is that you are seeking."

We did not receive a response from you regarding our refinement request.

Extension of timeframe

On 2 March, we extended the timeframe on our response to you by an additional 5 working days.

Release of information

We have decided to release information in response to the first, fourth and fifth points in your request. This includes:

- **Engineers' reports:**
 - o All nine reports on the 25 wellheads inspected by engineers from BECA, which were finalised in January 2018. We have released to you the final reports on ShareFile, as sent by the BECA to the Council (please advise if you are unable to access these and we will organise an alternative means of releasing the information). The draft reports were received by the Council on 14 December 2017.
 - o Correspondence between the engineers who carried out the assessments of the wellheads, and Council staff members.
- **CityCare report** dated 22 December, concerning the assessment of the below ground wellheads, and the works undertaken as part of the project to repair the wellheads.
- **Correspondence from the Canterbury Water Assessor** related to the wellheads assessments and the decision to remove Christchurch's secure water status, including the letter of 22 December, which constituted formal notification of this decision.
- An email sent by the Council Secretary to Elected Members to advise them of the Recess Committee Meeting of Tuesday 16 January, at which the Councillors present were first briefed about the loss of Christchurch's secure water status.

The Council has decided to withhold some information under section 7(2)(a) of the LGOIMA – to protect the privacy of natural persons. In the Council's view the reasons for withholding these details are not outweighed by public interest considerations in section 7(1) favouring their release.

We are currently finalising this information, and we will be releasing this to you on Monday.

Decision to refuse information under section 17(f) of the LGOIMA

After careful consideration, the Council has decided to refuse points two and three of your request under section 17(f) of the LGOIMA – the information requested cannot be made available without substantial collation or research. In all, the information you have requested under these points constitutes at least 400 items of correspondence, which would take a number of days for staff to collate and organise. This is an unreasonable amount of time.

As outlined to you in our email of 2 February, if you were able to identify more specifically the correspondence you are seeking, we would be happy to consider the release of these documents. In this instance, however, the request for 'all correspondence' is simply too broad.

Under the LGOIMA and the Council's policy for charging for official information (<https://ccc.govt.nz/the-council/plans-strategies-policies-and-bylaws/policies/council-organisational-policies/charging-for-official-information-policy>), the Council can impose a charge for the supply of official information. Please advise if you are willing to pay for the provision of this information. If this is the case, we will reconsider our decision.

Subsequent information

On 25 January, Council resolved to ask the CE to undertake an overarching independent external review of the situation that arose regarding the wellheads, to be reported back to Council. The review, along with its findings and recommendations, is intended to assist the Council to provide assurance for the future of

Christchurch's unchlorinated water supply. It is envisaged that the review will provide conclusions and recommendations including:

- An assessment of how the matter arose and was handled
- An assessment of existing practices, monitoring and assessment, and reporting
- Any recommendations for improvements in procedure, practice, levels of service, reporting or otherwise.

The draft Terms of Reference for the Below Ground Well Heads and Drinking Water Supply Status Review were considered and endorsed by Council on 8 February. You can find these on the Council's website (http://christchurch.infocouncil.biz/Open/2018/02/CNCL_20180208_ATT_2267_EXCLUDED.PDF).

You have the right to ask the Ombudsman to investigate and review our decision. Complaints can be sent by email to info@ombudsman.parliament.nz, by fax to (04) 471 2254, or by post to The Ombudsman, PO Box 10152, Wellington 6143.

Publication of responses to LGOIMA requests

Please note: our LGOIMA responses may be published on the Christchurch City Council website a month after they have been responded to, with requesters' personal details withheld. If you have any concerns about this please contact the Official Information team on officialinformation@ccc.govt.nz.

Yours sincerely,

Katie McFadden

Information Advisor
Office of the Chief Executive

Christchurch City Council
Civic Offices, 53 Hereford Street, Christchurch
PO Box 73016, Christchurch, 8154

Please consider the environment before printing this email

From: Official Information
Sent: Friday, 2 February 2018 11:36 a.m.
To: '██████████'@fairfaxmedia.co.nz'
Subject: RE: LGOIMA request from The Press

Hi ██████████

Thanks for your amendment – I have forwarded this on to staff. We will provide a response or update within 20 working days of the date we received your amendment.

Regarding point 3, I wonder if you are able to refine your request? As it stands this encompasses a very large amount of information, which will take quite some time to find and collate. For example, it would be helpful if you could specify a more particular topic (i.e. not only 'water status' or 'drinking water'), or limiting the individuals and groups included in the request. It would be very helpful for us to understand the particular information it is that you are seeking.

If you're unable to refine your request, we will consider what information we can reasonably supply. For example, we may need to omit supplying all administrative emails due to the time it would take to research and collate these.

Yours sincerely,

Katie McFadden

Information Advisor
Office of the Chief Executive

Christchurch City Council
Civic Offices, 53 Hereford Street, Christchurch
PO Box 73016, Christchurch, 8154

Please consider the environment before printing this email

From: ██████████ [mailto:██████████@stuff.co.nz]
Sent: Thursday, 1 February 2018 12:42 p.m.
To: Media Enquiries <MediaEnquiries@ccc.govt.nz>; Ritchie, Jocelyn <Jocelyn.Ritchie@ccc.govt.nz>
Subject: Fwd: LGOIMA request from The Press

Hi all,

Can we please make a tiny amendment to the below LGOIMA/OIA, to extend the request in question three to include all correspondence up to and including the council meeting on January 25.

Many thanks,

██████████

Hi Joss,

Request from news desk, as per below.

Please can you action these LGOIMAs / OIAs please:

- Can we please get copies of the report(s) / communication from the engineers who carried out the Christchurch well assessments, resulting in Canterbury Water Assessor removing the

city's secure status. The report was delivered, according to Mayor Lianne Dalziel in yesterday's media briefing, on December 22. I understand they were City Care contractors.

- Can we please get copies of all correspondence relating to the city's drinking water (including the aforementioned report) on December 22, 2017 involving Mayor Lianne Dalziel, the mayor's office, CEO Karleen Edwards, any members of the communication team, John Mackie and city councillors. This would include any emails, documents, text messages and any other methods of communication.

- All correspondence involving the same individuals regarding or relating to the water status between December 22 and January 23.

- The Canterbury Water Assessor's correspondence about the engineer's well assessments and decision to remove the city's secure water status.

- When were city councillors advised of the results of the engineers' well assessments / the city's loss of secure water status? Please provide information in relation to that.

Many thanks,

[REDACTED]
Senior reporter

[REDACTED]
Fairfax Media, 158 Gloucester Street, Christchurch, 8011, New Zealand

[REDACTED]

--
[REDACTED]
Senior reporter - environment and defence

[REDACTED]

stuff

 Neighbourly

 THE PRESS

The Press, 158 Gloucester Street, Christchurch, 8011, New Zealand

The information contained in this e-mail message and any accompanying files is or may be confidential. If you are not the intended recipient, any use, dissemination, reliance, forwarding, printing or copying of this e-mail or any attached files is unauthorised. This e-mail is subject to copyright. No part of it should be reproduced, adapted or communicated without the written consent of the copyright owner. If you have received this e-mail in error please advise the sender immediately by return e-mail or telephone and delete all copies. Fairfax Media Group does not guarantee the accuracy or completeness of any information contained in this e-mail or attached files. Internet communications are not secure, therefore Fairfax Media Group does not accept legal responsibility for the contents of this message or attached files.

From: Judy Williamson <[REDACTED]>
Sent: Wednesday, 20 December 2017 12:17 p.m.
To: Mackie, John; Muruges, Daniela
Cc: CPH Drinking Water Unit; Ramon Pink
Subject: forfiling_GEN_1_Concerns re Christchurch supplies

Hi John and Daniela

Ramon and I have had a discussion this morning and would ideally like to meet with you before we close for Christmas on Friday or early in the new year (week of 8-12th Jan).

Our main area of concern is the ongoing 'Provisionally' secure status that has been given to the Christchurch sources since the earthquakes in 2011, recently PDP's refusal to sign off security criteria two for several well heads and recent findings by BECA indicate that there are a number of wells that currently do not meet criteria 2. We are aware that the council has a comprehensive programme started to 'encase' and remediate several of the below ground chambers and that findings from the BECA reports for 25wells are planned to be addressed, but are concerned that the timeframe for when all Christchurch sources meet criteria 2 is still some time away.

Do you have any time slots available that we could meet to discuss further?

Regards

Judy

Judy Williamson
Drinking Water Assessor
Community & Public Health
PO Box 1475
Christchurch
[REDACTED]

Check out our web site: <http://www.cdhb.health.nz>

This email and attachments have been scanned for content and viruses and is believed to be clean This email or attachments may contain confidential or legally privileged information intended for the sole use of the addressee(s). Any use, redistribution, disclosure, or reproduction of this message, except as intended, is prohibited. If you received this email in error, please notify the sender and remove all copies of the message, including any attachments. Any views or opinions expressed in this email (unless otherwise stated) may not represent those of Canterbury District Health Board

From: Judy Williamson <[REDACTED]>
Sent: Friday, 22 December 2017 2:07 p.m.
To: Mackie, John; Muruges, Daniela
Cc: CPH Drinking Water Unit; Helen Graham; Ramon Pink; Alistair Humphrey; Cheryl Brunton
Subject: forfiling_CWS_1_CHR001+BRO012_Removal of Security Status
Attachments: 171222_CWS_1_CHR001+BRO012_RemovalOfSecurityStatus.pdf

Hi

Seemed sensible to just get this letter written after our meeting this morning.

I have not included Lyttelton as I know the bore is being worked on at present so would anticipate that it would be inspected with criteria 2 in mind before being put back into service.

Hope you have good breaks over Christmas.

Regards

Judy

Judy Williamson
Drinking Water Assessor
Community & Public Health
PO Box 1475
Christchurch
[REDACTED]

Check out our web site: <http://www.cdhb.health.nz>

This email and attachments have been scanned for content and viruses and is believed to be clean This email or attachments may contain confidential or legally privileged information intended for the sole use of the addressee(s). Any use, redistribution, disclosure, or reproduction of this message, except as intended, is prohibited. If you received this email in error, please notify the sender and remove all copies of the message, including any attachments. Any views or opinions expressed in this email (unless otherwise stated) may not represent those of Canterbury District Health Board

Canterbury

District Health Board

Te Poari Hauora o Waitaha

File: CWS_1_CHR001+BRO012

22nd December 2017

Head of 3 Waters and Waste
Christchurch City Council
PO Box 73014
CHRISTCHURCH 8154

Attention: John Mackie

Dear John

Removal of Provisional Security Status for Christchurch and Brooklands/Kainga sources (CHR001+BRO012)

Following the Christchurch earthquakes in 2011 the security status for Christchurch (CHR001) and Brooklands Kainga (BRO012) was changed from 'Full' security to 'Provisional'. This was in recognition that a number of bores were damaged but none of the transgressions recorded in the period following the earthquakes were associated with the individual bores or pump stations.

This provisional status has continued as the remediation/new bore work programme has been rolled out.

Security criteria 2 (bore head security) is required "*...to be judged by a person recognised as an expert in the field...*" (Section 4.5.2.2) when initially established and then reviewed at least every five years as part of the requirements for ongoing demonstration of secure bore water. As such, in accordance with this requirement the Drinking Water Assessor (DWA) has been provided each year with reports for approximately one fifth of the bores, confirming that criteria two is continuing to be met.

The reports from the bores inspected recently this year show that some bore heads do not meet the security criteria and therefore the security status for Christchurch and Brooklands Kainga is removed. This means that the supplies now are not able to demonstrate the protozoa requirements of section 5 of the Drinking Water Standards for New Zealand (DWSNZ) through demonstrating secure sources.

It is acknowledged that while in some instances the bore heads may have deteriorated, the assessment and acceptance of risk are the more likely drivers that have meant that

engineering experts are no longer willing to confirm the security of the bore head installations.

Christchurch City Council are also acknowledged for reacting swiftly as the findings from the Havelock North enquiry have emerged. This includes the programme for rehabilitation of below ground well heads and fast tracking of the new deep bores for Northwest Christchurch.

Yours sincerely



Judy Williamson
Drinking Water Assessor
SIDWAU
Community & Public Health
A division of Canterbury District Health Board



Dr Ramon Pink
Medical Officer of Health

From: Lisa Mace <[REDACTED]>
Sent: Thursday, 14 December 2017 9:54 a.m.
To: Muruges, Daniela
Cc: Mike Thorley; Paul Reed
Subject: Assistance with DWSNZ Wellhead Security Assessments - Draft Reports
Attachments: NZ1-14947565-Well Head Protection Assessments - Discussion about Most Recent Assessments.pdf

Hi Daniela,

I have just sent through the draft reports for each site through ShareFile. Please confirm that they have come through.

Note that these reports have not been formally reviewed and so there are likely to be changes (including to the recommendations) before we finalise them. Regardless, they will give you an idea of what the final product will look like. Comments are welcome. I haven't attached the bore logs at this stage.

Also attached is an agenda for our discussion on Tuesday. I have provided Judy with this agenda.

When I sent through the Dunbars report template I also sent through a list of additional information (copy and pasted below). This information would be useful if it exists in a form that is easy for you to send to us. If it doesn't, then don't worry.

- Water Safety Plan - I remember you saying that it is currently being updated. If the new version isn't in a state to be issued to us, can we please have a look at the previous version?
- Well Head Management Document - referred to in the previous
- Sump Pump Testing records – CityCare mentioned they were currently doing an overhaul of sump pumps and that there might be a list of those tested.
- List of bore pumps with backflow devices at the pump - this may not exist but I thought I would ask just in case
- List of bores that have had E. coli transgressions - the annual compliance reports may be a good source
- Can you confirm that SCADA receives on/off signals from all bore pumps?

Regards,

Lisa Mace

Process Engineer

Beca

Phone: [REDACTED] Fax: [REDACTED]

DDI: [REDACTED] Cell: [REDACTED]

www.beca.com



WINNER
CLIENT
CHOICE
AWARDS
2017
WINNER
beaton

A standout year!

Thank you to our clients for your recognition.

BECA

- Joint Best Professional Services Firm (revenue > \$200m)
- Joint Best Consulting Engineering Firm (revenue > \$200m)
- Market Leader: New Zealand



NOTICE: This email, if it relates to a specific contract, is sent on behalf of the Beca company which entered into the contract. Please contact the sender if you are unsure of the contracting Beca company or visit our web page <http://www.beca.com> for further information on the Beca Group. If this email relates to a specific contract, by responding you agree that, regardless of its terms, this email and the response by you will be a valid communication for the purposes of that contract, and may bind the parties accordingly. This e-mail together with any attachments is confidential, may be subject to legal privilege and may contain proprietary information, including information protected by copyright. If you are not the intended recipient, please do not copy, use or disclose this e-mail; please notify us immediately by return e-mail and then delete this e-mail.

Agenda

Well Head Protection Assessments - Discussion about Most Recent Assessments

To be held 19 December 2017 at 10am

at Christchurch City Council

Invitees:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Item	Action
1 Project Summary <ul style="list-style-type: none">ScopeResults so far including common issues	
2 Health, safety and Environment	
3 Discussion Points <ul style="list-style-type: none">Below ground installationsNot fenced, or fence at less than 5mNo record of grout sealsCheck valve said to be on the pump with no record of this or single check valve rather than dualDuty/standby sump pumpsNo air ventTime frames for remedial worksAny changes as a result of Havelock North Stage 2 Inquiry	

Citycare Water 

Below Ground Wellheads Benchmark

22/12/2017



1. Summary

Works carried out at Main Pumps Station Well 2 as a part of the repairing of below ground wellhead project are:

1. External grouting
2. Internal sealing and lining of the well
3. Sealing of glands and ducts
4. Cable relocation
5. Installation of a new sump pump
6. Floor regrading and sump deepening
7. Installation of a secure, accessible well cover
8. Construction of a 2m apron around well cover

The work undertaken on each component is considered to be the benchmark level required to minimise or eliminate water contamination from ground water and rainfall (or both).

Following are pictures of the finished works corresponding to the above list at Well 2 Main Pumps:

1.External Grouting



2/3.Internal Sealing and Lining of the Well



4.Cable Relocation



5/6. Floor Regrading (in progress)



7. Installation of Secure, Accessible Well cover



9.Construction of a 2m Apron around Well



2. External Grouting

Ideal Well Picture (Main pumps Well 2)



3. Cable Relocation

Ideal Picture (Main Pumps Well 2)



5. Install Secure Accessible Well Cover

Ideal picture (Main Pumps Well 2)



6. Construction of 2m Apron around well cover

Ideal picture (Main Pumps Well 2)



Timelines

The following high priority works will be completed by June 2018 – as these sites were assessed as having the highest potential risk of water contamination. There are 25 wells in this group. Of this, 16 wells require all eight (8) components of work to be undertaken. The remainder (nine) require lesser work in particular cable relocation.

In total 102 wells have been assessed, with the remainder (77) considered to be lower risk but still requiring remedial works. It is anticipated that this work will be completed by December 2018.

The table below identifies 25 wells, some with two work streams

Part 1: Cable Relocation where non External Grouting Require			
Part 2: All other works			
Site	Well Number	Estimated Start Date	Estimated Finish Date
Main Pumps Station	Well 1	26/10/2017	13/11/2017
	Well 2	12/09/2017	3/10/2017
	Well 4	7/11/2017	23/11/2017
	Well 5	15/01/2018	26/01/2018
	Well 6	29/01/2018	2/02/2018
Grampian	Well 5	5/02/2018	23/02/2018
Farrington (Part 1)	Well 4	17/11/2017	27/11/2017
Grassmere (Part 1)	Well 3	4/12/2018	15/12/2017
Farrington (Part 2)	Well 4	26/02/2018	9/03/2018
Palantine	Well 1	12/03/2018	30/03/2018
Thompsons (Part 1)	Well 2	15/01/2018	24/01/2018
Sydenham (Part 1)	Well 5	26/01/2018	2/02/2018
Sydenham (Part 2)	Well 5	2/04/2018	6/04/2018
	Well 6	20/04/2018	20/04/2018
Thompsons (Part 2)	Well 2	23/04/2018	27/04/2018
Burnside (Part 1)	Well 5	5/02/2018	14/02/2018
Belfast (Part 1)	Well 1	15/02/2018	22/02/2018
	Well 2	26/02/2018	6/03/2018
Grassmere (Part 1)	Well 2	12/03/2018	16/03/2018
Mays (Part 1)	Well 2	19/03/2018	27/03/2018
	Well 4	26/03/2018	3/04/2018
Redwood (Part 1)	Well 1	5/04/2018	12/04/2018
Burnside (Part 2)	Well 5	30/04/2018	9/05/2018
Belfast (Part 2)	Well 1	10/05/2018	18/05/2018
	Well 2	21/05/2018	29/05/2018
Blighs	Well 1	30/05/2018	13/06/2018
Grassmere (Part 2)	Well 1	14/06/2018	22/06/2018
	Well 2	25/06/2018	29/06/2018
	Well 3	2/07/2018	7/07/2018
Thorrington (Part 1)	Well 1	16/04/2018	24/04/2018
Bexley (Part 1)	Well 1	26/04/2018	2/05/2018
	Well 2	7/05/2018	15/05/2018
Brooklands (Part 1)	Well 1	16/05/2018	22/05/2018
Montreal (Part 1)	Well 1	23/05/2018	31/05/2018
	Well 2	4/06/2018	12/06/2018
St John (Part 1)	Well 1	14/06/2018	20/06/2018
Trafalgar (Part 1)	Well 1	21/06/2018	28/06/2018
	Well 2	29/06/2018	5/07/2018

From: Mike Thorley <[REDACTED]>
Sent: Friday, 19 January 2018 2:34 p.m.
To: Muruges, Daniela; Mace, Lisa (BECA)
Cc: Meek, Rob; O'Brien, Bridget; Davison, Keith
Subject: RE: Wellhead Inspections

Hi Daniela,

The well chamber now appears clear of rubbish and debris, and the cable entry points into the well head appear to be sealed now. These were our primary concerns about the continued operation of the well at this location.

Other issues relating to the below ground chamber will likely need to be addressed via the WSP process as per the recommendations in the Havelock North enquiry.

Please contact me if you have any further questions or comments.

Kind regards,
Mike

From: Muruges, Daniela [mailto:[REDACTED]]
Sent: Friday, 19 January 2018 11:48 a.m.
To: Mike Thorley <[REDACTED]>; Lisa Mace <[REDACTED]>
Cc: Meek, Rob <[REDACTED]>; O'Brien, Bridget <[REDACTED]>; Davison, Keith <[REDACTED]>
Subject: FW: Wellhead Inspections

Hi Mike and Lisa,
Attached are 2 photos of Denton Well 3. Can you please review them and advise if you are happy to close out the concerns you raised in your email from 9 November?

Regards,
Daniela

From: Wardman, Graham
Sent: Thursday, 18 January 2018 1:56 p.m.
To: Muruges, Daniela <[REDACTED]>
Subject: FW: Wellhead Inspections

Hope this is ok for today for Denton Well 3 ?

Graham Wardman

Reticulation Maintenance Contracts Supervisor (Pumps)
City Water & Waste

DDI [REDACTED]

Fax [REDACTED]

Mobile [REDACTED]

Email [REDACTED]

Web www.ccc.govt.nz

Christchurch City Council
Civic Offices, 53 Hereford Street, Christchurch
PO Box 73014, Christchurch, 8154



Please consider the environment before printing this email

From: Andrew Trinnaman [mailto:[REDACTED]]
Sent: Thursday, 18 January 2018 1:24 p.m.
To: Wardman, Graham <[REDACTED]>
Cc: Huddleston, Kevin (CityCare) <[REDACTED]>; Skevington, Tony (CityCare) <[REDACTED]>; Barron, Chris (CityCare) <[REDACTED]>
Subject: Re: Wellhead Inspections

Hey Graham,

See attached photo of Denton well3 today

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: "Wardman, Graham" <[REDACTED]>
Date: 18/01/18 1:15 PM (GMT+12:00)

To: Andrew Trinnaman <[REDACTED]>
Subject: FW: Wellhead Inspections

Graham Wardman

Reticulation Maintenance Contracts Supervisor (Pumps)
City Water & Waste

DDI [REDACTED]

Fax [REDACTED]

Mobile [REDACTED]

Email [REDACTED]

Web www.ccc.govt.nz

Christchurch City Council
Civic Offices, 53 Hereford Street, Christchurch
PO Box 73014, Christchurch, 8154



Please consider the environment before printing this email

From: Wardman, Graham
Sent: Thursday, 18 January 2018 1:05 p.m.
To: Huddleston, Kevin (CityCare) <[REDACTED]>
Subject: FW: Wellhead Inspections

Hi Kev

These are the photo's I already have with Chris's coments below.

Daniela would just like a few photo's from today and making sure the sump pump is working.

Thanks for your help AGAIN !!!

Well-deserved holiday next week.

Cheers

Graham

Graham Wardman

Reticulation Maintenance Contracts Supervisor (Pumps)
City Water & Waste

DDI [REDACTED]

Fax [REDACTED]

Mobile [REDACTED]

Email [REDACTED]

Web www.ccc.govt.nz

Christchurch City Council
Civic Offices, 53 Hereford Street, Christchurch
PO Box 73014, Christchurch, 8154



Please consider the environment before printing this email

From: Wardman, Graham
Sent: Thursday, 18 January 2018 12:54 p.m.
To: Muruges, Daniela <[REDACTED]>
Subject: FW: Wellhead Inspections

FYI

Graham Wardman

Reticulation Maintenance Contracts Supervisor (Pumps)
City Water & Waste

DDI [REDACTED]

Fax [REDACTED]
Mobile [REDACTED]
Email [REDACTED]
Web www.ccc.govt.nz

Christchurch City Council
Civic Offices, 53 Hereford Street, Christchurch
PO Box 73014, Christchurch, 8154



Please consider the environment before printing this email

From: Chris Barron [mailto:[REDACTED]]
Sent: Friday, 10 November 2017 4:29 p.m.
To: Wardman, Graham <[REDACTED]>
Subject: RE: Wellhead Inspections

Hi Graham,

Update on well head repairs.

Denton Well 1 The cable glands were checked and are not leaking.

Denton Well 3 The rubbish has been removed and cable entries have been sealed.

Denton Well 5 The cable glands were checked and are not leaking.

Dunbars Well 1 The leaking cable gland was tightened to stop the leak.

Dunbars Well 3 The cable entries are sealed with RTV.

Dunbars Well 4 New sump pump was installed yesterday cable glands are sealed and are not leaking

Regards
Chris

Chris Barron
Manager Pumps and Storage
[REDACTED]
Shuttle Drive, Bromley, Christchurch
PO Box 7669 Sydenham Christchurch 8240
citycarewater.co.nz



This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system.

From: Wardman, Graham [mailto:[REDACTED]]
Sent: Friday, 10 November 2017 12:30 p.m.
To: Chris Barron
Subject: Wellhead Inspections
Importance: High

Hi Chris
See comments below, please can you action the Dunbars and Denton issues immediately.

Cheers
Graham

Graham Wardman
Reticulation Maintenance Contracts Supervisor (Pumps)
City Water & Waste

DDI [REDACTED]
Fax [REDACTED]
Mobile [REDACTED]
Email [REDACTED]
Web www.ccc.govt.nz

Christchurch City Council
Civic Offices, 53 Hereford Street, Christchurch
PO Box 73014, Christchurch, 8154



Please consider the environment before printing this email

From: Muruges, Daniela

Sent: Friday, 10 November 2017 12:09 p.m.

To: Collins, Les <[REDACTED]>; Wardman, Graham <[REDACTED]>; Meek, Rob <[REDACTED]>

Cc: Johnson, Mark <[REDACTED]>

Subject: FW: Wellhead Inspections

Importance: High

Hi Les / Graham / Rob,

Beca carried out some wellhead inspections this week (required under the DWSNZ every 5 years). They identified some issues at Dunbars Well 4 and Denton Well 3 that they feel need to be rectified immediately, please see below.

There are also wells where the sump pumps weren't working and some wells where cable gland seals were non-existent.

Can the issues at Dunbars Well 4 and Denton Well 3 please be addressed immediately, the sump pumps at the wells listed below be checked and the cable glands be checked.

It would be great to check where these wells are on the City Care wellhead improvement priority list.

Many thanks,

Daniela

From: Lisa Mace [mailto:[REDACTED]]

Sent: Thursday, 9 November 2017 4:01 p.m.

To: Muruges, Daniela <[REDACTED]>

Cc: Paul Reed <[REDACTED]>; Andrew Watson <[REDACTED]>; Mike Thorley <[REDACTED]>

Subject: Wellhead Inspections

Hi Daniela,

Mike and I had a successful few days with Paul joining for some of the sites. We made it around all the locations including Wainui.

Unfortunately, we could not inspect Brooklands Well 2 due to safety concerns. A new chamber segment has recently been added making the total height about 3m without railing (see the first photo). I understand that CityCare have already planned to install fall protection railing but I will leave that with you to follow up.

Also, there are two wells which have immediate public health risks. We recommended taking these out of service and isolating until the issues can be rectified:

- Dunbars Well 4 – significant amounts of water in the chamber, the sump pump was not running, and water was leaking out of the cable gland. This well is in a driveway/footpath and has a level entry unsealed chamber lid (see photos);
- Denton Well 3 – garbage and vandalism in the chamber and its vicinity, open cable entry point (no cable glands), no sump pump (although dry), a bellow that looked to be sucked inwards indicating that the valve on the pump might need to be checked (see photos). If this chamber was inundated with water it would directly enter the well head.

Also we found a few wells with water sitting in them and no sump pumps. We recommend that you carry out an urgent review of all sump pumps and clear water out of the wet well chambers. We noticed water in:

- Tara
- Sockburn Well 3
- Picton Well 1
- Picton Well 3
- Kainga

And we noticed the following wells without cable gland seals:

- Wainui
- Denton Well 1
- Denton Well 3
- Denton Well 5
- Dunbars Well 1
- Dunbars Well 3
- Dunbars Well 4

We will include this information in our reports but I thought it would be best for you to have it earlier.

Regards,

Lisa Mace

Process Engineer

Beca

www.eca.com



2017 WINNER
CLIENT CHOICE AWARDS
2017
beaton

A standout year!

Thank you to our clients for your recognition.

- Joint Best Professional Services Firm (revenue > \$200m)
- Joint Best Consulting Engineering Firm (revenue > \$200m)
- Market Leader: New Zealand

BECA



NOTICE: This email, if it relates to a specific contract, is sent on behalf of the Beca company which entered into the contract. Please contact the sender if you are

From: Daly, Jo
Sent: Monday, 15 January 2018 5:03 p.m.
To: Councillors and Mayor; Edwards, Karleen; Adamson, David
Cc: Bruorton, Adair
Subject: Recess Committee Meeting - Tuesday 16 January 3.30pm - Availability

Importance: High

Good afternoon

To advise that a Council Recess Committee meeting has been called for tomorrow, Tuesday 16 January 3.30pm in the Council Chamber, Civic Offices.

The purpose of this meeting is to receive a public excluded report on **below ground well heads**. The report will be considered in public excluded session.

Members are asked to confirm their availability to attend this Recess Committee meeting to me **by 9am tomorrow**, Tuesday 16 January. An appointment will shortly be sent to all members.

The agenda for this meeting will be distributed to all Councillors and available on the Hub tomorrow morning.

Kind regards

Jo

Jo Daly
Council Secretary and Electoral Officer
Christchurch City Council

DDI: [REDACTED]
Mobile: [REDACTED]
Email: [REDACTED]
Web: www.ccc.govt.nz

From: Lisa Mace <[REDACTED]>
Sent: Thursday, 21 December 2017 11:24 a.m.
To: Murugesh, Daniela; 'Judy Williamson'; Mike Thorley; Paul Reed
Subject: Well Head Protection Assessments - Discussion Minutes
Attachments: NZ1-14974786-Well Head Protection Assessments - Discussion about Recent Assessments - Minutes.pdf

Hi all,

Attached is minutes from our meeting of Tuesday. Daniela, can you please distribute to Kenton, Rob and Graham?

Happy holidays all!

Regards,
Lisa Mace
Process Engineer
Beca

[REDACTED]
[REDACTED]

www.beca.com



NOTICE: This email, if it relates to a specific contract, is sent on behalf of the Beca company which entered into the contract. Please contact the sender if you are unsure of the contracting Beca company or visit our web page <http://www.beca.com> for further information on the Beca Group. If this email relates to a specific contract, by responding you agree that, regardless of its terms, this email and the response by you will be a valid communication for the purposes of that contract, and may bind the parties accordingly. This e-mail together with any attachments is confidential, may be subject to legal privilege and may contain proprietary information, including information protected by copyright. If you are not the intended recipient, please do not copy, use or disclose this e-mail; please notify us immediately by return e-mail and then delete this e-mail.

Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Muruges	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Dunbars Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

22 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Template for Client Review	22 November 2017
B	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
C	Lisa Mace / Mike Thorley	Final version	19 January 2018
D	Lisa Mace / Mike Thorley	Incorporating final changes	22 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		22 January 2018
Reviewed by	Andrew Watson		22 January 2018
Approved by	Paul Reed		22 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Hydrogeological Setting	3
4	Well Inspections	3
5	Status / Compliance with DWSNZ Criterion 2	3
6	Recommendations	3
7	Conclusion	6

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the wells supplying Dunbars Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as "secure", a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used in this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Dunbars Pumping Station (West Pressure Zone)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Original bore logs (Wells 1, 2, 3 and 5) as included in Appendix C
- Bore logs from ECan’s website (Well 4) as included in Appendix C - <https://www.ecan.govt.nz/gis-mapping/>
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Dunbars Pumping Station is supplied by five wells; Dunbars Wells 1 – 5. Each well feeds into a combined suction tank which then goes to the Pumping Station pump set. Dunbars Pumping Station and Wells are located near the corner of Halswell Road and Dunbars Road. The station supplies part of the West Pressure Zone. Table 2-1 summarises key information about the five wells.

Table 2-1: Dunbars Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 1	M36/4053	48.6 – 53.6	2
Well 2	M36/4052	48.3 – 54.3	2
Well 3	M36/4333	46.57 – 52.57	2

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 4	M36/3060	45.9 – 51.9	2
Well 5	M36/8019	106 - 110	4

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from both alpine river and rainfall to land surface recharge. The wells at Dunbars Pumping Station are screened within moderately-deep (Aquifer 2 – Linwood Gravel Aquifer) and deep (Aquifer 4 – Wainoni Gravel Aquifer) leaky (semi)-confined aquifers within the Christchurch Artesian Aquifer System.

4 Well Inspections

An inspections of each well was carried out on 8 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Matthew Thomas (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Dunbars Wells 1 – 5 do not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 2 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 2: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 1	<ul style="list-style-type: none"> ■ Locate source of leak and seal. The source is potentially the sample tap. ■ Seal chamber floor to prevent inundation of 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled 		

	First Priority	Second Priority	Third Priority	Ongoing
	<p>chamber from groundwater and install a sump pump with level sensor and alarms</p> <ul style="list-style-type: none"> Seal cable entry points 	<p>outside the chamber when samples are collected</p> <ul style="list-style-type: none"> Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. 		
Well 2	<ul style="list-style-type: none"> Seal the hole in the top of the chamber Seal chamber floor to prevent inundation and include a sump Install a sump pump (with a level sensor that alarms to an operator) 	<ul style="list-style-type: none"> Modify the sample tap connection point to prevent the collection of debris. This may be either a cap or the installation of a permanent sample tap connection device. The sample tap should allow collection outside of the chamber to avoid spilling water in the chamber. Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. 	<ul style="list-style-type: none"> Mitigation works to prevent inundation and contamination risk from adjacent drain 	
Well 3	<ul style="list-style-type: none"> Seal cabling Seal the chamber floor to prevent water inundation and either install a sump pump, or install drainage holes at the base of the chamber. Ensure that the drainage holes have vermin protection, probably in the form of mesh. 	<ul style="list-style-type: none"> Modify the sample tap connection point to prevent the collection of debris. This may be either a cap or the installation of a permanent sample tap connection device. The sample tap should allow collection outside of the chamber to avoid spilling water in the chamber. 	<ul style="list-style-type: none"> Mitigation works to prevent inundation and contamination risk from adjacent drain 	
Well 4	<ul style="list-style-type: none"> Install a level sensor and a chamber level alarm Seal the chamber lids 	<ul style="list-style-type: none"> Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled 		<ul style="list-style-type: none"> Regular monitoring of this well should be carried out because of the high risk to public health. We recommend weekly and during

	First Priority	Second Priority	Third Priority	Ongoing
	<ul style="list-style-type: none"> ■ Seal cables, pipework and casing if not already sealed (could not assess due to water in chamber) ■ Replace lid and form an apron with a fall away from the lid 	<p>outside the chamber when samples are collected</p> <ul style="list-style-type: none"> ■ Consider decommissioning this well and replacing with an above ground well in a new location ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. 		<p>heavy rain inspections to check that there is no water in the chamber and that there are no signs of it leakage. The sump pump should also be tested regularly.</p>
Well 5	<ul style="list-style-type: none"> ■ Seal cabling at chamber side wall ■ Ensure that casing-chamber connection is sealed ■ Check casing integrity, treat rust and seal chamber/floor ■ Install a sump pump (with a level sensor that alarms to an operator) 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Form an apron with a fall away from the chamber ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. 		
All wells	<ul style="list-style-type: none"> ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the 	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed. 	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

	First Priority	Second Priority	Third Priority	Ongoing
		<p>next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well.</p> <ul style="list-style-type: none"> ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. 		

7 Conclusion

The information reviewed and the inspections carried out indicate that none of the Dunbars wells meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Dunbars
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2017
2. Modifications since Previous Assessment	
No known modifications	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	Dunbars Wells 1 – 4 draw from Aquifer 2 (leaky-confined) Dunbars Well 5 draws from Aquifer 4 (leaky-confined)
Surface Water Ways, Drains, etc	Dunbars Drain
4. Photo Record and Comments	
Photo	Comment

	<p>Suction tank which all Dunbars wells feed</p>				
	<p>Reticulation pumps within the pump station</p>				
<p>5. Risks from Surrounding Environment</p>					
<p>a) Within the site:</p>					
<p>Diesel/Chemical Storage</p>	<table border="1"> <tr> <td data-bbox="783 1359 874 1458">None</td> <td data-bbox="879 1359 1107 1429"> <input type="checkbox"/> Underground <input type="checkbox"/> Aboveground </td> <td data-bbox="1112 1359 1187 1458">Fuel lines</td> <td data-bbox="1192 1359 1444 1429"> <input type="checkbox"/> Underground <input type="checkbox"/> Aboveground </td> </tr> </table>	None	<input type="checkbox"/> Underground <input type="checkbox"/> Aboveground	Fuel lines	<input type="checkbox"/> Underground <input type="checkbox"/> Aboveground
None	<input type="checkbox"/> Underground <input type="checkbox"/> Aboveground	Fuel lines	<input type="checkbox"/> Underground <input type="checkbox"/> Aboveground		
<p>Access by Animals</p>	<p>Not a fenced site but a locked and alarmed building</p>				
<p>Protection from vandalism, signs of vandalism</p>	<p>As above, no signs of vandalism</p>				
<p>Other Activities</p>	<p>N/A</p>				
<p>b) Immediate Neighbouring Land Use:</p>					
<p>Current Neighbouring Land Use</p>	<p>Residential</p>				
<p>Significant Changes Since Previous Inspection</p>	<p>None identified</p>				
<p>Zoning of Neighbouring Land</p>	<p>Residential Suburban Zone</p>				
<p>c) Wider Environment:</p>					

Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	Gas station located across the street. Risk from potential spills of petrol or diesel fuel from the gas station could enter underground pipework and potentially the wells. One active stormwater discharge to land consent within 400m Sewer nearby
Risk of flood inundation	Pump station is below ground but within a building
Potential sources of young water	No sources specific to the pumping station identified. See well assessments
General land use in catchment (LLUR)	As below
Contaminated sites (HAIL status)	None identified at the addresses of the wells Gas station across the road
Status and condition of surrounding wells (within 400 m radius)	Multiple wells
Landfill	None identified
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	
Immediate Action Required	Refer well assessments
Action Required within 12 Months	Refer well assessments
Future	Refer well assessments
Ongoing	Refer well assessments

Well Head Protection Assessment – Individual Well Heads

Dunbars Well 1

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Dunbars Well 1
ECan Well No.	M36/4053
Aquifer No.	2
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	48.6 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	48.6 – 53.6
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	28 December 1989
Control System/Alarms	Well pump on/off, lid opening alarm

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Well chamber is located adjacent to the road with a gas station across the street.
	Chamber is located in a slight low point. Ponding may occur around the exterior.



Water present on top of casing to pipe flange. The source of the water is unknown. It may be the pipe or it may be the sample tap.



Pipe sealed at chamber connection.



Chamber floor is gravel and so is not sealed from below. Casing is not sealed to chamber.




Signs of groundwater entering the chamber through the floor from outside.



Flow meter chamber near Dunbars Well 1 with water in the base and no sump pump

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Power cable joint not sealed
	Pipework	Sealed with sidewall of chamber. Some leaking on top of flange in chamber which may be a result of a pipework leak or from the sample tap.
	Well casing	No concrete seal, minor pitting
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No Some of the site is below the 50 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Good condition
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No, slight low point
100mm step above ground level?		No

Signs of ponding?	Not at time of inspection	
Access by animals	No fence to prevent access, in a residential area where cats and dogs would be common but livestock would be less likely	
Protection from vandalism, signs of vandalism	Lid access alarm installed. Lid locked with padlock	
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that a single check valve provides a low degree of protection. The well pump may also have a check valve but this is not known.	
If not, has this been agreed with the DWA?	N/A	
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached	
Bore casing type and condition (see NZS:4411 2.4.2)	Steel with minor pitting	
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown	
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown	
Does the well comply with NZS:4411?	No	
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No	
If no, what non-compliances require agreement with the DWA?	Non-Compliance	Agreed with DWA? (see Appendix D)
	Below ground installation	Agreed ok
	No 5m fenced	Agreed ok
	Casing not grout sealed	To be agreed
	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required

	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	3m from edge of busy road. There is the potential for a spill of gas or other liquid to enter the well. Gas station across the street. Sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	Base of chamber was damp at the time of inspection and there was some water on top of the casing to pipe flange	
Is there a sump pump?	No pump or sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Locate source of leak and seal. The source is potentially the sample tap. ■ Seal chamber floor to prevent inundation of chamber from groundwater and install a sump pump with level sensor and alarms ■ Seal cable entry points ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected 	


	<ul style="list-style-type: none"> ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced and the local contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Dunbars Well 2

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Dunbars Well 2
ECan Well No.	M36/3052
Aquifer No.	2
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	48.3 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	48.3 – 54.3
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	16 May 1990
Control System/Alarms	Well pump on/off, lid opening alarm

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Well chamber is 1.1m above ground. Located on the side of the road.
	Well is adjacent to sidewalk and road. A creek is on the other side of the well.

	<p>Pipework in reasonable condition with some rust.</p> <p>Bottom of chamber is gravel.</p> <p>Sample tap not installed but connection point is present.</p>
	<p>Cables appear to be sealed</p>
	<p>A hole in the top of the chamber was seen. This is a possible source of water, or vermin, ingress</p>
<p>5. Diagram with Well Measurements</p>	



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Sealed
	Pipework	Sealed
	Well casing	No concrete seal
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Good
Raw Water sample port?		Connection point is chamber, sample tap attachment must be brought to site
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		No
Signs of ponding?		No

Access by animals	No fence around well, in a residential area where cats and dogs would be common but livestock would be less likely	
Protection from vandalism, signs of vandalism	Lid access alarm installed. Padlock on lid	
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that a single check valve provides a low degree of protection. The well pump may also have a check valve but this is not known.	
If not, has this been agreed with the DWA?	N/A	
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached	
Bore casing type and condition (see NZS:4411 2.4.2)	Steel, good condition	
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown	
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown	
Does the well comply with NZS:4411?	No	
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No	
If no, what non-compliances require agreement with the DWA?	Non-Compliance	
	Agreed with DWA? (see Appendix D)	
	Below ground installation	Agreed ok
	No 5m fenced	Agreed ok
	Casing not grout sealed	To be agreed
	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required
No air vent	Air vent required	

c) Contamination Sources:	
Does the WSP address contaminant sources and contaminant migration pathways?	Not received
Any localised well specific sources of contamination?	Adjacent sidewalk and road Sewers in close proximity.
d) Below Ground Chambers:	
Water level of chamber	None at time of visit
Is there a sump pump?	No pump or sump
Are there duty/standby sump pumps?	No
Sump pump testing, include date a method	N/A
Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the bore head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal the hole in the top of the chamber ■ Seal chamber floor to prevent inundation and include a sump ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Modify the sample tap connection point to prevent the collection of debris. This may be either a cap or the installation of a permanent sample tap connection device. The sample tap should allow collection outside of the chamber to avoid spilling water in the chamber. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA.

	<ul style="list-style-type: none"> ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced and the local contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
Third Priority	<ul style="list-style-type: none"> ■ Mitigation works to prevent inundation and contamination risk from adjacent drain ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device


Dunbars Well 3

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Dunbars Well 3
ECan Well No.	M36/4333
Aquifer No.	2
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Above
Casing Depth (mbgl)	46.57 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	46.57 – 52.57
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	1 October 1990
Control System/Alarms	Well pump on/off, lid opening alarm

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Chamber sits on ground (not a below ground installation)
	<p>Pipework sealed with the chamber sidewalls. Sample connection point on top of pipework. A sample tap is brought to site for sampling.</p> <p>Gravel in bottom of chamber which allows water to come up through the ground and into the chamber.</p>

	<p>Adjacent creek</p>
	<p>Adjacent road</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

<p>a) Water Ingress:</p>		
	<p>Cabling</p>	<p>Not sealed</p>

Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Pipework	Sealed
	Well casing	No concrete seal
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		Not sealed, not floor Some of the site is below the 50 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Good
Raw Water sample port?		Connection point is chamber, sample tap attachment must be brought to site
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		No
Signs of ponding?		No, near a drain
Access by animals		No fence around well, in a residential area where cats and dogs would be common but livestock would be less likely
Protection from vandalism, signs of vandalism		Lid access alarm installed. Padlock on lid
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?		Yes – check valve installed (not tested) Note that a single check valve provides a low degree of protection. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?		N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?		Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)		Steel, good condition

Bore casing grouted (see the definitions section of the DWSNZ, "bore head protection" and NZS:4411 2.5.2.1 Grouting/sealing	Unknown										
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown										
Does the well comply with NZS:4411?	No										
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No										
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)									
	No 5m fenced	Agreed ok									
	Casing not grout sealed	To be agreed									
	Single check valve in headworks	To be agreed									
No air vent	Air vent required										
c) Contamination Sources:											
Does the WSP address contaminant sources and contaminant migration pathways?	Not received										
Any localised well specific sources of contamination?	Adjacent sidewalk, road and creek. Sewers in close proximity.										
d) Below Ground Chambers:											
Water level of chamber	None at time of visit										
Is there a sump pump?	N/A – above ground										
Are there duty/standby sump pumps?	N/A										
Sump pump testing, include date a method	N/A										
Sump pump operation method including start level	N/A										
Sump pump and/or level alarms	N/A										
Does the bore head meet the requirements of Criteria 2	No, see actions below										
7. Actions Arising											

Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal cabling ■ Seal the chamber floor to prevent water inundation and either install a sump pump, or install drainage holes at the base of the chamber. Ensure that the drainage holes have vermin protection, probably in the form of mesh. ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Modify the sample tap connection point to prevent the collection of debris. This may be either a cap or the installation of a permanent sample tap connection device. The sample tap should allow collection outside of the chamber to avoid spilling water in the chamber. ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced and the local contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
Third Priority	<ul style="list-style-type: none"> ■ Mitigation works to prevent inundation and contamination risk from adjacent drain ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device


Dunbars Well 4

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Dunbars Well 4
ECan Well No.	M36/3060
Aquifer No.	2
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	45.9 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	45.9 – 51.9
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	21 March 1985
Control System/Alarms	Well pump on/off, lid opening alarm
Type of Pump	Submersible

<p>Frequency of Pump Use</p>	<p>Generally runs about once a day</p>
<p>4. Photo Record and Comments</p>	
<p>Photo</p>	<p>Comment</p>
 <p>An aerial photograph showing a circular concrete well head located at the end of a paved driveway. The driveway is bordered by a white fence on the right and a road on the left. The well head has a central grate and is surrounded by a concrete curb.</p>	<p>Well is located at the end of a driveway, on the sidewalk and adjacent to a busy road.</p>
 <p>A photograph of a stormwater drain on a road. The drain is a rectangular grate set into the asphalt pavement. The road surface is wet, and there is some debris around the drain.</p>	<p>Stormwater drain on road approximately 2m away</p>
 <p>A photograph showing a drain from a driveway directed towards a well. Two workers in orange safety vests are standing near the well head. The drain is a small pipe that runs along the driveway and ends near the well head.</p>	<p>Drain from driveway directed towards well.</p>
 <p>A photograph looking down into a well chamber. The chamber contains a large, rusted metal pipe. The pipe shows signs of poor condition, including rust and debris. The chamber is surrounded by concrete walls and a metal lid is visible at the top.</p>	<p>Well with water in chamber and evidence that the lid is not water tight. Poor pipe condition can also be seen.</p> <p>Note that the lid has a security alarm.</p> <p>Sample point drains into chamber.</p>

	<p>Water in bottom of chamber. Sump pump outside of sump. Ripples in water imply that there is a leak from the side of the casing near the cable duct.</p>
	<p>A photo of a new sump pump in the chamber that was received after the site visit (19 January 2018). The photo shows a small amount of water in the chamber.</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

<p>a) Water Ingress:</p>		
<p>Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)</p>	<p>Cabling</p>	<p>Could not inspect due to water in chamber but ripples in the water implied that there was a leak from the cable ducting or adjacent casing</p>

	Pipework	Could not inspect due to water in chamber
	Well casing	Could not inspect due to water in chamber
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No Site is above the 50 year flood level and so flooding potential is low
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Surface rust
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No, driveway sloped into chamber
100mm step above ground level?		No
Signs of ponding?		Yes, some ponding on surrounding driveway. The adjacent driveway has a stormwater drain directed towards the chamber.
Access by animals		No fence, in a residential area where cats and dogs would be common but livestock would be less likely
Protection from vandalism, signs of vandalism		Lid access alarm installed. Lid tools required to access but no lock
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?		Yes – check valve installed (not tested) Note that a single check valve provides a low degree of protection. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?		N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?		Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)		Could not assess due to water in chamber

Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown												
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown												
Does the well comply with NZS:4411?	No												
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No												
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)											
	Below ground installation	Agreed ok											
	No 5m fenced	Agreed ok											
	Casing not grout sealed	To be agreed											
	Single check valve in headworks	To be agreed											
No air vent	Air vent required												
c) Contamination Sources:													
Does the WSP address contaminant sources and contaminant migration pathways?	Not received												
Any localised well specific sources of contamination?	Adjacent driveway, sidewalk and road. Sewers in close proximity.												
d) Below Ground Chambers:													
Water level of chamber	200 – 250 mm at time of visit												
Is there a sump pump?	Yes, but it was not running at the time of inspection despite the 200 – 250 mm of water in the bottom. Also not sitting in sump.												
Are there duty/standby sump pumps?	No												
Sump pump testing, include date a method	N/A												
Sump pump operation method including start level	N/A												
Sump pump and/or level alarms	None												

Does the bore head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Install a level sensor and a chamber level alarm ■ Seal the chamber lids ■ Seal cables, pipework and casing if not already sealed (could not assess due to water in chamber) ■ Replace lid and form an apron with a fall away from the lid ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Consider decommissioning this well and replacing with an above ground well in a new location ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced and the local contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ Regular monitoring of this well should be carried out because of the high risk to public health. We recommend weekly and during heavy rain inspections to check that there is no water in the chamber and that there are no signs of it leakage. The sump pump should also be tested regularly.

Dunbars Well 5

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Dunbars Well 5
ECan Well No.	M36/8019
Aquifer No.	4
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	106 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	106 - 110
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	10 May 2006
Control System/Alarms	Well pump on/off, lid opening alarm


Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Ground surrounding chamber is slightly lower



Chamber has a sump but no pump
Some pipe rust



Pitting and rust on casing




Untidy cable seals



Cable entry at side wall is not sealed

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Sealed at well, not at chamber side wall
	Pipework	Sealed
	Well casing	Reasonable rust at casing-chamber connection. This may no longer be sealed
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No Some of the site is below the 50 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Minor surface rust
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		No
Signs of ponding?		Not at time of inspection

Access by animals	No fence, in a residential area where cats and dogs would be common but livestock would be less likely	
Protection from vandalism, signs of vandalism	Lid access alarm installed. Lid locked with padlock	
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that a single check valve provides a low degree of protection. The well pump may also have a check valve but this is not known.	
If not, has this been agreed with the DWA?	N/A	
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached	
Bore casing type and condition (see NZS:4411 2.4.2)	Significant rust	
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown	
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown	
Does the well comply with NZS:4411?	No	
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No	
If no, what non-compliances require agreement with the DWA?	Non-Compliance	Agreed with DWA? (see Appendix D)
	Below ground installation	Agreed ok
	No 5m fenced	Agreed ok
	Casing not grout sealed	To be agreed
	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required
	No air vent	Air vent required

c) Contamination Sources:	
Does the WSP address contaminant sources and contaminant migration pathways?	Not received
Any localised well specific sources of contamination?	Adjacent sidewalk and road Sewers in close proximity.
d) Below Ground Chambers:	
Water level of chamber	None at time of visit
Is there a sump pump?	No pump but there is a sump
Are there duty/standby sump pumps?	No
Sump pump testing, include date a method	N/A
Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the bore head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal cabling at chamber side wall ■ Ensure that casing-chamber connection is sealed ■ Check casing integrity, treat rust and seal chamber/floor ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Form an apron with a fall away from the chamber ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) ■ DWA to confirm that a single check valve in the headworks meets the backflow prevention

	<p>requirements. Backflow prevention on the well pump may be installed but has not been confirmed.</p> <ul style="list-style-type: none"> ■ Agree with the DWA whether or not grout seals must be retrofitted requirements based on how soon the well will be replaced ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced and the local contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
<p>Third Priority</p>	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
<p>Ongoing</p>	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps



Discharge to Water CRC092047 Terminated-Surrendered Stormwater Industrial

Well Number: M36/8019

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Water	CRC092047	Terminated-Surrendered	Stormwater Industrial
Discharge to Land	CRC092611	Terminated--Surrendered	Stormwater Industrial

Well Number: M36/4053

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Water	CRC092047	Terminated-Surrendered	Stormwater Industrial
Discharge to Land	CRC092611	Terminated--Surrendered	Stormwater Industrial

Appendix C

Bore Logs



N.Z.D.F.
member

CLEMENCE DRILLING CONTRACTOR

Mill Road OHOKA Phone Ohoka 5252

D
M36/4053
point
1573

WELL-OWNER Poroporo County Council
ADDRESS 149 Main South Rd
Sockburn
DRILLER D Clemence
DRILLING DATE 28-12-89
LOCALITY Car Dunbars/Halswell Rd

No. 1. well

MAP SHEET No. _____
GRID REFERENCE* _____
N.Z.G.S. WELL No. _____
WATER RIGHT No. _____ Reduced Level _____

DEPTH FROM SURFACE (m)			COLOUR	STRATA	DEPTH FROM SURFACE (m)		STATIC WATER LEVEL (m)
Top	Bottom	Top			Bottom		
0	0			Blue silt & Top soil			
0	9.3			Big blue gravel			
1.3	13.8			Blue pug			
13.8	15.4			Peat			
15.4	18			Big blue gr			1.930 BGL
18	19.4			Big brown sandy gravel			
19.4	20.2			Well sorted br gravel			
20.2	20.5			Yellow clay			
20.5	21.7			Coarse clean well sorted gr			
21.7	24.7			Br stained "			
24.7	24.9			Br/blue gravel			
24.9	25.1			Blue clay			
25.1	26			Peat			
26	26.15			Tight greeny blue clay			
26.15	26.4			Bl/Br gravel			
26.4	26.65			Yellow clay			
26.65	27.7			clean loose gravel			
27.7	30.7			Sandy gravel (br)			1.1 BGL
30.7	31.2			Yellow clay			
31.2	34			Blue Pug			
34	37.1			Yellow clay			
37.1	43			Brown sand saturated with heavy clay content.			

CASING DIAMETER (cm) _____ DEPTH (m) _____
SCREEN TYPE _____ SET AT _____
SCREEN LENGTH (m) ± _____ STATIC WATER LEVEL _____
DRAWDOWN (m) _____ AFTER _____ HOURS PUMPING AT _____ (LITRES SEC/MIN)

REMARKS (INCLUDING NOTES ON CORES AND SAMPLES TAKEN) _____

N.Z.D.F.
member

CLEMENCE DRILLING CONTRACTOR

Mill Road OHOKA Phone Ohoka

Ⓝ
No. 1 Well

WELL-OWNER Papanui County Council
ADDRESS 149 Main South Rd
Sockburn
DRILLER D. Clemence
DRILLING DATE 28-12-89
LOCALITY Enc Dunbars / Halswell Rd

MAP SHEET No. _____
GRID REFERENCE* _____
N.Z.G.S. WELL No. _____
WATER RIGHT No. _____ Reduced Level _____

Ⓝ
No. 1

DEPTH FROM SURFACE (m)			COLOUR	STRATA			DETAILS OF AQUIFERS		
Top	Bottom			Top	Bottom	STATIC WATER LEVEL (m)			
3	43.4		Grey clay & Peat						
43.4	44.5		Yellow clay						
44.5	45		Claybound gravel						
45	47.25		sandy br gravel						
47.25	47.8		claybound gravel						
47.8	48.4		well sorted gravels						
48.4	50.8		Good well sorted gravels						
50.8	51.8		sandier gravels						
51.8	54.1		Good clean gravel						
54.1	54.6		Very sandy / stained						

CASING DIAMETER (cm) 300mm DEPTH (m) 53.6 Mtrs
SCREEN TYPE Harrison wedge wire SET AT 48.6 - 53.6
SCREEN LENGTH (m) 5 Mtr leader 720 STATIC WATER LEVEL +200
DRAWDOWN (m) 3 Mtrs AFTER 1 HOURS PUMPING AT 64 (LITRES SEC/MIN)
3.3 Mtrs 2 68 4/Sec

REMARKS (INCLUDING NOTES ON CORES AND SAMPLES TAKEN) - Pulled back 1mtr and gravel packed

N.Z.D.F.
member

CLEMENCE DRILLING CONTRACTOR

Mill Road

OHOKA

Phone Ohoka 528

WELL-OWNER Papanui County Council
ADDRESS 10 Ruyds & Garden
P.O Box 870

MAP SHEET No. _____

DRILLER D Clemence

GRID REFERENCE* _____

DRILLING DATE 16.5.90

N.Z.G.S. WELL No. _____

LOCALITY Dunbars Rd No 2 Bore

WATER RIGHT No. _____ Reduced Level _____

STRATA			DETAILS OF AQUIFERS		
DEPTH FROM SURFACE (m)		COLOUR	DEPTH FROM SURFACE (m)		STATIC WATER LEVEL (m)
Top	Bottom		Top	Bottom	
0	5.6	Top soil - Blue Pug			
5.6	8.8	clean blue gravel			
8.8	15	Blue pug			
15	16.1	Silty blue pug			
16.1	20.8	Rust stained loose gravel			
20.8	24.3	Good brown gravel			
24.3	26.1	Peat			
26.1	26.2	Yellow clay			
26.2	28	Br gravel clay seams			
28	28.6	Solid yellow clay			
28.6	31.7	Big well sorted sandy gr			
31.7	34.4	Good loose gravel			
34.4	44	Sandy brown gravel.			
44	47	Yellow clay			
47	47	clean br gravel			
47	48.1	Rust stained sandier gr			
48.1	49.3	Good clean gravel			
49.3	50	sandier big gravel			
50	51.7	Ex gravel			
51.7	52.9	Tight brown gravel			
52.9	53.6	Good HB seam			
53.6	54.3	loose pea gravel			
54.3		sandy			

CASING DIAMETER (cm) 300mm DEPTH (m) 54.3 Mtrs
 SCREEN TYPE Houston stainless steel SET AT 48.3 - 54.3 Mtrs
 SCREEN LENGTH (m)† 6 Mtrs STATIC WATER LEVEL 7.20 B.G.L.
 DRAWDOWN (m) 2.030 AFTER 3 HOURS PUMPING AT 56.5 L (LITRES SECURITY)

REMARKS (INCLUDING NOTES ON CORES AND SAMPLES TAKEN) _____

N.Z.D.F.
member

Bore No 3

CLEMENCE DRILLING CONTRACTOR

Mill Road

OHOKA

Phone Ohoka 528

WELL OWNER Christchurch City Council

ADDRESS P O Box 237
CH-CH

DRILLER J Blundell - T Watson

DRILLING DATE 1-10-1990

LOCALITY Dunbars Rd Halswell

MAP SHEET No. _____

GRID REFERENCE* _____

N.Z.G.S. WELL No. _____

WATER RIGHT No. _____ Reduced Level _____

STRATA			DETAILS OF AQUIFERS		
DEPTH FROM SURFACE (m)		COLOUR	DEPTH FROM SURFACE (m)		STATIC WATER LEVEL (m)
Top	Bottom		Top	Bottom	
0	2.5	Br silty clay			
2.5	7.6	Blue pug & timber			
7.6	7.75	claybound gr			
7.75	10.2	Good clean blue gr			
10.2	13.4	Blue pug & timber			
13.4	13.7	Peat			
13.7	15.3	Blue pug & timber			
15.3	15.45	Peat			
15.45	17.7	Good well sorted gr			
17.7	21.7	stained br gravel			4.4
21.7	22.4	sandy gravel			
22.4	22.6	Yellow clay & gravel			
22.6	24.0	stained br sandy gravel			
24	31.5	Brown gravel / lenses yellow clay			
31.5	38.4	Sandy stained gravel			
38.4	39.8	Sand			
39.8	41.85	sandy gravel			
41.85	42.5	Yellow clay claybound gr			
42.5	44.77	Blue Pug			
44.77	45.77	Yellow claybound gr			
45.77	52.57	Good clean gravel			
52.57		Yellow clay			


CASING DIAMETER (cm) 300mm DEPTH (m) 52.57 mtrs
 SCREEN TYPE Houston wedge wire SET AT 46.57 - 52.57
 SCREEN LENGTH (m) 6 mtrs STATIC WATER LEVEL 1.3 B.P.T
 DRAWDOWN (m) 3.7 AFTER 2 HOURS PUMPING AT 100 (LITRES SEC/MIN)

REMARKS (INCLUDING NOTES ON CORES AND SAMPLES TAKEN) — _____

Bore or Well No	M36/3060	 Environment Canterbury Regional Council <i>Kaunihera Taiao ki Waitaha</i>	
Well Name	DUNBARS ROAD		
Owner	Christchurch City Council		
Well Number	M36/3060	File Number	CO6C/03078
Owner	Christchurch City Council	Well Status	Active (exist, present)
Street/Road	DUNBARS ROAD	NZTM Grid Reference	BX24:64622-75939
Locality	OAKLANDS	NZTM X and Y	1564622 - 5175939
Location Description	SEE M36/4052	Location Accuracy	2 - 15m
CWMS Zone	Christchurch - West Melton	Use	Small Community Supply,
Groundwater Allocation Zone	Christchurch/West Melton	Water Level Monitoring	–
Depth	51.90m	Water Level Count	0
Diameter	300mm	Initial Water Level	
Measuring Point Description		Highest Water Level	
Measuring Point Elevation	16.30m above MSL (Lyttelton 1937)	Lowest Water Level	
Elevation Accuracy	< 0.5 m	First reading	
Ground Level	0.00m above MP	Last reading	
Strata Layers	18	Calc Min 95%	1.00m above MP
Aquifer Name	Linwood Gravel	Aquifer Tests	0
Aquifer Type	Unknown	Yield Drawdown Tests	0
Drill Date	21 Mar 1985	Max Tested Yield	0 l/s
Driller	A M Bisley & Co	Drawdown at Max Tested Yield	0 m
Drilling Method	Cable Tool	Specific Capacity	
Casing Material	STEEL	Last Updated	22 Dec 2015
Pump Type	Unknown	Last Field Check	
Water Use Data	Yes		

LOCATION SKETCH

908



Screens

Screen No.	Screen Type	Top (m)	Bottom (m)	Slot Size (mm)	Slot Length (mm)	Diameter (mm)	Leader Length (mm)
1	Stainless steel	45.9	51.9				

No step tests for this well


Comments


Comment Date	Comment
	FROM OLD CWS DB On Dunbars Rd near the corner of Halswell Rd. M36/3060 is on the south side of Dunbars Rd, approx. 240 m from M36/4333. Is in front of driveway for 83 Dunbars Red under a metal plate on footpath.
07 Oct 1998	Ex Paparua County Council
10 Feb 2000	FROM OLD CWS DB Surrounding area residential, paddocks used to graze horses & for cropping & is a BP petrol station on the south corner of Halswell & Dunbars Rd. GRID REF: M36:7462-3755.
13 Sep 2002	On the same consent as Dunbar P.S.
13 Jan 2004	Gridref changed from: M36:746-375 (from fieldwork 2000 Community Supply dtb)
17 Feb 2006	West Pressure Zone
28 Aug 2009	CCC advised taking from aquifer 2
06 May 2010	MfE source code added


Bore Log

Borelog for well M36/3060

Grid Reference (NZTM): 1564622 mE, 5175940 mN
 Location Accuracy: 2 - 15m
 Ground Level Altitude: 16.3 m +MSD Accuracy: < 0.5 m
 Driller: A M Bisley & Co
 Drill Method: Cable Tool
 Borelog Depth: 52.0 m Drill Date: 21-Mar-1985







Clemence Drilling Contractors Ltd

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

WELL OWNER	Christchurch City Council	CONSENT NUMBER	CRC061480
ADDRESS	Dunbars Road, Halswell	BORE NUMBER	M36/8019
	Christchurch	GRID REFERENCE	
LOCALITY	Dunbars Road, Halswell, Christchurch		
DRILLER	Tony Smith/Ira Leech	DRILLING DATE	10-May-06

Depth from Surface (m)		Strata	Details of Aquifers	
Top	Bottom		Depth from surface (m)	S/W Level
0.000	0.100	Topsoil		
0.100	0.600	Yellow clay and pit run		
0.600	4.000	Hard yellow clay - some gravel		
4.000	7.200	Grey puggy sand		
7.200	10.700	Medium - large blue grey gravel		
10.700	11.000	Grey pug and peat		
11.000	14.300	Soft grey pug		
14.300	15.000	Peat and timber		
15.000	15.700	Grey pug		
15.700	16.300	Peat and timber		
16.300	17.600	Tight grey gravel		
17.600	26.300	Loose brown sandy gravel		
26.300	28.300	Peat		
28.300	29.000	Yellow clay		
29.000	30.900	Loose grey/brown gravel		
30.900	31.100	Blue gravel		
31.100	31.300	Timber		
31.300	31.900	Hard yellow clay		
31.900	32.700	Brown water bearing sand		
32.700	37.200	Grey pug		
37.200	38.700	Brown clay		
38.700	42.000	Clay bound sand		
42.000	42.400	Yellow clay		
42.400	44.800	Clay bound sand		
44.800	46.300	Grey pug		
46.300	46.600	Peat		

Casing Diameter(mm)	300mm	Static water level	.63 AGL	Depth(M)	110.000
Screen Type	Aqua Link		Set At	106.000	110.000
Screen Length (m)	4 mtrs			Leader	1.200
Drawdown (m)	8.5 mtrs	Pumping	4	Hours @	70
					Ltrs/sec

REMARKS: * Well is on a mound approximately 1.5 metres high *

** Well should not be pumped at over 70 L/sec **



Clemence Drilling Contractors Ltd

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799


BORELOG

WELL OWNER	Christchurch City Council	CONSENT NUMBER	CRC061480
ADDRESS	Dunbars Road, Halswell	BORE NUMBER	M36/8019
	Christchurch	GRID REFERENCE	
LOCALITY	Dunbars Road, Halswell, Christchurch		
DRILLER	Tony Smith/Ira Leech	DRILLING DATE	10-May-06

Depth from Surface (m)		Strata	Details of Aquifers		
Top	Bottom		Depth from surface (m)	S/W Level	
46.600	47.100	Yellow clay			
47.100	48.700	Clay bound gravel			
48.700	54.200	Sandy brown gravel			
54.200	54.300	Clay seam			
54.300	56.700	Loose sandy brown gravel			
56.700	57.900	Brown sand			
57.900	58.100	Blue/green pug			
58.100	59.800	Peat and timber			
59.800	61.600	Loose blue gravel			
61.600	64.300	Grey pug and peat			
64.300	66.500	Blue pug/peat traces			
66.500	67.400	Blue clay bound gravel			
67.400	67.600	Brown clay bound gravel			
67.600	68.300	Brown gravel			
68.300	68.900	Yellow clay			
68.900	69.800	Tight water bearing gravel			
69.800	69.900	Clay seam			
69.900	70.800	Loose brown sandy gravel			
70.800	72.700	Very sandy gravel			
72.700	72.800	Yellow clay			
72.800	73.300	Very sandy gravel			
73.300	73.600	Yellow clay			
73.600	75.100	Grey pug			
75.100	76.300	Yellow clay			
76.300	78.200	Brown sand			
78.200	79.000	Yellow/brown clay			
Casing Diameter(mm)	300mm	Static water level	.63 AGL	Depth(M)	110.000
Screen Type	Aqua Link		Set At	106.000	110.000
Screen Length (m)	4 mtrs		Leader	1.200	
Drawdown (m)	8.5 mtrs	Pumping	4	Hours @	70
					Ltrs/sec

REMARKS * Well is on a mound approximately 1.5 metres high *

** Well should not be pumped at over 70 L/sec **



Clemence Drilling Contractors Ltd

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

WELL OWNER	Christchurch City Council	CONSENT NUMBER	CRC061480
ADDRESS	Dunbars Road, Halswell	BORE NUMBER	M36/8019
	Christchurch	GRID REFERENCE	
LOCALITY	Dunbars Road, Halswell, Christchurch		
DRILLER	Tony Smith/Ira Leech	DRILLING DATE	10-May-06

Strata			Details of Aquifers		
Depth from Surface (m)			Depth from		S/W Level
Top	Bottom		surface (m)		
79.000	80.300	Brown clay			
80.300	81.400	Yellow clay			
81.400	81.700	Clay bound gravel			
81.700	87.000	Very sandy water bearing gravel			
87.000	88.000	Yellow clay			
88.000	89.400	Very sandy gravel			
89.400	90.500	Sand			
90.500	92.900	Sandy stained gravel			
92.900	93.400	Yellow clay			
93.400	93.900	Blue pug			
93.900	94.400	Grey pug			
94.400	94.800	Peat			
94.800	99.800	Grey pug			
99.800	100.000	Peat			
100.000	100.400	Grey pug			
100.400	100.800	Peat and timber			
100.800	102.300	Grey pug			
102.300	103.000	Peat			
103.000	103.300	Yellow clay			
103.300	105.000	Clay bound gravel			
105.000	105.900	Loose stained sandy gravel			
105.900	106.000	Clay bound seam			
106.000	110.000	Tight sandy water bearing gravel			
110.000	111.100	Very loose very sandy gravel			
111.100	111.800	Hard yellow clay			

Casing Diameter(mm)	300mm	Static water level	.63 AGL	Depth(M)	110.000
Screen Type	Aqua Link		Set At	106.000	110.000
Screen Length (m)	4 mtrs			Leader	1.200
Drawdown (m)	8.5 mtrs	Pumping	4	Hours @	70
					Ltrs/sec

REMARKS * Well is on a mound approximately 1.5 metres high *

** Well should not be pumped at over 70 L/sec **

Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Brooklands Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Risks	2
4	Recommendations	3
5	Conclusion	4

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the wells supplying Brooklands Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as “secure”, a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used throughout this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Brooklands Pumping Station (Brooklands/Kaingā Pressure Zone)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Bore logs from ECan’s website (Well 1 and 2) as included in Appendix C - <https://www.ecan.govt.nz/gis-mapping/>
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Brooklands Pumping Station is supplied by two wells; Brooklands Wells 1 and 2. The station supplies the Brooklands/Kaingā pressure zone. Table 2-1 summarises key information about the two wells.

Table 2-1: Brooklands Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 1	M 35/7180	78.6 – 82.6	2
Well 2	M35/7291	78.75 – 81.75	2

Brookland Well 2 could not be accessed due to safety concerns. The chamber height has recently been increased to approximately 3 m above ground level and there is no railing or a permanent ladder. This report

includes some information and recommendation for this well, but it is important to note that a full inspection could not take place and is recommended once the safety concerns are addressed.

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from both alpine river and rainfall to land surface recharge. The wells supplying Brooklands Pumping Station are screened within moderately-deep (Aquifer 2 – Linwood Gravel Aquifer) leaky (semi)-confined aquifers within the Christchurch Artesian Aquifer System.

4 Well Inspections

An inspection of each well was carried out on 7 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Andrew Batchelor (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Brooklands Wells 1 and 2 do not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 6-1 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 6-1: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 1	<ul style="list-style-type: none"> ■ Seal cabling at wall penetration ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5m above 100 year flood level 			

	First Priority	Second Priority	Third Priority	Ongoing
Well 2	<ul style="list-style-type: none"> ■ Ensure that safe access to the bore is available without bringing temporary equipment to site. This includes installation of a permeant ladder and railings ■ Re-inspect well once access is available ■ Seal leaks in chamber 			
All wells		<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. 	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed. 	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

7 Conclusion

The information reviewed and the inspections carried out indicate that neither of the Brooklands wells meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether

Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2. A re-inspection of Brooklands Well 2 is also required as access could not be gained during the initial visit.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Brooklands
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	Brooklands Wells 1 and 2 draw from Aquifer 2 (leaky (semi)-confined)
Surface Water Ways, Drains, etc	Styx River/Brooklands Lagoon
4. Photo Record and Comments	
Photo	Comment
	Step up into Brooklands Pump Station. Note that some of the site is below the 100 year flood level and so there is the potential for flooding

	<p>Small diesel storage tank within a bund</p>		
	<p>Pipework inside pump house</p>		
<p>5. Risks from Surrounding Environment</p>			
<p>a) Within the site:</p>			
<p>Diesel/Chemical Storage</p>	<p>Small bund ed tank</p>	<p><input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground</p>	<p>Fuel lines <input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground</p>
<p>Access by Animals</p>	<p>Not a fenced site but building is locked</p>		
<p>Protection from vandalism, signs of vandalism</p>	<p>As above, no signs of vandalism</p>		

Other Activities	N/A
b) Immediate Neighbouring Land Use:	
Current Neighbouring Land Use	Some residential and rural, mostly red zoned property unused
Significant Changes Since Previous Inspection	None identified
Zoning of Neighbouring Land	Not available on CCC's Zones and Designation Map
c) Wider Environment:	
Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	Agriculture Sewer nearby
Risk of flood inundation	Some of the site is below the 100 year flood level and so there is the potential for flooding. Step up to pump station to minimise this risk
Potential sources of young water	No sources specific to the pumping station identified. See well assessments
General land use in catchment (LLUR)	As below
Contaminated sites (HAIL status)	At well and pump station address (1001 Lower Styx Road): ACT 10714 A17 - Storage tanks or drums for fuel, chemicals or liquid waste
Status and condition of surrounding wells (within 400 m radius)	Multiple wells
Landfill	None identified
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	Refer well assessments
Second Priority	Refer well assessments
Third Priority	Refer well assessments
Ongoing	Refer well assessments

Well Head Protection Assessment – Individual Well Heads


Brooklands Well 1

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Brooklands Well 1
ECan Well No.	M 35/7180
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	78.6 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	78.6 – 82.6
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	24 February 1995
Control System/Alarms	Pump failure

Type of Pump	Submersible
Frequency of Pump Use	Approximately twice a week
4. Photo Record and Comments	
Photo	Comment
	Deep chamber where access is not possible without meeting confined space requirements. Therefore, inspection was from above and by photo only.
	Cable glands appear sealed
	
	

	<p>Well casing appears to be sealed to the chamber floor from the photos collected</p>
	<p>Not obvious whether or not the cable penetrations through the chamber side wall are sealed</p>
	<p>Sample tap in cabinet on the outside of the chamber</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Cabling appears sealed at bore entry but it is not clear if it is sealed at the wall penetration
	Pipework	Sealed with sidewall of chamber
	Well casing	Sealed with floor (from photos)
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No – casing is below ground level and the cabling penetrations through the wall may not be sealed Some of the site is below the 100 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Good condition
Raw Water sample port?		Yes, on the outside of the chamber in a cabinet
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		No
Signs of ponding?		Not at time of inspection
Access by animals		5m fence from boundary installed. Chickens outside fence.
Protection from vandalism, signs of vandalism		Lid locked with padlock. No signs of vandalism.
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?		Yes –butterfly valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?		N/A

Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached												
Bore casing type and condition (see NZS:4411 2.4.2)	Good condition												
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown												
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown												
Does the well comply with NZS:4411?	No												
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No												
If no, what non-compliances require agreement with the DWA?	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;">Non-Compliance</th> <th style="width: 50%;">Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No sump pump</td> <td>Sump pump required</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No sump pump	Sump pump required	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)											
	Below ground installation	Agreed ok											
	Casing not grout sealed	To be agreed											
	Single check valve in headworks	To be agreed											
	No sump pump	Sump pump required											
No air vent	Air vent required												
c) Contamination Sources:													
Does the WSP address contaminant sources and contaminant migration pathways?	Not received												
Any localised well specific sources of contamination?	Diesel storage close by. Small tank with bunding to minimise the risk												
d) Below Ground Chambers:													
Water level of chamber	Dry at the time of inspection												
Is there a sump pump?	No pump or sump												
Are there duty/standby sump pumps?	No												
Sump pump testing, include date a method	N/A												

Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the well head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal cabling at wall penetration ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Brooklands Well 2

Note: this is not a full inspection. The well could not be accessed due to safety concerns.


1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Brooklands Well 2
ECan Well No.	M 35/7291
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl) (assume top of screen)	78.75
Casing Diameter (mm)	300
Screen Interval (mbgl)	78.75 – 81.75
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown

Date Drilled	12 September 1995
Control System/Alarms	Pump failure
Type of Pump	Submersible
Frequency of Pump Use	Approximately twice a week
4. Photo Record and Comments	
Photo	Comment
	Brookland Well 2 could not be accessed due to safety concerns. The chamber has recently been increase to ~3m above ground level and there is no railing or a permanent ladder
	Signs of leaking from inside the chamber



Evidence of ponding in the area

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Unknown
	Pipework	Unknown
	Well casing	Unknown
Any history of E. coli transgressions? Historical and current levels of total coliforms?	No E. coli transgressions recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No – leaking from the chamber could be seen from the outside	

	Some of the site is below the 100 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level	Unknown
Type and condition of borehead pipework (above ground)	Unknown
Raw Water sample port?	Yes, outside the chamber
Concrete apron sloped to drain away from well?	No
100mm step above ground level?	No
Signs of ponding?	Yes, leaking from chamber and in adjacent path
Access by animals	5m fence from boundary installed. Chickens outside fence.
Protection from vandalism, signs of vandalism	Lid locked with padlock. No signs of vandalism.
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Unknown
If not, has this been agreed with the DWA?	Unknown
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Unknown
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown
Does the well comply with NZS:4411?	No
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No

If no, what non-compliances require agreement with the DWA?	Non-Compliance		Agreed with DWA? (see Appendix D)	
	Below ground installation		Agreed ok	
	Casing not grout sealed		To be agreed	
	Single check valve in headworks		To be agreed	
	No sump pump		Sump pump required if not already installed	
	No air vent		Air vent required	
c) Contamination Sources:				
Does the WSP address contaminant sources and contaminant migration pathways?		Not received		
Any localised well specific sources of contamination?		Diesel storage close by. Small tank with bunding to minimise the risk. Roads and sewers in close proximity.		
d) Below Ground Chambers:				
Water level of chamber		Unknown		
Is there a sump pump?		Unknown		
Are there duty/standby sump pumps?		Unknown		
Sump pump testing, include date a method		Unknown		
Sump pump operation method including start level		Unknown		
Sump pump and/or level alarms		Unknown		
Does the bore head meet the requirements of Criteria 2		Unknown		
7. Actions Arising				
Identify issues and rank them in terms of whether they require:				
First Priority		<ul style="list-style-type: none"> ■ Ensure that safe access to the bore is available without bringing temporary equipment to site. This includes installation of a permeant ladder and railings ■ Re-inspect well once access is available 		

	<ul style="list-style-type: none"> ■ Seal leaks in chamber
Second Priority	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. <p>Ensure that the WSP addresses contaminant sources and contaminant migration pathways.</p>
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps





Figure 1: Summary of wells and consents within 400m of Brooklands Wells

Table 2: Summary of consents within 400m of Brooklands Wells

Brooklands Well Sites

Well Number: M35/7180

Type	Consent Number	Consent Status	Feature Type
Discharge to Land	NCY880584	Terminated - Expired	Stormwater Residential
Discharge to Water	CRC080874	Application withdrawn	Stormwater Residential
Discharge to Water	NCY880526C	Terminated- Surrendered	Stormwater Residential

Well Number: M35/7291

Type	Consent Number	Consent Status	Feature Type
Discharge to Land	NCY880584	Terminated - Expired	Stormwater Residential
Discharge to Water	NCY880526C	Terminated- Surrendered	Stormwater Residential

Appendix C

Bore Logs



Bore or Well No	M35/7180	 Environment Canterbury Regional Council <i>Kaunihera Taiao ki Waitaha</i>	
Well Name	1001 LOWER STYX ROAD		
Owner	Christchurch City Council		
Well Number	M35/7180	File Number	CO6C/09665
Owner	Christchurch City Council	Well Status	Active (exist, present)
Street/Road	1001 LOWER STYX ROAD	NZTM Grid Reference	BW24:75198-93914
Locality	BROOKLANDS	NZTM X and Y	1575198 - 5193914
Location Description		Location Accuracy	< 50m
CWMS Zone	Christchurch - West Melton	Use	Public Water Supply,
Groundwater Allocation Zone	Christchurch/West Melton	Water Level Monitoring	--
Depth	82.60m	Water Level Count	0
Diameter	300mm	Initial Water Level	5.90m above MP
Measuring Point Description		Highest Water Level	
Measuring Point Elevation	2.10m above MSL (Lyttelton 1937)	Lowest Water Level	
Elevation Accuracy	< 2.5 m	First reading	
Ground Level	0.00m above MP	Last reading	
Strata Layers	33	Calc Min 95%	0.60m below MP
Aquifer Name	Linwood Gravel	Aquifer Tests	2
Aquifer Type	Flowing Artesian	Yield Drawdown Tests	7
Drill Date	24 Feb 1995	Max Tested Yield	76 l/s
Driller	McMillan Drilling Ltd	Drawdown at Max Tested Yield	5 m
Drilling Method	Cable Tool	Specific Capacity	11.52 l/s/m
Casing Material	STEEL	Last Updated	08 Oct 2015
Pump Type	Unknown	Last Field Check	
Water Use Data	Yes		



Screens

Screen No.	Screen Type	Top (m)	Bottom (m)	Slot Size (mm)	Slot Length (mm)	Diameter (mm)	Leader Length (mm)
1	Stainless steel	78.6	82.6				

Step Tests

Step Test Date	Step	Yield	Yield GPM	DrawDown	Step Duration
24 Feb 1995	1	76	1003.06195	4.8	24
01 Jan 1996	1	19	250.765488	1.65	0.266666681
01 Jan 1996	2	34	448.738251	3.36	0.25
01 Jan 1996	3	43	567.5219	4.57	0.316666663
01 Jan 1996	4	51	673.107361	5.18	0.05
01 Jan 1996	5	60	791.891	6.7	0.0833333358
01 Jan 1996	6	75	989.8638	9.61	0


Comments


Comment Date	Comment
	NO.1 WELL.ALSO M35/7291
	FROM OLD CWS DB Located at Brooklands pumpstation, 1001 Lower Styx Rd (on west side of the rd). Situated in front of the pump room in the garden. Is enclosed in a 1 m tall round concrete tank with a metal lid (padlocked).
15 Oct 1998	Brooklands pressure zone.
11 Feb 2000	FROM OLD CWS DB Surrounding area residential, across rd is empty paddock & rear of pumpstation, west boundary, is the Styx River. GRID REF: M35:85203-55528.
06 Oct 2005	Step test data entered under 1/1/1996, actual date unknown.
26 Sep 2007	Gridref changed from: M35:8520-5553


Bore Log

Borelog for well M35/7180

Grid Reference (NZTM): 1575199 mE, 5193915 mN
 Location Accuracy: < 50m
 Ground Level Altitude: 2.1 m +MSD Accuracy: < 2.5 m
 Driller: McMillan Drilling Ltd
 Drill Method: Cable Tool
 Borelog Depth: 83.7 m Drill Date: 24-Feb-1995







Bore or Well No	M35/7291	 Environment Canterbury Regional Council <i>Kaunihera Taiao ki Waitaha</i>	
Well Name	1001 LOWER STYX ROAD		
Owner	Christchurch City Council		
Well Number	M35/7291	File Number	CO6C/09445
Owner	Christchurch City Council	Well Status	Not Used
Street/Road	1001 LOWER STYX ROAD	NZTM Grid Reference	BW24:75139-93923
Locality	BROOKLANDS	NZTM X and Y	1575139 - 5193923
Location Description	2 BORES ON SAME BLOCK, LOT 134	Location Accuracy	2 - 15m
CWMS Zone	Christchurch - West Melton	Use	Small Community Supply,
Groundwater Allocation Zone	Christchurch/West Melton	Water Level Monitoring	--
Depth	83.00m	Water Level Count	0
Diameter	300mm	Initial Water Level	6.09m above MP
Measuring Point Description		Highest Water Level	
Measuring Point Elevation	1.40m above MSL (Lyttelton 1937)	Lowest Water Level	
Elevation Accuracy	< 2.5 m	First reading	
Ground Level	0.00m above MP	Last reading	
Strata Layers	17	Calc Min 95%	0.40m below MP
Aquifer Name	Linwood Gravel	Aquifer Tests	1
Aquifer Type	Flowing Artesian	Yield Drawdown Tests	1
Drill Date	12 Sep 1995	Max Tested Yield	76 l/s
Driller	McMillan Drilling Ltd	Drawdown at Max Tested Yield	2 m
Drilling Method	Unknown	Specific Capacity	48.10 l/s/m
Casing Material	Steel	Last Updated	30 Mar 2016
Pump Type	Unknown	Last Field Check	
Water Use Data	No		



Screens

Screen No.	Screen Type	Top (m)	Bottom (m)	Slot Size (mm)	Slot Length (mm)	Diameter (mm)	Leader Length (mm)
1	Stainless steel	78.75	81.75				

Step Tests

Step Test Date	Step	Yield	Yield GPM	DrawDown	Step Duration
12 Sep 1995	1	76	1003.06195	1.58	24


Comments


Comment Date	Comment
	NO.2 WELL. ALSO M35/7180
	FROM OLD CWS DB Located at Brooklands pumpstation, 1001 Lower Styx Rd (on west side of the rd). Situated at the back of the pumpstation section, in a small reserve by the Styx River. Is enclosed in a 1.5 m tall concrete tank with a metal lid.
15 Oct 1998	Brooklands pressure zone.
11 Feb 2000	FROM OLD CWS DB Surrounding area residential, across rd is empty paddock & rear of pumpstation, west boundary, is the Styx River. GRID REF: M35:85140-55541.
05 Feb 2008	Gridref changed from: M35:8514-5554
26 Aug 2011	Unservicable as a result of earthquake activity. Will be replaced.
14 Apr 2016	Small monitoring piezo in front of well. Approx 3.8m deep. See picture. FROM WAIMAK PIEZO QA SUMMER 2015/16.
20 May 2016	Visited for Waimakariri Piezo QA Summer 2015/2016. Well details updated.

Bore Log

Borelog for well M35/7291

Grid Reference (NZTM): 1575140 mE, 5193924 mN
 Location Accuracy: 2 - 15m
 Ground Level Altitude: 1.4 m +MSD Accuracy: < 2.5 m
 Driller: McMillan Drilling Ltd
 Drill Method: Unknown
 Borelog Depth: 83.0 m Drill Date: 12-Sep-1995





Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Denton Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Risks	3
4	Recommendations	3
5	Conclusion	5

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the wells supplying Denton Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as "secure", a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used throughout this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Denton Pumping Station (West Pressure Zone)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Original bore logs (Wells 2, 3, 4 and 5) as included in Appendix C
- Bore logs from ECan’s website (Well 1) as included in Appendix C - <https://www.ecan.govt.nz/gis-mapping/>
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Denton Pumping Station is supplied by five wells; Denton Wells 1 – 5. The station supplies part of the West Pressure Zone. Table 1 summarises key information about the five wells.

Table 1: Denton Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 1	M35/7291	No Screen Data	3
Well 2	M35/1866	90.23 – 96.28	3
Well 3	M35/1865	94.3 – 102.4	3
Well 4	M35/3546	89.75 – 95.85	3

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 5	M35/1864	63.4 – 72.8	3

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from both alpine river and rainfall to land surface recharge. The wells supplying Denton Pumping Station are generally from Aquifer 3 and source groundwater from a leaky-confined aquifer.

4 Well Inspections

An inspection of each well was carried out on 8 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Matthew Thomas (City Care). The Inspection Reports in Appendix A include a complete list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Denton Wells 1 – 5 do not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 2 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 2: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 1	<ul style="list-style-type: none"> ■ Check seal between chamber floor and well casing and seal as required ■ Check pipework penetrations through chamber sidewall and seal if required 			

	First Priority	Second Priority	Third Priority	Ongoing
	<ul style="list-style-type: none"> Check cable entry points and seal if required 			
Well 2	<ul style="list-style-type: none"> Seal side entry to chamber Replace chamber lid so the chamber is protected from rainfall and runoff 			
Well 3	<ul style="list-style-type: none"> Install and seal cable glands Check that pipe wall penetrations are sealed Investigate bellows collapse and mitigate Investigate source of graffiti and trash. Mitigate likelihood of vandal access Seal chamber floor to prevent inundation from below. Ensure that casing is sealed to floor. Install a fence 5m away from well to minimise the likelihood of vandalism 	<ul style="list-style-type: none"> Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected 		
Well 4	<ul style="list-style-type: none"> Seal pipe penetration through chamber wall Seal casing and chamber floor 	<ul style="list-style-type: none"> Move sample tap to make lid removal easier. Sample tap should not drain in the well. Re-landscape so that water is not contained around well 		
Well 5	<ul style="list-style-type: none"> Seal cable glands Seal pipework penetrations through wall Check casing seal with chamber floor and seal if required Seal chamber floor to prevent inundation 	<ul style="list-style-type: none"> Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected 		
All wells	<ul style="list-style-type: none"> Install a sump pump (with a level sensor that alarms to an operator) Install a downward facing air vent 0.5 m 	<ul style="list-style-type: none"> We consider a single check valve at the headworks meets the backflow prevention requirements. This 	<ul style="list-style-type: none"> For the as-built records, confirm backflow prevention on the well pump has been installed. 	<ul style="list-style-type: none"> A sanitary inspection of the well should take place on a regular basis Establish routine testing and verification

First Priority	Second Priority	Third Priority	Ongoing
above 100 year flood level (unless the well is not located in a flood prone area)	<p>should be confirmed with the DWA.</p> <ul style="list-style-type: none"> ■ Grout seals must be retrofitted. <p>Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well.</p> <ul style="list-style-type: none"> ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. 		of backflow prevention device

7 Conclusion

The information reviewed and the inspections carried out indicate that none of the Denton wells meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Denton
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	All Denton Wells draw from Aquifer 3. Leaky (semi)-confined.
Surface Water Ways, Drains, etc	Stormwater detention in adjacent park.
4. Photo Record and Comments	
Photo	Comment
	Pump station is within fenced area

	<p>Double skinned and banded diesel storage tank inside the pump station</p>		
	<p>Pump room (underground) Water leaking through the ceiling was noticed</p>		
	<p>Pump room access not sealed. Source of leaking into the pump room. This should be sealed.</p>		
<p>5. Risks from Surrounding Environment</p>			
<p>a) Within the site:</p>			
<p>Diesel/Chemical Storage</p>	<p>Yes</p>	<p><input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground</p>	<p>Fuel lines <input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground</p>
<p>Access by Animals</p>	<p>Fenced site and locked building</p>		

Protection from vandalism, signs of vandalism	As above, no signs of vandalism
Other Activities	N/A
b) Immediate Neighbouring Land Use:	
Current Neighbouring Land Use	Park, train track adjacent
Significant Changes Since Previous Inspection	None identified
Zoning of Neighbouring Land	Open Space Metropolitan Facilities Zone
c) Wider Environment:	
Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	A number of stormwater consents and other bores within 400m Sewer nearby
Risk of flood inundation	Some of the site is below the 50 year flood level and so there is the potential for flooding
Potential sources of young water	No sources specific to the pumping station identified. See well assessments.
General land use in catchment (LLUR)	As below
Contaminated sites (HAIL status)	At well and pump station address (442 Main South Road): ACT 27077 A10 - Persistent pesticide bulk storage or use Persistent pesticide bulk storage or use including sports turfs, market gardens, orchards, glass houses or spray sheds ACT 3417 A17 - Storage tanks or drums for fuel, chemicals or liquid waste ACT 4313 B2 - Electrical transformers ACT 27067 A10 - Persistent pesticide bulk storage or use
Status and condition of surrounding wells (within 400 m radius)	Multiple wells
Landfill	None identified
6. Actions Arising	

Identify issues and rank them in terms of whether they require:	
First Priority	Refer well assessments
Second Priority	Refer well assessments
Third Priority	Refer well assessments
Ongoing	Refer well assessments

Well Head Protection Assessment – Individual Well Heads

Denton Well 1


1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Denton Well 1
ECan Well No.	M 35/3547
Aquifer No.	3
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Depth (mbgl)	96.3 (casing depth unknown)
Casing Diameter (mm)	250
Screen Interval (mbgl)	No Screen Data
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	11 June 1982
Control System/Alarms	Pump failure

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Well chamber is located adjacent to the pump station
	Well chamber is within a fenced area
	Pipework is in reasonable condition. Chamber was reasonably dry at the time of inspection.
	Sump installed with no sump pump. Some water in sump.



Some corrosion on the inside of the chamber. The source is unknown

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Could not be checked as chamber entry was not possible
	Pipework	From above the pipework looks to be sealed with sidewall of chamber. Cannot see if it is sealed at the bottom.
	Well casing	Could not be seen in person or with a camera
Any history of E. coli transgressions? Historical and current levels of total coliforms?		20 distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). The source is unknown and may not be this well. Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No

	Some of the site is below the 50 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level	Not installed
Type and condition of borehead pipework (above ground)	Steel in good condition, some surface rust
Raw Water sample port?	Yes, outside chamber
Concrete apron sloped to drain away from well?	No
100mm step above ground level?	Not on one side of the well chamber
Signs of ponding?	Not at time of inspection
Access by animals	Fenced site with only 4m on one side
Protection from vandalism, signs of vandalism	Locked areas with barbed wire fence. No signs of vandalism
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Could not be viewed
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown
Does the well comply with NZS:4411?	No

Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No	
If no, what non-compliances require agreement with the DWA?	Non-Compliance	Agreed with DWA? (see Appendix D)
	Below ground installation	Agreed ok
	No 5m fenced (4m fence)	Agreed ok
	Casing not grout sealed	To be agreed
	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required
	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Railway track 8m away. A spill could enter the wellhead chamber. Roads and sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	Water only in sump at the time of inspection	
Is there a sump pump?	No sump pump but there is a sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		

First Priority	<ul style="list-style-type: none"> ■ Check seal between chamber floor and well casing and seal as required ■ Check pipework penetrations through chamber sidewall and seal if required ■ Check cable entry points and seal if required ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device


Denton Well 2

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Denton Well 2
ECan Well No.	M35/1866
Aquifer No.	3
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl) (assume top of screen)	90.23
Casing Diameter (mm)	250
Screen Interval (mbgl)	90.23 – 96.28
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	14 June 1982
Control System/Alarms	Pump failure

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Well chamber lid flush with the ground and covered in bark and debris
	Well chamber is located on the edge of a park, close to the road
	Bark can be seen in the bottom of the chamber

	<p>Sealing on side entry to chamber has deteriorated</p>
	<p>Casing appears to be sealed to floor from photos</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

<p>a) Water Ingress:</p>		
<p>Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)</p>	<p>Cabling</p>	<p>Sealed</p>
	<p>Pipework</p>	<p>Side entry to chamber not sealed</p>
	<p>Well casing</p>	<p>Sealed</p>
<p>Any history of E. coli transgressions?</p>		<p>20 distribution system E. coli transgressions have been recorded in the data received (dating back to</p>

Historical and current levels of total coliforms?	2012-13 FY). The source is unknown and may not be this well. Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No Some of the site is below the 50 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level	Not installed
Type and condition of borehead pipework (above ground)	Steel, good condition
Raw Water sample port?	Yes, outside of chamber in a cabinet
Concrete apron sloped to drain away from well?	No
100mm step above ground level?	No
Signs of ponding?	Not close to the well at the time of inspection. Ponding on the road further downhill
Access by animals	No fence around well, in a residential area where cats and dogs would be common but livestock would be less likely
Protection from vandalism, signs of vandalism	Padlock on lid. No signs of vandalism
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Steel, some rust

Bore casing grouted (see the definitions section of the DWSNZ, "bore head protection" and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown														
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown														
Does the well comply with NZS:4411?	No														
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No														
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No sump pump</td> <td>Sump pump required</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No sump pump	Sump pump required	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)													
	Below ground installation	Agreed ok													
	No 5m fenced	Agreed ok													
	Casing not grout sealed	To be agreed													
	Single check valve in headworks	To be agreed													
	No sump pump	Sump pump required													
No air vent	Air vent required														
c) Contamination Sources:															
Does the WSP address contaminant sources and contaminant migration pathways?	Not received														
Any localised well specific sources of contamination?	Adjacent sidewalk and road														
d) Below Ground Chambers:															
Water level of chamber	None at time of visit														
Is there a sump pump?	No sump pump but there is a sump														
Are there duty/standby sump pumps?	No														
Sump pump testing, include date a method	N/A														
Sump pump operation method including start level	N/A														
Sump pump and/or level alarms	N/A														

Does the bore head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal side entry to chamber ■ Replace chamber lid so the chamber is protected from rainfall and runoff ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Denton Well 3

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Denton Well 3
ECan Well No.	M 35/1865
Aquifer No.	3
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl) (assume top of screen)	94.3
Casing Diameter (mm)	250
Screen Interval (mbgl)	94.3 – 102.4
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	February 1976
Control System/Alarms	Pump failure

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Well is located in a small park, adjacent to a car park, surrounded by trash
	Sample tap is located in chamber



Graffiti in chamber implying that vandals have gained access




Trash and debris in the bottom of the chamber



Rebar showing through the chamber wall

	<p>Cable penetrations through wall are sealed</p>
	<p>Photo received 19 January 2018 following a clean-up of the well. The well chamber now appears clear of rubbish and debris, and the cable entry points into the well head appear to be sealed now.</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection		
a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Not sealed – no glands, open holes at time of inspection. Have since received photos from CCC showing the cable entry points have been sealed.
	Pipework	Rebar showing through seal point. Can't be sure that penetration is sealed.
	Well casing	Could not access, not clear that there is a concrete floor, may be just soil
Any history of E. coli transgressions? Historical and current levels of total coliforms?		20 distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). The source is unknown and may not be this well. Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No Some of the site is below the 50 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Bellows have partially collapsed inwards likely due to back pressure
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		N/A
Signs of ponding?		Not at time of inspection. Well is at a low point so ponding is possible
Access by animals		No fence around well, in a residential area where cats and dogs would be common but livestock would be less likely
Protection from vandalism, signs of vandalism		Padlock on lid, no lid alarm. Graffiti in chamber implying vandal access has occurred in the past
b) Drilling Standard:		

Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.														
If not, has this been agreed with the DWA?	N/A														
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached														
Bore casing type and condition (see NZS:4411 2.4.2)	Steel, minor surface rust														
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown														
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown														
Does the well comply with NZS:4411?	No														
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No														
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Fence or other device to prevent vandalism is required</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No sump pump</td> <td>Sump pump required</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Fence or other device to prevent vandalism is required	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No sump pump	Sump pump required	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)													
	Below ground installation	Agreed ok													
	No 5m fenced	Fence or other device to prevent vandalism is required													
	Casing not grout sealed	To be agreed													
	Single check valve in headworks	To be agreed													
	No sump pump	Sump pump required													
No air vent	Air vent required														
c) Contamination Sources:															

Does the WSP address contaminant sources and contaminant migration pathways?	Not received
Any localised well specific sources of contamination?	Adjacent footpath and road. Lots of trash in the area and in the chamber
d) Below Ground Chambers:	
Water level of chamber	None present at time of visit
Is there a sump pump?	No pump or sump
Are there duty/standby sump pumps?	No
Sump pump testing, include date a method	N/A
Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the bore head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Install and seal cable glands ■ Check that pipe wall penetrations are sealed ■ Investigate bellows collapse and mitigate ■ Investigate source of graffiti and trash. Mitigate likelihood of vandal access ■ Seal chamber floor to prevent inundation from below. Ensure that casing is sealed to floor. ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a fence 5m away from well to minimise the likelihood of vandalism ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced

	<p>(i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well.</p> <ul style="list-style-type: none"> ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Denton Well 4

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Denton Well 4
ECan Well No.	M35/3546
Aquifer No.	3
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl) (assume top of screen)	89.75
Casing Diameter (mm)	300
Screen Interval (mbgl)	89.75 – 95.85
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	29 March 1982
Control System/Alarms	Pump failure

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	Well chamber within a partially fenced area, part of a residential community. Signs on ponding on footpath adjacent to well
	Pipework in reasonable condition
	Pipe penetrations through wall are not sealed
	Casing sealed to chamber floor




Cable glands sealed



Sump without a sump pump installed

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection		
a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Sealed
	Pipework	Not sealed
	Well casing	Sealed
Any history of E. coli transgressions? Historical and current levels of total coliforms?	20 distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). The source is unknown and may not be this well. Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No Some of the site is below the 50 year flood level and so there is the potential for flooding	
Downward facing air vent 0.5m above 100 year flood level	Air vent not installed above floor level	
Type and condition of borehead pipework (above ground)	Good	
Raw Water sample port?	Yes, on lid which makes lid removal difficult	
Concrete apron sloped to drain away from well?	No	
100mm step above ground level?	Yes	
Signs of ponding?	Yes, on path nearby. Landscaping also may keep water contained	
Access by animals	Not fully fenced, in a residential area where cats and dogs would be common but livestock would be less likely	
Protection from vandalism, signs of vandalism	Padlock on lid. No signs of vandalism	
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The	

	well pump may also have a check valve but this is not known.														
If not, has this been agreed with the DWA?	N/A														
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached														
Bore casing type and condition (see NZS:4411 2.4.2)	Steel, good condition														
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown														
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown														
Does the well comply with NZS:4411?	No														
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No														
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No sump pump</td> <td>Sump pump required</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No sump pump	Sump pump required	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)													
	Below ground installation	Agreed ok													
	No 5m fenced	Agreed ok													
	Casing not grout sealed	To be agreed													
	Single check valve in headworks	To be agreed													
	No sump pump	Sump pump required													
No air vent	Air vent required														
c) Contamination Sources:															
Does the WSP address contaminant sources and contaminant migration pathways?	Not received														
Any localised well specific sources of contamination?	Adjacent to footpath and road Roads and sewers in close proximity.														
d) Below Ground Chambers:															


Water level of chamber	None present at time of visit
Is there a sump pump?	No pump or sump
Are there duty/standby sump pumps?	No
Sump pump testing, include date a method	N/A
Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the bore head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal pipe penetration through chamber wall ■ Seal casing and chamber floor ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Move sample tap to make lid removal easier. Sample tap should not drain in the well. ■ Re-landscape so that water is not contained around well ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis

	<ul style="list-style-type: none">■ Establish routine testing and verification of backflow prevention device
--	--

Denton Well 5

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Denton Well 5
ECan Well No.	M35/1864
Aquifer No.	3
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl) (assume top of screen)	63.4
Casing Diameter (mm)	254
Screen Interval (mbgl)	63.4 – 72.8
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	1973
Control System/Alarms	Pump failure

Type of Pump	Submersible
Frequency of Pump Use	Generally runs about once a day
4. Photo Record and Comments	
Photo	Comment
	
	Sample tap drains into chamber. Some chamber corrosion behind sample tap.
	Pipe penetration through chamber wall not sealed. Dirt floor, not sealed
	Cable penetration through chamber wall not sealed



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Glands not sealed
	Pipework	Not sealed
	Well casing	Could not be viewed in person or with a camera
Any history of E. coli transgressions? Historical and current levels of total coliforms?	20 distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). The source is unknown and may not be this well. Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No Some of the site is below the 50 year flood level and so there is the potential for flooding	
Downward facing air vent 0.5m above 100 year flood level	Not installed	
Type and condition of borehead pipework (above ground)	Good	
Raw Water sample port?	Yes, in chamber	
Concrete apron sloped to drain away from well?	No	
100mm step above ground level?	N/A	

Signs of ponding?	Not at time of inspection												
Access by animals	Not fenced												
Protection from vandalism, signs of vandalism	Padlock on lid. No signs of vandalism												
b) Drilling Standard:													
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.												
If not, has this been agreed with the DWA?	N/A												
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached												
Bore casing type and condition (see NZS:4411 2.4.2)	Could not be viewed												
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown												
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown												
Does the well comply with NZS:4411?	No												
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No												
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No sump pump</td> <td>Sump pump required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No sump pump	Sump pump required
Non-Compliance	Agreed with DWA? (see Appendix D)												
Below ground installation	Agreed ok												
No 5m fenced	Agreed ok												
Casing not grout sealed	To be agreed												
Single check valve in headworks	To be agreed												
No sump pump	Sump pump required												

	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Adjacent to rail line and arterial road Roads and sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	None present at time of visit	
Is there a sump pump?	No pump or sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the bore head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Seal cable glands ■ Seal pipework penetrations through wall ■ Check casing seal with chamber floor and seal if required ■ Seal chamber floor to prevent inundation ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. 	

	<ul style="list-style-type: none"> ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps






Figure 1: Summary of wells and consents within 400m of Denton Wells

Table 3: Summary of consents within 400m of Denton Wells

Denton Well Sites

<i>Well Number:</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
M35/3547	<i>Type</i>		
	Discharge to Water	CRC101944	Issued - Active
	Discharge to Water	CRC990260	Terminated - Surrendered
M35/1866	Discharge to Land	CRC960782	Issued - Active
	<i>Type</i>		
M35/3547	Discharge to Land	CRC122386	Terminated - Replaced

Discharge to Land	CRC121736	Terminated - Replaced	Stormwater Industrial
Discharge to Land	CRC960782	Issued - Active	Stormwater Residential
Discharge to Water	CRC990260	Terminated - Surrendered	Stormwater Residential

Well Number: M35/1865

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Land	CRC960782	Issued - Active	Stormwater Residential
Discharge to Land	CRC952722	Terminated - Replaced	Stormwater Residential
Discharge to Water	CRC990260	Terminated - Surrendered	Stormwater Residential

Well Number: M35/3546

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Land	CRC960782	Issued - Active	Stormwater Residential
Discharge to Land	CRC952722	Terminated - Replaced	Stormwater Residential
Discharge to Water	CRC990260	Terminated - Surrendered	Stormwater Residential

Well Number: M35/1864

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Land	CRC110523	Issued - Active	Stormwater Industrial
Discharge to Land	CRC952722	Terminated - Replaced	Stormwater Residential
Discharge to Land	CRC101848	Issued - Active	Stormwater Industrial
Discharge to Land	CRC952110	Application Returned	Stormwater Residential

Appendix C

Bore Logs



Bore or Well No	M35/3547	 Environment Canterbury Regional Council <i>Kaunihera Taiao ki Waitaha</i>	
Well Name	442 Main South Rd		
Owner	Christchurch City Council		
Well Number	M35/3547	File Number	CO6C/03077
Owner	Christchurch City Council	Well Status	Active (exist, present)
Street/Road	442 Main South Rd	NZTM Grid Reference	BX23:61181-78980
Locality	HORNBY	NZTM X and Y	1561181 - 5178980
Location Description	Located on the north side of the Reservoir, by the access road	Location Accuracy	2 - 15m
CWMS Zone	Christchurch - West Melton	Use	Small Community Supply,
Groundwater Allocation Zone	Christchurch/West Melton	Water Level Monitoring	--
Depth	96.30m	Water Level Count	0
Diameter	250mm	Initial Water Level	9.00m below MP
Measuring Point Description		Highest Water Level	
Measuring Point Elevation	31.40m above MSL (Lytelton 1937)	Lowest Water Level	
Elevation Accuracy	< 2.5 m	First reading	
Ground Level	0.00m above MP	Last reading	
Strata Layers	17	Calc Min 95%	15.50m below MP
Aquifer Name	Burwood Gravel	Aquifer Tests	0
Aquifer Type	Non-Flowing Artesian	Yield Drawdown Tests	1
Drill Date	11 Jun 1982	Max Tested Yield	28 l/s
Driller	A M Bisley & Co	Drawdown at Max Tested Yield	6 m
Drilling Method	Cable Tool	Specific Capacity	5.07 l/s/m
Casing Material		Last Updated	22 Dec 2015
Pump Type	Unknown	Last Field Check	30 Jan 2008
Water Use Data	Yes		



No screen data for this well

Step Tests

Step Test Date	Step	Yield	Yield GPM	DrawDown	Step Duration
11 Jun 1982	1	28.4	374.8284	5.6	0


Comments


Comment Date	Comment
	WELL NO.2 = ONE OF 5 WELLS PUMPING TO DENTON PARK RESERVOIR Grid ref amended from M35:710-406 to M35:7105-4055, more accurate.
	FROM OLD CWS DB Located in Denton Park, Main South Rd near Carmen Rd & Shands Rd. Located on the west side of the park, at the Kathleen Crescent entrance, on the south side of the path. Is in the garden covered by a green round lid (padlocked).
15 Oct 1998	West pressure zone.
08 Feb 2000	FROM OLD CWS DB Surrounding area a sports ground, with several clubrooms. Park borders residential properties, railway line, a main road & a shopping centre on east boundary. GRID REF: M35:71045-40543.
03 Dec 2007	Screen length 9.0m, information form CCC
06 Dec 2007	FROM OLD CWS DB CCC Notation: Denton Stn Well-01=M35/3547
01 Feb 2008	From information supplied form CCC this well is Denton Well-01 not Well-02
01 Feb 2008	Gridref changed from: M35:7105-4055
01 Feb 2008	CCC PUB SUPPLY,KATHLEEN CRES,HORNBY PREV. PCC,ONE OF 5 DEEP BORES SUPPLING DENTON PARK PUMP STATION Updated Squalarc gridreference from Wells database 1-May-08
04 Sep 2009	Gridref changed from: M35:71177-40593 photo added
06 May 2010	MfE source code added


Bore Log

Borelog for well M35/3547

Grid Reference (NZTM): 1561181 mE, 5178980 mN
 Location Accuracy: 2 - 15m
 Ground Level Altitude: 31.4 m +MSD Accuracy: < 2.5 m
 Driller: A M Bisley & Co
 Drill Method: Cable Tool
 Borelog Depth: 100.6 m Drill Date: 11-Jun-1982







A. M. BISLEY & CO. LTD

WATER SUPPLY DIVISION

Denton Well 2

HAMILTON and CHRISTCHURCH

WELL LOG

June 14, 1982

CLARITY PRESS LTD

NAME: Paparua County Council
Kathleen Crescent

LOCATION:

DIA. OF WELL: 250mm

STATIC WATER LEVEL: 5metres

CASING: 90.23 metres

SHOE: 1 rolled

TOTAL DEPTH: 96.28metres drilled to 100.63metres

SCREEN: 6.10metres 3/8 Johnscreen 250mm T.S. 80 slot

LEADER: 1.21metres rolled

PACKER:

PUMPING TEST: 374gpm at 5.60m D.D. or 28.42l/sec at 5.60 M.D.D.
5.07l/sec/metre

SPECIFIC CAPACITY: 66.78gals/m/D.D.

LITHOLOGY

.00-0.10 metres	Top Soil
0.10-10.20 metres	Sandy med grey gravels
10.20-18.50 metres	Stained med grey gravel and clay trace
18.50-24.00 metres	Med grey gravels and sand
24.00-41.50 metres	St. grey gravels and clay
41.50-44.40 metres	Small brown gravels and sand
44.40-45.00 metres	Cemented gravels
45.00-48.80 metres	Grey clay (solid)
48.80-49.50 metres	Sandy med grey gravels
49.50-73.90 metres	Med brown gravels
73.90-74.30 metres	Clay bound brown gravel
74.30-79.40 metres	Med sandy brown gravels
79.40-79.60 metres	Clay bound gravel
79.60-86.30 metres	Med sandy brown gravels (some clay trace)
86.30-88.38 metres	Peat
88.38-97.13 metres	Dark stained brown gravels slight clay
97.13-100.63metres	Sandy brown gravels (tight)

RIG No. 3 *total 90-96*

DRILLER P. Sinclair

WATER SUPPLY DIVISION

HAMILTON and CHRISTCHURCH

WELL LOG

March 29 1982

CLARITY PRESS LTD

NAME: Paparua County Council

LOCATION: Main South Road Opp. Denton Park

DIA. OF WELL: 300mm

STATIC WATER LEVEL:

CASING: 89.75m Spiral

SHOE: 1

TOTAL DEPTH: 95.85m

SCREEN: 250mm Johnson St. St. 80 slots length 6.10m

LEADER: 0.60m 290mm O.D. Rolled Pipe.

PACKER: Screened between 65.4-71.5m
G.W.L. 10.64m Pumped 19.1l/sec DR.D. 13.83m

PUMPING TEST: 27.38l/sec

SPECIFIC CAPACITY: 3.78l/sec/m

DRAWDOWN: 7.25m

LITHOLOGY

0.3-3.3 Filling	41.3-49.5 Blue Clay - Peat
0.3-3.9 Silt	49.5-51.8 Tight Blue Gravel - Sand - Some Blue Clay
3.9-11.7 Grey Gravel Sand	51.8-57.8 Tight Blue Clay-Sandy Brown Gravel
11.7-15.6 Black and Brown stained gravel and sand	57.8-61.1 Brown Gravel - Sand
15.6-22.1 Grey Gravel - Sand	61.1-61.3 Brown Gravel - Yellow Clay
22.1-24.8 Grey-Brown Gravel- Sand some Yellow Clay	61.3-71.5 Sandy Brown Gravel some stained gravel
24.8-26.5 Tight Sandy Grey-Brown Gravel	71.5-72.6 Tight Sandy Brown Gravel
26.5-28.9 Grey-Brown Gravel-Sand	72.6-74.1 Brown Stained Gravel - Sand - Yellow Clay
28.9-29.6 Grey- Brown Gravel - Yellow Clay - Sand	74.1-77.2 Tight Sandy Brown stained gravel
29.6-40.5 Grey-Brown Gravel - Sand	77.2-82.8 Tight Sandy Brown stained gravel some Yellow Clay
40.5-41.3 Blue Clay - Blue Gravel	82.8-82.9 Yellow Clay

RIG No. 4

DRILLER B. Lagendyk

PTD

UNIT 22 - C.P. 11 & 12

100' - 100' - 100'

100' - 100' - 100'

100' - 100' - 100'

- 82.9-85.4 Tight Sandy Grey-Brown stained Gravel
- 85.4-86.6 Sandy Brown Stained Gravel
- 86.6-87.5 Hard Yellow Clay
- 87.5-87.8 Hard Gravel-Sand-Clay
- 87.8-95.8 Sandy Brown Stained Gravel

100' - 100' - 100'

Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Muruges	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Kainga Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Hydrogeological Settling	2
4	Risks	2
5	Status / Compliance with DWSNZ Criterion 2	3
6	Recommendations	3
7	Conclusion	4

Appendices

Appendix B

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the wells supplying Kainga Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as "secure", a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used in this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Kainga Pumping Station (Brooklands/Kainga Pressure Zone)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Original bore log as included in Appendix C
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Kainga Pumping Station is supplied by one well; Kainga Well 1. Kainga Pumping Station is one of the two pump stations that service the Brooklands/Kainga pressure zone. Table 2-1 summarises key information about the five wells.

Table 2-1: Kainga Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 1	M 35/6213	87.0-92.0	2

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from

both alpine river and rainfall to land surface recharge. The wells at Kainga Pumping Station are screened within moderately-deep (Aquifer 2 – Linwood Gravel Aquifer) leaky (semi)-confined aquifers within the Christchurch Artesian Aquifer System.

4 Well Inspections

An inspection of the well was carried out on 7 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Andrew Batchelor (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Kainga Well 1 does not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 6-1 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 6-1: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 1	<ul style="list-style-type: none"> ■ Seal casing at ground of well shed ■ Regrade the land around the well-house to promote draining away from the well. ■ Regrade the concrete floor within the well-house to promote draining away from the casing ■ Tighten the connection on the cooling tube as this is likely causing a leak in the well-shed ■ Install backflow prevention device ■ Install a downward facing air vent 0.5 m 	<ul style="list-style-type: none"> ■ Pipe and casing tidy ups including removing rust and peeling paint and resealing ■ Grout seals must be retrofitted. <p>Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well.</p> <ul style="list-style-type: none"> ■ Ensure that the WSP addresses 	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed. 	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

	First Priority	Second Priority	Third Priority	Ongoing
	above 100 year flood level (unless the well is not located in a flood prone area)	contaminant sources and contaminant migration pathways		

7 Conclusion

The information reviewed and the inspections carried out indicate that Kainga Well 1 does not meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix B

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Kainga
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	Draws from Aquifer 2 (leaky (semi)-confined)
Surface Water Ways, Drains, etc	Unnamed drain adjacent to pumping station building and close to the well, Waimakariri River nearby
4. Photo Record and Comments	
Photo	Comment



Step up into the pump station for flood protection

Note that the site is above the 100 year flood level and so flooding potential is low



Flow meter in underground chamber with stagnant water and a sump pump.

About 50mm of water at the time of inspection. There has been up to 250-300mm in the past.

This line is under pressure so entry of stagnant water from the chamber into the pipe is unlikely.

Pipe is rusty.

Chamber does not have cable seals.



As above



Above ground diesel storage tank adjacent to well shed



Diesel pipework in pump station is located above a trench for collection of leaks

	Stormwater collection drain with stagnant water			
5. Risks from Surrounding Environment				
a) Within the site:				
Diesel/Chemical Storage	2m from well	<input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground	Fuel lines	<input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground
Access by Animals	Locked site but low fence at road frontage Pump station door has an alarm			
Protection from vandalism, signs of vandalism	As above, no signs of vandalism			
Other Activities	N/A			
b) Immediate Neighbouring Land Use:				
Current Neighbouring Land Use	Residential/rural			
Significant Changes Since Previous Inspection	None identified			
Zoning of Neighbouring Land	Residential Small Settlement Zone			
c) Wider Environment:				
Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	Agricultural area, stormwater discharges in the area, drain within pump station site Sewer nearby			
Risk of flood inundation	Low risk as the site is above the 100 year flood level			
Potential sources of young water	Stormwater collection creek with stagnant drain adjacent to pump station			
General land use in catchment (LLUR)	As below			
Contaminated sites (HAIL status)	None identified at the address of the well and pump station			


Status and condition of surrounding wells (within 400 m radius)	Multiple wells
Landfill	None identified
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	Refer well assessments
Second Priority	Refer well assessments
Third Priority	Refer well assessments
Ongoing	Refer well assessments

Well Head Protection Assessment – Individual Well Heads

Kainga Well 1

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Kainga Well 1
ECan Well No.	M 35/6213
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Above
Casing Depth (mbgl)	87.0 (assume top of screen)
Casing Diameter (mm)	304.8
Screen Interval (mbgl)	87.0-92.0
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	26 October 1989
Control System/Alarms	Pump failure alarm

Type of Pump	Submersible
Frequency of Pump Use	Continuous
4. Photo Record and Comments	
Photo	Comment
	Concrete floor is flat and does not slope away from the casing. Water can be seen on the floor surrounding the casing
	Well casing not sealed to concrete floor
5. Diagram with Well Measurements	



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Good seal
	Pipework	Good seal
	Well casing	Not sealed – 1-2mm gap around casing
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No – casing to floor not sealed Site is above the 100 year flood level and so flooding potential is low
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Some rust, peeling paint
Raw Water sample port?		Yes, on opposite side of building and on the wellhead
Concrete apron sloped to drain away from well?		No, floor flat and not sloped away from wellhead
100mm step above ground level?		Yes, ground has been dug away and directed to drain
Signs of ponding?		Yes, inside the shed. The floor is not sloped away from wellhead
Access by animals		Fence is only 3m to west and 3.5m to south

Protection from vandalism, signs of vandalism	Fence with a low gate that could be climbed. No signs of vandalism										
b) Drilling Standard:											
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	None seen – there may be one on the pump but this could not be confirmed										
If not, has this been agreed with the DWA?	Unknown										
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached										
Bore casing type and condition (see NZS:4411 2.4.2)	Minor rust on casing. Leakage from direct supply to generator, pooling on floor.										
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown										
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown										
Does the well comply with NZS:4411?	No										
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No										
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>No 5m fence to prevent animal access</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>No confirmed backflow prevention device</td> <td>To be agreed</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	No 5m fence to prevent animal access	Agreed ok	Casing not grout sealed	To be agreed	No confirmed backflow prevention device	To be agreed	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)									
	No 5m fence to prevent animal access	Agreed ok									
	Casing not grout sealed	To be agreed									
	No confirmed backflow prevention device	To be agreed									
No air vent	Air vent required										
c) Contamination Sources:											
Does the WSP address contaminant sources and contaminant migration pathways?	Not received										
Any localised well specific sources of contamination?	Diesel storage tank adjacent to well Roads and sewers in close proximity										

d) Below Ground Chambers:	
Water level of chamber	N/A
Is there a sump pump?	N/A
Are there duty/standby sump pumps?	N/A
Sump pump testing, include date a method	N/A
Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the well head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal casing and concrete in well shed ■ Regrade the land around the well-house to promote draining away from the well. ■ Regrade the concrete floor within the well-house to promote draining away from the casing ■ Tighten the connection on the cooling tube as this is likely causing a leak in the well-shed ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Pipe and casing tidy ups including removing rust and peeling paint and resealing ■ Install backflow prevention device ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps



Appendix C

Bore Logs



McMILLAN WATER WELLS LTD

PH. 242-571 PH. 242-530 A.H. Fax (03) 242 431

WELL OWNER. Waimairi District Council
 ADDRESS. Private Bag, FENDALTON
 LOCALITY. Kaianga
 DRILLER. C Weaver
 DRILLING DATE. Completed 26 October 1989
 GRID REFERENCE. 824546



DEPTH FROM		STATIC	DESCRIPTION
SURFACE (m)		WATER	
TOP	BOTTOM	LEVEL.	
.000	.400		Topsoil
.400	2.650		Brown sand
2.650	3.100		Brown sand and small brown gravel
3.100	5.100		Very sandy small brown gravel
5.100	11.600		Sandy blue/grey pea gravel
11.600	12.100		Small/med sandy blue/grey gravel, trace blue silt
12.100	16.800		Small very sandy blue/grey gravel, trace shells
16.800	17.400		Very sandy grey gravel, shells and grey organic clay
17.400	22.800		Small/med grey sandy clay
22.800	26.350		Med grey/brown sandy gravel, trace brown clay
26.350	26.600		Brown sandy clay
26.600	35.200		Med grey/brown sandy gravel
35.200	35.450		Brown sandy gravel and brown clay
35.450	37.200		Small brown sandy gravel
37.200	42.950		Brown sand, trace very small brown gravel
42.950	48.100		Brown sand, rare brown pebbles
48.100	56.550		Med/some large grey/brown sandy gravel

CASING DIAMETER _____
 WELL DEPTH _____
 FINAL WATER LEVEL _____
 SCREEN TYPE _____
 SLOT SIZE _____
 SCREEN LENGTH _____
 LEADER & DIAMETER _____
 SET AT _____
 DRAWDOWN _____
 AFTER _____ HOURS PUMPING AT _____
 DRAWDOWN _____
 AFTER _____ HOURS PUMPING AT _____
 DRAWDOWN _____
 AFTER _____ HOURS PUMPING AT _____

REMARKS (INCLUDE NOTES ON CORES AND
 SAMPLES TAKEN)

McMILLAN WATER WELLS LTD

PH. 242-571 PH. 242-530 A.H. FAX (03) 242 431

WELL OWNER. Waimairi District Council
 ADDRESS. Private Bag, FENDALTON
 LOCALITY. Kaianga
 DRILLER. C Weaver
 DRILLING DATE. Completed 26 October 1989
 GRID REFERENCE. 824546




DEPTH FROM SURFACE (m)	STATIC WATER LEVEL.	DESCRIPTION
TOP	BOTTOM	
56.550	57.000	Med brown, some grey sandy gravel, trace grey clay
57.000	57.550	Med grey sandy gravel with grey clay (tight)
57.550	59.050	Grey sandy clay
59.050	61.500	Very fine grey clayey sand, rare grey and brown pebbles
61.500	62.000	Grey sandy organic clay
62.000	62.750	Peat and grey sand
62.750	63.300	Grey sandy gravel, trace grey clay and peat (tight)
		Patches claybound
63.300	63.500	Brown and grey claybound gravel (tight)
63.500	64.200	Brown stained sandy gravel with brown clay
64.200	65.800	Med grey/brown sandy gravel, some black stained
65.800	66.800	Med/some large grey/brown sandy gravel, trace brown claybound gravel
66.800	67.900	Med grey/brown sandy gravel, trace brown clay
67.900	68.500	Med grey/brown sandy gravel
68.500	70.300	Very sandy med grey/brown gravel
70.300	71.300	Brown/grey clay, brown sand, trace brown gravel

CASING DIAMETER _____
 WELL DEPTH _____
 FINAL WATER LEVEL _____
 SCREEN TYPE _____
 SLOT SIZE _____
 SCREEN LENGTH _____
 LEADER & DIAMETER _____
 SET AT _____
 DRAWDOWN _____
 AFTER _____ HOURS PUMPING AT _____
 DRAWDOWN _____
 AFTER _____ HOURS PUMPING AT _____
 DRAWDOWN _____
 AFTER _____ HOURS PUMPING AT _____

REMARKS (INCLUDE NOTES ON CORES AND SAMPLES TAKEN)

 Samples taken at 61.500 - 62.000 metres
 and at 62.000 - 62.750 metres.

SCREEN.



DRIVE RING, 290mm OD

LEADER. 260mm ID
275mm OD

BLANK. 260mm ID
275mm OD

JOHNSON STAINLESS
80 SLOT 265mm ID

SURESCREEN STAINLESS
80 SLOT. 265mm ID

DRIVE SHOE. 290mm OD.

Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Mairehau Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace/ Mike Thorley	Template for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Hydrogeological Settling	2
4	Risks	2
5	Status / Compliance with DWSNZ Criterion 2	3
6	Recommendations	3
7	Conclusion	4

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the well that supplies Mairehau Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as "secure", a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used in this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Original bore log as included in Appendix C
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)
- Note that the previous inspection report was not received

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Mairehau Pumping Station is supplied by one well; Mairehau Well 1. The well and pump station are located within Burwood Hospital. Table 2-1 summarises key information about the well.

Table 2-1: Mairehau Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 1	M 35/5830	147.8-153.8	4

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from both alpine river and rainfall to land surface recharge. The well at Mairehau Pumping Station is screened

within the deep (Aquifer 4 – Wainoni Gravel Aquifer) leaky (semi)-confined aquifer within the Christchurch Artesian Aquifer System.

4 Well Inspections

An inspection of the well was carried out on 7 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Andrew Batchelor (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Mairehau Well 1 do not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 6-1 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 6-1: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 1	<ul style="list-style-type: none"> ■ Seal chamber floor to prevent inundation of chamber from groundwater from the local near-surface groundwater ■ Seal pipework at chamber sidewall ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced 		<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

First Priority	Second Priority	Third Priority	Ongoing
		<p>(i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well.</p> <ul style="list-style-type: none"> ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. 	

7 Conclusion

The information reviewed and the inspections carried out indicate that Mairehau Well 1 does not meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Mairehau
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	8 February 2013
2. Modifications since Previous Assessment	
Upgrade of VSD and other electrics including a flowmeter. Occurred in ~2010 so before previous inspection.	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	Draws from Aquifer 4 (leaky (semi)-confined)
Surface Water Ways, Drains, etc	Stormwater detention basins at Hospital, Travis Wetland ~500 m away
4. Photo Record and Comments	
Photo	Comment
	Reticulation pump room. Diesel generator is shown in the background.

	Above ground diesel storage tank outside the pump station		
	The pump station is located between two roads		
5. Risks from Surrounding Environment			
a) Within the site:			
Diesel/Chemical Storage	8 – 10 m from bore	<input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground	Fuel lines <input checked="" type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground
Access by Animals	Locked and alarmed building		
Protection from vandalism, signs of vandalism	As above, no signs of vandalism		
Other Activities	N/A		
b) Immediate Neighbouring Land Use:			
Current Neighbouring Land Use	Hospital		
Significant Changes Since Previous Inspection	None identified		
Zoning of Neighbouring Land	SHP		
c) Wider Environment:			
Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	Hospital, boiler, discharge of stormwater to ground There is an active stormwater discharge consent within 400m		

	Sewer nearby
Risk of flood inundation	Unknown – no flood level data was available
Potential sources of young water	No sources specific to the pumping station identified. See well assessments
General land use in catchment (LLUR)	As below
Contaminated sites (HAIL status)	Unknown
Status and condition of surrounding wells (within 400 m radius)	An unused well (probably shallower), close by Multiple wells within 400m
Landfill	None identified
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	Refer well assessments
Second Priority	Refer well assessments
Third Priority	Refer well assessments
Ongoing	Refer well assessments

Well Head Protection Assessment – Individual Well Heads

Mairehau Well 1

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Mairehau Well 1
ECan Well No.	M 35/5830
Aquifer No.	4
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	8 February 2013
2. Modifications since Previous Assessment	
Recently refurbished including a new bellow on the pipework	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	147.8 (assume top of screen)
Casing Diameter (mm)	305
Screen Interval (mbgl)	147.8-153.8
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	1988
Control System/Alarms	Alarm in pump station for no flow

Type of Pump	Surface pumped
Frequency of Pump Use	Generally runs about once a day in summer and less frequent in winter
4. Photo Record and Comments	
Photo	Comment
	The well is located adjacent to the pump station and on the side of the road
	



Pipework in reasonable condition



Surface rust on casing and pitting at the gravel level

Floor is gravel rather than concrete



Chamber floor not sealed




Chamber side wall may not be sealed




Old suction tank now disconnected



Old well nearby



5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	None
	Pipework	May not be sealed
	Well casing	No concrete seal
Any history of E. coli transgressions?		No E. coli transgressions recorded in the data received (dating back to 2012-13 FY).

Historical and current levels of total coliforms?	Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No, no concrete seal at the base of the chamber (gravel) No flood level data available
Downward facing air vent 0.5m above 100 year flood level	Not installed, artesian
Type and condition of borehead pipework (above ground)	Good condition
Raw Water sample port?	Yes, discharges in chamber
Concrete apron sloped to drain away from well?	No
100mm step above ground level?	Yes, chamber is 600mm above ground
Signs of ponding?	Not at time of inspection
Access by animals	No fence to prevent access, within hospital grounds where cats and dogs may be found but livestock would be less likely
Protection from vandalism, signs of vandalism	Lid locked with padlock, no signs of vandalism
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – in pump station. Each of the two pumps have a reflux valve. Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Casing has surface rust and pitting in the casing at the gravel level
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown

Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown														
Does the well comply with NZS:4411?	No														
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No														
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Check valve at pumping station</td> <td>To be agreed</td> </tr> <tr> <td>No sump pump</td> <td>Sump pump required</td> </tr> <tr> <td>No air vent (but artesian)</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	Check valve at pumping station	To be agreed	No sump pump	Sump pump required	No air vent (but artesian)	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)													
	Below ground installation	Agreed ok													
	No 5m fenced	Agreed ok													
	Casing not grout sealed	To be agreed													
	Check valve at pumping station	To be agreed													
	No sump pump	Sump pump required													
No air vent (but artesian)	Air vent required														
c) Contamination Sources:															
Does the WSP address contaminant sources and contaminant migration pathways?	Not received														
Any localised well specific sources of contamination?	<p>Diesel storage on the other side of the pump station (8 – 10m away).</p> <p>Boiler at hospital nearby.</p> <p>Close to road where spills are possible.</p> <p>Sewers in close proximity.</p>														
d) Below Ground Chambers:															
Water level of chamber	Dry at the time of inspection but sample tap discharges into the chamber														
Is there a sump pump?	No pump or sump														
Are there duty/standby sump pumps?	No														
Sump pump testing, include date a method	N/A														
Sump pump operation method including start level	N/A														

Sump pump and/or level alarms	N/A
Does the well head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Seal chamber floor to prevent inundation of chamber from groundwater from the local near-surface groundwater ■ Seal pipework at chamber sidewall ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps






Figure 1: Summary of wells and consents within 400m of Mairehau Well

Table 2: Summary of consents within 400m of Mairehau Well

Mairehau Well Site

Well Number: M35/5830

Type	Consent Number	Consent Status	Feature Type
Discharge to land	CRC063313	Terminated - Replaced	Stormwater Residential
Discharge to land	CRC137035	Issued - Active	Stormwater Industrial
Discharge to land	CRC030243	Terminated - Surrendered	Stormwater Residential

Appendix C

Bore Logs



Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Picton Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Hydrogeological Setting	3
4	Risks	3
5	Status / Compliance with DWSNZ Criterion 2	3
6	Recommendations	3
7	Conclusion	5

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the wells supplying Picton Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as "secure", a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used in this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Picton Pumping Station (Riccarton Pressure Zone)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Original bore logs as included in Appendix C
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Picton Pumping Station is supplied by three wells; Picton Wells 1 – 3. Each well feeds into a combined suction tank which then goes to the Pumping Station pump set. Table 2-1 summarises key information about the five wells.

Table 2-1: Picton Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 1	M 35/8897	118-126	4
Well 2	M 35/8896	118-126	4
Well 3	M 35/8898	52.5-60.5	2

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from both alpine river and rainfall to land surface recharge. The wells at Picton Pumping Station are screened within moderately-deep (Aquifer 2 – Linwood Gravel Aquifer) and deep (Aquifer 4 – Wainoni Gravel Aquifer) leaky (semi)-confined aquifers within the Christchurch Artesian Aquifer System.

4 Well Inspections

An inspections of each well was carried out on 7 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Andrew Batchelor (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Picton Wells 1 – 3 do not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 6-1 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 6-1: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 1	<ul style="list-style-type: none"> ■ Locate source of water in chamber and seal. The source is potentially the sample tap. ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	<ul style="list-style-type: none"> ■ Cut back vegetation covering edge of well chamber 		
Well 2	<ul style="list-style-type: none"> ■ Install a downward facing air vent 0.5 m above 100 year flood level 			

	First Priority	Second Priority	Third Priority	Ongoing
Well 3	<ul style="list-style-type: none"> Seal cable glands 			
All wells	<ul style="list-style-type: none"> Install a sump pump (with a level sensor that alarms to an operator) 	<ul style="list-style-type: none"> Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. Ensure that the WSP addresses contaminant sources and contaminant migration pathways Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. 		<ul style="list-style-type: none"> A sanitary inspection of the well should take place on a regular basis Establish routine testing and verification of backflow prevention device
General	<ul style="list-style-type: none"> Seal the cooling water line that is leaking on the diesel line. Fix any corrosion of the 			

	First Priority	Second Priority	Third Priority	Ongoing
	diesel line that has already been caused.			

7 Conclusion

The information reviewed and the inspections carried out indicate that none of the Picton wells meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Picton
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
New filter wheels recently installed to make opening and closing filter trains easier	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	Picton Wells 1 and 2 draw from Aquifer 4 (leaky (semi)-confined) Picton Well 3 draws from Aquifer 2 (leaky (semi)-confined)
Surface Water Ways, Drains, etc	Avon River tributaries
4. Photo Record and Comments	
Photo	Comment



Pump station is located within a park



Waterways designed for stormwater drainage are within the park



Pump room



Diesel storage tank within a bunded area



Diesel lines within bunded concrete channel with sump pump installed



Cooling water leaking on diesel line causing corrosion



Four filters installed

5. Risks from Surrounding Environment

a) Within the site:	
Diesel/Chemical Storage	In pump station <input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground Fuel lines <input checked="" type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground
Access by Animals	Locked building within a park. Filters are in a fenced area.
Protection from vandalism, signs of vandalism	As above, no signs of vandalism
Other Activities	N/A
b) Immediate Neighbouring Land Use:	
Current Neighbouring Land Use	Park
Significant Changes Since Previous Inspection	None identified
Zoning of Neighbouring Land	Could not be confirmed on CCC's Planning Map
c) Wider Environment:	
Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	Active consents for discharge of contaminated water and de-watering water within 400m Stormwater, diesel leak, animals Sewer nearby
Risk of flood inundation	Some of the site is below the 50 year flood level and so there is the potential for flooding
Potential sources of young water	No sources specific to the pumping station identified. See well assessments
General land use in catchment (LLUR)	As below
Contaminated sites (HAIL status)	None identified at the address of the wells
Status and condition of surrounding wells (within 400 m radius)	Multiple wells
Landfill	None identified
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	

First Priority	<ul style="list-style-type: none">Seal the cooling water line that is leaking on the diesel line. Fix any corrosion of the diesel line that has already been caused.
Second Priority	Refer well assessments
Third Priority	Refer well assessments
Ongoing	Refer well assessments


Well Head Protection Assessment – Individual Well Heads

Picton Well 1

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Picton Well 1
ECan Well No.	M 35/8897
Aquifer No.	4
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	118 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	118-126
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	9 March 2001
Control System/Alarms	Pump failure

Type of Pump	None, artesian
Frequency of Pump Use	Runs everyday
4. Photo Record and Comments	
Photo	Comment
	<p>Chamber is within a park and partially covered by vegetation</p>
	<p>Pipework has surface rust.</p> <p>Approximately 60mm of water in bottom of chamber.</p>

	<p>Sample tap discharges into chamber. This may be the source of the water in the bottom</p>
	<p>Surface rust on casing. Sump installed but no sump pump.</p>
	<p>Pipe penetration through chamber appears to be sealed.</p>
<p>5. Diagram with Well Measurements</p>	



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	No cables
	Pipework	Sealed with sidewall of chamber
	Well casing	Appears to be sealed from photos. Chamber could not be accessed
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		Unknown Some of the site is below the 50 year flood level and so there is the potential for flooding. The flood level at this bore is not known
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Surface rust
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		No
Signs of ponding?		Only in the chamber

Access by animals	No fence to prevent access, in a park where cats and dogs would be common but livestock would be less likely												
Protection from vandalism, signs of vandalism	Lid locked with padlock												
b) Drilling Standard:													
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – butterfly valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.												
If not, has this been agreed with the DWA?	N/A												
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached												
Bore casing type and condition (see NZS:4411 2.4.2)	Steel with minor pitting												
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown												
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown												
Does the well comply with NZS:4411?	No												
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No												
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>Single check valve in headworks</td> <td>To be agreed</td> </tr> <tr> <td>No sump pump</td> <td>Sump pump required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	Single check valve in headworks	To be agreed	No sump pump	Sump pump required
Non-Compliance	Agreed with DWA? (see Appendix D)												
Below ground installation	Agreed ok												
No 5m fenced	Agreed ok												
Casing not grout sealed	To be agreed												
Single check valve in headworks	To be agreed												
No sump pump	Sump pump required												


	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Roads and sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	60mm of water in chamber at time of inspection	
Is there a sump pump?	No sump pump but there is a sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Locate source of water in chamber and seal. The source is potentially the sample tap. ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the 	

	<p>contamination risks in the immediate vicinity of the well.</p> <ul style="list-style-type: none"> ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Cut back vegetation covering edge of well chamber
Third Priority	
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Picton Well 2

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Picton Well 2
ECan Well No.	M 35/8896
Aquifer No.	4
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	118 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	118-126
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	27 April 2001
Control System/Alarms	Pump failure
Type of Pump	None, artesian
Frequency of Pump Use	Runs everyday

4. Photo Record and Comments	
Photo	Comment
	<p>Pipe work has some surface rust. Chamber is dry.</p>
	<p>Bore casing has some surface rust. Casing appears to be sealed with chamber floor.</p>
	<p>Pipe penetrations through chamber side wall are sealed</p>
5. Diagram with Well Measurements	



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	No cables
	Pipework	Sealed with sidewall of chamber
	Well casing	Appears to be sealed from photos. Chamber could not be accessed
Any history of E. coli transgressions? Historical and current levels of total coliforms?	No E. coli transgressions recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	Unknown Some of the site is below the 50 year flood level and so there is the potential for flooding. The flood level at this bore is not known	
Downward facing air vent 0.5m above 100 year flood level	Not installed	
Type and condition of borehead pipework (above ground)	Surface rust	
Raw Water sample port?	Yes, in chamber	
Concrete apron sloped to drain away from well?	No	
100mm step above ground level?	Yes	

Signs of ponding?	Not at time of inspection. Waterway/drain is less than 1m away	
Access by animals	No fence to prevent access, in a park where cats and dogs would be common but livestock would be less likely	
Protection from vandalism, signs of vandalism	Lid locked with padlock. No signs of vandalism	
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – butterfly valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.	
If not, has this been agreed with the DWA?	N/A	
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached	
Bore casing type and condition (see NZS:4411 2.4.2)	Steel with minor pitting	
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown	
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown	
Does the well comply with NZS:4411?	No	
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No	
If no, what non-compliances require agreement with the DWA?	Non-Compliance	Agreed with DWA? (see Appendix D)
	Below ground installation	Agreed ok
	No 5m fenced	Agreed ok
	Casing not grout sealed	To be agreed
	Single check valve in headworks	To be agreed

	No sump pump	Sump pump required
	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Roads and sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	None at the time of inspection	
Is there a sump pump?	No sump pump , but there is a sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the 	

	<p>contamination risks in the immediate vicinity of the well.</p> <ul style="list-style-type: none"> ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Picton Well 3


1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Picton Well 3
ECan Well No.	M 35/8898
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	52.5 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	52.5-60.5
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	6 June 2001
Control System/Alarms	Pump failure
Type of Pump	Submersible
Frequency of Pump Use	Runs everyday

4. Photo Record and Comments	
Photo	Comment
	<p>Condensation from the top of the chamber.</p> <p>Sump without a pump. Sump has water in it.</p> <p>Sample tap within chamber</p>
	<p>Cable entry at side wall is sealed</p>
	<p>Pipe penetration through side wall is sealed</p>



Casing appears to be sealed to chamber floor from photo.

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Cable gland not sealed
	Pipework	Sealed with sidewall of chamber
	Well casing	Appears to be sealed from photos. Chamber could not be accessed
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		Unknown Some of the site is below the 50 year flood level and so there is the potential for flooding. The flood level at this bore is not known

Downward facing air vent 0.5m above 100 year flood level	Installed at lid level. Exact flood level at the well is unknown.
Type and condition of borehead pipework (above ground)	Surface rust
Raw Water sample port?	Yes, in chamber
Concrete apron sloped to drain away from well?	No
100mm step above ground level?	Yes
Signs of ponding?	Not at time of inspection. Drain is less than 1m away
Access by animals	No fence to prevent access, in a park where cats and dogs would be common but livestock would be less likely
Protection from vandalism, signs of vandalism	Lid locked with padlock. No signs of vandalism
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – butterfly valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Steel with minor pitting
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown
Does the well comply with NZS:4411?	No
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No

If no, what non-compliances require agreement with the DWA?	Non-Compliance	Agreed with DWA? (see Appendix D)
	Below ground installation	Agreed ok
	No 5m fenced	Agreed ok
	Casing not grout sealed	To be agreed
	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Roads and sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	None at the time of inspection	
Is there a sump pump?	No sump pump , but there is a sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Seal cable glands ■ Install a sump pump (with a level sensor that alarms to an operator) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected 	

	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable.
Third Priority	
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps






Figure 1: Summary of wells and consents within 400m of Picton Wells

Table 2: Summary of consents within 400m of Picton Wells

Picton Well Sites

<i>Well Number:</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
M35/8897			
Discharge to Water	NCY880140	Terminated - Replaced	Contaminated Water
Discharge to Water	CRC971563	Terminated - Surrendered	Contaminated Water
Discharge to Water	NCY730262	Terminated - Expired	Human Effluent
Discharge to Water	CRC090465	Issued - Active	Contaminated Water
Discharge to Water	NCY730263	Terminated - Surrendered	Human Effluent
Discharge to Water	CRC147597	Issued - Active	De-watering Water
Well Number:	M35/8896		
	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>

Discharge to Water	NCY880140	Terminated - Replaced	Contaminated Water
Discharge to Water	CRC971563	Terminated - Surrendered	Contaminated Water
Discharge to Water	NCY730262	Terminated - Expired	Human Effluent
Discharge to Water	CRC090465	Issued - Active	Contaminated Water
Discharge to Water	NCY730263	Terminated - Surrendered	Human Effluent
Discharge to Water	CRC147597	Issued - Active	De-watering Water
Discharge to Water	NCY730264	Terminated - Surrendered	Human Effluent

Well Number: M35/8898

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Water	NCY880140	Terminated - Replaced	Contaminated Water
Discharge to Water	CRC971563	Terminated - Surrendered	Contaminated Water
Discharge to Water	NCY730262	Terminated - Expired	Human Effluent
Discharge to Water	CRC090465	Issued - Active	Contaminated Water
Discharge to Water	NCY730263	Terminated - Surrendered	Human Effluent
Discharge to Water	CRC147597	Issued - Active	De-watering Water

Appendix C

Bore Logs





GRUNDFOS

DAVEY

N.Z.D.F

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

WELL OWNER	Christchurch City Council	PERMIT NUMBER	CRC010770
ADDRESS		BORE NUMBER	Bore 1
		GRID REFERENCE	M35/8897
LOCALITY	Picton Avenue		
DRILLER	T Smith	DRILLING DATE	9-mar-01

Strata			Details of Aquifers	
Depth from Surface (m)			Depth from surface (m)	S/W Level
Top	Bottom			
0	0.5	Top Soil		
0.5	6.8	Grey Pug (some peat & timber)		
6.8	10.9	Loose Brown Stained Gravel		
10.9	18.3	Soft Grey Pug		
18.3	18.6	Peat & Timber		
18.6	22.7	Very loose Heavily Stained Brown Gravel		
22.7	25.2	Very Loose Clean Gravel (some heavy staining)		
25.2	28.9	Tight Sandy Gravel		
28.9	29.3	Very Loose Brown Stained Gravel		
29.3	30.3	Tight Sandy Gravel		
30.3	31.4	Very Loose Brown Stained Gravel		
31.4	32.4	Tight Sandy Gravel (yellow clay seams)		
32.4	34.1	Tight Sandy Gravel Some Claybound		
34.1	38.3	Very Loose Stained Sandy Gravel		
38.3	40.3	Brown Sand (some gravel)		
40.3	41.4	Peat & Timber		
41.4	45.5	Grey Puggy W/B Sand		
45.5	47.6	Hard Silty Grey Pug		
47.6	49.4	Hard Sticky Orange/Yellow Clay		
49.4	51.0	Very Loose Brown Stained Gravel		
51.0	51.7	Loose Heavily Stained Brown Gravel		
51.7	52.3	Tight Sandy Gravel (traces of clay)		
52.3	56.8	Very Loose Stained Gravel		
56.8	57.3	Tight Gravel (traces of clay)		
57.3	58.4	Very Loose heavy Stained Gravel		
58.4	58.9	Tight Gravel with Hard Clay Seams		
58.3	61.2	Loose Brown Stained Gravel		
61.2	63.3	Water Bearing Gravel		
63.3	65.0	Tight Large Blue Gravel With Traces of Blue Pug		
65.0	65.3	Hard Dry Green Clay		
65.3	66.5	Large Blue Water Bearing Gravels with Traces of Green Clay		
66.5	71.0	Loose Blue Sandy Gravel		
71.0	71.3	Peat		
71.3	72.4	Grey Pug and Peat		
72.4	72.8	Clay Bound Gravel		



GRUNDFOS

DAVEY

N.Z.D.F

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

WELL OWNER	Christchurch City Council	PERMIT NUMBER	CRC010770
ADDRESS		BORE NUMBER	Bore 1
		GRID REFERENCE	M35/8897
LOCALITY	Picton Avenue		
DRILLER	T Smith	DRILLING DATE	9-mar-01

Strata			Details of Aquifers		
Depth from Surface (m)			Depth from surface (m)	S/W Level	
Top	Bottom				
72.8	78.2	Loose Brown Sandy Gravel			
78.2	78.6	Pale Yellow Clay			
78.6	79.5	Loose Brown Gravel			
79.5	80.6	Hard Yellow Clay			
80.6	81.2	Hard Blue Pug			
81.2	83.6	Soft Grey Pug			
83.6	86.2	Hard Silty Grey Pug			
86.2	89.2	Hard Silty Yellow Clay			
89.2	89.8	Hard Silty Grey Pug			
89.8	92.0	Hard Yellow Clay			
92.0	92.6	Claybound Gravel			
92.6	93.3	Brown Stained Gravel			
93.3	93.5	Yellow Clay Seam			
93.5	97.4	Brown Stained Gravel (very sandy)			
97.4	98.4	Loose Lightly Stained Sandy Gravel			
98.4	100.0	Tight Large Sandy Gravel			
100.0	102.1	Loose Heavily Stained Sandy Gravel			
102.1	102.3	Blue Cemented Gravels			
102.3	102.9	Grey Pug (traces of peat)			
102.9	107.6	Very Hard Silty Grey Pug			
107.6	108.7	Grey Pug			
108.7	109.0	Hard Dry Peat			
109.0	110.6	Hard Grey Pug			
110.6	110.8	Peat			
110.8	114.4	Hard Grey Pug			
114.4	116.0	Hard Yellow Clay			
116.0	117.4	Hard Clay Bound Gravel			
117.4	122.2	Tight Grey/Brown Sandy Gravel			
122.2	124.8	Small Grey/Brown Sandy Gravels			
124.8	125.6	Loose Lightly Stained Sandy Gravel			
125.6	126.5	Loose Brown Gravel (some dark staining)			
126.5	127.9	Tight brown Gravel (traces of clay bound)			
127.9	128.3	Loose Rusty Brown Gravel			
128.3	128.7	Tight Grey Gravel			



GRUNDFOS

DAVEY

N.Z.D.F

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

WELL OWNER	Christchurch City Council	PERMIT NUMBER	CRC010770
ADDRESS		BORE NUMBER	Bore 1
		GRID REFERENCE	M35/8897
LOCALITY	Picton Avenue		
DRILLER	T Smith	DRILLING DATE	9-Mar-01

Strata			Details of Aquifers		
Depth from Surface (m)			Depth from surface (m)		S/W Level
Top	Bottom				
128.7	128.9	Yellow Clay Seam			
128.9	129.1	Rusty Brown Gravel			
129.1	129.3	Clay & Gravel			
129.3	130.0	Yellow Clay Bound Sand			

Casing Diameter(mm)	300mm	Static Water Level	+	4.1	Depth (m)	126.895
Screen Type	Houston Stainless Steel Wedge Wire			Set At	118	126
Screen Length (m)	8 mtrs	Sump	.895mm		Leader	.825mm
Drawdown (m)		Pumping	Hours at		Litres-Minute/Second	

Remarks	Freeflow at 9-3-01 52 Litres/Second					
	Drawdown 1.380mm from static					
	Oriface Height 1 mtr above ground					



GRUNDFOS

DAVEY

N.Z.D.F

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

Page 1

WELL OWNER	Christchurch City Council	CONSENT NUMBER	CRC 010770
ADDRESS	P O Box 237	BORE NUMBER	Bore 2
	Christchurch	GRID REFERENCE	M35 8896
LOCALITY	Picton Avenue		
DRILLER	Tony Smith	DRILLING DATE	27-4-01

Strata			Details of Aquifers		
Depth from Surface (m)			Depth from surface (m)	S/W Level	
Top	Bottom				
0	0.5	Soil			
0.5	6.35	Pug and peat			
6.4	10.5	Loose large gravel			
10.5	16.3	Grey pug			
16.3	17.5	Blue/grey gravel			
17.5	20.3	Loose brown gravel			
20.3	20.8	Heavily stained gravel (clay traces)			
20.8	27.9	Brown gravel			
27.8	30.5	Loose heavily stained gravel			
30.5	31.3	Tight heavily stained gravel (clay lumps)			
31.3	32.6	Loose stained gravel			
32.6	38.5	Brown water bearing gravel and sand			
38.5	39.7	Grey sand (some blue gravel)			
39.7	41.4	Grey pug and peat (some timber)			
41.4	43.9	Grey puggy sand (some shells)			
43.9	48.0	Silty grey pug			
48.0	48.9	Soft sticky yellow clay			
48.9	52.6	Tight large grey gravel			
52.6	56.3	Loose brown stained gravel			
56.3	57.5	Large sandy gravel			
57.5	60.9	Loose stained gravel			
60.9	63.2	Loose heavily stained gravel			
63.2	64.4	Hard yellow clay			
64.4	64.9	Hard blue pug			
64.9	68.3	Loose blue gravel			
68.3	71.0	Soft silty blue/grey pug (traces of peat)			
71.0	71.8	Peat			
71.8	72.0	Blue gravel seam			
72.0	72.4	Peat			
72.4	73.0	Clay bound gravel			
73.0	75.7	Very loose brown stained gravel			
75.7	75.9	Yellow clay seam			



GRUNDFOS

DAVEY

N.Z.D.F

65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

Page 2

WELL OWNER	Christchurch City Council	CONSENT NUMBER	CC010770
ADDRESS	P O Box 237	BORE NUMBER	Bore 2
	Christchurch City Council	GRID REFERENCE	M35 8296
LOCALITY	Picton Ave		
DRILLER		DRILLING DATE	

Strata			Details of Aquifers		
Depth from Surface (m)			Depth from surface (m)		S/W Level
Top	Bottom				
75.9	79.8	Loose brown gravel			
79.8	81.3	Hard sticky yellow clay			
81.3	84.6	Hard silty grey pug			
84.6	86.3	Sticky grey pug			
86.3	88.3	Hard sticky yellow clay			
88.3	89.9	Hard silty grey pug			
89.9	92.3	Hard sticky yellow clay			
92.3	94.1	Claybound gravel			
94.1	95.4	Loose stained gravel			
95.4	96.4	Med/ Large grey gravel			
96.4	96.6	Yellow clay seam			
96.6	100.2	Loose Med/Large stained gravel			
100.2	100.9	Loose Med/large grave (traces of claybound)			
100.9	101.4	Loosely claybound large gravel			
101.4	101.8	Tight blue gravel (blue clay traces)			
101.8	102.6	Tight large claybound gravel			
102.6	103.3	Hard silty blue pug			
103.3	104.2	Cemented blue claybound gravel			
104.2	104.9	Loose blue gravel (traces blue clay)			
104.9	108.2	Hard silty blue pug			
108.2	108.8	Peat			
108.8	114.2	Hard grey pug			
114.2	116.5	Hard yellow clay			
116.5	118.0	Cemented claybound gravel			

Casing Diameter(mm)		Static Water Level		Depth (m)	
Screen Type			Set At		
Screen Length (m)				Leader	
Drawdown (m)					

REMARKS _____



65 Main North Road • Kaiapoi • Canterbury • New Zealand • Phone 64 3 327 4300 • Fax 64 3 327 7799

BORELOG

WELL OWNER	CHCH City Council	CONSENT NUMBER	CR010770
ADDRESS	Tuam Street	BORE NUMBER	Number 3
		GRID REFERENCE	M35 889B
LOCALITY	Picton Avenue		
DRILLER	Tony Smith / Daniel Rodgers	DRILLING DATE	06-Jun-01

Strata			Details of Aquifers	
Depth from Surface (m)			Depth from surface (m)	S/W Level
Top	Bottom			
0.0	0.4	Top soil		
4.0	6.5	Grey Pug / Lenses Peat & Timber		
6.5	13.8	Loose W/B Stained Gravel		
13.8	14.0	Yellow Clay Seam		
14.0	14.4	Loose Blue Gravel (Traces of Blue Pug)		
14.4	17.9	Soft Silty Grey Pug & Sand (Some Timber)		
17.9	18.0	Sticky Blue Pug		
18.0	18.4	Peat		
18.4	30.4	Loose Stained Gravel		
30.4	31.0	Loose Stained Gravel (Traces of Clay)		
31.0	35.7	Loose Stained Sandy Gravel		
35.7	36.0	Hard Yellow Clay (Some Gravel)		
36.0	38.6	Loose Heavily Stained Sandy Gravel		
38.6	39.5	Very Loose Heavily Stained Gavel With Seams of Yellow Clay		
39.5	39.8	Grey Pug & Peat		
39.8	45.5	Grey Puggy Sand (Some Blue Gravel)		
45.5	48.8	Grey Pug (Traces of Peat)		
48.8	49.5	Yellow / Orange Clay		
49.5	51.4	Loose Lightly Stained Gravel (Some Large)		
51.4	52.7	Heavily Stained Loose Gravel		
52.7	55.5	Loose Lightly Stained Gravel		
55.5	55.7	Yellow Clay Seam		
55.7	60.5	Loose Gravel		

Casing Diameter (mm)	300 mls	Static water level	1.81	Depth (M)	60.5 Meters
Screen Type	Houston Stainless Steel 120 Slot Wedge Wire		Set At		52.5 to 60.5
Screen Length (m)	8 Meters		Leader		.720
Drawdown (m)	2.12 Pumping 3 Hours		Hours @		50 Ltrs/Sec

REMARKS

Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Muruges	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Tara Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Hydrogeological Settling	2
4	Risks	2
5	Status / Compliance with DWSNZ Criterion 2	3
6	Recommendations	3
7	Conclusion	4

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the well supplying Tara Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as “secure”, a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used in this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Tara Pumping Station (Riccarton Pressure Zone)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Original bore logs as included in Appendix C
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Tara Pumping Station is supplied by one well; Tara Well 4. Table 2-1 summarises key information about the well.

Table 2-1: Tara Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 4	M 35/6945	164.8-169.3	4

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from both alpine river and rainfall to land surface recharge. The well supplying Tara Pumping Station is screened

within deep (Aquifer 4 – Wainoni Gravel Aquifer) leaky (semi)-confined aquifer within the Christchurch Artesian Aquifer System.

4 Well Inspections

An inspection the well was carried out on 7 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Andrew Batchelor (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that the Tara Well does not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 6-1 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 6-1: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 4	<ul style="list-style-type: none"> ■ Locate source of leak and seal. The source is potentially the sample tap, the ducts, from a hole behind the electrical cable, a leak from the lid or a leak at the chamber floor. ■ Seal chamber floor to prevent inundation of chamber from groundwater from the local near-surface groundwater ■ Seal cable entry points ■ Install backflow prevention device ■ Move sump pump to sit in sump and install 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Regrade site to promote flow of water away from chamber ■ Grout seals must be retrofitted. 		<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

	First Priority	Second Priority	Third Priority	Ongoing
	level sensor with alarm to operator <ul style="list-style-type: none"> ■ Unblock the sump pump outlet ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. <ul style="list-style-type: none"> ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways 		
General		<ul style="list-style-type: none"> ■ Clean up and seal valve chamber including sealing the chamber floor 		

7 Conclusion

The information reviewed and the inspections carried out indicate that the Tara well does not meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Tara
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	Well draws from Aquifer 4 (leaky confined)
Surface Water Ways, Drains, etc	Avon River tributary flows through reserve
4. Photo Record and Comments	
Photo	Comment
	Valve chamber without a sealed floor



Cable penetration in valve chamber appear to be unsealed from photos. Chamber could not be accessed



Unsealed holes in valve chamber



A second valve chamber

	New wastewater wet well being installed within the park		
5. Risks from Surrounding Environment			
a) Within the site:			
Diesel/Chemical Storage	None	<input type="checkbox"/> Underground <input type="checkbox"/> Aboveground	Fuel lines <input type="checkbox"/> Underground <input type="checkbox"/> Aboveground
Access by Animals	Usually not a fenced site, within a park. However at the time of inspection the park was closed and the area was fenced off for construction works. Locked building.		
Protection from vandalism, signs of vandalism	As above, no signs of vandalism		
Other Activities	N/A		
b) Immediate Neighbouring Land Use:			
Current Neighbouring Land Use	Park		
Significant Changes Since Previous Inspection	None identified		
Zoning of Neighbouring Land	Open Space Community Parks Zone, Residential Suburban Density Transition Zone		
c) Wider Environment:			


Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	Sewage main with air vents less than 100m away. Drains into creek. Deep wet well. Sewer nearby
Risk of flood inundation	Some of the site is below the 100 year flood level and so there is the potential for flooding
Potential sources of young water	No sources specific to the pumping station identified. See well assessments
General land use in catchment (LLUR)	As below
Contaminated sites (HAIL status)	None identified at the well and pump station address
Status and condition of surrounding wells (within 400 m radius)	Multiple wells
Landfill	None identified
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	Refer well assessments
Second Priority	<ul style="list-style-type: none"> ■ Clean up and seal valve chamber including sealing the chamber floor
Third Priority	Refer well assessments
Ongoing	Refer well assessments

Well Head Protection Assessment – Individual Well Heads

Tara Well 4

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Tara Well 4
ECan Well No.	M 35/6945
Aquifer No.	4
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	164.8 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	164.8-169.3
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	1994
Control System/Alarms	Pump failure


Type of Pump	Submersible
Frequency of Pump Use	Daily in summer, weekly in winter
4. Photo Record and Comments	
Photo	Comment
	Well chamber is located on the side of the road within a park. Park was closed due to construction works at the time of inspection. Site grading does not promote the flow of water away from the chamber.
	Sample tap drains into chamber.
	Water in the bottom of the chamber (~170mm) which may be from the sample tap, the ducts, from a hole behind the electrical cable, lid or chamber floor. It is possible that the nearby construction work has had an effect on this.

	<p>Pipe penetration through chamber wall is sealed.</p> <p>Leaking down from the top of the chamber</p>
	<p>Chamber wall penetration sealed</p>
	<p>Potential leak from behind the electrical cabinet.</p> <p>Note that the sump pump is not sitting in the sump.</p>

	<p>Casing may not be sealed to chamber floor. It appears that sediment is coming up from the ground below the chamber.</p>
---	--

	<p>Cable glands may not be sealed</p>
--	---------------------------------------

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
	Cabling	Cable gland not sealed
	Pipework	Sealed with sidewall of chamber

Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Well casing	Not sealed. It appears that sediment from the ground below is coming up into the chamber.
Any history of E. coli transgressions? Historical and current levels of total coliforms?		No E. coli transgressions recorded in the data received (dating back to 2012-13 FY). Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No – leaks described above Some of the site is below the 100 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level		Not installed Air vent has been removed, this might be for the construction works
Type and condition of borehead pipework (above ground)		Good condition – minor rust
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		Yes
Signs of ponding?		Not at time of inspection
Access by animals		Usually not a fenced site, within a park. However at the time of inspection the park was closed and the area was fenced off for construction works. Locked building.
Protection from vandalism, signs of vandalism		As above, lid locked with padlock, no signs of vandalism
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?		No – unless on the pump (not confirmed) A pressure reducing valve is installed to reduce shock wave to the delicate Riccarton system, but no backflow prevention unless on the pump.
If not, has this been agreed with the DWA?		N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?		Yes – bore logs attached

Bore casing type and condition (see NZS:4411 2.4.2)	Surface rust												
Bore casing grouted (see the definitions section of the DWSNZ, "bore head protection" and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown												
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown												
Does the well comply with NZS:4411?	No												
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No												
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>No confirmed backflow prevention device</td> <td>To be agreed</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	No confirmed backflow prevention device	To be agreed	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)											
	Below ground installation	Agreed ok											
	No 5m fenced	Agreed ok											
	Casing not grout sealed	To be agreed											
	No confirmed backflow prevention device	To be agreed											
No air vent	Air vent required												
c) Contamination Sources:													
Does the WSP address contaminant sources and contaminant migration pathways?	Not received												
Any localised well specific sources of contamination?	Spills from road, animals and vandalism												
d) Below Ground Chambers:													
Water level of chamber	~170mm of water at the time of inspection												
Is there a sump pump?	Yes – but not working at the time of arrival despite the water in the chamber Sump outlet is blocked due to construction works												
Are there duty/standby sump pumps?	No												
Sump pump testing, include date a method	Unknown												

Sump pump operation method including start level	Unknown
Sump pump and/or level alarms	Unknown
Does the well head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Locate source of leak and seal. The source is potentially the sample tap, the ducts, from a hole behind the electrical cable, a leak from the lid or a leak at the chamber floor. ■ Seal chamber floor to prevent inundation of chamber from groundwater from the local near-surface groundwater ■ Seal cable entry points ■ Install backflow prevention device ■ Move sump pump to sit in sump and install level sensor with alarm to operator ■ Unblock the sump pump outlet ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Regrade site to promote flow of water away from chamber ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
Third Priority	
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis

	<ul style="list-style-type: none">■ Establish routine testing and verification of backflow prevention device
--	--

Appendix B

Maps



Appendix C

Bore Logs



P.O. Box 191
Kaiapoi
New Zealand

Clemence Drilling Contractors Ltd

☎ (03) 312 6528
Fax (03) 312 6528
Mobile 025 320 147

N.Z.D.F.
member

Mill Road, Ohoka, Canterbury, New Zealand

Well Owner Christchurch City Council
Address Cambridge House
CHRISTCHURCH

Permit Number _____
Bore Number Well 4
Water Right Number _____
Grid Reference _____
Drilling Date 1994

Driller D. Clemence
Locality Paeroa Street Riccarton.

Depth from Surface (m)		Strata	Details of Aquifers	
Top	Bottom		Depth from Surface (m)	Static water level
0	0.3	Top soil and fill		
0.3	2.0	Yellow clay		
2.0	6.4	Blue clay streaked with peat		
6.4	7.1	Sloppy blue pug		
7.1	9.9	Hard blue/green clay		
9.9	11.8	clean stained gravel		
11.8	14.9	Big clean gravel		
14.9	17.0	Blue pug with peat and timber		
17.0	17.3	Blue pug with green sandy lenses		
17.3	17.5	Gravel and blue silt		
17.5	20.6	Loose brown stained gravel		
20.6	25.3	Good clean loose gravel		
25.3	26.8	Sandier large gravels heavy staining		
26.8	27.6	Tighter rough clay washed gravel		
27.6	30.9	Good loose gravel		
30.9	32.0	Yellow clay bound gravel		
32.0	33.4	Brown stained gravel		
33.4	33.8	Brown sand		
33.8	34.0	Yellow clay		
34.0	34.4	Peat impregnated with gravel		
34.4	36.0	Clean loose grey gravel		
36.0	36.7	Sandy rough broken gravel		
36.7	37.0	Blue clay		
37.0	37.4	Blue loose gravel		
37.4	37.8	Peat and timber		
37.8	40.0	Hard blue clay		
40.0	49.9	Tight sand heavy clay content		
49.9	50.5	Very tight silty blue pug		
50.5	51.4	Very tight yellow clay peat and gravel mixed		
51.4	56.0	Sandy stained clay washed gravel		
56.0	58.1	Very sandy stained gravel		

Casing Diameter (cm) _____ Depth (m) _____
Screen type _____ Set at _____
Screen Length (m) _____ Static Water Level _____
Drawdown (m) _____ After _____ Hours Pumping at _____ (litres sec/min)

Remarks (including notes on core samples taken) _____

P.O. Box 191
Kaiapoi
New Zealand

Clemence Drilling Contractors Ltd

☎ (03) 312 6528
Fax (03) 312 6528
Mobile 025 320 147

N.Z.D.F.
member

Mill Road, Ohoka, Canterbury, New Zealand

Well Owner Christchurch City Council
Address Cambridge House
Christchurch
Driller D Clemence
Locality Paeroa St Riccarton

Permit Number _____
Bore Number _____
Water Right Number _____
Grid Reference _____
Drilling Date 20-5-94

Depth from Surface (m)		Strata	Details of Aquifers		
Top	Bottom		Depth from Surface (m) Top	Bottom	Static water level
58.1	58.5	Yellow clay bound gravel			
58.5	59.5	Clean clay washed gravel			
59.5	59.9	Sand and gravel			
59.9	61.0	Brown sand			
61.0	62.4	Sandy loose stained gravel			
62.4	63.4	sandy well sorted gravel			
63.4	64.8	Yellow clay			
64.8	65.8	Loose small gravel and sand			
65.8	66.1	Very light sandy gravel			
66.1	67.0	Good loose gravel			
67.0	68.1	Brown tight stained gravel			
68.1	68.9	Blue gravel and clay			
68.9	71.9	Peat			
71.9	72.3	Blue clay bound gravel			
72.3	74.8	Loose sand and stained gravel			
74.8	79.0	Tight clay bound gravel			
79.0	80.4	Good loose well sorted gravel			
80.4	81.4	Loose gravel with clay seams			
81.4	82.4	Good loose gravel			
82.4	83.5	Yellow clay			
83.5	90.0	Blue pug / clay			
90.0	90.4	Blue and yellow clay			
90.4	91.2	Yellow clay bound gravel			
91.2	93.5	Good clean gravel			
93.5	93.9	Sandy gravel and clay seams			
93.9	94.8	Silty claybound gravel			
94.8	95.4	Clean gravel			
95.4	96.2	Very sandy tight gravel			
96.2	98.6	Progressivly more stained gravel/sticky clay seams			
98.6	99.1	Rough silty claybound stained gravel			
99.1	101.5	Brown gravel and sand			

Casing Diameter (cm) _____ Depth (m) _____
Screen type _____ Set at _____
Screen Length (m) _____ Static Water Level _____
Drawdown (m) _____ After _____ Hours Pumping at _____ (litres sec/min)

Remarks (including notes on core samples taken) _____

P.O. Box 191
Kaiapoi
New Zealand

Clemence Drilling Contractors Ltd

☎ (03) 312 6528
Fax (03) 312 6528
Mobile 025 320 147

N.Z.D.F.
member

Mill Road, Ohoka, Canterbury, New Zealand

Well Owner Christchurch City Council
Address Cambridge House
CHRISTCHURCH
Driller D Clemence
Locality Paeroa ST Riccarton

Permit Number _____
Bore Number _____
Water Right Number _____
Grid Reference _____
Drilling Date 20-5-94

Depth from Surface (m)		Strata	Details of Aquifers		Static water level
Top	Bottom		Top	Bottom	
101.5	102.1	Sandy stained gravel			
102.1	102.6	Good loose gravel			
102.6	104.0	Tight sandy stained gravel			
104.0	104.7	Blue clay bound gravel			
104.7	104.9	Blue clay and peat			
104.9	106.2	Yellow clay			
106.2	107.5	Rust stained gravel			
107.5	108.8	Tight sandy clay washed gravel			
108.8	112.0	Good gravel			
112.0	112.2	Clay bound stained gravel			
112.2	113.8	Yellow clay and timber			
113.8	114.2	Blue pug			
114.2	115.0	Yellow clay bound gravel			
115.0	115.6	Yellow clay and timber			
115.6	116.1	Very tight clay bound gravel			
116.1	116.4	Good grey gravel			
116.4	117.3	Sandy gravel lots of fragmented timber			
117.3	117.6	Very tight clay bound gravel			
117.6	119.2	Stained sandy gravel			
119.2	122.5	Good clean gravel			
122.5	125.0	Sandy gravel stained			
125.0	125.6	Cleaner stained gravel			
125.6	126.3	Rust stained sandy gravel			
126.3	126.8	Good loose stained gravel			
126.8	127.1	Rough sandy gravel			
127.1	127.6	Good clean stained gravel			
127.6	127.8	Yellow clay			
127.8	128.1	Blue gravel			
128.1	128.5	Blue clay bound gravel			
128.5	129.8	Dry grey silt/organic material			
129.8	130.7	Blue/grey clay			

Casing Diameter (cm) _____ Depth (m) _____
Screen type _____ Set at _____
Screen Length (m) _____ Static Water Level _____
Drawdown (m) _____ After _____ Hours Pumping at _____ (litres sec/min)

Remarks (including notes on core samples taken) _____

CLEMENCE DRILLING CONTRACTORS LIMITED



Mill Road, Ohoka
P.O. Box 191, Kaiapoi, Canterbury, New Zealand
Tel 0064-033126528 Fax 0064-033126528

N.Z.D.F.
Member

17th February 1995

Bruce Henderson
Headworks Manager
Water Supply Unit
Cambridge House
CHRISTCHURCH

PAEROA/TARA STREET WELL
TEST PUMP AND FREE FLOW

Pumped using surface pump. 8 x 6 Ajax. Static water level + 4.3metres.

<u>FLOW</u>	<u>DRAWDOWN</u>	<u>FREEFLOW</u>	<u>DRAWDOWN FROM STATIC</u> <u>+ 4.3 METRES A.G.L.</u>
38 l/sec	4 metres	7 l/sec	.3metres
45 l/sec	5 metres	9 l/sec	.9 metres
52 l/sec	6 metres	15 l/sec	1.35 metres
57 l/sec	7 metres	21 l/sec	2.00 metres
62 l/sec	8 metres	24 l/sec	2.50 metres
65 l/sec	9 metres	32 l/sec	3.20 metres
68 l/sec	9.5 metres		

Constant testpump after 5.5 hours at 68 l/sec, drawdown 9.1metres.
Freeflow at wellhead - 38 l/sec

Freeflow test - 24 hours.

At start of test: 32 l/sec drawdown 3.0 metres

After 24 hours: 30 l/sec drawdown 3.2 metres

Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Wainui Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Hydrogeological Setting	2
4	Well Inspections	3
5	Status / Compliance with DWSNZ Criterion 2	3
6	Recommendations	3
7	Conclusion	4

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the well supplying Wainui Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as “secure”, a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used in this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Wainui Pumping Station (Banks Peninsula)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Bore log from ECan’s website as included in Appendix C - <https://www.ecan.govt.nz/gis-mapping/>
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Wainui Pumping Station is supplied by a single well. This well, Wainui Well, services the Wainui Pressure Zone. The pump station is approximately 1km from Akaroa Harbour.

Table 2-1:Wainui Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Wainui Well	N 36/0048	No Screen Data	BPS

3 Hydrogeological Setting

The aquifer system at Wainui consists of fractured Akaroa Volcanics which is likely to be an unconfined to leaky (semi)-confined aquifer.

4 Well Inspections

An inspection of the well was carried out on 8 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Matthew Thomas (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Wainui Well does not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 6-1 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 6-1: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Wainui Well	<ul style="list-style-type: none"> ■ Check to see if the pump has a compliant backflow prevention device, otherwise agree requirements with the DWA and install a device if required ■ Seal cable glands and penetration through wall ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) ■ Install mesh on drain hole for vermin control ■ Add additional drainage holes (or enlarge existing) with mesh for vermin control 	<ul style="list-style-type: none"> ■ Rust prevention and tidy up of pipework ■ Regrade concrete around chamber to promote drainage ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways 		<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

7 Conclusion

The information reviewed and the inspections carried out indicate that the Wainui well does not meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Wainui
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2017
2. Modifications since Previous Assessment	
No known modifications	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	Draws from a fractured volcanic aquifer. Unconfined to leaky (semi)-confined.
Surface Water Ways, Drains, etc	Wainui Stream
4. Photo Record and Comments	
Photo	Comment
	Pump station and wellhead are located adjacent to the road in a park

	<p>One cartridge filter in the pump station building. No information on how often it is maintained.</p>								
<p>5. Risks from Surrounding Environment</p>									
<p>a) Within the site:</p>									
<p>Diesel/Chemical Storage</p>	<table border="1"> <tr> <td data-bbox="791 1010 871 1043">None</td> <td data-bbox="895 1010 1098 1043"><input type="checkbox"/> Underground</td> <td data-bbox="1121 1010 1185 1043">Fuel lines</td> <td data-bbox="1225 1010 1406 1043"><input type="checkbox"/> Underground</td> </tr> <tr> <td></td> <td data-bbox="895 1048 1098 1081"><input type="checkbox"/> Aboveground</td> <td></td> <td data-bbox="1225 1048 1406 1081"><input type="checkbox"/> Aboveground</td> </tr> </table>	None	<input type="checkbox"/> Underground	Fuel lines	<input type="checkbox"/> Underground		<input type="checkbox"/> Aboveground		<input type="checkbox"/> Aboveground
None	<input type="checkbox"/> Underground	Fuel lines	<input type="checkbox"/> Underground						
	<input type="checkbox"/> Aboveground		<input type="checkbox"/> Aboveground						
<p>Access by Animals</p>	<p>Not a fenced site but a locked and alarmed building</p>								
<p>Protection from vandalism, signs of vandalism</p>	<p>As above, no signs of vandalism</p>								
<p>Other Activities</p>	<p>N/A</p>								
<p>b) Immediate Neighbouring Land Use:</p>									
<p>Current Neighbouring Land Use</p>	<p>Playground and carpark</p>								
<p>Significant Changes Since Previous Inspection</p>	<p>None identified</p>								
<p>Zoning of Neighbouring Land</p>	<p>Rural Banks Peninsula Zone</p>								
<p>c) Wider Environment:</p>									
<p>Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks</p>	<p>Young Men's Christian Association has a consent to discharge human effluent to land ~100m away</p>								
<p>Risk of flood inundation</p>	<p>No detailed flood modelling in area. Unlikely to flood from visual inspection of site grading.</p>								

Potential sources of young water	No sources specific to the pumping station identified. See well assessment
General land use in catchment (LLUR)	As below
Contaminated sites (HAIL status)	None identified at the address of the well and pump station
Status and condition of surrounding wells (within 400 m radius)	None identified
Landfill	None identified
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	Refer well assessments
Second Priority	Refer well assessments
Third Priority	Refer well assessments
Ongoing	Refer well assessments

Well Head Protection Assessment – Individual Well Heads


Wainui Well

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Wainui Well
ECan Well No.	N 36/0048
Aquifer No.	BPS
Date of Inspection/Assessment	8 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Matthew Thomas
Date of Previous Inspection/Assessment	2 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Above
Depth (mbgl)	91.7 (depth from bore log, casing depth unknown)
Casing Diameter (mm)	200
Screen Interval (mbgl)	No Screen Data
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	14 August 1996
Control System/Alarms	Well pump on/off, lid opening alarm

Type of Pump	Submersible
Frequency of Pump Use	Continuous
4. Photo Record and Comments	
Photo	Comment
	200mm casing and bore head. Headworks is rusty (especially cap)
	Drain on chamber, no mesh for vermin control
	Cable penetration through wall not sealed
	Cable gland not sealed

	<p>Well casing has some surface rust. Appears to be sealed with chamber floor</p>
	<p>No vermin control on drain hole</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection		
a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Cable gland not sealed
	Pipework	Appears to be sealed with sidewall of chamber
	Well casing	Appears to be sealed with chamber floor
Any history of E. coli transgressions? Historical and current levels of total coliforms?	Only distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). No transgressions at the well. Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No	
Downward facing air vent 0.5m above 100 year flood level	Not installed	
Type and condition of borehead pipework (above ground)	Steel, rusty	
Raw Water sample port?	Yes, in cabinet of building	
Concrete apron sloped to drain away from well?	No, well and building are not at a low point	
100mm step above ground level?	Yes	
Signs of ponding?	Not at time of inspection	
Access by animals	No fence to prevent access, in a park where cats and dogs would be common but livestock would be less likely	
Protection from vandalism, signs of vandalism	Lid access alarm installed. Lid locked with padlock. No signs of vandalism	
b) Drilling Standard:		
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	No – possible installed on the pump but this has not been confirmed Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.	

If not, has this been agreed with the DWA?	Unknown										
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached										
Bore casing type and condition (see NZS:4411 2.4.2)	Steel with surface rust										
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing)	Unknown										
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown										
Does the well comply with NZS:4411?	No										
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No										
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>No 5m fence to prevent animal access</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>No confirmed backflow prevention device</td> <td>To be agreed</td> </tr> <tr> <td>No air vent</td> <td>Air vent required</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	No 5m fence to prevent animal access	Agreed ok	Casing not grout sealed	To be agreed	No confirmed backflow prevention device	To be agreed	No air vent	Air vent required
	Non-Compliance	Agreed with DWA? (see Appendix D)									
	No 5m fence to prevent animal access	Agreed ok									
	Casing not grout sealed	To be agreed									
	No confirmed backflow prevention device	To be agreed									
No air vent	Air vent required										
c) Contamination Sources:											
Does the WSP address contaminant sources and contaminant migration pathways?	Not received										
Any localised well specific sources of contamination?	Well and pump station are in a park near a parking lot. There is the potential for a spill of gas or other liquid to enter the well. Roads and sewers in close proximity.										
d) Below Ground Chambers:											
Water level of chamber	None present at the time of inspection. A drain hole is installed										
Is there a sump pump?	No pump or sump										

Are there duty/standby sump pumps?	No
Sump pump testing, include date a method	N/A
Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the well head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	<ul style="list-style-type: none"> ■ Check to see if the pump has a compliant backflow prevention device, otherwise agree requirements with the DWA and install a device if required ■ Seal cable glands and penetration through wall ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) ■ Install mesh on drain hole for vermin control ■ Add additional drainage holes (or enlarge existing) with mesh for vermin control
Second Priority	<ul style="list-style-type: none"> ■ Rust prevention and tidy up of pipework ■ Regrade concrete around chamber to promote drainage ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
Third Priority	
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps






Figure 1: Summary of wells and consents within 400m of Wainui Well

Table 2: Summary of wells and consents within 400m of Wainui Well

Wainui Well Site

Well Number: N36/0048

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Land	CRC950353	Issued - Active	Human Effluent

Appendix C

Bore Logs



Bore or Well No	N36/0048	
Well Name	WAINUI VALLEY ROAD	
Owner	Christchurch City Council	

Well Number	N36/0048	File Number	CO6C/12030
Owner	Christchurch City Council	Well Status	Active (exist, present)
Street/Road	WAINUI VALLEY ROAD	NZTM Grid Reference	BY25:91479-48947
Locality	WAINUI	NZTM X and Y	1591479 - 5148947
Location Description		Location Accuracy	1 - 2m
CWMS Zone	Banks Peninsula	Use	Public Water Supply,
Groundwater Allocation Zone	Outside	Water Level Monitoring	--
Depth	91.70m	Water Level Count	0
Diameter	200mm	Initial Water Level	2.50m below MP
Measuring Point Description		Highest Water Level	
Measuring Point Elevation	31.63m above MSL (Lyttelton 1937)	Lowest Water Level	
Elevation Accuracy	< 5 m	First reading	
Ground Level	0.00m above MP	Last reading	
Strata Layers	12	Calc Min 95%	
Aquifer Name	Banks Peninsula Volcanics	Aquifer Tests	0
Aquifer Type	Unknown	Yield Drawdown Tests	1
Drill Date	14 Aug 1996	Max Tested Yield	6 l/s
Driller	McMillan Drilling Ltd	Drawdown at Max Tested Yield	77 m
Drilling Method	Rotary Rig	Specific Capacity	0.07 l/s/m
Casing Material	STEEL	Last Updated	08 Nov 2013
Pump Type	Unknown	Last Field Check	
Water Use Data	No		

No screen data for this well

Step Tests

Step Test Date	Step	Yield	Yield GPM	DrawDown	Step Duration
14 Aug 1996	1	5.7	75.2296448	76.85	26

Comments

Comment Date	Comment
	FROM OLD CWS DB Located on Wainui Valley Rd, at entrance to the YMCA camp, on south side of the rd. Next to well is a pump shed & small water storage tank. Well not enclosed or fenced.
21 Mar 2000	FROM OLD CWS DB Surrounding area grassed with trees & above land used for camping facilities, cabins etc. GRID REF: N36:01487-10545. CCC Wn Wainui Valley 1 Stn Well-01
10 Dec 2001	css 193
10 Dec 2001	200mm casing to 13.65m & 100mm casing to 28.82m.
19 May 2010	Added well to CCC large water user


Bore Log

Borelog for well N36/0048

Grid Reference (NZTM): 1591479 mE, 5148948 mN
 Location Accuracy: 1 - 2m
 Ground Level Altitude: 31.6 m +MSD Accuracy: < 0.5 m
 Driller: McMillan Drilling Ltd
 Drill Method: Rotary Rig
 Borelog Depth: 91.7 m Drill Date: 14-Aug-1996



Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
		0.30m	Soil	
		0.30m	Soil	
		3.00m	Brown clay	
		3.00m	Brown clay	
		3.00m	Brown claybound gravel	
5		8.00m	Brown claybound gravel	
		8.00m	Yellow gravel with clay matrix	
10		13.60m	Yellow gravel with clay matrix	
		13.60m	Water-bearing artesian (20-25 gpm)	
15		19.00m	Water-bearing artesian (20-25 gpm)	
		19.00m	Water-bearing loose rock chips -andesite/basalt (20-25gpm)	VO
20		24.50m	Water-bearing loose rock chips -andesite/basalt (20-25gpm)	VO
25		25.40m	Andesite/basalt (Nic water)	VO
		27.00m	Andesite/basalt (Nic water)	VO
		27.00m	Brown andesite/basalt chips with clay matrix	VO
		28.00m	Brown andesite/basalt chips with clay matrix	VO
30		28.00m	Yellow andesite/basalt chips with clay matrix	VO
		28.00m	Yellow andesite/basalt chips with clay matrix	VO
		28.00m	Water-bearing basalt (30gpm)	VO
35				
40				



Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace



CH2M Beca

www.ch2mbeqa.com

Report

Sockburn Well Head Protection Assessment

Prepared for Christchurch City Council

Prepared by CH2M Beca Ltd

23 January 2018



Revision History

Revision N°	Prepared By	Description	Date
A	Lisa Mace / Mike Thorley	Draft for Client Review	14 December 2017
B	Lisa Mace / Mike Thorley	Final version	22 January 2018
C	Lisa Mace / Mike Thorley	Incorporating final changes	23 January 2018

Document Acceptance

Action	Name	Signed	Date
Prepared by	Lisa Mace / Mike Thorley		23 January 2018
Reviewed by	Andrew Watson		23 January 2018
Approved by	Paul Reed		23 January 2018
on behalf of	CH2M Beca Ltd		

© CH2M Beca 2017 (unless CH2M Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by CH2M Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.

Contents

1	Preamble	1
2	General Details	2
3	Hydrogeological Settling	3
4	Risks	3
5	Status / Compliance with DWSNZ Criterion 2	3
6	Recommendations	3
7	Conclusion	5

Appendices

Appendix A

Inspection Reports

Appendix B

Maps

Appendix C

Bore Logs

Appendix D

DWA Discussion Minutes

1 Preamble

Christchurch City Council (CCC) commissioned CH2M Beca Ltd (CH2M Beca) to carry out a review of 25 water supply wells at 9 primary water supply pump stations against *Bore Water Security Criterion 2 (bore head must provide satisfactory protection)* of the Drinking Water Standards New Zealand 2005 (revised 2008) (DWSNZ). The scope of works included inspecting the bores and determining their compliance with Criterion 2, recommending upgrades to improve bore head protection and DWSNZ compliance, and summarising the findings with one report per water scheme. This report summarises the findings for the wells supplying Sockburn Pumping Station.

Criterion 2 from section 4.5 of DWSNZ states:

4.5.2.2 Bore water security criterion 2: bore head must provide satisfactory protection

The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.

The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater. Animals must be excluded from within 5 m of the bore head.

The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.

The supply's PHRMP must address contaminant sources and contaminant migration pathways.

Potential sources of contamination such as septic tanks or other waste discharges must be situated sufficiently far from the bore so contamination of the groundwater cannot occur (for further discussion, see the Guidelines, section 3.2.3).

Note that in order to be classified as “secure”, a groundwater supply must show compliance with the DWSNZ Criterion 1, 2 and 3. This assessment only includes findings associated with Criterion 2.

The assessment contains the following sections:

- Body of report
 - This is a summary of information from the Inspection Reports located in Appendix A. It includes a summary of recommendations.
- Location maps – Appendix B
- Pumping Station Inspection Report – Appendix A
 - Hydrogeological Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Risks from Surrounding Environment
 - Actions Arising
- Individual Well Head Inspection Reports – Appendix A
 - Well Details
 - Photo Record, made at the time of inspection unless otherwise indicated
 - Diagram with measurements
 - Assessment of DWSNZ Criterion 2
 - Actions Arising

The following acronyms are used throughout this report:

- WSP – Water Safety Plan
- DWA – Drinking Water Assessor
- ADWCRs – Annual Drinking Water Compliance Reports
- WTP – Water Treatment Plant

In addition to information collected during the site visits, the following documents were used to prepare this report:

- The previous inspection report – “Well Head Security Report for Christchurch City Council Sockburn Pumping Station (West Pressure Zone)”
- A summary sheet of the wells to be inspected including information such as the ECan Well ID – “FY 2017 – 18 Wellhead Security Assessments”
- Original bore logs (Wells 1, 3,4, 5 and 6) as included in Appendix C
 - Note that that bore log labelled Well 2 has been assumed to be mislabelled and should actually be Well 1. This correction aligns the bore logs with the summary sheet
- Bore logs from ECan’s website (Well 2) as included in Appendix C - <https://www.ecan.govt.nz/gis-mapping/>
- Canterbury maps website - <https://mapviewer.canterburymaps.govt.nz/>
- WSP (requested from CCC)
- ADWCRs (requested from CCC)

We note that the Stage 2 report from the Havelock North Drinking Water Inquiry was published on 6 December 2017. Its recommendations include abolishing the secure classification system forthwith. Given that the Government’s formal response to the recommendations is not expected until February, we have not taken into account the Inquiry’s specific recommendations. However, Recommendation 50 is of particular relevance. It states:

“DWA should ensure special attention is given to the risk of existing bores with below-ground headworks in future WSPs. Appropriate mitigation measures should be implemented, including treatment and raising them where practicable.”

This recommendation has been considered in this report. We note that the Inquiry also recommends that treatment is mandated but this is beyond our current scope.

2 General Details

Sockburn Pumping Station is supplied by six wells; Sockburn Wells 1 – 6. Each well feeds into a combined suction tank which then goes to the Pumping Station pump set. Sockburn Pumping Station and Wells are located on Main South Road, Weaver Place and Blenheim Road. The station supplies part of the West Pressure Zone. Table 1 summarises key information about the six wells.

Table 1: Sockburn Wells Summary

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
Well 1	M 35/1859	No Screen Data	2
Well 2	M 35/1860	Screen 1: 65.5 – 68.5	2

CCC Well No	ECan Well No	Screen Depth (mbgl)	Aquifer No
		Screen 2: 75.5 – 78.5	
Well 3	M 35/2272	63.05 – 77.17	2
Well 4	M 35/2273	61.2 – 68.4	2
Well 5	M 35/2274	Screen 1 : 64.8 – 67.8 Screen 2: 73.3 – 76.3	2
Well 6	M 35/2275	63.64 – 76.75	2

3 Hydrogeological Setting

The Christchurch Artesian Aquifer System is made up of a series of interbedded gravel, sand and silt deposits derived from marine or terrestrial sources which contain groundwater of varying ages sourced from both alpine river and rainfall to land surface recharge. The wells supplying Sockburn Pumping Station are screened within moderately-deep (Aquifer 2 – Linwood Gravel Aquifer) leaky (semi)-confined aquifers within the Christchurch Artesian Aquifer System.

4 Risks

An inspections of each well was carried out on 7 November 2017 by Mike Thorley (CH2M Beca), Lisa Mace (CH2M Beca), Richard McCracken (CCC) and Andrew Batchelor (City Care). The Inspection Reports in Appendix A include a list of the risks identified with regards to DWSNZ Criterion 2.

5 Status / Compliance with DWSNZ Criterion 2

The information reviewed and the inspections carried out indicate that Sockburn Wells 1 – 6 do not meet DWSNZ Criterion 2. Recommendations to improve bore head protection are listed below.

6 Recommendations

Table 2 summarises that recommendations from the Inspection Reports. These recommendations are divided into priority rankings. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection.

The recommendations included below have been modified since Revision A of this report. Some of these modifications are a result of discussion with the DWA. See Appendix D for the minutes from this discussion.

Table 2: Summary of Recommendations

	First Priority	Second Priority	Third Priority	Ongoing
Well 1	<ul style="list-style-type: none"> ■ Seal cable penetration through chamber 			
Well 2	<ul style="list-style-type: none"> ■ Check that the cable entries are sealed and seal if required ■ Seal side entry points to chamber 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Tidy up well casing including removing rust from above ground area 		
Well 3	<ul style="list-style-type: none"> ■ Locate source of leak and seal. ■ Seal cable entry points ■ Seal water supply pipe and sample tap pipe entry points to chamber 			
Well 4	<ul style="list-style-type: none"> ■ Seal pipework with side chamber wall. ■ Seal cable entry points 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected 		
Well 5	<ul style="list-style-type: none"> ■ Seal casing to chamber floor if required (could not be accessed during visit) ■ Seal cable entry points to the bore and at the chamber wall ■ Install backflow prevention device 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Rust removal and prevention for the pipework and casing 		

	First Priority	Second Priority	Third Priority	Ongoing
Well 6	<ul style="list-style-type: none"> ■ Check that the cable glands into the bore are sealed. Seal if required. ■ Seal cable entry point of chamber sidewall 	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected 		
All wells	<ul style="list-style-type: none"> ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways. 	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed. 	<ul style="list-style-type: none"> ■ A sanitary inspection of the well (and flow meter chamber if applicable) should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

7 Conclusion

The information reviewed and the inspections carried out indicate that none of the Sockburn wells meet DWSNZ Criterion 2. The recommendations listed above should be carried out according to the priority

rankings shown. Those listed in the *First Priority* column should be completed as soon as possible as they will reduce immediate risks to human health and also satisfy the requirements for Well Head Protection. A follow-up inspection should take place within one month of the works being completed to review whether Criterion 2 is met, or seek the DWA agreement on those items that do not meet Criterion 2.

Appendix A

Inspection Reports



Well Head Protection Assessment – General

1. General	
Water Supplier	Christchurch City Council
Pumping Station	Sockburn
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2017
2. Modifications since Previous Assessment	
No known modifications	
3. Hydrogeological Details	
Aquifer Details (geology, un/confined, etc)	All wells draw from Aquifer 2 (leaky (semi)-confined)
Surface Water Ways, Drains, etc	Stormwater detention in park
4. Photo Record and Comments	
Photo	Comment
	Reticulation pumps

	Diesel storage tank outside. Above ground fuel lines and storage		
5. Risks from Surrounding Environment			
a) Within the site:			
Diesel/Chemical Storage	Yes, away from wells	<input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground	Fuel lines <input type="checkbox"/> Underground <input checked="" type="checkbox"/> Aboveground
Access by Animals	No, locked building		
Protection from vandalism, signs of vandalism	As above, no signs of vandalism		
Other Activities	N/A		
b) Immediate Neighbouring Land Use:			
Current Neighbouring Land Use	Industrial and roading		
Significant Changes Since Previous Inspection	None identified		
Zoning of Neighbouring Land	Commercial Mixed Use Zone		
c) Wider Environment:			
Potential sources of contamination such as septic tanks or other waste discharges, sewage pump stations, sewage pumping mains, gravity sewers, agricultural risks	Active consents for stormwater discharge within 400m Sewer nearby		
Risk of flood inundation	Pump station is below ground but within a building		
Potential sources of young water	No sources specific to the pumping station identified. See well assessments		
General land use in catchment (LLUR)	As below		
Contaminated sites (HAIL status)	At well and pump station address (149 Main South Road):		

	ACT 3632 G3 - Landfill sites ACT 77 A17 - Storage tanks or drums for fuel, chemicals or liquid waste
Status and condition of surrounding wells (within 400 m radius)	Multiple wells
Landfill	At Well 1 location (149 Main South Road)
6. Actions Arising	
Identify issues and rank them in terms of whether they require:	
First Priority	Refer well assessments
Second Priority	Refer well assessments
Third Priority	Refer well assessments
Ongoing	Refer well assessments


Well Head Protection Assessment – Individual Well Heads

Sockburn Well 1

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Sockburn Well 1
ECan Well No.	M 35/1859
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached (Assumed to be "No 2 Well")
Borehead type (above or below ground)	Below
Depth (mbgl)	81.66 (casing depth unknown)
Casing Diameter (mm)	300
Screen Interval (mbgl)	No Screen Data
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	30 August 1976
Control System/Alarms	Well pump on/off

Type of Pump	Submersible
Frequency of Pump Use	Generally runs every day or two to maintain level in suction tank
4. Photo Record and Comments	
Photo	Comment
	Well chamber and sample cabinet
	

	<p>Pipe penetration through chamber wall is sealed</p>
	<p>Casing approximately 1m above the chamber floor. Casing appears to be sealed to chamber from photos taken. Chamber could not be entered</p>
	<p>Cable entry to chamber not sealed</p>
<p>5. Diagram with Well Measurements</p>	



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Sealed at casing entry but not at chamber wall
	Pipework	Sealed with chamber wall
	Well casing	Sealed with chamber floor
Any history of E. coli transgressions? Historical and current levels of total coliforms?	Only distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). No transgressions have been recorded at the well in this data Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No – cabling entry at chamber wall not sealed Some of the site is below the 50 year flood level and so there is the potential for flooding	
Downward facing air vent 0.5m above 100 year flood level	Not installed	
Type and condition of borehead pipework (above ground)	Good condition	
Raw Water sample port?	Yes, in cabinet next to chamber	
Concrete apron sloped to drain away from well?	No	
100mm step above ground level?	Mostly, slightly less than 100mm at one side	

Signs of ponding?	Not at time of inspection but the well is located at a slight low point
Access by animals	No fence to prevent access, near a road where cats and dogs would be common but livestock would be less likely
Protection from vandalism, signs of vandalism	No lid alarm but there is a padlock on the hatch. No signs of vandalism.
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Good condition
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown
Does the well comply with NZS:4411?	No
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No
If no, what non-compliances require agreement with the DWA?	Non-Compliance Agreed with DWA? (see Appendix D)
	Below ground installation Agreed ok
	No 5m fenced Agreed ok
	Casing not grout sealed To be agreed


	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required
	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	<p>Close to edge of busy road. There is the potential for a spill of gas or other liquid to enter the well.</p> <p>Gas station across the street.</p> <p>Sewers in close proximity.</p>	
d) Below Ground Chambers:		
Water level of chamber	None at the time of inspection	
Is there a sump pump?	No pump or sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Seal cable penetration through chamber ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. 	

	<ul style="list-style-type: none"> ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Sockburn Well 2

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Sockburn Well 2
ECan Well No.	M 35/1860
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	65.5 (assume top of screen)
Casing Diameter (mm)	300
Screen Interval (mbgl)	Screen 1 : 65.5 – 68.5 Screen 2 : 75.5 – 78.5
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	30 August 1976
Control System/Alarms	Well pump on/off
Type of Pump	Submersible

<p>Frequency of Pump Use</p>	<p>Generally runs every day or two to maintain level in suction tank</p>
<p>4. Photo Record and Comments</p>	
<p>Photo</p>	<p>Comment</p>
	<p>Well location</p>
	<p>Casing condition – some surface rust</p>
	<p>Casing and chamber connection appears to be sealed from photos although the chamber could not be entered.</p>
	<p>Well chamber</p>
<p>5. Diagram with Well Measurements</p>	



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Cable entries appear to be sealed (although chamber could not be entered)
	Pipework	Sealed with sidewall of chamber
	Well casing	Casing to chamber appear to be sealed (although chamber could not be entered)
Any history of E. coli transgressions? Historical and current levels of total coliforms?		Only distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). No transgressions have been recorded at the well in this data Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		Yes Some of the site is below the 50 year flood level and so there is the potential for flooding
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Good condition
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No

100mm step above ground level?	Yes								
Signs of ponding?	Not at time of inspection								
Access by animals	No fence to prevent access, in a residential area where cats and dogs would be common but livestock would be less likely								
Protection from vandalism, signs of vandalism	Lid locked with padlock, no signs of vandalism but well is adjacent to footpath								
b) Drilling Standard:									
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.								
If not, has this been agreed with the DWA?	N/A								
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached								
Bore casing type and condition (see NZS:4411 2.4.2)	Some surface rust								
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown								
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown								
Does the well comply with NZS:4411?	No								
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No								
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed
	Non-Compliance	Agreed with DWA? (see Appendix D)							
	Below ground installation	Agreed ok							
	No 5m fenced	Agreed ok							
Casing not grout sealed	To be agreed								

	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required
	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Close to busy road. There is the potential for a spill of gas or other liquid to enter the well. Sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	None at the time of inspection	
Is there a sump pump?	No pump, but there is a sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Check that the cable entries are sealed and seal if required ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Tidy up well casing including removing rust from above ground area 	

	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways.
Third Priority	
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Sockburn Well 3


1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Sockburn Well 3
ECan Well No.	M 35/2272
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
New wellhead as part of earthquake repairs	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	63.05 (assume top of screen)
Casing Diameter (mm)	305
Screen Interval (mbgl)	63.05 – 77.17
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	18 September 1978
Control System/Alarms	Well pump on/off, lid alarm
Type of Pump	Submersible

<p>Frequency of Pump Use</p>	<p>Generally runs every day or two to maintain level in suction tank</p>
<p>4. Photo Record and Comments</p>	
<p>Photo</p>	<p>Comment</p>
	<p>Well chamber locked with padlock</p>
	<p>Approximately 20 mm of water in the bottom of the chamber</p>
	<p>Chamber penetrations appear to be sealed</p>
	<p>Cable entries have minor leaks and need sealing</p>



Sample tap entry to chamber not sealed

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Minor leaks, needs sealing
	Pipework	Not sealed (water supply pipe and sample tap pipe)
	Well casing	Sealed
Any history of E. coli transgressions? Historical and current levels of total coliforms?	Only distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). No transgressions have been recorded at the well in this data Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No Site is above the 50 year flood level and so flooding potential is low	

Downward facing air vent 0.5m above 100 year flood level	Not installed
Type and condition of borehead pipework (above ground)	Good condition
Raw Water sample port?	Yes, in cabinet next to chamber
Concrete apron sloped to drain away from well?	No
100mm step above ground level?	Yes
Signs of ponding?	Not at time of inspection, it was noted that this site has flooded in the past
Access by animals	No fence to prevent access, in a park
Protection from vandalism, signs of vandalism	Lid access alarm installed. Lid locked with padlock. No signs of vandalism.
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Good condition
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown
Does the well comply with NZS:4411?	No
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No

If no, what non-compliances require agreement with the DWA?	Non-Compliance	Agreed with DWA? (see Appendix D)
	Below ground installation	Agreed ok
	No 5m fenced	Agreed ok
	Casing not grout sealed	To be agreed
	Single check valve in headworks	To be agreed
	No sump pump	Sump pump required
	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Close to busy road. There is the potential for a spill of gas or other liquid to enter the well. Sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	~20mm of water at the time of inspection	
Is there a sump pump?	No pump or sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Locate source of leak and seal. ■ Seal cable entry points ■ Seal water supply pipe and sample tap pipe entry points to chamber 	


	<ul style="list-style-type: none"> ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
Second Priority	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Sockburn Well 4

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Sockburn Well 4
ECan Well No.	M 35/2273
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	61.2 (assume top of screen)
Casing Diameter (mm)	305
Screen Interval (mbgl)	61.2 – 68.4
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	29 August 1978
Control System/Alarms	Well pump on/off, lid opening alarm
Type of Pump	Submersible

<p>Frequency of Pump Use</p>	<p>Generally runs every day or two to maintain level in suction tank</p>
<p>4. Photo Record and Comments</p>	
<p>Photo</p>	<p>Comment</p>
	<p>Well location</p>
	<p>Bore head – pipe glands not sealed</p>
	<p>Casing in reasonable condition with some rust</p>
	<p>Pipe to wall entry not sealed</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Power cable joint not sealed
	Pipework	Not sealed with sidewall of chamber
	Well casing	Sealed
Any history of E. coli transgressions? Historical and current levels of total coliforms?	Only distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). No transgressions have been recorded at the well in this data Total coliform levels are unknown	
Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No Site is above the 50 year flood level and so flooding potential is low	
Downward facing air vent 0.5m above 100 year flood level	Not installed	
Type and condition of borehead pipework (above ground)	Steel, reasonable condition	
Raw Water sample port?	Yes, in chamber	
Concrete apron sloped to drain away from well?	No	

100mm step above ground level?	Yes
Signs of ponding?	Not at time of inspection
Access by animals	No fence to prevent access, near road
Protection from vandalism, signs of vandalism	Lid access alarm installed. Lid locked with padlock. No signs of vandalism
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	No – possible installed on the pump but this has not been confirmed Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	Unknown
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Steel, ok condition
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown
Does the well comply with NZS:4411?	No
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No
If no, what non-compliances require agreement with the DWA?	Non-Compliance Agreed with DWA? (see Appendix D)
	Below ground installation Agreed ok
	No 5m fenced Agreed ok
	Casing not grout sealed To be agreed

	No confirmed backflow prevention device	To be agreed
	No sump pump	Sump pump required
	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Close to busy road. There is the potential for a spill of gas or other liquid to enter the well. Sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	None at the time of inspection	
Is there a sump pump?	No pump or sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Seal pipework with side chamber wall. ■ Seal cable entry points ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention 	


	<p>requirements. This should be confirmed with the DWA.</p> <ul style="list-style-type: none"> ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways.
<p>Third Priority</p>	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
<p>Ongoing</p>	<ul style="list-style-type: none"> ■ A sanitary inspection of the well and the flow meter chamber should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Sockburn Well 5

1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Sockburn Well 5
ECan Well No.	M35/2274
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
No known modifications	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	64.8 (assume top of screen)
Casing Diameter (mm)	305
Screen Interval (mbgl)	Screen 1: 64.8 – 67.8 Screen 2: 73.3 – 76.3
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	5 April 1979
Control System/Alarms	Well pump on/off, lid opening alarm
Type of Pump	Submersible

<p>Frequency of Pump Use</p>	<p>Generally runs every day or two to maintain level in suction tank</p>
<p>4. Photo Record and Comments</p>	
<p>Photo</p>	<p>Comment</p>
	<p>Well chamber floor. Casing to floor connection could not be viewed as the chamber could not be accessed.</p>
	<p>Pipework is rusty Chamber floor appears to be damp but on closer inspection it was found that sparkling spider webs cause the damp look.</p>
	<p>Pipework to chamber sidewall connection appears to be sealed.</p>
	<p>Cable penetrations through the chamber sidewall are not sealed</p>

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:		
Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)	Cabling	Cable entry not sealed
	Pipework	Sealed with sidewall of chamber
	Well casing	Cannot be seen as the chamber cannot be accessed
Any history of E. coli transgressions? Historical and current levels of total coliforms?		Only distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). No transgressions have been recorded at the well in this data Total coliform levels are unknown
Sanitary well seal watertight or elevated 0.5m above 100 year flood level		No
Downward facing air vent 0.5m above 100 year flood level		Not installed
Type and condition of borehead pipework (above ground)		Rusty pipework
Raw Water sample port?		Yes, in chamber
Concrete apron sloped to drain away from well?		No
100mm step above ground level?		Yes
Signs of ponding?		Yes

Access by animals	No fence to prevent access, in a commercial and construction area										
Protection from vandalism, signs of vandalism	Lid access alarm installed. Lid locked with padlock. No signs of vandalism										
b) Drilling Standard:											
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	No – possible installed on the pump but this has not been confirmed Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.										
If not, has this been agreed with the DWA?	Unknown										
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached										
Bore casing type and condition (see NZS:4411 2.4.2)	Rusty well casing										
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown										
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown										
Does the well comply with NZS:4411?	No										
Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No										
If no, what non-compliances require agreement with the DWA?	<table border="1"> <thead> <tr> <th>Non-Compliance</th> <th>Agreed with DWA? (see Appendix D)</th> </tr> </thead> <tbody> <tr> <td>Below ground installation</td> <td>Agreed ok</td> </tr> <tr> <td>No 5m fenced</td> <td>Agreed ok</td> </tr> <tr> <td>Casing not grout sealed</td> <td>To be agreed</td> </tr> <tr> <td>No confirmed backflow prevention device</td> <td>To be agreed</td> </tr> </tbody> </table>	Non-Compliance	Agreed with DWA? (see Appendix D)	Below ground installation	Agreed ok	No 5m fenced	Agreed ok	Casing not grout sealed	To be agreed	No confirmed backflow prevention device	To be agreed
	Non-Compliance	Agreed with DWA? (see Appendix D)									
	Below ground installation	Agreed ok									
	No 5m fenced	Agreed ok									
	Casing not grout sealed	To be agreed									
No confirmed backflow prevention device	To be agreed										

	No sump pump	Sump pump required
	No air vent	Air vent required
c) Contamination Sources:		
Does the WSP address contaminant sources and contaminant migration pathways?	Not received	
Any localised well specific sources of contamination?	Close to busy road. There is the potential for a spill of gas or other liquid to enter the well. Sewers in close proximity.	
d) Below Ground Chambers:		
Water level of chamber	None at the time of inspection	
Is there a sump pump?	No pump or sump	
Are there duty/standby sump pumps?	No	
Sump pump testing, include date a method	N/A	
Sump pump operation method including start level	N/A	
Sump pump and/or level alarms	N/A	
Does the well head meet the requirements of Criteria 2	No, see actions below	
7. Actions Arising		
Identify issues and rank them in terms of whether they require:		
First Priority	<ul style="list-style-type: none"> ■ Seal casing to chamber floor if required (could not be accessed during visit) ■ Seal cable entry points to the bore and at the chamber wall ■ Install backflow prevention device ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area) 	
Second Priority	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ Rust removal and prevention for the pipework and casing 	

	<ul style="list-style-type: none"> ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways.
Third Priority	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
Ongoing	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Sockburn Well 6


1. General	
Water Supplier	Christchurch City Council
CCC Well No.	Sockburn Well 6
ECan Well No.	M 35/2275
Aquifer No.	2
Date of Inspection/Assessment	7 November 2017
Inspection Team	CH2M Beca: Mike Thorley, Lisa Mace CCC: Richard McCracken City Care: Andrew Batchelor
Date of Previous Inspection/Assessment	3 October 2012
2. Modifications since Previous Assessment	
New top riser that has increased the level	
3. Bore Details	
Bore log	Attached
Borehead type (above or below ground)	Below
Casing Depth (mbgl)	63.64 (assume top of screen)
Casing Diameter (mm)	305
Screen Interval (mbgl)	63.64 – 76.75
Thickness of grout seal (mm) from the outside of the casing diameter	Unknown
Depth of grout seal (mbgl)	Unknown
Date Drilled	15 May 1979
Control System/Alarms	Well pump on/off, lid opening alarm
Type of Pump	Submersible

<p>Frequency of Pump Use</p>	<p>Generally runs every day or two to maintain level in suction tank</p>
<p>4. Photo Record and Comments</p>	
<p>Photo</p>	<p>Comment</p>
	<p>Well chamber location</p>
	<p>Borehead pipework, in reasonable condition</p>
	<p>Casing to chamber floor connection. Some debris build-up but appears to be sealed</p>
	<p>Rust and casing flaking</p>



Cable chamber penetrations not sealed

5. Diagram with Well Measurements



6. Assessment of Bore Water Security Criterion 2 – Bore head must provide satisfactory protection

a) Water Ingress:

Condition of seals (see NZS:4411 2.5.5.3 & 2.5.5.4)

Cabling

Cable penetration through chamber not sealed. Cable glands into bore appeared to be sealed but the chamber could not be accessed so they could not be properly checked

Pipework

Sealed with sidewall of chamber.

Well casing

Appears to be sealed from photo collected, chamber could not be accessed

Any history of E. coli transgressions?
Historical and current levels of total coliforms?

Only distribution system E. coli transgressions have been recorded in the data received (dating back to 2012-13 FY). No transgressions have been recorded at the well in this data

Total coliform levels are unknown

Sanitary well seal watertight or elevated 0.5m above 100 year flood level	No
Downward facing air vent 0.5m above 100 year flood level	Not installed
Type and condition of borehead pipework (above ground)	Good condition
Raw Water sample port?	Yes, in chamber
Concrete apron sloped to drain away from well?	No
100mm step above ground level?	Yes
Signs of ponding?	Not at time of inspection, next to carpark
Access by animals	No fence to prevent access, near a road and a carpark
Protection from vandalism, signs of vandalism	Lid access alarm installed. Lid locked with padlock. No signs of vandalism
b) Drilling Standard:	
Does the bore have backflow prevention complying with Backflow Mechanism (NZS:4411 2.5.5.8)?	Yes – check valve installed (not tested) Note that dual check valves are often used to provide a higher degree of protection, however we consider a single check valve at the headworks meets the backflow prevention requirements. The well pump may also have a check valve but this is not known.
If not, has this been agreed with the DWA?	N/A
Does the bore drilling and well construction record keeping meet NZS:4411 (Section 4)?	Yes – bore logs attached
Bore casing type and condition (see NZS:4411 2.4.2)	Some rust
Bore casing grouted (see the definitions section of the DWSNZ, “bore head protection” and NZS:4411 2.5.2.1 Grouting/sealing	Unknown
Does the bore construction meet casing and jointing requirements of NZS4411 2.5.1	Unknown
Does the well comply with NZS:4411?	No

Does the well comply with Minimum Construction Requirements for water bore in Australia 3 rd ed?	No
If no, what non-compliances require agreement with the DWA?	Non-Compliance Agreed with DWA? (see Appendix D)
	Below ground installation Agreed ok
	No 5m fenced Agreed ok
	Casing not grout sealed To be agreed
	Single check valve in headworks To be agreed
	No sump pump Sump pump required
	No air vent Air vent required
c) Contamination Sources:	
Does the WSP address contaminant sources and contaminant migration pathways?	Not received
Any localised well specific sources of contamination?	Close to busy road and carpark. There is the potential for a spill of gas or other liquid to enter the well. Sewers in close proximity.
d) Below Ground Chambers:	
Water level of chamber	None at the time of inspection
Is there a sump pump?	No pump or sump
Are there duty/standby sump pumps?	No
Sump pump testing, include date a method	N/A
Sump pump operation method including start level	N/A
Sump pump and/or level alarms	N/A
Does the well head meet the requirements of Criteria 2	No, see actions below
7. Actions Arising	
Identify issues and rank them in terms of whether they require:	

<p>First Priority</p>	<ul style="list-style-type: none"> ■ Check that the cable glands into the bore are sealed. Seal if required. ■ Seal cable entry point of chamber sidewall ■ Install a sump pump (with a level sensor that alarms to an operator) ■ Install a downward facing air vent 0.5 m above 100 year flood level (unless the well is not located in a flood prone area)
<p>Second Priority</p>	<ul style="list-style-type: none"> ■ Modify sample tap so that it is either outside the chamber, or so that it contains a length of flexible hose that can be pulled outside the chamber when samples are collected ■ We consider a single check valve at the headworks meets the backflow prevention requirements. This should be confirmed with the DWA. ■ Grout seals must be retrofitted. Requirements will be based on how soon the well will be replaced (i.e. if the well is due for replacement within the next two years, then undertake grout sealing as part of new well construction), and the contamination risks in the immediate vicinity of the well. ■ Address the risks associated with the below ground bore in the WSP. This includes treatment and raising above ground where practicable. ■ Ensure that the WSP addresses contaminant sources and contaminant migration pathways
<p>Third Priority</p>	<ul style="list-style-type: none"> ■ For the as-built records, confirm backflow prevention on the well pump has been installed.
<p>Ongoing</p>	<ul style="list-style-type: none"> ■ A sanitary inspection of the well should take place on a regular basis ■ Establish routine testing and verification of backflow prevention device

Appendix B

Maps






Figure 1: Summary of wells and consents within 400m of Sockburn Wells

Table 3: Summary of consents within 400m of Sockburn Wells

Sockburn Well Sites

Well Number: M35/1859

Type	Consent Number	Consent Status	Feature Type
Discharge to Water	CRC091739	Issued - Active	Stormwater Industrial
Discharge to Water	CRC010280	Terminated - Replaced	Cooling Water
Discharge to Land	CRC030353	Issued - Active	Stormwater Residential

Well Number: M35/1860

Type	Consent Number	Consent Status	Feature Type
Discharge to Water	CRC091739	Issued - Active	Stormwater Industrial
Discharge to Water	CRC010280	Terminated - Replaced	Cooling Water
Discharge to Land	CRC030353	Issued - Active	Stormwater Residential

Well Number: M35/2272

Type	Consent Number	Consent Status	Feature Type
Discharge to Water	CRC091739	Issued - Active	Stormwater Industrial

Discharge to Water	CRC010280	Terminated - Replaced	Cooling Water
Discharge to Land	CRC030353	Issued - Active	Stormwater Residential

Well Number: M35/2273

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Water	CRC010280	Terminated - Replaced	Cooling Water
Discharge to Land	CRC030353	Issued - Active	Stormwater Residential

Well Number: M35/2274

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Water	CRC091739	Issued - Active	Stormwater Industrial
Discharge to Water	CRC010280	Terminated - Replaced	Cooling Water
Discharge to Land	CRC030353	Issued - Active	Stormwater Residential
Discharge to Land	CRC130324	Issued - Inactive	Stormwater Residential

Well Number: M35/2275

<i>Type</i>	<i>Consent Number</i>	<i>Consent Status</i>	<i>Feature Type</i>
Discharge to Water	CRC091739	Issued - Active	Stormwater Industrial
Discharge to Water	CRC010280	Terminated - Replaced	Cooling Water
Discharge to Land	CRC130324	Issued - Inactive	Stormwater Residential

Appendix C

Bore Logs



Bore or Well No	M35/1860	 Environment Canterbury Regional Council <i>Kaunihera Taiao ki Waitaha</i>	
Well Name	149 MAIN SOUTH ROAD		
Owner	Christchurch City Council		
Well Number	M35/1860	File Number	CO6C/10597
Owner	Christchurch City Council	Well Status	Active (exist, present)
Street/Road	149 MAIN SOUTH ROAD	NZTM Grid Reference	BX24:64183-79350
Locality	SOCKBURN	NZTM X and Y	1564183 - 5179350
Location Description	Sth side Main South Rd - in reserve	Location Accuracy	2 - 15m
CWMS Zone	Christchurch - West Melton	Use	Small Community Supply,
Groundwater Allocation Zone	Christchurch/West Melton	Water Level Monitoring	--
Depth	78.50m	Water Level Count	0
Diameter	300mm	Initial Water Level	
Measuring Point Description		Highest Water Level	
Measuring Point Elevation	21.30m above MSL (Lyttelton 1937)	Lowest Water Level	
Elevation Accuracy	< 2.5 m	First reading	
Ground Level	0.00m above MP	Last reading	
Strata Layers	39	Calc Min 95%	3.10m below MP
Aquifer Name	Linwood Gravel	Aquifer Tests	0
Aquifer Type	Non-Flowing Artesian	Yield Drawdown Tests	0
Drill Date	30 Aug 1976	Max Tested Yield	0 l/s
Driller	A M Bisley & Co	Drawdown at Max Tested Yield	0 m
Drilling Method	Cable Tool	Specific Capacity	
Casing Material		Last Updated	25 Jul 2017
Pump Type	Unknown	Last Field Check	30 Jan 2008
Water Use Data	No		



Screens

Screen No.	Screen Type	Top (m)	Bottom (m)	Slot Size (mm)	Slot Length (mm)	Diameter (mm)	Leader Length (mm)
1	Stainless steel	65.5	68.5				
2	Stainless steel	75.5	78.5				

No step tests for this well

Comments

Comment Date	Comment
	FROM OLD CWS DB M35/1859, M35/1860, M35/2272, M35/2273, M35/2274 & M35/2275. All supply Sockburn pumpstation but some not in use. M35/1860 located in garden in front of storage tank & pumpstation on Main South Rd, opp. entrance to Sockburn Pool & Weaver Place. Is enclos
15 Oct 1998	West pressure zone.
14 Feb 2000	FROM OLD CWS DB Surrounding area Sockburn pumpstation & CCC service centre, a vehicle testing station, a swimming pool & recreation centre & all wells are adjacent to main rds. GRID REF: M35:74164-40953.
25 Aug 2008	NZMG update from air photo Aug 2008, gridref changed from M35:74177-40961
06 May 2010	MfE source code added


Bore Log


Borelog for well M35/1860

Grid Reference (NZTM): 1564183 mE, 5179350 mN
 Location Accuracy: 2 - 15m
 Ground Level Altitude: 21.3 m +MSD Accuracy: < 2.5 m
 Driller: A M Bisley & Co
 Drill Method: Cable Tool
 Borelog Depth: 81.7 m Drill Date: 30-Aug-1976



Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
		0.50m	Topsoil	SP?
			Sand, Yellow/Grey small gravel	SP?
		1.50m		
			Grey sand, small - large gravel	SP?
		3.00m		
		3.25m	Brown sand, stained gravel	SP?
			Grey sand medium - small gravel	SP?
		4.00m		
		4.50m	Brown sand medium - small gravel	SP?
			Blue sand medium - small gravel	SP?
5		5.00m		
			Grey clay	SP?
		8.50m		
		9.00m	Brown/Yellow clay	SP?
		9.50m	Grey small gravel	SP?
10			Small - large Grey gravel	RI
		11.00m		
			Small - medium Grey gravel & sand	RI
		14.00m		
		14.50m	Small - medium gravel, sand clay traces	RI
15			Small Brown gravel, sand	RI
		23.00m		
		23.50m	Small - medium Grey gravel, sand	RI
			Dark stained medium - small gravel	RI
			Yellow clay	RI
25				





No 2 Well

A. M. BISLEY & CO. LTD.

WELL DRILLING DIVISION

NO 1028/29

HAMILTON and CHRISTCHURCH

WELL LOG

30/8 1976

NAME: Papanua County Council

LOCATION: Main South Rd, Opp Sockburn Park.

DIA. OF WELL: 300 mm

STATIC WATER LEVEL:

CASING: Spiral Weld

SHOE: Rolled Steel

TOTAL DEPTH: 81.66

SCREEN: 5/S 3.11m x 250 ID (80 slot) .7m x 10" spiral weld blank
5/S 3.11 x 250 ID (80 slot)

LEADER: 600mm x 292mm OD (Sump 1.46 x 10" spiral weld)

PACKER: Nil

PUMPING TEST:

SPECIFIC CAPACITY:

LITHOLOGY

0 - .5	Top Soil	31 - 35	Dark Stain gr small to fine sand
.5 - 1.5	Sand, yellow grey small gr	35 - 35.75	Yellow Clay
1.5 - 3	Sand grey small to larger gr	35.75-37	Brown gr small to Medi
3-3.25	Sand brown stain gr	37 - 40	Dark stain gr small (WB)
3.25-4	Sand grey Medi to small gr	40-43	Yellow Clay
4-4.50	Sand Brown " " " "	43-44	Brown gr yellow clay sand
4.50-5	Sand Blue " " " "	44-49.5	Grey clay
5-8.5	Grey Clay	49.5-50	Tight brown gr yellow clay
8.5-9	Brown Yellow Clay	50-53	Small brown cemented gr sandy clay
9-9.5	Gray Gravel small	53-54.2	Yellow Clay
9.5-11	Gray gravel small to large	54.2-55.5	Fine brown sandy gr (WB)
11-14	Gray gravel small to Medi sand		
14-14.5	Grey gr small to medi sand trace clay		
14.5 - 23	Brown gr small sand		
23-23.5	Grey gr small to medi sand		
23.5-26	Dark stain gr small to fine yellow clay		
26-31	Grey brown gr small to medi sand		

A. M. BISLEY & CO. LTD.

WELL DRILLING DIVISION

HAMILTON and CHRISTCHURCH

WELL LOG

.....30.8.....19.76.

NAME: Papanua County Council

LOCATION: Main South Rd, Opp Sockburn Park

DIA. OF WELL: 300mm

STATIC WATER LEVEL:

CASING: Spiral Weld

SHOE: Rolled Steel

TOTAL DEPTH: 81.66

SCREEN: S/S 3.11m x 250 ID (80 slot) .7m x 10" spiral weld blank
S/S 3.11 x 250 ID (80 slot) (Sump 1.46 x 10" spiral weld)

LEADER:

PACKER: Nil

PUMPING TEST:

SPECIFIC CAPACITY:

LITHOLOGY

55.5 - 58 Brown gr small to medi trace clay
 58 - 60 Dark stain small to medi trace clay
 60 - 69 Dark stain small sand (WB)
 69 - 69.5 Yellow Clay
 69.5 - 70.25 Grey Clay
 70.25 - 73 Brown gr small sandy
 73 - 73.75 Dark stain gr sandy
 73.75 - 74 Yellow Clay
 74 - 79 Brown gr small sand
 79 - 81 Stain gr sand yellow clay trace
 81 - 81.66 Blue gr.

A. M. BISLEY & CO. LTD

WATER SUPPLY DIVISION

HAMILTON and CHRISTCHURCH

WELL LOG

April 5 1979

CLARITY PRESS LTD

NAME: Papanua County Council.

LOCATION: Sockburn Round About (Opp Council Yard)

~~AS~~ ~~WT~~ N°5

DIA. OF WELL: 305mm

STATIC WATER LEVEL: 4.5m from G.L.

CASING: 63.3m

SHOE: 1.

TOTAL DEPTH: 76m

SCREEN: 1m 250mm Black Pipe 3.10m 225mm I.D. Johnson St.St. 100 Slot.
5.5m 250mm " " 3.10m 225mm " " " " 100 Slot.

LEADER: 0.61m 280I.D. Rolled Pipe.

PACKER: -

PUMPING TEST: 28.1 l/sec.

SPECIFIC CAPACITY: 15 l/sec/m

DR.D: 1.87m

Screen 64.8 → 67.8.

73.3 → 76.3.

LITHOLOGY

- 0 - 6 Backfill and Grey Gravel.
- 6 - 6.1 Large Grey Gravel.
- 6.1 - 9.3 Blue Clay.
- 9.3 - 12.3 Small Grey Brown Gravel.
- 12.3 - 15.0 Medium Grey Brown Gravel.
- 15.0 - 16.4 Medium Grey Brown Gravel and Sand.
- 16.4 - 18.4 Grey Medium Brown Gravel.
- 18.4 - 21.5 Medium Grey Brown Gravel and Sand.
- 21.5 - 24.5 Medium Grey Gravel.
- 24.5 - 29.0 Medium Grey Brown Gravel and Brown Clay.
- 29.0 - 30.8 Brown Clay.
- 30.8 - 33.5 Medium to Small Grey Brown Gravel.
- 33.5 - 37.0 Sandy Brown Medium Gravel.
- 37.0 - 38.0 Large Sandy Brown Gravel.
- 38.0 - 40.1 Brown Clay and Some Gravel.
- 40.1 - 45.0 Brown Stained Sandy Gravel.
- 45.0 - 46.2 Medium Brown Gravel and Some Yellow Clay.
- 46.2 - 48.0 Medium to Small Brown Sandy Gravel.
- 48.0 - 48.5 Brown Sandy Clay.
- 48.5 - 49.3 Blue Clay.

RIG No. 4.

DRILLER B. Lagendyk.

Continued

A. M. BISLEY & CO. LTD

WATER SUPPLY DIVISION

HAMILTON and CHRISTCHURCH

WELL LOG

April 5 1979

CLARITY PRESS LTD

NAME: Papanua County Council.

LOCATION: Sockburn Round About (Opp Council Yard)

DIA. OF WELL:

STATIC WATER LEVEL:

CASING:

SHOE:

TOTAL DEPTH:

SCREEN:

LEADER:

PACKER:

PUMPING TEST:

SPECIFIC CAPACITY:

LITHOLOGY

49.3 - 50.0 Brown Clay.
50.0 - 55.0 Grey Gravel.
55.0 - 57.2 Medium to Small Brown Stained Gravel.
57.2 - 63.0 Large to Small Brown Gravel, Sand and Some Yellow Clay.
63.0 - 66.8 Large to Small Brown Stained Gravel and Fine Sand.
66.8 - 67.0 Yellow Clay and Gravel.
67.0 - 69.6 Sandy Brown Gravel.
69.6 - 71.1 Hard Blue Clay.
71.1 - 71.4 Hard Yellow Clay.
71.4 - 76.0 Sandy Brown Gravel and Some Yellow Clay.

RIG No. 4.

DRILLER B. Lagendyk.

A. M. BISLEY & CO. LTD

RECEIVED

29 MAY 1979

WATER SUPPLY DIVISION

HAMILTON and CHRISTCHURCH

Answer

WELL LOG

15 May 1979

No 6. Well

CLARITY PRESS LTD

NAME: Paparua County Council,

LOCATION: Soakburn Round About (Near Alloy Steel)

DIA. OF WELL: 305mm

STATIC WATER LEVEL: 4.40m From G.L.

CASING: 63.64m

SHOE: 1.

TOTAL DEPTH: 76.75m

SCREEN: 1^m 250mm Black pipe 3.10m 225mm I.D. Johnson S.S. 100 slot

5.84 250mm Black pipe 3.10m 225mm I.D. Johnson S.S. 100 slot

LEADER: 0.60m 280 I.D. Rolled pipe

PACKER: -

PUMPING TEST: 31.5 l/sec.

SPECIFIC CAPACITY: 9.78 l/sec/m

DR.D.: 3.22m

LITHOLOGY

0.0 - 4 Filling.
4.0 - 6.5 Grey Gravel & Sand.
6.5 - 9.3 Grey Clay & Roots.
9.3 - 12.0 Brown Stained Gravel.
12.0 - 12.5 Fine Brown Stained Gravel.
12.5 - 29.0 Grey Brown Gravel & Sand.
29.0 - 33.4 Brown Sandy Gravel.
33.4 - 33.9 Brown Gravel. Yellow Clay, and Sand.
33.9 - 35.0 Brown Stained Gravel & Sand.
35.0 - 37.2 Sandy Brown Gravel.
37.2 - 37.8 Yellow Clay.
37.8 - 42.0 Brown Stained Sandy Gravel.
42.0 - 46.2 Brown Stained Sandy Gravel Some Clay.
46.2 - 48.1 Fine Sand Some Gravel.
48.1 - 48.4 Brown Gravel. Yellow Clay & Sand.
48.4 - 48.9 Yellow Clay, Peat Timber.
48.9 - 50.3 Blue Clay.
50.3 - 51.7 Grey Gravel, Grey & Yellow Clay, Peat.
51.7 - 52.4 Grey Brown Gravel.
52.4 - 53.0 Sandy Brown Stained Gravel.
53.0 - 53.2 Tight Blue Gravel, Yellow Clay.

RIG No. 4

DRILLER

B. Legendyk.

PACKER:

PUMPING TEST: No 6 Well.

SPECIFIC CAPACITY:

4:15 G.A.M.

Pumped 31.5 l/sec

W.L. 4,40m from G.L.

LITHOLOGY

5 min	Draw Down	
		2.46m
30 "	" "	2.69m
60 "	" "	3.00m
90 "	" "	3.07m
120 "	" "	3.12m
150 "	" "	3.15m
180 "	" "	3.18m
210 "	" "	3.19m
240 "	" "	3.21m
300 "	" "	3.22m

RIG No.

DRILLER

53.2	-	53.5	Tight Brown Gravel & Yellow Clay.
53.5	-	63.0	Sandy Brown Stained Gravel.
63.0	-	66.5	Brown Stained Gravel & Sand.
66.5	-	66.7	Sandy Brown Gravel Some Yellow Clay,
66.7	-	69.4	Sandy Brown Gravel.
69.4	-	69.8	Sandy Blue Gravel.
69.8	-	70.9	Hard Blue Clay & Feat.
70.9	-	71.4	Hard Yellow Clay.
71.4	-	75.0	Very Sandy Brown Gravel.
75.0	-	75.2	Sandy Brown Gravel & Yellow Clay.
75.2	-	76.65	Very Sandy Brown Gravel.

RIG No. 4.

DRILLER

B. Legendyk.

A. M. BISLEY & CO. LTD.

WELL DRILLING DIVISION

HAMILTON and CHRISTCHURCH

WELL LOG

18th September 1978

NAME: PAPUA COUNTY COUNCIL

LOCATION: LEAVER PLACE/IN FRONT OF SOCKBURN POOL

DIA. OF WELL: 305mm

STATIC WATER LEVEL: 2.85m FROM G.L.

CASING: 63.05m

SHOE: 1

TOTAL DEPTH: 77.17m

SCREEN: 1m 225mm Black Pipe 3.06m 225mm I.D. Johnson SS 100 slot
1.98m 225mm Black Pipe 2.08m 225mm I.D. Johnson SS 100 slot

LEADER: 0.61m 280mm I.D. Rolled Pipe

PACKER: -

PUMPING TEST: 24.3l/sec

SPECIFIC CAPACITY: 5.9 l/sec/m

DR.D 3.50m

LITHOLOGY

0 - 5	Filling (Rubbish Dump)	64.5 - 67.5	Sandy brown and dark stained gravel and some yellow clay.
5 - 7.30	Grey Gravel & Sand		
7.30 - 8.30	Grey Clay		
8.30 - 8.80	Yellow Clay	67.5 - 70.3	Very sandy brown and dark stained gravel
8.80 - 28.2	Grey Brown Gravel some dark stained and sand	70.3 - 71.5	Hard Yellow Clay
28.2 - 32.7	Brown Gravel some dark stained and sand.	71.5 - 72	Brown Gravel, fine sand and some clay
32.7 - 36.7	Sandy brown Gravel	72 - 77	Sandy brown gravel
36.7 - 37.5	Brown Gravel and yellow clay		
37.5 - 38.7	Sandy brown gravel		
38.7 - 44	Yellow Clay		
44 - 44.9	Sandy Yellow Clay and gravel		
44.9 - 50.7	Grey clay, sand timber & some gravel		
50.7 - 52	Brown gravel and fine sand		
52.0 - 55.6	Tight sandy brown gravel		
55.6 - 64.5	Sandy brown and dark stained gravel		

RIG NO. 4

DRILLER: O. LAGERDYK

A. M. BISLEY & CO. LTD

WATER SUPPLY DIVISION

HAMILTON and CHRISTCHURCH

WELL LOG

29/8/ 1978

No 4 Well

CLARITY PRESS LTD

NAME: Paparua County Council

LOCATION: Weaver Place (Beside Sockburn Pool)

DIA. OF WELL: 305mm

STATIC WATER LEVEL: 3.2m From G.I.

CASING: 61.20m

SHOE: 1

TOTAL DEPTH: 68.40m

SCREEN: 1m 225mm Black pipe.

LEADER: 0.20m 225mm I.D. Johnson ST.ST. 100 slots
0.60m 280mm I.D. Rolled pipe

PACKER: -

PUMPING TEST: 25.25 l/sec

SPECIFIC CAPACITY: 5 l/sec/m

DR. D: 5.2m

LITHOLOGY

0	- 0.5	Filling
0.5	5	Grey Gravel & Sand
5	- 6.7	Grey Clay & Timber
6.7	- 12	Grey Sand Clay, Timber & Some Gravel
12	- 27.3	Grey - Brown Gravel Some Dark Stained & Sand
27.3	- 34.2	Brown Gravel Some Dark Stained & Sand
34.2	- 37.2	Sandy Brown Gravel
37.2	- 38.7	Yellow Clay & Some Gravel
38.7	- 39	Brown Gravel & Sand
39	- 42	Sandy Grey Clay
42	- 46	Grey Clay & Timber
46	- 48.10	Grey Sand Some Gravel & Timber
48.10	- 52.2	Grey Clay
52.2	- 57.6	Sandy Brown Gravel & Some Clay
57.6	- 57.9	Yellow Clay & Gravel
57.9	60.4	Brown Gravel & Fine Sand
60.4	- 63.5	Sandy Brown & Dark Stained Gravel
63.5	- 67	Brown Gravel Some Dark Stained & Fine Sand
67	- 68	Sandy Brown Gravel and Yellow Clay

RIG No. 4

DRILLER B. Legendyk

Appendix D

DWA Discussion Minutes



Minutes of Meeting

Well Head Protection Assessments - Discussion about Recent Assessments - Minutes

Held 19 December 2017 at 10am

at CCC

Present:	Daniela Murugesh	CCC
	Kenton Winckles	CCC
	Rob Meek	CCC
	Graham Wardman	CCC
	Judy Williamson	CDHB
	Mike Thorley	CH2M Beca
	Lisa Mace	CH2M Beca
	Paul Reed	CH2M Beca

Apologies: None

Distribution: All of the above

Item	Action
<p>1 General</p> <ul style="list-style-type: none">Inspections of 25 wells have been carried outThe purpose of the meeting was to discuss eight common items that are non-compliant with Criteria 2 the Drinking Water Standard New Zealand (DWSNZ) or are not considered best practice and to come to a conclusion on which items can be signed off by the Drinking Water Assessor (DWA) and which items require upgrades.	
<p>2 Cable glands</p> <ul style="list-style-type: none">CCC forwarded CityCare the list of sites where Beca identified that cable glands were not sealed.CityCare has since been around to inspect the cable glands and has said that they are okBeca made the point that cable glands can appear to be sealed from above, but on closer inspection that may be loose (move when touched) which mean that sealant is required	
<p>3 Below ground installations</p> <ul style="list-style-type: none">Decision: DWA agreed that existing below ground installations can meet Criteria 2 (so long as the chamber is sealed) of the DWA but new wells should be installed above ground	
<p>4 Not fenced, or fence at less than 5m</p> <ul style="list-style-type: none">Decision: DWA agreed that wells without fences (or fences at less than 5m) can meet Criteria 2 of the DWA when they are not located in an area with livestockOne possible exception is wells that have been seen to have issues with vandalism and rubbish although fencing still may not be the best solution.	
<p>5 No record of grout seals</p>	

<ul style="list-style-type: none"> ■ CCC is currently retrofitting grout seals on some wells ■ Grout seals are more important for non-artesian wells ■ Daniela to email Judy with a list of which wells don't have confirmed grout seals (all of the wells inspected) and the planned upgrade dates in CityCare's schedule ■ Decision: Judy will respond with which wells are acceptable based on how soon the grout seals will be installed and which should be retrofitted ■ Note that the Australian drilling standard provides depths that grout seals should go down to ■ Note that wells drilled after ~2014 are likely to have grout seals as the CCC standards required them. 	Daniela Judy
<p>6 Backflow Prevention</p> <ul style="list-style-type: none"> ■ DWA indicated that there must be a testable backflow preventer at all sites however this could be substituted with an air gap on the inlet to the suction tank or a backflow preventer on the outlet of the pump station ■ Lisa to send Daniela a list of wells without a check valve in the well headworks (<i>post meeting note: completed</i>) ■ Daniela to confirm that these wells have check valves at the well pumps (ie foot valves) ■ Decision: Beca to include which bores have check valves in the bore headworks in each report for DWA approval 	Lisa Daniela
<p>7 Sump pumps</p> <ul style="list-style-type: none"> ■ Decision: A single sump pump and a level sensor that alarms to an operator should be included on all below ground wells ■ In some cases this involves modification, or installation, of the floor to include a sump ■ In some cases low voltage power may be difficult to install in the well. Battery operated sump pumps may be considered ■ It was agreed a duty/standby sump pump is not required. ■ The sump pumps need to be on a regular testing programme 	
<p>8 No air vent</p> <ul style="list-style-type: none"> ■ Decision: Air vents should be installed on all wells with a priority for non-artesian wells. The air vents need to be 500mm above the 100 year flood level. 	
<p>9 Miscellaneous</p> <ul style="list-style-type: none"> ■ Some flowmeter chambers were found to be flooded but it was agreed that this was simply a maintenance item. That is, there'll be a programme to pump them out. 	
<p>10 Going Forward</p> <ul style="list-style-type: none"> ■ Daniela to send Lisa report comments ■ Beca to finalise reports based on this meeting and CCC comments ■ Reports to include a table of discretionary items for sign off by DWA 	Daniela Beca Beca

Minuted by: Lisa Mace