

REPORT TO CANTERBURY EARTHQUAKE RECOVERY AUTHORITY

Argent Building
82 Peterborough Street, Christchurch

Detailed Engineering Evaluation and Initial Evaluation Procedure Assessment

HARRISON GRIERSON CONSULTANTS LIMITED

Document Control Record

Client CHRISTCHURCH CITY COUNCIL

Project Argent Building, 82 Peterborough Street

HG Project No. 2150-131322-02

HG Document No. R001v1-CH131322-02_Argent-tck


Document Detailed Engineering Evaluation


ISSUE AND REVISION RECORD

Date of Issue August 2012

Status Final

Originator 
.....
Tony Kelly - Engineer

Reviewed 
.....
Ian Williams - Senior Engineer

Approved for Issue 
.....
Damien McGill - Engineering Manager,
Christchurch

Office of Origin Christchurch

Telephone 03 962 9770

Facsimile 03 962 9771

Email christchurch@harrisongrierson.com

REPORT TO CANTERBURY EARTHQUAKE RECOVERY AUTHORITY

Detailed Engineering Evaluation

Argent Building, 82 Peterborough Street, Christchurch

August 2012

HG Project No. 2150-131322-02

HG Document No. R001v1-CH131322-02_Argent-tck

CONTENTS

	Page
EXECUTIVE SUMMARY	III
1.0 INTRODUCTION	1
2.0 SITE ADDRESS AND DESCRIPTION	1
3.0 STRUCTURAL SYSTEM	3
4.0 GROUND CONDITIONS	3
5.0 SUMMARY OF OBSERVED DAMAGE	3
6.0 FLOOR LEVEL SURVEY	6
7.0 DISCUSSION – REPAIR WORKS	8
8.0 SEISMIC LATERAL LOAD RESISTANCE	9
9.0 FURTHER WORK	9
10.0 BUILDING CONSENT	9
11.0 SUMMARY	9
12.0 LIMITATIONS	10

APPENDICES

Appendix 1	Floor Level Survey Results
Appendix 2	Marked up drawings showing damage locations
Appendix 3	Detailed Engineering IEP Evaluation Sheets

DRAWINGS

Ian Krause Architects Ltd

A1.01	Site plan, foundation plan, and elevations
A1.02a	Floor, roof, and ceiling plans
A2.01a	Sections
A3.01	Details

Lovell-Smith & Cusiel Ltd

S1 to S10	Structural drawings
-----------	---------------------

EXECUTIVE SUMMARY

Harrison Grierson has been instructed by the Christchurch City Council, to carry out structural assessments for the buildings at 82 and 84 Peterborough Street, Christchurch. Each building has been evaluated in a separate report. This report is for the Argent Building at 82 Peterborough Street, to the front of the site.

Our scope is to produce a Detailed Engineering Evaluation report in accordance with CERA requirements.

This report includes a detailed review of the record drawings for the building and completing an Initial Evaluation Procedure (IEP) to determine seismic capacity in terms of % of New Building Standard (%NBS).

The building was designed by Lovell-Smith & Cusiel Ltd in 1999. Its construction is precast concrete panels with welded connections with shallow ground beam foundations. The floors are reinforced concrete and the roof is lightweight Trimdek supported on a steel rafter at mid span with pressed steel purlins.

A geotechnical investigation was not carried out as part of this evaluation however, some minor liquefaction was observed – water, sand and fine silts were ejected in the car park and roadway adjacent to the building, indicating liquefaction of the underlying soils.

Earthquake damage includes minor cracking to the precast panels, loss of sealant from panel joints and cracking of internal finishes. A floor level survey carried out indicates possible settlement of the foundations.

Some cosmetic repairs are required, including repairs to hairline cracks and minor spall in precast concrete panels; cracks to internal wall partitions; and repairs to flexible sealant to exterior wall joints.

An Initial Evaluation Procedure has been completed for the building using the CERA excel format. The seismic rating has been assessed as 65% NBS or Seismic Grade C (67% to 33% New Building Standard).

No critical structural weaknesses have been identified and repairs are not necessary for continued safe occupancy.

1.0 INTRODUCTION

Harrison Grierson has been instructed initially by VBASE and latterly by the Christchurch City Council, to carry out a structural assessment for the buildings situated at 82 & 84 Peterborough Street, Christchurch.

Our scope is to produce a Detailed Engineering Evaluation report in accordance with CERA requirements.

This report includes reviewing of the record drawings for the building including a review of wall connection details and the stairs, and completion of an Initial Seismic Evaluation (IEP) to determine seismic capacity in terms of % of New Building Standard (%NBS).

Our engineers have carried out site inspections on 12 & 13 May 2011, 21 June 2011 & 9th January 2012 following the 22nd February earthquake and subsequent significant aftershocks.

This report is specific to the Argent building at 82 Peterborough Street, to the rear of the site

2.0 SITE ADDRESS AND DESCRIPTION

The site address is 82 Peterborough Street, Christchurch. The legal description is Lot 1 DP 81332.

The Argent Building is located to the front of the site (Lot 1), and measures approximately 14.5m by 13m (Figure 1).



Figure 1: The Argent Building, 82 Peterborough Street

The Argent Building has a basic two level layout as follows:

- Access to the building is via the ground floor (side door).
- The ground floor consists of mixed office space, a lunchroom and kitchenette, and bathrooms.
- An internal staircase provides access to the first floor.
- The first floor also consists of mixed office space.
- The floor footprint area of the building is approximately 190m².
- The original structural drawings by Lovell-Smith & Cusiel Ltd (1999) and architectural drawings by Ian Krause Architects Limited (1999) have been obtained from Christchurch City Council.




Figure 2: Christchurch Post-earthquake Aerial Photo (24 February 2011) showing site.

3.0 STRUCTURAL SYSTEM

The following is a summary of the structural systems as determined from the drawings:

Gravity System

- Lightweight metal roof cladding on DHS purlins and a 310UB40 rafter at mid span.
- Precast concrete wall panels and spandrels.
- 180 Hibond suspended floor slabs.
- Precast floor beams.
- 100mm cast insitu ground floor slab with 665 mesh throughout.
- Reinforced concrete (in-situ) foundation beams and columns.
- Precast concrete stairs and landings.

Lateral System

- 150mm precast concrete panels/spandrels in the longitudinal and transverse directions. Wall panels typically reinforced with H12 at 300mm centres each way located central.
- 180 Hibond suspended floor diaphragm.

4.0 GROUND CONDITIONS

A geotechnical investigation was not carried out as part of this evaluation.

Some minor liquefaction was observed – water, sand and fine silts were ejected in the carpark and roadway adjacent to the building, indicating liquefaction of the underlying soils.

There have not been any obvious signs of settlement around the exterior of the building.

5.0 SUMMARY OF OBSERVED DAMAGE

A visual inspection was carried out by Harrison Grierson engineers on 12-13 May 2011. Our visual inspections included the exterior and interior of the Argent Building. The locations of the damage are shown on the marked up plans included as Appendix 2.

The following observations were made from this inspection:

- Hairline cracks in both wing-wall extensions of the eastern shear wall
- Loss of flexible sealant on corner joints between precast concrete panel walls (Figure 3)
- Fracture of bottom edge concrete of precast panels on the south side wall (Figure 4)
- Crack, and in one instance fracture, of internal wall partition lining (Figure 5)
- Racked door frames



Figure 3: Corner joints, external walls



Figure 4: Precast panels, external south side wall



Figure 5: Internal wall partition

Another visual inspection of the building exterior and interior was carried out by Harrison Grierson engineers on 21 June 2011, following significant aftershocks on 13 June 2011.

It was noted from this inspection that the observed aftershock damage was unchanged from damage after the February earthquake, although the non-structural cracks in the GIB lining may have increased slightly.

Another visual inspection of the exterior and interior of the building was carried out by Harrison Grierson engineers on 9 January 2012, following significant aftershocks on 23 December 2011.

The following observations were made from this inspection:

- Further loss of flexible sealant on corner joints between precast concrete panel walls.
- Further fracture of bottom edge concrete of precast panels on the south side wall (Figure 4).
- Cracks and fracture of internal wall partition linings slightly worse.

The observed damage to the building has been broken down into three categories: Superficial, Minor and Major. Damage has been summarised below in each category.

Superficial			
Damage description	Location	Investigations	Reason for damage
1. Cracks to wing wall extensions	External eastern shear wall	Visual inspection	Stress cracking from building flexure
2. Loss of flexible sealant on exterior walls	External precast walls	Visual inspection	Movement from building flexure
3. Cracks to internal wall partitions	Internal wall partition GIB lining on ground floor	Visual inspection	Movement from building flexure
4. Hairline cracking to exterior panels	Generally around window and door locations	Visual inspection	Stress cracking from building flexure.
5. Superficial inverse pitting of bitumen pavement surface	Between drive and carpark outside the building entrance	Visual inspection	Liquefaction rising but not breaking the surface.

Minor			
Damage description	Location	Investigations	Reason for damage
6. Fracture of precast panels	External south side wall	Visual inspection	Stress cracking from building flexure
7. Differential settlement in floor levels	Ground and first floors	Floor level survey	Likely settlement of foundations.

Major			
Damage description	Location	Investigations	Reason for damage
None noted			

6.0 FLOOR LEVEL SURVEY

6.1 COMMENTARY

One of the difficulties of assessing floor level surveys post-earthquake is that no pre-earthquake as-built surveys exist. Therefore, an assumption must be made as to the accuracy or adherence to the prescribed tolerances at construction.

Whilst DBH has issued guidance for applicable standards for acceptable floor level tolerance in residential buildings suffering from earthquake damage, Harrison Grierson is unaware of similar guidance for commercial and industrial buildings.

The DBH document "Revised guidance on repairing and rebuilding houses affected by the Canterbury earthquake sequence" states that the maximum vertical differential settlement of a floor should be less than 50mm and the floor slope less than 1:200 (0.5%) between any two points less than 2m apart.

However, it goes on to say that international research indicates that people are not able to perceive slopes of less than 1%.

The New Zealand building Code references three separate building standards for the construction of concrete floors.

1. NZS 3109 – Concrete Construction. Floor flatness is referred to NZS 3114.
2. NZS 3114 - Concrete Surface Finishes. This code dictates the maximum tolerances allowed during construction. It is defined as 5mm change over a 3m long straight edge for a U2 class finish, typical for a carpeted floor. We note that this code is for construction tolerances and does not cover deflection or tolerance caused by sag over a long period.

3. AS/NZS 1170.0 – Structural Design Actions. Appendix C to this code gives guidelines for functionality of structural elements such as floors, beams etc. The mid span deflection limit for normal floors is given as Span/400, or approximately 16mm over 6.4m. We note that this is not a mandatory requirement but a guideline.

However, these are construction tolerances which should not necessarily apply to buildings affected by earthquake damage. Further, the nature of these premises means that high tolerances were unlikely to have been enforced during construction and are unlikely to be required for future serviceability.

On the basis that the only applicable guidance available is from DBH and although this is for domestic dwellings, it appears broadly applicable to office accommodation, therefore for the purposes of this report on this building we have taken the DBH guidance as a reasonable limit of tolerance for acceptance as earthquake damage not requiring repair to these premises.

Note that differential settlement of floor levels do not generally affect the integrity of the structure, rather the serviceability of the useable space within. Factors such as the intended use of the space, the practicality of repair and the effects of gradients on amenity of the space, need to be taken into account when assessing the results of floor level settlement.

6.2 SURVEY RESULTS

Internal levels were surveyed to an accuracy of +/- 5mm over both floors of the building. Analysis of the floor levels gave the following information.

Ground Floor

From an arbitrary datum of 0.00 the variation of level is -18 to +60mm giving an overall difference in level of 78mm. This is in excess of the DBH guidance.

The average floor slope is greater than 0.5%. The area of greatest concern is adjacent the east boundary wall in the northern office area where the last 2.5m of floor dives down at a grade of 1.7%. This is clearly noticeable once pointed out by the current occupants.

This indicates that there has been settlement of the exterior foundation ground beam in this location. Due to the floor coverings we were unable to check whether the floor has cracked but the location of the change of grade is consistent with the saw-cut line shown on the structural drawings. The floor is reinforced with 665 Mesh but it is possible that this could have been cut by the saw when the shrinkage control cuts were made.

First Floor

The variation of level on the first floor is 3.312 – 3.248m giving an overall difference in level of 64mm. This is in excess of the DBH guidance.

The average floor slope is also greater than 0.5%. The area of greatest concern is the North West office floor where the floor slope is 1.3%. Interestingly this does not correspond with the critical ground floor location. It appears that the foundation settlement mentioned above has not dragged the first floor down with it.

Recommendations

The current tenants are due to move out around the 9th September 2012. Following their departure the carpet should be lifted to fully inspect the continuity of both the ground floor slab and the first floor Hi-bond slab.

7.0 DISCUSSION – REPAIR WORKS

Repairs to remedy the identified superficial damage are as follows:

Repair Works	
Damage	Repair methodology
1. Cracks to wing wall extensions	Break out loose concrete and fill with suitable non-shrink grout. Paint to finish.
2. Loss of flexible sealant on exterior walls	Remove damaged sealant. Replace with flexible sealant (Ramset Hi-Seal, Bostik Seal-N-Flex 1, or Roadware Flexible Cement II). Paint over.
3. Cracks to internal wall partitions	Repair internal linings per the GIB Information Bulletin dated November 2011, and re-paint.
4. Hairline cracking to exterior panels	To protect reinforcing steel apply a high-build flexible paint system in accordance with manufacturer's specifications.
5. Superficial inverse pitting of bitumen pavement surface	None required.
6. Fracture of precast panels	Break out loose concrete. Completely abrade surface to produce sound concrete with good mechanical key. Fill with suitable non-shrink cementitious grout (Ramset Premier Grout MP, Sika Mono Top Structural Mortar, or Roadware Concrete Mender). Paint over.
7. Differential settlement in the floor slabs.	Further investigation required.

8.0 SEISMIC LATERAL LOAD RESISTANCE

An Initial Evaluation Procedure has been completed for the building, in the CERA excel format. As the damage observed is minor in nature, it is not likely to affect the overall lateral load capacity of the building. We can therefore conclude that the seismic resistance has not changed from its original pre-earthquake rating.

Seismic Rating		
Building	Description and when built	Rating
The Argent Building, 82 Peterborough Street, Christchurch - pre earthquake	Predominantly a two level reinforced concrete shear wall structure built in 1999	65% NBS or C grade
The Argent Building, 82 Peterborough Street, Christchurch – post earthquake	Predominantly a two level reinforced concrete shear wall structure built in 1999	65% NBS or C grade

The standardised report form prepared by CERA has been prepared and is attached to this report (Appendix 3).

9.0 FURTHER WORK

It is recommended that once the existing tenants vacate the premises in early September, floor coverings are lifted to inspect the first and second floor slabs.

Due to the measured floor slab displacement a verticality survey will also be carried out at this time.

10.0 BUILDING CONSENT

With reference to the Christchurch City Council Earthquake Prone Building policy, the building has a structural strength greater than 33% of the building code, therefore this policy does not apply. A building consent is not required for buildings with minor structural damage, as these repairs are exempt from building consent under Schedule 1 (a). Further confirmation from the Council may be required.

11.0 SUMMARY

The Argent building is a two storey concrete tilt-up building designed in 1999. Precast concrete panels resist lateral loads in both the longitudinal and the transverse direction.

Damage to the structure is generally superficial to minor in nature, however floor level surveys carried out indicate that differential settlement of the foundations may have occurred. Further investigation is required. This is more a question of serviceability limits rather than structural integrity.

Based on the above findings, we conclude that while the building has suffered minor damage, we believe that the building has no obvious structural defects that would prevent occupation. Using the IEP process, the building has a seismic rating of 65%NBS or Seismic Grade C (67% to 33% New Building Standard).

12.0 LIMITATIONS

12.1 GENERAL

This report is for the use by Christchurch City Council only for the stated purpose, and should not be used or relied upon by any other person or entity or for any other project or purpose. This report is based on our interpretation of the Initial Evaluation Procedure (IEP) process described by the New Zealand Society for Earthquake Engineering (NZSEE) recommendations titled Assessment and Improvement of the Structural Performance of buildings in Earthquakes dated June 2006. Our assessment is based principally on the information found for the building in council archives and a visual inspection. This report should be read in conjunction with the IEP worksheets and other appendices. No responsibility is accepted for the accuracy of information supplied by the Client or obtained from third party sources such as council archives and relied on for our report. The IEP process is intended as a coarse screening procedure for earthquake prone buildings and the outcome of the procedure is not intended as a definitive building rating, but to be used as a preliminary guide only. A more detailed assessment is needed if the information in this report is intended to be relied upon for any other purpose other than an initial assessment.

N:\2150\131322_02 82-84 Peterborough St\500 Del\510 Reports\82 - Argent\R001v1-CH131322-02_Argent-tck.doc

APPENDIX 1

Floor Level Survey Results

NOTES

1. LEVELS HAVE BEEN SURVEYED USING A PRO2000 ZIP LEVEL. RELATIVE ACCURACY OF LEVELS +/-5mm.
2. ALL LEVELS IN mm, RELATIVE TO ASSUMED DATUM.
3. CONTOURS ARE AT 10mm INTERVALS.
4. THESE NOTES ARE AN INTEGRAL PART OF THIS PLAN.
5. THIS PLAN IS ISSUED FOR A SPECIFIC PROJECT AND MAY NOT BE ALTERED OR USED FOR ANY OTHER PURPOSE WITHOUT THE PRIOR WRITTEN CONSENT OF HARRISON GRIERSON.



ADVISORS AND DESIGNERS
Office of Origin: Christchurch
Level 1, 84 Peterborough Street
Christchurch 8013
P +64 3 962 9770
www.harrisongrierson.com

REF	REVISIONS	BY	DATE
-----	-----------	----	------

PROJECT:
**82-84 PETERBOROUGH STREET
CHRISTCHURCH**

TITLE:
**FLOOR LEVEL SURVEY
ARGENT BUILDING
GROUND FLOOR**

ORIGINATOR: EYS	DATE: 06.08.12	SIGNED:	PLOT BY: EYS
DRAWN: EYS	DATE: 06.08.12	SIGNED:	PLOT DATE: 15.08.12
CHECKED: ISW	DATE:	SIGNED:	SURVEY BY:
APPROVED: DXM	DATE: <i>K/L</i>	SIGNED: <i>Pine</i>	SURVEY DATE:


ISSUE STATUS:

PROJECT No: 2150-131322	SCALES: 1:50 A1 1:100 A3	A1
DRAWING No:		REV

131322-051
A

LEGEND

- CONTOUR
- ← 1.7% GRADE DOWN
- 0.032 POINT ELEVATION
- GULLY



NOTES

1. LEVELS HAVE BEEN SURVEYED USING A PRO2000 ZIP LEVEL. RELATIVE ACCURACY OF LEVELS +/-5mm.
2. ALL LEVELS IN mm, RELATIVE TO ASSUMED DATUM.
3. CONTOURS ARE AT 10mm INTERVALS.
4. THESE NOTES ARE AN INTEGRAL PART OF THIS PLAN.
5. THIS PLAN IS ISSUED FOR A SPECIFIC PROJECT AND MAY NOT BE ALTERED OR USED FOR ANY OTHER PURPOSE WITHOUT THE PRIOR WRITTEN CONSENT OF HARRISON GRIERSON.



HARRISON
GRIERSON

ADVISORS AND DESIGNERS
Office of Origin: Christchurch
Level 1, 84 Peterborough Street
Christchurch 8013
P +64 3 962 9770
www.harrisongrierson.com

REF	REVISIONS	BY	DATE
-----	-----------	----	------

PROJECT:
**82-84 PETERBOROUGH STREET
CHRISTCHURCH**


TITLE:
**FLOOR LEVEL SURVEY
ARGENT BUILDING
FIRST FLOOR**

ORIGINATOR: EYS	DATE: 06.08.12	SIGNED:	PLOT BY: EYS
DRAWN: EYS	DATE: 06.08.12	SIGNED:	PLOT DATE: 15.08.12
CHECKED: ISW	DATE:	SIGNED:	SURVEY BY:
APPROVED: DXM	DATE: 16/8	SIGNED: <i>[Signature]</i>	SURVEY DATE:

PROJECT No: 2150-131322	SCALES: 1:50 A1 1:100 A3	A1
DRAWING No: 131322-052	REV A	

LEGEND

- CONTOUR
- 0.9% GRADE DOWN
- 3.258 POINT ELEVATION



FIRST FLOOR
(ARGENT BUILDING)

APPENDIX 2

Marked Up Drawings Showing Damage Locations



- 1 *Fraxinus* Raywoodii
- 2 *Eugenioides* "Mini Green"
- 3 *Agapanthus* (blue) @ 500 cirs
- 4 *Cholysa* Temata @ 1.0m cirs

Tel 03 366 0323
Fax 03 379 8269
email ika@xtra.co.nz

Lot : 1
DP : 4922
CT : 350/94, 350/95
Area : 13648gm

NATIONWIDE BUILDING CERTIFIERS LTD

THESE PLANS AND SPECIFICATIONS ARE APPROVED
NATIONWIDE BUILDING CERTIFIERS LTD AS MEETING THE
REQUIREMENTS OF THE BUILDING CODE AND SUBJECT
SUCH CONDITIONS AS ARE ENDORSED HEREON.

BUILDING CERTIFICATE No:
00316

SIGNED FOR AND ON BEHALF OF NATIONWIDE BUILDING CERTIFIERS LTD

BUILDING CERTIFIER

SIGNED: [Signature] DATE: 5/8/99

THE APPROVAL OF THIS PROJECT IS SUBJECT TO COMPLIANCE WITH THE CONDITION(S) LISTED ON THE ACCOMPANYING BUILDING CERTIFICATE ISSUED BY NATIONWIDE BUILDING CERTIFIERS LIMITED.

THIS BUILDING PROJECT HAS
BEEN APPROVED TO THESE
PLANS ONLY. ANY VARIATIONS
OR CHANGES MUST BE
APPROVED BY NATIONWIDE
BUILDING CERTIFIERS LIMITED.

THESE PLANS AND
ACCOMPANYING DOCUMENTS
MUST BE KEPT ON THE
CONSTRUCTION SITE

FILE COPY
CHRISTCHURCH CITY COUNCIL
CONSENT DECISION
10 AUG 1999
All building work shall comply with New Zealand Building Code now standing any inconsistencies which occur in the drawings and specifications

DATE: *JULY 1999*

SCALE:
1 : 100, 1 : 50


JOB NO: 1381


SHEET NO:
A1.01
OF SHEETS



AFS Building

21 JUL 1999





AFS Building
First Floor

- (F)
- (E) 65mm dia. penetrate 1
- wade W 1
- wade W 1
- (D) butyl rubb. plywood
- (C) 50mm dia penetrate
- wade W 1
- 65mm dia penetrate
- (B)

(A)

APPENDIX 3

Detailed Engineering IEP Evaluation Sheets

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name: The Argent Building Unit No: Street
Building Address: 82 Peterborough Street
Legal Description: Lot 1, DP 81332
Degrees Min Sec
GPS south:
GPS east:
Building Unique Identifier (CCC):

Reviewer: Andrew Thompson
CPEng No: 149819
Company: Harrison Grierson Consultants Limited
Company project number: 2150-131322-02
Company phone number: 9175000

Date of submission:
Inspection Date: 12/05/2011, 13/05/2011, 21/06/2011, 9/01/2012
Revision: 1
Is there a full report with this summary? yes

Site

Site slope: flat
Soil type: mixed
Site Class (to NZS1170.5): D
Proximity to waterway (m, if <100m):
Proximity to clifftop (m, if < 100m):
Proximity to cliff base (m, if <100m):

Max retaining height (m):
Soil Profile (if available):

If Ground improvement on site, describe:
Approx site elevation (m): 4.00

Building

No. of storeys above ground: 2
Ground floor split? no
Storeys below ground: 0
Foundation type: strip footings
Building height (m): 7.80
Floor footprint area (approx): 190
Age of Building (years): 13

single storey = 1

Ground floor elevation (Absolute) (m): 4.10
Ground floor elevation above ground (m): 0.10

if Foundation type is other, describe:
height from ground to level of uppermost seismic mass (for IEP only) (m): 7.8

Date of design: 1992-2004

Strengthening present? no

If so, when (year)?
And what load level (%g)?
Brief strengthening description:

Use (ground floor): commercial
Use (upper floors): commercial
Use notes (if required):
Importance level (to NZS1170.5): IL2

Gravity Structure

Gravity System: load bearing walls
Roof: steel framed
Floors: other (note)
Beams: precast concrete
Columns:
Walls: load bearing concrete

rafter type, purlin type and cladding describe sytem overall depth (mm)
310UB40 rafters, DHS purlins, lightweight metal roof
HIBOND floor slabs
#N/A

Lateral load resisting structure

Lateral system along: concrete shear wall
Ductility assumed, μ : 1.25
Period along: 0.42
Total deflection (ULS) (mm):
maximum interstorey deflection (ULS) (mm):
Lateral system across: concrete shear wall
Ductility assumed, μ : 1.25
Period across: 0.42
Total deflection (ULS) (mm):
maximum interstorey deflection (ULS) (mm):

Note: Define along and across in detailed report!
enter height above at H31

enter height above at H31

note total length of wall at ground (m):
wall thickness (m):
estimate or calculation? estimated
estimate or calculation?
estimate or calculation?

note total length of wall at ground (m):
wall thickness (m):
estimate or calculation? estimated
estimate or calculation?
estimate or calculation?

Separations:

north (mm):
east (mm):
south (mm):
west (mm):

leave blank if not relevant

Non-structural elements

Stairs: precast, full flight
Wall cladding: precast panels
Roof Cladding: Metal
Glazing:
Ceilings: light tiles
Services(list): HVAC

describe supports
thickness and fixing type
describe
150mm
Lightweight metal roof
Suspended lightweight ceiling

Available documentation

Architectural: partial
Structural: partial
Mechanical: none
Electrical: none
Geotech report: none

original designer name/date
original designer name/date
original designer name/date
original designer name/date
original designer name/date

Damage

Site:
(refer DEE Table 4-2)

Site performance:
Settlement: none observed
Differential settlement: none observed
Liquefaction: none apparent
Lateral Spread: none apparent
Differential lateral spread: none apparent
Ground cracks: none apparent
Damage to area: moderate to substantial (1 in 5)

Describe damage: refer to HG standard spreadsheet

notes (if applicable):
notes (if applicable):
notes (if applicable):
notes (if applicable):
notes (if applicable):
notes (if applicable):
notes (if applicable):

Building:

Current Placard Status: green

Along

Damage ratio: 0%
Describe (summary):

Describe how damage ratio arrived at: estimated

Across

Damage ratio: 0%
Describe (summary):

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

Diaphragms

Damage?: no

Describe:

CSWs:

Damage?: no

Describe:

Pounding:

Damage?: no

Describe:

Non-structural:

Damage?: yes

Describe: Cracks to precast panels & partitions

Recommendations

Level of repair/strengthening required: minor structural
Building Consent required: no
Interim occupancy recommendations: full occupancy

Describe: Cracks to precast panels & partitions
Describe:
Describe: No major structural damage

Along

Assessed %NBS before: 65%
Assessed %NBS after: 65%
%NBS from IEP below

If IEP not used, please detail assessment methodology:
See attached HG standard IEP report

Across

Assessed %NBS before: 65%
Assessed %NBS after: 65%
%NBS from IEP below

IEP

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1992-2004

Seismic Zone, if designed between 1965 and 1992:

hn from above: 7.8m

not required for this age of building

Design Soil type from NZS4203:1992, cl 4.6.2.2:

Period (from above):

(%NBS)nom from Fig 3.3:

along

0.42

across

0.42

Note: 1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0

Note 2: for RC buildings designed between 1976-1984, use 1.2

Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)

Final (%NBS)nom:

along

0%

across

0%

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

Near Fault scaling factor (1/N(T,D), **Factor A**:

along

#DIV/0!

across

#DIV/0!

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:

Z1992, from NZS4203:1992

Hazard scaling factor, **Factor B**:

across

#DIV/0!

2.4 Return Period Scaling Factor

Building Importance level (from above):

Return Period Scaling factor from Table 3.1, **Factor C**:

2

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2)

Ductility scaling factor: =1 from 1976 onwards; or =kμ, if pre-1976, from Table 3.3:

along

across

Ductility Scaling Factor, **Factor D**:

1.00

1.00

2.6 Structural Performance Scaling Factor:

Sp:

Structural Performance Scaling Factor **Factor E**:

#DIV/0!

#DIV/0!

2.7 Baseline %NBS, (NBS%)b = (%NBS)nom x A x B x C x D x E

%NBSb:

#DIV/0!

#DIV/0!

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

3.2. Vertical irregularity, Factor B:

3.3. Short columns, Factor C:

3.4. Pounding potential

3.5. Site Characteristics

Pounding effect D1, from Table to right

Height Difference effect D2, from Table to right

Therefore, Factor D:

1

1

1

0

1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum

Rationale for choice of F factor, if not 1

Along

Across

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any:

Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

0.00

0.00

4.3 PAR x (%NBS)b:

PAR x Baselline %NBS:

#DIV/0!

#DIV/0!

4.4 Percentage New Building Standard (%NBS), (before)

#DIV/0!

Official Use only:

Accepted By

Date:


Table IEP-1 Initial Evaluation Procedure Step 1

Page 1


Building Name:	The Argent Building	Ref: 2150-131322-02
Location:	82 Peterborough Street, Christchurch	By: MCW
		Date: 20/08/2012

Step 1 - General Information

1.1 Photos (attach sufficient to describe building)



1.2 Sketch of building plan



1.3 List relevant features

Built c1999, Two storey office building, lateral load resisting systems RC panel walls supporting either the light metal roof or the HIBOND concrete floor slabs, ductility $\mu = 1.25$

1.4 Note information sources

Visual Inspection of Exterior
 Visual Inspection of Interior
 Drawings (partial set only)
 Specifications
 Geotechnical Reports
 Other (list)

Mark as appropriate

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Table IEP-2: Initial Evaluation Procedure – Step 2

Table IEP-2 Initial Evaluation Procedure Step 2

(Refer Table IEP - 1 for Step 1; Table IEP - 3 for Step 3; Table IEP - 4 for Steps 4, 5 and 6)

Page 2

Building Name:	The Argent Building	Ref:	2150-131322-02
Location:	82 Peterborough Street, Christchurch	By:	MCW
Date: 20/08/2012			

Step 2 - Determination of (%NBS)_b

2.1 Determine nominal (%NBS) = (%NBS)_{nom}

a) Date of Design and Seismic Zone

Pre 1935
1935-1965
1965-1976

1976-1992

1992-2004

Seismic Zone

A
B
C
A
B
C

Mark as appropriate

☐
☐
☐
☐
☐
☐
☐
☒

See also notes 1,3

See also note 2

b) Soil Type

From NZS1170.5:2004, Cl 3.1.3

A or B Rock
C Shallow Soil
D Soft Soil
E Very Soft Soil

From NZS4203:1992, Cl 4.6.2.2

(for 1992 to 2004 only and only if known)

a) Rigid
b) Intermediate

	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
	<input type="checkbox"/> <input type="checkbox"/>

c) Estimate Period, T

$T = 0.09h_n^{0.75}$	Moment Resisting Concrete Frames	where h_n = height in m from base to upper most seismic weight or mass. $A_c = \sum A_i(0.2 + L_{wi}/h_n)^2$,
$T = 0.14h_n^{0.75}$	Moment Resisting Steel Frames	A_i = cross-sectional shear area of shear wall
$T = 0.08h_n^{0.75}$	Eccentrically Braced Steel Frames	i' in the first storey of the building in m ² .
$T = 0.06h_n^{0.75}$	All Other Frame Structures	L_{wi} = length of shear wall 'i' in the first storey on the direction parallel to the applied force, in m
$T = 0.09h_n^{0.75}/A_c^{0.5}$	Concrete Shear Walls	with the restriction that L_{wi}/h_n not exceed 0.9
$T \leq 0.4$ sec	Masonry Shear Walls	
-	User Defined (input period)	

	Longitudinal	Transverse
Eqn	CSW ▼	CSW ▼
h_n =	7.8	7.8
A_c =	1.0	1.0
T =	0.42	0.42
		s

d) (%NBS)_{nom} determined from Figure 3.3

Longitudinal
Transverse

22.39%
22.39%

Note 1 For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)_{nom} by 1.25.
For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)_{nom} by 1.33 (Zone A) or 1.2 (Zone B)

Note 2 For reinforced concrete buildings designed between 1976-84 multiply (NBS)_{nom} by 1.2

Note 3 For Buildings designed prior to 1935 multiply (%NBS)_{nom} by 0.8 except for Wellington where the factor may be taken as 1

(%NBS)_{nom} -scaled

Longitudinal
Transverse

22%
22%

Table IEP-2: Initial Evaluation Procedure – Step 2 Continued

Table IEP-2 Initial Evaluation Procedure Step 2

Page 3

2.2 Near Fault Scaling Factor, Factor A If $T \leq 1.5\text{sec}$, Factor A = 1

a) Near Fault Factor, $N(T,D)$
(from NZS1170.5:2004, Cl 3.1.6)

Longitudinal: 1.0
Transverse: 1.0

b) Near Fault Scaling Factor = $1/N(T,D)$

Factor A
Longitudinal: 1.0
Transverse: 1.0

2.3 Hazard Scaling Factor, Factor B

a) Hazard Factor, Z, for site Site Area:
(from NZS1170.5:2004, Table 3.3)

Z = 0.3

b) Hazard Scaling Factor Pre 1992 = $1/Z$
1992/1992+ = Z_{1992}/Z Zone Factor = 0.8
(where Z_{1992} is the NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Factor B
2.67

2.4 Return Period Scaling Factor, Factor C

a) Building Importance Level
(from NZS1170.0:2004, Table 3.1 and 3.2)

2.0

b) Return Period Scaling Factor from accompanying Table 3.1

Factor C
1.0

2.5 Ductility Scaling Factor, D

a) Assessed Ductility of Existing Structure, μ
(shall be less than maximum given in accompanying table 3.2)

Max = 6

μ = 1.25 Longitudinal
 μ = 1.25 Transverse

b) Ductility Scaling Factor Pre 1976 = k_μ
1976/1976+ = 1

Factor D
Longitudinal: 1.00
Transverse: 1.00

2.6 Structural Performance Scaling Factor, Factor E

a) Structural Performance Factor, S_p
(from accompanying Figure 3.4)

Longitudinal: 0.925
Transverse: 0.925

b) Structural Performance Scaling Factor = $1/S_p$

Factor E
Longitudinal: 1.49
Transverse: 1.49

2.7 Baseline %NBS for Building, (%NBS)_b

(equals (%NBS)_{nom} x A x B x C x D x E)

Longitudinal: 89%
Transverse: 89%

Table IEP-3: Initial Evaluation Procedure – Step 3

Table IEP-3 Initial Evaluation Procedure Step 3 A- Longitudinal Direction

Page 4

Building Name:	The Argent Building	Ref.	2150-131322-02
Location:	82 Peterborough Street, Christchurch	By:	MCW
Direction Considered:	Longitudinal		
		Date:	20/08/2012

Step 3 - Determination of (%NBS)_b

(Refer Appendix B - Section B3.2)

Critical Structural Weakness

Effect on Structural Performance

Building Score

3.1 Plan Irregularity

Effect on Structural Performance:

☐
☐
☒

Comment:

Factor A **1.0**

3.2 Vertical Irregularity

Effect on Structural Performance:

☐
☐
☒

Comment:

Factor B **1.0**

3.3 Short Columns

Effect on Structural Performance:

☐
☐
☒

Comment:

Factor C **1.0**

3.4 Pounding Potential

(Estimate D1 and D2 and set D = to lower of the two, or = 1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings

Factor D1 For Longitudinal Direction **1.0**

Table for Selection Factor D1	Severe	Significant	Insignificant
Separation:	0<Sep<0.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Alignment of Floors not within 20% of Storey Height	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2 For Longitudinal Direction **1.0**

Table for Selection Factor D2	Severe	Significant	Insignificant
Separation:	0<Sep<0.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Height Difference 2 to 4 Storeys	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Height Difference < 2 Storeys	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Factor D **1.0**

3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)

Effect on Structural Performance:

☐
☐
☒

Factor E **1.0**

3.6 Other Factors

Record rationale for choice of Factor F:

For For < 3 storeys - Maximum value 2.5,
otherwise - Maximum value 1.5. No minimum.

Factor F **1.0**

2.7 Performance Achievement Ratio (PAR)

(equals A x B x C x D x E x F)

PAR (Longitudinal): **1.00**

Table IEP-3: Initial Evaluation Procedure – Step 3

Table IEP-3 Initial Evaluation Procedure Step 3 B- Transverse Direction

Page 5

Building Name:	The Argent Building	Ref.	2150-131322-02
Location:	82 Peterborough Street, Christchurch	By:	MCW
Direction Considered:	Transverse		
		Date:	20/08/2012

Step 3 - Determination of (%NBS)_b

(Refer Appendix B - Section B3.2)

Critical Structural Weakness

Effect on Structural Performance

Building Score

3.1 Plan Irregularity

Effect on Structural Performance:

☐
☐
☒

Comment:

Factor A **1.0**

3.2 Vertical Irregularity

Effect on Structural Performance:

☐
☐
☒

Comment:

Factor B **1.0**

3.3 Short Columns

Effect on Structural Performance:

☐
☐
☒

Comment:

Factor C **1.0**

3.4 Pounding Potential

(Estimate D1 and D2 and set D = to lower of the two, or = 1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings

Factor D1 For Transverse Direction **1.0**

Table for Selection Factor D1	Severe	Significant	Insignificant
Separation:	0<Sep<0.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Alignment of Floors not within 20% of Storey Height	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2 For Transverse Direction **1.0**

Table for Selection Factor D2	Severe	Significant	Insignificant
Separation:	0<Sep<0.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Height Difference 2 to 4 Storeys	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Height Difference < 2 Storeys	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Factor D **1.0**

3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)

Effect on Structural Performance:

☐
☐
☒

Factor E **1.0**

3.6 Other Factors

Record rationale for choice of Factor F:

For For < 3 storeys - Maximum value 2.5,
otherwise - Maximum value 1.5. No minimum.

Factor F **1.0**

2.7 Performance Achievement Ratio (PAR)

(equals A x B x C x D x E x F)

PAR (Transverse): **1.00**

Table IEP-4: Initial Evaluation Procedure – Step 4

Table IEP-4 Initial Evaluation Procedure Step 3 B- Transverse Direction

Page 6

Building Name:	The Argent Building	Ref. 2150-131322-02
Location:	82 Peterborough Street, Christchurch	By: MCW
		Date: 20/08/2012

Step 4 - Percentage of New Building Standard (%NBS)

	Longitudinal	Transverse
4.1 Assessed Baseline (%NBS)_b (from Table IEP - 1)	89%	89%
4.2 Performance Achievement Ratio (PAR) (from Table IEP - 2)	1	1
4.3 PAR x Baseline (%NBS)_b	89%	89%
4.4 Percentage New Building Standard (%NBS) (Use lower of two values from Step 3.3)		89%

Step 5 - Potentially Earthquake Prone? (Mark as appropriate)	%NBS ≤ 33%	NO
--	-------------------	----

Step 6 - Potentially Earthquake Risk? (Mark as appropriate)	%NBS < 67%	NO
---	----------------------	----

Step 7 - Provisional Grading for Seismic Risk based on IEP

Seismic Grade	A
----------------------	---

Evaluation Confirmed by...  Signature

Andrew Thompson Name

149819 CPEng. No.

Relationship between Seismic Grade and %NBS :

Grade	A+	A	B	C	D	E
%NBS	>100	100 to 80	80 to 67	67 to 33	33 to 20	<20

DRAWINGS