

# Ascot Community Centre Detailed Engineering Evaluation BU 1306-003 EQ2 Qualitative Report

**Prepared for Christchurch City Council (CCC)**

**By Beca Carter Hollings & Ferner Ltd (Beca)**

14 June 2013

© Beca 2013 (unless Beca has expressly agreed otherwise with the Client in writing).


This report has been prepared by Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.



## Revision History

Revision N°	Prepared By	Description	Date
A	Andrew Sporn	Draft for CCC review	9 October 2012
B	Andrew Sporn	Final	14 June 2013

## Document Acceptance

Action	Name	Signed	Date
Prepared by	Andrew Sporn		14 June 2013
Reviewed by	Nicholas Charman		14 June 2013
Approved by	David Whittaker		14 June 2013
on behalf of	Beca Carter Hollings & Ferner Ltd		

## Ascot Community Centre BU1306-003 EQ2

### Detailed Engineering Evaluation Qualitative Report – SUMMARY Version 1

#### Address

12 Ascot Avenue,  
Parklands, Christchurch



## Background

This is a summary of the Qualitative report for the building structure, and is based on the document 'Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury – Part 2 Evaluation Procedure' (draft) issued by the Engineering Advisory Group (EAG) on 19 July 2011.

The Ascot Community Centre is located at 12 Ascot Avenue, Parklands, Christchurch. It is assumed to have been built in 1968 (from information contained in a newspaper article about the opening) and has an approximate floor area of 290m<sup>2</sup> internally. It is currently used as a multipurpose community hall. The building is generally rectangular in plan and the main structural system comprises of concrete masonry block walls and timber/steel roof framing. No structural drawings were obtained and no calculations were carried out.

## Key Damage Observed

Visual inspections on 7 August 2012 indicate the building has suffered minor structural earthquake damage. The key damage observed includes:

- n Cracking in the plasterboard ceiling panels.
- n Minor cracking to the external concrete ground slab under the balustrade outside of the building.
- n We understand that there was damage to the internal masonry block walls. This damage appears to have been repaired.

## Critical Structural Weaknesses (CSW)

The following Critical Structural Weakness (CSW) was identified based on the structural inspection conducted on 7 August 2012:

- n Site characteristics: significant liquefaction potential due to widespread liquefaction observed in the surrounding area.

## Indicative Building Strength (from Initial Evaluation Procedure and CSW assessment)

The building has been assessed to have a seismic capacity of 36%NBS using the NZSEE Initial Evaluation Procedure (IEP) and is therefore classified as potentially Earthquake Risk and Seismic Grade C.

## Recommendations

In order that the owner can make an informed decision about the on-going use and occupancy of their building the following information is presented in line with the Department of Building and Housing document '*Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch*', June 2012.

The building is considered to be potentially earthquake risk, having an assessed capacity of between 34% and 67%NBS. The risk of collapse of an earthquake risk building is considered to be 5 to 10 times greater than that of an equivalent new building.

No significant damage or hazards were identified to the seismic or gravity load resisting system that would reduce its ability to resist further loads and therefore no restrictions on use or occupancy are recommended.

It is recommended that:

- n Further efforts are made to obtain structural drawings.
- n A verticality and level survey could be carried out to determine the extent of settlement of the building for insurance purposes.
- n Based on the use of the building and the %NBS score we recommend a Quantitative Assessment is carried out to give a more reliable %NBS assessment.
- n Repairs that would bring the building back to an "as new" condition are typically entitled under typical replacement insurance policies. We suggest you consult with your insurance advisor as to how you wish to proceed.

## Table of Contents

<b>Qualitative Report – SUMMARY</b> .....	<b>ii</b>
<b>1 Background</b> .....	<b>1</b>
<b>2 Compliance</b> .....	<b>1</b>
2.1 Canterbury Earthquake Recovery Authority (CERA).....	1
2.2 Building Act .....	2
2.3 Christchurch City Council Policy.....	3
2.4 Building Code .....	3
<b>3 Earthquake Resistance Standards</b> .....	<b>4</b>
<b>4 Building Description</b> .....	<b>5</b>
4.1 General .....	5
4.2 Structural ‘Hot-spots’ .....	6
<b>5 Site Investigations</b> .....	<b>6</b>
5.1 Previous Assessments.....	6
5.2 Level 4 Damage Inspection.....	7
<b>6 Damage Assessment</b> .....	<b>7</b>
6.1 Damage Summary.....	7
6.2 Surrounding Buildings.....	8
6.3 Residual Displacements and General Observations.....	8
6.4 Implication of Damage .....	8
<b>7 Generic Issues</b> .....	<b>8</b>
<b>8 Critical Structural Weaknesses</b> .....	<b>8</b>
8.1 Site Characteristics.....	8
<b>9 Geotechnical Consideration</b> .....	<b>8</b>
<b>10 Survey</b> .....	<b>9</b>
<b>11 Initial Capacity Assessment</b> .....	<b>9</b>
11.1 %NBS Assessment.....	9
11.2 Seismic Parameters.....	9
11.3 Expected Structural Ductility Factor .....	9
11.4 Discussion of results.....	10
<b>12 Initial Conclusions</b> .....	<b>10</b>
<b>13 Recommendations</b> .....	<b>10</b>
13.1 Occupancy .....	10
13.2 Further Investigations, Survey or Geotechnical Work .....	10
13.3 Damage Reinstatement .....	10
<b>14 Design Features Report</b> .....	<b>11</b>
<b>15 Limitations</b> .....	<b>11</b>

## Appendices

**Appendix A - Photographs**

**Appendix B - CERA DEE Summary Data**

**Appendix C - Previous Reports and Assessments**

## 1 Background

Beca Carter Hollings & Ferner Ltd (Beca) has been engaged by Christchurch City Council (CCC) to undertake a qualitative Detailed Engineering Evaluation (DEE) of the Ascot Community Centre located at 12 Ascot Avenue, Parklands, Christchurch.

This report is a Qualitative Assessment of the building structure, and is based on the document 'Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury – Part 2 Evaluation Procedure' (draft) issued by the Engineering Advisory Group (EAG) on 19 July 2011.

A qualitative assessment involves inspections of the building, a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available and an assessment of the level of seismic capacity against current code using the Initial Evaluation Procedure (IEP).

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential Critical Structural Weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of New Building Standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure has been carried out. No drawings were available and hence this report is based on our visual inspection of the building only.

The format and content of this report follows a template provided by CCC, which is based on the EAG document.

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building

Act). It is understood that CERA is adopting the Detailed Engineering Evaluation Procedure document (draft) issued by the Engineering Advisory Group on 19 July 2011, which sets out a methodology for both qualitative and quantitative assessments. We understand this report will be used in response to CERA Section 51.

The qualitative assessment includes a thorough visual inspection of the building coupled with a desktop review of available documentation such as drawings, specifications and IEP's. The quantitative assessment involves analytical calculation of the building's strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- n The importance level and occupancy of the building
- n The placard status that was assigned during the state of emergency following the 22 February 2011 earthquake
- n The age and structural type of the building
- n Consideration of any Critical Structural Weaknesses
- n The extent of any earthquake damage

## 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

### Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- n In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- n In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- n There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- n There is a risk that that other property could collapse or otherwise cause injury or death; or
- n A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

## Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

## Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

## Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

### 2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- n A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- n A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- n A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- n Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

It is understood that any building with a capacity of less than 33%NBS (including consideration of Critical Structural Weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- n The accessibility requirements of the Building Code.
- n The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

### 2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a. Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)

- b. Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

### 3 Earthquake Resistance Standards

For this assessment, the building's Ultimate Limit State earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

No consideration has been given at this stage to checking the level of compliance against the increased Serviceability Limit State requirements.

The likely ultimate capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a building's capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 3.1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

**Figure 3.1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 3.1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. on average 0.2% in any year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

**Table 3.1: %NBS compared to relative risk of failure**

Building Grade	Percentage of New Building Standard (%NBS)	Approx. Risk Relative to a New Building
A+	>100	<1
A	80-100	1-2 times
B	67-80	2-5 times
C	33-67	5-10 times
D	20-33	10-25 times
E	<20	>25 times

## 4 Building Description

### 4.1 General

Summary information about the building is given in the following table.

**Table 4.1: Building Summary Information**

Item	Details	Comment
Building name	Ascot Community Centre	
Street Address	12 Ascot Avenue, Parklands, Christchurch	
Age	44 years	Constructed in 1968. Based on a newspaper article about the opening of the building.
Description	The Ascot Community Centre is a multipurpose community space, surrounded by a golf course. The building is generally rectangular in plan and is a single storey structure with the main structural elements being concrete masonry walls.	
Building Footprint / Floor Area	26m x 11m, 290m <sup>2</sup> internally	
No. of storeys / basements	1 / No basement	
Occupancy / use	Multipurpose community centre	Importance Level 2 (capacity less than 300)
Construction	The main structural system is concrete masonry walls. Given the age of the building it is likely that the masonry is partially filled and lightly reinforced. The roofing consists of lightweight metal sheeting supported by timber/steel purlins and timber/steel rafters spanning between the external masonry walls.	Based on visual inspection. No drawings available.  The roof structure was concealed by the ceiling.

Item	Details	Comment
Gravity load resisting system	The gravity loads from the roof are supported by timber/steel purlins spanning between steel rafters which transmit the load into load bearing concrete masonry walls. Gravity loads from the floor are supported by a concrete slab on grade.	No drawings available.
Seismic load resisting system	The lateral loads in both directions are resisted by the partially filled concrete masonry shear walls. The lateral load from the walls is transmitted into the foundations. It is unknown if there is a concealed roof diaphragm (e.g. timber sarking) or bracing to transmit lateral load from the roof to the walls. Some areas appear to have a fixed plasterboard ceiling which may act as a roof diaphragm.	No drawings available.
Foundation system	Unknown, but assumed to be shallow foundations with a concrete slab on grade.	No drawings available.
Stair system	No stairs	
Other notable features		
External works	Paved and landscaped courtyard.	
Construction information	Visual inspections	No drawings available.
Likely design standard	NZSS 1900 Chapter 8:1965	Inferred from age of building.
Heritage status	Not heritage listed	
Other		

## 4.2 Structural 'Hot-spots'

- n Connections between the roof diaphragm and the walls.
- n Shear strength of masonry walls.
- n Out of plane capacity of masonry block walls.

## 5 Site Investigations

### 5.1 Previous Assessments

The building had a level 2 rapid assessment undertaken following June 2011 earthquake (refer to Appendix C). The June 2011 Rapid Assessment notes that repair works were in progress at the time of the inspection. It is therefore likely that some of the damage caused by the earthquakes is no longer visible.

## 5.2 Level 4 Damage Inspection

Visual inspections as part of the level 4 damage assessment were undertaken on 7 August 2012. Photographs were taken as a record of inspection.

## 6 Damage Assessment

### 6.1 Damage Summary

The table below provides a summary of damage observed during our inspection. Refer to Appendix A for photographs of the observed damage. As noted in Section 5.1 some earthquake damage repair work has been completed.

**Table 6.1: Damage Summary**

Damage type					Comment
	Unknown	Minor	Moderate	Major	
settlement of foundations	ü				None observed during visual inspection. Level survey may be required to confirm.
tilt of building	ü				None observed during visual inspection. Verticality survey may be required to confirm.
liquefaction	ü				No liquefaction was observed during visual inspection. Aerial photographs taken on 24 February 2011 show there was a high degree of liquefaction observed in the area surrounding the site (refer Appendix A)
settlement of external ground	ü				None observed during visual inspection.
lateral spread / ground cracks	ü				None observed during visual inspection.
frame					No damage observed during visual inspection.
masonry walls					No damage observed during visual inspection. The previous level two assessment noted damage to the masonry walls with repairs underway at the time of the level 2 inspection.
cracking to concrete floors		ü			Minor cracking was observed in the concrete path outside the building.
bracing	ü				Roof bracing, if present, was obscured by the fixed ceiling.
precast flooring seating					Not Applicable
stairs					Not Applicable
cladding /envelope		ü			Minor damage was observed in the ceiling plasterboard lining.
internal fit out					No damage was observed during visual inspection.

Damage type					Comment
	Unknown	Minor	Moderate	Major	
building services	ü				Building services were not inspected.
other					Not Applicable

## 6.2 Surrounding Buildings

The Ascot Community Centre is adjacent to a golf course and is not in close proximity to any other buildings.

## 6.3 Residual Displacements and General Observations

No evidence of permanent settlement or displacements were observed during our visual inspection, however a global settlement survey may reveal movement that could be described as damage under insurance entitlement.

## 6.4 Implication of Damage

Other than minor localised cracking in the plasterboard ceiling no superstructure damage was observed during our visual inspection and therefore we believe the structural capacity has not been materially affected.

## 7 Generic Issues

The following generic issues referred to in Appendix A of the EAG guideline document have been identified as applicable to the Ascot Community Centre:

### Partially Filled Concrete Masonry Walls

- n Inadequate shear and/or flexural strength of the concrete masonry walls.
- n Inadequate connection of roof diaphragm to the walls.

## 8 Critical Structural Weaknesses

Based on the inspection of the building conducted on 7 August 2012 the following Critical Structural Weakness (CSW) was observed.

### 8.1 Site Characteristics

Based on the aerial reconnaissance on 24 February 2011 evidence of liquefaction was visible on the site. Consequently a significant site characteristic factor of 0.7 representing significant liquefaction was used to assess the %NBS in the IEP assessment of the building.

## 9 Geotechnical Consideration

No geotechnical information was available for this site. During the inspection, any damage to the surrounding pavement was noted and any affect to the structure was considered.

## 10 Survey

No level or verticality surveys were carried out as there was no evidence of settlement or displacement observed during the inspection. CCC may wish to undertake a level survey as part of insurance entitlement considerations.

## 11 Initial Capacity Assessment

### 11.1 %NBS Assessment

The building has had its seismic capacity assessed using the Initial Evaluation Procedure based on the assumed age, visually determined construction type and assessed structural system. The building's capacity is expressed as a percentage of New Building Standard (%NBS) and is in the order of that shown below in Table 11.1. A factor of 2.5 has been selected for the F factor as the building is a simple single storey structure and no damage other than cracking in the plasterboard ceiling was observed during the inspection (and minor cracking to internal blockwalls which had been repaired prior to inspection). These capacities are subject to confirmation by a quantitative analysis which is more detailed. The post-damage capacity is considered to be the same as the original capacity.

**Table 11.1: Indicative Building Capacities**

System	Direction	Seismic Performance in %NBS	Notes
Partially filled, reinforced, concrete masonry shear walls.	Longitudinal	36%	NZSEE Initial Evaluation Procedure. IL 2, Z=0.3.
Partially filled, reinforced, concrete masonry shear walls.	Transverse	36%	NZSEE Initial Evaluation Procedure. IL 2, Z=0.3.

### 11.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS1170:2004 and the NZBC clause B1 for this building are:

- n Site soil class: D – NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- n Site hazard factor,  $Z = 0.3$  – NZBC, Clause B1 Structure, Amendment 11 effective from 19 May 2011
- n Return period factor  $R_u = 1$  – NZS 1170.5:2004, Table 3.5, Importance level 2 structure with a 50 year design life.
- n Near fault factor  $N(T,D) = 1$  – NZS 1170.5:2004, Clause 3.1.6, Distance more than 20 km from fault line.

### 11.3 Expected Structural Ductility Factor

The lateral load resisting system in both directions is partially filled, lightly reinforced concrete masonry shear walls which have been assumed to have a ductility factor of 1.25 in the IEP assessment.

## 11.4 Discussion of results

Based on the IEP results, the Ascot Community Centre is considered potentially Earthquake Risk and Seismic Grade C as the IEP result is between 33%NBS and 67%NBS. This assessment is qualitative and based on the NZSEE IEP only.

## 12 Initial Conclusions

- n Minor structural earthquake damage observed.
- n The building has been assessed to have a seismic capacity of 36%NBS and is therefore classified as potentially Earthquake Risk.
- n A Critical Structural Weakness has been identified but its impact on the structure is not considered significant.

## 13 Recommendations

### 13.1 Occupancy

In order that the owner can make an informed decision about the on-going use and occupancy of their building the following information is presented in line with the Department of Building and Housing document '*Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch*', June 2012.

The building is considered to be potentially earthquake risk, having an assessed capacity of between 34% and 67%NBS. The risk of collapse of an earthquake risk building is considered to be 5 to 10 times greater than that of an equivalent new building.

No significant damage or hazards were identified to the seismic or gravity load resisting system that would reduce its ability to resist further loads and therefore no restrictions on use or occupancy are recommended.

### 13.2 Further Investigations, Survey or Geotechnical Work

It is recommended that:

- n A verticality and level survey could be carried out to determine the extent of settlement of the building for insurance purposes.
- n Given the community use of the building a quantitative assessment should be undertaken to give a more reliable assessment of %NBS.
- n Further efforts are made to obtain structural drawings.

### 13.3 Damage Reinstatement

Repairs that would bring the building back to an "as new" condition are typically entitled under typical replacement insurance policies. We suggest you consult with your insurance advisor as to how you wish to proceed.

## 14 Design Features Report

Repairs will be required to reinstate the existing structural system. No new load paths are expected. A repair methodology has not been prepared at this stage.

## 15 Limitations

The following limitations apply to this engagement:

- n Beca and its employees and agents are not able to give any warranty or guarantee that all defects, damage, conditions or qualities have been identified.
- n Inspections are primarily limited to visible structural components. Appropriate locations for invasive inspection, if required, will be based on damage patterns observed in visible elements, and review of the construction drawings and structural system. As such, there will be concealed structural elements that will not be directly inspected.
- n The inspections are limited to building structural components only.
- n Inspection of building services, pipework, pavement, and fire safety systems is excluded from the scope of this report.
- n Inspection of the glazing system, linings, carpets, claddings, finishes, suspended ceilings, partitions, tenant fit-out, or the general water tightness envelope is excluded from the scope of this report.
- n The preliminary assessment of the lateral load capacity of the building is limited by the completeness and accuracy of the drawings provided. Assumptions have been made in respect of the geotechnical conditions at the site and any aspects or material properties not clear on the drawings. Where these assumptions are considered material to the outcome further investigations may be recommended. It is noted the assessment has not been exhaustive, our analysis and calculations have focused on representative areas only to determine the level of provision made. At this stage we have not undertaken any checks of the gravity system, wind load capacity, or foundations.
- n The information in this report provides a snapshot of building damage at the time the detailed inspection was carried out. Additional inspections required as a result of significant aftershocks are outside the scope of this work.

This report is of defined scope and is for reliance by CCC only, and only for this commission. Beca should be consulted where any question regarding the interpretation or completeness of our inspection or reporting arises.

Appendix A

# Photographs



**Figure 1:** Site layout




**Photo 1:** External view of the building



**Photo 2:** Liquefaction of areas surrounding site (aerial photo taken 24 February 2011)



**Photo 3:** Internal view of the building



**Photo 4:** Damage to plasterboard ceiling

**Damage:** Minor cracking (<1mm) to plasterboard ceiling panels.



**Photo 5:** External concrete pavement

**Damage:** Minor cracking to concrete slab.

Appendix B

## CERA DEE Summary Data

<b>Location</b>		Building Name: <input type="text" value="Ascot Community Centre"/>	Unit: <input type="text" value="12"/>	Street: <input type="text" value="Ascot Avenue, Parklands"/>	Reviewer: <input type="text" value="David Whittaker"/>
Building Address: <input type="text"/>	Legal Description: <input type="text"/>	CP/Eng No: <input type="text" value="123089"/>	Company: <input type="text" value="Beca"/>	Company project number: <input type="text" value="5323355"/>	Company phone number: <input type="text" value="03 3663521"/>
GPS south: <input type="text"/>	GPS east: <input type="text"/>	Degrees: <input type="text"/>	Min: <input type="text"/>	Sec: <input type="text"/>	Date of submission: <input type="text" value="14/06/2013"/>
Building Unique Identifier (CCC): <input type="text" value="BU 1306-003"/>	Is there a full report with this summary? <input type="text" value="yes"/>		Revision: <input type="text" value="A"/>	Inspection Date: <input type="text" value="7/08/2012"/>	

<b>Site</b>	Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text" value="0"/>
Soil type: <input type="text"/>	Soil Profile (if available): <input type="text" value="Unknown"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>	If Ground improvement on site, describe: <input type="text" value="N/A"/>	
Proximity to waterway (m, if <100m): <input type="text"/>	Approx site elevation (m): <input type="text"/>	
Proximity to cliff top (m, if <100m): <input type="text"/>		
Proximity to cliff base (m, if <100m): <input type="text"/>		

<b>Building</b>	No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split? <input type="text" value="no"/>	Storeys below ground: <input type="text" value="0"/>	Foundation type: <input type="text" value="other (describe)"/>	Ground floor elevation above ground (m): <input type="text" value="0.00"/>
Building height (m): <input type="text" value="5.00"/>	Floor footprint area (approx): <input type="text" value="290"/>	Age of Building (years): <input type="text" value="44"/>	if Foundation type is other, describe: <input type="text" value="Shallow Foundations"/>
Strengthening present? <input type="text" value="no"/>	Use (ground floor): <input type="text" value="other (specify)"/>	Use notes (if required): <input type="text" value="General purpose community centre"/>	Importance level (to NZS1170.5): <input type="text" value="IL2"/>
			height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="5"/>
			Date of design: <input type="text" value="1965-1976"/>
			If so, when (year)? <input type="text"/>
			And what load level (%g)? <input type="text"/>
			Brief strengthening description: <input type="text"/>

<b>Gravity Structure</b>	Gravity System: <input type="text" value="load bearing walls"/>	rafter type, purlin type and cladding: <input type="text"/>
Roof: <input type="text" value="steel framed"/>	Floors: <input type="text" value="other (note)"/>	describe system: <input type="text" value="Shallow foundations"/>
Beams: <input type="text" value="timber"/>	Columns: <input type="text" value="load bearing walls"/>	typical dimensions (mm x mm): <input type="text"/>
Walls: <input type="text" value="partially filled concrete masonry"/>		thickness (mm): <input type="text"/>

<b>Lateral load resisting structure</b>	Lateral system along: <input type="text" value="partially filled CMU"/>	Ductility assumed, $\mu$ : <input type="text" value="1.25"/>	Period along: <input type="text" value="0.40"/>	Total deflection (ULS) (mm): <input type="text"/>	maximum interstorey deflection (ULS) (mm): <input type="text"/>	<b>Note: Define along and across in detailed report!</b>	enter height above at H31: <input type="text"/>	note total length of wall at ground (m): <input type="text" value="26"/>	estimate or calculation? <input type="text" value="estimated"/>
	Lateral system across: <input type="text" value="partially filled CMU"/>	Ductility assumed, $\mu$ : <input type="text" value="1.25"/>	Period across: <input type="text" value="0.40"/>	Total deflection (ULS) (mm): <input type="text"/>	maximum interstorey deflection (ULS) (mm): <input type="text"/>	enter height above at H31: <input type="text"/>	note total length of wall at ground (m): <input type="text" value="11"/>	estimate or calculation? <input type="text" value="estimated"/>	

<b>Separations:</b>	north (mm): <input type="text"/>	east (mm): <input type="text"/>	south (mm): <input type="text"/>	west (mm): <input type="text"/>	leave blank if not relevant
---------------------	----------------------------------	---------------------------------	----------------------------------	---------------------------------	-----------------------------

<b>Non-structural elements</b>	Stairs: <input type="text" value="exposed structure"/>	describe: <input type="text" value="none"/>
Wall cladding: <input type="text" value="Metal"/>	describe: <input type="text" value="Concrete masonry walls"/>	
Roof cladding: <input type="text" value="timber frames"/>	describe: <input type="text" value="Lightweight metal sheeting"/>	
Glazing: <input type="text" value="plaster, fixed"/>		
Ceilings: <input type="text" value="Electrical, Plumbing"/>		

<b>Available documentation</b>	Architectural: <input type="text" value="none"/>	original designer name/date: <input type="text"/>
Structural: <input type="text" value="none"/>	original designer name/date: <input type="text"/>	
Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text"/>	
Electrical: <input type="text" value="none"/>	original designer name/date: <input type="text"/>	
Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text"/>	

<b>Damage</b>	Site performance: <input type="text" value="Good"/>	Describe damage: <input type="text"/>
Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>	
Differential settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text" value="Aerial photos showed liquefaction occurred in surrounding area"/>	
Liquefaction: <input type="text" value="2-5 m³/100m²"/>	notes (if applicable): <input type="text"/>	
Lateral Spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	
Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	
Ground cracks: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	
Damage to area: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	

<b>Building:</b>	Current Placard Status: <input type="text" value="green"/>	Describe how damage ratio arrived at: <input type="text" value="Damage not considered to have reduced capacity"/>
Along	Damage ratio: <input type="text" value="0%"/>	$\text{Damage Ratio} = \frac{(\% \text{ NBS (before)} - \% \text{ NBS (after)})}{\% \text{ NBS (before)}}$
Across	Damage ratio: <input type="text" value="0%"/>	
Diaphragms	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text" value="Minor cracking to plasterboard ceilings"/>

<b>Recommendations</b>	Level of repair/strengthening required: <input type="text" value="minor structural"/>	Describe: <input type="text" value="Repair cracking to plasterboard"/>
Building Consent required: <input type="text" value="no"/>	Describe: <input type="text"/>	
Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>	
Along	Assessed %NBS before e'quakes: <input type="text" value="36%"/>	36% %NBS from IEP below
	Assessed %NBS after e'quakes: <input type="text" value="36%"/>	
Across	Assessed %NBS before e'quakes: <input type="text" value="36%"/>	36% %NBS from IEP below
	Assessed %NBS after e'quakes: <input type="text" value="36%"/>	

IEP

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1965-1976

h<sub>n</sub> from above: 5m

Seismic Zone, if designed between 1965 and 1992: B

not required for this age of building  
not required for this age of building

	along	across
Period (from above):	0.4	0.4
(%NBS) <sub>nom</sub> from Fig 3.3:	5.0%	5.0%

Note 1: for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0  
 Note 2: for RC buildings designed between 1976-1984, use 1.2  
 Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)

	along	across
Final (%NBS) <sub>nom</sub> :	5%	5%

## 2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6: 1.00

	along	across
Near Fault scaling factor (1/N(T.D), Factor A:	1	1

## 2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3: 0.30

Z<sub>1992</sub>, from NZS4203:1992: 0.8

Hazard scaling factor, Factor B: 3.333333333

## 2.4 Return Period Scaling Factor

Building Importance level (from above): 2

Return Period Scaling factor from Table 3.1, Factor C: 1.00

## 2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2): 1.25

Ductility scaling factor: =1 from 1976 onwards; or =k<sub>u</sub>, if pre-1976, from Table 3.3: 1.14

Ductility Scaling Factor, Factor D: 1.14

## 2.6 Structural Performance Scaling Factor:

S<sub>p</sub>: 0.925

Structural Performance Scaling Factor Factor E: 1.081081081

2.7 Baseline %NBS, (NBS%)<sub>0</sub> = (%NBS)<sub>nom</sub> x A x B x C x D x E%NBS<sub>0</sub>: 21%

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A: 1

3.2. Vertical irregularity, Factor B: 1

3.3. Short columns, Factor C: 1

3.4. Pounding potential

Pounding effect D1, from Table to right: 1.0

Height Difference effect D2, from Table to right: 1.0

Therefore, Factor D: 1

3.5. Site Characteristics: significant 0.7

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

## 3.6. Other factors, Factor F

For ≤ 3 storeys, max value = 2.5, otherwise max value = 1.5, no minimum

Along: 2.5

Across: 2.5

Rationale for choice of F factor, if not 1: Simple single storey structure, only minor damage sustained

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

## 3.7. Overall Performance Achievement ratio (PAR)

1.75

1.75

4.3 PAR x (%NBS)<sub>0</sub>:

PAR x Baseline %NBS: 36%

36%

## 4.4 Percentage New Building Standard (%NBS), (before)

36%

Official Use only:

Accepted By: \_\_\_\_\_

Date: \_\_\_\_\_

Appendix C

## Previous Reports and Assessments

# Christchurch Eq. RAPID Assessment Form - LEVEL 1

Inspector Initials  
Territorial Authority

*RS.*  
Christchurch City

Date of Inspection  
Time

18/6/2011  
12-15p

Exterior Only  
Exterior and Interior

Building Name *Ascot Community Ctr.*

Short Name *BU 1306-003.0* Type of Construction

Address *193 Traill Pl.*  Timber frame  Concrete shear wall

Steel frame  Unreinforced masonry

GPS Co-ordinates S° E°  Tilt-up concrete  Reinforced masonry

Contact Name  Concrete frame  Confined masonry

Contact Phone  RC frame with masonry infill  Other:

Storeys at and above ground level *1* Below ground level *0* Primary Occupancy  Dwelling  Commercial/ Offices

Total gross floor area (m<sup>2</sup>) *300-400* Year built *1968*  Other residential  Industrial

No of residential Units  Public assembly  Government

School  Heritage Listed

Photo Taken  Yes  No  Religious  Other

Investigate the building for the conditions listed below:

Overall Hazards / Damage	Minor/None	Moderate	Severe	Comments
Collapse, partial collapse, off foundation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Building or storey leaning	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Wall or other structural damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<i>damage to internal masonry wall from Feb quake.</i>
Overhead falling hazard	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Ground movement, settlement, slips	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Neighbouring building hazard	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Choose a posting based on the evaluation and team judgement. Severe conditions affecting the whole building are grounds for an UNSAFE posting. Localised Severe and overall Moderate conditions may require a RESTRICTED USE. Place INSPECTED placard at main entrance. Post all other placards at every significant entrance.

INSPECTED  
GREEN

RESTRICTED USE  
YELLOW

UNSAFE  
RED

Record any restriction on use or entry:

Further Action Recommended:

Tick the boxes below only if further actions are recommended

- Barricades are needed (state location):
- Level 2 or detailed engineering evaluation recommended
  - Structural
  - Geotechnical
  - Other:
- Other recommendations:

Estimated Overall Building Damage (Exclude Contents)

None	<input type="checkbox"/>		
0-1 %	<input type="checkbox"/>	31-60 %	<input type="checkbox"/>
2-10 %	<input checked="" type="checkbox"/>	61-99 %	<input type="checkbox"/>
11-30 %	<input type="checkbox"/>	100 %	<input type="checkbox"/>

Sign here on completion

*[Signature]*

Date & Time *18/6/2011*  
ID *204904*

*CPEng*

Inspection ID \_\_\_\_\_ (Office Use Only)

# Christchurch Eq RAPID Assessment Form - LEVEL 2

Inspector Initials	<input style="width: 90%;" type="text"/>	Date	<input style="width: 90%;" type="text"/>	Final Posting (e.g. UNSAFE)	<input style="width: 90%;" type="text"/>
Territorial Authority	Christchurch City	Time	<input style="width: 90%;" type="text"/>		

Building Name	<input style="width: 95%;" type="text"/>		Type of Construction	
Short Name	<input style="width: 95%;" type="text"/>		<input type="checkbox"/> Timber frame	<input type="checkbox"/> Concrete shear wall
Address	<input style="width: 95%;" type="text"/>		<input type="checkbox"/> Steel frame	<input type="checkbox"/> Unreinforced masonry
GPS Co-ordinates	S° <input style="width: 40%;" type="text"/>	E° <input style="width: 40%;" type="text"/>	<input type="checkbox"/> Tilt-up concrete	<input type="checkbox"/> Reinforced masonry
Contact Name	<input style="width: 95%;" type="text"/>		<input type="checkbox"/> Concrete frame	<input type="checkbox"/> Confined masonry
Contact Phone	<input style="width: 95%;" type="text"/>		<input type="checkbox"/> RC frame with masonry infill	<input type="checkbox"/> Other:
Storeys at and above ground level	Below ground level	<input style="width: 40%;" type="text"/>	Primary Occupancy	
Total gross floor area (m <sup>2</sup> )	Year built	<input style="width: 40%;" type="text"/>	<input type="checkbox"/> Dwelling	<input type="checkbox"/> Commercial/ Offices
No of residential Units	<input style="width: 95%;" type="text"/>		<input type="checkbox"/> Other residential	<input type="checkbox"/> Industrial
Photo Taken	Yes	No	<input type="checkbox"/> Public assembly	<input type="checkbox"/> Government
			<input type="checkbox"/> School	<input type="checkbox"/> Heritage Listed
			<input type="checkbox"/> Religious	<input type="checkbox"/> Other

Investigate the building for the conditions listed on page 1 and 2, and check the appropriate column. A sketch may be added on page 3

Overall Hazards / Damage	Minor/None	Moderate	Severe	Comments
Collapse, partial collapse, off foundation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input style="width: 95%;" type="text"/>
Building or storey leaning	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input style="width: 95%;" type="text"/>
Wall or other structural damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input style="width: 95%;" type="text"/>
Overhead falling hazard	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input style="width: 95%;" type="text"/>
Ground movement, settlement, slips	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input style="width: 95%;" type="text"/>
Neighbouring building hazard	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input style="width: 95%;" type="text"/>
Electrical, gas, sewerage, water, hazmats	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input style="width: 95%;" type="text"/>

Record any existing placard on this building:

Existing Placard Type (e.g. UNSAFE)

Choose a new posting based on the new evaluation and team judgement. Severe conditions affecting the whole building are grounds for an UNSAFE posting. Localised Severe and overall Moderate conditions may require a RESTRICTED USE. Place INSPECTED placard at main entrance. Post all other placards at every significant entrance. Transfer the chosen posting to the top of this page.

INSPECTED  
GREEN  G1  G2

RESTRICTED USE  
YELLOW  Y1  Y2

UNSAFE  
RED  R1  R2  R3

Record any restriction on use or entry:

Further Action Recommended:

- Tick the boxes below only if further actions are recommended*
- Baricades are needed (state location):
  - Detailed engineering evaluation recommended
    - Structural
    - Geotechnical
  - Other recommendations:

Other:

Estimated Overall Building Damage (Exclude Contents)

None	<input type="checkbox"/>		<input type="checkbox"/>
0-1 %	<input type="checkbox"/>	31-60 %	<input type="checkbox"/>
2-10 %	<input type="checkbox"/>	61-99 %	<input type="checkbox"/>
11-30 %	<input type="checkbox"/>	100 %	<input type="checkbox"/>

Sign here on completion

\_\_\_\_\_

Date & Time \_\_\_\_\_

ID \_\_\_\_\_

Inspection ID: \_\_\_\_\_ (Office Use Only)

PROP 1:

Structural Hazards/ Damage	Minor/None	Moderate	Severe	Comments
Foundations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Roofs, floors (vertical load)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Columns, pilasters, corbels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Diaphragms, horizontal bracing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Pre-cast connections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Beam	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<b>Non-structural Hazards / Damage</b>				
Parapets, ornamentation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Cladding, glazing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Ceilings, light fixtures	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	minor repair works in process to block walls + ceilings.
Interior walls, partitions	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Elevators	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Stairs/ Exits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Utilities (eg. gas, electricity, water)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<b>Geotechnical Hazards / Damage</b>				
Slope failure, debris	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Ground movement, fissures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	liquefaction on street nearby.
Soil bulging, liquefaction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<b>General Comment</b>				

**Usability Category**

Damage Intensity	Posting	Usability Category	Remarks
Light damage	Inspected (Green)	G1. Occupiable, no immediate further investigation required	in process of repairs
Low risk		G2. Occupiable, repairs required	
Medium damage	Restricted Use (Yellow)	Y1. Short term entry	
Medium risk		Y2. No entry to parts until repaired or demolished	
Heavy damage	Unsafe (Red)	R1. Significant damage: repairs, strengthening possible	
High risk		R2. Severe damage: demolition likely	
		R3. At risk from adjacent premises or from ground failure	

