



CLIENTS | PEOPLE | PERFORMANCE

Botanic Gardens Cycle Shelter
PRK 1566 BLDG 019
Detailed Engineering Evaluation
Qualitative Report
Version Final

7 Rolleston Avenue, Christchurch



**Botanic Gardens Cycle Shelter
PRK 1566 BLDG 019**

Detailed Engineering Evaluation
Qualitative Report
Version Final

7 Rolleston Avenue, Christchurch

Christchurch City Council

Prepared By
Peter O'Brien

Reviewed By
Cormac Joy

Date
15th May 2013



Contents

1.	Background	1
2.	Compliance	2
2.1	Canterbury Earthquake Recovery Authority (CERA)	2
2.2	Building Act	3
2.3	Christchurch City Council Policy	4
2.4	Building Code	4
3.	Earthquake Resistance Standards	5
4.	Building Description	7
4.1	General	7
4.2	Gravity Load Resisting System	8
4.3	Lateral Load Resisting System	8
5.	Assessment	9
6.	Damage Assessment	10
6.1	Surrounding Buildings	10
6.2	Residual Displacements and General Observations	10
6.3	Ground Damage	10
7.	Critical Structural Weakness	11
7.1	Short Columns	11
7.2	Lift Shaft	11
7.3	Roof	11
7.4	Staircases	11
7.5	Site Characteristics	11
7.6	Plan Irregularity	11
8.	Geotechnical Consideration	12
8.1	Site Description	12
8.2	Published Information on Ground Conditions	12
8.3	Seismicity	14
8.4	Slope Failure and/or Rockfall Potential	14
8.5	Liquefaction Potential	15



8.6	Recommendations	15
8.7	Conclusions & Summary	15
9.	Survey	16
10.	Initial Capacity Assessment	17
10.1	% NBS Assessment	17
10.2	Seismic Parameters	17
10.3	Expected Structural Ductility Factor	17
10.4	Discussion of Results	17
10.5	Occupancy	18
11.	Initial Conclusions	19
12.	Recommendations	20
13.	Limitations	21
13.1	General	21
13.2	Geotechnical Limitations	21

Table Index

Table 1	%NBS compared to relative risk of failure	6
Table 2	ECan Borehole Summary	12
Table 3	Summary of Known Active Faults	14

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	5
Figure 2	Plan Sketch Showing Key Structural Elements	7
Figure 3	Post February 2011 Earthquake Aerial Photography	13

Appendices

- A Photographs
- B Existing Drawings
- C CERA Building Evaluation Form



Qualitative Report Summary

Botanic Gardens Cycle Shelter

PRK 1566 BLDG 019

Detailed Engineering Evaluation

Qualitative Report - SUMMARY

Version Final

7 Rolleston Avenue, Christchurch

Background

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 4th April 2012 and available construction drawings.

Building Description

The Botanic Gardens Cycle Shelter is located at 7 Rolleston Avenue, Christchurch Central. It is located in the Botanic Gardens Yard. The exact date of construction of the cycle shelter is unknown but it is estimated to be mid-1980's.

The cycle shelter is a timber framed structure. The roof of the structure is clad with corrugated steel. Timber rafters spanning across the building are at approximately 0.7m centres. Timber roof cross bracing is present in the structure. Rafters are supported by the timber framed wall to the west and the steel and timber frame to the east. The frame system along the east comprises two timber beams spanning between the north and south walls and a central steel circular hollow section post. The north and south walls are timber framed with timber cladding to the exterior and are unlined internally. The western wall of the building comprises four timber posts with three horizontal timber members spanning between them and cladding fixed to them. The timber posts and the single steel post are cantilevered out of the ground. The timber framed walls of the north and south are supported by concrete strip footings. Internal floors are concrete slab on grade.

Key Damage Observed

No damage was observed to the building.

Critical Structural Weaknesses

The following potential critical structural weaknesses have been identified in the structure.

Plan Irregularity (30% Reduction)

83% NBS

Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the original capacity of the building has been assessed to be 83% NBS and post-earthquake capacity also in the



order of 83% NBS. These buildings post-earthquake capacity excluding critical structural weaknesses is in the order of 119% NBS.

This building has been assessed to have a seismic capacity in the order of 83% NBS and is therefore not considered to be potentially Earthquake Risk or Earthquake Prone.

Recommendations

As the cycle shelter has achieved greater than 67% NBS following an initial IEP assessment of the buildings, no further assessment is required.



1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Botanic Gardens Cycle Shelter.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings were made available, and these have been considered in our evaluation of the building. The building description is based on a review of the drawings and our visual inspections.



2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage



2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The Botanic Gardens Cycle Shelter is located at 7 Rolleston Avenue, Christchurch Central. It is located in the Botanic Gardens Yard. The exact date of construction of the cycle shelter is unknown but it is estimated to be early 1980's.

The cycle shelter is a timber framed structure. The roof of the structure is clad with corrugated steel fixed to timber purlins running the length of the building. The timber purlins are attached to timber rafters spanning across the building at approximately 0.7 m centres. Timber roof diagonal bracing is present in the structure. The roof is mono-pitched sloping from front to back. Rafters are supported by the timber framed wall to the rear and the steel post and timber beam frame to the front. The frame system along the front of the structure comprises two timber beams spanning between the side walls and a central steel circular hollow section post. The timber frame side walls have plywood sheet cladding to the exterior and are unlined internally. The timber frame rear wall comprises four timber posts, as indicated in Figure 2, with external timber cladding fixed to three horizontal timber members spanning between the posts. The timber posts and the single steel post are cantilevered out of concrete. The timber framed walls of the north and south are supported by concrete strip footings. Internal floors are concrete slab on grade.




Figure 2 Plan Sketch Showing Key Structural Elements

The building footprint is approximately 18 m². The length of the building is 7.8 m and the width is 2.3 m. The building is 2 m in height and it is situated approximately 40 m south from the banks of the Avon River.



4.2 Gravity Load Resisting System

Gravity loads are transferred from the roof cladding through to the supporting timber purlins running the length of the building. The timber purlins transfer the loads to the timber rafters that are supported by the timber framed rear wall and the timber beams at the front of the building. Loads transferred to the timber framed rear wall are transferred down through four timber posts to the ground below. The timber beams, at the front, transfer loads to the central steel post and to the timber framed walls at either end of the building. The steel post transfers the loads directly down to the ground below. The timber framed side walls transfer the loads down to the concrete strip footings, which transfer the load through to the ground below.

Internal gravity loads are transferred directly through the concrete ground floor slab to the ground below.

4.3 Lateral Load Resisting System

In the longitudinal direction, timber diagonal bracing in the roof, enables the transfer of loads from the front of the building back to the rear wall. Resistance to lateral loading is provided by the cantilever action of the rear wall's timber posts. Torsional effects on the rear wall, carrying all lateral loads longitudinally, are resisted by the sheet clad timber frame side walls.

In the transverse direction, lateral loads are transferred from the roof through the timber framed roof system and diagonal bracing back to the timber framed side walls. Lateral loads are transferred down through the external walls, by sheet bracing action of the plywood wall linings, to the concrete strip foundations and through to the ground below.



5. Assessment

An inspection of the buildings was undertaken on the 4th of April 2012. Both the interior and exterior of the buildings were inspected. The main structural components of the roof of the buildings were all able to be viewed.

The inspection consisted of scrutinising the buildings to determine the structural systems and likely behaviour of the buildings during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for these buildings has been based on the IEP procedure described by the NZSEE and based on the information obtained from visual observation of the building and available drawings.



6. Damage Assessment

6.1 Surrounding Buildings

The cycle shelter is located in the Botanic Gardens yard. There are several other buildings located in the yard. These include the Office Store, the Office Library, the Irrigation Pump House, the Potting Facility and numerous glasshouses. There was no significant damage noted to any of the glasshouses. The potting facility has suffered minor damage with cracking to the plasterboard linings the only damage noted. Cracking to the office store was noted in several locations. Shear cracking was noted to the blockwork in the office library building.

6.2 Residual Displacements and General Observations

No residual displacements of the structure were noted during the inspection of the building.

No damage was evident to the roof structure.

No cracking was noted to the strip footings.

6.3 Ground Damage

No ground damage was observed during the inspection of the site. Ground remediation works were in progress during inspection. These works included strengthening of the river banks. Due to the presence of gravel to accommodate heavy machinery, any ground damage that may have been present was not identifiable.



7. Critical Structural Weakness

7.1 Short Columns

No short columns are present in the structure.

7.2 Lift Shaft

The building does not contain a lift shaft.

7.3 Roof

Diagonal timber roof bracing was seen in the cycle shelter and is expected to be sufficient to form a braced roof structure.

7.4 Staircases

The building does not contain a staircase.

7.5 Site Characteristics

The site has been identified as having a moderate to high liquefaction potential following the desktop geotechnical review. As the building is timber framed and able to accommodate moderate movement, for the purposes of the IEP assessment of the building and the determination of the %NBS score, the effects of liquefaction on the performance of the building has been assessed as an 'insignificant' site characteristic in accordance with NZSEE guidelines.

7.6 Plan Irregularity

Due to the presence of a large opening in the front of the building, a 'significant' plan irregularity critical structural weakness has been assumed.



8. Geotechnical Consideration

8.1 Site Description

The site is situated within a recreational reserve, in central Christchurch. It is relatively flat at approximately 8m above mean sea level. The structure is situated between 7m south of the Avon River, and 9.5km west of the coast (Pegasus Bay) at New Brighton.

8.2 Published Information on Ground Conditions

8.2.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by Holocene alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, comprising alluvial sand and silt overbank deposits.

8.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that three boreholes are located within 200m of the site (see Table 2). Of these, two contained adequate lithographic logs. The site geology described in the logs is stratified gravel, sand, silt and clay. Also present are layers of peat between 20m and 40m bgl.

Table 2 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35/1936	100.9m	1.4m bgl	50m E of office buildings
M35/10619	104.5m	0.8m bgl	100m E of office buildings

It should be noted that the purpose of the boreholes the well logs are associated with, were sunk for groundwater extraction and not for geotechnical purposes. Therefore, the amount of material recovered and available for interpretation and recording will have been variable at best and may not be representative. The logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

8.2.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the subject site.

8.2.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has published areas showing the Green Zone Technical Category in relation to the risk of future liquefaction and how these areas are expected to


¹ Brown, L. J. and Weeber, J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.

perform in future earthquakes. The site is classified as Technical Category N/A. This is due to the site not being classified as within a residential area.

8.2.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows moderate amounts of liquefaction on the northern side of the Avon and in Victoria Lake, in the top-left and top-right corners of Figure 3. However, there is no evidence of liquefaction at the surface within the botanic gardens themselves.

Figure 3 Post February 2011 Earthquake Aerial Photography²



8.2.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to be alluvial deposits comprising multiple strata of gravel, sandy gravel and silt/clay. Occasional layers of peat are also anticipated to be present between 20 and 40 m bgl.

The Avon River is immediately adjacent to the site, and hence groundwater levels are expected to be close to the surface.

² Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>



8.3 Seismicity

8.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

Table 3 Summary of Known Active Faults^{3,4}

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120 km	NW	~8.3	~300 years
Greendale (2010) Fault	20 km	W	7.1	~15,000 years
Hope Fault	100 km	N	7.2~7.5	120~200 years
Kelly Fault	100 km	NW	7.2	150 years
Porters Pass Fault	55 km	NW	7.0	1100 years

Recent earthquakes since 22 February 2011 have identified the presence of a previously unmapped active fault system underneath Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.3.2 Ground Shaking Hazard

This recent seismic activity has produced earthquakes of Magnitude 6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city and has resulted in widespread liquefaction throughout Christchurch.

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

Ground conditions are anticipated to comprise stratified alluvial deposits of varying density, and a 475-year PGA (peak ground acceleration) of ~0.4 (Stirling et al, 2002⁴). In addition, bedrock is anticipated to be in excess of 500 m deep, and hence ground shaking is likely to be moderate to high.

8.4 Slope Failure and/or Rockfall Potential

Given the site's elevation and location in Central Christchurch, global slope instability is considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

³ Stirling, M.W., McVerry, G.H., and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

⁴ GNS Active Faults Database



8.5 Liquefaction Potential

Due to the anticipated presence of alluvial deposits and evidence from the post-earthquake aerial photography, it is considered possible that liquefaction will occur at the site in layers where sands and silts are present.

However, due to the presence of gravel and clay layers, evidence may not necessarily propagate to the surface. This gives the site a moderate liquefaction potential.

Further investigation is recommended to better determine subsoil conditions. From this, a more comprehensive liquefaction assessment could be undertaken.

8.6 Recommendations

Given the anticipated ground conditions and limited existing investigation in the vicinity of the site, we recommend that further investigation is undertaken. Specifically, three CPT investigations should be conducted to a target depth of 20 m bgl.

8.7 Conclusions & Summary

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on stratified alluvial deposits, predominantly comprising gravel and sand, interlain by clay. Associated with this the site also has a moderate liquefaction potential, in particular where sands and/or silts are present.

It is recommended that intrusive investigation comprising of three piezocone CPT's be conducted.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.



9. Survey

No level or verticality surveys have been undertaken for these buildings at this stage as per Christchurch City Council requirements.



10. Initial Capacity Assessment

10.1 % NBS Assessment

The cycle shelter's capacity was assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity excluding critical structural weaknesses and the capacity of any identified weaknesses are expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 4. These capacities are subject to confirmation by a more detailed quantitative analysis.

<u>Critical Structural Weakness</u>	<u>%NBS</u>
Building excluding CSW's	>100%
Plan Irregularity (30% Reduction)	83%

Table 4 Indicative Building and Critical Structural Weaknesses Capacities based on the NZSEE Initial Evaluation Procedure

Following an IEP assessment, the building has been assessed as achieving 83% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered neither potentially Earthquake Risk or Earthquake Prone as they achieve more than 67% NBS. These scores have not been adjusted when considering damage to the structure no damage was noted to the structure.

10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class: D, NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- ▶ Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- ▶ Return period factor $R_u = 0.5$, NZS 1170.5:2004, Table 3.5, Importance level 1 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

10.3 Expected Structural Ductility Factor

A structural ductility factor of 1.25 has been assumed based on the structural system observed and the date of construction.

10.4 Discussion of Results

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age, importance level and construction type founded on Class D soils.

The building would have been designed to standards at the time, NZS 4203: 1976, that would have used design loads significantly less than those required by the current loading standard and lower detailing



requirements for ductile seismic behaviour than those that are present in the current standards. However; as the building is considered to be of Importance Level 1, the %NBS excluding critical structural weaknesses would be expected to be >100%. A 'significant' Plan Irregularity critical structural weakness has reduced the % NBS by 30%. These factors combined with the increase in the hazard factor for Christchurch to 0.3 it is reasonable to expect the building to be classified as not potentially Earthquake Risk or Prone.

10.5 Occupancy

As the structure has been assessed to have a % NBS exceeding 67% NBS, it is deemed as not potentially Earthquake Prone. The building can remain occupied, as it is not considered to be a potentially Earthquake Prone building.



11. Initial Conclusions

The recent seismic activity in Christchurch has caused no damage to the building. The building has been assessed to have a seismic capacity in the order of 83% NBS and is deemed to be neither Earthquake Prone nor Earthquake Risk in accordance with the NZSEE guidelines.



12. Recommendations

As the cycle shelter has achieved greater than 67% NBS following an initial IEP assessment of the building, no further assessment is required.



13. Limitations

13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report or a specific limitations section.

13.2 Geotechnical Limitations


This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.



Appendix A
Photographs



Photograph 1 Aerial photograph of Botanic Gardens yard indicating the propagating house.



Photograph 2 Eastern side of the cycle shelter. All structural elements are clearly visible.



Photograph 3 Underside of the roof of the building showing cross bracing, rafters, purlins and metal cladding.



Photograph 4 Internal view showing steel CHS post at front and timber post system at the rear. Timber framed end walls are clearly visible.




Photograph 5 Eastern view of the cycle shelter.



Appendix B
Existing Drawings

No drawings were made available for this building. Attached is a sketch showing the key structural elements.





Appendix C
CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: Botanic Gardens Cycle Shelter	Reviewer: Stephen Lee
	Unit No: Street		CPEng No: 1006840
Building Address:	19 7 Rolleston Avenue	Company: GHD Limited	Company project number: 5130902-01
Legal Description:	Pt RES 25	Company phone number: 03 3780 900	
	Degrees Min Sec	Date of submission: 15/05/2013	Inspection Date: 4/04/2012
GPS south:	43 31 47.74	Revision: Final	
GPS east:	172 37 22.12	Is there a full report with this summary? yes	
Building Unique Identifier (CCC):	PRK 1566 BLDG 019		

Site		Max retaining height (m): 0
Site slope:	flat	Soil Profile (if available):
Soil type:	silty sand	If Ground improvement on site, describe:
Site Class (to NZS1170.5):	D	Approx site elevation (m): 8.00
Proximity to waterway (m, if <100m):	40	
Proximity to clifftop (m, if < 100m):		
Proximity to cliff base (m,if <100m):		

Building		single storey = 1	Ground floor elevation (Absolute) (m): 8.00
No. of storeys above ground:	1	Ground floor elevation above ground (m): 0.00	
Ground floor split?	no	if Foundation type is other, describe:	
Storeys below ground:	0	height from ground to level of uppermost seismic mass (for IEP only) (m): 2	
Foundation type:	strip footings	Date of design: 1976-1992	
Building height (m):	2.00	If so, when (year)?	
Floor footprint area (approx):	18	And what load level (%g)?	
Age of Building (years):	27	Brief strengthening description:	
Strengthening present?	no		
Use (ground floor):	parking		
Use (upper floors):			
Use notes (if required):	Bicycle Shelter		
Importance level (to NZS1170.5):	IL1		

Gravity Structure		rafter type, purlin type and cladding
Gravity System:	frame system	slab thickness (mm)
Roof:	timber framed	type
Floors:	concrete flat slab	typical dimensions (mm x mm)
Beams:	timber	0
Columns:	timber	
Walls:	non-load bearing	

Lateral load resisting structure		Note: Define along and across in	note typical wall length (m)
Lateral system along:	lightweight timber framed walls		7.8

Ductility assumed, μ :	1.25	detailed report!	
Period along:	0.10		0.00
Total deflection (ULS) (mm):			estimate or calculation?
maximum interstorey deflection (ULS) (mm):			estimate or calculation?
Lateral system across:	lightweight timber framed walls		note typical wall length (m)
Ductility assumed, μ :	1.25		
Period across:	0.10	0.00	
Total deflection (ULS) (mm):			estimate or calculation?
maximum interstorey deflection (ULS) (mm):			estimate or calculation?

Separations:

north (mm):		leave blank if not relevant
east (mm):		
south (mm):		
west (mm):		

Non-structural elements

Stairs:		
Wall cladding:	other light	describe Timber
Roof Cladding:	Metal	describe Corrugated Steel
Glazing:		
Ceilings:		
Services(list):		

Available documentation

Architectural	none	original designer name/date	
Structural	none	original designer name/date	
Mechanical	none	original designer name/date	
Electrical	none	original designer name/date	
Geotech report	none	original designer name/date	

Damage

Site: (refer DEE Table 4-2)

Site performance:		Describe damage:	
Settlement:	none observed	notes (if applicable):	
Differential settlement:	none observed	notes (if applicable):	
Liquefaction:	none apparent	notes (if applicable):	
Lateral Spread:	none apparent	notes (if applicable):	
Differential lateral spread:	none apparent	notes (if applicable):	
Ground cracks:	none apparent	notes (if applicable):	
Damage to area:	none apparent	notes (if applicable):	

Building:

Current Placard Status:	green	
Along	Damage ratio: 0%	Describe how damage ratio arrived at:
	Describe (summary): None	
Across	Damage ratio: 0%	
	Describe (summary): None	

$$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
CSWs:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Pounding:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Non-structural:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>

Recommendations

Level of repair/strengthening required:	<input type="text" value="none"/>	Describe:	<input type="text"/>
Building Consent required:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Interim occupancy recommendations:	<input type="text" value="full occupancy"/>	Describe:	<input type="text"/>

Along	Assessed %NBS before:	<input type="text" value="100%"/>	83% %NBS from IEP below	If IEP not used, please detail assessment methodology:	<input type="text"/>
	Assessed %NBS after:	<input type="text" value="100%"/>			
Across	Assessed %NBS before:	<input type="text" value="100%"/>	83% %NBS from IEP below		
	Assessed %NBS after:	<input type="text" value="100%"/>			

IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1976-1992 h_n from above: 2m

Seismic Zone, if designed between 1965 and 1992: not required for this age of building
not required for this age of building

	along	across
Period (from above):	0.1	0.1
(%NBS) _{nom} from Fig 3.3:	<input type="text" value="16.5%"/>	<input type="text" value="16.5%"/>

Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0

Note 2: for RC buildings designed between 1976-1984, use 1.2

Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)

	along	across
Final (%NBS)_{nom}:	<input type="text" value="17%"/>	<input type="text" value="17%"/>

2.2 Near Fault Scaling Factor Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

	along	across
Near Fault scaling factor (1/N(T,D), Factor A:	<input type="text" value="1"/>	<input type="text" value="1"/>

2.3 Hazard Scaling Factor Hazard factor Z for site from AS1170.5, Table 3.3:

Z₁₉₉₂, from NZS4203:1992

Hazard scaling factor, **Factor B:**

2.4 Return Period Scaling Factor Building Importance level (from above):

Return Period Scaling factor from Table 3.1, **Factor C:**

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2)
 Ductility scaling factor: =1 from 1976 onwards; or = $\kappa\mu$, if pre-1976, from Table 3.3:

	along	across
Assessed ductility (less than max in Table 3.2)	1.25	1.25
Ductility scaling factor: =1 from 1976 onwards; or = $\kappa\mu$, if pre-1976, from Table 3.3:	1.14	1.14

Ductility Scaling Factor, **Factor D:**

along	1.00	1.00
-------	------	------

2.6 Structural Performance Scaling Factor:

Sp:

along	0.925	0.925
-------	-------	-------

Structural Performance Scaling Factor **Factor E:**

along	1.081081081	1.081081081
-------	-------------	-------------

2.7 Baseline %NBS, $(NBS\%)_b = (\%NBS)_{nom} \times A \times B \times C \times D \times E$

%NBS_b:

along	119%	119%
-------	------	------

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

significant	0.7
-------------	-----

3.2. Vertical irregularity, Factor B:

insignificant	1
---------------	---

3.3. Short columns, Factor C:

insignificant	1
---------------	---

3.4. Pounding potential

Pounding effect D1, from Table to right	1.0
Height Difference effect D2, from Table to right	1.0

Therefore, Factor D: **1**

3.5. Site Characteristics

insignificant	1
---------------	---

Table for selection of D1	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum
 Rationale for choice of F factor, if not 1

	Along	Across
For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum	1.0	1.0
Rationale for choice of F factor, if not 1		

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

along	0.70	0.70
-------	------	------

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS:

along	83%	83%
-------	-----	-----

4.4 Percentage New Building Standard (%NBS), (before)

83%

Official Use only:

Accepted By:
 Date:



GHD

Level 4, Spicer Building
148 Victoria Street, Christchurch 8013
T: 64 3 378 0900 F: 64 3 377 8575 E: chcmail@ghd.com

© GHD Limited 2012

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Peter O'Brien	Cormac Joy		Stephen Lee		15/5/13