



CLIENTS | PEOPLE | PERFORMANCE

**Denton Oval**  
**BU 0770-003 EQ2**  
Detailed Engineering Evaluation  
Quantitative Report  
Version FINAL

442 Main South Road, Hornby

**Denton Oval  
BU 0770-003 EQ2**

Detailed Engineering Evaluation  
Quantitative Report  
Version FINAL

442 Main South Road, Hornby

Christchurch City Council

**Prepared By**  
Jay Zeus B. Rivera

**Reviewed By**  
Stephen Lee

**Date**  
07/03/13



# Contents

Quantitative Report Summary	1
1. Background	3
2. Compliance	4
2.1 Canterbury Earthquake Recovery Authority (CERA)	4
2.2 Building Act	4
2.3 Christchurch City Council Policy	6
2.4 Building Code	6
3. Earthquake Resistance Standards	7
4. Building Description	9
4.1 General	9
4.2 Gravity Load Resisting System	15
4.3 Lateral Load Resisting System	15
5. Assessment	17
5.1 Site Inspection	17
5.2 Investigation & Opening Up Work	17
5.3 Analysis and Modelling Methodology	17
5.4 Calculations	19
6. Damage Assessment	20
6.1 Surrounding Buildings	20
6.2 Residual Displacements and General Observations	20
6.3 Ground Damage	20
7. Analysis	21
7.1 Seismic Parameters	21
7.2 Wind Parameters	21
7.3 Structural Ductility Factor	22
8. Geotechnical Consideration	23
8.1.1 Published Information on Ground Conditions	23
8.1.2 Seismicity	25
8.1.3 Field Investigations	26



8.1.4	Ground Conditions Encountered	27
8.1.5	Interpretation of Ground Conditions	27
9.	Results	28
9.1	%NBS	28
9.2	Lateral Seismic Drift	31
9.3	Discussion of Results	31
10.	Conclusions	32
10.1	Building Capacity Assessment	32
11.	Recommendations	33
12.	Limitations	34
12.1	General	34
12.2	Geotechnical Limitations	34
13.	References	36

## Table Index

Table 1	%NBS compared to relative risk of failure	8
Table 2	ECan Bore Log Summary Table	23
Table 3	Summary of Active Known Faults	235
Table 4	Coordinates of Investigation Locations	26
Table 5	Summary of CPT-Inferred Lithology	27

## Figure Index

Figure 1	NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE	7
Figure 2	Aerial photograph of Denton Oval	10
Figure 3	Framing plan of the grandstand	11
Figure 4	Roof framing plan of the grandstand	12
Figure 5	Typical frame elevation	13
Figure 6	Masonry wall layout for Amenity Building	14
Figure 7	3D Mathematical Model of Denton Oval's Grandstand in Etabs	18
Figure 8	Post February 2011 Earthquake Aerial Photography	25



## Appendices

- A Geotechnical Investigation Reports and Analysis
- B Photographs
- C Existing Drawings
- D CERA Report Forms



# Quantitative Report Summary

**Denton Oval**

**BU 0770-003 EQ2**

**Detailed Engineering Evaluation**

**Quantitative Report - SUMMARY**

**Version FINAL**

**442 Main South Road, Hornby**

## **Background**

This is a summary of the Quantitative report for the structures of the buildings at Denton Oval, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on 18<sup>th</sup> May 2012.

## **Building Description**

The buildings at Denton Oval consist of a steel and reinforced concrete grandstand structure with a one(1) storey unreinforced masonry amenity building beneath it and a two (2) storey masonry Hornby Cycling Clubrooms building. The grandstand and the Hornby cycling clubroom building were separated by a seismic gap. This report focusses on the assessment of the grandstand and the amenity building only.

## **Building Capacity Assessment**

For the purpose of seismic assessment, the grandstand and the amenity building have been analysed separately. This is due to the lack of connection between the walls of the amenity building and the concrete frame of the grandstand. The grandstand is composed of steel frame atop of the concrete frame while the amenity building is composed mainly of unreinforced masonry block wall. The amenity building is then classified into two blocks, Block A serves as an office and changing room for players and officials while Block B is for Men's and Women's toilet.

The grandstand achieved a rating of 35% NBS while the amenity building scored 22% NBS. The rating of the changing area is greatly affected by the unreinforced masonry block walls that support the lightweight roof. The walls do not have sufficient strength to resist lateral loads that are transferred to it by the roof. Therefore the building is considered "Earthquake Prone".

However it should be noted that considering the size and location of the amenity building (the weakest part of the building), it does not pose significant risk to the grandstand even if it collapses.



### **Key Damage Observed**

Key damage observed:

- ▶ Minor cracking in concrete masonry walls in the changing room areas of the amenity building.

### **Recommendations**

GHD recommend that further work is undertaken in order to develop a strengthening and repair scheme. This work should involve:

- ▶ Developing a strengthening works scheme to increase the seismic capacity of the grandstand and the amenity building to as near as practicable to 100% NBS, or at least 67% NBS.
- ▶ The structure should remain unoccupied until such time that strengthening works are completed.



## 1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of Denton Oval.

This report is a Quantitative Assessment of the building structure, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A quantitative assessment involves analysis and checking of all structural members that forms part of the structure that contributes in resisting of horizontal and vertical forces that are subjected to it. Furthermore, it is also used to evaluate the existing conditions of the structure with respect to our prevailing industry codes and standards.

The main purpose of this procedure is to assess how the structure will respond upon application of external forces and to what extend will the damage may be with respect to its existing condition. Evaluating the capacity of the structure versus the applied loads, we can determine the structure's rating in terms of percentage of New Building Standards (%NBS) as per NZSEE requirements.



## 2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

CERA now requires a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). The Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 has been adopted by CERA for evaluations. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

Factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage

### 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

#### Section 112 – Alterations



This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

#### **2.2.1 Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



## 2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## 2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



### 3. Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’ (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	% NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (Improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34% NBS.	100% NBS desirable. Improvement should achieve at least 67% NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally, Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement Required)	Unacceptable	Unacceptable

**Figure 1 NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE**

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

**Table 1      %NBS compared to relative risk of failure**



## 4. Building Description

### 4.1 General

Denton Oval is located in 442 Main South Road, Hornby Christchurch and can be accessed thru Chalmers Road. The site is consisting of a 400 m length concrete velodrome, a rugby playing field, a reinforced concrete grandstand with an amenity building underneath and a two storey concrete masonry Hornby cycling clubrooms building. The stadium was built in 1974 for the Commonwealth games. In 1990, the Hornby cycling clubrooms were constructed at the right side of the grandstand. A seismic gap was created in order to have a separation between the existing grandstand and the new Hornby cycling clubrooms building.

The main structure is composed of a grandstand and the amenity building. For the purpose of analysis, the two (2) are separately assessed and checked.

The grandstand is divided into two major components which are the steel frame and the concrete frame assembly. The grandstand has a base dimension of 11.80 m x 41.40 m and a height of approximately 9.30 m from ground to roof apex. It has a capacity of approximately 2000 people and offers a full view of the whole velodrome and the playing field.

The steel frame assembly serves as the support for the roof of the structure. The roof consists of lightweight metal roof sheeting on light gauge metal purlins supported by a series of 250UB rafters spanning from the back of the structure up to the front. These rafters are then supported by a 460UB longitudinal beam at the front and a series of 250UB columns at the back of the structure. The 460UB longitudinal beam is supported by 4-150x150x6 SHS columns spaced at every 13.80 m. Three (3) layers of 125x75x6 RHS horizontal girt beams are seen at the back of the structure in between 250UB columns. These girt beams are equally spaced up the height of the column and give lateral support to the columns and also supports the cladding for the grandstand. All the columns, both the 250UB and the 150x150x6 SHS, are pinned connected to the concrete frame structure below it.

The concrete frame assembly serves as the support for the steel frame and the bleacher seats. It is composed of a series of 450 mm x 450 mm R.C. columns supporting the 300 mm x 1000 mm pre-stressed concrete raking beams. These raking beams are inclined from the ground by 27°. A series of 225 mm x 550 mm longitudinal beams laterally support the columns in the longitudinal direction. Double T precast concrete units serve as the flooring for the grandstand and are supported by the raking beams. The concrete columns sit on reinforced concrete pad footings that are tied together by R.C. footing tie beams.


The amenity building is located underneath the grandstand. It is divided into two (2) blocks, namely Block A and B. Block A has a base dimension of 9.00 m x 22.90 m and Block B has 5.40 m x 13.80 m. Roof height for both Block A and B is 3.45 m from finished floor level. Block A serves as a changing room and office while Block B is the toilet block. A portion of Block A is under the grandstand while the rest is extended outward. Block B has its back wall at the face of the grandstand columns and extends outward from the grandstand. The roof is made of lightweight metal sheet on 75 mm x 50 mm timber purlins supported by 250 mm x 50 mm timber rafters. The walls are made up of 190 mm thick concrete masonry block. A 100 mm thick concrete ground slab serves as the floor for both Blocks A and B. The masonry block walls are only reinforced horizontally in bond beams at the top of the walls and vertically

at corners and edges of openings. The masonry block walls are just butted against the grandstand columns without any structural connection. The block walls sit on reinforced concrete strip footings.

Refer to Figure 3 to 6 for steel, concrete and masonry plans and a typical frame elevation of the structure.



**Figure 2** Aerial photograph of Denton Oval



Note:

B1 – 250mm x 550mm R.C. Beam

B2 – 250mm x 550mm R.C. Beam


PB1 – 300mm x 1000mm Pre-stress Concrete Beam

C1 – 450mm x 450mm R.C. Column

SC1 – 150x150x6 SHS

SC2 – 250UB

Figure 3 Framing plan of the grandstand



Note:

SB1 – 460UB

SB2(a-c) – 125x75x6 RHS

R1 – 250UB

Figure 4 Roof framing plan of the grandstand




Figure 5 Typical frame elevation




Figure 6 Masonry wall layout for Amenity Building



## **4.2 Gravity Load Resisting System**

### **4.2.1 Grandstand**

The gravity loads for this structure are resisted by the steel frame and concrete frame system.

The roof structure of the grandstand consists of lightweight metal roofing on light gauge metal purlins supported by a series of 250UB steel rafters. These steel rafters are supported by a 460UB longitudinal steel beam along Gridline B and series of 250UB steel columns along Gridline D. The longitudinal steel beam is then supported by 4-150x150x6SHS steel columns. These SHS columns are located along Gridline 1, 4, 7 and 10. Then this steel frame transfer the gravity loads to the pre-stressed concrete beam in which forms part of the concrete frame structure below.

The floor of the grandstand is composed of precast double tee units which are bolted and grouted to the pre-stressed concrete raking beams. These precast double tee units support the wood benches for the spectators. The raking beams then transferred the gravity forces to the R.C. columns along Gridline A and C. These columns then transfer the gravity load to the foundations.

### **4.2.2 Amenity Building**

The gravity loads in the amenity building for both Block A and B are resisted by the unreinforced masonry walls. These gravity loads are transferred by the roof consisting of lightweight metal sheeting on timber purlins supported by timber rafters to the unreinforced concrete masonry walls.

## **4.3 Lateral Load Resisting System**

### **4.3.1 Grandstand**

Lateral loads acting on the structure are resisted by the steel frame and concrete frame system.

The steel frame resists the lateral load for the upper portion of the grandstand. The roof cladding on steel purlins acts as a diaphragm that transfers lateral load to the steel rafters that are supported by steel columns. Lateral loads in longitudinal direction along Gridline D are resisted by series of 250UB columns and RHS girt beams while on Gridline B, the 4-SHS columns and the 460UB beam act together to provide a frame. For the transverse direction, steel frames consisting of a steel rafter and columns resist lateral loads.

The concrete frame resists the lateral load for the lower part of the structure. With the help of the precast concrete double tee units, which acts as diaphragms and as flooring as well for the grandstand, lateral loads are transferred to the pre-stressed raking beams. Lateral loads in longitudinal direction are resisted by reinforced concrete frame consisting of concrete columns and beams. Lateral loads in the transverse direction are resisted by the combination of reinforced concrete columns and pre-stressed concrete raking beams.

### **4.3.2 Amenity Building**

In the changing room areas, lateral loads are resisted by concrete masonry walls in both the long and short directions of the building.



The lateral loads in the amenity building are resisted by the unreinforced masonry walls. The lightweight roof acts as a diaphragm and transfers lateral loads to the walls in plane. Also, the timber rafters act as out-of-plane braces for these walls.



## 5. Assessment

### 5.1 Site Inspection

An inspection of the building was undertaken on the 18<sup>th</sup> of January 2012. Both the interior and exterior of the building were inspected. The building was observed to have a green placard in place. The main structural components of the building were all able to be viewed due to the exposed nature of the structure. The underside of the grandstand is open and the concrete masonry changing rooms and the two storey addition are unlined. No inspection of the foundations of the structure was able to be undertaken.

The inspection consisted of observing the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including observing the ground conditions, checking for damage in areas where damage would be expected for the structure and noting damage observed throughout the building in both structural and non-structural elements.

### 5.2 Investigation & Opening Up Work


Further inspections were carried out on the 17<sup>th</sup> and 18<sup>th</sup> of May 2012. The work included drafting of an as-built plan of the structure because there are no available drawings/plans, taking of measurements and dimensions of the structure as well as the key structural elements (i.e. columns, beams and walls). Reinforcement scanning using a Hilti PS200 Ferroscan was also performed. A series of photographs of key structural elements and connections were also taken.

### 5.3 Analysis and Modelling Methodology

#### 5.3.1 Mathematical Modelling

The three-dimensional frame modelling of the Denton Oval Grandstand structure was performed to realistically simulate the effects of the applied loads on the structure under different conditions such as normal operation, wind, earthquake and combinations thereof.

This modelling approach determines the adequacy of members or sections for the structure under various loading conditions.



**Figure 7 3D Mathematical Model of Denton Oval's Grandstand in Etabs**

Each section, member and node of the model was defined using the physical dimensions, material properties and connection details gathered from site inspections as stated in Section 5.2. Using Etabs Version 9.7.2 structural analysis software, a computer model that incorporates all the properties of the steel portal frame and reinforced concrete structure was prepared.

The Amenity Building was analysed separately using manual calculations and spread sheets.

### **5.3.2 Loadings**

Loadings such as permanent actions, imposed actions as well as wind and earthquake actions are considered in the analysis of the structure. Also the different loading combinations and factors of safety are used. New Zealand Standards (NZS) are used for the determination of each of the parameters and values required. The references used are listed in Section 13.

### **5.3.3 Seismic Design**

The Denton Oval structure was checked to the seismic design standards in accordance with the AS/NZ 1170.5, NZBC Clause B1 Structure and New Zealand Society of Earthquake Engineering Guidelines for Assessment and Improvement of the Structural Performance of Buildings in Earthquakes.

### **5.3.4 Wind Design**

As wind had the potential to be a dominant effect, additional action was considered in the analysis and checking of Denton Oval Grandstand structure. Wind action is included in order to take into account its effect to the structure. AS/NZ 1170.2:2011 was used as reference.



## **5.4 Calculations**

### **5.4.1 Determination of %NBS**

After analysing the structure with the use of the mathematical model and spread sheets, all the structural elements that form part for the structure were checked and individual demand capacity ratios were computed. From there the %NBS of each element was determined.



## 6. Damage Assessment

### 6.1 Surrounding Buildings

No damage to surrounding buildings was observed during our inspection of the site.

### 6.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during our inspection of the building.

Minor cracking was noted in the concrete masonry partition wall that was built around one of the beams supporting the stand seating as can be seen in Photograph 6.

Minor cracking was also noted in a number of the concrete masonry walls of the changing room areas. These cracks have typically occurred around the doorways and in the corners of the rooms as can be seen in Photograph 7.

### 6.3 Ground Damage

No ground damage was observed during our inspection of the site.



## 7. Analysis

### 7.1 Seismic Parameters

The seismic design parameters based on current design requirements from NZS1170.5:2002, NZS 3604:2011 and the NZBC clause B1 for this building are:

Location	:	Christchurch
Importance Level	:	3
Site Classification	:	D
Seismic Zone Factor	:	0.30
(Table 3.3, NZS 1170.5:2004)		
Annual Probability of Exceedance	:	1/1000 (ULS)
(Table 3.3, NZS 1170.0:2002)		
Annual Probability of Exceedance	:	1/25 (SLS)
(Table 3.3, NZS 1170.0:2002)		
Return Period Factor (Ru)	:	1.30 (ULS)
(Table 3.5, NZS 1170.5:2004)		
Return Period Factor (Ru)	:	0.33 (SLS)
(Table 3.5, NZS 1170.5:2004)		
Ductility Factor,		
Concrete Structure, ( $\mu_c$ )	:	1.25
Steel Structure, ( $\mu_s$ )	:	2.00
Masonry Wall, ( $\mu_w$ )	:	1.25
Performance Factor (Sp)	:	0.925
Gravitational Constant (g)	:	9.81 m/sec <sup>2</sup>
Liquefaction Potential	:	Low

### 7.2 Wind Parameters

The wind design parameters based on current design requirements from NZS1170.2:2011 are:

Location	:	Christchurch
Importance Level	:	3
Terrain Category Definition	:	Category 2
Region Classification	:	A7
Annual Probability of Exceedance	:	1/1000 (ULS)



(Table 3.3, NZS 1170.0:2002)

Annual Probability of Exceedance : 1/25 (SLS)

(Table 3.3, NZS 1170.0:2002)

Wind Direction Multiplier (Md) : 1.00

Shielding Multiplier (Ms) : 1.00

Topographic Multiplier (Mt) : 1.00

Density of Air : 1.20 kg/m<sup>3</sup>

### **7.3 Structural Ductility Factor**

A structural ductility factor of 1.25 has been assumed for the reinforced concrete frame while 2.00 for the steel frame. With this, a structural ductility factor of 1.25 was adopted for the whole structure because the frames are connected to each other.

For the unreinforced masonry wall, a structural ductility factor of 1.25 has been assumed.



## 8. Geotechnical Consideration

The site is situated within a recreational reserve, within the suburb of Hornby in western Christchurch. It is relatively flat at approximately 30m above mean sea level. It is approximately 2.5km west of the Heathcote River, and 15km west of the coast (Pegasus Bay) at New Brighton.

The park is located between the Main South Railway line to the north and Main South Road (SH1) to the south. It is bound to the east by commercial properties and west by residential properties. The property is owned and maintained by the Christchurch City Council.

### 8.1.1 Published Information on Ground Conditions

#### 8.1.1.1 Published Geology

The geological map of the area<sup>1</sup> indicates that the site is underlain by:

- Holocene alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, which contains alluvial gravel, sand and silt of historic river flood channels.

#### 8.1.1.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates eight boreholes are located within a 200m radius of the site. Of these boreholes, six of them had lithographic logs of which four are considered for this report. The site geology described in these logs shows the area is predominantly sandy gravels with varying amounts of silt and clay.

**Table 2 ECan Bore Log Summary Table**

Bore Name	Depth (m bgl)	Log Summary
(110m SE of site)	0 – 1	Hardfill
	1 – 21	Fine to coarse GRAVEL and SAND
	21 – 49	Medium dense to dense GRAVEL, with some sand and clay
	49 – 52	Dense GRAVEL, with sand and clay
	52 – 79	Fine to medium GRAVEL, with traces of clay
	79 – 86	Sandy medium GRAVEL
	86 – 88	PEAT
	88 – 94	Dense GRAVEL, and stiff CLAY
	94 – 102	Dense Sandy GRAVEL, with some yellow clay
	0 – 0.3	
	0.3 – 3.9	

<sup>1</sup> Brown, L. J. and Weeber J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.



Bore Name	Depth (m bgl)	Log Summary
	3.9 – 40.5	Sandy GRAVEL, with some clay
	40.5 – 49.5	CLAY, with some gravel and peat
	49.5 – 52	Dense GRAVEL, with some clay
	52 – 95.8	Layers of CLAY, SAND and GRAVEL
	0 – 6	Gravelly SAND
	6 – 23.5	Sandy GRAVEL, with traces of silt and clay
	23.5 – 29.5	Sandy GRAVEL
	0 – 1	Clayey GRAVEL
	1 – 9	Sandy GRAVEL, with some clay and silt
	9 – 10.8	Sandy GRAVEL
	10.8 – 12.5	Slightly clayey, fine SAND
	12.5 – 20.7	Clayey GRAVEL and sandy GRAVEL

It should be noted the quality of soil logging descriptions included on the boreholes is unknown and were likely written by the well driller and not a geotechnical professional or to a recognised geotechnical standard. In addition strength data is not recorded.

#### 8.1.1.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the site.

#### 8.1.1.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has zoned the site as Green, indicating repair and rebuild may take place

CERA has published areas showing the Green Zone Technical Category in relation to the risk of future liquefaction and how these areas are expected to perform in future earthquakes.

The site is classified as “not applicable”. This indicates that it is a non-residential properties in an urban area that has not been given a Technical Category. However, nearby land has been classified as Technical category 1 (TC1) which means that liquefaction is unlikely in a future earthquake event.

#### 8.1.1.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake (Figure 8) shows no signs of liquefaction outside the building footprint or adjacent to the site.

**Figure 8 Post February 2011 Earthquake Aerial Photography<sup>2</sup>**



#### 8.1.1.6 Summary of Ground Conditions from desk study

From the ECan borehole information the ground conditions on Main South Road comprise multiple strata of gravel, sandy gravel and sand, with varying amounts of silt and clay.

### 8.1.2 Seismicity

#### 8.1.2.1 Nearby Faults

There are many faults in the Christchurch region, however only those considered most likely to have an adverse effect on the site are detailed below.

**Table 3 Summary of Known Active Faults<sup>3,4</sup>**

Known Active Fault	Distance from Site (km)	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120 NW	8.3	~300 years
Greendale (2010) Fault	13 W	7.1	~15,000 years

<sup>2</sup> Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>

<sup>3</sup> Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002); "A New Seismic Hazard Model for New Zealand", *Bulletin of the Seismological Society of America*, Vol. 92 No. 5, pp 1878-1903, June 2002.

<sup>4</sup> GNS Active Faults Database <http://maps.gns.cri.nz/website/af/viewer>



Known Active Fault	Distance from Site (km)	Max Likely Magnitude	Avg Recurrence Interval
Hope Fault	100 N	7.2~7.5	120~200 years
Kelly Fault	100 NW	7.2	~150 years
Porters Pass Fault	54 NW	7.0	~1100 years

Recent earthquakes since 4 September 2010 have identified the presence of a previously unmapped fault system underneath the Canterbury Plains including, Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available and average recurrence intervals are yet to be estimated.

### 8.1.2.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 now quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

The recent seismic activity in Canterbury has produced earthquakes of Magnitude-7.1 (Sept., Darfield), 6.3 (Feb., and June, Christchurch) with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

### 8.1.3 Field Investigations

In order to further understand the ground conditions at the site, intrusive testing comprising one piezocone CPT investigation was conducted at the site on 12 April 2012.

The location of the test is tabulated in Table 4.

**Table 4 Coordinates of Investigation Locations**

Investigation	Depth (m bgl)	Easting (NZMG)	Northing (NZMG)
CPT 001	2.0	2471263	5740467

The CPT investigation was undertaken by McMillan Drilling Service on 12 April 2012, typically to a target depth of 20m below ground level. However, refusal was reached at depth of 2.0m due to the presence of dense gravels. Please refer to the attached CPT results for detail (Appendix A).

Interpretation of output graphs<sup>5</sup> from the investigation showing Cone Tip Resistance ( $q_c$ ), Friction Ratio (Fr), Inferred Lithology and Inferred Liquefaction Potential are presented in Table 5.

<sup>5</sup> McMillans Drilling CPT data plots, Appendix A.



## 8.1.4 Ground Conditions Encountered

### 8.1.4.1 Summary of CPT-Inferred Lithology

**Table 5 Summary of CPT-Inferred Lithology**

Depth (m)	Lithology <sup>1</sup>	Cone Tip Resistance $q_c$ (MPa)	Friction Ratio Fr (%)
0 – 2.0	Surface soil	~5	~1
>2.0	Gravel	> 20	~0

## 8.1.5 Interpretation of Ground Conditions

### 8.1.5.1 Liquefaction Assessment

Based on an overall assessment of the following, the site is considered unlikely to be susceptible to liquefaction confirming the CERA TC1 classification.

- The identified ground conditions confirmed by CPT;
- The minimal damage to ground (and building) caused by the Canterbury earthquake sequence evidenced by aerial and visual inspection.

### 8.1.5.2 Slope Failure and/or Rockfall Potential

The site is located within Hornby, a flat suburb in western Christchurch. Global slope instability risk is considered negligible. However, any localised retaining structures and/or embankments should be further investigated to determine the site-specific slope instability potential.

### 8.1.5.3 Foundation Recommendations

Following the guidance provided by the Department of Housing and building<sup>6</sup> (DBH) in Section 4 for repairing of foundations for TC1 dwellings, the following geotechnical recommendations are provided.

- A site subsoil class of **D**, Deep or Soft Soil, should be adopted for this sites (in accordance with NZS 1170.5:2004)
- An allowable bearing capacity of 100kPa can be used for any replacement shallow foundations required.
- If a re-build is deemed necessary a shallow investigation specific to the new building footprint should be undertaken. Shallow ground improvement is not required.



## 9. Results

The following are the results of the structural analysis for Denton Oval structure.


### 9.1 %NBS

Our analysis showed that seismic effects were most critical.

#### 9.1.1 Grandstand

##### Steel Rafters

Ten (10) steel rafters rated below 67% NBS and they are highlighted in red in the figure below. The lowest rating achieved is 35% NBS.




##### Steel Beams

All steel beams have a rating of greater than 67% NBS.



### Steel Columns

Ten (10) steel columns rated below 67% NBS. They are highlighted in red in the figure below.



### Pre-stressed Raking Beams


All pre-stressed concrete beams have a rating of greater than 67% NBS.

### Reinforced Concrete Beams

All reinforced concrete beams have a rating of greater than 67% NBS.


### Reinforced Concrete Footing Tie Beams

Nine (9) reinforced concrete footing tie beams rated below 67% NBS and they are highlighted in red in the figure below. The lowest rating achieved is 44% NBS.



### Reinforced Concrete Columns

Ten (10) reinforced concrete columns rated below 67% NBS and they are highlighted in red in the figure below. The lowest rating achieved is 52% NBS.




#### 9.1.2 Amenity Building

##### Unreinforced Masonry Walls

Block A - Three (3) unreinforced masonry wall rated below 34% NBS and twenty two (22) unreinforced masonry walls rated below 67% NBS. They are highlighted in red in the figure below.

Block B - Five (5) unreinforced masonry wall rated below 34% NBS and two (2) unreinforced masonry walls rated below 67% NBS. They are highlighted in red in the figure below.





## **Reinforced Concrete Masonry Bond Beam**

All reinforced concrete masonry bond beams have a rating of greater than 67% NBS.

### **9.1.3 Hornby Cycling Clubrooms**

This building was assessed at 65% NBS based on a qualitative assessment completed in February 2012. No further assessment has been carried out.

## **9.2 Lateral Seismic Drift**

The computed drift of the Denton Oval is 34 mm and 60 mm in the longitudinal and transverse direction respectively.

The existing seismic gap between the grandstand and the two (2) storey masonry horny cycling club building is approximately 100 mm in the longitudinal direction.

## **9.3 Discussion of Results**

Based on the quantitative analysis done for the structure, it is found that the lowest rating achieved is 22% NBS. This rating comes from the unreinforced masonry wall in Block B of Amenity building. This is to be expected since there is virtually no vertical or horizontal reinforcement present in the walls. It would appear that the amenity building, considering the materials used and the prevailing codes and standards at the time it was constructed, serves only to carry gravity loads and not lateral loads.

The grandstand as a structure, considered in isolation, achieved a ratings of 35% NBS.



## 10. Conclusions

### 10.1 Building Capacity Assessment

Based on the quantitative assessment of the structure, it is found that the overall seismic capacity is 22% NBS. This is a result of the unreinforced masonry walls in Block B of the Amenity building under the grandstand. Therefore, the building is classified as an 'Earthquake Prone' building.



## 11. Recommendations

GHD recommend that further work is undertaken in order to develop a strengthening and repair scheme. This work should involve:

- ▶ Developing a strengthening works scheme to increase the seismic capacity of the Denton Oval grandstand and the amenity building to as near as practicable to 100% NBS, or at least 67% NBS. This will need to consider compliance with accessibility and fire requirements.
- ▶ The structure should remain unoccupied until such time that strengthening works are completed.



## 12. Limitations

### 12.1 General

This report has been prepared subject to the following limitations:

- ▶ The only available drawing is for the amenity building with nothing for the grandstand. As a result, the information contained in this report has been inferred from site inspection done on the structure.
- ▶ The Hornby cycling clubrooms building was not checked.
- ▶ The foundations of the structure were not checked.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report.

### 12.2 Geotechnical Limitations

The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data by third parties.

Where drill hole or test pit logs, cone tests, laboratory tests, geophysical tests and similar work have been performed and recorded by others under a separate commission, the data is included and used in the form provided by others. The responsibility for the accuracy of such data remains with the issuing authority, not with GHD.

The advice tendered in this report is based on information obtained from the desk study investigation location test points and sample points. It is not warranted in respect to the conditions that may be encountered across the site other than at these locations. It is emphasised that the actual characteristics of the subsurface materials may vary significantly between adjacent test points, sample intervals and at locations other than where observations, explorations and investigations have been made. Subsurface conditions, including groundwater levels and contaminant concentrations can change in a limited time. This should be borne in mind when assessing the data.

It should be noted that because of the inherent uncertainties in subsurface evaluations, changed or unanticipated subsurface conditions may occur that could affect total project cost and/or execution. GHD does not accept responsibility for the consequences of significant variances in the conditions and the requirements for execution of the work.

The subsurface and surface earthworks, excavations and foundations should be examined by a suitably qualified and experienced Engineer who shall judge whether the revealed conditions accord with both the assumptions in this report and/or the design of the works. If they do not accord, the Engineer shall modify advice in this report and/or design of the works to accord with the circumstances that are revealed.



An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances which arise from the issue of the report which have been modified in any way as outlined in Section 8.



## 13. References

1. Detailed Engineering Evaluation Qualitative Report for Denton Oval, February 24, 2012, GHD Pty. Ltd.
2. AS/NZS 1170.0:2002 Structural design actions, Part 0: General Principles, New Zealand Standards
3. AS/NZS 1170.0 Supplement 1:2002 Structural design actions - General principles - Commentary
4. AS/NZS 1170.1:2002 Structural design actions, Part 1: Permanent, imposed and other actions, New Zealand Standards
5. AS/NZS 1170.1 Supplement 1:2002 Structural design actions – Permanent, imposed and other actions - Commentary
6. AS/NZS 1170.2:2011 Structural design actions, Part 2: Wind actions, New Zealand Standards
7. AS/NZS 1170.2 Supplement 1:2002 Structural design actions – Wind actions - Commentary
8. NZS 1170.5:2004 Structural design actions, Part 5: Earthquake actions, New Zealand Standards
9. NZS 1170.5 Supplement 1:2004 Structural design actions –Earthquake actions – New Zealand - Commentary
10. NZS 3101:2006 Concrete Structure Standard, Part 1-The design of concrete structures
11. NZSEE 2006, Assessment and Improvement of the Structural Performance of Buildings in Earthquakes, New Zealand Society for earthquake Engineering
12. Compliance Document for New Zealand Building Code Clause B1: Structure, Department of Building and Housing
13. Engineering Advisory Group, Guidance in Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft, issued by Engineering Advisory Group on 19 July 2011.
14. Australian Steel Institute (ASI), Design capacity tables for structural steel, Volume 1: Open Sections
15. Australian Steel Institute (ASI), Design capacity tables for structural steel, Volume 2: Hollow Sections



Appendix A

# Geotechnical Investigation Reports and Analysis

## CPT ANALYSIS NOTES

### Soil Type

Interpretation using chart of Robertson & Campanella (1983). This is a simple but well proven interpretation using cone tip resistance ( $q_c$ ) and friction ratio ( $f_R$ ) only. No normalisation for overburden stress is applied. Cone tip resistance measured with the piezocone is corrected with measured pore pressure ( $u_c$ ).

	sand (and gravel)
	silt-sand
	silt
	clay-silt
	clay
	peat

### Liquefaction Screening

The purpose of the screening is to highlight susceptible soils, that is sand and silt-sand in a relatively loose condition. This is not a full liquefaction risk assessment which requires knowledge of the particular earthquake risk at a site and additional analysis. The screening is based on the chart of Shibata and Teparaksa (1988).

	high susceptibility
	medium susceptibility
	low susceptibility

High susceptibility is here defined as requiring a shear stress ratio of 0.2 to cause liquefaction with  $D_{50}$  for sands assumed to be 0.25 mm and for silty sands to be 0.05 mm.

Medium susceptibility is here defined as requiring a shear stress ratio of 0.4 to cause liquefaction with  $D_{50}$  for sands assumed to be 0.25 mm and for silty sands to be 0.05 mm.

Low susceptibility is all other cases.

### Relative Density ( $D_R$ )

Based on the method of Baldi et. al. (1986) from data on normally consolidated sand.

### Undrained Shear Strength ( $S_u$ )

Derived from the bearing capacity equation using  $S_u = (q_c - \sigma_{vo})/15$ .

DEPTH IN METERS BELOW GROUND LEVEL




CLIENT : GHD  
LOCATION : Christchurch Various (CCC Properties)  
DATE : 12-4-2012  
OPERATOR : S. Cardona  
REMARK 1 : CPTu04  
REMARK 2 : Effective Refusal

JOB # : 10386  
TEST # : 4

**McMILLAN**  
DRILLING SERVICES  
120 High St Southbridge CANTERBURY NZ  
Ph +64 3 324 2571 Fax +64 3 324 2431  
www.drilling.co.nz

# PIEZOCONE PENETROMETER TEST (CPTU) INTERPRETIVE REPORT



Job No: 10386  
 CPT No: CPTu04  
 Project: GHD  
 Location: Christchurch Various (CCC Properties)

Date: 12-4-2012  
 Operator: S. Cardona  
 Remark: Effective Refusal



Appendix B  
Photographs



**Photograph 1 Two storey concrete masonry extension.**



**Photograph 2 View of the stand from the south.**




**Photograph 3 View of the stand from the west.**



**Photograph 4 Double Tee units supported by reinforced concrete beams.**



**Photograph 5 Bolting and grouting of Double Tee units.**



**Photograph 6 Cracking in concrete masonry wall where beam has moved relative to the wall.**



**Photograph 7 Cracking in the corner between concrete masonry walls in changing rooms.**



**Photograph 8 Steel girts between steel posts in the roof.**



**Photograph 9 View of the stand from the north.**




**Photograph 10 Connection of RHS posts to concrete beams.**




**Photograph 11 Beam-column joints in frame running along building. Note the short column between the beams.**




Appendix C  
Existing Drawings





Note: Cover to main reinforcement to be 2" (Except below ground level where cover to be 3" min.)



Section A-A



Section B-B



Note: Structural concrete in Columns and Beams to be 3000 PSI at 28 days. All other concrete 2500 PSI at 28 days.

Drawn T.J.B. Oct 7  
Traced " "  
Checked " "


Scales 1/2" = 1' foot  
1/8" Full size.

Proposed Amenity Building  
for  
Paparu County Council.  
Denton Park.




Approved  
Hjshberg MNZIE  
County Engineer



Reference No  
B25/4



Detail H




Section 4-6




Section 1-1

Section 2-2




Section 3-3

Section 4-4



Section 11-11



End Elevation of Ticket Box Section 8-8


Note All openings, ends of free standing walls and corners to be reinforced vertically with 2 1/2 inch diameter rods.

Drawn T.J.B Oct 17	Scale 1/2" = 1 foot.
Traced " "	
Checked " "	


Proposed Amenity Building Denton Park.  
for  
Paparua County Council.

Approved  
Ryherberg MNZIE  
County Engineer


Reference No.  
B25/5



North Elevation.



South Elevation.



Plan.





Drawn T.J.B. Oct 67  
 Traced " " "  
 Checked " " "

Scale 1/8" = 1 foot.

Proposed Amenity Building Denton Park.  
 for  
 Paparua County Council.

Approved  
 H. Hysberg MNZIE  
 County Engineer

Reference No  
 B 25/2



Drawn TJB Oct 67	Scales 1/2" = 1 foot 1/2 Full Size.	Proposed Amenity Building for Papara County Council. Denton Park.	Approved M. J. M. MNZIE County Engineer	Reference No B 25/3
Traced				
Checked				



Appendix D  
CERA Report Forms

Detailed Engineering Evaluation Summary Data

V1.11

<b>Location</b>		Building Name: Denton Oval - Stand	Reviewer: Stephen Lee
Building Address: _____	Unit No: _____	Street: 442 Main Road South	CPEng No: 1006840
Legal Description: RS 41304			Company: GHD
			Company project number: 51/30596/04
			Company phone number: 04 472 0799
			Date of submission: 7/03/2013
			Inspection Date: 18/1/12
			Revision: FINAL
			Is there a full report with this summary? yes
GPS south: _____	Degrees	Min	Sec
GPS east: _____	43	32	31.98
	172	31	14.11
Building Unique Identifier (CCC): BU 0770-003 EQ2			

<b>Site</b>	Site slope: flat	Max retaining height (m): 0
	Soil type: mixed	Soil Profile (if available): _____
	Site Class (to NZS1170.5): D	If Ground improvement on site, describe: _____
Proximity to waterway (m, if <100m): _____		Approx site elevation (m): 30.00
Proximity to cliff top (m, if < 100m): _____		
Proximity to cliff base (m, if <100m): _____		

<b>Building</b>	No. of storeys above ground: 1	single storey = 1	Ground floor elevation (Absolute) (m): 30.00
	Ground floor split? no		Ground floor elevation above ground (m): 0.00
	Storeys below ground: 0		
	Foundation type: isolated pads, no tie beams		if Foundation type is other, describe: Foundations are assumed.
	Building height (m): 11.00	height from ground to level of uppermost seismic mass (for IEP only) (m): 11	
	Floor footprint area (approx): 900		Date of design: 1965-1976
	Age of Building (years): 38		
	Strengthening present? no		If so, when (year)? _____
	Use (ground floor): other (specify) _____		And what load level (%g)? _____
	Use (upper floors): other (specify) _____		Brief strengthening description: _____
	Use notes (if required): Sports stand with changing facilities.		
	Importance level (to NZS1170.5): IL3		

<b>Gravity Structure</b>	Gravity System: frame system	
	Roof: steel framed	rafter type, purlin type and cladding _____
	Floors: precast concrete toppingless	unit type and depth (mm), diaphragm _____
	Beams: cast-insitu concrete	overall depth x width (mm x mm) _____
	Columns: cast-insitu concrete	typical dimensions (mm x mm) _____
	Walls: partially filled concrete masonry	thickness (mm) _____

<b>Lateral load resisting structure</b>	Lateral system along: ductile concrete moment frame	<b>Note: Define along and across in detailed report!</b>	note typical bay length (m) 5.3
	Ductility assumed, $\mu$ : 2.00	0.54 from parameters in sheet	estimate or calculation? calculated
	Period along: 0.54		estimate or calculation? _____
	Total deflection (ULS) (mm): _____		estimate or calculation? _____
	maximum interstorey deflection (ULS) (mm): _____		
	Lateral system across: ductile concrete moment frame		note typical bay length (m) 12
	Ductility assumed, $\mu$ : 2.00	0.00	estimate or calculation? calculated
	Period across: 0.54		estimate or calculation? _____
	Total deflection (ULS) (mm): _____		estimate or calculation? _____
	maximum interstorey deflection (ULS) (mm): _____		

**Separations:**

north (mm):		leave blank if not relevant
east (mm):	150	
south (mm):		
west (mm):		

**Non-structural elements**

Stairs:	other (specify)	describe	none
Wall cladding:	exposed structure	describe	
Roof Cladding:	Metal	describe	
Glazing:	other (specify)		none
Ceilings:	none		
Services(list):			

**Available documentation**

Architectural	none	original designer name/date	
Structural	none	original designer name/date	
Mechanical	none	original designer name/date	
Electrical	none	original designer name/date	
Geotech report	none	original designer name/date	

**Damage**

Site: (refer DEE Table 4-2)

Site performance:	No ground damage noted.	Describe damage:	
Settlement:	none observed	notes (if applicable):	
Differential settlement:	none observed	notes (if applicable):	
Liquefaction:	none apparent	notes (if applicable):	
Lateral Spread:	none apparent	notes (if applicable):	
Differential lateral spread:	none apparent	notes (if applicable):	
Ground cracks:	none apparent	notes (if applicable):	
Damage to area:	none apparent	notes (if applicable):	

**Building:**

Current Placard Status: green

Along

Damage ratio: 3%

Describe (summary): Minor, non-structural cracking. Less than 5%. Describe how damage ratio arrived at:

Across

Damage ratio: 3%

Describe (summary): Minor, non-structural cracking. Less than 5%.  $Damage\_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$

Diaphragms

Damage?: no Describe:

CSWs:

Damage?: no Describe:

Pounding:

Damage?: no Describe:

Non-structural:

Damage?: no Describe:

**Recommendations**

Level of repair/strengthening required:	significant structural and strengthening	Describe:	Strengthening to 67% Recommended
Building Consent required:	yes	Describe:	
Interim occupancy recommendations:	do not occupy	Describe:	

Along

Assessed %NBS before: 35% ##### %NBS from IEP below

Assessed %NBS after: 35%

Across

Assessed %NBS before: 35% ##### %NBS from IEP below

Assessed %NBS after: 35%

If IEP not used, please detail assessment methodology: Quantitative Assessment

Detailed Engineering Evaluation Summary Data

V1.11

<b>Location</b>		Building Name: Denton Oval - Masonry Extension	Reviewer: Stephen Lee
Building Address: _____	Unit No: _____	Street: 442 Main Road South	CPEng No: 1006840
Legal Description: RS 41304			Company: GHD
			Company project number: 51/30596/04
			Company phone number: 04 472 0799
			Date of submission: 7/03/2013
			Inspection Date: 18/1/12
			Revision: FINAL
			Is there a full report with this summary? yes
GPS south: _____	Degrees	Min	Sec
GPS east: _____	43	32	31.98
	172	31	14.11
Building Unique Identifier (CCC): BU 0770-003 EQ2			

<b>Site</b>	Site slope: flat	Max retaining height (m): 0
	Soil type: mixed	Soil Profile (if available): _____
	Site Class (to NZS1170.5): D	If Ground improvement on site, describe: _____
Proximity to waterway (m, if <100m): _____		Approx site elevation (m): 30.00
Proximity to cliff top (m, if < 100m): _____		
Proximity to cliff base (m, if <100m): _____		

<b>Building</b>	No. of storeys above ground: 2	single storey = 1	Ground floor elevation (Absolute) (m): 30.00
	Ground floor split? no		Ground floor elevation above ground (m): 0.00
	Storeys below ground: 0		if Foundation type is other, describe: Foundations are assumed.
	Foundation type: strip footings	height from ground to level of uppermost seismic mass (for IEP only) (m): 6	Date of design: 1976-1992
	Building height (m): 6.00		
	Floor footprint area (approx): 300		
	Age of Building (years): 25		
	Strengthening present? no		If so, when (year)? _____
	Use (ground floor): other (specify) _____		And what load level (%g)? _____
	Use (upper floors): other (specify) _____		Brief strengthening description: _____
	Use notes (if required): Sports stand with changing facilities.		
	Importance level (to NZS1170.5): IL2		

<b>Gravity Structure</b>	Gravity System: load bearing walls	rafter type, purlin type and cladding: _____
	Roof: timber framed	slab thickness (mm): _____
	Floors: concrete flat slab	overall depth x width (mm x mm): _____
	Beams: cast-insitu concrete	typical dimensions (mm x mm): _____
	Columns: cast-insitu concrete	thickness (mm): _____
	Walls: partially filled concrete masonry	

<b>Lateral load resisting structure</b>	Lateral system along: partially filled CMU	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): 5.3
	Ductility assumed, $\mu$ : 1.50	##### enter height above at H31	wall thickness (m): _____
	Period along: 0.40		estimate or calculation? estimated
	Total deflection (ULS) (mm): _____		estimate or calculation? _____
	maximum interstorey deflection (ULS) (mm): _____		estimate or calculation? _____
	Lateral system across: partially filled CMU		note total length of wall at ground (m): 12
	Ductility assumed, $\mu$ : 1.50		wall thickness (m): _____
	Period across: 0.40	##### enter height above at H31	estimate or calculation? estimated
	Total deflection (ULS) (mm): _____		estimate or calculation? _____
	maximum interstorey deflection (ULS) (mm): _____		estimate or calculation? _____

**Separations:**

north (mm):		leave blank if not relevant
east (mm):		
south (mm):		
west (mm):	150	

**Non-structural elements**

Stairs:	other (specify)	describe	none
Wall cladding:	exposed structure	describe	
Roof Cladding:	Metal	describe	
Glazing:	other (specify)		none
Ceilings:	none		
Services(list):			

**Available documentation**

Architectural	none	original designer name/date	
Structural	none	original designer name/date	
Mechanical	none	original designer name/date	
Electrical	none	original designer name/date	
Geotech report	none	original designer name/date	

**Damage**

Site: (refer DEE Table 4-2)

Site performance:	No ground damage noted.	Describe damage:	
Settlement:	none observed	notes (if applicable):	
Differential settlement:	none observed	notes (if applicable):	
Liquefaction:	none apparent	notes (if applicable):	
Lateral Spread:	none apparent	notes (if applicable):	
Differential lateral spread:	none apparent	notes (if applicable):	
Ground cracks:	none apparent	notes (if applicable):	
Damage to area:	none apparent	notes (if applicable):	

**Building:**

Current Placard Status: green

Along	Damage ratio:	4%	Describe how damage ratio arrived at:	
	Describe (summary):	Minor cracking.		
Across	Damage ratio:	4%		
	Describe (summary):	Minor cracking.		

$$Damage\_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

Diaphragms	Damage?:	no	Describe:	
CSWs:	Damage?:	no	Describe:	
Pounding:	Damage?:	no	Describe:	
Non-structural:	Damage?:	no	Describe:	

**Recommendations**

Level of repair/strengthening required:	significant structural and strengthening	Describe:	Strengthening to 67% NBS
Building Consent required:	yes	Describe:	
Interim occupancy recommendations:	do not occupy	Describe:	

Along	Assessed %NBS before:		22%	##### %NBS from IEP below	If IEP not used, please detail assessment methodology:
	Assessed %NBS after:		22%		
Across	Assessed %NBS before:		22%	##### %NBS from IEP below	
	Assessed %NBS after:		22%		



**GHD**

Level 11, Guardian Trust House  
15 Willeston street, Wellington 6011  
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

**© GHD Limited 2013**

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

**Document Status**

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
FINAL	Jay Zeus Rivera	Stephen Lee		Nick Waddington		07/03/2013