



**Sockburn Civil Defence Training Centre**

**BU 1531-003 EQ2**

***Detailed Engineering Evaluation***

**Quantitative Assessment Report**

**149 Main South Road, Christchurch**

**Christchurch City Council**



# Sockburn Civil Defence Training Centre Detailed Engineering Evaluation

**Quantitative Assessment Report**  
**149 Main South Road, Sockburn, Christchurch**  
**Christchurch City Council**

Prepared By

  
Toby Tscherry  
Graduate Structural Engineer, GIPENZ

Reviewed By

  
Alistair Boyce  
Senior Structural Engineer, CPEng 209860

Opus International Consultants Limited  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140, New Zealand

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Date: September 2012  
Reference: 6-QUCCC.68  
Status: Final

Training Centre, Sockburn Civil Defence Depot  
BU 1531-003 EQ2

Detailed Engineering Evaluation  
Quantitative Report - SUMMARY  
Final

149 Main South Road, Christchurch

## **Background**

This is a summary of the quantitative assessment report for the building structure at 149 Main South Road, Sockburn, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 22 March 2011 and 13 July 2012 and available drawings.

## **Key Damage Observed**

The following damage has been noted:

- Cracking up to 4mm wide at intersecting walls throughout the building in the top courses of the concrete block.
- Minor internal step cracks in the block walls in along the north-east side of the building, and in the west corner in the toilet block.
- Minor cracking of the Pinex ceiling lining in the shower area.
- A new gap between the suspended tiled ceiling system and the walls in the lecture room indicating rotation of the ceiling system.

## **Critical Structural Weaknesses**

No critical structural weaknesses have been identified in this building.

## **Indicative Building Strength (from quantitative assessment)**

Based on the information available, and from undertaking a quantitative assessment, the building's original capacity has been assessed to be in the order of 42% NBS and post-earthquake capacity in the order of 42% NBS. The building is therefore not classed as an earthquake prone building.

## **Recommendations**

- a) A strengthening works scheme be developed to increase the seismic capacity of the building to at least 67% NBS - this will need to consider compliance with accessibility and fire requirements.
- b) Access to the building should be prevented until such time that the cordon around the Sockburn Service Centre has been removed.

## **Contents**

|           |   |           |
|-----------|---|-----------|
| <b>1</b>  | <b>Introduction.....</b>                      | <b>1</b>  |
| <b>2</b>  | <b>Compliance .....</b>                       | <b>1</b>  |
| <b>3</b>  | <b>Earthquake Resistance Standards .....</b>  | <b>4</b>  |
| <b>4</b>  | <b>Background Information .....</b>           | <b>7</b>  |
| <b>5</b>  | <b>Survey.....</b>                            | <b>8</b>  |
| <b>6</b>  | <b>Structural Damage.....</b>                 | <b>9</b>  |
| <b>7</b>  | <b>Detailed Seismic Assessment.....</b>       | <b>9</b>  |
| <b>8</b>  | <b>Summary of Geotechnical Appraisal.....</b> | <b>11</b> |
| <b>9</b>  | <b>Remedial Options .....</b>                 | <b>11</b> |
| <b>10</b> | <b>Conclusions .....</b>                      | <b>12</b> |
| <b>11</b> | <b>Recommendations.....</b>                   | <b>12</b> |
| <b>12</b> | <b>Limitations.....</b>                       | <b>12</b> |
| <b>13</b> | <b>References .....</b>                       | <b>12</b> |

**Appendix 1 – Photographs**

**Appendix 2 – Floor Plan**

**Appendix 3 – DEEP Spreadsheet**

## **1 Introduction**

Opus International Consultants Limited has been engaged by Christchurch City Council (CCC) to undertake a detailed seismic assessment of the Civil Defence Training Centre building at the Sockburn Civil Defence Depot, located at 149 Main South Road, Christchurch following the Canterbury earthquake events since 2010.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [3] [4].

## **2 Compliance**

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### **2.1 Canterbury Earthquake Recovery Authority (CERA)**

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial quantitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.
2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Any building with a capacity of less than 34% of new building standard (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% as required by the CCC Earthquake Prone Building Policy.

## **2.2 Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

### **Section 112 - Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration.

This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) is satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'.

This is typically interpreted by CCC as being 67% of the strength of an equivalent new building. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### **Section 121 – Dangerous Buildings**

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.

- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- 36% increase in the basic seismic design load for Christchurch (Z factor increased from 0.22 to 0.3);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

## 3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

| Description            | Grade  | Risk     | %NBS        | Existing Building Structural Performance      | Improvement of Structural Performance   |   |
|------------------------|--------|----------|-------------|---|---|---|
|                        |        |          |             |   | Legal Requirement   | NZSEE Recommendation  |
| Low Risk Building      | A or B | Low      | Above 67    | Acceptable (improvement may be desirable)     | The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS. | 100%NBS desirable. Improvement should achieve at least 67%NBS |
| Moderate Risk Building | B or C | Moderate | 34 to 66    | Acceptable legally. Improvement recommended   |   | Not recommended. Acceptable only in exceptional circumstances |
| High Risk Building     | D or E | High     | 33 or lower | Unacceptable (Improvement required under Act) | Unacceptable  | Unacceptable  |

**Figure 1: NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

**Table 1: %NBS compared to relative risk of failure**

| Percentage of New Building Standard (%NBS) | Relative Risk (Approximate) |
|--|-----------------------------|
| >100                                       | <1 time                     |
| 80-100                                     | 1-2 times                   |
| 67-80                                      | 2-5 times                   |
| 33-67                                      | 5-10 times                  |
| 20-33                                      | 10-25 times                 |
| <20  | >25 times                   |

### 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

#### 3.1.1 Occupancy

- The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once

they are made aware of our assessment. Based on information received from CERA to date and from the DBH guidance document dated 12 June 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

### **3.1.2 Cordoning**

- Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/Christchurch City Council guidelines.

### **3.1.3 Strengthening**

- Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.
- It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### **3.1.4 Our Ethical Obligation**

- In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

---

<sup>i</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

## 4 Background Information

### 4.1 Building Description

The Civil Defence Training Centre building in the Sockburn Depot, located at 149 Main South Road, is a single storey concrete block structure. The date of construction of the building is unknown, but is expected to be in the 1980's.

For the purposes of this report, the north-west to south-east direction and the south-west to north-east direction are referred to as the longitudinal and transverse directions respectively. Refer to the site plan in Figure 2 below.



**Figure 2: Civil Defence Sockburn Depot (taken from Google Maps)**

The building has overall dimensions of approximately 18.5m long (longitudinal direction) and 11m wide (transverse direction), with an overall floor area of approximately 214 square metres. The roof consists of timber framed trusses spanning between the longitudinal concrete block walls. The high point of the roof is approximately 3.6m above ground level. Steel portal frames composed of 200UB25 beams and columns support trusses above the lecture room at the southern end of the building. These frames were introduced during alterations carried out in 1991.

The Training Centre has a reinforced slab on grade with variable thickness. Reinforcement was identified by cover meter survey in the foundation at the south-east end of the building, with the reinforcement consisting of two horizontal layers and vertical bars at 250mm

centres. The interior portal frame columns are supported on base plates connected into the foundation slab. The slab level is approximately 300mm above ground level.

Vertical reinforcing bars were identified in the original building extending the full height of the wall on each side of wall openings such as doors and windows. Horizontal reinforcement bars were identified underneath windows, and at the top of the wall in the bond beam. A small portion of the building on the south-east end was observed to have additional starter bars at 900mm centres extending approximately 1.2m above the foundation.

## **4.2 Seismic Load Resisting System**

In both directions, lateral loads are resisted by in plane shear action in the reinforced concrete block walls. A bond beam runs along the top of the block walls around the building providing a small amount of restraint to the walls. Several reinforced masonry internal walls are also located throughout the building and also provide contribution to resisting lateral loads.

The suspended ceiling in the lecture room does not provide diaphragm action to transfer lateral loads to the wall elements. Diaphragm action is obtained in the café room plasterboard ceiling and also in the remainder of the building, which has an original Pinex ceiling lining. This ceiling type is expected to have a diagonal cut-between brace although this was not observed due to limited access to the roof space.

## **4.3 Original Documentation**

Copies of the following construction drawings were provided by the CCC:

- Alterations to Amenities Building – Sockburn Service Centre Structural Drawings, dated 20 March 1991
- Amenities Building Alterations, Sockburn Service Centre Site Architectural Drawings, dated 10 October 2001.

The drawings have been used to confirm the structural systems, investigate potential critical structural weaknesses (CSWs) and identify details which required particular attention.

# **5 Survey**

## **5.1 Post 22 February 2011 Rapid Assessment**

A structural (Level 2) assessment of the above buildings/property was undertaken on 22 March 2011 by Opus International Consultants.

The site was posted with a Green (G2) placard on 22 March 2011, indicating that the building access is not restricted.

## **5.2 Further Inspections**

Further inspections were undertaken by Opus International Consultants on 13 July 2012. These inspections included non-intrusive external and internal visual inspections of all structural elements above foundation level, and areas of damage to structural and non-structural elements. Measurements were obtained, and a cover meter was used to ascertain the presence of reinforcing steel in the walls.

## **5.3 Sockburn Service Centre**

The Sockburn Service Centre building, located immediately adjacent to the north, has recently been identified as an earthquake prone building with a collapse hazard. The Service Centre building was subsequently cordoned off, and the Training Centre building is partly located within this cordon. Access is prevented to all areas within the cordon.

# **6 Structural Damage**

The following damage has been noted:

- a) Cracking up to 4mm wide at intersecting walls throughout the building in the top courses of the concrete block.
- b) Minor internal step cracks in the block walls in along the north-east side of the building, and in the west corner in the toilet block.
- c) Minor cracking of the Pinex ceiling lining in the shower area.
- d) A new gap between the suspended tiled ceiling system and the walls in the lecture room indicating rotation of the ceiling system.

# **7 Detailed Seismic Assessment**

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5]

issued on 21 December 2011.

## **7.1 Critical Structural Weaknesses**

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building. No CSW's have been identified for this building.

## **7.2 Seismic Coefficients**

The seismic design parameters based on current design requirements from NZS1170.5:2004 are as follows:

- Site soil class D, clause 3.1.3 NZS 1170.5:2004
- Site hazard factor,  $Z = 0.3$ , B1/VM1 clause 2.2.14B
- Return period factor,  $R_u = 1.0$  from table 3.5, NZS 1170.5:2004, for an Importance Level 2 structure with a 50 year design life.
- Ductility factor of  $\mu = 1.25$  for the concrete block walls. The ductility factor chosen is based on the material and detailing of the walls.

## **7.3 Limitations and Assumptions in Results**

Our analysis and assessment is based on an assessment of the building in its undamaged state. Therefore the current capacity of the building will be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.

## **7.4 Quantitative Assessment Results**

A summary of the structural performance of the building is shown in the following tables. Note that the values given represent the worst performing elements in the building, when redistributed can be relied on as these effectively define the building's capacity.

**Table 2: Summary of Seismic Performance**

| <b>Structural Element/System</b>  | <b>Failure mode or description of limiting criteria based on capacity of critical element.</b> | <b>% NBS based on calculated capacity</b> |
|---|--|---|
| Masonry walls (in-plane)<br>Southern wall   | In-plane flexural capacity of the reinforced masonry walls                                     | 69%                                       |
| Masonry walls (out of plane)<br>Side wall next to southern entrance to lecture room | Out of plane flexural failure of the reinforced masonry walls                                  | 79%                                       |
| Bond beam (south-east end)  | Flexural failure of the bond beam due to the lack of a ceiling diaphragm.                      | 42%                                       |

## 7.5 Discussion of Results

Based on the building being assessed as an Importance Level 2 structure, the building has a calculated capacity of 42% NBS as governed by the out-of-plane capacity of the concrete block bond beam. This means the building is not classified as Earthquake Prone in accordance with the Building Act.

It is recommended that the building be strengthened to at least 67% NBS.

## 8 Summary of Geotechnical Appraisal

### 8.1 General

A geotechnical investigation was not conducted as part of this assessment. Due to the site location and lack of visible ground damage it was not considered essential to complete a geotechnical investigation in order to assess the seismic capacity of the building. The geotechnical information below has been taken from the quantitative seismic assessment report completed for the Sockburn Service Centre building directly adjacent to this building.

### 8.2 Liquefaction Potential

The site is indicated to have low potential for liquefaction in the ECAN study. The residential areas on the other side of Main South Road are indicated on the CERA map as being in Technical Category TC1 (grey), meaning they are unlikely to incur future land damage from liquefaction.

### 8.3 Further Work

If strengthening works are undertaken for the building, a geotechnical investigation will be required for the design of any foundation elements.

## 9 Remedial Options

Remedial repair works to the cracked walls are required.

## **10 Conclusions**

- a) The seismic capacity of the building is governed by the out-of-plane strength of the concrete block bond beam which is calculated in this quantitative assessment to be around 42% NBS. The building is therefore not considered to be earthquake prone in accordance with the Building Act 2004.
- b) It is recommended that the building be strengthened to at least 67% NBS.
- c) Cracks of up to 4mm wide have been identified at the intersection of concrete block walls.
- d) The building is currently partly located within the cordon around the Sockburn Service Centre building, and it is therefore not recommended that this building is occupied.

## **11 Recommendations**

- c) A strengthening works scheme be developed to increase the seismic capacity of the building to at least 67% NBS - this will need to consider compliance with accessibility and fire requirements.
- d) Access to the building should be prevented until such time that the cordon around the Sockburn Service Centre has been removed.

## **12 Limitations**

- a) This report is based on an inspection of the structure of the buildings and focuses on the structural damage resulting from the 22 February 2011 Canterbury Earthquake and aftershocks only. Some non-structural damage is described but this is not intended to be a complete list of damage to non-structural items.
- b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- c) This report is prepared for CCC to assist with assessing the remedial works required for council buildings and facilities. It is not intended for any other party or purpose.

## **13 References**

- [1] NZS 1170.5: 2004, *Structural design actions, Part 5 Earthquake actions*, Standards New Zealand.
- [2] NZSEE: 2006, *Assessment and improvement of the structural performance of buildings in earthquakes*, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.

- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC, *Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes*, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] DBH (2012), *Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch*, Department of Building and Housing, June 2012


## **Appendix 1 – Photographs**

| Sockburn Civil Defence Training Centre |  |   |
|--|--|---|
| No.                                    | Item description                           | Photo   |
| 1.                                     | Looking at north-east face of the building |   |
| 2.                                     | Looking at south west face of the building |  |

|           |                                      |  |
|-----------|--------------------------------------|--|
| <p>3.</p> | <p>Looking at the south-east end</p> |  A photograph showing the south-east end of a teal-colored building. The building has a gabled roof and several windows. A sign on the wall reads "SHAWNEE SCHOOL". The ground is paved and there is a fence in the foreground. The sky is overcast.             |
| <p>4.</p> | <p>Western corner of building</p>    |  A photograph showing the western corner of the teal-colored building. The building has a gabled roof and several windows. Two green trash bins are visible in the foreground. The ground is paved and there is a bush in the foreground. The sky is overcast. |


|           |   |  |
|-----------|---|--|
| <p>5.</p> | <p>Roof space above lecture room tiled ceiling</p>  |    |
| <p>6.</p> | <p>Western face of southern corner showing different construction type of walls (notice vents at wall-foundation interface)</p> |  |

|           |  |  |
|-----------|--|--|
| <p>7.</p> | <p>Gap opening up between ceiling tiles and portal frame in lecture room</p>   |   |
| <p>8.</p> | <p>Cracking above door way in hallway at entrance to lecture room and café</p> |  |

|           |   |   |
|-----------|---|---|
| <p>9.</p> | <p>Step crack<br/>in toilet wall<br/>lining</p> |  |
|-----------|---|---|

## **Appendix 2 – Floor Plan**

Sockburn Civil Defence Training Centre, 149 Main South Road  
 Detailed Engineering Evaluation



## **Appendix 3 – DEEP Spreadsheet**

|  |  |   |
|--|--|---|
| Building Name: <u>Sockburn Civil Defence Training Centre</u> |  | Reviewer: <u>Alister Boyce</u>            |
| Building Address: <u>149 Main South Road</u>                 | Unit No: <u></u>                                     | CPEng No: <u>209860</u>                   |
| Legal Description: <u></u>                                   | Company: <u>Opus International Consultants</u>       | Company project number: <u>1502000008</u> |
| GPS south: <u>43 32 19.86</u>                                | Degrees Min Sec: <u>172 33 20.86</u>                 | Company phone number: <u>03 363 5400</u>  |
| GPS east: <u></u>  | Date of submission: <u>Sep-12</u>                    | Inspection Date: <u>13-Jul-12</u>         |
| Building Unique Identifier (CCC): <u>BU 1531-003 EQ2</u>     | Is there a full report with this summary? <u>yes</u> | Revision: <u>Final</u>                    |

|   |  |
|---|--|
| Site slope: <u>flat</u>                         | Max retaining height (m): <u></u>                |
| Soil type: <u></u>                              | Soil Profile (if available): <u></u>             |
| Site Class (to NZS 1170.5): <u>D</u>            | If Ground improvement on site, describe: <u></u> |
| Proximity to waterway (m, if < 100m): <u></u>   | Approx site elevation (m): <u>20.00</u>          |
| Proximity to cliff top (m, if < 100m): <u></u>  |  |
| Proximity to cliff base (m, if < 100m): <u></u> |  |

|  |   |  |
|--|---|--|
| No. of storeys above ground: <u>1</u>                        | single storey = 1   | Ground floor elevation (Absolute) (m): <u>20.30</u>  |
| Ground floor split? <u>no</u>                                |   | Ground floor elevation above ground (m): <u>0.30</u> |
| Storeys below ground: <u>0</u>                               |   | If Foundation type is other, describe: <u></u>       |
| Foundation type: <u>mat slab</u>                             | height from ground to level of uppermost seismic mass (for IEP only) (m): <u></u> | Date of design: <u>1976-1992</u>                     |
| Building height (m): <u>3.20</u>                             |   |  |
| Floor footprint area (approx): <u>214</u>                    |   |  |
| Age of Building (years): <u></u>                             |   |  |
| Strengthening present? <u></u>                               | If so, when (year)? <u></u>   | And what load level (%g)? <u></u>                    |
| Use (ground floor): <u>institutional</u>                     | Brief strengthening description: <u></u>  |  |
| Use (upper floors): <u>Training centre for Civil Defence</u> |   |  |
| Use notes (if required): <u></u>                             |   |  |
| Importance level (to NZS 1170.5): <u>L2</u>                  |   |  |

|   |   |
|---|---|
| Gravity System: <u>load bearing walls</u>       | truss depth, purlin type and cladding: <u>1.7m depth, 140x45mm purlin, timber sarking &amp; corrugated steel cladding</u> |
| Roof: <u>timber truss</u>                       | slab thickness (mm): <u>Slab on grade</u>   |
| Floors: <u>concrete flat slab</u>               | beam and connector type: <u>Steel portal frame 203x135x25 UB sections</u>   |
| Beams: <u>steel non-composite</u>               | typical dimensions (mm x mm): <u>Steel portal frame 203x135x25 UB sections</u>  |
| Columns: <u>structural steel</u>                | thickness (mm): <u>190</u>  |
| Walls: <u>partially filled concrete masonry</u> |   |

|  |  |  |
|--|--|--|
| Lateral system along: <u>partially filled CMU</u>  | Note: Define along and across in detailed report!    | note total length of wall at ground (m): <u>20.2</u> |
| Ductility assumed, $\mu$ : <u>1.25</u>             | estimate or calculation? <u>estimated</u>            |  |
| Period along: <u>0.40</u>                          | estimate or calculation? <u>estimated</u>            |  |
| Total deflection (U.S) (mm): <u></u>               | estimate or calculation? <u>estimated</u>            |  |
| maximum interstorey deflection (U.S) (mm): <u></u> | estimate or calculation? <u>estimated</u>            |  |
| Lateral system across: <u>partially filled CMU</u> | note total length of wall at ground (m): <u>19.9</u> |  |
| Ductility assumed, $\mu$ : <u>1.25</u>             | estimate or calculation? <u>estimated</u>            |  |
| Period across: <u>0.40</u>                         | estimate or calculation? <u>estimated</u>            |  |
| Total deflection (U.S) (mm): <u></u>               | estimate or calculation? <u>estimated</u>            |  |
| maximum interstorey deflection (U.S) (mm): <u></u> | estimate or calculation? <u>estimated</u>            |  |

|                     |                             |
|---------------------|-----------------------------|
| Separations:        | leave blank if not relevant |
| north (mm): <u></u> |                             |
| east (mm): <u></u>  |                             |
| south (mm): <u></u> |                             |
| west (mm): <u></u>  |                             |

|   |   |
|---|---|
| Non-structural elements:                        | describe:   |
| Stairs: <u></u>                                 |   |
| Wall cladding: <u>plaster system</u>            | describe: <u>Corrugated iron, supported by sarking</u>                      |
| Roof Cladding: <u>Metal</u>                     |   |
| Cladding: <u></u>                               |   |
| Ceilings: <u>fibrous plaster, fixed</u>         | describe: <u>various: Pinex board, light tile system &amp; plasterboard</u> |
| Services(list): <u>Mains water, Electricity</u> |   |

|                                |   |
|--------------------------------|---|
| Available documentation:       | original designer name/date:  |
| Architectural: <u>partial</u>  | Christchurch City Council Design Services - Architects 20 March 1991; City Design - Christchurch, The Garden City 10 April 2001 |
| Structural: <u>partial</u>     | Christchurch City Council Design Services - Architects 20 March 1991  |
| Mechanical: <u>partial</u>     | Christchurch City Council Design Services - Architects 20 March 1991  |
| Electrical: <u>partial</u>     | Christchurch City Council Design Services - Architects 20 March 1991  |
| Geotech report: <u>partial</u> | Christchurch City Council Design Services - Architects 20 March 1991  |

|   |                        |
|---|------------------------|
| Site performance:                                 | Describe damage:       |
| Settlement: <u>none observed</u>                  | notes (if applicable): |
| Differential settlement: <u>none observed</u>     | notes (if applicable): |
| Liquefaction: <u>none apparent</u>                | notes (if applicable): |
| Lateral Spread: <u>none apparent</u>              | notes (if applicable): |
| Differential lateral spread: <u>none apparent</u> | notes (if applicable): |
| Ground cracks: <u>none apparent</u>               | notes (if applicable): |
| Damage to areas: <u>none apparent</u>             | notes (if applicable): |

|  |  |
|--|--|
| Building:  | Current Placard Status: <u>green</u>                                   |
| Along:   | Damage ratio: <u>0%</u>  |
| Describe (summary): <u></u>                          | Describe how damage ratio arrived at: <u></u>                          |
| Across:  | Damage ratio: <u>0%</u>  |
| Describe (summary): <u></u>                          | $Damage\_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$ |
| Diaphragms:  | Damage?: <u>yes</u>  |
| Describe: <u>Minor cracking in Pinex board</u>       |  |
| CSWs:  | Damage?: <u>yes</u>  |
| Describe: <u>Cracking to masonry walls (not CSW)</u> |  |
| Pounding:  | Damage?: <u>no</u>   |
| Describe: <u></u>                                    |  |
| Non-structural:                                      | Damage?: <u>no</u>   |
| Describe: <u></u>                                    |  |

|   |  |
|---|--|
| Recommendations:  | Describe:  |
| Level of repair/strengthening required: <u>minor structural</u> | Minor/moderate cracking in CMU walls   |
| Building Consent required: <u>no</u>                            | Describe:  |
| Interim occupancy recommendations: <u>full occupancy</u>        | Describe: <u>Adjacent building (Service Centre) is a falling hazard</u>          |
| Along:  | Assessed %NBS before e/quake: <u>42%</u>   |
| Assessed %NBS after e/quake: <u>42%</u>                         | Note: for RC buildings designed between 1976-1994, use 1.2                       |
| Across:   | Assessed %NBS before e/quake: <u>42%</u>   |
| Assessed %NBS after e/quake: <u>42%</u>                         | Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0) |

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

|  |  |
|--|--|
| Period of design of building (from above): 1976-1992   | $h_u$ from above: <u>m</u>   |
| Seismic Zone, if designed between 1965 and 1992: <u></u>   | not required for this age of building  |
| Period (from above): <u>0.4</u>  | across: <u>0.4</u>   |
| (%NBS) from Fig 3.3: <u></u>   |  |
| Note 1: for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0 | 1.00   |
| Note 2: for RC buildings designed between 1976-1994, use 1.2   | 1.0  |
| Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)   | 1.0  |
| Final (%NBS) = <u>0%</u>   | across: <u>0%</u>  |
| 2.2 Near Fault Scaling Factor:   | Near Fault scaling factor, from NZS1170.5, cl 3.1.6: <u>1.00</u>   |
| Near Fault scaling factor (1/N(T,D), Factor A): <u>1</u>   |  |
| 2.3 Hazard Scaling Factor:   | Hazard factor Z for site from AS1170.5, Table 3.3: <u></u>   |
| Z <sub>max</sub> , from NZS4203:1992: <u></u>  |  |
| Hazard scaling factor, Factor B: <u>#DIV/0!</u>  |  |
| 2.4 Return Period Scaling Factor:  | Building Importance level (from above): <u></u>  |
| Return Period Scaling factor from Table 3.1, Factor C: <u></u>   |  |
| 2.5 Ductility Scaling Factor:  | Assessed ductility (less than max in Table 3.2): <u></u>   |
| Ductility scaling factor: -1 from 1976 onwards; or - $\mu$ , if pre-1976, from Table 3.3: <u></u>  |  |
| Ductility Scaling Factor, Factor D: <u>1.00</u>  | across: <u>1.00</u>  |
| 2.6 Structural Performance Scaling Factor:   | Sp: <u></u>  |
| Structural Performance Scaling Factor Factor E: <u>#DIV/0!</u>   | across: <u>#DIV/0!</u>   |
| 2.7 Baseline %NBS, (NBS) <sub>b</sub> = (%NBS) <sub>nom</sub> x A x B x C x D x E  | %NBS <sub>b</sub> : <u>#DIV/0!</u>   |
| Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)  |  |
| 3.1 Plan Irregularity, factor A: <u>1</u>  |  |
| 3.2 Vertical Irregularity, Factor B: <u>1</u>  |  |
| 3.3 Short columns, Factor C: <u>1</u>  |  |
| 3.4 Pounding potential:  | Pounding effect D1, from Table to right: <u>1.0</u>  |
| Height Difference effect D2, from Table to right: <u>1.0</u>   |  |
| Therefore, Factor D: <u>1</u>  |  |
| 3.5 Site Characteristics: <u>1</u>   |  |
| 3.6 Other factors, Factor F:   | For ≤ 3 storeys, max value = 2.5, otherwise max value = 1.5, no minimum  |
| Rationale for choice of F factor, if not 1: <u></u>  |  |
| Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)  |  |
| List any: <u></u>  | Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses |
| 3.7 Overall Performance Achievement ratio (PAR):   | Along: <u>0.00</u>   |
| Across: <u>0.00</u>  |  |
| 4.3 PAR x (%NBS) <sub>b</sub> :  | PAR x Baseline %NBS: <u>#DIV/0!</u>  |
| 4.4 Percentage New Building Standard (%NBS), (before):   | #DIV/0!  |

