

**CHRISTCHURCH CITY COUNCIL**  
BU 0697-009 EQ2  
Plant Shed - Woodham Park  
157 Woodham Road, Linwood



QUALITATIVE ASSESSMENT REPORT  
FINAL

- Rev B
- 24 September 2012



**CHRISTCHURCH CITY COUNCIL**  
BU 0697-009 EQ2  
Plant Shed - Woodham Park  
157 Woodham Road, Linwood

QUALITATIVE ASSESSMENT REPORT

FINAL

- Rev B
- 24 September 2012

---

Sinclair Knight Merz  
142 Sherborne Street  
Saint Albans  
PO Box 21011, Edgeware  
Christchurch, New Zealand  
Tel: +64 3 940 4900  
Fax: +64 3 940 4901  
Web: [www.skmconsulting.com](http://www.skmconsulting.com)

**COPYRIGHT:** The concepts and information contained in this document are the property of Sinclair Knight Merz Limited. Use or copying of this document in whole or in part without the written permission of Sinclair Knight Merz constitutes an infringement of copyright.

**LIMITATION:** This report has been prepared on behalf of and for the exclusive use of Sinclair Knight Merz Limited's Client, and is subject to and issued in connection with the provisions of the agreement between Sinclair Knight Merz and its Client. Sinclair Knight Merz accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.

## Contents

<b>1. Executive Summary</b>	<b>1</b>
1.1. Background	1
1.2. Key Damage Observed	2
1.3. Critical Structural Weaknesses	2
1.4. Indicative Building Strength (from IEP and CSW assessment)	2
1.5. Recommendations	2
<b>2. Introduction</b>	<b>3</b>
<b>3. Compliance</b>	<b>4</b>
3.1. Canterbury Earthquake Recovery Authority (CERA)	4
3.2. Building Act	5
3.3. Christchurch City Council Policy	6
3.4. Building Code	7
<b>4. Earthquake Resistance Standards</b>	<b>8</b>
<b>5. Building Details</b>	<b>10</b>
5.1. Building description	10
5.2. Gravity Load Resisting system	10
5.3. Seismic Load Resisting system	10
5.4. Geotechnical Conditions	10
<b>6. Damage Summary and Remediation</b>	<b>11</b>
<b>7. Initial Seismic Evaluation</b>	<b>12</b>
7.1. The Initial Evaluation Procedure Process	12
7.2. Available Information, Assumptions and Limitations	13
7.3. Critical Structural Weaknesses	14
7.4. Qualitative Assessment Results	14
<b>8. Further Investigation</b>	<b>15</b>
<b>9. Conclusion</b>	<b>16</b>
<b>10. Limitation Statement</b>	<b>17</b>
<b>11. Appendix 1 – Photos</b>	<b>18</b>
<b>12. Appendix 2 – IEP Reports</b>	<b>24</b>
<b>13. Appendix 3 – CERA Standardised Report Form</b>	<b>31</b>
<b>14. Appendix 4 – Geotechnical Desktop Study</b>	<b>33</b>



## Document history and status

Revision	Date issued	Reviewed by	Approved by	Date approved	Revision type
A	16/07/2012	D Bradshaw	N Calvert	16/07/2012	Draft for Client Approval
B	21/09/2012	N Calvert	N Calvert	21/09/2012	Final Issue

## Distribution of copies

Revision	Copy no	Quantity	Issued to
A	1	1	Christchurch City Council
B	1	1	Christchurch City Council

<b>Printed:</b>	24 September 2012
<b>Last saved:</b>	24 September 2012 05:06 PM
<b>File name:</b>	ZB01276.151_CCC_BU_0697_009_EQ2_Qualitative Assmt_B.docx
<b>Author:</b>	Willow Patterson-Kane
<b>Project manager:</b>	Nick M. Calvert
<b>Name of organisation:</b>	Christchurch City Council
<b>Name of project:</b>	Christchurch City Council Structures Panel
<b>Name of document:</b>	Plant Shed - Woodham Park Qualitative Assessment
<b>Document version:</b>	B
<b>Project number:</b>	ZB01276.151

# 1. Executive Summary

## 1.1. Background

A Qualitative Assessment was carried out on the building BU 0697-009 EQ 2 located in Woodham Park at 157 Woodham Road, Linwood. The building is single storey and is currently utilised as a plant room for the nearby paddling pool. It is believed to be constructed from partially reinforced masonry walls and a timber-framed ceiling with a lightweight roof. An aerial photograph illustrating this area is shown below in Figure 1. Detailed descriptions outlining the buildings age and construction type is given in Section 5 of this report.



### ■ Figure 1: Aerial Photograph of the toilet block BU 0697-009 EQ2 in Woodham Park

The qualitative assessment includes a summary of the building damage as well as an initial assessment of the current seismic capacity compared with current seismic code loads using the Initial Evaluation Procedure (IEP).

This Qualitative report for the building structure is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and a visual inspection on 22 May 2012.



## **1.2. Key Damage Observed**

No external damage was observed during our site inspection.

## **1.3. Critical Structural Weaknesses**

No potential critical structural weaknesses have been identified for this building.

## **1.4. Indicative Building Strength (from IEP and CSW assessment)**

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the buildings original capacity has been assessed to be in the order of 40%NBS. No damage was observed during the site investigation therefore the post earthquake capacity will not change as a result of earthquake damage.

The building has been assessed to have a seismic capacity less than 67% NBS and is therefore potentially earthquake risk.

## **1.5. Recommendations**

It is recommended that:

- a) The current placard status of the building of Green 1 should remain as is.
- b) We consider that barriers around the building are not necessary.

## 2. Introduction

Sinclair Knight Merz was engaged by Christchurch City Council to prepare a qualitative assessment report for the building located in Woodham Park at 157 Woodham Road following the magnitude 6.3 earthquake which occurred in the afternoon of the 22nd of February 2011 and the subsequent aftershocks.

The Qualitative Assessment uses the methodology recommended in the Engineering Advisory Group draft document “Guidance on Detailed Engineering Evaluation of Earthquake affected Non-residential Buildings in Canterbury”, issued 19 July 2011. The qualitative assessment includes a summary of the building damage as well as an initial assessment of the likely current Seismic Capacity compared with current seismic code requirements.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

This report describes the structural damage observed during our inspection and indicates suggested remediation measures. The inspection was undertaken from floor levels and was a visual inspection only. Our report reflects the situation at the time of the inspection and does not take account of changes caused by any events following our inspection. A full description of the basis on which we have undertaken our visual inspection is set out in Section 7.

The NZ Society for Earthquake Engineering (NZSEE) Initial Evaluation Procedure (IEP) was used to assess the likely performance of the building in a seismic event relative to the New Building Standard (NBS). 100% NBS is equivalent to the strength of a building that fully complies with current codes. This includes a recent increase of the Christchurch seismic hazard factor from 0.22 to 0.3<sup>1</sup>.

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. The building description below is based on our visual inspections.

---

<sup>1</sup> <http://www.dbh.govt.nz/seismicity-info>

### **3. Compliance**

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

#### **3.1. Canterbury Earthquake Recovery Authority (CERA)**

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

##### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

##### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage



## **3.2. Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

### **3.2.1. Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **3.2.2. Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

### **3.2.3. Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **3.2.4. Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **3.2.5. Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **3.2.6. Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **3.3. Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4<sup>th</sup> September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone. Council recognises that it may not be practicable for some repairs to meet that target. The council will work closely with building owners to achieve sensible, safe outcomes;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

### **3.4. Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a) Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b) Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



## 4. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 2 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

■ **Figure 2: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below provides an indication of the risk of failure for an existing building with a given percentage NBS, relative to the risk of failure for a new building that has been designed to meet current Building Code criteria (the annual probability of exceedance specified by current earthquake design standards for a building of 'normal' importance is 1/500, or 0.2% in the next year, which is equivalent to 10% probability of exceedance in the next 50 years).



■ **Table 1: %NBS compared to relative risk of failure**

<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

## **5. Building Details**

### **5.1. Building description**

The building is located in Woodham Park at 155 Main Road. There is only one building on this site. The building has one storey that is currently utilised as a plant room for the nearby paddling pool. The building is believed to be constructed from partially reinforced masonry walls and a lightweight corrugated steel roof with timber-framing. It is assumed the building was designed and constructed in the 1970's.

Our evaluation was based on the external visual inspection carried out on 22 May 2012. Internal inspection was not able to be performed as the building was inaccessible at the time of the inspection. Drawings were not available to verify the foundation system and the date of construction.

### **5.2. Gravity Load Resisting system**

It appears that the gravity loads are taken by a masonry block walls and steel hollow section columns, with direct transfer into the concrete slab foundation below.

### **5.3. Seismic Load Resisting system**

Lateral loads acting across and along the building will be resisted by the masonry walls in shear, with the steel hollow section columns acting as cantilevers in both directions.

Note that for this building the 'across direction' has been taken as east-west and the 'along direction' has been taken as north-south.

### **5.4. Geotechnical Conditions**

A geotechnical desktop study was carried out for this site. The main conclusions from this report are:

- In accordance with NZS1170.5 the site is likely to be seismic subsoil Class D (deep or soft soil) ground performance and properties.
- Liquefaction risk is moderate to severe at this site.

If any major changes are planned for the structure, the following ground investigations would be recommended:

- One borehole to 20m with full sampling and SPT testing and one CPT test to refusal.

## 6. Damage Summary and Remediation

SKM undertook an inspection on 21 May 2012. The following areas of damage were observed during the time of inspection:

### General

- 1) No visual evidence of settlement was noted at this site, therefore a level survey is not required at this stage of assessment.

### Building Damage

- 1) No earthquake-related damage was observed during our site inspection.
- 2) Dislodged gutter on the north side was noted due to lack of supporting elements, however this is localised and not believed to be earthquake-related damage.

Photos of the above damage can be found in Appendix 1 – Photos.

Only damage thought to be the cause of the earthquakes have been considered for reinstatement.



## 7. Initial Seismic Evaluation

### 7.1. The Initial Evaluation Procedure Process

This section covers the initial seismic evaluation of the building as detailed in the NZSEE 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes'. The IEP grades buildings according to their likely performance in a seismic event. The procedure is not yet recognised by the NZ Building Code but is widely used and recognised by the Christchurch City Council as the preferred method for preliminary seismic investigations of buildings<sup>2</sup>.

The IEP is a coarse screening process designed to identify buildings that are likely to be earthquake prone. The IEP process ranks buildings according to how well they are likely to perform relative to a new building designed to current earthquake standards, as shown in Table 2. The building rank is indicated by the percent of the required New Building Standard (%NBS) strength that the building is considered to have. Earthquake prone buildings are defined as having less than 33% NBS strength which correlates to an increased risk of approximately 20 times that of 100% NBS<sup>3</sup>. Buildings that are identified to be earthquake prone are required by law to be followed up with a detailed assessment and strengthening work within 30 years of the owner being notified that the building is potentially earthquake prone<sup>4</sup>.

**Table 2: IEP Risk classifications**

Description	Grade	Risk	%NBS	Structural performance
Low risk building	A+	Low	> 100	Acceptable. Improvement may be desirable.
	A		100 to 80	
	B		80 to 67	
Moderate risk building	C	Moderate	67 to 33	Acceptable legally. Improvement recommended.
High risk building	D	High	33 to 20	Unacceptable. Improvement required.
	E		< 20	

<sup>2</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

<sup>3</sup> NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p 2-2

<sup>4</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>



The IEP is a simple desktop study that is useful for risk management. No detailed calculations are done and so it relies on an inspection of the building and its plans to identify the structural members and describe the likely performance of the building in a seismic event. A review of the plans is also likely to identify any critical structural weaknesses. The IEP assumes that the building was properly designed and built according to the relevant codes at the time of construction. The IEP method rates buildings based on the code used at the time of construction and some more subjective parameters associated with how the building is detailed and so it is possible that %NBS derived from different engineers may differ.

This assessment describes only the likely seismic Ultimate Limit State (ULS) performance of the building. The ULS is the level of earthquake that can be resisted by the building without catastrophic failure. The IEP does not attempt to estimate Serviceability Limit State (SLS) performance of the building, or the level of earthquake that would start to cause damage to the building<sup>5</sup>. This assessment concentrates on matters relating to life safety as damage to the building is a secondary consideration. SLS performance of the building can be estimated by scaling the current code levels if required.

The NZ Building Code describes that the relevant codes for NBS are primarily:

- AS/NZS 1170 Structural Design Actions
- NZS 3101:2006 Concrete Structures Standard
- NZS 3404:1997 Steel Structures Standard

## **7.2. Available Information, Assumptions and Limitations**

Following our inspection on 22 May 2012, SKM carried out a preliminary structural review. The structural review was undertaken using the available information which was as follows:

- SKM site measurements and external inspection findings of the building. Please note no intrusive investigations were undertaken.
- There were no drawings available to carry out our review.

The following assumptions and design criteria were used in this assessment:

- Standard design assumptions for typical office and factory buildings as described in AS/NZS1170.0:2002
  - 50 year design life, which is the default NZ Building Code design life.

---

<sup>5</sup> NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p2-9



- Structure Importance Level 1. This level of importance is described as ‘low’ with small or moderate consequence of failure.
- Ductility level of 1.25 in both directions, based on our assessment and code requirements at the time of design.
- Site hazard factor,  $Z = 0.3$ , NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011

This IEP was based on our external visual inspection of the building. Since it is not a full design and construction review, it has the following limitations:

- It is not likely to pick up on any original design or construction errors (if they exist)
- Other possible issues that could affect the performance of the building such as corrosion and modifications to the building will not be identified
- The IEP deals only with the structural aspects of the building. Other aspects such as building services are not covered.

### 7.3. Critical Structural Weaknesses

No critical structural weaknesses have been identified in this building.

### 7.4. Qualitative Assessment Results

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity is expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 3. This capacity is subject to confirmation by a quantitative analysis.

**Table 3: Qualitative Assessment Summary**

<u>Item</u>	<u>%NBS</u>
Likely Seismic Capacity of Building	42

Our qualitative assessment found that the building is likely to be classed as a potentially earthquake prone and probably a ‘Moderate Risk Building’ (capacity less than 67% of NBS). The full IEP assessment form is detailed in Appendix 2 – IEP Reports.

## 8. Further Investigation

Due to the lack of structural drawings and the likely seismic capacity of the building being less than 67% NBS, a quantitative assessment would generally be recommended, but is not required as it is greater than 33% NBS. However, we recommend that a quantitative assessment is not carried out in this case given the small scale of the building and the low consequences of failure.

If a quantitative assessment is carried out then intrusive investigations will be required to confirm the following structural details:

- Foundation layout and size of elements.
- Roof member layout and size and elements.
- Connections sizes and layouts.

It is believed that a building consent will likely be required to strengthen the building.

## 9. Conclusion

A qualitative assessment was carried out on the building located in Woodham Park at 157 Woodham Road, Linwood. The building has sustained no earthquake-related damage. The building has been assessed to have a seismic capacity in the order of 42% NBS and is therefore a potential earthquake risk and is likely to be classified as a 'Moderate Risk Building' (capacity less than 67% NBS).

Further investigation is generally recommended to confirm our initial findings and to establish possible strengthening concepts. However, due to the small scale of the building, the low consequences of failure and its likely seismic capacity being greater than 33% NBS, no further work will be recommended. But if the building is to be strengthened, building consent will likely be required.

It is recommended that:

- a) The current placard status of the building of Green 1 should remain as is.
- b) We consider that barriers around the building are not necessary.

## 10. Limitation Statement

This report has been prepared on behalf of, and for the exclusive use of, SKM's client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and the Client. It is not possible to make a proper assessment of this report without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to, and the assumptions made by, SKM. The report may not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, in the event of any liability, SKM's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited in as set out in the terms of the engagement with the Client.

It is not within SKM's scope or responsibility to identify the presence of asbestos, nor the responsibility of SKM to identify possible sources of asbestos. Therefore for any property pre-dating 1989, the presence of asbestos materials should be considered when costing remedial measures or possible demolition.

There is a risk of further movement and increased cracking due to subsequent aftershocks or settlement.

Should there be any further significant earthquake event, of a magnitude 5 or greater, it will be necessary to conduct a follow-up investigation, as the observations, conclusions and recommendations of this report may no longer apply. Earthquake of a lower magnitude may also cause damage, and SKM should be advised immediately if further damage is visible or suspected.

## 11. Appendix 1 – Photos



Photo 1: West elevation



Photo 2: South elevation



Photo 3: East elevation



Photo 4: North elevation





Photo 5: Concrete footing under masonry wall and entrance on west side.



Photo 6: Roof cladding over west masonry wall and entrance.



Photo 7: Spalling of low quality concrete footing under entrance on west side.



Photo 8: Doorframe for entrance on west side.



Photo 9: Gutter and south masonry wall.



Photo 10: West masonry wall and footing underneath.



Photo 11: Ventilation grate on west wall.  
Anchors in masonry blocks.



Photo 12: Gutter and downpipe on south side.





Photo 13: Downpipe from south gutter and footing on east side.



Photo 14: Roof cladding over south masonry wall.



Photo 15: Gutter and downpipe on north side.



Photo 16: Sloped gutter on north side due to loose support connection.



Photo 17: Sloped gutter on north side due to loose support connection.



Photo 18: Paddling pool notices and gate.



Photo 19: Paddling pool west of building.



Photo 20: Ventilation grate on east wall. Anchors in masonry blocks.





Photo 21: Anchors into masonry elements on north side for top gate connection.



Photo 22: Gate ground connection on north side.

Christchurch City Council  
BU 0697-009 EQ2  
Plant Shed - Woodham Park  
157 Woodham Road, Linwood  
Qualitative Assessment Report  
24 September 2012



## **12. Appendix 2 – IEP Reports**


Building Name: <b>BU 0697-009 EQ2 Plant Shed - Woodham Park</b>	Ref. <b>ZB01276.151</b>
Location: <u>155 Woodham Road, Linwood</u>	By <b>WPK</b>
	Date <b>29/05/2012</b>

**Step 1 - General Information**

**1.1 Photos (attach sufficient to describe building)**



**1.2 Sketch of building plan**



**1.3 List relevant features**

The building in Woodham Park at 155 Woodham Road is one storey and is currently in use as a plant room for the nearby paddling pool. The building consists of concrete masonry block walls and appears to have a lightweight roof with timber framing. The main lateral load-resisting system appear to be the walls. These act as shear walls in the north-south and east-west direction. The block walls appear to be founded on a concrete slab footing. Internal inspection was not able to be carried out as the building was inaccessible at the time of the inspection. The building is assumed to have been constructed in the 1970's.

**1.4 Note information sources**

Tick as appropriate

- Visual Inspection of Exterior
- Visual Inspection of Interior
- Drawings (note type)
- Specifications
- Geotechnical Reports
- Other (list)

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

**Table IEP-2 Initial Evaluation Procedure – Step 2**  
(Refer Table IEP - 1 for Step 1; Table IEP - 3 for Step 3, Table IEP - 4 for Steps 4, 5 and 6)

Building Name:	<b>BU 0697-009 EQ2 Plant Shed - Woodham Park</b>	Ref.	<b>ZB01276.151</b>
Location:	155 Woodham Road, Linwood	By	WPK
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	29/05/2012
( Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 2 - Determination of (%NBS)b**

**2.1 Determine nominal (%NBS) = (%NBS)nom**

Pre 1935		
1935-1965		
1965-1976	Seismic Zone;	A
		B
		C
1976-1992	Seismic Zone;	A
		B
		C
1992-2004		

<input type="radio"/>	See also notes 1, 3
<input type="radio"/>	
<input type="radio"/>	
<input checked="" type="radio"/>	See also note 2
<input type="radio"/>	
<input type="radio"/>	
<input type="radio"/>	
<input type="radio"/>	
<input type="radio"/>	

**b) Soil Type**

From NZS1170.5:2004, Cl 3.1.3	A or B Rock	<input type="radio"/>
	C Shallow Soil	<input type="radio"/>
	D Soft Soil	<input checked="" type="radio"/>
	E Very Soft Soil	<input type="radio"/>

<input type="radio"/>
<input type="radio"/>
<input checked="" type="radio"/>
<input type="radio"/>

From NZS4203:1992, Cl 4.6.2.2 (for 1992 to 2004 only and only if known)	a) Rigid	<input checked="" type="radio"/>
	b) Intermediate	<input type="radio"/>

<input checked="" type="radio"/>	N-A
<input type="radio"/>	

**c) Estimate Period, T**

**building Ht = 2.7 meters**

Can use following:

$T = 0.09h_n^{0.75}$	for moment-resisting concrete frames
$T = 0.14h_n^{0.75}$	for moment-resisting steel frames
$T = 0.08h_n^{0.75}$	for eccentrically braced steel frames
$T = 0.06h_n^{0.75}$	for all other frame structures
$T = 0.09h_n^{0.75}/A_c^{0.5}$	for concrete shear walls
$T \leq 0.4\text{sec}$	for masonry shear walls

Ac =	Longitudinal	Transverse	m2
	10	6	
	<input type="radio"/> MRCF	<input type="radio"/> MRCF	
	<input type="radio"/> MRSF	<input type="radio"/> MRSF	
	<input type="radio"/> EBSF	<input type="radio"/> EBSF	
	<input type="radio"/> Others	<input type="radio"/> Others	
	<input type="radio"/> CSW	<input type="radio"/> CSW	
	<input checked="" type="radio"/> MSW	<input checked="" type="radio"/> MSW	

Where  $h_n$  = height in m from the base of the structure to the uppermost seismic weight or mass.  
 $A_c = \sum A_i(0.2 + L_{wi}/h_n)^2$   
 $A_i$  = cross-sectional shear area of shear wall  $i$  in the first storey of the building, in m<sup>2</sup>  
 $L_{wi}$  = length of shear wall  $i$  in the first storey in the direction parallel to the applied forces, in m  
 with the restriction that  $L_{wi}/h_n$  shall not exceed 0.9

Longitudinal	Transverse	Seconds
0.4	0.4	

**d) (%NBS )nom determined from Figure 3.3**

**Note 1:** For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.25.  
 For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.33 - Zone A or 1.2 - Zone B

Factor  
No  1

**Note 2:** For reinforced concrete buildings designed between 1976 -1984 (%NBS )nom by 1.2

No  1

**Note 3:** For buildings designed prior to 1935 multiply (%NBS)nom by 0.8 except for Wellington where the factor may be taken as 1.

No  1

Longitudinal	5	(%NBS )nom
Transverse	5	(%NBS )nom

Longitudinal	5.0	(%NBS )nom
Transverse	5.0	(%NBS )nom

Continued over page

Building Name:	<b>BU 0697-009 EQ2 Plant Shed - Woodham Park</b>	Ref.	<b>ZB01276.151</b>
Location:	155 Woodham Road, Linwood	By	WPK
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	29/05/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**2.2 Near Fault Scaling Factor, Factor A**  
If T < 1.5sec, Factor A = 1

a) Near Fault Factor, N(T,D) **1**  
(from NZS1170.5:2004, Cl 3.1.6)

b) Near Fault Scaling Factor = 1/N(T,D) 

Factor A	1.00
----------	------

**2.3 Hazard Scaling Factor, Factor B**

Select Location Christchurch

a) Hazard Factor, Z, for site  
(from NZS1170.5:2004, Table 3.3)

Z =	0.3		
Z 1992 =	0.8	Auckland 0.6	Palm Nth 1.2
		Wellington 1.2	Dunedin 0.6
		Christchurch 0.8	Hamilton 0.67

b) Hazard Scaling Factor

For pre 1992 = 1/Z  
For 1992 onwards = Z 1992/Z

# (Where Z 1992 is the NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Factor B	3.33
----------	------

**2.4 Return Period Scaling Factor, Factor C**

a) Building Importance Level  
(from NZS1170.0:2004, Table 3.1 and 3.2)

1

b) Return Period Scaling Factor from accompanying Table 3.1

Factor C	2.00
----------	------

**2.5 Ductility Scaling Factor, D**

a) Assessed Ductility of Existing Structure,  $\mu$   
(shall be less than maximum given in accompanying Table 3.2)

Longitudinal	1.25	$\mu$ Maximum = 2
Transverse	1.25	$\mu$ Maximum = 2

b) Ductility Scaling Factor

For pre 1976 =  $k_u$   
For 1976 onwards = 1  
(where  $k_u$  is NZS1170.5:2005 Ductility Factor, from accompanying Table 3.3)

Longitudinal	Factor D	1.14
Transverse	Factor D	1.14

**2.6 Structural Performance Scaling Factor, Factor E**

Select Material of Lateral Load Resisting System

Longitudinal  
Transverse

Masonry Block  
Masonry Block

a) Structural Performance Factor,  $S_p$   
from accompanying Figure 3.4

Longitudinal	$S_p$	0.90
Transverse	$S_p$	0.90

b) Structural Performance Scaling Factor

Longitudinal	$1/S_p$	Factor E	1.11
Transverse	$1/S_p$	Factor E	1.11

**2.7 Baseline %NBS for Building, (%NBS)<sub>b</sub>**  
(equals (%NSB)<sub>nom</sub> x A x B x C x D x E)

Longitudinal	42.3	(%NBS) <sub>b</sub>
Transverse	42.3	(%NBS) <sub>b</sub>

**Table IEP-3 Initial Evaluation Procedure – Step 3**

(Refer Table IEP - 1 for Step 1; Table IEP - 2 for Step 2, Table IEP - 4 for Steps 4, 5 and 6)

Building Name: <b>BU 0697-009 EQ2 Plant Shed - Woodham Park</b>	Ref. <b>ZB01276.151</b>
Location: <b>155 Woodham Road, Linwood</b>	By <b>WPK</b>
Direction Considered: <b>a) Longitudinal</b>	Date <b>29/05/2012</b>
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)	

**Step 3 - Assessment of Performance Achievement Ratio (PAR)**  
(Refer Appendix B - Section B3.2)

**Critical Structural Weakness**

**Effect on Structural Performance**  
(Choose a value - Do not interpolate)

**Building Score**

**3.1 Plan Irregularity**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

**3.2 Vertical Irregularity**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

**3.3 Short Columns**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

**3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect  
Select appropriate value from Table

Note:  
Values given assume the building has a frame structure. For stiff buildings ( eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

		<b>Factor D1</b>	<input type="text" value="1"/>
Table for Selection of Factor D1		Severe	Significant
	Separation	0<Sep<.005H	.005<Sep<.01H
		0.7	0.8
Alignment of Floors within 20% of Storey Height		<input type="radio"/>	<input type="radio"/>
Alignment of Floors not within 20% of Storey Height		<input type="radio"/>	<input type="radio"/>
		0.4	0.7
		<input type="radio"/>	<input type="radio"/>
			1
			<input checked="" type="radio"/>
			0.8
			<input type="radio"/>

b) Factor D2: - Height Difference Effect  
Select appropriate value from Table

		<b>Factor D2</b>	<input type="text" value="1"/>
Table for Selection of Factor D2		Severe	Significant
	Separation	0<Sep<.005H	.005<Sep<.01H
		0.4	0.7
Height Difference > 4 Storeys		<input type="radio"/>	<input type="radio"/>
Height Difference 2 to 4 Storeys		<input type="radio"/>	<input type="radio"/>
Height Difference < 2 Storeys		<input type="radio"/>	<input type="radio"/>
		0.7	0.9
		1	1
		<input type="radio"/>	<input type="radio"/>
			1
			<input checked="" type="radio"/>
			1

**Factor D**   
(Set D = lesser of D1 and D2 or..  
set D = 1.0 if no prospect of pounding)

**3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)**

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>
0.5	0.7	1

Factor E

**3.6 Other Factors**

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

**3.7 Performance Achievement Ratio (PAR)**  
(equals A x B x C x D x E x F)

PAR



Building Name:	<b>BU 0697-009 EQ2 Plant Shed - Woodham Park</b>	Ref.	<b>ZB01276.151</b>
Location:	155 Woodham Road, Linwood	By	WPK
Direction Considered:	<b>b) Transverse</b>	Date	29/05/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 3 - Assessment of Performance Achievement Ratio (PAR)**

(Refer Appendix B - Section B3.2)

**Critical Structural Weakness**

**Effect on Structural Performance**

(Choose a value - Do not interpolate)

**Building Score**

**Score**

**3.1 Plan Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

**3.2 Vertical Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

**3.3 Short Columns**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

**3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:  
Values given assume the building has a frame structure. For stiff buildings ( eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

Factor D1

Table for Selection of Factor D1	Separation		
	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2

Table for Selection of Factor D2	Separation		
	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D

(Set D = lesser of D1 and D2 or..  
set D = 1.0 if no prospect of pounding)

**3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)**

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E

**3.6 Other Factors**

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

**3.7 Performance Achievement Ratio (PAR)**  
(equals A x B x C x D x E x F)

PAR

Building Name:	<u>BU 0697-009 EQ2 Plant Shed - Woodham Park</u>	Ref.	<u>ZB01276.151</u>
Location:	<u>155 Woodham Road, Linwood</u>	By	<u>WPK</u>
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	<u>29/05/2012</u>
<small>( Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)</small>			

**Step 4 - Percentage of New Building Standard (%NBS)**

	Longitudinal	Transverse
<b>4.1 Assessed Baseline (%NBS)<sub>b</sub></b> (from Table IEP - 1)	<input type="text" value="42"/>	<input type="text" value="42"/>
<b>4.2 Performance Achievement Ratio (PAR)</b> (from Table IEP - 2)	<input type="text" value="1.00"/>	<input type="text" value="1.00"/>
<b>4.3 PAR x Baseline (%NBS)<sub>b</sub></b>	<input type="text" value="42"/>	<input type="text" value="42"/>
<b>4.4 Percentage New Building Standard (%NBS)</b> ( Use lower of two values from Step 4.3)		<input type="text" value="42"/>

**Step 5 - Potentially Earthquake Prone?**  
(Mark as appropriate)


%NBS ≤ 33     

**Step 6 - Potentially Earthquake Risk?**

%NBS < 67     

**Step 7 - Provisional Grading for Seismic Risk based on IEP**

Seismic Grade     

Evaluation Confirmed by  Signature

DAVE BRADSHAW Name

43522 CPEng. No

**Relationship between Seismic Grade and % NBS :**

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	80 to 67	67 to 33	33 to 20	< 20



## **13. Appendix 3 – CERA Standardised Report Form**

<b>Location</b>		Building Name: <u>BU 0697-009 EQ2</u>	Unit No: Street	Reviewer: <u>David Bradshaw</u>
Building Address: <u>Plant Shed - Woodham Park</u>		155 Woodham Road, Linwood		CPEng No: <u>43522</u>
Legal Description:				Company: <u>SKM</u>
GPS south:		Degrees Min Sec		Company project number: <u>ZB01276.151</u>
GPS east:				Company phone number: <u>09 928 5500</u>
Building Unique Identifier (CCC):				Date of submission:
				Inspection Date: <u>22/05/2012</u>
				Revision: <u>A</u>
				Is there a full report with this summary? <u>yes</u>

<b>Site</b>		Site slope: <u>flat</u>	Max retaining height (m):
Soil type:			Soil Profile (if available):
Site Class (to NZS1170.5): <u>D</u>			
Proximity to waterway (m, if <100m):			If Ground improvement on site, describe:
Proximity to cliff top (m, if < 100m):			
Proximity to cliff base (m, if <100m):			Approx site elevation (m):

<b>Building</b>		No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m):
Ground floor split?: <u>no</u>				Ground floor elevation above ground (m):
Storeys below ground: <u>0</u>				
Foundation type: <u>mat slab</u>				if Foundation type is other, describe:
Building height (m): <u>2.70</u>			height from ground to level of uppermost seismic mass (for IEP only) (m): <u>2.7</u>	
Floor footprint area (approx): <u>7</u>				Date of design: <u>1965-1976</u>
Age of Building (years): <u>35</u>				
Strengthening present?: <u>no</u>				If so, when (year)?
Use (ground floor): <u>public</u>				And what load level (%g)?
Use (upper floors):				Brief strengthening description:
Use notes (if required):				
Importance level (to NZS1170.5): <u>IL1</u>				

<b>Gravity Structure</b>		Gravity System: <u>load bearing walls</u>	rafter type, purlin type and cladding: <u>Assumed</u>
Roof: <u>timber framed</u>		Floors: <u>concrete flat slab</u>	slab thickness (mm): <u>Unknown</u>
Beams: <u>none</u>		Columns: <u>none</u>	overall depth x width (mm x mm): <u>None</u>
Walls: <u>partially filled concrete masonry</u>			typical dimensions (mm x mm): <u>None</u>
			thickness (mm): <u>200</u>

<b>Lateral load resisting structure</b>		Lateral system along: <u>partially filled CMU</u>	Ductility assumed, μ: <u>1.25</u>	Period along: <u>0.40</u>	0.40 from parameters in sheet	note total length of wall at ground (m): <u>3.4</u>	wall thickness (m): <u>0.2</u>
Total deflection (ULS) (mm):		<u>10</u>				estimate or calculation? <u>estimated</u>	
maximum interstorey deflection (ULS) (mm):						estimate or calculation? <u>estimated</u>	
Lateral system across: <u>partially filled CMU</u>		Ductility assumed, μ: <u>1.25</u>	Period across: <u>0.40</u>	0.40 from parameters in sheet	note total length of wall at ground (m): <u>2</u>	wall thickness (m): <u>0.2</u>	
Total deflection (ULS) (mm):		<u>10</u>				estimate or calculation? <u>estimated</u>	
maximum interstorey deflection (ULS) (mm):						estimate or calculation? <u>estimated</u>	

<b>Separations:</b>		north (mm):	east (mm):	south (mm):	west (mm):	leave blank if not relevant

<b>Non-structural elements</b>		Stairs: <u>exposed structure</u>	describe: <u>Masonry walls</u>
Wall cladding: <u>exposed structure</u>		Roof Cladding: <u>Metal</u>	describe: <u>Lightweight corrugated sheeting</u>
Glazing:			
Ceilings:			
Services (list):			

<b>Available documentation</b>		Architectural: <u>none</u>	original designer name/date:
Structural: <u>none</u>		Mechanical: <u>none</u>	original designer name/date:
Electrical: <u>none</u>		Geotech report: <u>partial</u>	original designer name/date:
			original designer name/date:

<b>Damage Site:</b>		Site performance:	Describe damage: <u>No damage observed</u>
(refer DEE Table 4-2)		Settlement: <u>none observed</u>	notes (if applicable):
Differential settlement: <u>none observed</u>		Liquefaction: <u>none apparent</u>	notes (if applicable):
Lateral Spread: <u>none apparent</u>		Differential lateral spread: <u>none apparent</u>	notes (if applicable):
Ground cracks: <u>none apparent</u>		Damage to area: <u>none apparent</u>	notes (if applicable):
			notes (if applicable):

<b>Building:</b>		Current Placard Status: <u>green</u>	
Along	Damage ratio: <u>0%</u>	Describe (summary): <u>No damage observed</u>	Describe how damage ratio arrived at: <u>No damage observed during our site inspection.</u>
Across	Damage ratio: <u>0%</u>	Describe (summary): <u>No damage observed</u>	
		$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$	
Diaphragms	Damage?: <u>no</u>	Describe:	
CSWs:	Damage?: <u>no</u>	Describe:	
Pounding:	Damage?: <u>no</u>	Describe:	
Non-structural:	Damage?: <u>no</u>	Describe:	

<b>Recommendations</b>		Level of repair/strengthening required: <u>none</u>	Describe:
Building Consent required: <u>no</u>		Interim occupancy recommendations: <u>full occupancy</u>	Describe:
Along	Assessed %NBS before: <u>42%</u>	Assessed %NBS after: <u>42%</u>	%NBS from IEP below
Across	Assessed %NBS before: <u>42%</u>	Assessed %NBS after: <u>42%</u>	%NBS from IEP below
		If IEP not used, please detail assessment methodology:	
		Qualitative Assessment carried out includes NZSEE IEP (refer to SKM report).	

Christchurch City Council  
BU 0697-009 EQ2  
Plant Shed - Woodham Park  
157 Woodham Road, Linwood  
Qualitative Assessment Report  
24 September 2012



## **14. Appendix 4 – Geotechnical Desktop Study**



## Christchurch City Council - Structural Engineering Service

### Geotechnical Desk Study

SKM project number	ZB01276
SKM project site number	151
Address	Plant Shed - Woodham Park, 155 Woodham Road,
Report date	4 July 2012
Author	Chris Ritchie
Reviewer	Ross Kendrick
Approved for issue	Yes

### 1. Introduction

This report outlines the geotechnical information that Sinclair Knight Merz (SKM) has been able to source from our database and other sources in relation to the property listed above. We understand that this information will be used as part of an initial qualitative Detailed Engineering Evaluation (DEE), and will be supplemented by more detailed information and investigations to allow detailed scoping of the repair or rebuild of the pool shed.

### 2. Scope

This geotechnical desk top study incorporates information sourced from:

- Published geology
- Publically available borehole records
- Liquefaction records
- Aerial photography
- Council files
- A preliminary site walkover

### 3. Limitations


This report was prepared to address geotechnical issues relating to the specific site in accordance with the scope of works as defined in the contract between SKM and our Client. This report has been prepared on behalf of, and for the exclusive use of, our Client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and our Client. The findings presented in this report should not be applied to another site or another development within the same site without consulting SKM.

The assessment undertaken by SKM was limited to a desktop review of the data described in this report. SKM has not undertaken any subsurface investigations, measurement or testing of materials from the site. In preparing this report, SKM has relied upon, and presumed accurate, any information (or confirmation of the absence thereof) provided by our Client, and from other sources as described in the report. Except as otherwise stated in this report, SKM has not attempted to verify the accuracy or completeness of any such information.



This report should be read in full and no excerpts are to be taken as representative of the findings. It must not be copied in parts, have parts removed, redrawn or otherwise altered without the written consent of SKM.

#### 4. Site location




■ **Figure 1 – Site location (courtesy of LINZ <http://viewers.geospatial.govt.nz>)**

The structure is located in Woodham Park between Woodham Road and Gloucester Street at grid reference 1573445 E, 5180889 N (NZTM).




## 5. Review of available information

### 5.1 Geological maps



■ Figure 2 – Regional geological map (Forsyth et al, 2008). Site marked in red.





■ **Figure 3 – Local geological map (Brown et al, 1992). Site marked in red.**

The site is shown to be underlain by Holocene deposits comprising predominantly alluvial sand and silt overbank deposits of the Springston Formation.



## 5.2 Liquefaction map



- **Figure 4 – Liquefaction map (Cubrinovski & Taylor, 2011). Site marked in yellow.**

Following the 22 February 2011 event drive through reconnaissance was undertaken from 23 February until 1 March by M Cubrinovski and M Taylor of Canterbury University. Their findings show moderate to severe liquefaction around the site.

### 5.3 Aerial photography



■ **Figure 5 – Aerial photography from 24 Feb 2011 (<http://viewers.geospatial.govt.nz/>)**

Aerial photography shows moderate to significant liquefaction after the 22 Feb 2011 event, particularly to the south and east of the site.

### 5.4 CERA classification

A review of the LINZ website (<http://viewers.geospatial.govt.nz/>) shows that the site is:

- Zone: Green
- DBH Technical Category TC3





## 5.5 Historical land use

Reference to historical documents (eg Appendix A) shows that the site is located within an old swamp and within close proximity to an old watercourse. It is therefore possible that soft or potentially liquefiable ground could be present near the site.

## 5.6 Existing ground investigation data



- **Figure 6 – Local boreholes from Project Orbit and SKM files (<https://canterburyrecovery.projectorbit.com/>)**

Where available logs from these investigation locations are attached to this report (Appendix B), and the results are summarised in Appendix C.

## 5.7 Council property files

Council property files were not available at the time of this report.



## 5.8 Site walkover

An engineer from SKM undertook a site walkover in the week commencing 13 June 2012.

The building is a masonry block construction with corrugated sheet metal roof and slab on grade foundation. The paddling pool appears to be poured in-situ concrete, with a surrounding concrete slab. There was some damage to the gutter on the northern side of the building; otherwise no apparent structural damage was noted during the external site inspection. There was little or no evidence of liquefaction around the site. However, this is most likely due to a significant lapse of time between the seismic event and the external site walkover undertaken, as there is some evidence of liquefied material ejected at surface from the aerial photographs. No land damage was observed during the site walkover.



■ **Figure 7 Overview of structure**

## 6. Conclusions and recommendations

### 6.1 Site geology

An interpretation of the most relevant local investigation suggests that the site is underlain by:

Depth range (mBLG)	Soil type
0-5m	Silty Sand
5m+	Sand



## 6.2 Seismic site subsoil class

The site has been assessed as NZS1170.5 Class D (deep or soft soil).

As described in NZS1170, the preferred site classification method is from site periods based on four times the shear wave travel time through material from the surface to the underlying rock. The next preferred methods are from borelogs including measurement of geotechnical properties or by evaluation of site periods from Nakamura ratios or from recorded earthquake motions. Lacking this information, classification may be based on boreholes with descriptors but no geotechnical measurements. The least preferred method is from surface geology and estimates of the depth to underlying rock.

In this case the absence of deep boreholes near the site has resulted in the use of the least preferred method. It is therefore possible that site specific investigation could revise the site class.

## 6.3 Building Performance

Although detailed records of the existing foundations are not available, the performance to date suggests that they are adequate for their current purpose.

## 6.4 Ground performance and properties

Liquefaction risk is moderate to severe at this site. Sand and silty sand layers below the ground water table (approximately 2 metres) are highly susceptible to liquefaction and would explain the moderate to significant liquefaction observed from the aerial photographs after the recent earthquake. It must be noted that no sign of liquefaction was observed during the site walkover. However, this inconsistency could be due to the length of time between the earthquake event and the site walkover. From the available ground investigation data, the ground conditions are consistent across the site.

For the purposes of carrying out a Quantitative Detailed Engineering Evaluation the engineer can assume this site is 'good ground' (as defined in NZS3604:2011) and therefore the following parameters are recommended for the shallow materials:

Parameter	Estimated value
Effective angle of friction	34 degrees
Apparent cohesion	0 kPa
Unit weight	18 kPa
Ultimate bearing capacity of a shallow square pad footing	300 kPa

NOTE: These figures are based on geological data from outside the site for the purposes of preliminary structural assessment. These parameters should not be relied upon for any design work. Site specific investigations are required to confirm that these assumed values are correct. Additionally, further geotechnical investigation could potentially increase the ultimate bearing capacity stated above.

## 6.5 Further investigations

The structure appear to be a one storey, timber and masonry block construction with a concrete pad foundation. As this time additional investigation is not seen as a priority, however if any major changes are planned for the structure, the following ground investigation would be recommended.

- One borehole to 20m with full sampling and SPT testing and one CPT test to refusal.



## 7. References

Brown LJ, Weeber JH, 1992. Geology of the Christchurch urban area. Scale 1:25,000. Institute of Geological & Nuclear Sciences geological map 1.

Cubrinovski & Taylor, 2011. Liquefaction map summarising preliminary assessment of liquefaction in urban areas following the 2010 Darfield Earthquake.

Forsyth PJ, Barrell DJA, Jongens R, 2008. Geology of the Christchurch area. Institute of Geological & Nuclear Sciences geological map 16.


Land Information New Zealand (LINZ) geospatial viewer (<http://viewers.geospatial.govt.nz/>)

EQC Project Orbit geotechnical viewer (<https://canterburyrecovery.projectorbit.com/>)





## Appendix A – Christchurch 1856 land use





The swamps and previous creeks/riders from 1856 have been overlaid onto a map of Christchurch in 2012


- Key**
- █ Previous creeks/riders
  - █ Existing creeks/riders
  - █ New creeks/riders
  - Swamp/Marshland










## **Appendix B – Existing ground investigation logs**


<b>Project:</b> Christchurch 2011 Earthquake - EQC Ground Investigations			<b>Page:</b> 1 of 1	<b>CPT-AVS-43</b>	
<b>Test Date:</b> 12-Aug-2011	<b>Location:</b> Avonside	<b>Operator:</b> Opus		 	
<b>Pre-Drill:</b> 1.2m	<b>Assumed GWL:</b> 2mBGL	<b>Located By:</b> Survey GPS			
<b>Position:</b> 2483392mE	5742448.8mN	2.82mRL			
<b>Other Tests:</b>			<b>Comments:</b>		



<b>Project:</b> Christchurch 2011 Earthquake - EQC Ground Investigations			<b>Page:</b> 1 of 2	<b>CPT-AVS-45</b>	
<b>Test Date:</b> 18-Jul-2011	<b>Location:</b> Avonside	<b>Operator:</b> Perry		 	
<b>Pre-Drill:</b> 1.2m	<b>Assumed GWL:</b> 2.4mBGL	<b>Located By:</b> Survey GPS			
<b>Position:</b> 2483368.6mE	5742712.1mN	2.77mRL			
<b>Other Tests:</b>			<b>Comments:</b>		




<b>Project:</b> Christchurch 2011 Earthquake - EQC Ground Investigations			<b>Page:</b> 2 of 2	<b>CPT-AVS-45</b>	
<b>Test Date:</b> 18-Jul-2011	<b>Location:</b> Avonside	<b>Operator:</b> Perry		 	
<b>Pre-Drill:</b> 1.2m	<b>Assumed GWL:</b> 2.4mBGL	<b>Located By:</b> Survey GPS			
<b>Position:</b> 2483368.6mE 5742712.1mN 2.77mRL	<b>Coord. System:</b> NZMG & MSL				
<b>Other Tests:</b>			<b>Comments:</b>		



# Borelog for well M35/12325

Gridref: M35:83702-42422 Accuracy : 3 (1=high, 5=low)  
 Ground Level Altitude : 6.53 +MSD  
 Well name : CCC BorelogID 389  
 Drill Method : Not Recorded  
 Drill Depth : -4.98m Drill Date :





## **Appendix C – Geotechnical Investigation Summary**



■ **Table 1 Summary of most relevant investigation data**

ID	1	2	3
Type *	WW	CPT	CPT
Ref	M35_12325	CPT-AVS-43	CPT-AVS-45
Depth (m)	5	6	26
Distance from site (m)	260	95	200
Ground water level (mBGL)		2	2.4
Simplified recorded geological profile (depth below ground level to top of stratum, m)	0	Predrill	Predrill
	1		
	2		
	3		
	4		
	5		
	6		
	7		
	8		
	9		
	10		
	11		
	12		
	13		
	14		
	15		
	16		
	17		
	18		
	19		
	20		
	21		
	22		
	23		
	24		
25			
Greater depths			

\*BH: Borehole, HA: Hand Auger, WW: Water Well, CPT: Cone Penetration Test

Sensitive or organic clay/silt	Clay to silty clay	Clayey silt to silt	Silty sand to silt
Clayey sand	Sand	Gravelly sand or gravel	

VL = very loose, L = loose, MD = medium dense, D = dense, VD = very dense  
 VS = very soft, So = soft, F = firm, St = stiff, VS = very stiff, H = hard