

Christchurch City Council Below Ground Water Well Head Repair Recommendations



For: Christchurch City Council - Reticulation Manager [Robert Meek]

By: Citycare Group [Water] Christchurch

Date: 21 August 2017

Version: For Approval

1. Table of Contents

| | |
|---|----|
| 1. Background | 3 |
| 2. Timeline – Key Points | 3 |
| 3. Repairs | 4 |
| 3.1 Minimum Requirements | 4 |
| 3.2 Priority and Extent of Repair Works | 4 |
| 3.3 Residual Risk | 6 |
| 4. Costs | 7 |
| 5. Summary | 10 |
| 6. Quality Assurance | 11 |
| Appendix One – Below Ground Well Head Locations | 12 |
| Appendix Two – Total Costs by Site | 13 |

1. Background

- 1.1 A meeting was held with Council staff¹ on 26 June 2017, with concern raised at the risk to contamination of the untreated drinking water supply via below ground well head assets. It was noted that this was not a new risk, though evidence from the Inquiry [Havelock North Water Contamination Event] identified the risk of contamination via this pathway was likely.
- 1.2 It was agreed that Citycare Water continue with urgency to assess, review and recommend repairs to below ground well heads. It was also noted by the Head of 3 Waters that this was an unacceptable risk to supply of clean safe to drink water and should be addressed urgently.
- 1.3 All well heads have been inspected, as below and Appendix One and Two:
- # Station Sites Inspected 47
 - # Well heads Inspected at Stations 108
- 1.4 As a result of several wet weather events [20/7/17 and 14/8/17], some well heads were inspected up to three times. This was considered appropriate as observation of wet well inundation (if any) provided direct evidence of shallow surface water and/or elevated groundwater level ingress.
- 1.5 This report provides the following information:
- i) The scope of works – inclusions/exclusions
 - ii) A risk profile, which sets the priority order in which well head repair works will be undertaken
 - iii) A general schematic describing typical well head works
 - iv) Cost estimates against the works

2. Timeline – Key Points

- 2.1 An interim report was tabled with the Councils Head of 3 Waters Manager and others² on 25 July 2017. At that time, site information from a limited number of wellheads had been reviewed due to the time required to inspect sites and wet weather events disrupting access. Further, Council staff had not yet provided feedback on the risk profile (priority ranking for repairs), and repair scope of works with cost estimates had not been completed.
- 2.2 At a meeting³ on 17 August 2017, images of a set of common defects were tabled and typical repair scope of works outlined. Discussion occurred as to whether there was a requirement under the Drinking Water Standards for impermeable plinths to be installed around the below ground wellheads as a part solution to shedding some surface away from the chamber.
- 2.3 This report is tabled to support immediate commencement of physical works.

¹ 26/6 - Attendance by CCC [J. Mackie, J. Moore, M. Johnson, K. Winkles, R. Meek], CCG-W [H. Blake-Manson, C. Barron]

² 25/7 – Attendance by CCC [J. Mackie, J. Moore], CCG-W [H Blake-Manson, B. Triplow]

³ 17/8 – Attended by CCC [D. Murugesh, R. Meek, K. Winkles, G. Wardman], CCG-W [H. Blake-Manson, C. Barron]

3. Repairs

3.1 Minimum Requirements

- 3.1.1 The requirement for this work is driven by written and verbal statements Stage 1 and Stage 2 – Havelock North Inquiry; and the requirement to meet the Drinking Water Standards 2005 (amended 2008):

NB Bore head = well head

Section 4.5.3.2 Bore water security criterion 2: bore head must provide satisfactory protection:

- a. The bore head must be judged to provide satisfactory protection by a person recognised as an expert in the field.
 - b. The bore head must be sealed at the surface to prevent the ingress of surface water and contaminants, and the casing must not allow ingress of shallow groundwater.
 - c. Animals must be excluded from within 5 m of the bore head.
 - d. The bore construction must comply with the environmental standard for drilling soil and rock (NZS 4411, Standards New Zealand (2001)), including providing an effective backflow prevention mechanism, unless agreed by the DWA.
 - e. The supply's water safety plan must address contaminant sources and contaminant migration pathways.
- 3.1.2 With respect to these requirements, it is the writers opinion based on site evidence, industry practice and general discussion with another industry experts that:
- i) A person recognised as an expert would not approve the current below ground bore head standard of work. **Outcome: Watershed plinths are required**
 - ii) Bore heads are not currently sealed at the surface – including air release valves, sample taps, infiltration, inflow **Outcome: Repair all chamber wall defects**
- 3.1.3 Citycare are not able to comment on items d. and e. as these are considered to be matters for the Council to respond to at present. Citycare do not hold or have access to this information at the time of this reports issue.


3.2 Priority and Extent of Repair Works

- 3.2.1 At the meeting of 25 July 2017, Citycare Group – Water were instructed to undertake repair works only. This therefore excludes raising well heads above ground and any barrier based treatment. It is noted that raising well heads is estimated to cost \$65,000 with associated exclusions.
- 3.2.2 At the meeting of 17 August 2017, it was also agreed that significant asset deterioration works would not be included e.g. Grade 4-5 external corrosion on well pipes and fittings
- 3.2.3 The extent of works would therefore include any of the following:
- i) Raised chamber, above any surface flood pathway. Includes rivers (1 in 200 year event 0.2% AEP).
 - ii) Watertight/vandal proof access hatch. Locked, with ability to remove entirely when servicing is required.
 - iii) Surface watershed plinth, approximately 2 sq.m. around access lid.
 - iv) External impermeable grouting around chamber perimeter, and under base to well riser pipe

- v) Internal mass major defect removal and grouting e.g. brick/timber packing, riser ring grouting
- vi) Sloped internal floor with sump pump and "water on floor" alarm
- vii) Removal of all water sampling taps and pipework to above ground secure boxes.
- viii) Removal of all air valves where possible, particularly where a suction tank is located downstream of the well head.

3.2.4 Please refer to Figure 2 for a schematic of a repaired below ground well head.

Figure 1 - Schematic of A Repaired Below Ground Well Head



- 3.2.5 Repairs at well heads will be undertaken against the following risk matrix - Table 1. That is works are well heads with highest overall scores will be undertaken first.


Table 1 - Risk Profile Driving Site Order of Priority

| Weighting Factor | | | | |
|--|----------|--------------|-----------------------|---|
| | 2 | 1.5 | 1 | |
| Risk Item | Scale | | | Comments |
| Surface Water Ingress | Monthly | Annually | >= Five Yearly | Risk of contaminants entering water supply increase as frequency of inundation increases |
| Shallow Ground Water Ingress | Always | Weekly | Annual | Risk of contaminants entering water supply increase as frequency of inundation increases |
| Well security designation (secure/unsecure) | Unsecure | - | Secure | Northwest zone wells are not in secure aquifers? Or there is a higher potential risk that contamination may occur from upstream sources |
| Well Water Supply Zone (CCC # connections) | >50K | 49-10K | <10k | If contaminants enter the network, exposure increases with connected population |
| Chlorination/UV Treatment | None | CL2(g) or UV | Both CL2(g) & UV | This may only apply to BP |
| Well Depth to Screen (m) | 0-49 | 50-119 | Artesian and/or >120m | As well depth increases, there is an assumed greater protection with more "clean water" above the screen, and less mixing of any potential contaminants down inside/external wall of casing |
| PS Peak Abstraction Rate (l/s) | >120 | 119-50 | <50 | As PS abstraction increases, so does drawdown of potential contaminants |

3.3 Residual Risk

- 3.3.1 During the rainfall event of 20-22 July 2017, river water inundated a number of well heads, contaminating them with sewage wastewater which had been washed in via surcharged sewerage networks/pump stations.
- 3.3.2 High groundwater (above chamber base) and rainfall seepage are also considered to present the highest risk and therefore drive the most extensive and intensive action
- 3.3.3 The repair works focus on minimising the ingress of surface water and very shallow unsecure groundwater (~2 m BGL) into the below ground well head chamber/pipework. The extent of works will not however eliminate the potential for pathogen ingress into the water supply via connected pipes eg between the suction tank, deep groundwater and other vectors - Figure 2.

Figure 2 - Focus Area for Repair Work – Below Ground Well Head Zone Only



- 3.3.4 The Council has not sought advice from, request or authorised Citycare to install a water treatment barrier e.g. ultra violet treatment. If pathogens (in particular viruses) are able to enter the groundwater source and migrate while still functional then contaminated water may enter the network. There is no regular testing for viruses to the writers knowledge.
- 3.3.5 The Council could consider pathogen monitoring, and the need for barriers.
- 3.3.6 The residual risks which will remain following completion of the repair works include:
- i) Chamber inundation through higher than design rainfall events (river/waterway flooding)
 - ii) Further chamber wall deterioration resulting in severe acute groundwater ingress
 - iii) No treatment barrier and monitoring in place for pathogen entry to the network via deep groundwater
 - iv) Contamination via other connected assets including well head pipes to suction tanks, suction tanks, pipes to pump station, pump casing and mainfolds to the network.

4. Costs

- 4.1.1 Cost estimates by work item are provided in Table 2
- 4.1.2 Examples of site costs are provided in Figure 4. Total water supply station cost estimates against the number of well heads is provided in Figure 5.
- 4.1.3 A complete list of sites, works and costs is provided in Appendix Two.

Table 2 Work Item Cost Estimate

| Work Item | ESTIMATED COST (per wellhead) |
|---|----------------------------------|
| External Grouting | \$4,000 |
| Internal Grouting of Well Rings | \$1,000 |
| Sealing of Glands and Open Ducts | \$500 |
| Construction of a 2 m Plinth Around Well Cover | \$3,500 |
| Install Secure, Accessible Well Cover | \$3,000 |
| Raise Wellhead Cover above Ground | \$5,000 |
| Seal Tight Wellhead Cover with Well Wall | \$600 |
| Sump Pump and Water On Floor Alarm | \$3,500 |
| Fix Fittings Leaks | \$400 |
| Reconstruct and Seal Wellhead Delivery Pipe In Wall | \$1,500 |
| Move Internal sample Point to External Sample Point | \$1,500 |

Figure 3 - Total Cost Estimate by Repair Work Type




Figure 4 - Typical By Site Distribution of Costs





Figure 5 - Station Cost Estimate / # Well Heads

5. Summary

- 5.1 Criteria for high risk sites have been developed to support determination of appropriate work and the order of prioritisation. Works should either result in minimisation or elimination of the risk of drinking water contamination – refer Risk Weighing Table 1.
- 5.2 Recommendations for risk reduction works at sites are estimated to cost \$840,000

6. Quality Assurance

| | | | |
|----------------------|--------------------|---------------|--|
| VERSION NO. | 1 (For Approval) | DATE: | 21 August 2017 |
| APPROVED BY: | Bjorn Triplow | TITLE: | Southern Regional Manager |
| PREPARED BY: | Hugh Blake-Manson | TITLE: | Contract Manager CPeng, IntPE Nat. Dip. Drinking Water (Assessor) Nat. Dip. Infrastructure Asset Management |
| CERTIFIED BY: | Alan Gramstrup | TITLE: | Operations Manager |
| INPUT BY: | Neena Parul Sharma | TITLE: | Engineer |
| INPUT BY: | Chris Barron | TITLE: | Pumps and Storage Manager |

Appendix One – Below Ground Well Head Locations

Figure 4- Map Showing all Below Ground Well heads Inspected





Figure 5- Map Showing Below Ground Wellheads Inspected After 20/07/17 Rainfall



Appendix Two – Total Costs by Site

The following wellheads have been inspected to date:

| Belowground Wellheads | Address | Number of belowground wellheads | Cost of Repair Works (\$) |
|------------------------------|---------------------------|--|----------------------------------|
| Addington | 479 Barrington St. | 2 | 18500 |
| Aldwins | 54 Aldwins Road | 3 | 44000 |
| Aston Drive | 67 Aston drive | 2 | 7600 |
| Auburn | 29A Auburn Avenue | 1 | 8000 |
| Averill | 57 Averill St. | 3 | 23100 |
| Belfast | 38 Darroch St. | 2 | 9000 |
| Bexley | 551 Pages Road | 2 | 21500 |
| Blighs | 1 Blighs Road | 1 | 17000 |
| Brooklands | 1001 Lower Styx Mill Road | 1 | 4400 |
| Burnside | Burnside Park | 1 | 5000 |
| Burwood | 160 Burwood Road | 2 | 10000 |
| Carters | 4 Carters Road | 4 | 33500 |
| Chapmans | Opposite LPG Tanks | 1 | 17000 |
| Crosbie | 22A Woodbury St. | 2 | 8400 |
| Denton Park | 58 Kathleen Cres | 4 | 33000 |
| Dunbars | CNR Halswell Road | 5 | 14600 |
| Effingham | 72 Effingham St. | 3 | 19000 |
| Farrington | 114 Farrington Avenue | 2 | 14600 |
| Grampian | 62 Grampian St. | 3 | 21600 |
| Grassmere | 21 Grassmere St. | 3 | 23700 |
| Harewood | 8 Whitchurch Place | 1 | 5900 |
| Hillmorton | 14 Halswell Road | 3 | 26000 |
| Hills | 320 Hills Road | 1 | 11500 |
| Jeffreys | 30 Jeffreys Road | 1 | 7100 |
| Kerrs | 50 Kerrs Road | 2 | 25600 |
| Lake Terrace | 5 lake Terrace Road | 1 | 6000 |
| Main Station | 54 Colombo St. | 5 | 40200 |
| Mairehau | Burwood Hospital Grounds | 1 | 5000 |
| Marshlands | 220 Marshlands Road | 2 | 15700 |
| Mays | 107 Mays Road | 3 | 20100 |
| Montreal | 447A Montreal St. | 2 | 20800 |
| Palantine | Opposite Number 24 | 1 | 9100 |

| | | | |
|-------------|--------------------------------------|---|-------|
| Parklands | 8A Portnall Place | 3 | 15000 |
| Picton | 61-69 Picton Avenue | 3 | 19200 |
| Redwood | 54 Prestons Road | 2 | 17700 |
| Sockburn | Service Centre Yard | 6 | 30000 |
| Spreydon | 83 Lyttelton St. | 5 | 59100 |
| St. Johns | 120 St. Johns Street | 2 | 13100 |
| Sydenham | 245 Milton street | 2 | 27200 |
| Tara | In Park | 1 | 10600 |
| Thompsons | Off Blakes Road | 1 | 5500 |
| Thorrington | 24 Thorrington Road | 1 | 8100 |
| Trafalgar | Entrance Next to 41 Edgeware Road | 2 | 8500 |
| Wilmers | 4 Wilmers Road | 2 | 15200 |
| Woolston | 58 Glenroy Road | 2 | 12700 |
| Worcester | 325 Worcester St. | 2 | 10000 |
| Wrights | Trotting Club Grounds | 4 | 41600 |