



Ataahua Domain Garage
Quantitative Engineering
Evaluation

Functional Location ID: PRK 3672 BLDG 002

Address: Christchurch Akaroa Road

Reference: 235461

Prepared for:
Christchurch City Council

Revision: 2

Date: 10 April 2014

Document Control Record

Document prepared by:

Aurecon New Zealand Limited
 Level 2, 518 Colombo Street
 Christchurch 8011
 PO Box 1061
 Christchurch 8140
 New Zealand

T +64 3 375 0761
F +64 3 379 6955
E christchurch@aurecongroup.com
W aurecongroup.com

A person using Aurecon documents or data accepts the risk of:

- a) Using the documents or data in electronic form without requesting and checking them for accuracy against the original hard copy version.
- b) Using the documents or data for any purpose not agreed to in writing by Aurecon.

Document control							aurecon
Report Title		Quantitative Engineering Evaluation					
Functional Location ID		PRK 3672 BLDG 002	Project Number		235461		
File Path		P:\ 235461 - Ataahua Domain Garage.docx					
Client		Christchurch City Council	Client Contact		Michael Sheffield		
Rev	Date	Revision Details/Status	Prepared	Author	Verifier	Approver	
1	11 July 2013	Draft	T Bolton	T Bolton	C Lillywhite	L Howard	
2	07 April 2014	Final	T Bolton	T Bolton	C Lillywhite	L Howard	
Current Revision		2					

Approval			
Author Signature		Approver Signature	
Name	Thomas Bolton	Name	Lee Howard
Title	Structural Engineer	Title	Senior Structural Engineer



Contents

Executive Summary	1
1 Introduction	2
1.1 General	2
2 Description of the Building	2
2.1 Building Age and Configuration	2
2.2 Building Structural Systems Vertical and Horizontal	2
2.3 Reference Building Type	2
2.4 Building Foundation System and Soil Conditions	3
2.5 Available Structural Documentation and Inspection Priorities	3
2.6 Available Survey Information	3
3 Structural Investigation	4
3.1 Summary of Building Damage	4
3.2 Record of Intrusive Investigation	4
3.3 Damage Discussion	4
4 Building Review Summary	5
4.1 Building Review Statement	5
4.2 Critical Structural Weaknesses	5
5 Building Strength (Refer to Appendix C for background information)	5
5.1 General	5
5.2 Initial %NBS Assessment	5
5.3 Results Discussion	6
6 Conclusions and Recommendations	6
7 Explanatory Statement	6

Appendices

Appendix A Site Map, Photos and Levels Survey Results

Appendix B References

Appendix C Strength Assessment Explanation

Appendix D Background and Legal Framework

Appendix E Standard Reporting Spread Sheet

Executive Summary

This is a summary of the Quantitative Engineering Evaluation for the Ataahua Domain Garage and is based on the Detailed Engineering Evaluation Procedure document issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

Building Details	Name	Ataahua Domain Garage			
Building Location ID	PRK 3672 BLDG 002			Multiple Building Site	Y
Building Address	Christchurch Akaroa Road			No. of residential units	0
Soil Technical Category	NA	Importance Level	1	Approximate Year Built	1940
Foot Print (m²)	24	Stories above ground	1	Stories below ground	0
Type of Construction	Lightweight roof, insitu concrete and concrete masonry walls, concrete strip footings, slab on grade floor.				

Quantitative L5 Report Results Summary

Building Occupied	Y	The Ataahua Domain Garage is currently in use.
Suitable for Continued Occupancy	Y	The Ataahua Domain Garage is suitable for continued occupation.
Key Damage Summary	Y	Refer to summary of building damage section 3.1 report body.
Critical Structural Weaknesses (CSW)	N	There were no critical structural weaknesses found.
Levels Survey Results	Y	Floor levels are within tolerance.
Building %NBS From Analysis	81%	Based on an analysis of bracing capacity and demand.

Approval

Author Signature		Approver Signature	
Name	Thomas Bolton	Name	Lee Howard
Title	Structural Engineer	Title	Senior Structural Engineer



1 Introduction

1.1 General

On 2 May 2012 Aurecon engineers visited the Ataahua Domain Garage to carry out a quantitative building damage assessment on behalf of Christchurch City Council. Detailed visual inspections were carried out to assess the damage caused by the earthquakes on 4 September 2010, 22 February 2011, 13 June 2011, 23 December and related aftershocks.

The scope of work included:

- Assessment of the nature and extent of the building damage.
- Visual assessment of the building strength particularly with respect to safety of occupants if the building is currently occupied.
- Assessment of requirements for detailed engineering evaluation including geotechnical investigation, level survey and any areas where linings and floor coverings need removal to expose structural damage.

This report outlines the results of our Qualitative Assessment of damage to the Ataahua Domain Garage and is based on the Detailed Engineering Evaluation Procedure document issued by the Structural Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

2 Description of the Building

2.1 Building Age and Configuration


Likely built in the 1940s the Ataahua Domain Garage is a single story building used for storage and it was extended in the 1980s. The building has a lightweight corrugated steel roof supported by timber rafters. The older walls are insitu reinforced concrete between 100 and 150mm thick. The extension walls are partially reinforced blockwork 190mm thick. We assume the walls are founded on reinforced concrete thickenings in the ground floor concrete floor slab. The approximate floor area of the building is 26 square metres. It is an importance level 1 structure in accordance with NZS 1170 Part 0:2002.

2.2 Building Structural Systems Vertical and Horizontal

The Ataahua Domain Garage has easily defined load paths. Its lightweight steel roof is supported on timber rafters that transfer loads to the blockwork and reinforced concrete walls. These walls which provide the lateral support for the structure are supported on edge thickenings of slab.

2.3 Reference Building Type

The Ataahua Domain Garage is a basic shed typical of its age and style. This type and height of building has typically performed well under seismic loading.



2.4 Building Foundation System and Soil Conditions

The Ataahua Domain Garage foundations, as discussed above consist of concrete strip footings. The land and surrounds of Ataahua Domain Garage have been zoned as Port Hills/Banks Peninsula which means future land damage from liquefaction is unlikely. There were no signs in the vicinity of Ataahua Domain Garage of liquefaction bulges and boils.

2.5 Available Structural Documentation and Inspection Priorities

Structural drawings were not available for the Ataahua Domain Garage. The structure was measured during the inspection. Priority for our assessment was the review of potential damage to the building and consideration of wall bracing adequacy. The generic building type for the Ataahua Domain Garage is a small 1940s reinforced concrete/1980s blockwork building and this type of structure has generally performed well during the Canterbury Earthquakes.

2.6 Available Survey Information

We undertook a floor levels survey to establish the amount of settlement that has occurred. The building contained various implements which meant that a full survey was unable to be undertaken. Spot checks were able to be completed in random areas where the floor was not covered with



obstacles. All of the levels were taken on top of the existing floor coverings which will have introduced some variation.

The Department of Building and Housing (DBH) published the “Revised Guidance on Repairing and Rebuilding Houses Affected by the Canterbury Earthquake Sequence” in November 2011, which recommends some form of re-levelling or rebuilding of the floor:

1. If the slope is greater than 0.5% for any two points more than 2m apart, or
2. If the variation in level over the floor plan is greater than 50mm, or
3. If there is significant cracking of the floor.

It is important to note that these figures are recommendations and are only intended to be applied to residential buildings. However, they provide useful guidance in determining acceptable floor level variations.

The floor levels for the Ataahua Domain Garage were found to be within acceptable levels and the maximum variation was 8mm. The slight variations in floor level that were recorded were reported to be pre-existing. The floor level results have not been included as they were taken at random locations throughout the shed.

3 Structural Investigation

3.1 Summary of Building Damage

The Ataahua Domain Garage is currently in use and were occupied at the time the damage assessment was carried out.

The Ataahua Domain Garage has performed well and no damage from the recent earthquakes was observed.

3.2 Record of Intrusive Investigation

The building structure is largely exposed and therefore, an intrusive investigation was not required for the Ataahua Domain Garage. Reinforcing was detected in the walls using a ferro scanner.

3.3 Damage Discussion

The building structure is largely exposed, is a small structure of importance level 1, and has limited damage therefore an intrusive investigation was not required for the Ataahua Domain Garage.

4 Building Review Summary

4.1 Building Review Statement

As noted above no intrusive investigations were carried out for the Ataahua Domain Garage, although scanning of the walls was completed. Because of the generic nature of the building the primary structure was able to be observed with an external and internal visual inspection.

4.2 Critical Structural Weaknesses

No specific critical structural weaknesses were identified as part of the building qualitative assessment.

5 Building Strength (Refer to Appendix C for background information)

5.1 General

The Ataahua Domain Garage is, as discussed above, a unusual combination of a 1940s reinforced concrete and 1980's blockwork shed, though these two building types work well together due to similar properties. Individually these types of buildings have typically performed well. The Ataahua Domain Garage has performed well in the Canterbury earthquake sequence as evidenced by having no damage observed.

5.2 Initial %NBS Assessment

The Ataahua Domain Garage has not been subject to specific engineering design and the initial evaluation procedure or IEP is not an appropriate method of assessment for this building. Nevertheless an estimate of lateral load capacity can be made by adopting assumed values for strengths of existing materials and calculating the capacity of existing walls.

Selected assessment seismic parameters are tabulated in the Table below.

Table 1: Parameters used in the Seismic Assessment

Seismic Parameter	Quantity	Comment/Reference
Site Soil Class	D	NZS 1170.5:2004, Clause 3.1.3, Deep or Soft Soil
Site Hazard Factor, Z	0.30	DBH Info Sheet on Seismicity Changes (Effective 19 May 2011)
Return period Factor, R_u	0.5	NZS 1170.5:2004, Table 3.5
Ductility Factor in Across (NW-SE) Direction, μ	1.25	Blockwork or concrete walls
Ductility Factor in Along (NE-SW) Direction, μ	1.25	Blockwork or concrete walls



The seismic demand for the Ataahua Domain Garage has been calculated based on the current code requirements. The capacity of the existing walls in the building was calculated from assumed strengths of existing materials and the number and length of walls present for both the along (Northwest – southeast) and across (northwest – southeast directions). The seismic demand was then compared with the building capacity in these directions. The building was found to have a sufficient strength in both the along and across directions to achieve 100% NBS. The out of plane capacity of these walls were checked using section 8 of NZS1170.5 Parts and Components. The strength was found to be 100% NBS in the along direction and 81%NBS in the across direction.

5.3 Results Discussion

This quantitative analysis shows that the Ataahua Domain Garage has a strength of 81% NBS. The building is therefore in the low risk category for building earthquake capacity (NZSEE 2006). This is expected as the building generates a low seismic demand due to its small size thus the walls are able to provide adequate bracing to resist seismic loading. In addition the building has suffered very little if any earthquake related damage.

6 Conclusions and Recommendations

The land below the Ataahua Domain Garage is not zoned by CERA and little land damage from liquefaction is expected in future significant earthquakes. Aerial photographs show that no liquefaction occurred in the area of the Ataahua Domain Garage after the 22 February 2011 earthquake. The levels survey carried out showed that the floor levels were within allowable tolerances and minimal settlement has occurred.

As there is no evidence of settlement of the Ataahua Domain Garage **a geotechnical investigation is currently not considered necessary.**

The building is currently occupied and in our opinion the Ataahua Domain Garage **are considered suitable for continued occupation.**

7 Explanatory Statement

The inspections of the building discussed in this report have been undertaken to assess structural earthquake damage. No analysis has been undertaken to assess the strength of the building or to determine whether or not it complies with the relevant building codes, except to the extent that Aurecon expressly indicates otherwise in the report. Aurecon has not made any assessment of structural stability or building safety in connection with future aftershocks or earthquakes – which have the potential to damage the building and to jeopardise the safety of those either inside or adjacent to the building, except to the extent that Aurecon expressly indicates otherwise in the report.

This report is necessarily limited by the restricted ability to carry out inspections due to potential structural instabilities/safety considerations, and the time available to carry out such inspections. The report does not address defects that are not reasonably discoverable on visual inspection, including



defects in inaccessible places and latent defects. Where site inspections were made, they were restricted to external inspections and, where practicable, limited internal visual inspections.

To carry out the structural review, existing building drawings were obtained from the Christchurch City Council records. We have assumed that the building has been constructed in accordance with the drawings.

While this report may assist the client in assessing whether the building should be strengthened, that decision is the sole responsibility of the client.

This review has been prepared by Aurecon at the request of its client and is exclusively for the client's use. It is not possible to make a proper assessment of this review without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to and the assumptions made by Aurecon. The report will not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, Aurecon's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited as set out in the terms of the engagement with the client.

Appendices



Appendix A

Site Map and Photos

2 May 2012 – Ataahua Domain Garage site photographs

<p>Location of Ataahua Domain.</p>	
<p>Aerial photograph of the Ataahua Domain Garage.</p>	
<p>Building south elevation.</p>	

Building southern elevation.




Inside building



Typical connection from top plate to walls.





Appendix B

References

1. Engineering Advisory Group (EAG): Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury: July 2011
2. Ministry of Business, Innovation and Employment (MBIE) “Repairing and rebuilding houses affected by the Canterbury earthquakes”, December 2012
3. New Zealand Society for Earthquake Engineering (NZSEE), “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes”, April 2012
4. Standards New Zealand, “AS/NZS 1170 Part 0, Structural Design Actions: General Principles”, 2002
5. Standards New Zealand, “AS/NZS 1170 Part 1, Structural Design Actions: Permanent, imposed and other actions”, 2002
6. Standards New Zealand, “NZS 1170 Part 5, Structural Design Actions: Earthquake Actions – New Zealand”, 2004
7. Standards New Zealand, “NZS 3101 Part 1, The Design of Concrete Structures”, 2006
8. Standards New Zealand, “NZS 4230, Design of Reinforced Concrete Masonry Structures”, 2004



Appendix C

Strength Assessment Explanation

New building standard (NBS)

New building standard (NBS) is the term used with reference to the earthquake standard that would apply to a new building of similar type and use if the building was designed to meet the latest design Codes of Practice. If the strength of a building is less than this level, then its strength is expressed as a percentage of NBS.

Earthquake Prone Buildings

A building can be considered to be earthquake prone if its strength is less than one third of the strength to which an equivalent new building would be designed, that is, less than 33%NBS (as defined by the New Zealand Building Act). If the building strength exceeds 33%NBS but is less than 67%NBS the building is considered at risk.

Christchurch City Council Earthquake Prone Building Policy 2010

The Christchurch City Council (CCC) already had in place an Earthquake Prone Building Policy (EPB Policy) requiring all earthquake-prone buildings to be strengthened within a timeframe varying from 15 to 30 years. The level to which the buildings were required to be strengthened was 33%NBS.

As a result of the 4 September 2010 Canterbury earthquake the CCC raised the level that a building was required to be strengthened to from 33% to 67% NBS but qualified this as a target level and noted that the actual strengthening level for each building will be determined in conjunction with the owners on a building-by-building basis. Factors that will be taken into account by the Council in determining the strengthening level include the cost of strengthening, the use to which the building is put, the level of danger posed by the building, and the extent of damage and repair involved.

Irrespective of strengthening level, the threshold level that triggers a requirement to strengthen is 33%NBS.

As part of any building consent application fire and disabled access provisions will need to be assessed.

Christchurch Seismicity

The level of seismicity within the current New Zealand loading code (AS/NZS 1170) is related to the seismic zone factor. The zone factor varies depending on the location of the building within NZ. Prior to the 22nd February 2011 earthquake the zone factor for Christchurch was 0.22. Following the earthquake the seismic zone factor (level of seismicity) in the Christchurch and surrounding areas has been increased to 0.3. This is a 36% increase.

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also

provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure C1 below.


Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

Figure C1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table C1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% probability of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% probability of exceedance in the next year.

Table C1: Relative Risk of Building Failure In A

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times



Appendix D

Background and Legal Framework

Background

Aurecon has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the building

This report is a Qualitative Assessment of the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings were made available, and these have been considered in our evaluation of the building. The building description below is based on a review of the drawings and our visual inspections.

Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:


Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.



The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use


This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’. Regarding seismic capacity ‘as near as reasonably practicable’ has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings



This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:


- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Building Code


The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)

- 
- Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



Appendix E

Standard Reporting Spread Sheet

Location		Building Name: <u>Ataahua Domain Garage</u>	Unit No: <u>Street</u>	Reviewer: <u>Lee Howard</u>
Building Address: <u>Christchurch Akaroa Road</u>		CP/Eng No: <u>1008889</u>	Company: <u>Aurecon</u>	Company project number: <u>235461</u>
Legal Description: _____		Company phone number: <u>03 371 2028</u>	Date of submission: <u>9/04/2014</u>	Inspection Date: <u>2/05/2013</u>
GPS south: <u>43</u> Degrees <u>48</u> Min <u>29</u> Sec		GPS east: <u>172</u> <u>38</u> <u>55</u>	Revision: <u>2</u>	Is there a full report with this summary: <u>Yes</u>
Building Unique Identifier (CC): <u>PRK 3672 BLDG 002</u>				

Site	Site slope: <u>flat</u>	Max retaining height (m): _____
Site Class (to NZS1170.5): <u>D</u>	Soil type: _____	Soil Profile (if available): _____
Proximity to waterway (m, if <100m): _____	Proximity to cliff top (m, if <100m): _____	Proximity to cliff base (m, if <100m): _____
	If Ground improvement on site, describe: _____	Approx site elevation (m): _____

Building	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): _____
Ground floor split: <u>no</u>	Storeys below ground: <u>0</u>	Foundation type: <u>strip footings</u>	Ground floor elevation above ground (m): <u>0.00</u>
Building height (m): <u>2.20</u>	Floor footprint area (approx): <u>26</u>	Age of Building (years): <u>70</u>	Date of design: <u>1935-1965</u>
Strengthening present: <u>no</u>	Use (ground floor): <u>public</u>	Use (upper floors): _____	Use notes (if required): _____
Importance level (to NZS1170.5): <u>IL1</u>			

Gravity Structure	Gravity System: <u>load bearing walls</u>	rafter type, purlin type and cladding: <u>timber purlins, corrugated iron roof</u>
Roof: <u>timber framed</u>	Floors: _____	Beams: _____
Columns: _____	Walls: <u>load bearing concrete</u>	#N/A: <u>100</u>

Lateral load resisting structure	Lateral system along: <u>concrete shear wall</u>	Ductility assumed, μ : <u>1.25</u>	Period along: <u>0.40</u>	Total deflection (ULS) (mm): <u>10</u>	maximum interstorey deflection (ULS) (mm): <u>10</u>	enter wall data in "IEP period calcs worksheet for period calculation estimate or calculation: <u>estimated</u>
	Lateral system across: <u>concrete shear wall</u>	Ductility assumed, μ : <u>1.25</u>	Period across: <u>0.40</u>	Total deflection (ULS) (mm): <u>10</u>	maximum interstorey deflection (ULS) (mm): <u>10</u>	enter wall data in "IEP period calcs worksheet for period calculation estimate or calculation: <u>estimated</u>

Separations:	north (mm): _____	east (mm): _____	south (mm): _____	west (mm): _____	leave blank if not relevant
---------------------	-------------------	------------------	-------------------	------------------	-----------------------------

Non-structural elements	Stairs: _____	Wall cladding: _____	Roof Cladding: <u>Metal</u>	Cladding: _____	Ceilings: _____	Services (list): _____	describe: <u>corrugated iron</u>
--------------------------------	---------------	----------------------	-----------------------------	-----------------	-----------------	------------------------	----------------------------------

Available documentation	Architectural: <u>none</u>	Structural: <u>none</u>	Mechanical: <u>none</u>	Electrical: <u>none</u>	Geotech report: <u>none</u>	original designer name/date: _____
--------------------------------	----------------------------	-------------------------	-------------------------	-------------------------	-----------------------------	------------------------------------

Damage Site:	Site performance: <u>good</u>	Describe damage: _____
(refer DEE Table 4-2)	Settlement: <u>none observed</u>	Differential settlement: <u>none observed</u>
	Liquefaction: <u>none apparent</u>	Lateral Spread: <u>none apparent</u>
	Differential lateral spread: <u>none apparent</u>	Ground cracks: <u>none apparent</u>
	Damage to area: <u>none apparent</u>	

Building:	Current Placard Status: <u>green</u>	
Along	Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: _____
Across	Damage ratio: <u>0%</u>	Describe (summary): _____
Diaphragms	Damage?: _____	Describe: _____
CSWs:	Damage?: _____	Describe: _____
Pounding:	Damage?: _____	Describe: _____
Non-structural:	Damage?: _____	Describe: _____

Recommendations	Level of repair/strengthening required: <u>none</u>	Describe: _____
	Building Consent required: <u>no</u>	Describe: _____
	Interim occupancy recommendations: <u>full occupancy</u>	Describe: _____
Along	Assessed %NBS before e'quakes: <u>100%</u>	Assessed %NBS after e'quakes: <u>100%</u>
Across	Assessed %NBS before e'quakes: <u>81%</u>	Assessed %NBS after e'quakes: <u>81%</u>

IEP	Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.	
Period of design of building (from above): <u>1935-1965</u>	h_n from above: <u>2m</u>	
Seismic Zone, if designed between 1965 and 1994: _____	not required for this age of building	not required for this age of building
	along: <u>0.4</u>	across: <u>0.4</u>
	(%NBS)nom from Fig 3.3: _____	
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0		
Note 2: for RC buildings designed between 1976-1984, use 1.2		
Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)		
	along: <u>0%</u>	across: <u>0%</u>
	Final (%NBS)nom: _____	

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6

Near Fault scaling factor (1/N(T,D), Factor A: along across

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3
 Z₁₉₉₂, from NZS4203:1992
 Hazard scaling factor, Factor B:

2.4 Return Period Scaling Factor

Building Importance level (from above)
 Return Period Scaling factor from Table 3.1 Factor C:

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2) along across
 Ductility scaling factor: =1 from 1976 onwards; or = μ , if pre-1976, from Table 3.3

Ductility Scaling Factor, Factor D: along across

2.6 Structural Performance Scaling Factor:

Sp: along across

Structural Performance Scaling Factor Factor E: along across

2.7 Baseline %NBS, (NBS)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS_b: along across

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

3.2. Vertical irregularity, Factor B:

3.3. Short columns, Factor C:

3.4. Pounding potential Pounding effect D1, from Table to right
 Height Difference effect D2, from Table to right

Therefore, Factor D:

3.5. Site Characteristics

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum along across
 Rationale for choice of F factor, if not

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

along across

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS along across

4.4 Percentage New Building Standard (%NBS), (before)



Aurecon New Zealand Limited
Level 2, 518 Colombo Street
Christchurch 8011

PO Box 1061
Christchurch 8140
New Zealand

T +64 3 375 0761

F +64 3 379 6955

E christchurch@aurecongroup.com

W aurecongroup.com

Aurecon offices are located in:
Angola, Australia, Botswana, China,
Ethiopia, Hong Kong, Indonesia,
Lesotho, Libya, Malawi, Mozambique,
Namibia, New Zealand, Nigeria,
Philippines, Singapore, South Africa,
Swaziland, Tanzania, Thailand, Uganda,
United Arab Emirates, Vietnam.