



CLIENTS | PEOPLE | PERFORMANCE

**Barrington Park Cricket Club Shed
PRK 1125 BLDG 003**

Detailed Engineering Evaluation
Quantitative Report
Version FINAL

270 Barrington Street, Spreydon,
Christchurch



**Barrington Park Cricket Club Shed
PRK 1125 BLDG 003**

Detailed Engineering Evaluation
Quantitative Report
Version FINAL

270 Barrington Street, Spreydon,
Christchurch

Christchurch City Council

Prepared By
Eddie He

Reviewed By
Hamish Mackinven

Date
29th October 2013



Contents

Quantitative Report Summary	1
1. Background	3
2. Compliance	4
2.1 Canterbury Earthquake Recovery Authority (CERA)	4
2.2 Building Act	5
2.3 Christchurch City Council Policy	6
2.4 Building Code	6
3. Earthquake Resistance Standards	7
4. Building Description	8
4.1 General	8
4.2 Gravity Load Resisting System	9
4.3 Lateral Load Resisting System	9
5. Damage Assessment	10
5.1 Surrounding Buildings	10
5.2 Residual Displacements and General Observations	10
5.3 Ground Damage	10
6. Geotechnical Consideration	11
6.1 Site Description	11
6.2 Published Information on Ground Conditions	11
6.3 Seismicity	14
6.4 Slope Failure and/or Rockfall Potential	16
6.5 Liquefaction Potential	16
6.6 "Sufficiently Tested at SLS"	16
6.7 Summary & Recommendations	16
7. Seismic Capacity Assessment	17
7.1 Seismic Parameters	17
7.2 Quantitative Assessment Procedure	17
7.3 % NBS Assessment	18
7.4 Discussion of Results	19



8.	Conclusions and Recommendations	20
9.	Limitations	21
9.1	General	21
9.2	Geotechnical Limitations	21

Table Index

Table 1:	%NBS compared to relative risk of failure	7
Table 2	ECan Borehole Summary	11
Table 3	Geotechnical Investigation Summary Table	12
Table 4	Summary of Known Active Faults'	15
Table 5	Conditional PGA's	15
Table 6:	Calculated Building Seismic Capacities	19

Figure Index

Figure 1:	NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE	7
Figure 2:	Plan Sketch Showing Key Structural Elements	8
Figure 3	Post February 2011 Earthquake Aerial Photography	14
Figure 4:	Building Plan	18

Appendices

- A Photographs
- B CERA Building Evaluation Form



Quantitative Report Summary

Barrington Park Cricket Club Shed

PRK 1125 BLDG 003

Detailed Engineering Evaluation

Quantitative Report - SUMMARY

Version FINAL

270 Barrington Street, Spreydon, Christchurch

Background

This is a summary of the Quantitative report for the Barrington Park Cricket Club Shed building located at 270 Barrington Street, Spreydon, Christchurch, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, a visual inspection on the 29th of August 2013, and seismic capacity calculations.

Building Construction

- ▶ Roof: timber rafters and timber sarking clad with corrugated lightweight metal sheets;
- ▶ Walls: 20 series unreinforced unfilled masonry walls;
- ▶ Floor: reinforced concrete slab on-grade;
- ▶ Foundation: perimeter concrete strip footings.

Key Damage Observed

Key damage observed includes:

- ▶ Stepped cracking to the boundary wall on the northeast side;
- ▶ Cracking to concrete floor outside the front of the building;

Critical Structural Weaknesses

No critical structural weaknesses have been identified when assessing the structure.

Geotechnical Investigation

The geotechnical assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site is considered to be susceptible to significant liquefaction. A soil class of D (in accordance with NZS 1170.5:2004) should be adopted for the site.



Quantitative Assessment Summary

The overall seismic capacity for the Barrington Park Cricket Club Shed building assessed in accordance with NZSEE guidelines is 20% NBS. The rate of 20% NBS represents the out-of-plane seismic capacity of the cantilevered partition walls. The in-plane seismic capacity of the building has been assessed as over 100% NBS in the along direction and 58% NBS in the across direction. The out-of-plane seismic capacity of the simply supported walls has been assessed as 60% NBS and 42% NBS for the parapet on the eastern wall.

Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered as an Earthquake Prone Building as it achieves less than 34% NBS.

Conclusion and Recommendations

The building has been assessed to have a seismic capacity in the order of 20% NBS and is therefore deemed to be an Earthquake Prone Building in accordance with the NZSEE guidelines.

The recent seismic activity in Christchurch has only caused minor damage to the building, with minor cracking in the concrete blockwork masonry walls the only damage noted. However the building has been assessed as having a seismic capacity of less than 34% NBS following a Quantitative Detailed Engineering Evaluation, therefore the building should be strengthened to minimum of 34% NBS to comply with Christchurch City Council's "Earthquake Prone, Dangerous and Insanitary Buildings Policy (2010)". However, GHD recommends strengthening options to the blockwork walls should be explored and implemented to bring the %NBS of the building to a minimum of 67% as recommended by the NZSEE guidelines.



1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Barrington Park Cricket Club Shed.

This report is a Quantitative Assessment and is based in general on NZS 1170.5: 2004, the New Zealand Society for Earthquake Engineering (NZSEE) guidelines for the Assessment and Improvement of Unreinforced Concrete Masonry Buildings for Earthquake Resistance (02/2011) and the Assessment and Improvement of the Structural Performance of Buildings in Earthquakes (06/2006) with the recent supplement from the University of Auckland (05/2013).

This quantitative assessment to the building comprises of an investigation of the in-plane and out-of-plane strengths of the unreinforced masonry block walls. The investigation is based on the analysis of the seismic loads that the structure is subjected to, the analysis of the distribution of these forces throughout the structure and the analysis of the capacity of the existing structural elements to resist the seismic forces applied to them. The capacity of the existing structural elements is compared to the demand placed on the elements to give the percentage of New Building Standard (%NBS) of each of the structural elements.

Electromagnetic scans have been carried out on site to ascertain the extent of the reinforcement in the block masonry walls.

At the time of this report, no finite element modelling of the building structure has been carried out.



2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building;
- ▶ The placard status and amount of damage;
- ▶ The age and structural type of the building;
- ▶ Consideration of any critical structural weaknesses; and
- ▶ The extent of any earthquake damage.



2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

4. Building Description

4.1 General

The building is a single-storey rectangular structure, located within Barrington Park at 270 Barrington Street, Spreydon, Christchurch. The date of construction is unknown; however it appears consistent with building construction in the 1960s. The building is currently used as the Barrington Park Cricket Club Shed, including toilets and changing rooms. No alterations to the original structure were obvious during the site inspection.

The building measures approximately 16.4 m long by 4.2 m wide by average 3.0 m high. It is rectangular in plan, with a gross floor area of approximately 69 m², as shown in Figure 2.

No plans or drawings for the building were made available. This assessment is based on observations, measurements and reinforcing scans from the site inspection.




Figure 2: Plan Sketch Showing Key Structural Elements

The roof comprises 200x50 timber rafters spanning across the building at approximately 450 mm centres, clad with 20 mm timber sarking and lightweight corrugated metal sheets.

The building is constructed from 190 mm thick masonry blockwork, which form both the internal and external walls. A 190 mm blockwork cantilever wall forms a partition in the northern end of the building.

The eastern boundary wall is constructed with 190 mm thick blockwork masonry with a 0.6 m high parapet.

Electromagnetic scans have been carried out on site to ascertain the extent of the reinforcement in the block masonry walls. The existing blockwork walls were found to be unreinforced and appeared to be unfilled.

The floor of the building is a concrete slab on grade, approximately 150 mm above surrounding ground level. Electromagnetic scans detected 6 mm diameter bars at 150 mm centres each way, which are inferred to be 665 mesh.



Perimeter foundations are inferred to be present underneath the blockwork perimeter walls; the thickness of floor and perimeter foundation details could not be confirmed.

4.2 Gravity Load Resisting System

The gravity load resisting system of the building consists of external loadbearing masonry walls founded on concrete strip footings and supporting the timber roof rafters and timber sarking with lightweight metal roof cladding.

4.3 Lateral Load Resisting System

Lateral loads in both the along and the across directions are resisted by the unreinforced masonry walls through in-plane action.



5. Damage Assessment

An inspection of the building was undertaken on the 29th of August 2013. Both the interior and exterior of the building were inspected. Foundations were unable to be viewed due to inaccessibility.

The inspection consisted of observing the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

No level or verticality surveys have been undertaken for this building at this stage.

A Hilti PS 200 Ferroskan was used to determine the position, depth and diameter of any reinforcement in the blockwork masonry structure. This scanning equipment uses electro-magnetic fields to determine the size and depth of the reinforcing steel in the building. In the case of conflicting results, the most conservative bar diameter is chosen for capacity calculations. No reinforcement was found to be present in the walls.

5.1 Surrounding Buildings

Moderate signs of liquefaction were observed on the nearby streets and properties from the Post February 2011 Earthquake Aerial Photography.

5.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during our inspection of the building.

Key damage observed included:

- ▶ Stepped cracking to the boundary wall on the northeast side;
- ▶ Cracking to concrete floor outside the front of the building;

This damage observed is not considered to have an impact on the seismic capacity of the building. Refer photographs of the damage in Appendix A.

5.3 Ground Damage

No evidence of ground movement was observed during the site inspection.



6. Geotechnical Consideration

This desktop geotechnical study outlines the ground conditions, as indicated from sources quoted within, for inclusion in the subject structure's DEE Quantitative Assessment. This is a desktop study report and no site visit has been undertaken by GHD Geotechnical personnel.

This report is specific to the Cricket Club Shed at Barrington Park. The site is surrounded by residential properties, and is owned by the Christchurch City Council.

6.1 Site Description

The site is situated in the suburb of Spreydon, in southern Christchurch. It is relatively flat at approximately 9 m above mean sea level. It is approximately 1 km northeast of the Heathcote River, and 10 km west of the coast (Pegasus Bay).

6.2 Published Information on Ground Conditions

6.2.1 Published Geology

Brown & Weeber, 1992¹ describes the site geology as:

- Dominantly alluvial sand and silt overbank deposits, being alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, Holocene in age;
- Underlying sediments (younger than 6500 years) are surface alluvial silt and sand, subsurface marine sand and alluvial silt and sand, and some peat. No interbedded gravel;
- The Riccarton gravels are located 20 m and 25 m bgl; and
- Groundwater is within 1 m of ground level.

6.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that four boreholes with lithographic logs are located within 200 m of the site. ECan boreholes with appropriate logs are summarised in Table 2.

These indicate the area is underlain by fill and topsoil to 0.4 m bgl. This overlies sand, silt and clay to 1.4 m bgl, and underlain by a further sand layer to 1.8 m bgl. A further sand and silt layer is present to 4.1 m bgl, underlain by silty clay to 4.6 m bgl.

Groundwater was recorded at 2.6 m bgl in the borehole logs.

Table 2 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	From Site	Log Summary
M36/8723	4.6 m	2.6 m	190 m W	0.0 – 0.6 m Topsoil 0.6 – 1.1 m Clayey silt 1.1 – 2.1 m Silt

¹ Brown, L. J. & Weeber, J.H. (1992): *Geology of the Christchurch Urban Area*. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. IGNS Limited: Lower Hutt.



Bore Name	Log Depth	Groundwater	From Site	Log Summary
				2.1 – 3.1 m Clayey silt 3.1 – 3.6 m Silty clay 3.6 – 4.1 m Sand and silt 4.1 – 4.6 m Silty clay
M36/9136	2.4 m	N/A	190 m NE	0.0 – 0.2 m Fill 0.2 – 0.4 m Topsoil 0.4 – 1.4 m Sand and clay 1.4 – 2.0 m Sand 2.0 – 2.4 m Sandy silt
M36/9137	2.1 m	N/A	180 m NE	0.0 – 0.4 m Fill 0.4 – 1.5 m Sand and clay 1.5 – 1.8 m Sand 1.8 – 2.1 m Sandy silt
M36/9355	3.1 m	N/A	190 m W	0.0 – 1.5 m Clay 1.5 – 2.1 m Sand 2.1 – 3.1 m Sand and silt

It should be noted that the logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

6.2.3 Previous Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the subject site.

However, the Canterbury Geotechnical Database (CGD) shows that three historical CPTs were undertaken within 300 m of the site², and are summarised below in Table 3.

Table 3 Geotechnical Investigation Summary Table

Bore Name	Orientation from Site	Depth (m bgl)	Log Summary ³
CPT-HIS-0225	280 m NW	0.0 – 3.0	Silty Clay; firm to stiff (WT not recorded)
CPT-HIS-0731	200 m S	0.0 – 3.0	Silty Clay; firm to stiff (WT not recorded)
CPT-HIS-0877	230 m NE	0.0 – 2.0 2.0 – 2.5	Clayey Silt to Sandy Silt; very stiff Silty Sand; very loose

² Canterbury Geotechnical Database (2012) "Geotechnical Investigation Data", Map Layer CGD0010 - 30 May 2013, retrieved [22/08/2013] from <https://canterburygeotechnicaldatabase.projectorbit.com/>

³ Log Summary for CPT's interpreted from Soil Behavior Type Robertson *et al.* 2010



Bore Name	Orientation from Site	Depth (m bgl)	Log Summary ³
		2.5 – 3.0	Silty Clay; firm to stiff
			(WT not recorded)

Initial observations of the CPT results indicate the site is underlain by silty clay, firm to stiff, to 3.0 m bgl.

6.2.4 CERA Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has indicated the site is situated within the Green Zone, indicating that repair and rebuild may take place.

Land in the CERA green zone has been divided into three technical categories. These categories describe how the land is expected to perform in future earthquakes.

The site has been categorised as “N/A” – Urban Non-residential⁴. However, neighbouring residential properties have been categorised as TC2 (yellow), indicating minor to moderate land damage from liquefaction is possible in future significant earthquakes, with TC3 (blue) properties nearby to the west on Sugden St, indicating moderate to significant land damage from liquefaction is possible in future significant earthquakes.

6.2.5 Historic Land Use

The Listed Land Use Register (LLUR)⁵ indicates that no hazardous activities have occurred at the site.

The Black Maps⁶ shows that the area was historically “Broken Ground”.

Historical aerial photography shows that the site was previously farm land (1946 and 1955).

6.2.6 Post-Earthquake Land Observations

Aerial photography⁷ taken following the 22 February 2011 earthquake shows significant liquefaction in the form of sand boils on Barrington Park, as well as moderate liquefaction on Sugden St, as shown in Figure 3. Aerial photography taken following the 13 June 2011 earthquake shows moderate signs of liquefaction on Sugden St and Barrington Park. Aerial photography taken following the 23 December 2011 earthquake shows no further signs of liquefaction in the area. No coverage was taken following the 4 September 2010 earthquake.

⁴ CERA Landcheck website, <http://cera.govt.nz/my-property>

⁵ Environmental Canterbury Regional Council: *Listed Land Use Register*, retrieved 16/07/2013 from <http://llur.ecan.govt.nz/>

⁶ Waterways, Swamps and Vegetation Cover in 1856 Compiled from "Black Maps", Source: Christchurch City Council retrieved 29 October 2013, <http://resources.ccc.govt.nz/files/blackmap-environmentecology.pdf>

⁷ Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>

Figure 3 Post February 2011 Earthquake Aerial Photography



The Canterbury Geotechnical database shows there are no ground cracks within 1 km of the site⁸.

6.2.7 Summary of Ground Conditions

From the information presented above, the site is anticipated to be underlain by fill and topsoil to 0.4 m bgl, underlain by interbedded layers sand, silt and clay to 4.6 m bgl, underlain by silt and sand with some peat. The Riccarton Gravels are anticipated to be approximately 20 m to 25 m bgl.

Groundwater is considered to vary between 1 m and 2.6 m bgl.

6.3 Seismicity

6.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

⁸ Canterbury Geotechnical Database (2012) "Observed Ground Crack Locations", Map Layer CGD0400 - 23 July 2012, retrieved [22/08/2013] from <https://canterburygeotechnicaldatabase.projectorbit.com/>



Table 4 Summary of Known Active Faults^{9,10}

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	130 km	NW	~8.3	~300 years
Greendale Fault (2010)	20 km	W	7.1	~15,000 years
Hope Fault	110 km	N	7.2~7.5	120~200 years
Porters Pass Fault	60 km	NW	7.0	~1100 years
Port Hills Fault (2011)	3 km	S	6.3	Not Estimated

The recent earthquake sequence since 4 September 2010 has identified the presence of a previously unmapped active fault system underneath the Canterbury Plains; this includes the Greendale Fault and Port Hills Fault listed in Table 4 above. Research and published information on this system is in development and the average recurrence interval is yet to be established for the Port Hills Fault.

6.3.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value was upgraded on 1 August 2011 (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

The Christchurch earthquake sequence has produced earthquakes with significant peak ground accelerations (PGA) across large parts of greater Christchurch. The CGD contains conditional peak ground acceleration contours¹¹ during selected earthquakes of the Canterbury earthquake sequence. These are summarized for this site in Table 5 below.

Table 5 Conditional PGA's

Earthquake Event	EQ Magnitude, Mw	Conditional PGA*
4 September 2010	7.1	0.23 g
22 February 2011	6.2	0.42 g
13 June 2011	6.0	0.20 g
23 December 2011	5.9	0.16 g

* Conditional PGA's have been estimated by combining an empirical ground motion model and PGA's recorded at strong motion stations. Refer Bradley & Hughes (2012) for detail.

⁹ Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002): "A New Seismic Hazard Model for New Zealand", *Bulletin of the Seismological Society of America*, Vol. 92 No. 5, June 2002, pp. 1878-1903.

¹⁰ GNS Active Faults Database, <http://maps.gns.cri.nz/website/af/viewer>

¹¹ Canterbury Geotechnical Database (2012): "Conditional PGA for Liquefaction Assessment", Map Layer CGD5110 - 27 Sept 2012, retrieved 31/10/2012 from <https://canterburygeotechnicaldatabase.projectorbit.com/>



6.4 Slope Failure and/or Rockfall Potential

Given the site's location in Spreydon, global slope instability is considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

6.5 Liquefaction Potential

The site is considered to be susceptible to moderate to significant land damage due to liquefaction, due to:

- Significant liquefaction on Barrington Park, adjacent to the site, as well as moderate liquefaction nearby on Sugden St;
- Adjacent residential properties are categorised as TC2, with some residential properties to the west on Sugden St categorised as TC3.

Further investigation is recommended to better determine subsoil conditions. From this, a more comprehensive liquefaction assessment could be undertaken.

6.6 “Sufficiently Tested at SLS”

Site observations of recent earthquake damage can be correlated to the likely performance of the site at serviceability limit state (SLS) by comparing the PGA observed with design values. This methodology is outlined in the MBIE guidance on Liquefaction Methodology.

Since the PGA for 22 February exceeds 170% of the SLS value, the site can be considered “sufficiently tested at SLS”. As a result, the ground damage during a future moderate earthquake (SLS) is likely to be similar or less than that observed in the 22 February 2011 earthquake.

6.7 Summary & Recommendations

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on stratified alluvial deposits, sand and silt. Associated with this the site also has a moderate to significant liquefaction potential, in particular where sands and/or silts are present.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that intrusive investigation be conducted.



7. Seismic Capacity Assessment

7.1 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class: D
(NZS 1170.5:2004, Clause 3.1.3, “Deep or Soft Soil”);
- ▶ Site hazard factor, $Z = 0.3$
(NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011);
- ▶ Return period factor $R_u = 1.0$
(NZS 1170.5:2004, Table 3.5: Importance Level 2, 50 year design life).

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

7.1.1 Expected Structural Ductility Factor

In accordance with NZSEE Guideline (02/2011), a displacement ductility of 2 is used in the in-plane assessment of unreinforced masonry elements. This corresponds to a structural performance factor S_p of 0.7 and k_u is 1.2 as recommended in the guideline.

7.1.2 Material strength

Average masonry compressive strength, f'_m is calculated using the average masonry compressive strength and average mortar compressive strength in accordance with NZSEE Guideline (02/2011). The compressive strength of masonry was assumed to be 9.9 MPa which was determined as follows:

$$f'_m = 0.7 f'_b{}^{0.75} f'_j{}^{0.3}$$

Where,

$f'_b = 21.5$ MPa, hardness of masonry assumed to be medium,

$f'_j = 3.2$ MPa, hardness of mortar assumed to be medium.

7.2 Quantitative Assessment Procedure

A quantitative assessment of the building was carried out using the information gathered from a full site measure of the building on the 29th of August 2013. From this information, the building's seismic capacity was determined in accordance with New Zealand Society for Earthquake Engineering (NZSEE) guidelines with the recent supplement from the University of Auckland (05/2013). The seismic demand for the building was calculated in accordance with NZS 1170.5:2004 and the percentage of New Building Standard (%NBS) was assessed.

The lateral load resisting system of the building was modelled as in-plane and out-of-plane shear walls.

7.2.1 %NBS

The in-plane capacity of the walls and the out of plane moment capacities were compared to their respective demands to assess which was the most critical and thus determine the overall %NBS for the structure as follows:

$$\%NBS = \frac{\phi S_n (\text{Capacity})}{S^* (\text{Demand})} \times 100\%$$

7.3 % NBS Assessment

The overall seismic capacity for the Barrington Park Cricket Club Shed building assessed in accordance with NZSEE guidelines is 20% NBS. The 20% NBS represents the out-of-plane seismic capacity of the cantilevered partition walls (as shown in Figure 4). The in-plane seismic capacity of the building has been assessed as over 100% NBS in the along direction and 58% NBS in the across direction. The out-of-plane seismic capacity of the simply supported walls has been assessed as 60% NBS and 42% NBS for the parapet on the eastern wall.




Figure 4: Building Plan



Table 6: Calculated Building Seismic Capacities

In-Plane Capacity		
<i>Along direction – in-plane shear</i>		<i>>100% NBS</i>
<i>Across direction – in-plane shear</i>		<i>58% NBS</i>
Out-Of-Plane Capacity		
<i>190mm simply supported walls (Typical) h= 3.0m</i>		<i>60% NBS</i>
<i>190mm cantilevered partition wall</i>	<i>h=2.0m</i>	<i>20% NBS</i>
<i>190mm cantilevered boundary wall</i>	<i>h=1.8m</i>	<i>21% NBS</i>
<i>190mm cantilevered parapet</i>	<i>h=0.6m</i>	<i>42% NBS</i>
Critical %NBS for building		20% NBS

The overall seismic capacity for the Barrington Park Cricket Club Shed building assessed in accordance with NZSEE guidelines is 20% NBS.

This score has not been adjusted when considering damage to the structure as all damage observed was relatively minor and considered unlikely to affect the load carrying capacity of the structural systems.

7.4 Discussion of Results

Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered as an Earthquake Prone Building as it achieves less than 34% NBS. The results obtained from the seismic capacity assessment are consistent with those expected for a building of this age and construction type, and combined with the increase in the hazard factor for Christchurch to 0.3, it would be expected that the building would not achieve 100% NBS. Also, the out-of-plane capacity achieves less than 67% NBS, which is consistent with expectations for buildings constructed with unreinforced masonry block walls.



8. Conclusions and Recommendations

The building has been assessed to have a seismic capacity in the order of 20% NBS and is therefore deemed to be an Earthquake Prone Building in accordance with the NZSEE guidelines.

The recent seismic activity in Christchurch has only caused minor damage to the building, with minor cracking in the concrete blockwork masonry walls the only damage noted. However the building has been assessed as having a seismic capacity of less than 34% NBS following a Quantitative Detailed Engineering Evaluation, therefore the building should be strengthened to minimum of 34% NBS to comply with Christchurch City Council's "Earthquake Prone, Dangerous and Insanitary Buildings Policy (2010)". However, GHD recommends strengthening options to the blockwork walls should be explored and implemented to bring the %NBS of the building to a minimum of 67% as recommended by the NZSEE guidelines.



9. Limitations

9.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken;
- ▶ No intrusive geotechnical investigations have been undertaken;
- ▶ Visual inspections of the roof space were limited to the vicinity of the access hatch and due to its non-central location, the entirety of the roof space could not be inspected visually;
- ▶ No level or verticality surveys have been undertaken;
- ▶ No material testing has been undertaken; and

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report. A specific limitations section.

9.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.



Appendix A

Photographs



Photograph 1: West elevation (front)



Photograph 2: North elevation



Photograph 3: Boundary wall



Photograph 4: South elevation



Photograph 5: Corrugated metal roofing



Photograph 6: Mono pitched roof and the front elevation



Photograph 7: Blockwork Parapet on the eastern boundary wall



Photograph 8: As above



Photograph 9: Minor cracking to the exterior concrete floor slab



Photograph 10: Cantilever partition wall in the toilet area



Photograph 11: Typical stepped cracking on the eastern wall



Photograph 12: As above



Photograph 13: Timber sarking



Photograph 14: Typical interior view



Appendix B
CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.14

Location		Building Name: <input type="text" value="Barrington Park Cricket Club Shed"/>	Reviewer: <input type="text" value="Hamish Mackenvin"/>
	Unit No: Street	CPEng No: <input type="text" value="1003941"/>	Company: <input type="text" value="GHD Ltd"/>
Building Address: <input type="text" value="Barrington Park Cricket Club Shed"/>	<input type="text" value="270"/> <input type="text" value="Barrington Street, Spreydon"/>	Company project number: <input type="text" value="51/31526/29"/>	Company phone number: <input type="text" value="64 03 378 0000"/>
Legal Description: <input type="text" value="Pt RS 41317"/>		Date of submission: <input type="text" value="16/09/2013"/>	Inspection Date: <input type="text" value="29/10/2013"/>
	Degrees Min Sec	Revision: <input type="text" value="FINAL"/>	Is there a full report with this summary? <input type="text" value="yes"/>
GPS south: <input type="text" value="43"/>	<input type="text" value="33"/> <input type="text" value="15.00"/>		
GPS east: <input type="text" value="172"/>	<input type="text" value="37"/> <input type="text" value="5.00"/>		
Building Unique Identifier (CCC): <input type="text" value="PRK 1125 BLDG 003"/>			

Site		Max retaining height (m): <input type="text"/>
Site slope: <input type="text" value="flat"/>	Soil type: <input type="text" value="mixed"/>	Soil Profile (if available): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="D"/>	Proximity to waterway (m, if <100m): <input type="text"/>	If Ground improvement on site, describe: <input type="text"/>
Proximity to cliff top (m, if < 100m): <input type="text"/>	Proximity to cliff base (m,if <100m): <input type="text"/>	Approx site elevation (m): <input type="text"/>

Building		single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value="9.00"/>
No. of storeys above ground: <input type="text" value="1"/>	Ground floor split? <input type="text" value="no"/>	Stores below ground: <input type="text" value="0"/>	Ground floor elevation above ground (m): <input type="text" value="0.10"/>
Foundation type: <input type="text" value="strip footings"/>	Building height (m): <input type="text" value="3.20"/>	if Foundation type is other, describe: <input type="text"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="3.2"/>
Floor footprint area (approx): <input type="text" value="69"/>	Age of Building (years): <input type="text" value="50"/>	Date of design: <input type="text" value="1935-1965"/>	
Strengthening present? <input type="text"/>	Use (ground floor): <input type="text" value="public"/>	Use (upper floors): <input type="text"/>	Use notes (if required): <input type="text" value="pavilion/cricket club shed"/>
Importance level (to NZS1170.5): <input type="text" value="IL2"/>			

Gravity Structure		Gravity System: <input type="text" value="load bearing walls"/>	rafter type, purlin type and cladding: <input type="text" value="200x50 timber rafters @ 450 crs with 20mm thick timber sarking with corrugated metal roofing"/>
Roof: <input type="text" value="timber framed"/>	Floors: <input type="text" value="concrete flat slab"/>	Beams: <input type="text"/>	slab thickness (mm): <input type="text" value="unknown"/>
Columns: <input type="text"/>	Walls: <input type="text"/>		

Lateral load resisting structure				
Lateral system along:	<input type="text" value="other (note)"/>	0.00	Note: Define along and across in detailed report!	describe system <input type="text" value="URM - block"/>
Ductility assumed, μ :	<input type="text" value="2.00"/>			estimate or calculation? <input type="text" value="estimated"/>
Period along:	<input type="text" value="0.10"/>			estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm):	<input type="text"/>			estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm):	<input type="text"/>			
Lateral system across:	<input type="text" value="other (note)"/>	0.00		describe system <input type="text" value="URM - block"/>
Ductility assumed, μ :	<input type="text" value="2.00"/>			estimate or calculation? <input type="text" value="estimated"/>
Period across:	<input type="text" value="0.10"/>			estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm):	<input type="text"/>			estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm):	<input type="text"/>			

Separations:			
north (mm):	<input type="text"/>	leave blank if not relevant	
east (mm):	<input type="text"/>		
south (mm):	<input type="text"/>		
west (mm):	<input type="text"/>		

Non-structural elements			
Stairs:	<input type="text"/>		
Wall cladding:	<input type="text" value="exposed structure"/>	describe	<input type="text" value="URM walls"/>
Roof Cladding:	<input type="text" value="Metal"/>	describe	<input type="text" value="butynol roofing on timber sarking"/>
Glazing:	<input type="text"/>		
Ceilings:	<input type="text"/>		
Services(list):	<input type="text"/>		

Available documentation			
Architectural	<input type="text"/>	original designer name/date	<input type="text"/>
Structural	<input type="text"/>	original designer name/date	<input type="text"/>
Mechanical	<input type="text"/>	original designer name/date	<input type="text"/>
Electrical	<input type="text"/>	original designer name/date	<input type="text"/>
Geotech report	<input type="text"/>	original designer name/date	<input type="text"/>

Damage			
Site: (refer DEE Table 4-2)	Site performance: <input type="text" value="minor"/>	Describe damage:	<input type="text"/>
Settlement:	<input type="text" value="none observed"/>	notes (if applicable):	<input type="text"/>
Differential settlement:	<input type="text" value="none observed"/>	notes (if applicable):	<input type="text"/>
Liquefaction:	<input type="text" value="2-5 m<sup>3</sup>/100m<sup>2</sup>"/>	notes (if applicable):	<input type="text" value="from the aerial photograph (2011)"/>
Lateral Spread:	<input type="text" value="none apparent"/>	notes (if applicable):	<input type="text"/>
Differential lateral spread:	<input type="text" value="none apparent"/>	notes (if applicable):	<input type="text"/>
Ground cracks:	<input type="text" value="0-20mm/20m"/>	notes (if applicable):	<input type="text" value="minor cracking to concrete slab outside the building"/>
Damage to area:	<input type="text" value="slight"/>	notes (if applicable):	<input type="text" value="damage to the pavement"/>

Building: Current Placard Status:

Along Damage ratio: Describe how damage ratio arrived at:

Describe (summary):

Across Damage ratio: $Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$

Describe (summary):

Diaphragms Damage?: Describe:

CSWs: Damage?: Describe:

Pounding: Damage?: Describe:

Non-structural: Damage?: Describe:

Recommendations

Level of repair/strengthening required: Describe:

Building Consent required: Describe:

Interim occupancy recommendations: Describe:

Along Assessed %NBS before e'quakes: ##### %NBS from IEP below If IEP not used, please detail assessment methodology:

Assessed %NBS after e'quakes:

Across Assessed %NBS before e'quakes: ##### %NBS from IEP below

Assessed %NBS after e'quakes:

IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1935-1965 h_n from above: 3.2m

Seismic Zone, if designed between 1965 and 1992: not required for this age of building

not required for this age of building

Period (from above): along across

0.1 0.1

(%NBS)_{nom} from Fig 3.3:

Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0

Note 2: for RC buildings designed between 1976-1984, use 1.2

Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)

Final (%NBS)_{nom}: along across

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

along across

Near Fault scaling factor (1/N(T,D), Factor A):

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:
 Z₁₉₉₂, from NZS4203:1992
 Hazard scaling factor, **Factor B:**

2.4 Return Period Scaling Factor

Building Importance level (from above):
 Return Period Scaling factor from Table 3.1, **Factor C:**

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2) along across
 Ductility scaling factor: =1 from 1976 onwards; or = μ , if pre-1976, from Table 3.3:
 Ductility Scaling Factor, **Factor D:**

2.6 Structural Performance Scaling Factor:

Sp:
 Structural Performance Scaling Factor **Factor E:**

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS:

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

3.2. Vertical irregularity, Factor B:

3.3. Short columns, Factor C:

3.4. Pounding potential
 Pounding effect D1, from Table to right
 Height Difference effect D2, from Table to right

Therefore, Factor D:

3.5. Site Characteristics

Table for selection of D1	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum
 Rationale for choice of F factor, if not 1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS:

4.4 Percentage New Building Standard (%NBS), (before)



GHD

GHD House
Unit 2, 226 Antigua Street, Christchurch
T: 64 3 378 0900 F: 64 3 377 8575 E: chcmail@ghd.com

© GHD Limited 2013

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Draft	E J He	H Mackinven		D Bridgman		Sep 2013
FINAL	E J He	H Mackinven		D Bridgman		Oct 2013