



*Christchurch City Council*

**Birdlings Flat  
Reserve Toilets  
PRK 3655 BLDG 002 EQ2**

**Detailed Engineering Evaluation**

**Quantitative Assessment Report**





*Christchurch City Council*

---

# **Birdlings Flat Reserve Toilets Quantitative Assessment Report**

Opus International Consultants Ltd  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail  
Centre, Christchurch 8140  
New Zealand

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Date: November 2012  
Reference: 6-QUCC1.43  
Status: Final

# Summary

Birdlings Flat Reserve Toilets  
PRK 3655 BLDG 002 EQ2

Detailed Engineering Evaluation  
Quantitative Report - SUMMARY  
Final

## Background

This is a summary of the quantitative report for the Birdlings Flat Reserve Toilets building, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 8 June 2012, drawings provided by CCC and calculations.

## Key Damage Observed

No major damage was identified. Minor wall lining cracks were observed at internal door openings, a crack in the corner of a wall and a crack in the ceiling adjacent to the roof light.

## Critical Structural Weaknesses

No critical structural weaknesses have been identified.

## Indicative Building Strength

Based on the information available, and from undertaking a quantitative assessment, the building's seismic capacity has been assessed to be 78%NBS. The capacity of the building is limited by the pile foundation capacity. It is therefore not classed as an earthquake prone building under the NZSEE classification system.

## Recommendations

We recommend that the minor cracks in the wall linings are repaired.

# Contents

**Summary ..... i**

**1 Introduction.....1**

**2 Compliance .....1**

**3 Earthquake Resistance Standards..... 4**

**4 Building Description ..... 7**

**5 Survey ..... 7**

**6 Damage Assessment..... 7**

**7 General Observations..... 8**

**8 Detailed Seismic Assessment ..... 8**

**9 Conclusions..... 9**

**10 Recommendations ..... 9**

**11 Limitations..... 9**

**12 References ..... 10**

**Appendix A – Photographs**

**Appendix B – Existing Drawings**

**Appendix C – CERA DEE Data Sheet**

# 1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council (CCC) to undertake a detailed seismic assessment of the Birdlings Flat Reserve Toilets, Lot 2 OP 26174 C/T. BA 1123, following the M6.3 Christchurch earthquake on 22 February 2011. The neighbouring water tower has been excluded from this assessment.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011.

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

## 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

### Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or

5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.

- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

## 3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

### 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

### 3.1.1 Occupancy

The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the DBH guidance document dated 12 June 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

### 3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

### 3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### 3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

---

<sup>1</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

## 4 Building Description

### 4.1 General

The Birdlings Flat Reserve Toilets building consists of a raised timber framed toilet block supported on timber floor joists and double bearers bolted to braced timber piles. Access to the toilets is by way of a 3800mm wide by 5400mm timber framed ramp. The walls are externally clad with plywood and internally with compressed cement sheet. The roof is timber framed with profiled steel roofing.

The building is approximately 4.5m long in the east-west direction and 1.8m wide in the north-south direction. The monoslope timber framed roof is approximately 2.5m from the floor.

The drawings indicate that the building was built in 2007.

### 4.2 Gravity Load Resisting System

The timber rafters span to load bearing timber framed walls that are supported by timber bearers and embedded and braced timber piles.

The floor consists of timber joists spanning to the bearers.

### 4.3 Seismic Load Resisting System

Seismic loads in both principal directions are resisted by sheet lined bracing walls to the upper level. The ceiling provides an adequate flexible diaphragm to distribute the seismic induced lateral loads to the wall bracing elements.

The subfloor has been braced in one direction by diagonal timber bracing bolted to proprietary steel pole cleats, and in the other direction by embedded timber piles and timber portal action.

## 5 Survey

Copies of the architectural / structural drawings have been obtained for this building.

The survey photos have been used to confirm the structural systems, investigate potential critical structural weaknesses (CSW) wherever possible, and identify details which required particular attention.

## 6 Damage Assessment

The building structure appears to have performed well during the recent earthquake events with only minor cracks at door openings in the wall linings and ceiling lining.

## 7 General Observations

Overall the building has performed well under seismic conditions which would be expected for a low height timber framed structure. The building has only sustained minor damage.

## 8 Detailed Seismic Assessment

### 8.1 Critical Structural Weaknesses

As outlined in the Critical Structural Weakness and Collapse Hazards draft briefing document, issued by the Structural Engineering Society (SESOC) on 7 May 2011, the term ‘Critical Structural Weakness’ (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of the building.

We have not identified any critical structural weaknesses with this building.

### 8.2 Seismic Coefficient Parameters

The seismic design parameters based on current design requirements from NZS1170.5:2004 and the NZBC clause B1 for this building are:

- Site soil class D, clause 3.1.3 NZS 1170.5:2004;
- Site hazard factor,  $Z=0.3$ , B1/VM1 clause 2.2.14B;
- Return period factor  $R_u = 1.0$  from Table 3.5, NZS 1170.5:2004, for an Importance Level 2 structure with a 50 year design life;
- $\mu_{max} = 2.0$  for wall sheet bracing elements

### 8.3 Detailed Seismic Assessment Results

A summary of the structural performance of the building is shown in the following table.

**Table 2: Summary of Seismic Performance**

Structural Element/System	Failure mode and description of limiting criteria	% NBS based on calculated capacity
Walls in the north-south direction i.e. across the building	Bracing capacity of walls across the building	>100%
Walls in the east-west direction i.e. along the building	Bracing capacity of walls along the building	>100%
Sub floor bracing in north-south direction	Lateral load capacity of embedded piles along the building	78%
Sub floor bracing in east-west direction	Lateral load capacity of embedded piles across the building	>100%

## 8.4 Discussion of Results

The building has a calculated capacity of 78%NBS, as limited by the lateral load capacity of the embedded pile foundation. At the time of design the calculated capacity would have been greater than 100%NBS due to the lower seismic hazard value in use.

This calculated capacity though is based on an assumed strength parameter (effective stress angle) for the existing gravelly sandy subsoils, and could thus be confirmed with a geotechnical verification of this parameter. The %NBS could be either greater or lower than the above value if geotechnical verification was undertaken.

As the building has a capacity of more than 67%NBS it is not defined as an earthquake prone building under the NZSEE classification system. No strengthening work is required for the building and only minor damage repairs will be required.

## 8.5 Limitations and Assumptions in Results

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity;
- Assessments of material strengths based on drawings, specifications and site inspections;
- The normal variation in material properties which change from batch to batch;
- Approximations made in the assessment of the capacity of each element..

## 9 Conclusions

The building has a seismic capacity of greater than 67%NBS and is therefore not classified as earthquake prone in accordance with the Building Act 2004.

## 10 Recommendations

We recommend that the minor cracks in the wall linings are repaired.

## 11 Limitations

- (a) This report is based on an inspection of the structure with a focus on the damage sustained from the 22 February 2011 Canterbury Earthquake and aftershocks only. Some non-structural damage is mentioned but this is not intended to be a comprehensive list of non-structural items.

- (b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at the time.
- (c) This report is prepared for the CCC to assist with assessing remedial works required for council buildings and facilities. It is not intended for any other party or purpose.

## 12 References

- [1] NZS 1170.5: 2004, *Structural design actions, Part 5 Earthquake actions*, Standards New Zealand.
- [2] NZSEE: 2006, *Assessment and improvement of the structural performance of buildings in earthquakes*, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC, *Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes*, Structural Engineering Society of New Zealand, 21 December 2011.

## **Appendix A – Photographs**

## Birdlings Flat Reserve Toilets – Detailed Engineering Evaluation

---




**Photo 1: View of the building from the street**



**Photo 2: Side view of the building**




**Photo 3: Crack in the roof ceiling**



**Photo 4: Crack above the door frame**



**Photo 5: Crack in the wall above the door frame**




**Photo 6: Crack in the corner wall at floor level**



**Photo 7: Subfloor bracing**

## **Appendix B – Existing Drawings**

# Birdlings Flat Reserve Toilets – Detailed Engineering Evaluation







## **Appendix C – CERA DEE Data Sheet**

<b>Location</b>		Building Name: Birdlings Flat Reserve Toilet	Unit No: Street	Reviewer: Jan Stanway
Building Address:				CPEng No: 222291
Legal Description: Lot 2 OP26174 C/T BA 1123				Company: Opus International Consultants Ltd
				Company project number: 6-QUCC1.43
				Company phone number: 03 363 5400
	Degrees	Min	Sec	Date of submission: 29-Nov-12
GPS south: 43	49	32.79		Inspection Date: 8/06/2012
GPS east: 172	42	27.70		Revision: Final
Building Unique Identifier (CCC): PRK 3655-BLDG-002 EQ2				Is there a full report with this summary? yes

<b>Site</b>	Site slope:		Max retaining height (m):	
	Soil type:	gravel	Soil Profile (if available):	
	Site Class (to NZS1170.5):	D	If Ground improvement on site, describe:	
	Proximity to waterway (m, if <100m):		Approx site elevation (m):	0.50
	Proximity to cliff top (m, if <100m):			
	Proximity to cliff base (m, if <100m):			

<b>Building</b>	No. of storeys above ground:	2	single storey = 1	Ground floor elevation (Absolute) (m):	
	Ground floor split?	no		Ground floor elevation above ground (m):	2.30
	Storeys below ground:	0		if Foundation type is other, describe:	cast in timber pile
	Foundation type:	other (describe)	height from ground to level of uppermost seismic mass (for IEP only) (m):		
	Building height (m):	5.10	Date of design:	2004-	
	Floor footprint area (approx):	8			
	Age of Building (years):	5			
	Strengthening present?	no	If so, when (year)?		
	Use (ground floor):	other (specify)	And what load level (%g)?		
	Use (upper floors):		Brief strengthening description:		
	Use notes (if required):	public toilet			
	Importance level (to NZS1170.5):	IL2			

<b>Gravity Structure</b>	Gravity System:	load bearing walls	rafter type, purlin type and cladding:	timber and trimdeck roofing
	Roof:	timber framed	joist depth and spacing (mm):	
	Floors:	timber		
	Beams:			
	Columns:			
	Walls:			

<b>Lateral load resisting structure</b>	Lateral system along:	lightweight timber framed walls	Note: Define along and across in detailed report!	note typical wall length (m)	
	Ductility assumed, μ:	2.00		estimate or calculation?	estimated
	Period along:	0.40		estimate or calculation?	estimated
	Total deflection (ULS) (mm):	3		estimate or calculation?	estimated
	maximum interstorey deflection (ULS) (mm):	2			
	Lateral system across:	lightweight timber framed walls		note typical wall length (m)	
	Ductility assumed, μ:	2.00		estimate or calculation?	estimated
	Period across:	0.40		estimate or calculation?	estimated
	Total deflection (ULS) (mm):	3		estimate or calculation?	estimated
	maximum interstorey deflection (ULS) (mm):	2			

<b>Separations:</b>	north (mm):		leave blank if not relevant
	east (mm):		
	south (mm):		
	west (mm):		

<b>Non-structural elements</b>	Stairs:		
	Wall cladding:		ply external, villaboard internal
	Roof Cladding:		
	Glazing:	timber frames	Sky lights
	Ceilings:		
	Services(list):		

<b>Available documentation</b>	Architectural:	full	original designer name/date:	City Solutions - 22/06/2007
	Structural:	full	original designer name/date:	City Solutions - 22/06/2007
	Mechanical:	none	original designer name/date:	
	Electrical:	none	original designer name/date:	
	Geotech report:	none	original designer name/date:	

<b>Damage</b>	Site performance:		Describe damage:	
<b>Site:</b> (refer DEE Table 4-2)	Settlement:		notes (if applicable):	
	Differential settlement:		notes (if applicable):	
	Liquefaction:		notes (if applicable):	
	Lateral Spread:		notes (if applicable):	
	Differential lateral spread:		notes (if applicable):	
	Ground cracks:		notes (if applicable):	
	Damage to area:		notes (if applicable):	

<b>Building:</b>	Current Placard Status:	green	
<b>Along</b>	Damage ratio:	0%	Describe how damage ratio arrived at:
	Describe (summary):		
<b>Across</b>	Damage ratio:	0%	$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
	Describe (summary):		
<b>Diaphragms</b>	Damage?:	no	Describe:
<b>CSWs:</b>	Damage?:	no	Describe:
<b>Pounding:</b>	Damage?:	no	Describe:
<b>Non-structural:</b>	Damage?:	yes	Describe: wall lining cracks, ceiling lining cracks

<b>Recommendations</b>	Level of repair/strengthening required:	minor non-structural	Describe:	Repair wall, ceiling lining cracks
	Building Consent required:	no	Describe:	
	Interim occupancy recommendations:	full occupancy	Describe:	
<b>Along</b>	Assessed %NBS before e'quakes:	78%	#### %NBS from IEP below	If IEP not used, please detail assessment methodology:
	Assessed %NBS after e'quakes:	78%		
<b>Across</b>	Assessed %NBS before e'quakes:	100%	#### %NBS from IEP below	
	Assessed %NBS after e'quakes:	100%		



**Opus International Consultants Ltd**  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

t: +64 3 363 5400  
f: +64 3 365 7858  
w: [www.opus.co.nz](http://www.opus.co.nz)