



**Bottle Lake Forest Rangers House
Qualitative Engineering Evaluation**

Reference: 228594
Prepared for:
Christchurch City Council

Functional Location ID: PRK_0158_BLDG_011

Revision: 3

Address: 70 Waitikiri Drive

Date: 10 October 2013

Document Control Record

Document prepared by:

Aurecon New Zealand Limited
 Level 2, 518 Colombo Street
 Christchurch 8011
 PO Box 1061
 Christchurch 8140
 New Zealand

T +64 3 375 0761
F +64 3 379 6955
E christchurch@aurecongroup.com
W aurecongroup.com

A person using Aurecon documents or data accepts the risk of:

- Using the documents or data in electronic form without requesting and checking them for accuracy against the original hard copy version.
- Using the documents or data for any purpose not agreed to in writing by Aurecon.

Document control				aurecon		
Report Title		Qualitative Engineering Evaluation				
Functional Location ID		PRK_0158_BLDG_011	Project Number		228594	
File Path		P:\ 228594 - Bottle Lake Forest Rangers House.docx				
Client		Christchurch City Council	Client Contact		Michael Sheffield	
Rev	Date	Revision Details/Status	Prepared	Author	Verifier	Approver
1	4 May 2012	Draft	C. Bong	C. Bong	S. Manning	S. Manning
2	18 December 2012	Final	C. Bong	C. Bong	L. Castillo	L. Castillo
3	10 October 2013	Final	C. Bong	C. Bong	L. Castillo	L. Castillo
Current Revision		3				

Approval			
Author Signature		Approver Signature	
Name	Chris Bong	Name	Luis Castillo
Title	Structural Engineer	Title	Senior Structural Engineer



Contents

Executive Summary	1
1 Introduction	2
1.1 General	2
2 Description of the Building	2
2.1 Building Age and Configuration	2
2.2 Building Structural Systems Vertical and Horizontal	2
2.3 Reference Building Type	2
2.4 Building Foundation System and Soil Conditions	3
2.5 Available Structural Documentation and Inspection Priorities	3
2.6 Available Survey Information	3
3 Structural Investigation	3
3.1 Summary of Building Damage	3
3.2 Record of Intrusive Investigation	3
3.3 Damage Discussion	3
4 Building Review Summary	4
5 Building Strength	4
6 Conclusions and Recommendations	4
7 Explanatory Statement	5

Appendices

Appendix A Photos, Site Map and Levels Survey

Appendix B References

Appendix C Strength Assessment Explanation

Appendix D Background and Legal Framework

Appendix E Standard Reporting Spread Sheet

Executive Summary

This is a summary of the Qualitative Engineering Evaluation for the Bottle Lake Forest Rangers House building and is based on the Detailed Engineering Evaluation Procedure document issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

Building Details	Name	Bottle Lake Forest Rangers House			
Building Location ID	PRK_0158_BLDG_011	Multiple Building Site	Y		
Building Address	70 Waitikiri Drive	No. of Residential Units	1		
Soil Technical Category	N/A	Importance Level	2	Approximate Year Built	1994
Foot Print (m²)	140	Storeys above ground	1	Storeys below ground	0
Type of Construction	Lightweight timber frame, light truss roof, brick veneer cladding, concrete slab on grade.				
Qualitative L4 Report Results Summary					
Building Occupied	Y	Currently the ranger's residence.			
Suitable for Continued Occupancy	Y	Suitable for continued use.			
Key Damage Summary	Y	Refer to summary of building damage Section 3.1 report body.			
Critical Structural Weaknesses (CSW)	N	No critical structural weaknesses were found.			
Levels Survey Results	Y	Levels survey results are within acceptable limits.			
Building Analysis	%NBS From	Approx. 100%	Analysis based on assumed approximate building material strengths.		
Qualitative L4 Report Recommendations					
Geotechnical Survey Required	N	Uncategorised, Technical Category 2 by extrapolation.			
Proceed to Quantitative DEE	L5	N	A quantitative DEE is not required for this structure.		
Approval					
Author Signature			Approver Signature		
Name	Chris Bong		Name	Luis Castillo	
Title	Structural Engineer		Title	Senior Structural Engineer	



1 Introduction

1.1 General

On 14 March 2012, Aurecon engineers visited the Bottle Lake Forest Rangers House to carry out a qualitative and quantitative building damage assessment on behalf of Christchurch City Council. Detailed visual inspections were carried out to assess the damage caused by the earthquakes on 4 September 2010, 22 February 2011, 13 June 2011, 23 December 2011 and their subsequent aftershocks.

The scope of work included:

- Assessment of the nature and extent of the building damage; and
- Visual assessment of the building strength particularly with respect to safety of occupants if the building is currently occupied.

This report outlines the results of our qualitative assessment of damage to the Bottle Lake Forest Rangers House and is based on the Detailed Engineering Evaluation Procedure document issued by the Structural Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

2 Description of the Building

2.1 Building Age and Configuration

The Bottle Lake Forest Rangers House is a single storey, lightweight timber framed, brick veneer clad building constructed in 1994. In 2002 the concrete foundation slab was extended and additional bedrooms were added.

The approximate floor area of the Rangers House is 140 square metres and it is classified as an importance level 2 building according to NZS 1170 Part 0: 2002.

2.2 Building Structural Systems Vertical and Horizontal

Vertical loads from the corrugated iron roof are resisted by timber purlins supported by nail plate trusses spanning between the external walls. The external walls provide lateral restraint to the brick veneer and transfer vertical loads from the trusses into the concrete slab edge foundation beam that also provides vertical support for the brick veneer.

Horizontal or lateral loads for the Rangers House in each principle direction are resisted by the internal and external timber framed walls. The loads are transferred to the walls by the roof diaphragm and the wall framing is braced by the plaster board fixed to it. Loads are transferred to the wall bottom plate by the linings through the bottom plate fixings into the foundations.

2.3 Reference Building Type

The Bottle Lake Forest Rangers House is a very typical example of a relatively low cost, concrete pad, single story, timber framed, brick veneer clad house. The most vulnerable aspect of this house is the brick veneer cladding which, being rigid and brittle, is prone to seismic damage. Inspection of potential damage to the brick veneer cladding was a priority for this structure.



2.4 Building Foundation System and Soil Conditions

The Bottle Lake Forest Rangers House is founded on a reinforced concrete perimeter foundation. Drawings were available and these show that a 200mm wide concrete perimeter footing cast 300mm into the ground has been provided. Approximately 200mm of compacted hard fill has been used to build up levels and onto this a 100mm thick floor slab has been cast. Starter bars have been provided between the footing and the slab and mesh has been used in the slab.

CERA land zone maps indicate that Bottle Lake Forest Park currently sits on “Yet To be Classified Rural & Unmapped Land”, however the land to the immediate south has classed as Technical Category 2 Land. By extrapolation, the land is deemed unlikely to be subject to liquefaction or settlement in to future earthquakes. The site inspection has shown no obvious ground disturbance or movement have been noted in the immediate vicinity of the Rangers House.

2.5 Available Structural Documentation and Inspection Priorities

Construction drawings for both the original house, built in 1994, and the 2002 addition were available and these were referenced as part of the review process. As stated above inspection for damage to the brick veneer cladding was a priority.

2.6 Available Survey Information

A levels survey has been carried out in Bottle Lake Forest Rangers House and a sketch of the results is attached in appendix A. The results show that the floor levels are within acceptable limits.

3 Structural Investigation

3.1 Summary of Building Damage

An interior and exterior visual inspection was undertaken. The only visible damage that was seen on 14 March 2012 was minor cracking of the plasterboard linings at wall-ceiling intersections on the building interior. No damage was observed to the brick veneer on the exterior of the ranger’s house.

3.2 Record of Intrusive Investigation

Although cladding and lining elements concealed the primary structural elements of this house, because the observed displacement damage was minimal it was inferred that little or no damage to the primary structure had occurred and an intrusive investigation was deemed to be unnecessary.

3.3 Damage Discussion

The Bottle Lake Forest Rangers House has suffered only minor damage as a result of recent seismic activity. Although the cracking in the plasterboard internal lining indicates some degree of displacement damage, lack of associated damage in the mortar of the brickwork indicates that the degree of displacement damage was minor.



4 Building Review Summary

Not all of the structural components for this building were assessable. As such, the visual inspection focused primarily on the damage to the non-structural linings and trimming as key indicators of displacement damage.

The observed displacement damage for this building was found to be little to none, thus implying a commensurate degree of damage to the corresponding structural elements.

5 Building Strength

(Refer to Appendix C for background information)

Because the Bottle Lake Forest Rangers House is not an optimised engineered structure that was subject to specific engineering design the initial engineering procedure or IEP is not an appropriate method of initial assessment. The approach taken to determine the approximate seismic capacity of this structure was to calculate demand from first principles and then estimate capacity by assuming approximate strengths for existing materials. The size of existing load resisting elements, walls, in each direction was measured and from this an approximate capacity was calculated.

This exercise resulted in a longitudinal capacity in terms of percentage new building strength (%NBS) of 130%NBS and a transverse capacity also of approximately 130%NBS. These values are in excess of current code requirements or new building standards.

6 Conclusions and Recommendations

As the Bottle Lake Forest Rangers House has been estimated to have greater than 100%NBS the building does not require strengthening and can be considered safe for continued occupancy.



7 Explanatory Statement

The inspections of the building discussed in this report have been undertaken to assess structural earthquake damage. No analysis has been undertaken to assess the strength of the building or to determine whether or not it complies with the relevant building codes, except to the extent that Aurecon expressly indicates otherwise in the report. Aurecon has not made any assessment of structural stability or building safety in connection with future aftershocks or earthquakes – which have the potential to damage the building and to jeopardise the safety of those either inside or adjacent to the building, except to the extent that Aurecon expressly indicates otherwise in the report.

This report is necessarily limited by the restricted ability to carry out inspections due to potential structural instabilities/safety considerations, and the time available to carry out such inspections. The report does not address defects that are not reasonably discoverable on visual inspection, including defects in inaccessible places and latent defects. Where site inspections were made, they were restricted to external inspections and, where practicable, limited internal visual inspections.

To carry out the structural review, existing building drawings were obtained (where available) from the Christchurch City Council records. We have assumed that the building has been constructed in accordance with the drawings.

While this report may assist the client in assessing whether the building should be repaired, strengthened, or replaced that decision is the sole responsibility of the client.

This review has been prepared by Aurecon at the request of its client and is exclusively for the client's use. It is not possible to make a proper assessment of this review without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to and the assumptions made by Aurecon. The report will not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, Aurecon's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited as set out in the terms of the engagement with the client.

Appendices




Appendix A

Photos, Site Map and Levels Survey


14 March 2012 – Bottle Lake Forest Rangers House Site Photographs

1	Elevation of the exterior of the Ranger's House.	
2	Elevation of the exterior of the Ranger's House.	
3	Cracks in the plaster board in the interior of the Ranger's house	

4	Cracks in the plaster board in the exterior of the Ranger's house	
---	---	--



Plan Layout: Bottle Lake Forest Buildings



3/2/2012 3:16:44 p.m.



REV	DATE	REVISION DETAILS	APPROVAL

DRAWN	DESIGNED
D.HUNIA	C.BONG
CHECKED	
L.CASTILLO	
APPROVED	
	DATE
L.CASTILLO	

PROJECT
BOTTLE LAKE FOREST CHRISTCHURCH
TITLE
RANGER HOUSE FLOOR LEVEL SURVEY

PRELIMINARY NOT FOR CONSTRUCTION	
PROJECT No. 228594	
SCALE 1:100	SIZE A4
DRAWING No. S-01-00	REV

Appendix B

References

1. Department of Building and Housing (DBH), “Revised Guidance on Repairing and Rebuilding Houses Affected by the Canterbury Earthquake Sequence”, November 2011
2. New Zealand Society for Earthquake Engineering (NZSEE), “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes”, April 2012
3. Standards New Zealand, “AS/NZS 1170 Part 0, Structural Design Actions: General Principles”, 2002
4. Standards New Zealand, “AS/NZS 1170 Part 1, Structural Design Actions: Permanent, imposed and other actions”, 2002
5. Standards New Zealand, “NZS 1170 Part 5, Structural Design Actions: Earthquake Actions – New Zealand”, 2004
6. Standards New Zealand, “NZS 3101 Part 1, The Design of Concrete Structures”, 2006
7. Standards New Zealand, “NZS 3404 Part 1, Steel Structures Standard”, 1997
8. Standards New Zealand, “NZS 3603, Timber Structures Standard”, 1993
9. Standards New Zealand, “NZS 3604, Timber Framed Structures”, 2011
10. Standards New Zealand, “NZS 4229, Concrete Masonry Buildings Not Requiring Specific Engineering Design”, 1999
11. Standards New Zealand, “NZS 4230, Design of Reinforced Concrete Masonry Structures”, 2004

Appendix C

Strength Assessment Explanation

New Building Standard (NBS)

New building standard (NBS) is the term used with reference to the earthquake standard that would apply to a new building of similar type and use if the building was designed to meet the latest design Codes of Practice. If the strength of a building is less than this level, then its strength is expressed as a percentage of NBS.

Earthquake Prone Buildings

A building can be considered to be earthquake prone if its strength is less than one third of the strength to which an equivalent new building would be designed, that is, less than 33%NBS (as defined by the New Zealand Building Act). If the building strength exceeds 33%NBS but is less than 67%NBS the building is considered at risk.

Christchurch City Council Earthquake Prone Building Policy 2010

The Christchurch City Council (CCC) already had in place an Earthquake Prone Building Policy (EPB Policy) requiring all earthquake-prone buildings to be strengthened within a timeframe varying from 15 to 30 years. The level to which the buildings were required to be strengthened was 33%NBS.

As a result of the 4 September 2010 Canterbury earthquake the CCC raised the level that a building was required to be strengthened to from 33% to 67% NBS but qualified this as a target level and noted that the actual strengthening level for each building will be determined in conjunction with the owners on a building-by-building basis. Factors that will be taken into account by the Council in determining the strengthening level include the cost of strengthening, the use to which the building is put, the level of danger posed by the building, and the extent of damage and repair involved.

Irrespective of strengthening level, the threshold level that triggers a requirement to strengthen is 33%NBS.

As part of any building consent application fire and disabled access provisions will need to be assessed.

Christchurch Seismicity

The level of seismicity within the current New Zealand loading code (AS/NZS 1170) is related to the seismic zone factor. The zone factor varies depending on the location of the building within NZ. Prior to the 22nd February 2011 earthquake the zone factor for Christchurch was 0.22. Following the earthquake the seismic zone factor (level of seismicity) in the Christchurch and surrounding areas has been increased to 0.3. This is a 36% increase.

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure C1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

Figure C1: NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table C1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% probability of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% probability of exceedance in the next year.

Table C1: Relative Risk of Building Failure In A

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Appendix D

Background and Legal Framework

Background

Aurecon has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the building

This report is a Qualitative Assessment of the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

Appendix E

Standard Reporting Spread Sheet

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: <u>Bottle Lake Forest Rangers House</u>	Unit No: <u> </u>	Street: <u>70 Waitikiri Drive</u>	Reviewer: <u>Simon Manning</u>
Building Address: <u>Bottle Lake Forest</u>		Legal Description: <u>RS 26529</u>			CP/Eng No: <u>132063</u>
GPS south: <u>43</u>		Degrees: <u>28</u>	Min: <u>17</u>	Sec: <u>32</u>	Company: <u>Aurecon</u>
GPS east: <u>172</u>		Building Unique Identifier (CCC): <u>FRK_0158_BLDG_011</u>			Company project number: <u>228544</u>
Is there a full report with this summary? <u>yes</u>		Date of submission: <u>10/10/2013</u>			Company phone number: <u>03 375 0761</u>
		Inspection Date: <u>14/03/2012</u>			Revision: <u>3</u>

Site		Site slope: <u>flat</u>	Max retaining height (m): <u> </u>
Site Class (to NZS1170.5): <u>D</u>		Soil type: <u>mixed</u>	Soil Profile (if available): <u> </u>
Proximity to waterway (m, if <100m): <u> </u>		If Ground improvement on site, describe: <u> </u>	
Proximity to cliff top (m, if <100m): <u> </u>		Approx site elevation (m): <u>3.30</u>	
Proximity to cliff base (m, if <100m): <u> </u>			

Building		No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>3.60</u>
Ground floor split? <u>no</u>		Foundation type: <u>raft slab</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>4</u>	Ground floor elevation above ground (m): <u>0.30</u>
Stores below ground: <u>0</u>		if Foundation type is other, describe: <u> </u>		
Building height (m): <u>4.00</u>		Date of design: <u>1992-2004</u>		
Floor footprint area (approx): <u>130</u>		Strengthening present? <u>no</u>		
Age of Building (years): <u>50</u>		If so, when (year)? <u> </u>		
Use (ground floor): <u>other (specify)</u>		And what load level (%g)? <u> </u>		
Use (upper floors): <u>Residential</u>		Brief strengthening description: <u> </u>		
Use notes (if required): <u>IL2</u>				
Importance level (to NZS1170.5): <u>IL2</u>				

Gravity Structure		Gravity System: <u>load bearing walls</u>	truss depth, purlin type and cladding: <u> </u>
Roof: <u>timber truss</u>		Floors: <u>concrete flat slab</u>	slab thickness (mm): <u> </u>
Beams: <u>timber</u>		Columns: <u>timber</u>	typical dimensions (mm x mm): <u> </u>
Walls: <u>non-load bearing</u>		type: <u> </u>	

Lateral load resisting structure		Lateral system along: <u>lightweight timber framed walls</u>	Note: Define along and across in detailed report!	note typical wall length (m): <u>15.4</u>
Ductility assumed, μ: <u>3.00</u>		Period along: <u>0.40</u>	estimate or calculation? <u>estimated</u>	
Total deflection (ULS) (mm): <u> </u>		maximum interstorey deflection (ULS) (mm): <u> </u>	estimate or calculation? <u>estimated</u>	
Lateral system across: <u>lightweight timber framed walls</u>		Period across: <u>0.40</u>	estimate or calculation? <u>estimated</u>	note typical wall length (m): <u>8</u>
Ductility assumed, μ: <u>3.00</u>		Total deflection (ULS) (mm): <u> </u>	estimate or calculation? <u>estimated</u>	
maximum interstorey deflection (ULS) (mm): <u> </u>				

Separations:		north (mm): <u> </u>	leave blank if not relevant
east (mm): <u> </u>			
south (mm): <u> </u>			
west (mm): <u> </u>			

Non-structural elements		Stairs: <u> </u>	describe (note cavity if exists): <u> </u>
Wall cladding: <u>brick or tile</u>		Roof Cladding: <u>Metal</u>	describe: <u>corrugated iron</u>
Ceilings: <u>fibrous plaster, fixed</u>			
Services (list): <u> </u>			

Available documentation		Architectural: <u>none</u>	original designer name/date: <u>Stonewood Homes Ltd 30/08/1994</u>
Structural: <u>partial</u>		Mechanical: <u>none</u>	(Original); City Solutions 27/09/2002
Electrical: <u>none</u>		original designer name/date: <u> </u>	(Alterations)
Geotech report: <u>none</u>		original designer name/date: <u> </u>	

Damage		Site performance: <u> </u>	Describe damage: <u>minor - none</u>
Settlement: <u>none observed</u>		Differential settlement: <u>none observed</u>	notes (if applicable): <u> </u>
Liquefaction: <u>none apparent</u>		Lateral Spread: <u>none apparent</u>	notes (if applicable): <u> </u>
Differential lateral spread: <u>none apparent</u>		Ground cracks: <u>none apparent</u>	notes (if applicable): <u> </u>
Damage to area: <u>none apparent</u>		notes (if applicable): <u> </u>	

Building:		Current Placard Status: <u>green</u>	
Along		Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: <u> </u>
Describe (summary): <u> </u>			
Across		Damage ratio: <u>0%</u>	$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$
Describe (summary): <u> </u>			
Diaphragms		Damage?: <u>no</u>	Describe: <u> </u>
CSWs:		Damage?: <u>no</u>	Describe: <u> </u>
Pounding:		Damage?: <u>no</u>	Describe: <u> </u>
Non-structural:		Damage?: <u>no</u>	Describe: <u> </u>

Recommendations		Level of repair/strengthening required: <u>none</u>	Describe: <u> </u>
Building Consent required: <u>no</u>		Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u> </u>
Along		Assessed %NBS before: <u>100%</u>	Assessed %NBS after: <u>100%</u>
Assessed %NBS after: <u>100%</u>		If IEP not used, please detail assessment methodology: <u>Calculate demand from first principles, estimate capacity</u>	
Across		Assessed %NBS before: <u>100%</u>	Assessed %NBS after: <u>100%</u>

IEP		Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.	
Period of design of building (from above): <u>1992-2004</u>		h _n from above: <u>4m</u>	
Seismic Zone, if designed between 1965 and 1992: <u> </u>		not required for this age of building	
		Design Soil type from NZS4203:1992, cl 4.6.2.2: <u> </u>	
		along	across
		0.4	0.4
		Note 1: for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0	
		Note 2: for RC buildings designed between 1976-1984, use 1.2	
		Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)	

Final (%NBS)_{nom}:

along	0%
across	0%

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

Near Fault scaling factor (1/N(T,D), Factor A):

along	#DIV/0!
across	#DIV/0!

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:

Z₁₉₉₂, from NZS4203:1992:

Hazard scaling factor, Factor B:

#DIV/0!

2.4 Return Period Scaling Factor

Building Importance level (from above):

2

Return Period Scaling factor from Table 3.1, Factor C:

1.00

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2)

Ductility scaling factor: =1 from 1976 onwards; or =k_y, if pre-1976, from Table 3.3:

Ductility Scaling Factor, Factor D:

1.00	1.00
------	------

2.6 Structural Performance Scaling Factor:

Sp:

Structural Performance Scaling Factor Factor E:

#DIV/0!	#DIV/0!
---------	---------

2.7 Baseline %NBS, (NBS)₀ = (%NBS)_{nom} x A x B x C x D x E

%NBS₀:

#DIV/0!	#DIV/0!
---------	---------

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

insignificant	1
---------------	---

3.2. Vertical irregularity, Factor B:

insignificant	1
---------------	---

3.3. Short columns, Factor C:

insignificant	1
---------------	---

3.4. Pounding potential

Pounding effect D1, from Table to right:

Height Difference effect D2, from Table to right:

Therefore, Factor D:

0

3.5. Site Characteristics

insignificant	1
---------------	---

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum

Rationale for choice of F factor, if not 1:

--	--

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

0.00	0.00
------	------

4.3 PAR x (%NBS)₀: PAR x Baseline %NBS:

#DIV/0!	#DIV/0!
---------	---------

4.4 Percentage New Building Standard (%NBS), (before)

#DIV/0!



Aurecon New Zealand Limited

**Level 2, 518 Colombo Street
Christchurch 8011**

PO Box 1061
Christchurch 8140
New Zealand

T +64 3 375 0761

F +64 3 379 6955

E christchurch@aurecongroup.com

W aurecongroup.com

Aurecon offices are located in:

Angola, Australia, Botswana, China,
Ethiopia, Hong Kong, Indonesia,
Lesotho, Libya, Malawi, Mozambique,
Namibia, New Zealand, Nigeria,
Philippines, Singapore, South Africa,
Swaziland, Tanzania, Thailand, Uganda,
United Arab Emirates, Vietnam.