



aurecon

**Bottle Lake Forest - Toilets
Qualitative Engineering Evaluation**

Reference: 228596
Prepared for:
Christchurch City Council

Functional Location ID: PRK_0158_BLDG_012

Revision: 3

Address: 70 Waitikiri Drive

Date: 10 October 2013

Document Control Record

Document prepared by:

Aurecon New Zealand Limited
 Level 2, 518 Colombo Street
 Christchurch 8011
 PO Box 1061
 Christchurch 8140
 New Zealand

T +64 3 375 0761
F +64 3 379 6955
E christchurch@aurecongroup.com
W aurecongroup.com

A person using Aurecon documents or data accepts the risk of:

- Using the documents or data in electronic form without requesting and checking them for accuracy against the original hard copy version.
- Using the documents or data for any purpose not agreed to in writing by Aurecon.

Document control				aurecon		
Report Title		Qualitative Engineering Evaluation				
Functional Location ID		PRK_0158_BLDG_012	Project Number		228596	
File Path		P:\ 228596 - Bottle Lake Forest - Toilets.docx				
Client		Christchurch City Council	Client Contact		Michael Sheffield	
Rev	Date	Revision Details/Status	Prepared	C. Bong	Verifier	Approver
1	4 May 2012	Draft	C. Bong	C. Bong	S. Manning	S. Manning
2	21 December 2012	Final	C. Bong	C. Bong	L. Castillo	L. Castillo
3	10 October 2013	Final	C. Bong	C. Bong	L. Castillo	L. Castillo
Current Revision		3				

Approval			
Author Signature		Approver Signature	
Name	Chris Bong	Name	Luis Castillo
Title	Structural Engineer	Title	Senior Structural Engineer



Contents

Executive Summary	1
1 Introduction	2
1.1 General	2
2 Description of the Building	2
2.1 Building Age and Configuration	2
2.2 Building Structural Systems Vertical and Horizontal	2
2.3 Reference Building Type	2
2.4 Building Foundation System and Soil Conditions	3
2.5 Available Structural Documentation and Inspection Priorities	3
2.6 Available Survey Information	3
3 Structural Investigation	3
3.1 Summary of Building Damage	3
3.2 Record of Intrusive Investigation	3
3.3 Damage Discussion	3
4 Building Review Summary	4
5 Building Strength (Refer to Appendix C for background information)	4
6 Conclusions and Recommendations	4
7 Explanatory Statement	5

Appendices

Appendix A Photos, Site map and Level Survey

Appendix B References

Appendix C Strength Assessment Explanation

Appendix D Background and Legal Framework

Appendix E Standard Reporting Spread Sheet

Executive Summary

This is a summary of the Qualitative Engineering Evaluation for the Bottle Lake Forest - Toilets building and is based on the Detailed Engineering Evaluation Procedure document issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

Building Details	Name	Bottle Lake Forest - Toilets			
Building Location ID	PRK_0158_BLDG_012	Multiple Building Site	Y		
Building Address	70 Waitikiri Drive	No. of residential units	0		
Soil Technical Category	N/A	Importance Level	1	Approximate Year Built	1995
Foot Print (m²)	10	Storeys above ground	1	Storeys below ground	0
Type of Construction	Light weight timber purlins on steel truss roof, partially filled concrete masonry walls, concrete pad				

Qualitative L4 Report Results Summary

Building Occupied	Y	Currently used as a toilet block.
Suitable for Continued Occupancy	Y	Little to no visible damage.
Key Damage Summary	Y	Refer to summary of building damage Section 3.1 report body.
Critical Structural Weaknesses (CSW)	N	No critical structural weaknesses were found.
Levels Survey Results	Y	Levels survey results indicate levels are within allowable limits.
Building %NBS From Analysis	Approx. 100%	Analysis based on assumed approximate building material strengths.

Qualitative L4 Report Recommendations

Geotechnical Survey Required	N	Uncategorised, Technical Category 2 by extrapolation.
Proceed to L5 Quantitative DEE	N	A quantitative DEE is not required for this structure.

Approval

Author Signature		Approver Signature	
Name	Christopher Bong	Name	Luis Castillo
Title	Structural Engineer	Title	Senior Structural Engineer



1 Introduction

1.1 General

On 14 March 2012, Aurecon engineers visited the Bottle Lake Forest - Toilets to conduct a Qualitative Engineering Evaluation on behalf of the Christchurch City Council. Detailed visual inspections were carried out to assess the damage caused by the earthquakes during the 4 September 2010, 22 February 2011, 13 June 2011, 23 December 2011 and their subsequent aftershocks.

The scope of work included:

- Assessment of the nature and extent of the building damage; and
- Visual assessment of the building strength, particularly with respect to the safety of the building occupants, if occupied; and
- Assessment of requirements for detailed engineering evaluation including geotechnical investigation, level survey and any areas where linings and floor coverings need removal to expose structural damage.

This report outlines the results of our qualitative assessment of damage to the Bottle Lake Forest - Toilets and is based on the Detailed Engineering Evaluation Procedure Guidance prepared by the Engineering Advisory Group on 19 July 2011, as well as visual inspections, available structural documentations and summary calculations as appropriate.

2 Description of the Building

2.1 Building Age and Configuration

The Bottle Lake Forest - Toilets is a single storey, concrete masonry wall structure. From the construction drawings, the building was constructed in 1995. The corrugated steel roof is supported on lightweight timber purlins supported by steel trusses made of hot rolled hollow steel sections. The roof sits on reinforced concrete masonry walls founded on a concrete pad.

The floor area of the toilet block is approximately 10 square metres and is classified as an importance level 1 building according to NZS 1170 Part 0: 2002.

2.2 Building Structural Systems Vertical and Horizontal

The load paths in both the vertical and horizontal directions for the toilet block are resisted by the same systems. Tracing the loads from top to bottom, the vertical loads originate from the corrugated steel roof before running through the lightweight timber purlins and hollow section steel trusses. The roof loads are then transferred to the ground by masonry walls and into the concrete pad foundation.

2.3 Reference Building Type

Being a concrete masonry building the Bottle Lake Forest - Toilets is a low ductility structure. Due to rigidity and low ductility buildings of this nature are more prone to seismic damage than light weight timber framed structures. However being a small structure with numerous walls there is the potential to resist loads adequately within the elastic limit and as a consequence experience little damage.



2.4 Building Foundation System and Soil Conditions

The Bottle Lake Forest - Toilets is founded on a reinforced concrete pad foundation. Drawings indicate the foundation structure is likely appropriate for the supported loads from the toilet structure.

The CERA land zone maps indicate that the Bottle Lake Forest - Toilets currently sits on “Yet to be Classified Rural & Unmapped Land”, however the land to the immediate south has been classed as Technical Category 2 Land. Thus by extrapolation, the land has been deemed possibly subject to minor to moderate damage from liquefaction or settlement in future earthquakes or associated aftershocks. The site inspection has shown no obvious ground disturbance or movement in the immediate vicinity of the building.

2.5 Available Structural Documentation and Inspection Priorities

Drawings for the building were available for review after the damage assessment was carried out. The connections and details for the building looked to be of sound design and consistent with site observations.

2.6 Available Survey Information

A levels survey has been carried out and a sketch of the results is attached in appendix B. The results of the survey show that existing floor levels are within acceptable limits.

3 Structural Investigation

3.1 Summary of Building Damage

A detailed visual inspection was undertaken for the interior and exterior of the Bottle Lake Forest - Toilets. There was no visible damage to the roof structure, concrete masonry walls or mortar joints when the interior and exterior of the building was inspected on PRK_0158_BLDG_012.

3.2 Record of Intrusive Investigation

In light of the lack of associated damage to the primary structural elements, an intrusive investigation was neither warranted nor undertaken.

3.3 Damage Discussion

The building has suffered no damage as a result of recent seismic activity. Lack of damage indicates that, due to the presence of sufficient walls in each direction, the Bottle Lake Forest - Toilets was able to respond within its elastic limits.



4 Building Review Summary

All the primary structural elements of the Bottle Lake Forest - Toilets were immediately visible and construction drawings were available. The only area not immediately visible and not able to be inspected was the building foundation. However as there was no slab damage visible and no obvious signs of settlement it was decided that it could be inferred that little damage had occurred in this area.

5 Building Strength (Refer to Appendix C for background information)

The seismic capacity of the structure was estimated from first principals. For the damage assessment, the rough size and geometry of the wall was obtained and the capacity in each direction was calculated based on approximate figures for material strength. The capacity was then compared to the load demand required based on current code.

The findings of this exercise resulted in a demand/capacity ratio expressed in terms of percentage new building strength (%NBS) in excess of 100%. This implies that the building is capable of achieving the strength of a new building as required by current building codes. This is not surprising considering the recent construction of the building.

6 Conclusions and Recommendations

Bottle Lake Forest - Toilets has been assessed as having in excess of 100%NBS and no critical structural weaknesses were found accordingly it is considered acceptable for building to continue to be occupied in a manner similar to current occupancy.

As a levels survey has been carried out and levels have been found to be within acceptable limits no further action or investigations are required at this point.



7 Explanatory Statement

The inspections of the building discussed in this report have been undertaken to assess structural earthquake damage. No analysis has been undertaken to assess the strength of the building or to determine whether or not it complies with the relevant building codes, except to the extent that Aurecon expressly indicates otherwise in the report. Aurecon has not made any assessment of structural stability or building safety in connection with future aftershocks or earthquakes – which have the potential to damage the building and to jeopardise the safety of those either inside or adjacent to the building, except to the extent that Aurecon expressly indicates otherwise in the report.

This report is necessarily limited by the restricted ability to carry out inspections due to potential structural instabilities/safety considerations, and the time available to carry out such inspections. The report does not address defects that are not reasonably discoverable on visual inspection, including defects in inaccessible places and latent defects. Where site inspections were made, they were restricted to external inspections and, where practicable, limited internal visual inspections.

To carry out the structural review, existing building drawings were obtained (where available) from the Christchurch City Council records. We have assumed that the building has been constructed in accordance with the drawings.

While this report may assist the client in assessing whether the building should be repaired, strengthened, or replaced that decision is the sole responsibility of the client.

This review has been prepared by Aurecon at the request of its client and is exclusively for the client's use. It is not possible to make a proper assessment of this review without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to and the assumptions made by Aurecon. The report will not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, Aurecon's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited as set out in the terms of the engagement with the client.

Appendices




Appendix A

Photos, Site Map and Level survey


14 March 2012 – Bottle Lake Forest - Toilets Site Photographs

<p>Front elevation of Bottle Lake Forest Toilets</p>	 A photograph showing the front elevation of a small, white, rectangular building with a corrugated metal roof. The building is surrounded by trees and a metal railing is visible in the foreground.
<p>Side elevation of Bottle Lake Forest Toilets</p>	 A photograph showing the side elevation of the building, highlighting the white wall and the red-painted timber truss structure supporting the roof.
<p>Steel truss to timber purlin connection taken from the interior and exterior of the building</p>	 A close-up photograph showing the connection between a steel truss and a timber purlin, with a corrugated metal roof panel visible below.

Steel truss to timber purlin connection taken from the interior and exterior of the building



Site Layout Plan



3/2/2012 3:59:21 p.m.



REV	DATE	REVISION DETAILS	APPROVAL

DRAWN	DESIGNED
D.HUNIA	C.BONG
CHECKED	
L.CASTILLO	
APPROVED	
	DATE
L.CASTILLO	

PROJECT
BOTTLE LAKE FOREST CHRISTCHURCH
TITLE
TOILET BLOCK FLOOR LEVEL SURVEY

PRELIMINARY NOT FOR CONSTRUCTION	
PROJECT No. 228596	
SCALE 1:50	SIZE A4
DRAWING No. S-01-00	REV

Appendix B

References

1. Department of Building and Housing (DBH), "Revised Guidance on Repairing and Rebuilding Houses Affected by the Canterbury Earthquake Sequence", November 2011
2. New Zealand Society for Earthquake Engineering (NZSEE), "Assessment and Improvement of the Structural Performance of Buildings in Earthquakes", April 2012
3. Standards New Zealand, "AS/NZS 1170 Part 0, Structural Design Actions: General Principles", 2002
4. Standards New Zealand, "AS/NZS 1170 Part 1, Structural Design Actions: Permanent, imposed and other actions", 2002
5. Standards New Zealand, "NZS 1170 Part 5, Structural Design Actions: Earthquake Actions – New Zealand", 2004
6. Standards New Zealand, "NZS 3101 Part 1, The Design of Concrete Structures", 2006
7. Standards New Zealand, "NZS 3404 Part 1, Steel Structures Standard", 1997
8. Standards New Zealand, "NZS 3603, Timber Structures Standard", 1993
9. Standards New Zealand, "NZS 3604, Timber Framed Structures", 2011
10. Standards New Zealand, "NZS 4229, Concrete Masonry Buildings Not Requiring Specific Engineering Design", 1999
11. Standards New Zealand, "NZS 4230, Design of Reinforced Concrete Masonry Structures", 2004

Appendix C

Strength Assessment Explanation

New Building Standard (NBS)

New building standard (NBS) is the term used with reference to the earthquake standard that would apply to a new building of similar type and use if the building was designed to meet the latest design Codes of Practice. If the strength of a building is less than this level, then its strength is expressed as a percentage of NBS.

Earthquake Prone Buildings

A building can be considered to be earthquake prone if its strength is less than one third of the strength to which an equivalent new building would be designed, that is, less than 33%NBS (as defined by the New Zealand Building Act). If the building strength exceeds 33%NBS but is less than 67%NBS the building is considered at risk.

Christchurch City Council Earthquake Prone Building Policy 2010

The Christchurch City Council (CCC) already had in place an Earthquake Prone Building Policy (EPB Policy) requiring all earthquake-prone buildings to be strengthened within a timeframe varying from 15 to 30 years. The level to which the buildings were required to be strengthened was 33%NBS.

As a result of the 4 September 2010 Canterbury earthquake the CCC raised the level that a building was required to be strengthened to from 33% to 67% NBS but qualified this as a target level and noted that the actual strengthening level for each building will be determined in conjunction with the owners on a building-by-building basis. Factors that will be taken into account by the Council in determining the strengthening level include the cost of strengthening, the use to which the building is put, the level of danger posed by the building, and the extent of damage and repair involved.

Irrespective of strengthening level, the threshold level that triggers a requirement to strengthen is 33%NBS.

As part of any building consent application fire and disabled access provisions will need to be assessed.

Christchurch Seismicity

The level of seismicity within the current New Zealand loading code (AS/NZS 1170) is related to the seismic zone factor. The zone factor varies depending on the location of the building within NZ. Prior to the 22nd February 2011 earthquake the zone factor for Christchurch was 0.22. Following the earthquake the seismic zone factor (level of seismicity) in the Christchurch and surrounding areas has been increased to 0.3. This is a 36% increase.

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure C1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

Figure C1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table C1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% probability of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% probability of exceedance in the next year.

Table C1: Relative Risk of Building Failure In A

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Appendix D

Background and Legal Framework

Background

Aurecon has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the building

This report is a Qualitative Assessment of the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

Appendix E

Standard Reporting Spread Sheet

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: <u>Bottle Lake Forest - Toilets</u>	Reviewer: <u>Simon Manning</u>
Building Address: <u>Unit No: Street</u>	CP/Eng No: <u>132053</u>	Company: <u>Aurecon</u>	Company project number: <u>228596</u>
Legal Description: _____	Company phone number: <u>03 375 0761</u>	Date of submission: <u>10/10/2013</u>	Inspection Date: <u>14/03/2012</u>
GPS south: <u>43</u> Degrees <u>28</u> Min <u>57</u> Sec	GPS east: <u>172</u> <u>40</u> <u>52.75</u>	Revision: <u>3</u>	Is there a full report with this summary? <u>yes</u>
Building Unique Identifier (CCC): <u>FRK_0158_BLDG_012</u>			

Site	Site slope: <u>flat</u>	Max retaining height (m): _____
Soil type: <u>mixed</u>	Soil Profile (if available): _____	
Site Class (to NZS1170.5): <u>D</u>	If Ground improvement on site, describe: _____	
Proximity to waterway (m, if <100m): _____		
Proximity to cliff top (m, if <100m): _____		
Proximity to cliff base (m, if <100m): _____	Approx site elevation (m): <u>3.30</u>	

Building	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>3.40</u>
Ground floor split? <u>no</u>	Foundation type: <u>other (describe)</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>2.8</u>	Ground floor elevation above ground (m): <u>0.10</u>
Stores below ground: _____	Building height (m): <u>4.00</u>	Date of design: <u>1992-2004</u>	
Floor footprint area (approx): <u>10</u>	Age of Building (years): <u>10</u>	Strengthening present? <u>no</u>	
Use (ground floor): <u>public</u>	Use (upper floors): <u>toilet block</u>	Importance level (to NZS1170.5): <u>IL1</u>	

Gravity Structure	Gravity System: <u>load bearing walls</u>	truss depth, purlin type and cladding: _____
Roof: <u>steel truss</u>	Floors: <u>concrete flat slab</u>	slab thickness (mm): _____
Beams: <u>none</u>	Columns: <u>load bearing walls</u>	overall depth x width (mm x mm): _____
Walls: <u>partially filled concrete masonry</u>		typical dimensions (mm x mm): _____
		thickness (mm): <u>140</u>

Lateral load resisting structure	Lateral system along: <u>partially filled CMU</u>	Ductility assumed, μ : <u>1.25</u>	Period along: <u>0.40</u>	Total deflection (ULS) (mm): _____	maximum interstorey deflection (ULS) (mm): _____	note total length of wall at ground (m): _____	wall thickness (mm): _____	estimate or calculation? <u>estimated</u>
	Lateral system across: <u>partially filled CMU</u>	Ductility assumed, μ : <u>1.25</u>	Period across: <u>0.40</u>	Total deflection (ULS) (mm): _____	maximum interstorey deflection (ULS) (mm): _____	note total length of wall at ground (m): _____	wall thickness (mm): _____	estimate or calculation? <u>estimated</u>

Separations:	north (mm): _____	east (mm): _____	south (mm): _____	west (mm): _____	leave blank if not relevant
---------------------	-------------------	------------------	-------------------	------------------	-----------------------------

Non-structural elements	Stairs: <u>exposed structure</u>	describe: _____
Wall cladding: <u>Metal</u>	describe: <u>corrugated iron</u>	
Roof Cladding: _____		
Ceilings: _____		
Services (list): _____		

Available documentation	Architectural: <u>none</u>	original designer name/date: <u>Design service unit CCC 1994</u>
Structural: <u>none</u>	original designer name/date: <u>Design service unit CCC 1994</u>	
Mechanical: <u>none</u>	original designer name/date: _____	
Electrical: <u>none</u>	original designer name/date: _____	
Geotech report: <u>none</u>	original designer name/date: _____	

Damage	Site performance: _____	Describe damage: <u>minor - none</u>
Settlement: <u>none observed</u>	notes (if applicable): _____	
Differential settlement: <u>none observed</u>	notes (if applicable): _____	
Liquefaction: <u>none apparent</u>	notes (if applicable): _____	
Differential lateral spread: <u>none apparent</u>	notes (if applicable): _____	
Ground cracks: <u>none apparent</u>	notes (if applicable): _____	
Damage to area: <u>none apparent</u>	notes (if applicable): _____	

Building:	Current Placard Status: <u>green</u>	
Along	Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: _____
Across	Damage ratio: <u>0%</u>	$Damage_Ratio = \frac{(\%NBS\ before) - (\%NBS\ after)}{\%NBS\ before}$
Diaphragms	Damage?: <u>no</u>	Describe: _____
CSWs:	Damage?: <u>no</u>	Describe: _____
Pounding:	Damage?: <u>no</u>	Describe: _____
Non-structural:	Damage?: <u>no</u>	Describe: _____

Recommendations	Level of repair/strengthening required: <u>minor non-structural</u>	Describe: _____
Building Consent required: <u>no</u>	Interim occupancy recommendations: <u>full occupancy</u>	Describe: _____
Along	Assessed %NBS before: <u>100%</u>	Assessed %NBS after: <u>100%</u>
Across	Assessed %NBS before: <u>100%</u>	Assessed %NBS after: <u>100%</u>

IEP	Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.
Period of design of building (from above): <u>1992-2004</u>	h_n from above: <u>2.8m</u>
Seismic Zone, if designed between 1965 and 1992: <u>B</u>	Design Soil type from NZS4203:1992, cl 4.6.2.2: _____
Period (from above): <u>0.4</u>	along: _____
(%NBS)nom from Fig 3.3:	across: <u>0.4</u>
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0	
Note 2: for RC buildings designed between 1976-1984, use 1.2	
Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)	
Final (%NBS)nom:	along: <u>0%</u>
	across: <u>0%</u>

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

Near Fault scaling factor (1/N(T,D), Factor A: along across
#DIV/0! #DIV/0!

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:
Z₁₉₉₂, from NZS4203:1992
Hazard scaling factor, Factor B: #DIV/0!

2.4 Return Period Scaling Factor

Building Importance level (from above): 1
Return Period Scaling factor from Table 3.1, Factor C:

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2) along across
Ductility scaling factor: =1 from 1976 onwards; or =k_μ, if pre-1976, from Table 3.3:

Ductility Scaling Factor, Factor D: 1.00 1.00

2.6 Structural Performance Scaling Factor:

Sp:
Structural Performance Scaling Factor Factor E: #DIV/0! #DIV/0!

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS_b: #DIV/0! #DIV/0!

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A: insignificant 1

3.2. Vertical irregularity, Factor B: insignificant 1

3.3. Short columns, Factor C: insignificant 1

3.4. Pounding potential
Pounding effect D1, from Table to right:
Height Difference effect D2, from Table to right:

Therefore, Factor D: 0

3.5. Site Characteristics insignificant 1

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	0.7	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	0.4	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum
Rationale for choice of F factor, if not 1:

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

0.00 0.00

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS: #DIV/0! #DIV/0!

4.4 Percentage New Building Standard (%NBS), (before)

#DIV/0!



Aurecon New Zealand Limited

**Level 2, 518 Colombo Street
Christchurch 8011**

PO Box 1061
Christchurch 8140
New Zealand

T +64 3 375 0761

F +64 3 379 6955

E christchurch@aurecongroup.com

W aurecongroup.com

Aurecon offices are located in:

Angola, Australia, Botswana, China,
Ethiopia, Hong Kong, Indonesia,
Lesotho, Libya, Malawi, Mozambique,
Namibia, New Zealand, Nigeria,
Philippines, Singapore, South Africa,
Swaziland, Tanzania, Thailand, Uganda,
United Arab Emirates, Vietnam.