

Christchurch City Council

**Briggs Row
Housing Complex
PRO 3519**

**Detailed Engineering Evaluation
Quantitative Assessment Report**



Christchurch City Council

Briggs Row Housing Complex

Quantitative Assessment Report

31 Winchester Street, Lyttelton,


Revision History

Revision No.	Prepared By	Description	Date
1	AS	Final V1	28/03/2014
2	LMH	Draft V2 – Following Strengthening	16/11/2015
3	SPT	Final V3 – Following Strengthening	21/12/2015


Prepared By
Andrew Sawers
Building Technologist

Opus International Consultants Ltd
Christchurch Office

20 Moorhouse Avenue
PO Box 1482, Christchurch Mail
Centre, Christchurch 8140
New Zealand


Reviewed By
Lachlan Howat
Structural Engineer

Telephone: +64 3 363 5400
Facsimile: +64 3 365 7858

Date: December 2015
Reference: 6-QC319.00
Status: Final V3


Approved By
Mary Ann Halliday
Senior Structural Engineer

Christchurch City Council

Briggs Row Housing Complex

Quantitative Assessment Report

31 Winchester Street, Lyttelton,



Summary

Briggs Row Housing Complex
PRO 3519

Detailed Engineering Evaluation
Quantitative Report - Summary
Final V3

Background

This is a summary of the quantitative report for the Briggs Row Housing Complex, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This assessment covers the 4 residential units on the site.

Key Damage Observed

The residential units suffered minor damage to non-structural elements. This included cracking of the interior wall and ceiling linings. Structural damage to the residential units was generally minor. This damage was deemed low enough to not affect the capacities of the buildings.

Level Survey

All floor slopes assessed in a laser level survey. All were less than the 5mm/m limitation set out in the MBIE guidelines [6].

Internal Lining Nail Spacings

The internal lining nail spacings were measured on site to vary between 200-300mm.

Critical Structural Weaknesses

No critical structural weaknesses were found in any of the buildings.

Indicative Building Strength

Table A: Summary of Seismic Performance by Blocks

Block	%NBS (Prior to Strengthening)	%NBS (Following Strengthening)	Indicative Floor Levels	Nail Spacings
PRO 3519 B001 (Block A)	35%	100%	Pass	Pass

The residential units have capacities of 100% NBS (as a result of the structural strengthening scheme outlined below) and are limited by the in-plane shear capacity of the lined timber-framed shear walls.

Original Recommendations

It is recommended that;

1. Structural schemes be developed such that the seismic capacity of the subfloor is increased to more than 67% of NBS.
2. Cosmetic repairs be undertaken as required.
3. Remove construction material from subfloor space.

Remediation and Structural Strengthening

On the 16th of December 2014 building consent exemption BCN/2014/12204 for “Strengthening work to Briggs row housing units - Addition of sub-floor bracing” was accepted by Christchurch City Council and issued by Opus to the Christchurch City Council Social Housing Unit to repair the damage sustained in the Canterbury Earthquake sequence. This plan addressed the recommendations in the following way:-

1. A strengthening works scheme was developed with works completed in July 2015 increasing the seismic capacity of the subfloor bracing to 100% NBS.
2. Cosmetic repairs were completed as part of the strengthening works.
3. Construction material was removed from around the new bracing during the repairs.

The strengthening included adding new anchor piles and plywood linings to increase the seismic capacity of the subfloor. This work has been completed as of July 2015 and increases the capacity of the structure to 100%NBS.

The repair and strengthening works met all recommendations in the Detailed Engineering Evaluation report of March 2014.

Contents

Summary	i
1 Introduction.....	1
2 Compliance	1
3 Earthquake Resistance Standards.....	5
4 Background Information	7
5 Original Damage	11
6 Detailed Seismic Assessment	12
7 Geotechnical Summary	16
8 Conclusions.....	16
9 Original Recommendations (March 2014).....	16
10 Remediation and Structural Strengthening.....	16
11 Limitations.....	17
12 References	17

Appendix A – Photographs

Appendix B – Strengthening Photographs

Appendix C - Methodology and Assumptions

Appendix D - Updated CERA DEE Spreadsheet

Appendix E – Strengthening Scheme

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Briggs Row Housing Complex, located at 31 Winchester Street, Lyttelton, following the Canterbury earthquake sequence since September 2010. The site was visited by Opus International Consultants on 12 November 2013 and the subfloors were re-inspected on 24 March 2014.

The purpose of the assessment is to determine if the buildings in the village are classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [2] [3] [4] [5].

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in October 2011 following the Darfield Earthquake on 4 September 2010.

The policy includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure, was amended to include increased seismic design requirements for Canterbury as follows:

- Increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use). This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines [2]

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the MBIE guidance document dated December 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority.

4 Background Information

4.1 Building Descriptions

The site contains 4 residential units which were constructed in 1968. A site plan showing the location of the units, numbered 1 to 4, is shown in Figure 2. Figure 3 shows the location of the site in Christchurch City and Figure 4 shows the location within the Lyttelton area. The units are grouped together to form a block of four units.



Figure 2: Site plan of Briggs Row Housing Complex.




Figure 3: Location of Briggs Row (circled) relative to Christchurch City CBD (Source: Google Earth).




Figure 4 - Location of Briggs Row in Lyttelton.

The residential units are timber-framed buildings with diagonal timber braces. The roof structure comprises of timber roof framing supporting lightweight metal roofing. The walls and ceilings are lined with plasterboard. External walls are clad with lightweight timber weatherboards. Foundations consist of ordinary concrete piles with timber jack studs. There is a concrete perimeter wall on the east and south sides. There is a large subfloor on the west side which is covered by plywood panels. The original chimneys have been removed although the shape of these is still evident on the outsides of Units 1 and 4. The roofs of Units 2, 3, and 4 are mono slope while the roof of Unit 1 is pitched.

The units are separated by 190mm thick concrete block work fire walls which are reinforced to the perimeter.

There is minimal longitudinal subfloor bracing in the units. The plywood which currently forms the barrier to the subfloor is not properly framed and does not adequately transfer loads to the foundations. There is currently no strip footing for the loads to transfer to.

During the subfloor inspection it was noted that several members were rotted and cracking. There were large piles of soil, bricks and other construction debris under the units and in some cases these meant the concrete (structural) piles could not be inspected. These piles of material have buried some timber members which will now be more prone to rotting.

Figure 5 shows a typical floor plan of a residential unit produced from site measurements by Opus. Figure 6 shows a typical cross section, taken from original documentation. The roof is that of Unit 1.




Figure 5: Typical partial floor plan of residential unit blocks.




Figure 6: Typical cross-section of Briggs Row.

4.2 Survey

4.2.1 Post 22 February 2011 Rapid Assessment

A structural (Level 2) assessment of the buildings/property was undertaken on 3 March 2011 by Opus International Consultants.

4.2.2 Level Survey

A full level survey was not deemed to be necessary at Briggs Row as it is located in a Port Hills zone. Properties in Port Hill zones suffered nil damage due to liquefaction and/or settlement but are potentially at risk of rock fall, cliff collapse and land slips. In lieu of a full level survey, a laser level was placed in each unit so that differentials in vertical levels could be measured at the extreme ends of the unit. These values could then be used to determine the floor slope of the entire unit. For this site, all floor slopes were less than the 5mm/m limitation imposed by MBIE guidelines.

Table 2: Summary of the Level Survey

Block	Unit No.	Comment	Maximum Fall*
A	1	Pass	-
	2	Pass	-
	3	Pass	-
	4	Pass	-

* Values are only recorded if greater than 5mm/m

4.2.3 Nail Spacings

The internal lining nail spacings were measured on site to vary between 200-300mm.

4.3 Original Documentation

The following documentation was provided by the Christchurch City Council:

- 750/14 – Lyttelton Borough Council – Pensioners Cottages – p. 1/1 – Elevations, plans, cross-sections, details, perspective view – 1969
- Proposed alterations – Briggs Row Units – Peter Dunbar Architectural Designer – 23/6/2009 Resource Consent RMA 92014024/1

In addition, a typical floor plan has been produced by Opus to help confirm as-built measurements.

Copies of the design calculations were not provided.

5 Original Damage

This section outlines the damage to the buildings that was observed during site visits. It is not intended to be a complete summary of the damage sustained by the buildings due to the earthquakes. Some forms of damage may not be able to be identified with a visual inspection only.

It is noticeable that none of the residential units have suffered any significant damage.

Note: Any photo referenced in this section can be found in Appendix A.

5.1 Residual Displacements

The results of the level survey indicate that no significant ground settlement has occurred in the units due to the earthquakes.

5.2 Foundations

Foundation damage was limited to a small area of spalling in the concrete foundation perimeter footing on the corner of Unit 4 (photo 9).

5.3 Primary Gravity Structure

No damage was evident in the timber framing or roof structure.

5.4 Primary Lateral-Resistance Structure

Some stepped cracking was observed on the face of the block work fire wall of Unit 3. No damage was observed in any other units.

5.5 Non Structural Elements

Minimal cracking of plasterboard ceiling diaphragms and wall linings was observed in the units (photo 10). This form of damage is common throughout the units. Cracked external weatherboards were also observed on some faces (photo 11).

5.6 General Observations

The buildings appeared to have performed reasonably well, as would be expected for buildings of this type, during the earthquakes. They have suffered distributed amounts of minor damage which is typical of the construction type and age of construction.

6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

As the residential units have the same floor plan, the analysis was simplified by conducting the analysis of one multi-unit block with similar cladding and using this for all multi-unit blocks.

6.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSWs were identified in the buildings.

6.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix B. A brief summary follows:

Hand calculations were performed to determine seismic forces from the current building codes. These forces were applied globally to the structure and the capacities of the walls were calculated and used to estimate the %NBS. The walls, highlighted in Figure 7 and Figure 8, were used for bracing in their respective directions.




Figure 7: Walls used for bracing in the longitudinal direction.




Figure 8: Walls used for bracing in the transverse direction.

6.3 Limitations and Assumptions in Results

The observed level of damage suffered by the buildings was deemed low enough to not affect their capacity. Therefore the analysis and assessment of the buildings was based on them being in an undamaged state. There may have been damage to the buildings that was unable to be observed that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections.
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.
- Construction is consistent with normal practise of the era in which constructed.

6.4 Assessment

A summary of the structural performance of the buildings is shown in Table 3 (which has now been superseded by Table 4). Note that the values given represent the worst performing elements in the building, where these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

Table 3: Summary of Seismic Performance prior to Structural Strengthening (Superseded)

Building Description	Critical element	% NBS based on calculated capacity in longitudinal direction	% NBS based on calculated capacity in transverse direction.
Block A	In plane bracing walls	100%	100%
	Sub Floor Bracing	35%	100%

Table 4: Summary of Seismic Performance following Structural Strengthening

Building Description	Critical element	% NBS based on calculated capacity in longitudinal direction	% NBS based on calculated capacity in transverse direction.
Block A	In plane bracing walls	100%	100%
	Sub Floor Bracing	100%	100%

7 Geotechnical Summary

CERA indicates that Briggs Row is located in a Port Hills zone (as shown in Figure 9). This classification suggests there is a low geological hazard risk due to rock fall, cliff collapse and land movement.



Figure 9: CERA Technical Categories map (loc. starred).

There is no evidence to suggest that further geotechnical investigation is warranted for this site.

8 Conclusions

- The residential units have a capacity of 100% NBS, as limited by the in-plane shear capacity of the lined shear walls. They are deemed to be a ‘low risk’ in a design seismic event according to NZSEE guidelines.

9 Original Recommendations (March 2014)

It is recommended that;

1. Structural schemes be developed such that the seismic capacity of the subfloor is increased to more than 67% of NBS.
2. Cosmetic repairs be undertaken as required.
3. Remove construction material from subfloor space.

10 Remediation and Structural Strengthening

On the 16th of December 2014 building consent exemption BCN/2014/12204 for “Strengthening work to Briggs row housing units - Addition of sub-floor bracing” was accepted by Christchurch City Council and issued by Opus to the Christchurch City Council Social Housing Unit to repair the damage sustained in the Canterbury Earthquake sequence. This plan addressed the recommendations in the following way:-

1. A strengthening works scheme was developed with works completed in July 2015 increasing the seismic capacity of the subfloor bracing to 100% NBS.
2. Cosmetic repairs were completed as part of the strengthening works.
3. Construction material was removed from around the new bracing during the repairs.

The strengthening included adding new anchor piles and plywood linings to increase the seismic capacity of the subfloor. This work has been completed as of July 2015 and increases the capacity of the structure to 100%NBS.

The repair and strengthening works met all recommendations in the Detailed Engineering Evaluation report of March 2014.

11 Limitations

- This report is based on an inspection of the buildings and focuses on the structural damage resulting from the Canterbury Earthquake sequence since September 2010. Some non-structural damage may be described but this is not intended to be a complete list of damage to non-structural items.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- This report is prepared for the Christchurch City Council to assist in the assessment of any remedial works required for the Briggs Row Housing Complex. It is not intended for any other party or purpose.

12 References

- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] MBIE (2012), Repairing and rebuilding houses affected by the Canterbury earthquakes, Ministry of Building, Innovation and Employment, December 2012.

Appendix A – Original Report Photographs

Briggs Row Housing Complex – Detailed Engineering Evaluation


Briggs Row Housing Complex		
No.	Item description	Photo
Residential Units Layout		
1.	Site view	
2.	Typical exterior elevation (end)	

Briggs Row Housing Complex – Detailed Engineering Evaluation

<p>3.</p>	<p>Typical exterior elevation (front)</p>	
<p>4.</p>	<p>Typical unit exterior elevation (front)</p>	
<p>5.</p>	<p>Typical exterior elevation (back)</p>	


<p>6.</p>	<p>Typical floor void</p>	 A photograph showing the interior of a floor void. The structure consists of wooden joists supported by vertical wooden posts. A brick wall is visible on the right side, with the number '1970' painted on it. The floor is covered with a layer of insulation and some debris.
<p>7.</p>	<p>Typical internal lining nail spacings (300mm)</p>	 A photograph showing a person's hand holding a yellow measuring tape against a white internal lining wall. The tape is held vertically, and the person's hand is positioned at the top of the tape. The wall has several vertical lines, likely indicating the nail spacings. The person's hair and a blue brush are visible in the foreground.

Briggs Row Housing Complex – Detailed Engineering Evaluation

<p>8.</p>	<p>Typical unit living area</p>	
<p>9.</p>	<p>Spalling of concrete on perimeter footing</p>	
<p>10.</p>	<p>Typical cracking of wall lining</p>	

Briggs Row Housing Complex – Detailed Engineering Evaluation

11.	Cracked weatherboard	
12.	Typical sub floor jack stud	

<p>13.</p>	<p>Tall, concrete piles 800mm proud of ground level.</p>	
<p>14.</p>	<p>Typical subfloor framing.</p>	

Appendix B – Strengthening Scheme Photographs

Briggs Row Housing Complex – Detailed Engineering Evaluation

Briggs Row Housing Complex Strengthening		
No.	Item description	Photo
Strengthening		
1.	External View of Completed Bracing.	
2.	External View of Completed Bracing.	

Briggs Row Housing Complex – Detailed Engineering Evaluation

<p>3.</p>	<p>Internal View of Completed Bracing to unit 3.</p>	 An interior photograph showing a large, light-colored wooden panel, likely a bracing element, installed against a wall. The panel has a natural wood grain and shows some staining. To the right, a white cable runs vertically. The ceiling above shows wooden joists and insulation.
<p>4.</p>	<p>External View of Completed Bracing to Unit 3/4.</p>	 An exterior photograph of a building's corner. A white, vertical bracing element is visible, supporting a balcony or walkway with a white railing. The wall is light-colored with vertical siding. A small tree and some landscaping are in the foreground.
<p>5.</p>	<p>Adequate Nail spacing provided to new bracing elements.</p>	 A close-up photograph of a white wall where a wooden bracing element is attached. A yellow folding ruler is placed horizontally against the wall to measure the spacing between nails. The ruler shows markings in inches and centimeters, indicating the nail spacing is consistent.

Briggs Row Housing Complex – Detailed Engineering Evaluation

<p>6.</p>	<p>Connections of New Framing to existing foundation walls.</p>	
<p>7.</p>	<p>Connections of New Framing to existing foundation walls and flooring.</p>	

8.	Anchor Pile Connection	 A photograph showing a close-up of a structural connection. A vertical wooden beam, possibly a pile or post, is secured to a horizontal wooden beam. A square metal plate is bolted to the vertical beam, with the bolt passing through the horizontal beam. The surrounding area includes other wooden framing and white insulation material.
----	------------------------	--

Appendix C - Methodology and Assumptions

Seismic Parameters

As per NZS 1170.5:

- $T < 0.4s$ (assumed)
- Soil: Category D
- $Z = 0.3$
- $R = 1.0$ (IL2, 50 year)
- $N(T,D) = 1.0$

For the analyses, a μ of 2 was assumed for the residential units.

Analysis Procedure

As the units are small and have a number of closely spaced walls in both directions, the fibrous plaster board ceilings are assumed to be capable of transferring loads to all walls. It was therefore assumed that a global method could be used to carry the forces down to ground level in each direction. Bracing capacities were found by assuming a certain kN/m rating for the walls along each line. Due to the relatively unknown nature of the walls, the kN/m rating was taken as 3 kN/m for all timber walls with an aspect ratio (height: length) of less than 2:1. This was scaled down to zero kN/m at an aspect ratio of 3.5:1 as per NZSEE guidelines. %NBS values were then found through the ratio of bracing demand to bracing capacity for all walls in each direction.

Additional Assumptions

Further assumptions about the seismic performance of the buildings were:

- Connections between all elements of the lateral load resisting systems are detailed to adequately transfer their loads sufficiently and are strong enough so as to not fail before the lateral load resisting elements.

Appendix D – Updated CERA DEE Spreadsheet

Location		Building Name: <input type="text" value="Briggs Row Housing Complex"/>	Unit No: <input type="text" value="31"/>	Street: <input type="text" value="Winchester Street, Lyttelton"/>	Reviewer: <input type="text" value="Mary Ann Halliday"/>
Building Address: <input type="text" value="31 Winchester Street, Lyttelton"/>		Legal Description: <input type="text" value=""/>			CPEng No: <input type="text" value="67073"/>
GPS south: <input type="text" value="43 36 4.90"/>		GPS east: <input type="text" value="172 43 12.15"/>			Company: <input type="text" value="Opus International Consultants"/>
Building Unique Identifier (CCC): <input type="text" value="PRO3519"/>		Company project number: <input type="text" value="6-QC319.00"/>			Company phone number: <input type="text" value="03-363-5400"/>
		Date of submission: <input type="text" value="16-Nov-15"/>			Inspection Date: <input type="text" value="12/11/2013"/>
		Revision: <input type="text" value="1"/>			Is there a full report with this summary? <input type="text" value="yes"/>

Site	Site slope: <input type="text" value="slope >1 in 5"/>	Max retaining height (m): <input type="text" value=""/>
Soil type: <input type="text" value=""/>	Soil Profile (if available): <input type="text" value=""/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>	If Ground improvement on site, describe: <input type="text" value=""/>	
Proximity to waterway (m, if <100m): <input type="text" value=""/>	Approx site elevation (m): <input type="text" value=""/>	
Proximity to clifftop (m, if <100m): <input type="text" value=""/>		
Proximity to cliff base (m, if <100m): <input type="text" value=""/>		

Building	No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value=""/>
Ground floor split? <input type="text" value="yes"/>	Storeys below ground: <input type="text" value="0"/>		Ground floor elevation above ground (m): <input type="text" value=""/>
Foundation type: <input type="text" value="timber piles"/>	Building height (m): <input type="text" value="3.00"/>	if Foundation type is other, describe: <input type="text" value=""/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value=""/>
Floor footprint area (approx): <input type="text" value="152"/>	Age of Building (years): <input type="text" value="45"/>	Date of design: <input type="text" value="1965-1976"/>	
Strengthening present? <input type="text" value="no"/>	Use (ground floor): <input type="text" value="multi-unit residential"/>	If so, when (year)? <input type="text" value=""/>	And what load level (%g)? <input type="text" value=""/>
Use (upper floors): <input type="text" value=""/>	Use notes (if required): <input type="text" value=""/>	Brief strengthening description: <input type="text" value=""/>	
Importance level (to NZS1170.5): <input type="text" value="IL2"/>			

Gravity Structure	Gravity System: <input type="text" value="frame system"/>	rafter type, purlin type and cladding: <input type="text" value=""/>
Roof: <input type="text" value="timber framed"/>	Floors: <input type="text" value="timber"/>	joist depth and spacing (mm): <input type="text" value=""/>
Beams: <input type="text" value="none"/>	Columns: <input type="text" value="timber"/>	overall depth x width (mm x mm): <input type="text" value=""/>
Walls: <input type="text" value="non-load bearing"/>		typical dimensions (mm x mm): <input type="text" value="0"/>

Lateral load resisting structure	Lateral system along: <input type="text" value="lightweight timber framed walls"/>	Note: Define along and across in detailed report!	note typical wall length (m): <input type="text" value=""/>
Ductility assumed, μ: <input type="text" value="2.00"/>	0.00		estimate or calculation? <input type="text" value="estimated"/>
Period along: <input type="text" value="0.10"/>			estimate or calculation? <input type="text" value=""/>
Total deflection (ULS) (mm): <input type="text" value=""/>			estimate or calculation? <input type="text" value=""/>
maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>			
Lateral system across: <input type="text" value="lightweight timber framed walls"/>			note typical wall length (m): <input type="text" value=""/>
Ductility assumed, μ: <input type="text" value="2.00"/>	0.00		estimate or calculation? <input type="text" value="estimated"/>
Period across: <input type="text" value="0.10"/>			estimate or calculation? <input type="text" value=""/>
Total deflection (ULS) (mm): <input type="text" value=""/>			estimate or calculation? <input type="text" value=""/>
maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>			

Separations:	north (mm): <input type="text" value=""/>	leave blank if not relevant
east (mm): <input type="text" value=""/>		
south (mm): <input type="text" value=""/>		
west (mm): <input type="text" value=""/>		

Non-structural elements	Stairs: <input type="text" value=""/>	describe: <input type="text" value="weatherboard"/>
Wall cladding: <input type="text" value="other light"/>	Roof Cladding: <input type="text" value="Metal"/>	describe: <input type="text" value="corrugated iron"/>
Glazing: <input type="text" value="timber frames"/>	Ceilings: <input type="text" value="strapped or direct fixed"/>	
Services(list): <input type="text" value=""/>		

Available documentation	Architectural: <input type="text" value="full"/>	original designer name/date: <input type="text" value="Paul Pascoe and Linton Architects/1969"/>
Structural: <input type="text" value="partial"/>	Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
Electrical: <input type="text" value="none"/>	Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
		original designer name/date: <input type="text" value=""/>

Damage Site: (refer DEE Table 4-2)	Site performance: <input type="text" value="Good"/>	Describe damage: <input type="text" value=""/>
Settlement: <input type="text" value="none observed"/>	Differential settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text" value=""/>
Liquefaction: <input type="text" value="none apparent"/>	Lateral Spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
Differential lateral spread: <input type="text" value="none apparent"/>	Ground cracks: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
Damage to area: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text" value=""/>

Building:	Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio: <input type="text" value="0%"/>	Describe how damage ratio arrived at: <input type="text" value=""/>
Across	Damage ratio: <input type="text" value="0%"/>	
Diaphragms	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>
Non-structural:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

Recommendations	Level of repair/strengthening required: <input type="text" value="none"/>	Describe: <input type="text" value=""/>
Building Consent required: <input type="text" value="no"/>	Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text" value=""/>
Along	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	Assessed %NBS after e'quakes: <input type="text" value="100%"/>
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	Assessed %NBS after e'quakes: <input type="text" value="100%"/>

%NBS from IEP below
If IEP not used, please detail assessment methodology:

Appendix E – Strengthening Scheme



Building Code Clause(s) B1 & B2.....

PRODUCER STATEMENT – PS1 – DESIGN

(Guidance notes on the use of this form are printed on page 2)

ISSUED BY: Opus International Consultants.....
(Design Firm)

TO: Christchurch City Council
(Owner/Developer)

TO BE SUPPLIED TO: Christchurch City Council
(Building Consent Authority)

IN RESPECT OF: Superstructure Bracing.....
(Description of Building Work)

AT: Briggs Courts Housing Complex, 31 Winchester Street,
Lyttleton.....
(Address)
..... LOT...Lot 1... DP ...27071 SO

We have been engaged by the owner/developer referred to above to provide To provide a permanent strengthening scheme to 100%NBS. services in respect of the requirements of
(Extent of Engagement)

Clause(s) B1 and B2.....of the Building Code for
All or Part only (as specified in the attachment to this statement), of the proposed building work.

The design carried out by us has been prepared in accordance with:

- Compliance Documents issued by the Ministry of Business, Innovation & Employment B1 & B2, NZS3604.... or
(verification method / acceptable solution)
- Alternative solution as per the attached schedule.....

The proposed building work covered by this producer statement is described on the drawings titled Briggs Row Subfloor strengthening plan.

and numbered N/A.....;
together with the specification, and other documents set out in the schedule attached to this statement.

On behalf of the Design Firm, and subject to:

- (i) Site verification of the following design assumptions ... Existing structure is built as per drawings and good practice at the time. ✓
- (ii) All proprietary products meeting their performance specification requirements;

I believe on reasonable grounds that a) the building, if constructed in accordance with the drawings, specifications, and other documents provided or listed in the attached schedule, will comply with the relevant provisions of the Building Code and that b), the persons who have undertaken the design have the necessary competency to do so. I also recommend the following level of construction monitoring/observation:

CM1 CM2 CM3 CM4 CM5 (Engineering Categories) OR as per agreement with owner/developer (Architectural)

I, Mary Ann Halliday..... am: CPEng 67073.....#
(Name of Design Professional) Reg Arch#

I am a Member of: IPENZ NZIA and hold the following qualifications: CPEng, ME (Civil).....
The Design Firm Issuing this statement holds a current policy of Professional Indemnity Insurance no less than \$200,000*.

The Design Firm is a member of ACENZ:

SIGNED BY Mary Ann Halliday ON BEHALF OF Opus International Consultants
(Design Firm)

Date 31/10/2014..... (signature) *M. Halliday*

Note: This statement shall only be relied upon by the Building Consent Authority named above. Liability under this statement accrues to the Design Firm only. The total maximum amount of damages payable arising from this statement and all other statements provided to the Building Consent Authority in relation to this building work, whether in contract, tort or otherwise (including negligence), is limited to the sum of \$200,000*.



This form is to accompany **Form 2 of the Building (Forms) Regulations 2004** for the application of a Building Consent.

THIS FORM AND ITS CONDITIONS ARE COPYRIGHT TO ACENZ, IPENZ AND NZIA

CALCULATION SHEET

Project/Task/File No: BRILCS ROW


Sheet No 1 of

Project Description: SUBFLOOR STRENGTHENING


Office:

Computed: 29/5/14

Check: / /



PLAN



PLAN - 1 UNIT

CALCULATION SHEET

Project/Task/File No: BRIGGS ROW


Sheet No _____ of _____

Project Description: ANCHOR PILE CONNECTION

Office: _____

Computed: MJP 4/6/14


Check: / /



ANCHOR PILE BEARER / JOIST CONNECTION

- LOOKING EAST

BRIGGS ROW - TYPICAL SUBFLOOR STRENGTHENING



- ECOPLY FASTENERS
- 300mm CENTRES FOR INTERMEDIATE STUDS
 - 150mm CENTRES AROUND THE PERIMETER
 - 50x2.8mm STAINLESS STEEL FLATHEAD NAILS

CALCULATION SHEET

Project/Task/File No:

Briggs Row Remedial Detail

Sheet No

1

of

1

Project Description:

For units where concrete paths impede nailing for plywood.

Office:


CHK LMK

Computed:

5 / 6 / 15

Check:

1 / 1



FORM OF PRODUCER STATEMENT PS3 – CONSTRUCTION

At project completion, this form shall be completed by the building contractor and supplied to the Engineer.

ISSUED BY: CORBEL CONSTRUCTION.....
(Building Contractor)

TO: CHRISTCHURCH CITY COUNCIL.....
(Owner/Principal)

IN RESPECT OF: SUB-FLOOR STRENGTHENING WORKS.....
(Description of Contract Works)

AT: 31 WINCHESTER STREET, LYTTTELTON
(Address)

T/A: CHRISTCHURCH CITY COUNCIL..... **BUILDING CONSENT No: BCN/2014/12204**...
(Territorial Authority / Building Consent Authority)

The above Building Contractor has contracted to the above Owner/Principal to carry out and complete certain building works in accordance with the contract, titled

PRO3519 Briggs Row Strengthening and Repairs – Contract # 4600001353/026..... (“the contract”)
(Title of building contract)

I James French..... a duly authorised representative of the
(Builder’s Authorised Agent)

above building contractor, believe on reasonable grounds that the above building contractor has carried out and completed

All Part only as specified in the attached particulars

of the building works in accordance with the contract.



.....
(Signature of Authorised Agent on behalf of the Building Contractor)

26/11/2015.....
(Date)

213 Lichfield Street.....

Christchurch.....
(Address)

This producer statement is confirmation by the builder(s) that they have carried out the building work in accordance with the drawings, specifications (and site amendments) that are part of the contract / building consent documents.

Work covered by this statement should have been supervised and checked by suitably qualified tradespersons.

The Engineer requires this producer statement and a copy of the T/A’s building consent conditions, to confirm that items of the contract that he has not personally examined, have in fact been built according to the documents, so that the Engineer may issue appropriate documents to the T/A for it to release the Code Compliance Certificate.



PRODUCER STATEMENT – PS4 – CONSTRUCTION REVIEW

(Guidance notes on the use of this form are printed on page 2)

ISSUED BY: Opus International Consultants Ltd
(Construction Review Firm)

TO: Christchurch City Council
(Owner/Developer)

TO BE SUPPLIED TO: Christchurch City Council
(Building Consent Authority)

IN RESPECT OF: Subfloor Bracing
(Description of Building Work)

AT: Briggs Row Housing Complex, 31 Winchester Street, Lyttleton
(Address)
..... LOT DP SO

..... has been engaged by
(Construction Review Firm)

To provide CM1 CM2 CM3 CM4 CM5 (Engineering Categories) or observation as per agreement with owner/developer
or other services

..... (Extent of Engagement)
in respect of clause(s) B1 and B2 of the Building Code for the building work described in

documents relating to Building Consent No. BCN / 2014 / 122204
and those relating to

Building Consent Amendment(s) Nos. issued during the
course of the works. We have sighted these Building Consents and the conditions of attached to them.

Authorised instructions / variations(s) No. Remedial detail, dated 5/6/2015..... (copies attached)
or by the attached Schedule have been issued during the course of the works.

On the basis of this these review(s) and information supplied by the contractor during the course of the works and
on behalf of the firm undertaking this Construction Review, I believe on reasonable grounds that All Part only of
the building works have been completed in accordance with the relevant requirements of the Building Consent and Building
Consent Amendments identified above, with respect to Clause(s) B1 and B2 of the Building Code.

I also believe on reasonable grounds that the persons who have undertaken this construction review have the necessary
competency to do so.

I, Mary Ann Halliday am: CPEng No. 67073
(Name of Construction Review Professional) Reg Arch No.

I am a Member of : IPENZ NZIA and hold the following qualifications: ME(Civil), CPEng

The Construction Review Firm issuing this statement holds a current policy of Professional Indemnity Insurance no less
than \$200,000*.

The Construction Review Firm is a member of ACENZ :

SIGNED BY Mary Ann Halliday ON BEHALF OF Opus International Consultants Ltd

Date: 21 / 12 / 2015..... Signature:.....

Note: This statement shall only be relied upon by the Building Consent Authority named above. Liability under this statement accrues to the
Design Firm only. The total maximum amount of damages payable arising from this statement and all other statements provided to the Building
Consent Authority in relation to this building work, whether in contract, tort or otherwise (including negligence), is limited to the sum of
\$200,000*.

This form is to accompany Forms 6 or 8 of the Building (Form) Regulations 2004 for the issue of a Code Compliance
Certificate.



Opus International Consultants Ltd
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400
f: +64 3 365 7858
w: www.opus.co.nz