

*Christchurch City Council*

**Clent Lane  
Housing Complex  
PRO 1091**

**Detailed Engineering Evaluation  
Quantitative Assessment Report**





*Christchurch City Council*


---

# Clent Lane Housing Complex

## Quantitative Assessment Report

**32 Cobham Street, Spreydon,**

Prepared By

  
-----  
Claire Ford

Engineering Assistant

Opus International Consultants Ltd

Christchurch Office


20 Moorhouse Avenue

PO Box 1482, Christchurch Mail

Centre, Christchurch 8140

New Zealand

Reviewed By

  
-----  
Lachlan Howat

Structural Engineer

Telephone: +64 3 363 5400

Facsimile: +64 3 365 7858

Date: April 2014

Reference: 6-QC331.00

Status: Final

Approved for  
Release By

  
-----  
Mary Ann Halliday

Senior Structural Engineer

# Summary

Clent Lane Housing Complex  
PRO 1091

Detailed Engineering Evaluation  
Quantitative Report - Summary  
Final

## Background

This is a summary of the quantitative report for the Clent Lane Housing Complex, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This assessment covers the 36 residential units and the Residents Lounge on the site.

## Key Damage Observed

The residential units have suffered minor damage to non-structural elements. This included cracking of the internal wall linings and ceiling diaphragms. There is minor cracking to the concrete bond beam and firewall. This damage was deemed low enough to not affect the capacities of the buildings.

## Level Survey

All accessible floor slopes were assessed in a laser level survey. Some of the floor slopes were greater than the 5mm/m limitation set out in the MBIE guidelines [6], as shown below.

## Internal Lining Nail Spacings

The internal lining nail spacings were measured on site to vary between 150 – 400 mm.

## Critical Structural Weaknesses

No critical structural weaknesses were found in any of the buildings.

## Indicative Building Strength

**Table A: Summary of Seismic Performance by Blocks**

Block	NBS%	Indicative Floor Levels	Nail Spacings
PRO 1091 B001 (Block A)	27%	Pass	Pass
PRO 1091 B002 (Block B)	27%	Pass	Pass
PRO 1091 B003 (Block C)	27%	Pass	Pass
PRO 1091 B004 (Block D)	27%	Pass	Pass
PRO 1091 B005 (Block E)	27%	Pass	Pass
PRO 1091 B006 (Block F)	27%	Fail	Pass
PRO 1091 B007 (Block G)	27%	Fail	Pass
PRO 1091 B008 (Block H)	27%	Pass	Pass

All buildings on the site are considered to be Earthquake Prone.

Blocks A, B, C, D F, G and H have capacities of 27%NBS as limited by the capacity of the timber framed walls in the longitudinal direction. They are deemed to be a 'high risk' in a design seismic event according to NZSEE guidelines.

Block E has a capacity of 27%NBS as limited by the capacity of the timber framed walls and temporary braces in the residential units in the longitudinal direction. It is deemed to be a 'high risk' in a design seismic event according to NZSEE guidelines.

Increasing the number of nails in the plasterboard will not significantly improve the strength of the buildings.

### **Recommendations**

It is recommended that;

- Strengthening schemes be developed to bring the capacities of the structures to at least 67%NBS.
- Cracking in the concrete bond beam and block firewall be repaired.
- Replace temporary propping with permanent strengthening solution.
- Cosmetic repairs be undertaken as required.

# Contents

<b>Summary .....</b>	<b>i</b>
<b>1 Introduction.....</b>	<b>4</b>
<b>2 Compliance .....</b>	<b>4</b>
<b>3 Earthquake Resistance Standards.....</b>	<b>8</b>
<b>4 Background Information.....</b>	<b>10</b>
<b>5 Damage .....</b>	<b>16</b>
<b>6 Detailed Seismic Assessment .....</b>	<b>17</b>
<b>7 Geotechnical Summary .....</b>	<b>21</b>
<b>8 Conclusions.....</b>	<b>22</b>
<b>9 Recommendations .....</b>	<b>22</b>
<b>10 Limitations.....</b>	<b>22</b>
<b>11 References .....</b>	<b>23</b>
<b>Appendix A – Photographs</b>	
<b>Appendix B – Level Survey</b>	
<b>Appendix C – Methodology and Assumptions</b>	
<b>Appendix D – CERA DEE Spreadsheet</b>	

# 1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Clent Lane Housing Complex, located at 32 Cobham Street, Spreydon, following the Canterbury earthquake sequence since September 2010. The site was visited by Opus International Consultants on 2 December 2013.

The purpose of the assessment is to determine if the buildings in the complex are classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [2] [3] [4] [5].

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

## 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

### Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in October 2011 following the Darfield Earthquake on 4 September 2010.

The policy includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure, was amended to include increased seismic design requirements for Canterbury as follows:

- Increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

### 3 Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use). This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines [2]

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

## 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

### 3.1.1 Occupancy

The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the MBIE guidance document dated December 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

### 3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

### 3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### 3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

---

<sup>1</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority.

## 4 Background Information

### 4.1 Building Descriptions

The site contains 36 residential units which were constructed in 1977 and a resident's lounge which was converted from two residential units. The roofs of all units were replaced and interiors refurbished in 2011. A site plan showing the location of the units, numbered 1 to 38 (residential lounge occupies units 21 and 22), is shown in Figure 2. Figure 3 shows the location of the site in Christchurch City. The units are grouped together to form 7 blocks of three, four, six or eight units.

Unit 18 could not be entered due to fire damage.





Figure 2: Site plan of Clent Lane Housing Complex.



**Figure 3: Location of Clent Lane (circled) relative to Christchurch City CBD (Source: Google Earth).**

The residential units have reinforced concrete block walls with 12mm diameter rods vertically at 600mm centres. The roof structure comprises of timber roof trusses supporting light-weight metal roofs. The walls and ceilings are lined with plasterboard. The internal timber framed walls in the transverse direction are not full height. The ‘front wall’ of the units is thought to have no bracing capacity as it consists of large windows and doors.

The units are separated by 190mm block masonry fire walls which are filled with 12mm diameter rods at 600mm centres. A reinforced cast in situ bond beam is located at the ceiling line within the block fire wall.

Foundations are strip footings with 190mm by 900mm reinforced ‘spade’ footings 2.5m from either end of the fire walls and end walls. All other walls have reinforced concrete footings around the perimeter. A reinforced concrete slab is tied into these footings.

The Residents Lounge has been converted from two adjacent units in Block E. After initial investigations by Opus International Consultants, temporary braces (Figure 6 and Photos 20 and 21) were installed on 20 March 2014 so that the units in this block could remain occupied.

Figure 4 and Figure 5 show floor plans of a typical residential unit and the Residents Lounge respectively produced from site measurements by Opus. Figure 7 shows a comparable cross section used in calculations, from Clent Lane prior to the roof replacement.




Figure 4: Typical partial floor plan of residential unit blocks.




Figure 5: Partial floor plan of Residents Lounge.




Figure 6: Braces used in residents lounge




Figure 7: Comparable cross section of Clent Lane (before roof replacement).

## 4.2 Survey

### 4.2.1 Post 22 February 2011 Rapid Assessment

A structural (Level 2) assessment of the buildings/property was undertaken on 8 March 2011 by Opus International Consultants.

### 4.2.2 Level Survey

A full level survey was not deemed to be necessary at Clent Lane as it is located in a TC2 zone. Properties in TC2 zones suffered minor to moderate damage due to liquefaction and/or settlement. In lieu of a full level survey, a laser level was placed in each unit so that differentials in vertical levels could be measured at the extreme ends of the unit. These values could then be used to determine the floor slope of the entire unit. For this site, the maximum slope in a unit was 6 mm/m (which exceeds the 5mm/m limitation imposed by MBIE guidelines), the general slopes across all units was approximately 3 mm/m.

Table 2: Summary of the Level Survey

Block	Unit No.	Comment	Maximum Fall*
A	1	Pass	-
	2	Pass	-
	3	Pass	-
	4	Pass	-
B	5	Pass	-
	6	Pass	-
	7	Pass	-
	8	Pass	-
	9	Pass	-
	10	Pass	-
C	11	Pass	-
	12	Pass	-
	14	Pass	-
	15	Pass	-
	16	Pass	-
D	17	Pass	-
	18	Pass	-
	19	Pass	-
	20	Pass	-
E	Residents Lounge	Pass	-
	23	Pass	-
	24	Pass	-
F	25	Fail	5 mm/m
	26	Pass	-
	27	Pass	-
	28	Pass	-
	29	Pass	-
	30	Pass	-
	31	Pass	-
	32	Pass	-
G	33	Fail	6 mm/m
	34	Pass	-
	35	Pass	-
H	36	Pass	-
	37	Pass	-
	38	Pass	-

\* Values are only recorded if greater than 5mm/m

Orange results represent floor levels which fall outside the MBIE guidelines when using the laser level but may comply when surveyed using more accurate equipment.

#### 4.2.3 Nail Spacings

The internal lining nail spacings were measured on site to vary between 150 – 400 mm.

### 4.3 Original Documentation

The following documentation was provided by the Christchurch City Council:

- Document No. A241 – Christchurch City Council – Cobham Street Elderly Persons Housing – p. 1-13/14 – Site plan; Services plan; Unit plans and Elevations by block; Foundation plans and Sections; Electrical layouts, Door elevations and details, Fencing details; Wall elevations; Amendments to original plans – 1975 (amended in 1976).

In addition, a typical floor plan has been produced by Opus to help confirm as-built measurements.

Copies of the design calculations were not provided.

## 5 Damage

This section outlines the damage to the buildings that was observed during site visits. It is not intended to be a complete summary of the damage sustained by the buildings due to the earthquakes. Some forms of damage may not be able to be identified with a visual inspection only.

Although most damage is evenly distributed, it is noticeable that some residential unit blocks, and individual units, have suffered more damage than others. Overall, Unit 19 appears to have suffered the highest levels of damage.

Note: Any photo referenced in this section can be found in Appendix A.

### 5.1 Residual Displacements

Only minor displacements were observed in all units inspected. Two units exhibited levels which exceeded the 5mm/m MBIE guideline.

### 5.2 Foundations

No damage was observed to the foundations.

### 5.3 Primary Gravity Structure

Stepped cracking was observed in the concrete block walls.

### 5.4 Primary Lateral-Resistance Structure

Minor damage was observed to the primary lateral resistance structure in the form of cracking to wall and ceiling linings. Cracking was also observed to the bond beam at the top of the fire walls in most units (photo 12). Similar cracks were also observed from the exterior of the bond beams (photo 15) which have been patched between the time of the damage and the site inspection. Stepped cracking was also observed in the fire wall of Unit 19 (photo 13).

## 5.5 Non Structural Elements

Minor to moderate damage to non-structural elements was observed. This included cracking to plasterboard wall linings where they join at corners (photos 11 and 14).

Damage was also observed to the paths around the complex in the form of cracking and displacement.

## 5.6 General Observations

The buildings appeared to have performed reasonably well, as would be expected for buildings of this type, during the earthquakes. They have suffered distributed amounts of minor damage which is typical of the type and age of construction.

# 6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

As the residential units have the same floor plan, the analysis was simplified by conducting the analysis of one multi-unit block with similar cladding and using this for all multi-unit blocks.

## 6.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSWs were identified in the buildings.

## 6.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix C. A brief summary follows:

Hand calculations were performed to determine seismic forces from the current building codes. These forces were applied globally to the structure and the capacities of the walls were calculated and used to estimate the %NBS. The walls, highlighted in Figure 8 through Figure 10, were used for bracing in their respective directions.




Figure 8: Walls used for bracing in the longitudinal direction residential units.




Figure 9: Walls used for bracing in the transverse direction residential units.




Figure 10: Walls used for bracing in the longitudinal direction Residents Lounge.




Figure 11: Walls used for bracing in the transverse direction Residents Lounge.

### 6.3 Limitations and Assumptions in Results

The observed level of damage suffered by the buildings was deemed low enough to not affect their capacity. Therefore the analysis and assessment of the buildings was based on them being in an undamaged state. There may have been damage to the buildings that was unable to be observed that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections.
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.
- Construction is consistent with normal practise of the era in which constructed.

### 6.4 Assessment

A summary of the structural performance of the buildings is shown in Table 3. Note that the values given represent the worst performing elements in the building, where these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

Although the governing criteria is less than 33%NBS it is not considered to be a brittle failure mechanism so the buildings remain safe to occupy.

**Table 3: Summary of Seismic Performance**

Building Description	Critical element	% NBS based on calculated capacity in longitudinal direction	% NBS based on calculated capacity in transverse direction.
Blocks A-D and F-H	Out of plane bending of Fire Wall	41%	-
	In plane shear of bracing walls	27%	100%
Block E	Out of plane bending of Fire Wall A (Figure 10) with temporary propping	55%	-
	In plane shear of bracing walls in residential units	27%	100%

## 7 Geotechnical Summary

CERA indicates that Clent Lane is located in a TC2 zone (as shown in Figure 12). This classification suggests future significant earthquakes will cause minor to moderate land damage due to liquefaction and settlement.



**Figure 12: CERA Technical Categories map (loc. starred).**

There is no evidence to suggest that further geotechnical investigation is warranted for this site.

## 8 Conclusions

- Blocks A, B, C, D, F, G and H have capacities of 27% NBS, as limited by the in-plane capacity of the bracing walls. They are deemed to be a ‘high risk’ in a design seismic event according to NZSEE guidelines. Their level of risk is 10-25 times that of a 100% NBS building (Figure 1).
- Block E has a capacity of 27%NBS as limited by the capacity of the timber framed walls and temporary braces in the residential units in the longitudinal direction. It is deemed to be a ‘high risk’ in a design seismic event according to NZSEE guidelines. The level of risk is 10-25 times that of a 100% NBS building (Figure 1).
- The buildings remain safe to occupy as they are not considered to have a brittle failure mechanism.

## 9 Recommendations

It is recommended that;

- Strengthening schemes be developed to bring the capacities of the structures to at least 67%NBS.
- Cracking in the concrete bond beam and block firewall be repaired.
- Replace temporary propping with permanent strengthening solution.
- Cosmetic repairs be undertaken as required.

## 10 Limitations

- This report is based on an inspection of the buildings and focuses on the structural damage resulting from the Canterbury Earthquake sequence since September 2010. Some non-structural damage may be described but this is not intended to be a complete list of damage to non-structural items.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- This report is prepared for the Christchurch City Council to assist in the assessment of any remedial works required for the Clent Lane Housing Complex. It is not intended for any other party or purpose.

## 11 References

- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] MBIE (2012), Repairing and rebuilding houses affected by the Canterbury earthquakes, Ministry of Building, Innovation and Employment, December 2012.

## **Appendix A – Photographs**



Clent Lane Housing Complex – Detailed Engineering Evaluation

Clent Lane Housing Complex		
Residential Units Layout		
1.	Typical exterior elevation (front)	
2.	Typical exterior elevation (end)	


Clent Lane Housing Complex – Detailed Engineering Evaluation

<p>3.</p>	<p>Typical attic space</p>	
<p>4.</p>	<p>Typical roof space (showing fire wall)</p>	
<p>5.</p>	<p>Typical dining area view</p>	

Clent Lane Housing Complex – Detailed Engineering Evaluation

<p>6.</p>	<p>Typical lounge view</p>	 A photograph of a typical lounge area. A man in a high-visibility orange vest and dark jacket stands in the doorway on the left. The room features a wooden side table with books, a framed picture of a butterfly, and a patterned sofa. The walls are decorated with several small circular plaques.
<p>7.</p>	<p>Typical bedroom view</p>	 A photograph of a typical bedroom. A bed with a patterned duvet and a blue blanket is the central feature. A wooden bedside table holds a lamp and a small clock. The wall behind the bed is covered in white acoustic panels.
<p>8.</p>	<p>Typical bathroom view</p>	 A photograph of a typical bathroom. It shows a shower area with a glass door, a white sink on a wooden vanity, and a mirror above the sink. A blue bucket is visible on the floor to the right.

Clent Lane Housing Complex – Detailed Engineering Evaluation


9.	Typical kitchen view	
10.	Typical cracking to ceiling diaphragm	
11.	Typical cracking where wall and ceiling linings meet	

Clent Lane Housing Complex – Detailed Engineering Evaluation

<p>12.</p>	<p>Cracking in bond beam</p>	 A photograph showing a horizontal wooden bond beam on a wall. The wall is made of light-colored concrete blocks. There are several vertical cracks running down the wall, some of which appear to be related to the bond beam. A red circular object with white numbers is partially visible on the left side of the frame.
<p>13.</p>	<p>Stepped cracking observed in the interior fire wall of Unit 19</p>	 A photograph showing a wall with a stepped cracking pattern in the mortar joints between concrete blocks. The wall is made of light-colored concrete blocks. A wooden beam is visible at the top of the frame. A small framed picture or document is visible at the bottom of the frame.

Clent Lane Housing Complex – Detailed Engineering Evaluation

---

<p>14.</p>	<p>Typical separation of interior wall linings from fire wall</p>	 A photograph showing the interior corner of a room. The walls are white, and there is a significant vertical crack running down the corner where the wall meets the ceiling. The crack appears to be a separation between the interior wall lining and the underlying fire wall. A wooden door frame is visible in the lower right corner.
<p>15.</p>	<p>Exterior crack in bond beam</p>	 A photograph of an exterior wall made of white concrete blocks. A vertical crack runs through the wall, passing through a horizontal bond beam. A small metal tool or level is placed horizontally against the wall to the left of the crack for scale. The sky is visible in the background.

Clent Lane Housing Complex – Detailed Engineering Evaluation

Residents Lounge		
16.	Entrance view	 A photograph showing the entrance area of the Residents Lounge. On the left, there is a long counter with a dark top and light-colored cabinets underneath. Two red chairs are tucked under the counter. In the center, there are large windows with white curtains. To the right, there is a set of glass double doors leading outside to a paved area and a green lawn. The room has a dark carpet.
17.	Kitchen view	 A photograph of the kitchen area. A white refrigerator is the central feature. To its right is a kitchen counter with a sink, a white stove with four burners, and a window with white curtains above the counter. A white cabinet is mounted on the wall above the counter. In the background, there is a doorway leading to another room. A red fire extinguisher is visible on the wall near the refrigerator.
18.	Bathroom view	 A photograph of a bathroom. The walls are a light pink color. A white sink is mounted on a white vanity. A white toilet is visible in the background. A white door is on the right side of the frame. In the foreground, a white door handle with a red emergency release lever is visible on a light pink wall.


**Clent Lane Housing Complex – Detailed Engineering Evaluation**

<p>19.</p>	<p>Main room view</p>	 A photograph showing a large, open-plan living and dining area. In the foreground, a long table is covered with a brown cloth. The middle ground features a dining table with several chairs. In the background, a person in a high-visibility vest stands near a window, and other people are seated at a table. Large windows with sheer curtains allow natural light into the room.
<p>20.</p>	<p>Temporary braces installed in Residents Lounge</p>	 A photograph of a room with a blue carpet and light-colored walls. A large, diagonal wooden brace, painted green and red, is secured to the ceiling and floor. The brace is positioned near a table and chairs. To the right, there is a small table with a bookshelf on top, filled with books and magazines. A television is mounted on the wall above the bookshelf.


<p>21.</p>	<p>Temporary braces installed in Residents Lounge</p>	
------------	---	---

## **Appendix B – Level Survey**

Unit 25



Unit 33



## **Appendix C – Methodology and Assumptions**

## Seismic Parameters

As per NZS 1170.5:

- $T < 0.4s$  (assumed)
- Soil: Category D
- $Z = 0.3$
- $R = 1.0$  (IL2, 50 year)
- $N(T,D) = 1.0$

For the analyses, a  $\mu$  of 2 was assumed for the residential units.

## Analysis Procedure

As the units are small and have a number of closely spaced walls in both directions, the fibrous plaster board ceilings are assumed to be capable of transferring loads to all walls. It was therefore assumed that a global method could be used to carry the forces down to ground level in each direction. Bracing capacities were found by assuming a certain kN/m rating for the walls along each line. Due to the relatively unknown nature of the walls, the kN/m rating was taken as 3 kN/m for all timber walls with an aspect ratio (height: length) of less than 2:1. This was scaled down to zero kN/m at an aspect ratio of 3.5:1 as per NZSEE guidelines. Concrete block walls were analysed using New Zealand Standards %NBS values were then found through the ratio of bracing demand to bracing capacity for all walls in each direction.

## Additional Assumptions

Further assumptions about the seismic performance of the buildings were:

- Foundations and foundation connections had adequate capacity to resist and transfer earthquake loads.
- Connections between all elements of the lateral load resisting systems are detailed to adequately transfer their loads sufficiently and are strong enough so as to not fail before the lateral load resisting elements.

## **Appendix D – CERA DEE Spreadsheet**

<b>Location</b>		Building Name: <u>Clent Lane Housing Complex (Blocks A &amp; D)</u>	Reviewer: <u>Mary Ann Halliday</u>
Building Address: <u>62 Cobham Street</u>	Unit No: <u>        </u>	Street: <u>        </u>	CPEng No: <u>67073</u>
Legal Description: <u>        </u>	Company: <u>Opus International Consultants Ltd.</u>		Company project number: <u>6-OC331.00</u>
GPS south: <u>        </u>		Degrees: <u>43</u>	Min: <u>33</u>
GPS east: <u>        </u>		Sec: <u>22.40</u>	
Building Unique Identifier (CCC): <u>PRO 1091</u>		Date of submission: <u>28-Feb-14</u>	
		Inspection Date: <u>2-Dec-13</u>	
		Revision: <u>1</u>	
		Is there a full report with this summary? <u>yes</u>	

<b>Site</b>	Site slope: <u>flat</u>	Max retaining height (m): <u>        </u>
Soil type: <u>        </u>	Soil Profile (if available): <u>        </u>	
Site Class (to NZS1170.5): <u>D</u>		
Proximity to waterway (m, if <100m): <u>        </u>	If Ground improvement on site, describe: <u>        </u>	
Proximity to cliff top (m, if < 100m): <u>        </u>		
Proximity to cliff base (m, if <100m): <u>        </u>		Approx site elevation (m): <u>11.00</u>

<b>Building</b>	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>        </u>
Ground floor split? <u>no</u>			Ground floor elevation above ground (m): <u>        </u>
Storeys below ground: <u>0</u>			
Foundation type: <u>strip footings</u>			if Foundation type is other, describe: <u>        </u>
Building height (m): <u>3.00</u>			height from ground to level of uppermost seismic mass (for IEP only) (m): <u>        </u>
Floor footprint area (approx): <u>168</u>			
Age of Building (years): <u>36</u>			Date of design: <u>1976-1992</u>
Strengthening present? <u>no</u>			If so, when (year)? <u>        </u>
			And what load level (%g)? <u>        </u>
Use (ground floor): <u>multi-unit residential</u>			Brief strengthening description: <u>        </u>
Use (upper floors): <u>        </u>			
Use notes (if required): <u>        </u>			
Importance level (to NZS1170.5): <u>IL2</u>			

<b>Gravity Structure</b>	Gravity System: <u>load bearing walls</u>	truss depth, purlin type and cladding: <u>        </u>
Roof: <u>timber truss</u>		slab thickness (mm): <u>        </u>
Floors: <u>concrete flat slab</u>		type: <u>        </u>
Beams: <u>timber</u>		typical dimensions (mm x mm): <u>timber (only present in some units)</u>
Columns: <u>other (note)</u>		#N/A: <u>        </u>
Walls: <u>fully filled concrete masonry</u>		

<b>Lateral load resisting structure</b>	Lateral system along: <u>fully filled CMU</u>	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): <u>        </u>
Ductility assumed, μ: <u>2.00</u>		enter height above at H31: <u>        </u>	estimate or calculation? <u>estimated</u>
Period along: <u>0.10</u>			estimate or calculation? <u>        </u>
Total deflection (ULS) (mm): <u>        </u>			estimate or calculation? <u>        </u>
maximum interstorey deflection (ULS) (mm): <u>        </u>			
Lateral system across: <u>fully filled CMU</u>			note total length of wall at ground (m): <u>        </u>
Ductility assumed, μ: <u>2.00</u>			estimate or calculation? <u>estimated</u>
Period across: <u>0.10</u>			estimate or calculation? <u>        </u>
Total deflection (ULS) (mm): <u>        </u>			estimate or calculation? <u>        </u>
maximum interstorey deflection (ULS) (mm): <u>        </u>			

<b>Separations:</b>	north (mm): <u>        </u>	leave blank if not relevant
east (mm): <u>        </u>		
south (mm): <u>        </u>		
west (mm): <u>        </u>		

<b>Non-structural elements</b>	Stairs: <u>        </u>	describe: <u>        </u>
Wall cladding: <u>exposed structure</u>		describe: <u>        </u>
Roof Cladding: <u>Metal</u>		
Glazing: <u>timber frames</u>		
Ceilings: <u>plaster, fixed</u>		
Services(list): <u>        </u>		

<b>Available documentation</b>	Architectural: <u>full</u>	original designer name/date: <u>Christchurch City Council, 1995-1996</u>
Structural: <u>partial</u>		original designer name/date: <u>Christchurch City Council, 1995-1996</u>
Mechanical: <u>none</u>		original designer name/date: <u>        </u>
Electrical: <u>none</u>		original designer name/date: <u>        </u>
Geotech report: <u>none</u>		original designer name/date: <u>        </u>

<b>Damage</b>	Site performance: <u>good</u>	Describe damage: <u>        </u>
Site: (refer DEE Table 4-2)	Settlement: <u>none observed</u>	notes (if applicable): <u>        </u>
Differential settlement: <u>none observed</u>		notes (if applicable): <u>        </u>
Liquefaction: <u>none apparent</u>		notes (if applicable): <u>        </u>
Lateral Spread: <u>none apparent</u>		notes (if applicable): <u>        </u>
Differential lateral spread: <u>none apparent</u>		notes (if applicable): <u>        </u>
Ground cracks: <u>none apparent</u>		notes (if applicable): <u>        </u>
Damage to area: <u>none apparent</u>		notes (if applicable): <u>        </u>

<b>Building:</b>	Current Placard Status: <u>green</u>	
Along	Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: <u>        </u>
	Describe (summary): <u>        </u>	
Across	Damage ratio: <u>0%</u>	$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
	Describe (summary): <u>        </u>	
Diaphragms	Damage?: <u>yes</u>	Describe: <u>minor ceiling cracking</u>
CSWs:	Damage?: <u>no</u>	Describe: <u>        </u>
Pounding:	Damage?: <u>no</u>	Describe: <u>        </u>
Non-structural:	Damage?: <u>yes</u>	Describe: <u>minor cracking and damage</u>

<b>Recommendations</b>	Level of repair/strengthening required: <u>minor non-structural</u>	Describe: <u>        </u>
Building Consent required: <u>no</u>		Describe: <u>        </u>
Interim occupancy recommendations: <u>full occupancy</u>		Describe: <u>        </u>
Along	Assessed %NBS before e'quakes: <u>27%</u>	##### %NBS from IEP below
	Assessed %NBS after e'quakes: <u>27%</u>	
		If IEP not used, please detail assessment methodology: <u>Equivalent Static</u>
Across	Assessed %NBS before e'quakes: <u>100%</u>	##### %NBS from IEP below
	Assessed %NBS after e'quakes: <u>100%</u>	

<b>Location</b>		Building Name: <u>Clent Lane Housing Complex (Blocks B&amp;C)</u>	Reviewer: <u>Mary Ann Halliday</u>
Building Address: <u>62 Cobham Street</u>	Unit No: <u>        </u>	Street: <u>        </u>	CPEng No: <u>67073</u>
Legal Description: <u>        </u>	Company: <u>Opus International Consultants Ltd.</u>		Company project number: <u>6-OC331.00</u>
GPS south: <u>        </u>		Degrees: <u>43</u>	Min: <u>33</u>
GPS east: <u>        </u>		Sec: <u>22.40</u>	
Building Unique Identifier (CCC): <u>PRO 1091</u>		Date of submission: <u>28-Feb-14</u>	Inspection Date: <u>2-Dec-13</u>
		Revision: <u>1</u>	Is there a full report with this summary? <u>yes</u>

<b>Site</b>	Site slope: <u>flat</u>	Max retaining height (m): <u>        </u>
Soil type: <u>        </u>	Soil Profile (if available): <u>        </u>	
Site Class (to NZS1170.5): <u>D</u>	If Ground improvement on site, describe: <u>        </u>	
Proximity to waterway (m, if <100m): <u>        </u>	Approx site elevation (m): <u>11.00</u>	
Proximity to cliff top (m, if < 100m): <u>        </u>		
Proximity to cliff base (m, if <100m): <u>        </u>		

<b>Building</b>	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>        </u>
Ground floor split? <u>no</u>	Storeys below ground: <u>0</u>	Foundation type: <u>strip footings</u>	Ground floor elevation above ground (m): <u>        </u>
Building height (m): <u>3.00</u>	Floor footprint area (approx): <u>252</u>	Age of Building (years): <u>36</u>	if Foundation type is other, describe: <u>        </u>
Strengthening present? <u>no</u>	Use (ground floor): <u>multi-unit residential</u>	Use (upper floors): <u>        </u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>        </u>
Use notes (if required): <u>        </u>	Importance level (to NZS1170.5): <u>IL2</u>	Date of design: <u>1976-1992</u>	If so, when (year)? <u>        </u>
		Brief strengthening description: <u>        </u>	And what load level (%g)? <u>        </u>

<b>Gravity Structure</b>	Gravity System: <u>load bearing walls</u>	Roof: <u>timber truss</u>	Floors: <u>concrete flat slab</u>	Beams: <u>timber</u>	Columns: <u>other (note)</u>	Walls: <u>fully filled concrete masonry</u>	truss depth, purlin type and cladding: <u>        </u>	slab thickness (mm): <u>        </u>	type: <u>        </u>	typical dimensions (mm x mm): <u>timber (only present in some units)</u>	#N/A: <u>        </u>
--------------------------	---	---------------------------	-----------------------------------	----------------------	------------------------------	---	--	--------------------------------------	-----------------------	--	-----------------------

<b>Lateral load resisting structure</b>	Lateral system along: <u>fully filled CMU</u>	Ductility assumed, $\mu$ : <u>2.00</u>	Period along: <u>0.10</u>	Total deflection (ULS) (mm): <u>        </u>	maximum interstorey deflection (ULS) (mm): <u>        </u>	Lateral system across: <u>fully filled CMU</u>	Ductility assumed, $\mu$ : <u>2.00</u>	Period across: <u>0.10</u>	Total deflection (ULS) (mm): <u>        </u>	maximum interstorey deflection (ULS) (mm): <u>        </u>	Note: Define along and across in detailed report! ##### enter height above at H31	note total length of wall at ground (m): <u>        </u>	estimate or calculation? <u>estimated</u>	estimate or calculation? <u>        </u>	estimate or calculation? <u>        </u>
---	---	--	---------------------------	--	--	--	--	----------------------------	--	--	---	--	---	--	--

<b>Separations:</b>	north (mm): <u>        </u>	east (mm): <u>        </u>	south (mm): <u>        </u>	west (mm): <u>        </u>	leave blank if not relevant
---------------------	-----------------------------	----------------------------	-----------------------------	----------------------------	-----------------------------

<b>Non-structural elements</b>	Stairs: <u>        </u>	Wall cladding: <u>exposed structure</u>	Roof Cladding: <u>Metal</u>	Glazing: <u>timber frames</u>	Ceilings: <u>plaster, fixed</u>	Services(list): <u>        </u>	describe: <u>        </u>	describe: <u>        </u>
--------------------------------	-------------------------	---	-----------------------------	-------------------------------	---------------------------------	---------------------------------	---------------------------	---------------------------

<b>Available documentation</b>	Architectural: <u>full</u>	Structural: <u>partial</u>	Mechanical: <u>none</u>	Electrical: <u>none</u>	Geotech report: <u>none</u>	original designer name/date: <u>Christchurch City Council, 1995-1996</u>	original designer name/date: <u>Christchurch City Council, 1995-1996</u>	original designer name/date: <u>        </u>	original designer name/date: <u>        </u>
--------------------------------	----------------------------	----------------------------	-------------------------	-------------------------	-----------------------------	--	--	--	--

<b>Damage</b>	Site performance: <u>good</u>	Describe damage: <u>        </u>
Site: (refer DEE Table 4-2)	Settlement: <u>none observed</u>	Differential settlement: <u>none observed</u>
Liquefaction: <u>none apparent</u>	Lateral Spread: <u>none apparent</u>	Differential lateral spread: <u>none apparent</u>
Ground cracks: <u>none apparent</u>	Damage to area: <u>none apparent</u>	notes (if applicable): <u>        </u>

<b>Building:</b>	Current Placard Status: <u>green</u>	Describe how damage ratio arrived at: <u>        </u>
Along	Damage ratio: <u>0%</u>	Describe (summary): <u>        </u>
Across	Damage ratio: <u>0%</u>	Describe (summary): <u>        </u>
Diaphragms	Damage?: <u>yes</u>	Describe: <u>minor ceiling cracking</u>
CSWs:	Damage?: <u>no</u>	Describe: <u>        </u>
Pounding:	Damage?: <u>no</u>	Describe: <u>        </u>
Non-structural:	Damage?: <u>yes</u>	Describe: <u>minor cracking and damage</u>

<b>Recommendations</b>	Level of repair/strengthening required: <u>minor non-structural</u>	Building Consent required: <u>no</u>	Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u>        </u>
Along	Assessed %NBS before e'quakes: <u>27%</u>	Assessed %NBS after e'quakes: <u>27%</u>	##### %NBS from IEP below	If IEP not used, please detail assessment methodology: <u>Quantitative</u>
Across	Assessed %NBS before e'quakes: <u>100%</u>	Assessed %NBS after e'quakes: <u>100%</u>	##### %NBS from IEP below	

<b>Location</b>		Building Name: <u>Clent Lane Housing Complex (Blocks G &amp; H)</u>	Reviewer: <u>Mary Ann Halliday</u>
Building Address: <u>62 Cobham Street</u>	Unit No: <u>        </u>	Street: <u>        </u>	CPEng No: <u>67073</u>
Legal Description: <u>        </u>	Company: <u>Opus International Consultants Ltd.</u>		Company project number: <u>6-OC331.00</u>
GPS south: <u>        </u>		Degrees: <u>43</u>	Min: <u>33</u>
GPS east: <u>        </u>		Sec: <u>22.40</u>	Company phone number: <u>(03) 363 5400</u>
Building Unique Identifier (CCC): <u>PRO 1091</u>		Date of submission: <u>28-Feb-14</u>	Inspection Date: <u>2-Dec-13</u>
		Revision: <u>1</u>	Is there a full report with this summary? <u>yes</u>

<b>Site</b>	Site slope: <u>flat</u>	Max retaining height (m): <u>        </u>
Soil type: <u>        </u>	Soil Profile (if available): <u>        </u>	
Site Class (to NZS1170.5): <u>D</u>		
Proximity to waterway (m, if <100m): <u>        </u>	If Ground improvement on site, describe: <u>        </u>	
Proximity to cliff top (m, if < 100m): <u>        </u>		
Proximity to cliff base (m,if <100m): <u>        </u>	Approx site elevation (m): <u>11.00</u>	

<b>Building</b>	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>        </u>
Ground floor split? <u>no</u>	Storeys below ground: <u>0</u>	Foundation type: <u>strip footings</u>	Ground floor elevation above ground (m): <u>        </u>
Building height (m): <u>3.00</u>	Floor footprint area (approx): <u>126</u>	Age of Building (years): <u>36</u>	if Foundation type is other, describe: <u>        </u>
Strengthening present? <u>no</u>	Use (ground floor): <u>multi-unit residential</u>	Use (upper floors): <u>        </u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>        </u>
Use notes (if required): <u>        </u>	Importance level (to NZS1170.5): <u>IL2</u>	Date of design: <u>1976-1992</u>	If so, when (year)? <u>        </u>
		Brief strengthening description: <u>        </u>	And what load level (%g)? <u>        </u>

<b>Gravity Structure</b>	Gravity System: <u>load bearing walls</u>	Roof: <u>timber truss</u>	Floors: <u>concrete flat slab</u>	Beams: <u>timber</u>	Columns: <u>other (note)</u>	Walls: <u>fully filled concrete masonry</u>	truss depth, purlin type and cladding: <u>        </u>	slab thickness (mm): <u>        </u>	type: <u>        </u>	typical dimensions (mm x mm): <u>timber (only present in some units)</u>	#N/A: <u>        </u>
--------------------------	---	---------------------------	-----------------------------------	----------------------	------------------------------	---	--	--------------------------------------	-----------------------	--	-----------------------

<b>Lateral load resisting structure</b>	Lateral system along: <u>fully filled CMU</u>	Ductility assumed, μ: <u>2.00</u>	Period along: <u>0.10</u>	Total deflection (ULS) (mm): <u>        </u>	maximum interstorey deflection (ULS) (mm): <u>        </u>	Lateral system across: <u>fully filled CMU</u>	Ductility assumed, μ: <u>2.00</u>	Period across: <u>0.10</u>	Total deflection (ULS) (mm): <u>        </u>	maximum interstorey deflection (ULS) (mm): <u>        </u>	Note: Define along and across in detailed report! ##### enter height above at H31	note total length of wall at ground (m): <u>        </u>	estimate or calculation? <u>estimated</u>	estimate or calculation? <u>        </u>	estimate or calculation? <u>        </u>
---	---	-----------------------------------	---------------------------	--	--	--	-----------------------------------	----------------------------	--	--	---	--	---	--	--

<b>Separations:</b>	north (mm): <u>        </u>	east (mm): <u>        </u>	south (mm): <u>        </u>	west (mm): <u>        </u>	leave blank if not relevant
---------------------	-----------------------------	----------------------------	-----------------------------	----------------------------	-----------------------------

<b>Non-structural elements</b>	Stairs: <u>        </u>	Wall cladding: <u>exposed structure</u>	Roof Cladding: <u>Metal</u>	Glazing: <u>timber frames</u>	Ceilings: <u>plaster, fixed</u>	Services(list): <u>        </u>	describe: <u>        </u>	describe: <u>        </u>
--------------------------------	-------------------------	---	-----------------------------	-------------------------------	---------------------------------	---------------------------------	---------------------------	---------------------------

<b>Available documentation</b>	Architectural: <u>full</u>	Structural: <u>partial</u>	Mechanical: <u>none</u>	Electrical: <u>none</u>	Geotech report: <u>none</u>	original designer name/date: <u>Christchurch City Council, 1995-1996</u>	original designer name/date: <u>Christchurch City Council, 1995-1996</u>	original designer name/date: <u>        </u>	original designer name/date: <u>        </u>
--------------------------------	----------------------------	----------------------------	-------------------------	-------------------------	-----------------------------	--	--	--	--

<b>Damage</b>	Site performance: <u>good</u>	Describe damage: <u>        </u>
Site: (refer DEE Table 4-2)	Settlement: <u>none observed</u>	Differential settlement: <u>none observed</u>
Liquefaction: <u>none apparent</u>	Lateral Spread: <u>none apparent</u>	Differential lateral spread: <u>none apparent</u>
Ground cracks: <u>none apparent</u>	Damage to area: <u>none apparent</u>	notes (if applicable): <u>        </u>

<b>Building:</b>	Current Placard Status: <u>green</u>	Describe how damage ratio arrived at: <u>        </u>
Along	Damage ratio: <u>0%</u>	Describe (summary): <u>        </u>
Across	Damage ratio: <u>0%</u>	Describe (summary): <u>        </u>
Diaphragms	Damage?: <u>yes</u>	Describe: <u>minor ceiling cracking</u>
CSWs:	Damage?: <u>no</u>	Describe: <u>        </u>
Pounding:	Damage?: <u>no</u>	Describe: <u>        </u>
Non-structural:	Damage?: <u>yes</u>	Describe: <u>minor cracking and damage</u>

<b>Recommendations</b>	Level of repair/strengthening required: <u>minor non-structural</u>	Building Consent required: <u>no</u>	Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u>        </u>
Along	Assessed %NBS before e'quakes: <u>27%</u>	Assessed %NBS after e'quakes: <u>27%</u>	##### %NBS from IEP below	If IEP not used, please detail assessment methodology: <u>Equivalent Static</u>
Across	Assessed %NBS before e'quakes: <u>100%</u>	Assessed %NBS after e'quakes: <u>100%</u>	##### %NBS from IEP below	

<b>Location</b>		Building Name: <input type="text" value="Clent Lane Housing Complex (Block E)"/>	Unit No: <input type="text" value="62"/>	Street: <input type="text" value="Cobham Street"/>	Reviewer: <input type="text" value="Mary Ann Halliday"/>
Building Address: <input type="text"/>	Legal Description: <input type="text"/>				CPEng No: <input type="text" value="67073"/>
			Company: <input type="text" value="Opus International Consultants Ltd."/>		
			Company project number: <input type="text" value="6-OC331.00"/>		
			Company phone number: <input type="text" value="(03) 363 5400"/>		
GPS south: <input type="text" value="43 33 22.40"/>		Degrees		Min	Sec
GPS east: <input type="text" value="172 36 36.32"/>					
Building Unique Identifier (CCC): <input type="text" value="PRO 1091"/>			Date of submission: <input type="text" value="28-Feb-14"/>		
			Inspection Date: <input type="text" value="2-Dec-13"/>		
			Revision: <input type="text" value="1"/>		
			Is there a full report with this summary? <input type="text" value="yes"/>		

<b>Site</b>		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
Soil type: <input type="text"/>		Soil Profile (if available): <input type="text"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>		If Ground improvement on site, describe: <input type="text"/>	
Proximity to waterway (m, if <100m): <input type="text"/>		Approx site elevation (m): <input type="text" value="11.00"/>	
Proximity to cliff top (m, if < 100m): <input type="text"/>			
Proximity to cliff base (m,if <100m): <input type="text"/>			

<b>Building</b>		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split? <input type="text" value="no"/>		Storeys below ground: <input type="text" value="0"/>	Foundation type: <input type="text" value="strip footings"/>	Ground floor elevation above ground (m): <input type="text"/>
Building height (m): <input type="text" value="3.00"/>		if Foundation type is other, describe: <input type="text"/>		
Floor footprint area (approx): <input type="text" value="168"/>		height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>		
Age of Building (years): <input type="text" value="36"/>		Date of design: <input type="text" value="1976-1992"/>		
Strengthening present? <input type="text" value="no"/>		If so, when (year)? <input type="text"/>		
Use (ground floor): <input type="text" value="multi-unit residential"/>		And what load level (%g)? <input type="text"/>		
Use (upper floors): <input type="text"/>		Brief strengthening description: <input type="text"/>		
Use notes (if required): <input type="text"/>				
Importance level (to NZS1170.5): <input type="text" value="IL2"/>				

<b>Gravity Structure</b>		Gravity System: <input type="text" value="load bearing walls"/>	truss depth, purlin type and cladding: <input type="text"/>
Roof: <input type="text" value="timber truss"/>		Floors: <input type="text" value="concrete flat slab"/>	slab thickness (mm): <input type="text"/>
Beams: <input type="text" value="timber"/>		Columns: <input type="text" value="other (note)"/>	typical dimensions (mm x mm): <input type="text" value="timber (only present in some units)"/>
Walls: <input type="text" value="fully filled concrete masonry"/>			#N/A: <input type="text"/>

<b>Lateral load resisting structure</b>		Lateral system along: <input type="text" value="fully filled CMU"/>	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>		Period along: <input type="text" value="0.10"/>	##### enter height above at H31	estimate or calculation? <input type="text" value="estimated"/>
Total deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>		
maximum interstorey deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>		
Lateral system across: <input type="text" value="fully filled CMU"/>		note total length of wall at ground (m): <input type="text"/>		
Ductility assumed, μ: <input type="text" value="2.00"/>		Period across: <input type="text" value="0.10"/>	##### enter height above at H31	
Total deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text" value="estimated"/>		
maximum interstorey deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>		

<b>Separations:</b>		north (mm): <input type="text"/>	leave blank if not relevant
east (mm): <input type="text"/>			
south (mm): <input type="text"/>			
west (mm): <input type="text"/>			

<b>Non-structural elements</b>		Stairs: <input type="text"/>	describe: <input type="text"/>
Wall cladding: <input type="text" value="exposed structure"/>		Roof Cladding: <input type="text" value="Metal"/>	describe: <input type="text"/>
Glazing: <input type="text" value="timber frames"/>		Ceilings: <input type="text" value="plaster, fixed"/>	
Services(list): <input type="text"/>			

<b>Available documentation</b>		Architectural: <input type="text" value="full"/>	original designer name/date: <input type="text" value="Christchurch City Council, 1995-1996"/>
Structural: <input type="text" value="partial"/>		Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text" value="Christchurch City Council, 1995-1996"/>
Electrical: <input type="text" value="none"/>		Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text"/>
			original designer name/date: <input type="text"/>

<b>Damage</b>		Site performance: <input type="text" value="good"/>	Describe damage: <input type="text"/>
Site: (refer DEE Table 4-2)		Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>
Differential settlement: <input type="text" value="none observed"/>		Liquefaction: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Lateral Spread: <input type="text" value="none apparent"/>		Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Ground cracks: <input type="text" value="none apparent"/>		Damage to area: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>

<b>Building:</b>		Current Placard Status: <input type="text" value="green"/>	Describe how damage ratio arrived at: <input type="text"/>
Along	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
Across	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
Diaphragms	Damage?: <input type="text" value="yes"/>	Describe: <input type="text" value="minor ceiling cracking"/>	
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>	
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>	
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text" value="minor cracking and damage"/>	

<b>Recommendations</b>		Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text"/>
Building Consent required: <input type="text" value="no"/>		Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before e'quakes: <input type="text" value="27%"/>	Assessed %NBS after e'quakes: <input type="text" value="27%"/>	##### %NBS from IEP below
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	Assessed %NBS after e'quakes: <input type="text" value="100%"/>	##### %NBS from IEP below
			If IEP not used, please detail assessment methodology: <input type="text" value="Equivalent Static"/>

<b>Location</b>		Building Name: <input type="text" value="Clent Lane Housing Complex (Block F)"/>	Unit No: <input type="text" value="62"/>	Street: <input type="text" value="Cobham Street"/>	Reviewer: <input type="text" value="Mary Ann Halliday"/>
Building Address: <input type="text"/>	Legal Description: <input type="text"/>				CPEng No: <input type="text" value="67073"/>
			Company: <input type="text" value="Opus International Consultants Ltd."/>		
			Company project number: <input type="text" value="6-OC331.00"/>		
			Company phone number: <input type="text" value="(03) 363 5400"/>		
GPS south: <input type="text" value="43 33 22.40"/>		Degrees		Min	Sec
GPS east: <input type="text" value="172 36 36.32"/>					
Building Unique Identifier (CCC): <input type="text" value="PRO 1091"/>			Date of submission: <input type="text" value="28-Feb-14"/>		
			Inspection Date: <input type="text" value="2-Dec-13"/>		
			Revision: <input type="text" value="1"/>		
			Is there a full report with this summary? <input type="text" value="yes"/>		

<b>Site</b>		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
Soil type: <input type="text"/>		Soil Profile (if available): <input type="text"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>		If Ground improvement on site, describe: <input type="text"/>	
Proximity to waterway (m, if <100m): <input type="text"/>		Approx site elevation (m): <input type="text" value="11.00"/>	
Proximity to cliff top (m, if < 100m): <input type="text"/>			
Proximity to cliff base (m,if <100m): <input type="text"/>			

<b>Building</b>		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split?: <input type="text" value="no"/>		Ground floor elevation above ground (m): <input type="text"/>		
Storeys below ground: <input type="text" value="0"/>		if Foundation type is other, describe: <input type="text"/>		
Foundation type: <input type="text" value="strip footings"/>		height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>		
Building height (m): <input type="text" value="3.00"/>		Date of design: <input type="text" value="1976-1992"/>		
Floor footprint area (approx): <input type="text" value="336"/>				
Age of Building (years): <input type="text" value="36"/>				
Strengthening present?: <input type="text" value="no"/>		If so, when (year)? <input type="text"/>		
Use (ground floor): <input type="text" value="multi-unit residential"/>		And what load level (%g)? <input type="text"/>		
Use (upper floors): <input type="text"/>		Brief strengthening description: <input type="text"/>		
Use notes (if required): <input type="text"/>				
Importance level (to NZS1170.5): <input type="text" value="IL2"/>				

<b>Gravity Structure</b>		Gravity System: <input type="text" value="load bearing walls"/>	truss depth, purlin type and cladding: <input type="text"/>
Roof: <input type="text" value="timber truss"/>		slab thickness (mm): <input type="text"/>	
Floors: <input type="text" value="concrete flat slab"/>		type: <input type="text"/>	
Beams: <input type="text" value="timber"/>		typical dimensions (mm x mm): <input type="text" value="timber (only present in some units)"/>	
Columns: <input type="text" value="other (note)"/>		#N/A: <input type="text"/>	
Walls: <input type="text" value="fully filled concrete masonry"/>			

<b>Lateral load resisting structure</b>		Lateral system along: <input type="text" value="fully filled CMU"/>	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>		Period along: <input type="text" value="0.10"/>	##### enter height above at H31	estimate or calculation? <input type="text" value="estimated"/>
Total deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>		
maximum interstorey deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>		
Lateral system across: <input type="text" value="fully filled CMU"/>		note total length of wall at ground (m): <input type="text"/>		
Ductility assumed, μ: <input type="text" value="2.00"/>		Period across: <input type="text" value="0.10"/>	##### enter height above at H31	estimate or calculation? <input type="text" value="estimated"/>
Total deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>		
maximum interstorey deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>		

<b>Separations:</b>		north (mm): <input type="text"/>	leave blank if not relevant
east (mm): <input type="text"/>			
south (mm): <input type="text"/>			
west (mm): <input type="text"/>			

<b>Non-structural elements</b>		Stairs: <input type="text"/>	describe: <input type="text"/>
Wall cladding: <input type="text" value="exposed structure"/>		describe: <input type="text"/>	
Roof Cladding: <input type="text" value="Metal"/>			
Glazing: <input type="text" value="timber frames"/>			
Ceilings: <input type="text" value="plaster, fixed"/>			
Services(list): <input type="text"/>			

<b>Available documentation</b>		Architectural: <input type="text" value="full"/>	original designer name/date: <input type="text" value="Christchurch City Council, 1995-1996"/>
Structural: <input type="text" value="partial"/>		original designer name/date: <input type="text" value="Christchurch City Council, 1995-1996"/>	
Mechanical: <input type="text" value="none"/>		original designer name/date: <input type="text"/>	
Electrical: <input type="text" value="none"/>		original designer name/date: <input type="text"/>	
Geotech report: <input type="text" value="none"/>		original designer name/date: <input type="text"/>	

<b>Damage</b>		Site performance: <input type="text" value="good"/>	Describe damage: <input type="text"/>
Site: (refer DEE Table 4-2)		notes (if applicable): <input type="text"/>	
Settlement: <input type="text" value="none observed"/>		notes (if applicable): <input type="text"/>	
Differential settlement: <input type="text" value="none observed"/>		notes (if applicable): <input type="text"/>	
Liquefaction: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>	
Lateral Spread: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>	
Differential lateral spread: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>	
Ground cracks: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>	
Damage to area: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>	

<b>Building:</b>		Current Placard Status: <input type="text" value="green"/>	Describe how damage ratio arrived at: <input type="text"/>
Along	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
Across	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
Diaphragms		Damage?: <input type="text" value="yes"/>	Describe: <input type="text" value="minor ceiling cracking"/>
CSWs:		Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Pounding:		Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Non-structural:		Damage?: <input type="text" value="yes"/>	Describe: <input type="text" value="minor cracking and damage"/>

<b>Recommendations</b>		Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text"/>
Building Consent required: <input type="text" value="no"/>		Describe: <input type="text"/>	
Interim occupancy recommendations: <input type="text" value="full occupancy"/>		Describe: <input type="text"/>	
Along	Assessed %NBS before e'quakes: <input type="text" value="27%"/>	##### %NBS from IEP below	If IEP not used, please detail assessment methodology: <input type="text" value="Equivalent Static"/>
	Assessed %NBS after e'quakes: <input type="text" value="27%"/>		
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	##### %NBS from IEP below	
	Assessed %NBS after e'quakes: <input type="text" value="100%"/>		



**Opus International Consultants Ltd**

20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

t: +64 3 363 5400

f: +64 3 365 7858

w: [www.opus.co.nz](http://www.opus.co.nz)