



CLIENTS | PEOPLE | PERFORMANCE

Denton Park Toilets
PRK 0770 BLDG 007
Detailed Engineering Evaluation
Qualitative Report
Version Final

442 Main South Road
Hornby, Christchurch



**Denton Park Toilets
PRK 0770 BLDG 007**

Detailed Engineering Evaluation
Qualitative Report
Version Final

442 Main South Road
Hornby

Christchurch City Council

Prepared By
Chris Wells

Reviewed By
Razel Ramilo

Date
23rd of May 2013



Contents

Qualitative Report Summary	i
1. Background	1
2. Compliance	2
2.1 Canterbury Earthquake Recovery Authority (CERA)	2
2.2 Building Act	3
2.3 Christchurch City Council Policy	4
2.4 Building Code	4
3. Earthquake Resistance Standards	5
4. Building Description	7
4.1 General	7
4.2 Gravity Load Resisting System	8
4.3 Lateral Load Resisting System	8
5. Assessment	9
6. Damage Assessment	10
6.1 Surrounding Buildings	10
6.2 Residual Displacements and General Observations	10
6.3 Ground Damage	10
7. Critical Structural Weakness	11
7.1 Short Columns	11
7.2 Lift Shaft	11
7.3 Roof	11
7.4 Staircases	11
7.5 Plan Irregularity	11
8. Geotechnical Consideration	12
8.1 Site Description	12
8.2 Published Information on Ground Conditions	12
8.3 Seismicity	14
9. Survey	17



10.	Initial Capacity Assessment	18
10.1	% NBS Assessment	18
10.2	Seismic Parameters	18
10.3	Expected Structural Ductility Factor	18
10.4	Discussion of Results	18
10.5	Occupancy	19
11.	Initial Conclusions	20
12.	Recommendations	21
13.	Limitations	22
13.1	General	22
13.2	Geotechnical Limitations	22

Table Index

Table 1	%NBS compared to relative risk of failure	6
Table 2	ECan Bore Log Summary Table	12
Table 3	Summary of Known Active Faults Summary of Known Active Faults	14

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	5
Figure 2	Plan Sketch Showing Key Structural Elements	7
Figure 3	Post February 2011 Earthquake Aerial Photography	14

Appendices

- A Photographs
- B CERA Building Evaluation Form



Qualitative Report Summary

Denton Park Toilets

PRK 0770 BLDG 007

Detailed Engineering Evaluation

Qualitative Report - SUMMARY

Version Final

442 Main South Road

Hornby, Christchurch

Background

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 19th July 2012.

Building Description

The building is located at 442 Main South Road, Hornby. The date of construction is estimated as 1980's and the sole use of the building is a public toilet. The building appears to be in its original form.

The approximately 25 degree duo-pitch roof is formed by corrugated sheet metal on timber board and rafters. The 200mm external walls is most probable of partial filled masonry construction while the internal wall is timber stud, both finished internally with ceramic tiles. External walls are likely supported on strip footings and the floor is a concrete slab on grade.

The building is approximately 4.2m in length by 4.2m in width with a height of 3.4m. The building occupies a footprint of approximately 17.64m² and is approximately 50m from the nearest structure. The site the building is located on is flat.

Key Damage Observed

No damage to the structure was observed.

Critical Structural Weaknesses

No critical structural weaknesses have been identified in the structure.

Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the baseline capacity (excluding critical structural weaknesses and earthquake damage) of the building has been assessed to be in the order of 59% NBS.



There was no damage nor critical structural weaknesses identified in our visual inspection; consequently have not reduced the baseline %NBS.

The building has therefore been assessed to have a seismic capacity in the order of 59% NBS and is potentially of Earthquake Risk.

Recommendations

The building has not been assessed as being Earthquake Prone. As a result, the building can remain occupied. However, GHD recommends a quantitative assessment of the building be undertaken to confirm the seismic capacity.



1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Denton Park toilets.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. No construction drawings were made available, hence the evaluation is based on our visual inspections.



2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage



2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



3. Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’ (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The building is located at 442 Main South Road, Hornby. The date of construction is estimated as 1980's and the sole use of the building is a public toilet. The building appears to be in its original form.

The approximately 25 degree duo-pitch roof is formed by corrugated sheet metal on timber board and rafters. The 200mm external walls is most probable of partial filled masonry construction while the internal wall is timber stud, both finished internally with ceramic tiles. External walls are likely supported on strip footings and the floor is a concrete slab on grade.




Figure 2 Plan Sketch Showing Key Structural Elements

The building is approximately 4.2m in length by 4.2m in width with a height of 3.4m. The building occupies a footprint of approximately 17.64m² and is approximately 50m from the nearest structure. The site the building is located on is flat.

No plans are available for the structure.



4.2 Gravity Load Resisting System

The building resists gravity loads by load bearing concrete masonry walls. Gravity loads on the roof are transferred via rafters and the propped timber ridge beam to walls. The walls support the gravity loads and transfer them to the strip footings where they distribute into the ground. Floor gravity loads are transferred through the concrete slab to grade and the underlying ground.

4.3 Lateral Load Resisting System

Lateral loads are resisted primarily by the panel action of concrete masonry units. In both transverse and longitudinal directions, lateral roof loads are transferred to walls by the diaphragm action of roof timber boards and rafters and into the foundations.



5. Assessment

An inspection of the building was undertaken on the 19th June 2012. Both the interior and exterior of the building were inspected.

The inspection consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for this building has been based on the IEP procedure described by the NZSEE and based on the information obtained from visual observation of the building.



6. Damage Assessment

6.1 Surrounding Buildings

The toilet is relatively isolated with the nearest structure approximately 50m away.

6.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during our inspection of the building.

6.3 Ground Damage

There was no evidence of ground damage in the park area.



7. Critical Structural Weakness

7.1 Short Columns

No critical short columns are present in the structure.

7.2 Lift Shaft

The building does not contain a lift shaft.

7.3 Roof

Close spacing of timber boards on rafters stiffens the structure and distribute more effectively loads to the walls in-plane. Critical structural weakness is not observed due to the diaphragm capability of the roof.

7.4 Staircases

The building does not contain a staircase.

7.5 Plan Irregularity

In the longitudinal direction, the lateral loads are resisted by the concrete masonry walls located to the front and rear of the building. The four door openings in the front of the building result in a difference in stiffness between the opposing sides. Under strong lateral loading this may produce some torsional effects; however, due to the close spacing of the walls this is not regarded as a critical structural weakness.



8. Geotechnical Consideration

8.1 Site Description

The site is located between the Main South Railway Line to the north and Main South Road (SH1) to the south. It is bound to the east by commercial properties and west by residential properties. The property is owned and maintained by the Christchurch City Council.

The site is situated within a recreational reserve, within the suburb of Hornby in western Christchurch. It is relatively flat at approximately 30m above mean sea level. It is approximately 2.5km west of the Heathcote River, and 15km west of the coast (Pegasus Bay) at New Brighton.

8.2 Published Information on Ground Conditions

8.2.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by Holocene alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, comprising alluvial gravel, sand, and silt of historic river flood channels.

8.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that eight boreholes are located within a 200m radius of the site. Of these boreholes, six of them had a lithographic log of which the four most relevant are summarised below. The site geology described in these logs shows the area is predominantly sandy gravels with varying amounts of silt and clay.

Table 2 ECan Bore Log Summary Table

Bore Name	Depth (m bgl)	Log Summary
M35/1865	0 – 1	Hardfill
(110m SE of site)	1 – 21	Fine to coarse GRAVEL and SAND
	21 – 49	Medium dense to dense GRAVEL, with some sand and clay
	49 – 52	Dense GRAVEL, with sand and clay
	52 – 79	Fine to medium GRAVEL, with traces of clay
	79 – 86	Sandy medium GRAVEL
	86 – 88	PEAT
	88 – 94	Dense GRAVEL, and stiff CLAY
	94 – 102	Dense Sandy GRAVEL, with some yellow clay

¹ Brown, L. J. and Weeber J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.



Bore Name	Depth (m bgl)	Log Summary
M35/3546	0 – 0.3	Filling Material
	0.3 – 3.9	SILT
	3.9 – 40.5	Sandy GRAVEL, with some clay
	40.5 – 49.5	CLAY, with some gravel and peat
	49.5 – 52	Dense GRAVEL, with some clay
	52 – 95.8	Layers of CLAY, SAND and GRAVEL
M35/7739	0 – 6	Gravelly SAND
	6 – 23.5	Sandy GRAVEL, with traces of silt and clay
	23.5 – 29.5	Sandy GRAVEL
M35/7743	0 – 1	Clayey GRAVEL
	1 – 9	Sandy GRAVEL, with some clay and silt
	9 – 10.8	Sandy GRAVEL
	10.8 – 12.5	Slightly clayey, fine SAND
	12.5 – 20.7	Clayey GRAVEL and sandy GRAVEL

It should be noted that the purpose of the boreholes the well logs are associated with, were sunk for groundwater extraction and not for geotechnical purposes. Therefore, the amount of material recovered and available for interpretation and recording will have been variable at best and may not be representative. The logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

8.2.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the site.

8.2.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has published areas showing the Green Zone Technical Category in relation to the risk of future liquefaction and how these areas are expected to perform in future earthquakes.

The site is in the “not applicable” technical category. Not applicable means that non-residential properties in urban areas, properties in rural areas or beyond the extent of land damage mapping, and properties in the Port Hills and Banks Peninsula have not been given a Technical Category.

8.2.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows no signs of liquefaction outside the building footprint or adjacent to the site, as shown in the Figure 3.

Figure 3 Post February 2011 Earthquake Aerial Photography²



8.2.6 Summary of Ground Conditions

From the ECan borehole information the ground conditions on Main South Road comprise multiple strata of gravel, sandy gravel and sand, with varying amounts of silt and clay.

8.3 Seismicity

8.3.1 Nearby Faults

There are many faults in the Christchurch region, however only those considered most likely to have an adverse effect on the site are detailed in Table 3.

Table 3 Summary of Known Active Faults Summary of Known Active Faults³⁴

Known Active Fault	Distance from Site (km)	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120	8.3	~300 years
Greendale (2010) Fault	13	7.1	~15,000 years

² Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>

³ Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

⁴ GNS Active Faults Database



Known Active Fault	Distance from Site (km)	Max Likely Magnitude	Avg Recurrence Interval
Hope Fault	100	7.2~7.5	120~200 years
Kelly Fault	100	7.2	~150 years
Porters Pass Fault	54	7.0	~1100 years

Recent earthquakes since 22 February 2011 have identified the presence of a new active fault system / zone underneath Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.3.2 Ground Shaking Hazard

This seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

8.3.3 Slope Failure and/or Rockfall Potential

The site is located within Hornby, a flat suburb in western Christchurch. Global slope instability risk is considered negligible. However, any localised retaining structures and/or embankments should be further investigated to determine the site-specific slope instability potential.

8.3.4 Liquefaction Potential

No effects of liquefaction were reportedly observed at the ground surface in Hornby.

Due to the anticipated presence of predominantly gravels and sandy gravels beneath the site, it is considered that liquefaction is less likely to occur at this site than other areas of Christchurch. However, during the inspection undertaken on 18th January, no liquefaction was observed. However, the grain size of the sands present is not recorded, and silts are also recorded as present in varying amounts within the gravels. Therefore it is considered possible and likely that liquefaction will occur where sands and silts are present.

8.3.5 Recommendations

If a more detailed assessment is required to quantify the assessment results then an intrusive investigation comprising of at least one piezocone CPT test to 20m bgl should be undertaken. This will allow a numerical liquefaction analysis to be carried out.

8.3.6 Conclusions & Summary

This assessment is based on a review of the published geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.



The site appears to be situated on stratified alluvial deposits, comprising gravel, sand and silt. Considering these likely anticipated ground conditions the site also has a low-moderate liquefaction potential, the potential, the potential is increased however where sands and/or silts are present.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that an intrusive investigation comprising of at least one piezocone CPT be conducted.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.



9. Survey

No level or verticality surveys have been undertaken for this building at this stage as indicated by Christchurch City Council guidelines.



10. Initial Capacity Assessment

10.1 % NBS Assessment

The building's capacity was assessed using the Initial Evaluation Procedure based on the information available. The building's capacity is expressed as a percentage of New Building Standard (%NBS) as shown below. This capacity is subject to confirmation by a more detailed quantitative analysis.

<u>Item</u>	<u>%NBS</u>
Building's seismic capacity (No CSW observed)	59

Table 4 Indicative Building's Capacity based on the NZSEE Initial Evaluation Procedure

Following an IEP assessment, the building has been assessed as achieving 59% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered Earthquake Risk as it achieves greater than 33% and less than 67% NBS. This score has not been adjusted when considering damage to the structure as none was observed.

10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- Site soil class: D, NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- Return period factor $R_u = 1$, NZS 1170.5:2004, Table 3.5, Importance level 2 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

10.3 Expected Structural Ductility Factor

A structural ductility factor 1.25 has been assumed based on the structural system observed and the date of construction.

10.4 Discussion of Results

Although the buildings construction date is unknown, comparisons were made with similarly constructed buildings and an engineering judgment was made that the building was constructed in or around 1980's. The building was likely designed to the loading standard current at the time, NZS 4203:1976. The design loads used in accordance with this standard are likely to have been less than those required by the current loading standard. When combined with the increase in the hazard factor for Christchurch to 0.3, it would be expected that the building would not achieve 100% NBS.

There was no damage nor critical structural weaknesses identified in our visual inspection; consequently the %NBS has not reduced the baseline percentage of NBS as 59%.



10.5 Occupancy

The building does not pose an immediate risk to users and occupants. Following the assessment the building has not been found to be earthquake prone and as such can remain occupied.



11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 59% NBS and is therefore potentially Earthquake Risk.



12. Recommendations

The recent seismic activity in Christchurch has caused no visible damage to the building, with no visible damage to any of the buildings elements as a result of significant earthquakes.

As the building is not potentially earthquake prone it can remain occupied. However, as the building is potentially earthquake risk, GHD recommends that a quantitative detailed seismic assessment is undertaken.



13. Limitations

13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report. A specific limitations section.

13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.



Appendix A
Photographs



Photograph 1 Toilet South-west Elevation



Photograph 2 Toilet South-east Elevation



Photograph 3 Toilet North-east Elevation



Photograph 4 Toilet North-west Elevation



Photograph 5 Toilet exposed rafters



Photograph 6 Toilet eave detail



Photograph 7 Toilet roof



Photograph 8 Toilet entrance



Photograph 9 Toilet partition



Photograph 10 Toilet exposed rafters showing the connection between rafters and block wall



Appendix B
CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: <input type="text" value="Denton Park Toilets"/>	Reviewer: <input type="text" value="Stephen Lee"/>
Building Address: <input type="text" value="7 442 Main South Road"/>	Unit No: <input type="text" value="7 442"/>	Street: <input type="text" value="Main South Road"/>	CPEng No: <input type="text" value="1006840"/>
Legal Description: <input type="text" value="RS 41304"/>			Company: <input type="text" value="GHD"/>
		Company project number: <input type="text" value="513090247"/>	Company phone number: <input type="text" value="04 472 0799"/>
GPS south: <input type="text" value="43 32 36.90"/>	Degrees	Min	Sec
GPS east: <input type="text" value="172 31 16.10"/>			
Building Unique Identifier (CCC): <input type="text" value="PRK_0770_BLDG_007"/>	Date of submission: <input type="text" value="23/05/2013"/>		Inspection Date: <input type="text" value="19/07/2012"/>
		Revision: <input type="text" value="Final"/>	Is there a full report with this summary? <input type="text" value="yes"/>

Site		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
		Soil type: <input type="text" value="mixed"/>	Soil Profile (if available): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="D"/>		If Ground improvement on site, describe: <input type="text"/>	
Proximity to waterway (m, if <100m): <input type="text"/>			Approx site elevation (m): <input type="text" value="30.00"/>
Proximity to clifftop (m, if < 100m): <input type="text"/>			
Proximity to cliff base (m,if <100m): <input type="text"/>			

Building		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value="30.30"/>
Ground floor split? <input type="text" value="no"/>	Storesys below ground: <input type="text" value="0"/>	Foundation type: <input type="text" value="strip footings"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>	Ground floor elevation above ground (m): <input type="text" value="0.30"/>
Building height (m): <input type="text" value="3.40"/>	Floor footprint area (approx): <input type="text" value="18"/>	Age of Building (years): <input type="text" value="32"/>	if Foundation type is other, describe: <input type="text"/>	
Strengthening present? <input type="text" value="no"/>			Date of design: <input type="text" value="1976-1992"/>	
Use (ground floor): <input type="text" value="public"/>			If so, when (year)? <input type="text"/>	
Use (upper floors): <input type="text"/>			And what load level (%g)? <input type="text"/>	
Use notes (if required): <input type="text" value="Public Toilet"/>			Brief strengthening description: <input type="text"/>	
Importance level (to NZS1170.5): <input type="text" value="IL2"/>				

Gravity Structure		Gravity System: <input type="text" value="load bearing walls"/>	rafter type, purlin type and cladding: <input type="text" value="metal cladding on board and rafters"/>
Roof: <input type="text" value="timber framed"/>	Floors: <input type="text" value="concrete flat slab"/>	Beams: <input type="text" value="none"/>	slab thickness (mm): <input type="text" value="Slab on grade"/>
Columns: <input type="text" value="none"/>	Walls: <input type="text" value="partially filled concrete masonry"/>	overall depth x width (mm x mm): <input type="text"/>	typical dimensions (mm x mm): <input type="text"/>
		thickness (mm): <input type="text" value="20 series concrete block masonry"/>	

Lateral load resisting structure		Lateral system along: <input type="text" value="partially filled CMU"/>	Note: Define along and across in note total length of wall at ground (m): <input type="text"/>
---	--	---	---

Ductility assumed, μ :
 Period along:
 Total deflection (ULS) (mm):
 maximum interstorey deflection (ULS) (mm):

detailed report!
 ##### enter height above at H31

wall thickness (m):
 estimate or calculation?
 estimate or calculation?
 estimate or calculation?

Lateral system across:
 Ductility assumed, μ :
 Period across:
 Total deflection (ULS) (mm):
 maximum interstorey deflection (ULS) (mm):

note total length of wall at ground (m):
 wall thickness (m):
 estimate or calculation?
 estimate or calculation?
 estimate or calculation?

Separations:

north (mm):
 east (mm):
 south (mm):
 west (mm):

leave blank if not relevant

Non-structural elements

Stairs:
 Wall cladding:
 Roof Cladding:
 Glazing:
 Ceilings:
 Services(list):

describe
 describe
 describe

Available documentation

Architectural
 Structural
 Mechanical
 Electrical
 Geotech report

original designer name/date
 original designer name/date
 original designer name/date
 original designer name/date
 original designer name/date

Damage

Site:
 (refer DEE Table 4-2)

Site performance:
 Settlement:
 Differential settlement:
 Liquefaction:
 Lateral Spread:
 Differential lateral spread:
 Ground cracks:
 Damage to area:

Describe damage:

notes (if applicable):
 notes (if applicable):

Building:

Current Placard Status:

Along
 Damage ratio:
 Describe (summary):

Describe how damage ratio arrived at:

Across
 Damage ratio:
 Describe (summary):

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

Diaphragms	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
CSWs:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text" value="No damage observed"/>
Pounding:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Non-structural:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text" value="No damage observed"/>

Recommendations

Level of repair/strengthening required:	<input type="text" value="none"/>	Describe:	<input type="text"/>
Building Consent required:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Interim occupancy recommendations:	<input type="text" value="full occupancy"/>	Describe:	<input type="text"/>

Along	Assessed %NBS before:	<input type="text" value="59%"/>	59% %NBS from IEP below	If IEP not used, please detail assessment methodology:	<input type="text"/>
	Assessed %NBS after:	<input type="text" value="59%"/>			
Across	Assessed %NBS before:	<input type="text" value="59%"/>	59% %NBS from IEP below		
	Assessed %NBS after:	<input type="text" value="59%"/>			

IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1976-1992 h_n from above: m

Seismic Zone, if designed between 1965 and 1992: not required for this age of building
not required for this age of building

	along	across
Period (from above):	0.4	0.4
(%NBS) _{nom} from Fig 3.3:	<input type="text" value="16.5%"/>	<input type="text" value="16.5%"/>

Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0

Note 2: for RC buildings designed between 1976-1984, use 1.2

Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)

	along	across
Final (%NBS)_{nom}:	<input type="text" value="17%"/>	<input type="text" value="17%"/>

2.2 Near Fault Scaling Factor Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

	along	across
Near Fault scaling factor (1/N(T,D), Factor A:	<input type="text" value="1"/>	<input type="text" value="1"/>

2.3 Hazard Scaling Factor Hazard factor Z for site from AS1170.5, Table 3.3:

	<input type="text" value="0.8"/>
Hazard scaling factor, Factor B:	<input type="text" value="3.33333333"/>

2.4 Return Period Scaling Factor Building Importance level (from above):

Return Period Scaling factor from Table 3.1, Factor C:	<input type="text" value="1.00"/>
---	-----------------------------------

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2)
 Ductility scaling factor: =1 from 1976 onwards; or =kμ, if pre-1976, from Table 3.3:

	along	across
Assessed ductility (less than max in Table 3.2)	1.25	1.25
Ductility scaling factor: =1 from 1976 onwards; or =kμ, if pre-1976, from Table 3.3:	1.00	1.00

Ductility Scaling Factor, **Factor D:**

along	1.00	1.00
-------	------	------

2.6 Structural Performance Scaling Factor:

Sp:

along	0.925	0.925
-------	-------	-------

Structural Performance Scaling Factor **Factor E:**

along	1.081081081	1.081081081
-------	-------------	-------------

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS_b:

along	59%	59%
-------	-----	-----

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

	1
--	---

3.2. Vertical irregularity, Factor B:

	1
--	---

3.3. Short columns, Factor C:

	1
--	---

3.4. Pounding potential

Pounding effect D1, from Table to right	1.0
Height Difference effect D2, from Table to right	1.0

Therefore, Factor D: **1**

3.5. Site Characteristics

	1
--	---

Table for selection of D1	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum
 Rationale for choice of F factor, if not 1

	Along	Across
For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum	1.0	1.0
Rationale for choice of F factor, if not 1		

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

along	1.00	1.00
-------	------	------

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS:

along	59%	59%
-------	-----	-----

4.4 Percentage New Building Standard (%NBS), (before)

	59%
--	-----

Official Use only:

Accepted By:
 Date:



GHD

Level 11, Guardian Trust House
15 Willeston street, Wellington 6011
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

© GHD Limited 2013

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Chris Wells	Razel Ramilo		Stephen Lee		23/5/13