

Christchurch City Council

Huggins Place Housing Complex PRO 0638

**Detailed Engineering Evaluation
Quantitative Assessment Report**



Christchurch City Council

Huggins Place Housing Complex Quantitative Assessment Report

Huggins Place, Richmond,

Prepared By




Chris Gilbert
Graduate Structural Engineer

Opus International Consultants Ltd
Christchurch Office

20 Moorhouse Avenue
PO Box 1482, Christchurch Mail
Centre, Christchurch 8140
New Zealand

Reviewed By




Lachlan Howat
Structural Engineer

Telephone: +64 3 363 5400
Facsimile: +64 3 365 7858

Date: February 2014
Reference: 6-QC361.00
Status: Final

Approved for
Release By



Mary Ann Halliday
Senior Structural Engineer

Summary

Huggins Place Housing Complex
PRO 0638

Detailed Engineering Evaluation
Quantitative Report - Summary
Final

Background

This is a summary of the quantitative report for the Huggins Place Housing Complex, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This assessment covers the 30 residential units on the site.

Key Damage Observed

The residential units have suffered moderate damage to structural and non-structural elements. This included cracking of the weatherboard veneer cladding due to settlement of the perimeter wall and shear cracking. There is also cracking to both the render and the concrete of the perimeter footing in all residential unit blocks. Cracking was severe in the extension perimeter walls of block F and G. This damage was deemed low enough to not affect the capacities of the buildings.

Level Survey

All accessible floor slopes were assessed in a full level survey. All floor slopes were greater than the 5mm/m limitation set out in the MBIE guidelines [6], as shown below.

Internal Lining Nail Spacings

The internal lining nail spacings were measured on site to vary between 300-400mm.

Critical Structural Weaknesses

No critical structural weaknesses were found in any of the buildings.

Indicative Building Strength

Table A: Summary of Seismic Performance by Blocks

| Block | NBS% | Indicative Floor Levels | Nail Spacings |
|-------------------------|------|-------------------------|---------------|
| PRO 0638 B001 (Block A) | 43% | Fail | Pass |
| PRO 0638 B002 (Block B) | 43% | Fail | Pass |
| PRO 0638 B003 (Block C) | 43% | Fail | Pass |
| PRO 0638 B004 (Block D) | 43% | Fail | Pass |
| PRO 0638 B005 (Block E) | 43% | Fail | Pass |
| PRO 0638 B006 (Block F) | 43% | Fail | Pass |
| PRO 0638 B007 (Block G) | 43% | Fail | Pass |
| PRO 0638 B008 (Block H) | 43% | Fail | Pass |

No buildings on the site are considered to be earthquake prone.

The residential units (Blocks A – H) have capacities of 43%NBS as limited by the in-plane shear capacity of the timber-framed shear walls in the longitudinal direction. They are deemed to be a ‘moderate risk’ in a design seismic event according to NZSEE guidelines.

Increasing the number of nails in the plasterboard will not significantly improve the strength of the buildings.

Recommendations

It is recommended that;

- Strengthening schemes be developed to increase the seismic capacity of Blocks A – H to at least 67%NBS.
- Units be releveled as required.
- The concrete perimeter footings be repaired where cracking occurs.
- Additional weight in the roof space be removed, in particular, the concrete header tanks.
- Cosmetic repairs be undertaken as required.

Contents

| | |
|---|-----------|
| Summary | i |
| 1 Introduction..... | 4 |
| 2 Compliance | 4 |
| 3 Earthquake Resistance Standards..... | 8 |
| 4 Background Information..... | 10 |
| 5 Damage | 13 |
| 6 Detailed Seismic Assessment | 14 |
| 7 Geotechnical Summary | 17 |
| 8 Conclusions..... | 17 |
| 9 Recommendations | 17 |
| 10 Limitations..... | 18 |
| 11 References | 18 |
| Appendix A – Photographs | |
| Appendix B – Level Survey | |
| Appendix C – Methodology and Assumptions | |
| Appendix D – CERA DEE Spreadsheet | |

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Huggins Place Housing Complex, located at Huggins Place, Richmond, following the Canterbury earthquake sequence since September 2010. The site was visited by Opus International Consultants on 4 December 2013 and 12 December 2013.

The purpose of the assessment is to determine if the buildings in the complex are classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [2] [3] [4] [5].

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.
2. The placard status and amount of damage.

3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in October 2011 following the Darfield Earthquake on 4 September 2010.

The policy includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure, was amended to include increased seismic design requirements for Canterbury as follows:

- Increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

| Description | Grade | Risk | %NBS | Existing Building Structural Performance | Improvement of Structural Performance | |
|------------------------|--------|----------|-------------|---|---|---|
| | | | | | Legal Requirement | NZSEE Recommendation |
| Low Risk Building | A or B | Low | Above 67 | Acceptable (improvement may be desirable) | The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS. | 100%NBS desirable. Improvement should achieve at least 67%NBS |
| Moderate Risk Building | B or C | Moderate | 34 to 66 | Acceptable legally. Improvement recommended | | Not recommended. Acceptable only in exceptional circumstances |
| High Risk Building | D or E | High | 33 or lower | Unacceptable (Improvement required under Act) | Unacceptable | Unacceptable |

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines [2]

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

| Percentage of New Building Standard (%NBS) | Relative Risk (Approximate) |
|--|-----------------------------|
| >100 | <1 time |
| 80-100 | 1-2 times |
| 67-80 | 2-5 times |
| 33-67 | 5-10 times |
| 20-33 | 10-25 times |
| <20 | >25 times |

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the MBIE guidance document dated December 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority.

The residential units are timber-framed buildings with diagonal timber braces. The roof structure comprises of timber roof framing supporting light-weight metal roofs with timber sarking. The walls and ceilings are lined with plasterboard. External walls are clad with a light timber veneer. Foundations consist of ordinary concrete piles with a concrete perimeter wall. The extension, constructed in 1988, is also founded on concrete piles with a concrete perimeter wall.

The units are separated by 190mm block masonry fire walls which (based on information available for other similar blocks of the same era) is potentially filled with reinforcement to its perimeter. A reinforced bond beam is assumed to be located at ceiling height within the block fire wall.

Figure 4 shows a typical floor plan of a residential unit produced from site measurements by Opus.




Figure 4: Typical partial floor plan of residential unit blocks.

4.2 Survey

4.2.1 Level Survey

A full level survey was deemed to be necessary at Huggins Place as it is located in a TC3 zone. Properties in TC3 zones suffered moderate to severe damage due to liquefaction and/or settlement. A gas level was used to determine floor elevations of each unit where the datum was set up such that each block could be compared as a whole. These values could then be used to determine the floor slope of the entire unit. For this site, the maximum slope in a unit was 16mm/m (which exceeds the 5mm/m limitation imposed by MBIE guidelines). This guideline was exceeded in all units either by a localised residual displacement or a slope over the entire unit.

Table 2: Summary of the Level Survey

| Block | Unit No. | Comment | Maximum Fall* |
|-------|----------|-----------|---------------|
| A | 1 | Fail | 9 mm/m |
| | 3 | Fail | 9 mm/m |
| | 5 | Fail | 9 mm/m |
| B | 7 | Fail | 8 mm/m |
| | 9 | Fail | 8 mm/m |
| | 11 | Fail | 15 mm/m |
| C | 15 | Fail | 9 mm/m |
| | 17 | Fail | 10 mm/m |
| | 19 | Fail | 6 mm/m |
| | 21 | Fail | 11 mm/m |
| D | 23 | Fail | 7 mm/m |
| | 25 | Fail | 7 mm/m |
| | 27 | Fail | 5 mm/m |
| | 29 | Fail | 8 mm/m |
| E | 31 | Fail | 14 mm/m |
| | 33 | Fail | 7 mm/m |
| | 35 | Fail | 12 mm/m |
| | 37 | Fail | 14 mm/m |
| F | 2 | Fail | 16 mm/m |
| | 4 | Fail | 16 mm/m |
| | 6 | Fail | 11 mm/m |
| | 8 | Fail | 8 mm/m |
| G | 10 | Fail | 16 mm/m |
| | 12 | Fail | 5 mm/m |
| | 14 | No Access | - |
| | 16 | Fail | 8 mm/m |
| H | 18 | Fail | 11 mm/m |
| | 20 | Fail | 8 mm/m |
| | 22 | Fail | 10 mm/m |
| | 24 | Fail | 10 mm/m |

* Values are only recorded if greater than 5mm/m

4.2.2 Nail Spacings

The internal lining nail spacings were measured on site to vary between 300-400mm. Increasing the number of nails in the plasterboard will not significantly improve the strength of the buildings.

4.3 Original Documentation

The following documentation was provided by the Christchurch City Council:

- A.82/11 – Christchurch City Council – Pensioner's Cottages Hills Road For The C.C.C – p. 1/1 – Site Plan – 1956.
- BU/1B/1– Christchurch City Council – Huggins Place Remodelling – p. 1/1 – Floor Plan – 1988.

In addition, a typical floor plan has been produced by Opus to help confirm as-built measurements.

Copies of the design calculations were not provided.

5 Damage

This section outlines the damage to the buildings that was observed during site visits. It is not intended to be a complete summary of the damage sustained by the buildings due to the earthquakes. Some forms of damage may not be able to be identified with a visual inspection only.

It was observed that all units suffered residual displacement resulting in excessive floor slopes.

Note: Any photo referenced in this section can be found in Appendix A.

5.1 Residual Displacements

Residual displacements were observed in all units. Slopes in all units exceeded the MBIE guideline of 5 mm/m. Blocks typically sloped upward toward the north.

5.2 Foundations

The concrete piles have settled differentially causing excessive floor slopes. There is moderate cracking to the concrete perimeter wall, this cracking was observed to extend through both the render and the concrete itself. Cracks greater than 3.5mm were observed in the new concrete perimeter wall of Blocks F and G (photo 22).

5.3 Primary Gravity Structure

No damage was observed to the primary gravity structure.

5.4 Primary Lateral-Resistance Structure

Plasterboard cracking was observed in all units typically above doorways, windows and at the roofline. Cracking of the ceiling diaphragm was also observed.

5.5 Non Structural Elements

Cracking through the weatherboard veneer was observed at the ends of most blocks (photo 16). Hairline cracking of the concrete entrance patio was observed in all units. Minor splitting was observed between the weatherboard veneer and the firewall (photo 20).

5.6 General Observations

Concrete header tanks were located within the roof space (photo 19).

The buildings appeared to have performed as would be reasonably expected for buildings of this type, during the earthquakes. They have suffered distributed amounts of minor damage which is typical of the construction type and age.

6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

As the residential units have the same floor plan, the analysis was simplified by conducting the analysis of one multi-unit block with similar cladding and using this for all multi-unit blocks.

6.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSWs were identified in the buildings.

6.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix C. A brief summary follows:

Hand calculations were performed to determine seismic forces from the current building codes. These forces were applied globally to the structure and the capacities of the walls were calculated and used to estimate the %NBS. The walls, highlighted in Figure 5 and Figure 6, were used for bracing in their respective directions.




Figure 5: Walls used for bracing in the longitudinal direction.




Figure 6: Walls used for bracing in the transverse direction.

6.3 Limitations and Assumptions in Results

The observed level of damage suffered by the buildings was deemed low enough to not affect their capacity. Therefore the analysis and assessment of the buildings was based on them being in an undamaged state. There may have been damage to the buildings that was unable to be observed that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections.
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.
- Construction is consistent with normal practise of the era in which constructed.

6.4 Assessment

A summary of the structural performance of the buildings is shown in Table 3. Note that the values given represent the worst performing elements in the building, where these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

Table 3: Summary of Seismic Performance

| Building Description | Critical element | % NBS based on calculated capacity in longitudinal direction | % NBS based on calculated capacity in transverse direction. |
|----------------------------------|--|--|---|
| Residential Units (Blocks A – H) | Timber bracing in the longitudinal direction | 43% | 100% |

7 Geotechnical Summary

CERA indicates that Huggins Place is located in a TC3 zone (as shown in Figure 7). This classification suggests future significant earthquakes likely to cause moderate to severe land damage due to liquefaction and settlement.




Figure 7: CERA Technical Categories map (loc. starred).

There is no evidence to suggest that further geotechnical investigation is warranted for this site.

8 Conclusions

- None of the buildings on site are considered to be Earthquake Prone.
- The residential units (Blocks A – H) have capacities of 43% NBS, as limited by the in-plane capacity of the bracing walls. They are deemed to be a ‘moderate risk’ in a design seismic event according to NZSEE guidelines. Their level of risk is 5-10 times that of a 100% NBS building (Figure 1).
- Based on the geotechnical appraisal, differential settlement as a result of liquefaction could result in further damage, similar in nature to that which has occurred in the recent earthquake sequence. However, based on the nature of construction, this is unlikely to result in the collapse of structure.

9 Recommendations

It is recommended that;

- Strengthening schemes be developed to increase the seismic capacity of Blocks A – H to at least 67%NBS.
- Units be releveled as required.
- The concrete perimeter footings be repaired where cracking occurs.
- Additional weight in the roof space be removed, in particular, the concrete header tanks.
- Cosmetic repairs be undertaken as required.

10 Limitations



- This report is based on an inspection of the buildings and focuses on the structural damage resulting from the Canterbury Earthquake sequence since September 2010. Some non-structural damage may be described but this is not intended to be a complete list of damage to non-structural items.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- This report is prepared for the Christchurch City Council to assist in the assessment of any remedial works required for the Huggins Place Housing Complex. It is not intended for any other party or purpose.

11 References




- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] MBIE (2012), Repairing and rebuilding houses affected by the Canterbury earthquakes, Ministry of Building, Innovation and Employment, December 2012.

Appendix A – Photographs




Huggins Place Housing Complex – Detailed Engineering Evaluation




| Huggins Place Housing Complex | | |
|-------------------------------|------------------------------------|--|
| No. | Item description | Photo |
| Residential Units Layout | | |
| 1. | Complex view |  |
| 2. | Typical exterior elevation (front) |  |



Huggins Place Housing Complex – Detailed Engineering Evaluation



| | | |
|----|----------------------------------|--|
| 3. | Typical exterior elevation (end) |  |
| 4. | Typical lounge view (Blocks A-E) |  |
| 5. | Typical lounge view (Blocks A-E) |  |




Huggins Place Housing Complex – Detailed Engineering Evaluation




| | | |
|----|-------------------------------------|---|
| 6. | Typical kitchen view |  A photograph of a kitchen interior. On the left is a white electric stove with a blue and white patterned towel hanging over its front. To the right of the stove is a white countertop with a double sink and a chrome faucet. Above the sink is a window with white blinds. On the wall above the stove, there is a wooden rack with various kitchen items. To the right of the sink, a grey jacket is hanging on a hook. The floor is covered with light-colored square tiles. |
| 7. | Typical bedroom view |  A photograph of a bedroom. A bed with a yellow pillow and a dark purple blanket is visible. To the left of the bed is a large, floor-to-ceiling wardrobe with glass doors and internal lighting. A patterned curtain hangs on the wall behind the bed. The room has white walls and a light-colored floor. |
| 8. | Typical lounge view (Blocks F-H) |  A photograph of a lounge area. A man is sitting on a small wooden table in the foreground, looking at a television. The television is on a stand and displays a colorful image. On the wall above the television, there is a poster of the band Pink Floyd. To the left of the television, there is a desk with various items on it, including a laptop and some papers. A large window with white blinds is on the right side of the room. The floor is covered with a dark carpet. |


| | | |
|-----|------------------------------------|--|
| 9. | Typical roof space (Blocks A-E) |  |
| 10. | Typical roof space (Blocks F-H) |  |
| 11. | Typical floor space |  |

| | | |
|-----|---------------------------------|---|
| 12. | Typical cracking above doorways |  A photograph showing a vertical crack in the wall above a doorway. The ceiling is textured, and the wall is a light beige color. A doorway is visible on the left, and some items are on the right. |
| 13. | Typical cracking around windows |  A photograph showing a hand pointing to a crack in the wall around a window. The wall is light grey, and the window has a colorful, patterned curtain. |

| | | |
|-----|---|--|
| 14. | Typical cracking at the roofline |  A photograph showing the corner of a room where the ceiling meets the wall. There is a significant crack running along the roofline, and some peeling paint is visible on the wall. |
| 15. | Typical cracking of the ceiling diaphragm |  A photograph showing a large, vertical crack running down the center of a white ceiling. A light fixture is visible on the ceiling, and a box is on the floor in the bottom left corner. |


| | | |
|-----|--|---|
| 16. | Cracking through the weatherboard veneer |  A photograph showing a vertical crack running through a light-colored, horizontal weatherboard veneer on an exterior wall. Below the veneer, a concrete foundation is visible, and some green foliage is at the base of the wall. |
| 17. | Cracking of the concrete perimeter wall |  A close-up photograph of a concrete perimeter wall. A vertical crack is visible on the left side of the wall. To the right, there is a rectangular section of the wall with a grid-like pattern, possibly a drainage or ventilation feature. The ground at the base of the wall is covered with some debris and small plants. |
| 18. | Cracking of the concrete patio |  A photograph of a concrete patio surface. A horizontal crack runs across the middle of the frame. On the right side, a portion of a yellow metal railing is visible, suggesting the patio is adjacent to a walkway or stairs. |

| | | |
|-----|--|--|
| 19. | Concrete water tank (Blocks A-E) |  |
| 20. | Slight splitting of the veneer and firewall |  |
| 21. | 400mm nail spacings |  |


| | | |
|-----|---|--|
| 22. | Cracking of the extension perimeter wall of Blocks F and G (greater than 3.5mm) |  |
|-----|---|--|

Appendix B – Level Survey


Huggins Place Housing Complex – Detailed Engineering Evaluation




Unit 23



Unit 25




Unit 27




Unit 29


Huggins Place Housing Complex – Detailed Engineering Evaluation




Unit 10



Unit 12




Unit 14




Unit 16


Huggins Place Housing Complex – Detailed Engineering Evaluation




Unit 18



Unit 20



Unit 22



Unit 24

Appendix C – Methodology and Assumptions

Seismic Parameters

As per NZS 1170.5:

- $T < 0.4s$ (assumed)
- Soil: Category D
- $Z = 0.3$
- $R = 1.0$ (IL2, 50 year)
- $N(T,D) = 1.0$

For the analyses, a μ of 2 was assumed for the residential units.

Analysis Procedure

As the units are small and have a number of closely spaced walls in both directions, the fibrous plaster board ceilings are assumed to be capable of transferring loads to all walls. It was therefore assumed that a global method could be used to carry the forces down to ground level in each direction. Bracing capacities were found by assuming a certain kN/m rating for the walls along each line. Due to the relatively unknown nature of the walls, the kN/m rating was taken as 3 kN/m for all timber walls with an aspect ratio (height: length) of less than 2:1. This was scaled down to zero kN/m at an aspect ratio of 3.5:1 as per NZSEE guidelines. %NBS values were then found through the ratio of bracing demand to bracing capacity for all walls in each direction.

Additional Assumptions

Further assumptions about the seismic performance of the buildings were:

- Foundations and foundation connections had adequate capacity to resist and transfer earthquake loads.
- Connections between all elements of the lateral load resisting systems are detailed to adequately transfer their loads sufficiently and are strong enough so as to not fail before the lateral load resisting elements.

Appendix D – CERA DEE Spreadsheet

Detailed Engineering Evaluation Summary Data

V1.14

Location

| | | | | | |
|-----------------------------------|-------------------------------|----------|-------|--------|-------|
| Building Name: | Huggins Place Housing Complex | Unit No: | 65 | Street | Hills |
| Building Address: | | | | | |
| Legal Description: | | | | | |
| GPS south: | Degrees | Min | Sec | | |
| GPS east: | 43 | 30 | 55.17 | | |
| | 172 | 39 | 2.03 | | |
| Building Unique Identifier (CCC): | PRO0638 | | | | |

| | |
|---|--------------------------------|
| Reviewer: | Mary Ann Halliday |
| CPEng No: | 67073 |
| Company: | Opus International Consultants |
| Company project number: | 6-OC361.00 |
| Company phone number: | |
| Date of submission: | 14-Feb-14 |
| Inspection Date: | 12/12/2013 |
| Revision: | 1 |
| Is there a full report with this summary? | yes |

Site

| | |
|--|------|
| Site slope: | flat |
| Soil type: | |
| Site Class (to NZS1170.5): | D |
| Proximity to waterway (m, if <100m): | |
| Proximity to cliff top (m, if < 100m): | |
| Proximity to cliff base (m,if <100m): | |

| | |
|--|--|
| Max retaining height (m): | |
| Soil Profile (if available): | |
| If Ground improvement on site, describe: | |
| Approx site elevation (m): | |

Building

| | |
|----------------------------------|----------------------------------|
| No. of storeys above ground: | 1 |
| Ground floor split? | no |
| Storeys below ground: | 0 |
| Foundation type: | bored cast-insitu concrete piles |
| Building height (m): | 3.00 |
| Floor footprint area (approx): | 100 |
| Age of Building (years): | 55 |
| Strengthening present? | no |
| Use (ground floor): | multi-unit residential |
| Use (upper floors): | |
| Use notes (if required): | |
| Importance level (to NZS1170.5): | IL2 |

| | | |
|-------------------|---|-----------|
| single storey = 1 | Ground floor elevation (Absolute) (m): | |
| | Ground floor elevation above ground (m): | |
| | if Foundation type is other, describe: | |
| | height from ground to level of uppermost seismic mass (for IEP only) (m): | |
| | Date of design: | 1935-1965 |

Gravity Structure

| | |
|-----------------|------------------|
| Gravity System: | frame system |
| Roof: | timber framed |
| Floors: | timber |
| Beams: | timber |
| Columns: | timber |
| Walls: | non-load bearing |

| | |
|---------------------------------------|----------------|
| rafter type, purlin type and cladding | timber sarking |
| joist depth and spacing (mm) | |
| typical dimensions (mm x mm) | |
| | 0 |

Lateral load resisting structure

| | | |
|--|---------------------------------|------|
| Lateral system along: | lightweight timber framed walls | 0.00 |
| Ductility assumed, μ : | 2.00 | |
| Period along: | 0.10 | |
| Total deflection (ULS) (mm): | | |
| maximum interstorey deflection (ULS) (mm): | | |
| Lateral system across: | lightweight timber framed walls | 0.00 |
| Ductility assumed, μ : | 2.00 | |
| Period across: | 0.10 | |
| Total deflection (ULS) (mm): | | |
| maximum interstorey deflection (ULS) (mm): | | |

Note: Define along and across in detailed report!

| | |
|------------------------------|-----------|
| note typical wall length (m) | |
| estimate or calculation? | estimated |
| estimate or calculation? | |
| estimate or calculation? | |
| note typical wall length (m) | |
| estimate or calculation? | estimated |
| estimate or calculation? | |
| estimate or calculation? | |

Separations:

| | |
|-------------|--|
| north (mm): | |
| east (mm): | |
| south (mm): | |
| west (mm): | |

leave blank if not relevant

Non-structural elements

| | |
|-----------------|--------------------------|
| Stairs: | |
| Wall cladding: | other light |
| Roof Cladding: | Metal |
| Glazing: | aluminium frames |
| Ceilings: | strapped or direct fixed |
| Services(list): | |

| | |
|----------|--------------|
| describe | Weatherboard |
| describe | |
| | |
| | |

Available documentation

| | |
|-----------------|---------|
| Architectural: | partial |
| Structural: | partial |
| Mechanical: | none |
| Electrical: | none |
| Geotech report: | none |

| | |
|-----------------------------|--|
| original designer name/date | |
| original designer name/date | |
| original designer name/date | |
| original designer name/date | |
| original designer name/date | |

Damage

Site:
(refer DEE Table 4-2)

| | |
|------------------------------|--|
| Site performance: | moderate |
| Settlement: | 25-100mm |
| Differential settlement: | 1:150 or more |
| Liquefaction: | 5-10 m ³ /100m ² |
| Lateral Spread: | none apparent |
| Differential lateral spread: | none apparent |
| Ground cracks: | none apparent |
| Damage to area: | moderate to substantial (1 in 5) |

| | |
|------------------------|--|
| Describe damage: | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |

Building:

| | |
|-------------------------|---------------------|
| Current Placard Status: | green |
| Along | Damage ratio: 0% |
| | Describe (summary): |
| Across | Damage ratio: 0% |
| | Describe (summary): |
| Diaphragms | Damage?: yes |
| CSWs: | Damage?: no |
| Pounding: | Damage?: no |
| Non-structural: | Damage?: yes |

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

| | |
|---------------------------------------|--|
| Describe how damage ratio arrived at: | |
| Describe: | |
| Describe: | |
| Describe: | |
| Describe: | |

Recommendations

| | |
|---|----------------------|
| Level of repair/strengthening required: | minor non-structural |
| Building Consent required: | no |
| Interim occupancy recommendations: | full occupancy |

| | |
|-----------|--|
| Describe: | |
| Describe: | |
| Describe: | |

| | | | |
|--------|--------------------------------|------|---------------------------|
| Along | Assessed %NBS before e'quakes: | 43% | ##### %NBS from IEP below |
| | Assessed %NBS after e'quakes: | 43% | |
| Across | Assessed %NBS before e'quakes: | 100% | ##### %NBS from IEP below |
| | Assessed %NBS after e'quakes: | 100% | |

If IEP not used, please detail assessment methodology:

Equivalent Static

Detailed Engineering Evaluation Summary Data

V1.14

Location

| | | | |
|-----------------------------------|-------------------------------|----------|--------|
| Building Name: | Huggins Place Housing Complex | Unit No: | Street |
| Building Address: | 65 | Hills | |
| Legal Description: | | | |
| | Degrees | Min | Sec |
| GPS south: | 43 | 30 | 55.17 |
| GPS east: | 172 | 39 | 2.03 |
| Building Unique Identifier (CCC): | PRO0638 | | |

| | |
|---|--------------------------------|
| Reviewer: | Mary Ann Halliday |
| CPEng No: | 67073 |
| Company: | Opus International Consultants |
| Company project number: | 6-OC361.00 |
| Company phone number: | |
| Date of submission: | 14-Feb-14 |
| Inspection Date: | 12/12/2013 |
| Revision: | 1 |
| Is there a full report with this summary? | yes |

Site

| | |
|--|------|
| Site slope: | flat |
| Soil type: | |
| Site Class (to NZS1170.5): | D |
| Proximity to waterway (m, if <100m): | |
| Proximity to cliff top (m, if < 100m): | |
| Proximity to cliff base (m,if <100m): | |

| | |
|--|--|
| Max retaining height (m): | |
| Soil Profile (if available): | |
| If Ground improvement on site, describe: | |
| Approx site elevation (m): | |

Building

| | |
|----------------------------------|----------------------------------|
| No. of storeys above ground: | 1 |
| Ground floor split? | no |
| Storeys below ground: | 0 |
| Foundation type: | bored cast-insitu concrete piles |
| Building height (m): | 3.00 |
| Floor footprint area (approx): | 133 |
| Age of Building (years): | 55 |
| Strengthening present? | no |
| Use (ground floor): | multi-unit residential |
| Use (upper floors): | |
| Use notes (if required): | |
| Importance level (to NZS1170.5): | IL2 |

| | | |
|-------------------|---|-----------|
| single storey = 1 | Ground floor elevation (Absolute) (m): | |
| | Ground floor elevation above ground (m): | |
| | if Foundation type is other, describe: | |
| | height from ground to level of uppermost seismic mass (for IEP only) (m): | |
| | Date of design: | 1935-1965 |

Gravity Structure

| | |
|-----------------|------------------|
| Gravity System: | frame system |
| Roof: | timber framed |
| Floors: | timber |
| Beams: | timber |
| Columns: | timber |
| Walls: | non-load bearing |

| | |
|---------------------------------------|----------------|
| rafter type, purlin type and cladding | timber sarking |
| joist depth and spacing (mm) | |
| typical dimensions (mm x mm) | |
| | 0 |

Lateral load resisting structure

| | | |
|--|---------------------------------|------|
| Lateral system along: | lightweight timber framed walls | 0.00 |
| Ductility assumed, μ : | 2.00 | |
| Period along: | 0.10 | |
| Total deflection (ULS) (mm): | | |
| maximum interstorey deflection (ULS) (mm): | | |
| Lateral system across: | lightweight timber framed walls | 0.00 |
| Ductility assumed, μ : | 2.00 | |
| Period across: | 0.10 | |
| Total deflection (ULS) (mm): | | |
| maximum interstorey deflection (ULS) (mm): | | |

Note: Define along and across in detailed report!

| | |
|------------------------------|-----------|
| note typical wall length (m) | |
| estimate or calculation? | estimated |
| estimate or calculation? | |
| estimate or calculation? | |
| note typical wall length (m) | |
| estimate or calculation? | estimated |
| estimate or calculation? | |
| estimate or calculation? | |

Separations:

| | |
|-------------|--|
| north (mm): | |
| east (mm): | |
| south (mm): | |
| west (mm): | |

leave blank if not relevant

Non-structural elements

| | |
|-----------------|--------------------------|
| Stairs: | |
| Wall cladding: | other light |
| Roof Cladding: | Metal |
| Glazing: | aluminium frames |
| Ceilings: | strapped or direct fixed |
| Services(list): | |

| | |
|----------|--------------|
| describe | Weatherboard |
| describe | |
| | |
| | |

Available documentation

| | |
|----------------|---------|
| Architectural | partial |
| Structural | partial |
| Mechanical | none |
| Electrical | none |
| Geotech report | none |

| | |
|-----------------------------|--|
| original designer name/date | |
| original designer name/date | |
| original designer name/date | |
| original designer name/date | |
| original designer name/date | |

Damage

Site:
(refer DEE Table 4-2)

| | |
|------------------------------|--|
| Site performance: | moderate |
| Settlement: | 25-100mm |
| Differential settlement: | 1:150 or more |
| Liquefaction: | 5-10 m ³ /100m ² |
| Lateral Spread: | none apparent |
| Differential lateral spread: | none apparent |
| Ground cracks: | none apparent |
| Damage to area: | moderate to substantial (1 in 5) |

| | |
|------------------------|--|
| Describe damage: | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |
| notes (if applicable): | |

Building:

| | |
|-------------------------|---------------------|
| Current Placard Status: | green |
| Along | Damage ratio: 0% |
| | Describe (summary): |
| Across | Damage ratio: 0% |
| | Describe (summary): |
| Diaphragms | Damage?: yes |
| CSWs: | Damage?: no |
| Pounding: | Damage?: no |
| Non-structural: | Damage?: yes |

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

| | |
|---------------------------------------|--|
| Describe how damage ratio arrived at: | |
| Describe: | |
| Describe: | |
| Describe: | |
| Describe: | |

Recommendations

| | |
|---|----------------------|
| Level of repair/strengthening required: | minor non-structural |
| Building Consent required: | no |
| Interim occupancy recommendations: | full occupancy |

| | |
|-----------|--|
| Describe: | |
| Describe: | |
| Describe: | |

| | | | |
|--------|--------------------------------|------|---------------------------|
| Along | Assessed %NBS before e'quakes: | 43% | ##### %NBS from IEP below |
| | Assessed %NBS after e'quakes: | 43% | |
| Across | Assessed %NBS before e'quakes: | 100% | ##### %NBS from IEP below |
| | Assessed %NBS after e'quakes: | 100% | |

If IEP not used, please detail assessment methodology:

Equivalent Static



Opus International Consultants Ltd
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400
f: +64 3 365 7858
w: www.opus.co.nz