



CLIENTS | PEOPLE | PERFORMANCE

Pavilion Toilets - Jellie Park
PRK 0266 BLDG 002
Detailed Engineering Evaluation
Qualitative Report
Version FINAL

140 Greers Road
Christchurch



**Pavilion Toilets – Jellie Park
PRK 0266 BLDG 002**

Detailed Engineering Evaluation
Qualitative Report
Version FINAL

140 Greers Road
Christchurch

Christchurch City Council

Prepared By
Simon Barker

Reviewed By
Stephen Lee

Date
17th May 2013



Contents

Qualitative Report Summary	i
1. Background	1
2. Compliance	2
2.1 Canterbury Earthquake Recovery Authority (CERA)	2
2.2 Building Act	3
2.3 Christchurch City Council Policy	4
2.4 Building Code	4
3. Earthquake Resistance Standards	5
4. Building Description	7
4.1 General	7
4.2 Gravity Load Resisting System	8
4.3 Lateral Load Resisting System	8
5. Assessment	9
6. Damage Assessment	10
6.1 Surrounding Buildings	10
6.2 Residual Displacements and General Observations	10
6.3 Ground Damage	10
7. Critical Structural Weakness	11
7.1 Short Columns	11
7.2 Lift Shaft	11
7.3 Roof	11
7.4 Staircases	11
7.5 Site Characteristics	11
7.6 Plan Irregularity	11
7.7 Vertical irregularity	11
8. Geotechnical Consideration	12
8.1 Introduction	12
8.2 Site Description	12



8.3	Published Information on Ground Conditions	12
8.4	Seismicity	14
8.5	Slope Failure and/or Rockfall Potential	15
8.6	Liquefaction Potential	15
8.7	Recommendations	16
8.8	Conclusions and Summary	16
9.	Survey	17
10.	Initial Capacity Assessment	18
10.1	% NBS Assessment	18
10.2	Seismic Parameters	18
10.3	Expected Structural Ductility Factor	18
10.4	Discussion of Results	18
10.5	Occupancy	19
11.	Initial Conclusions	20
12.	Recommendations	21
13.	Limitations	22
13.1	General	22
13.2	Geotechnical Limitations	22

Table Index

Table 1	%NBS compared to relative risk of failure	6
Table 2	ECan Borehole Summary	112
Table 3	Summary of Known Active Faults	15
Table 4	Indicative Building and Critical Structural Weaknesses Capacities based on the NZSEE Initial Evaluation Procedure	18

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	5
Figure 2	Plan Sketch Showing Key Structural Elements	7
Figure 3	Post February 2011 Earthquake Aerial Photography	14



Appendices

- A Photographs
- B Existing Drawings
- C CERA Building Evaluation Form



Qualitative Report Summary

Pavilion Toilets – Jellie Park

PRK 0266 BLDG 002

Detailed Engineering Evaluation

Qualitative Report - SUMMARY

Version FINAL

295 Teddington Road

Background

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 28th of June 2012 and available construction drawings.

Building Description

The toilet is located in Jellie Park on 140 Greers Road, it sits on level ground, has no nearby waterways and lies 50m from the nearest structure. The toilet was designed in 2009 and is for public use, no alterations have been made to the building since its original construction. The toilet is a single storied structure and has a steel framed roof clad with 0.4mm colorsteel sheeting. There is a partition wall splitting the toilet into two cubicles. Both the perimeter and partition walls are built from a stack arrangement of fully filled reinforced 200 series concrete masonry blocks. The walls are not clad.

Key Damage Observed

No damage was observed to the structure.

Critical Structural Weaknesses

No critical structural weaknesses have been identified in the structure.

Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the original capacity of the building has been assessed to be in the order of 64% NBS and post-earthquake capacity also in the order of 64% NBS.

This building was constructed post 2004 and was most likely built to the current building standards. However, for the purpose of this assessment it was assumed the design was completed to the standards current in 2004.

The building has been assessed to have a seismic capacity in the order of 64% NBS and is therefore considered Earthquake Risk.



Recommendations

The building has been assessed as not being Earthquake Prone. CCC are not required to undertake a detailed seismic assessment, however due to the relatively low score, GHD recommend a detailed seismic assessment is carried out.



1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Toilet on Jellie Park.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings were made available, and these have been considered in our evaluation of the building. The building description below is based on a review of the drawings and our visual inspections.



2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage



2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The toilet is located in Jellie Park at 140 Greers Road, it sits on level ground, has no nearby waterways and lies approximately 50m from the nearest structure. It was designed in 2009 and is for public use, no alterations have been made to the building since its original construction.

The toilet is a single story structure approximately 2.8m in height and has a plan area of 11 m². The plan dimensions are shown below in mm.




Figure 2 Plan Sketch Showing Key Structural Elements

The roof frame is constructed from arched steel trusses clad with 0.4mm color steel corrugated sheeting. The trusses are made from arched 50 mm diameter steel tube rafters and ceiling joists, they are connected by purlins spaced at regular intervals along the arch. The trusses are raised off the walls by 50 mm diameter steel tube legs.

There is a partition wall splitting the toilet into two cubicles of equal area. Both the perimeter and partition walls are built from a stack arrangement of reinforced fully filled 20 series concrete masonry blocks. There is no cladding on any of the wall faces.



The toilet is founded on a strip foundation.

The available construction plans are attached in appendix B.

4.2 Gravity Load Resisting System

Gravity roof loads are first carried by the colorsteel sheeting into the purlins and rafters. The loads are then transferred through the steel tube roof trusses spanning the longitudinal direction. Loads from the trusses are transferred to the concrete masonry walls, into the reinforced strip foundation and finally into the ground. Internal gravity loads are transferred through the reinforced strip foundation into the ground.

4.3 Lateral Load Resisting System

In the transverse direction the rigid connection of the purlins, roof trusses and wall provide a rigid diaphragm which distributes lateral roof loads to the walls in the plane of loading. The lateral loads are then resisted by the panel action of the concrete masonry walls and are passed to the foundation and finally to the ground.

In the longitudinal direction the lateral roof loads are transferred from the purlins, via the roof trusses to the walls in the plane of loading. Panel action is used by these walls to transfer the longitudinal loads into the foundation. In this direction there is an imbalance in the distribution of walls and there will be an offset of the centre of mass with the centre of rigidity. This may create slight torsional effects.

Walls perpendicular to the loading are restrained by the diaphragm action provided by the roof. This action redistributes the lateral loads to the in plane walls.



5. Assessment

An inspection of the building was undertaken on the 23th of May, 2012. Both the interior and exterior of the building were inspected. The main structural components of the roof of the building were all able to be viewed. The foundations were able to be partially viewed from the exterior; detailing of these was confirmed via construction plans. The inspection consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for this building has been based on the IEP procedure described by the NZSEE and based on the information obtained from visual observation of the building and available drawings.



6. Damage Assessment

6.1 Surrounding Buildings

The public toilet sits on level ground approximately 50m from the nearest structure. There was no obvious damage to surrounding buildings.

6.2 Residual Displacements and General Observations

No residual displacements or damage to the structure were noticed during our inspection of the building.

6.3 Ground Damage

There was no evidence of ground damage on the property or surrounding neighbours land.



7. Critical Structural Weakness

7.1 Short Columns

No short columns are present in the structure.

7.2 Lift Shaft

The building does not contain a lift shaft.

7.3 Roof

Rigid connections between the roof trusses, wall plates and timber purlins form a rigid braced diaphragm.

7.4 Staircases

The building does not contain a staircase.

7.5 Site Characteristics

Following the geotechnical appraisal it was found that the site has a moderate potential for liquefaction. For the purposes of the IEP assessment of the building and the determination of the %NBS score, the effects of soil liquefaction on the performance of the building has been assessed as an insignificant site characteristic in accordance with the NZSEE guidelines. This is because settlements are not likely to cause premature collapse of the structure.

7.6 Plan Irregularity

There is an imbalance of stiffness when considering lateral loading in the transverse direction. The back face has two walls spanning the width of the toilet where the front face has two openings for doors (See Figure 2). This imbalance of stiffness has the potential to cause torsional effects; however, due to the size and nature of this structure these potential torsional effects have not been considered a critical structural weakness.

7.7 Vertical irregularity

There is no vertical irregularity in this structure.



8. Geotechnical Consideration

8.1 Introduction

This desktop geotechnical study outlines the ground conditions, as indicated from sources quoted within. This is a desktop study report and no site visit has been undertaken by Geotechnical personnel.

This report is only specific to the pavilion/toilet structure at Jellie Park, Greers Road, Ilam. The park is surrounded by residential properties, and is owned and maintained by the Christchurch City Council.

8.2 Site Description

The site is situated within a recreational reserve in Ilam. It is relatively flat at approximately 15m above mean sea level. It is approximately 100m southwest of the Wairarapa Stream (a tributary of the Avon), and 12km west of the coast (Pegasus Bay).

8.3 Published Information on Ground Conditions

8.3.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by Holocene alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, comprising alluvial sand and silt overbank deposits.

In addition, the map also indicates the site to be within an historic river channel, now containing the Wairarapa Stream.

8.3.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that four boreholes are located within 200m of the site (see Table 2).

Of these boreholes, two had adequate lithographic logs, those logs indicates the area typically comprises layers of sand and sandy silt to ~2.2m, underlain by gravel and sandy gravel.

Table 2 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35/3040	20.4m	2.8m	300m W
M35/12856	2.3m	-	130m N
M35/16263	2.8m	-	150m N

¹ Brown, L. J. and Weeber, J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.



Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35/16264	1.8m	-	150m N

Recent earthquakes since 4 September 2010 have identified the presence of a previously unmapped active fault system underneath Canterbury Plains and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.3.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the subject site.

8.3.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has indicated the site is situated within the Green Zone, meaning that repair and rebuild may take place.

Land in the CERA green zone has been divided into three technical categories. These categories describe how the land is expected to perform in future earthquakes.

The technical categories – TC1 (grey), TC2 (yellow) and TC3 (blue) describe the foundation systems most likely to be required in the corresponding areas on the maps

For TC3 areas site specific geotechnical work will be required to determine the actual foundations required for each house. In some cases this will mean TC2 level foundations will be enough in TC3 areas based on actual ground tests.

The site is indicated as being on the boundary of all three technical categories.

8.3.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows no signs of liquefaction outside the building footprint or adjacent to the site, as shown in **Figure 3**.

Figure 3 Post February 2011 Earthquake Aerial Photography ²



8.3.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to comprise layers of sand and sandy silt to ~2.2m, underlain by gravel and sandy gravel.

8.4 Seismicity

8.4.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

² Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>



Table 3 Summary of Known Active Faults³⁴

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120 km	NW	~8.3	~300 years
Greendale (2010) Fault	20 km	SW	7.1	~15,000 years
Hope Fault	100 km	N	7.2~7.5	120~200 years
Kelly Fault	100 km	NW	7.2	~150 years
Porters Pass Fault	55 km	NW	7.0	~1100 years

Recent earthquakes since 22 February 2011 have identified the presence of a previously unmapped active fault system underneath Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.4.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

Seismic activity since September 2010 has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

In addition, anticipation of alluvial deposits overlying bedrock over 500m deep, and a 475-year PGA (peak ground acceleration) of ~0.4 (Stirling et al, 2002⁴), ground shaking is likely to be moderate to high.

8.5 Slope Failure and/or Rockfall Potential

Given the site's location in Ilam, a flat suburb in northwest Christchurch, global slope instability is considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

8.6 Liquefaction Potential

Due to the anticipated presence of predominantly gravels and sandy gravels beneath the site, it is considered that liquefaction is less likely to occur at this site than other areas of Christchurch. However, the grain size of the sands present is not recorded, and silts are also recorded as present in varying

³ Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

⁴ GNS Active Faults Database



amounts within the gravels. Therefore it is considered possible and likely that liquefaction will occur where sands and silts are present.

Further investigation is recommended to better determine subsoil conditions. From this, a more comprehensive liquefaction assessment could be undertaken.

8.7 Recommendations

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that further investigation be undertaken.

8.8 Conclusions and Summary

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

The site appears to be situated on stratified alluvial deposits, comprising gravel, sand and silt. Associated with this the site also has a moderate liquefaction potential, in particular where sands and/or silts are present.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that further investigation be undertaken.



9. Survey

No level or verticality surveys have been undertaken for this building at this stage as indicated by Christchurch City Council guidelines.



10. Initial Capacity Assessment

10.1 % NBS Assessment

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity excluding critical structural weaknesses and the capacity of any identified weaknesses are expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 4. These capacities are subject to confirmation by a more detailed quantitative analysis.

<u>Item</u>	<u>%NBS</u>
Building excluding CSW's	64
Building including CSW's	64

Table 4 Indicative Building and Critical Structural Weaknesses Capacities based on the NZSEE Initial Evaluation Procedure

Following an IEP assessment, the building has been assessed as achieving 64% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered as Earthquake Risk as it achieves greater than 33% NBS but less than 67% NBS.

This building was constructed post 2004 and was most likely built to the current building standards. We would expect the building to be 100% NBS; however, for the purpose of this IEP it was assumed the design was completed to the standards current in 2004.

10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- Site soil class: D, NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- Return period factor $R_u = 1.0$, NZS 1170.5:2004, Table 3.5, Importance level 2 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

10.3 Expected Structural Ductility Factor

A structural ductility factor of 1.25 has been assumed based on the structural system observed and the date of construction.

10.4 Discussion of Results

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age and construction type. Due to increase in hazard factor the design loads used would have been



less than those required by the current loading standard. Therefore it would be expected that the building would not achieve 100% NBS.

Because of the limited ductility in this building and the lack of horizontal reinforcement in the concrete masonry walls it is reasonable to consider the building as Earthquake Risk. However, due to the lack of any Critical Structural Weaknesses and sufficient bracing it is reasonable to expect the building to not be classified Earthquake Prone.

10.5 Occupancy

The building does not pose an immediate risk to users and occupants and no critical structural weaknesses have been identified. The building has not been assessed as being Earthquake Prone.



11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 64% NBS and is therefore not potentially Earthquake Prone but can be considered potentially Earthquake Risk.



12. Recommendations

The recent seismic activity in Christchurch has caused no damage to the building. As the building suffered no apparent damage the load resisting capacity of the existing structural systems should be unaffected. Because the building has achieved between 34% and 67% NBS following an initial IEP assessment of the building, no further assessment is required by Christchurch City Council to comply with the building act.



13. Limitations

13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No visual inspections of the sub-floor space undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report or a specific limitations section.

13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.



Appendix A
Photographs

Photograph 1 Front and Right Elevations



Photograph 2 Rear and Left Elevations.



Photograph 3 Roof Structure (from inside)



Photograph 4 Roof Structure (from outside)




Photograph 5 Interior





Appendix B
Existing Drawings



DESIGNED	NAME	SIGNED	DATE
DESIGNED	DESIGNED	SIGNED	DATE
DES. REVIEW	DES. REVIEW	SIGNED	DATE
DRAWN	DRAWN	SIGNED	DATE
CONSTR. EB	CONSTR. EB	SIGNED	DATE
CONSTR. LB	CONSTR. LB	SIGNED	DATE

APPROVED
DATE 16/12/09



PROJECT TITLE
JELLIE PARK - NEW PUBLIC TOILETS
FOR GREEN SPACE UNIT 2009/10.
NO 140 GREERS ROAD.

DRAWING TITLE
WORKING DRAWINGS.

ISSUE	AMENDMENTS	SIGNED	DATE
FILE NUMBER	501332	ORIGINAL SHEET SIZE	A1
CONTRACT NUMBER	09/10-134	SCALES	as shown
DRAWING & PROJECT NUMBER	562/1959	SHEET	A1 of 1.



Appendix C
CERA Building Evaluation Form

Location		Building Name: Pavilion Toilets Jellie Park	Reviewer: Stephen Lee
Building Address: [Unit No.] Street	140 Greens Road	CPEng No: 1006840	Company: GHD
Legal Description: RS 40044 11.8133		Company project number: 513090212	Company phone number: 04 472 0799
GPS south: Degrees 43 Min 30 Sec 28.00	GPS east: 172 34 53.00	Date of submission: 17-05-13	Inspection Date: 23-05-12
Building Unique Identifier (CCC): PRK 0266 BLDG 002		Revision: FINAL	Is there a full report with this summary? yes

Site		Site slope: flat	Max retaining height (m):
Soil type: mixed	Site Class (to NZS1170.5): D	Soil Profile (if available):	
Proximity to waterway (m, if <100m):	Proximity to clifftop (m, if <100m):	Proximity to cliff base (m, if <100m):	If Ground improvement on site, describe:
			Approx site elevation (m): 0.00

Building		No. of storeys above ground: 1	single storey = 1	Ground floor elevation (Absolute) (m):
Ground floor split?: no	Storeys below ground:	Foundation type: strip footings	Building height (m): 2.80	Ground floor elevation above ground (m): 0.10
Floor footprint area (approx): 11	Age of Building (years): 3	height from ground to level of uppermost seismic mass (for IEP only) (m): 2.8	Date of design: 2004-	
Strengthening present?: no	Use (ground floor): public	Use (upper floors):	Use notes (if required):	Importance level (to NZS1170.5): IL2

Gravity Structure		Gravity System: load bearing walls	rafter type, purlin type and cladding:
Roof: steel framed	Floors: concrete flat slab	Beams: none	slab thickness (mm):
Columns: fully filled concrete masonry	Walls: fully filled concrete masonry	overall depth x width (mm x mm):	#N/A

Lateral load resisting structure		Lateral system along: fully filled CMU	Ductility assumed, μ: 1.25	Period along: 0.40	note total length of wall at ground (m):
Total deflection (ULS) (mm):	maximum interstorey deflection (ULS) (mm):	Lateral system across: fully filled CMU	Ductility assumed, μ: 1.25	Period across: 0.40	estimate or calculation? estimated
					estimate or calculation? estimated

Separations:		north (mm):	east (mm):	south (mm):	west (mm):	leave blank if not relevant
---------------------	--	-------------	------------	-------------	------------	-----------------------------

Non-structural elements		Stairs:	Wall cladding:	Roof Cladding: Metal	Glazing:	Ceilings: none	Services(list): Water, Electricity	describe:
--------------------------------	--	---------	----------------	----------------------	----------	----------------	------------------------------------	-----------

Available documentation		Architectural: none	Structural: full	Mechanical: none	Electrical: none	Geotech report: full	original designer name/date: 16-12-09	original designer name/date: 06-06-12
--------------------------------	--	---------------------	------------------	------------------	------------------	----------------------	---------------------------------------	---------------------------------------

Damage Site:		Site performance:	Describe damage:
(refer DEE Table 4-2)	Settlement: none observed	Differential settlement: none observed	Liquefaction: none apparent
Lateral Spread: none apparent	Differential lateral spread: none apparent	Ground cracks: none apparent	Damage to area: none apparent
			notes (if applicable):

Building:		Current Placard Status:	Describe how damage ratio arrived at:
Along	Damage ratio: 0%	Describe (summary):	
Across	Damage ratio: 0%	Describe (summary):	
Diaphragms	Damage?: no	Describe:	
CSWs:	Damage?: no	Describe:	
Pounding:	Damage?: no	Describe:	
Non-structural:	Damage?: no	Describe:	

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

Recommendations			
Level of repair/strengthening required:	none		Describe:
Building Consent required:	no		Describe:
Interim occupancy recommendations:	full occupancy		Describe:
Along	Assessed %NBS before e'quakes:	70%	64% %NBS from IEP below If IEP not used, please detail assessment methodology:
	Assessed %NBS after e'quakes:	70%	
Across	Assessed %NBS before e'quakes:	70%	64% %NBS from IEP below
	Assessed %NBS after e'quakes:	70%	

IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 2004- h_n from above: 2.8m

Seismic Zone, if designed between 1965 and 1992: Design Soil type from NZS1170.5:2004, cl 3.1.3: D soft soil
not required for this age of building

	along	across
Period (from above):	0.4	0.4
(%NBS) _{nom} from Fig 3.3:	22.3%	22.3%
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0		1.00
Note 2: for RC buildings designed between 1976-1984, use 1.2		1.0
Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)		1.0
Final (%NBS)_{nom}:	22%	22%

2.2 Near Fault Scaling Factor Near Fault scaling factor, from NZS1170.5, cl 3.1.6: 1.00

	along	across
Near Fault scaling factor (1/N(T,D)), Factor A:	1	1

2.3 Hazard Scaling Factor Hazard factor Z for site from AS1170.5, Table 3.3: 0.30
Z₁₉₉₂, from NZS4203:1992 0.8
Hazard scaling factor, **Factor B:** 2.66666667

2.4 Return Period Scaling Factor Building Importance level (from above): 2
Return Period Scaling factor from Table 3.1, **Factor C:** 1.00

2.5 Ductility Scaling Factor Assessed ductility (less than max in Table 3.2) 1.50 1.50
Ductility scaling factor: =1 from 1976 onwards; or =k_u, if pre-1976, from Table 3.3: 1.00 1.00
Ductility Scaling Factor, **Factor D:** 1.00 1.00

2.6 Structural Performance Scaling Factor: Sp: 0.925 0.925
Structural Performance Scaling Factor **Factor E:** 1.081081081 1.081081081

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E **%NBS:** 64% 64%

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A: insignificant 1

3.2. Vertical irregularity, Factor B: insignificant 1

3.3. Short columns, Factor C: insignificant 1

3.4. Pounding potential Pounding effect D1, from Table to right 1.0
Height Difference effect D2, from Table to right 1.0
Therefore, Factor D: 1

	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.5. Site Characteristics insignificant 1

3.6. Other factors, Factor F For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum
Rationale for choice of F factor, if not 1 1 1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)
List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR) 1.00 1.00

4.3 PAR x (%NBS)_b: PAR x Baseline %NBS: 64% 64%

4.4 Percentage New Building Standard (%NBS), (before) 64%

Official Use only:

Accepted By:

Date:



GHD

GHD Office
226 Antigua St
Christchurch 8011
T: 64 3 378 0900 F: 64 3 377 8575 E: chcmail@ghd.com

© GHD Limited 2013

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Simon Barker	Rob Collins		Stephen Lee		17/05/13