



*Christchurch City Council*

**Linwood Library &  
Service Centre  
Building  
PRO 1982 001**

**Detailed Engineering Evaluation  
Quantitative Assessment Report**





*Christchurch City Council*

---

# **Linwood Library & Service Centre Building**

**Detailed Engineering Evaluation**

**10 Cranley Street, Linwood**

Prepared By Alex Walters/Ian MacDonald  
Structural Engineer/Structural Engineer

Opus International Consultants Ltd  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail  
Centre, Christchurch 8140  
New Zealand

Approved for  
Release By

.....  
Robert Davey  
Principal Structural Engineer  
CPEng 17912

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Date: September 2013  
Reference: 6-QUCCC.22  
Status: Final V3

# Summary

Linwood Library  
PRO 1982 001

Detailed Engineering Evaluation  
Quantitative Report - Summary  
Final V3

## **Background**

This is a summary of the quantitative report for Linwood Library, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

## **Building Type**

The building is single storey steel portal frame with tilt-up concrete cladding panels. It was constructed circa 1993.

## **Damage Observed**

Earthquake damage comprised yielding of the roof bracing, minor to moderate cracking of concrete panels and collapse of the suspended ceiling. The building was further damaged in a fire in March 2012.

## **Critical Structural Weaknesses**

There are no critical structural weaknesses.

## **Indicative Building Strength**

The building is assessed to be 25%NBS based on the capacities of the steel portals and diagonal roof bracing. This is the as-designed rating prior to the earthquake damage and fire damage.

# Contents

<b>Summary .....</b>	<b>i</b>
<b>1 Introduction.....</b>	<b>1</b>
<b>2 Building Description .....</b>	<b>1</b>
<b>3 Seismic Load Resisting System.....</b>	<b>2</b>
<b>4 Seismic Forces .....</b>	<b>2</b>
<b>5 Material Properties .....</b>	<b>3</b>
<b>6 Analysis Results .....</b>	<b>3</b>
<b>7 Performance in the 22 February 2011 Christchurch Earthquake .....</b>	<b>5</b>
<b>8 Geotechnical Information .....</b>	<b>6</b>
<b>9 Evaluation of Results.....</b>	<b>7</b>
<b>10 Conclusions.....</b>	<b>8</b>
<b>11 References .....</b>	<b>8</b>

# 1 Introduction

Opus International Consultants Limited has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Linwood Library & Service Centre building, located at 10 Cranley Road, Linwood, Christchurch.

A limited quantitative assessment was recommended in order to determine whether the building has a seismic rating of at least 67% NBS, which is the recommended performance standard for existing buildings [1].

The scope of the quantitative assessment is as follows:

1. An analysis of the seismic capacity of the precast walls on grids 1 and 3 for loads in the north-west to south-east direction for to determine the % NBS.
2. An analysis of the seismic capacity of the precast façade walls on the north-west elevation for seismic loads to determine the % NBS.
3. An analysis of the seismic capacity of the connections between the precast concrete walls and the portal frames for seismic loads to determine the % NBS.
4. An analysis of the seismic capacity of the roof bracing.
5. An analysis of the steel portal frames.

# 2 Building Description

The Linwood Library and Service Centre is a single level structure located with a street frontage to Cranley Street. Cranley Street is of short length with a 90 degree corner, and links with Linwood Ave to the south-west and Chelsea Street to the south-east. The building is located on the bend and is orientated perpendicular to the streets. For the purposes of this report we refer to the direction parallel to Chelsea St as the north-east to south-west direction and the direction parallel to Linwood Ave as the south-east to north-west direction.

The original building was constructed in 1993. Some minor internal office alterations took place in 2004.

The building is a single level hybrid steel portal frame and precast perimeter concrete wall building. The building is 29 metres long (south-east to north-west) by 28 metres wide (north-east to south-west) in plan dimension.

### 3 Seismic Load Resisting System

Loads and the existing structural layout have been assessed by referring to the 2008 record drawings by Christchurch City Council and the 1993 record drawings by O’Loughlin Taylor Spence.

Seismic forces in the north-west to south-east direction are generated by the response of the roof and external concrete wall panel masses. The load path is from the diagonal steel roof plane bracing located between grids B and C, into the concrete wall panels located on the grids 1 and 3, and into the foundations.

The roof bracing comprises small section 40x40x5mm steel angles and these are detailed on the drawings as being notched where they intersect, significantly reducing their strength.

There is no direct load path between the roof bracing and the panels, rather there is an indirect path via the purlins nearest to the portal knees to the portal columns and then via single M16 bolt inserts to the wall panels. The wall panels are anchored into an unreinforced floor slab thickening with threaded rods. The panels have large window openings forming deep beams/column frames that resist the in-plane shears.

There is a large concrete façade or colonnade on the north-west face which stands forwards of the main structure. The roof of the library extends to the façade creating an external sheltered area. The roof purlins are bolted to and retrain the tops of the façade panels for out-of-plane loads, with the exception of the two end bays which stand clear of the building and are not directly connected to it. These parts of the façade rely upon the rocking resistance of the end columns for stability. In plane forces are resisted by frame action between the colonnade beams and columns.

### 4 Seismic Forces

The following criteria from the earthquake loadings NZS 1170.5 [2] were used to determine the site loading spectrum:

**Table 1: Earthquake Loadings Criteria**

Parameter	Value	Comments
$C_h(T)$	3.0	Class D soil, $T_1 < 0.5$ secs
Z	0.3	Increased seismic hazard factor for Christchurch
R	1.0	Importance level 2, normal building
$N(T,D)$	1.0	

For the purpose of the analyses carried out in this assessment it was assumed that the bracing wall panels were rigid in-plane so that the forces input to the roof diaphragm diagonal bracing were not amplified by the in-plane response of the walls. This is considered to be a reasonable assumption in the circumstances, although it may result in the bracing forces being somewhat under-estimated. The face-load forces on fixings of the panels to the bracing system were analysed as parts in accordance with NZS 1170.5.

The forces in the various components were calculated in accordance with the ductility criteria shown in Table 2 below:

**Table 2: Ductility Factors**

Component	Ductility Factor $\mu$
Roof plane steel bracing	1.25 (NZS 3404 [4] category 3,
Steel Portal Frame (Flexure)	1.25 (NZS 3404 [4] category 3
Wall panels in-plane shear and flexure	1.25 (NZS 3101 [5], nominally ductile)
Fixing of wall panels to columns (welds and anchors)	1.25
Fixing of wall panels to columns (steel plate in flexure)	2.0
Rocking of façade end columns	2.0

While flexure in the wall panels is a potentially ductile mechanism, in this case the walls are lightly reinforced so that inelastic deformation is likely to be concentrated at one crack rather than spreading, leading to high reinforcement strains and potentially low-cycle fatigue fracture.

In some cases a higher ductility factor than 2.0 could be appropriate for rocking response. However this will result in increased rocking displacements, leading in this case to damage at the connection of the façade with the building.

## 5 Material Properties

The following material properties were used in the analyses:

**Table 3: Material Properties**

Material	Nominal Strength
Structural steel	$f_y = 250\text{MPa}$
Reinforcing steel	$f_y = 430\text{MPa}$
Concrete	$f_c = 40\text{MPa}$

## 6 Analysis Results

The equivalent static load method was used to analyse the forces in the components of the north-south bracing system. The results of the analysis are reported in Table 4 below as %NBS, where for the components:

$$\%NBS = \text{the reliable strength} \div \text{new building standard force}$$


**Table 4: Summary of Seismic Performance**

<b>Component</b>	<b>Action</b>	<b>Seismic Rating % NBS</b>
Steel Portal Frame	Flexure	24%NBS
Wall panels on grids 1 and 3 (force in-plane)	Flexure	>100%NBS
“	Shear	>100%NBS
“	Overtuning	62%NBS
Wall panels on grids 1 and 3 (force out-of-plane)	Flexure	82%NBS
“	Shear	>100%NBS
Bolted fixing of grid 1 and 2 wall panels to portal frames	Tension (out of plane force)	60%NBS
“	Shear (in plane force)	>100%NBS
Façade panels (force in-plane)	Flexure	67%NBS
“	Shear	>100%NBS
Façade panels (force out-of-plane)	Flexure	>100%NBS
Façade panels (force out-of-plane)	Shear	>100%NBS
Façade and rear wall panel connections to roof bracing	Tension	>100%NBS
Façade end columns (forces out of plane)	Rocking	48%NBS
Diagonal roof bracing	Tension	25%NBS




## 7 Performance in the 22 February 2011 Christchurch Earthquake

There is a Geonet earthquake strong motion recording station (PRPC) in Pages Road approximately 1km from Linwood library (see Figure 1). It can be assumed that the ground motions recorded at the Geonet station were similar to those recorded at the library site. It is therefore possible to compare the loads applied to the building by this earthquake with the current code new building standard loads used for this assessment.



**Figure 1: Relative locations of the Linwood Library and Service Centre, Geonet station PRPC and the epicentre of the Christchurch earthquake**

Figure 2 shows the 5% damped response spectra for ground motions from the 22 February magnitude 6.3 Christchurch earthquake recorded at the PRPC station, along with the current design standard spectrum.



**Figure 2: Acceleration response spectra from ground motions recorded by Geonet station PRPC near to Linwood Library, compared with the current design standard 100%NBS acceleration spectrum for the site**

The north-south natural period of vibration of the building is in the 0.15 to 0.25 second range. It can be seen from Figure 2 that the loads experienced were similar to or in excess of the code loads in this period range.

The building sustained moderate structural damage in the Christchurch earthquake, and total collapse of suspended ceilings. The structural damage included tension yielding of the roof bracing and cracking of concrete wall and colonnade panels.

## 8 Geotechnical Information

A desk study was carried out to assess the site at 10 Cranley Street, Linwood, Christchurch. No geotechnical investigations were undertaken for this assessment. The building is located on flat-lying ground in the eastern Christchurch suburb of Linwood. The area is underlain by marine/estuarine silts and sands of the Christchurch Formation, which are underlain by Riccarton Gravels (Brown and Wilson, 1998; IGNS, 1992; IGNS, 2008; Environment Canterbury well database).

Deep boreholes in Christchurch show the alluvial and estuarine deposits exceed 200 metres depth (Brown and Wilson, 1988). The site is therefore classified as subsoil Class D (deep soil) in accordance with NZS 1170.5:2004.

The closest known active fault to the site is the Port Hills Fault; however this lies approximately 4 km to the south of the site and although it ruptured during the Christchurch earthquake on 22 February 2011 it did not rupture the ground surface. Therefore the fault rupture hazard at the site is considered to be very low.

The liquefaction hazard at the site is high, as the area around the building is underlain by at least 20 metres of silt and fine sand (Tonkin and Taylor, 2011a; Environment Canterbury, 2004).

However strong ground shaking during the Christchurch earthquake in February did not cause liquefaction (Tonkin and Taylor, 2011a; Environment Canterbury, 2004).

Following the Canterbury earthquake sequence, land in the green zone was divided into three technical categories. Each category describes the level of land damage (liquefaction induced subsidence) predicted in future earthquakes, and guidance is given for the repair and rebuild of structures (Department of Building and Housing, Nov 2011). This guidance has been used primarily for residential properties, therefore in accordance with the revised guidelines this site is classified as being Urban Nonresidential. However, based on the assessment of the surrounding properties, it can be assumed that this site would be Technical Category 2 (TC2). This means that enhanced foundation solutions are required in the rebuild and repair of buildings; standard NZS 3604 solutions are no longer viable to satisfy Building Code requirements.

A more detailed evaluation will be required at detailed design stage.

## 9 Evaluation of Results

The major deficiencies relative to the new building standard are the strength of the roof bracing (25% NBS), the rocking resistance of the end façade columns (48% NBS), the rafters of the portal frames require braces to prevent lateral torsional buckling (24%NBS) and the effectiveness of the wall panels (62%NBS). These deficiencies have contributed to the damage that was observed following the Christchurch earthquake, i.e. loose, yielded roof bracing, and cracking in the colonnade concrete panels. It should be noted that that yielding of the bracing and foundation rocking are expected and acceptable response mechanisms given the magnitude of shaking experienced at the site. However it is probable that the amount of damage to the building would have been less if it had complied with current design standards.

The building design and detailing generally gives the impression of having been targeted at the minimum code requirements of the day. As an example, the floor slab is unreinforced and the thickening foundation has only limited reinforcement in places. A detailed inspection of the floor slab for damage has not yet been carried out.

Although the wall panels in the longitudinal direction could provide the capacity required, the foundations will not provide the stability between gridlines D and E for the panels to be effective. Therefore a separate analysis was carried out to account for these panels overturning. The panels within the steel frame will provide more overturning resistance because they are fixed to the concrete encased steelwork but will pick up more stress as a result. However, the fixing of the wall panels on grids 1 and 3 to the steel framing lack robustness in view of their role in supporting both out of plane and in plane forces. A braced bay in the longitudinal direction is strongly recommended given the unreinforced slab and foundations. The options for this are steel cross braces, a panel thickening or window infills combined with angle connectors for the panels and concrete encased stanchions.

A continuous eaves member connected to the panels is required to improve the out of plane capacity.

The roof bracing has become elongated and cannot be considered as having load bearing capacity. Replacement of the roof bracing is required in all cases.

## 10 Conclusions

We conclude as follows:

1. The seismic rating of the building is approximately 24% of current building code new building standard.
2. The following improvements are required to improve the rating to at least 67%NBS:
  - Strengthen the roof plane diagonal bracing;
  - Provide a braced bay panel to grids 1 and 3;
  - Provide tie members at the eaves between the portal frames connected to the wall panels on grids 1 and 3;
  - Increase the rocking resistance of the two colonnade end columns;
  - Include lateral torsional buckling braces to portal frame rafters.

## 11 References

- [1] *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, draft prepared by the Engineering Advisory Group, Revision 5, July 2011.
- [2] *NZS 1170.5:2004, Structural Design Actions, Part 5 Earthquake Actions New Zealand*, Standards New Zealand.
- [3] *NZS 3404:1997, Steel Structures Standard*, Standards New Zealand.
- [4] *NZS 3101:2006, Concrete Structures Standard*, Standards New Zealand.

## **Appendix A – CERA DEE Spreadsheet**

Detailed Engineering Evaluation Summary Data

V1.14

<b>Location</b>		Building Name: <input type="text" value="Linwood Library"/>	Unit No: <input type="text" value=""/>	Street: <input type="text" value="Cranley St"/>	Reviewer: <input type="text" value="Robert Davey"/>
Building Address: <input type="text" value=""/>	Legal Description: <input type="text" value=""/>				CPEng No: <input type="text" value="17912"/>
					Company: <input type="text" value="Opus International Consultants"/>
					Company project number: <input type="text" value="6-QUCCC.22"/>
					Company phone number: <input type="text" value="03-3635400"/>
					Date of submission: <input type="text" value="Sep-13"/>
					Inspection Date: <input type="text" value="1-Jun-11"/>
					Revision: <input type="text" value="Final V3"/>
Building Unique Identifier (CCC): <input type="text" value="PRO 1982-001"/>					Is there a full report with this summary? <input type="text" value="yes"/>

<b>Site</b>		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text" value=""/>
		Soil type: <input type="text" value="silty sand"/>	Soil Profile (if available): <input type="text" value=""/>
		Site Class (to NZS1170.5): <input type="text" value="D"/>	If Ground improvement on site, describe: <input type="text" value=""/>
		Proximity to waterway (m, if <100m): <input type="text" value=""/>	Approx site elevation (m): <input type="text" value="12.00"/>
		Proximity to cliff top (m, if <100m): <input type="text" value=""/>	
		Proximity to cliff base (m, if <100m): <input type="text" value=""/>	

<b>Building</b>		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value="12.30"/>
		Ground floor split?: <input type="text" value="no"/>		Ground floor elevation above ground (m): <input type="text" value="0.30"/>
		Storeys below ground: <input type="text" value="0"/>		if Foundation type is other, describe: <input type="text" value="Ties in one direction only"/>
		Foundation type: <input type="text" value="pads with tie beams"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value=""/>	Date of design: <input type="text" value="1992-2004"/>
		Building height (m): <input type="text" value="4.00"/>		
		Floor footprint area (approx): <input type="text" value="800"/>		
		Age of Building (years): <input type="text" value="20"/>		
		Strengthening present?: <input type="text" value="no"/>		If so, when (year)? <input type="text" value=""/>
		Use (ground floor): <input type="text" value="public"/>		And what load level (%g)? <input type="text" value=""/>
		Use (upper floors): <input type="text" value=""/>		Brief strengthening description: <input type="text" value=""/>
		Use notes (if required): <input type="text" value=""/>		
		Importance level (to NZS1170.5): <input type="text" value="IL2"/>		

<b>Gravity Structure</b>		Gravity System: <input type="text" value="frame system"/>	rafter type, purlin type and cladding: <input type="text" value="Steel UB, steel pulins, steel cladding"/>
		Roof: <input type="text" value="steel framed"/>	describe sytem: <input type="text" value="concrete slab on ground"/>
		Floors: <input type="text" value="other (note)"/>	beam and connector type: <input type="text" value="530UB, welded connection"/>
		Beams: <input type="text" value="steel non-composite"/>	typical dimensions (mm x mm): <input type="text" value="530UB concrete encased"/>
		Columns: <input type="text" value="structural steel"/>	<input type="text" value="0"/>
		Walls: <input type="text" value="non-load bearing"/>	<input type="text" value="125"/>

<b>Lateral load resisting structure</b>		Lateral system along: <input type="text" value="single level tilt panel"/>	Note: Define along and across in detailed report!	note total length of wall at ground (m): <input type="text" value="15"/>
		Ductility assumed, μ: <input type="text" value="1.25"/>		estimate or calculation? <input type="text" value="estimated"/>
		Period along: <input type="text" value="0.40"/>		estimate or calculation? <input type="text" value="estimated"/>
		Total deflection (ULS) (mm): <input type="text" value="50"/>		estimate or calculation? <input type="text" value="estimated"/>
		maximum interstorey deflection (ULS) (mm): <input type="text" value="50"/>		
		Lateral system across: <input type="text" value="welded and bolted steel moment frame"/>		note typical bay length (m): <input type="text" value=""/>
		Ductility assumed, μ: <input type="text" value="1.25"/>		estimate or calculation? <input type="text" value="estimated"/>
		Period across: <input type="text" value="0.40"/>		estimate or calculation? <input type="text" value="estimated"/>
		Total deflection (ULS) (mm): <input type="text" value="50"/>		estimate or calculation? <input type="text" value="estimated"/>
		maximum interstorey deflection (ULS) (mm): <input type="text" value="50"/>		

<b>Separations:</b>		north (mm): <input type="text" value=""/>	leave blank if not relevant
		east (mm): <input type="text" value=""/>	
		south (mm): <input type="text" value=""/>	
		west (mm): <input type="text" value=""/>	

<b>Non-structural elements</b>		Stairs: <input type="text" value=""/>	thickness and fixing type: <input type="text" value="125mm, weld plates"/>
		Wall cladding: <input type="text" value="precast panels"/>	describe: <input type="text" value="steel profile"/>
		Roof Cladding: <input type="text" value="Metal"/>	
		Glazing: <input type="text" value="aluminium frames"/>	
		Ceilings: <input type="text" value="light tiles"/>	
		Services(list): <input type="text" value=""/>	

<b>Available documentation</b>		Architectural: <input type="text" value="full"/>	original designer name/date: <input type="text" value="CCC, 1992"/>
		Structural: <input type="text" value="full"/>	original designer name/date: <input type="text" value="O'Loughlin, Taylor, Spence 1993"/>
		Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
		Electrical: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
		Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>

<b>Damage</b>		Site performance: <input type="text" value="Slight damage"/>	Describe damage: <input type="text" value="Minor settlement"/>
Site: (refer DEE Table 4-2)		Settlement: <input type="text" value="0-25mm"/>	notes (if applicable): <input type="text" value=""/>
		Differential settlement: <input type="text" value="0-1:350"/>	notes (if applicable): <input type="text" value=""/>
		Liquefaction: <input type="text" value="0-2 m³/100m²"/>	notes (if applicable): <input type="text" value=""/>
		Lateral Spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
		Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
		Ground cracks: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
		Damage to area: <input type="text" value="slight"/>	notes (if applicable): <input type="text" value=""/>

<b>Building:</b>		Current Placard Status: <input type="text" value="red"/>	
Along	Damage ratio: <input type="text" value="28%"/>	Describe (summary): <input type="text" value="Minor to moderate cracking in concrete panels, yielding and buckling of roof bracing"/>	Describe how damage ratio arrived at: <input type="text" value=""/>
Across	Damage ratio: <input type="text" value="25%"/>	Describe (summary): <input type="text" value="Minor to moderate cracking in concrete panels"/>	$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
Diaphragms	Damage?: <input type="text" value="no"/>		Describe: <input type="text" value=""/>
CSWs:	Damage?: <input type="text" value="no"/>		Describe: <input type="text" value=""/>
Pounding:	Damage?: <input type="text" value="no"/>		Describe: <input type="text" value=""/>
Non-structural:	Damage?: <input type="text" value="yes"/>		Describe: <input type="text" value="Collapsed suspended ceiling"/>

<b>Recommendations</b>		Level of repair/strengthening required: <input type="text" value="significant structural"/>	Describe: <input type="text" value="Crack repairs and improved roof bracing, wall bracing and foundation ties. The building was extensively fire damaged in March 2012."/>
		Building Consent required: <input type="text" value="yes"/>	Describe: <input type="text" value=""/>
		Interim occupancy recommendations: <input type="text" value="do not occupy"/>	Describe: <input type="text" value=""/>
Along	Assessed %NBS before e'quakes: <input type="text" value="25%"/>	Assessed %NBS after e'quakes: <input type="text" value="18%"/>	#### %NBS from IEP below
Across	Assessed %NBS before e'quakes: <input type="text" value="24%"/>	Assessed %NBS after e'quakes: <input type="text" value="18%"/>	#### %NBS from IEP below
			If IEP not used, please detail assessment methodology: <input type="text" value="Quantitative"/>



**Opus International Consultants Ltd**  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

t: +64 3 363 5400  
f: +64 3 365 7858  
w: [www.opus.co.nz](http://www.opus.co.nz)