



Christchurch City Council

**Little River Cemetery
Community Building
PRK 3668 BLDG 001 EQ2**

Detailed Engineering Evaluation

Quantitative Assessment Report






Christchurch City Council

Little River Cemetery Community Building

Quantitative Assessment Report

32 Upper Church Rd, Little River, Canterbury

Prepared By 
Clayton Taylor
Structural Engineer

Reviewed By 
Simon Biggs
Senior Structural Engineer

Approved By 
Paul Campbell
Principal Structural Engineer
CPEng 197688

Opus International Consultants Ltd
Christchurch Office
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail
Centre, Christchurch 8140
New Zealand

Telephone: +64 3 363 5400
Facsimile: +64 3 365 7858

Date: March 2013
Reference: 6-QUCC1.51
Status: Final

Summary

Little River Cemetery Community Building
PRK 3668 BLDG 001 EQ2

Detailed Engineering Evaluation
Quantitative Report - Summary
Final

Background

This is a summary of the quantitative report for the Little River Cemetery Community Building, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on 14 June 2012 and 25 January 2013

Key Damage Observed

Key damage observed includes multiple cracking in internal wall and ceiling linings which is likely a result of the recent seismic activity.

Critical Structural Weaknesses

No critical structural weaknesses were identified.

Indicative Building Strength

The structure has been found to have a seismic capacity of 84%NBS, limited by lack of footing tie down, and is therefore classified as a low risk building. The factors limiting the structure from achieving 100% NBS or greater, is the lack of tie-down between floor bearers and footings and, to a lesser extent, the bracing capacity of the northern end wall.

Recommendations

The following recommendations have been made for the building:

- (a) If improved performance is required then install hold-down connections between the timber bearers and piles in accordance with NZS 3604.
- (b) Repair wall lining cracks.

Contents

Summary i

1 Introduction.....1

2 Compliance1

3 Earthquake Resistance Standards..... 4

4 Building Description 7

5 Survey 8

6 Damage Assessment..... 8

7 General Observations..... 8

8 Detailed Seismic Assessment 8

9 Summary of Geotechnical Appraisal 10

10 Conclusions..... 10

11 Recommendations 10

12 Limitations..... 11

13 References 11

Appendix 1 - Photographs

Appendix 2 – CERA DEE Spreadsheet

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of Little River Cemetery Community Building, located at 32 Upper Church Rd, Little River following the Canterbury Earthquake Sequence since September 2010.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [3] [4].

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or

5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.

- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the DBH guidance document dated 12 June 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

4 Building Description

4.1 General

The building is a single-storey, timber framed structure approximately 12.7m long and 4.5m wide. The metal roof is supported by rafters on a central longitudinal timber truss. Timber stud walls are supported on a timber framed floor with floor bearers supported by a mixture of driven timber and concrete piles.

The structure is connected to the adjacent church by a passageway.



Figure 2: Little River Cemetery Community Building location (Courtesy Google Earth)

4.2 Gravity Load Resisting System

The gravity load system supporting the roof is timber rafters supported by a central longitudinal truss supported by load bearing timber stud walls on a timber floor. Floor bearers are supported by piled footings. The longitudinal truss appears to be a recent addition and we suspect it has replaced a previous ridge beam.

4.3 Seismic Load Resisting System

The seismic load resisting system is a lined roof/ceiling that distributes lateral load to bracing walls by diaphragm action. As this building is of pre 1978 construction it has been assumed that the lined walls are constructed with diagonal braces within the framing. The loads in the bracing walls transfer to ground through the floor and piles.

5 Survey

Inspections were undertaken by Opus on 14 June 2012 and 25 January 2013, to measure, photograph and ascertain the structural systems and extent of damage.

6 Damage Assessment

There appears to be separation of the timber encasing and the wall to the roof beam spanning over the kitchen at the northern end of the building, likely to be caused by longitudinal shrinkage. A closer inspection should be undertaken to ensure that the beam remains fully connected to the wall and that only the timber encasing has pulled away. This damage is not considered to be the result of the recent seismic activity.

There is a noticeable sag in the ceiling section over the passageway to the adjoining church. This damage is not believed to be as a result of the recent seismic activity.

There are numerous instances of minor cracking in the internal wall lining. These are likely the result of excessive wall deflections caused by the seismic activity since September 2010. However these will not significantly impact the performance of the building in future seismic events.

7 General Observations

Visual inspection shows that there is no significant connection between bearers and the supporting piles. No indications of failure were observed, but a lack of hold down fixings is not in accordance with current design codes.

It was noted that the connecting passageway between the community building and the church is a flexible structure, hence during seismic activity it is not expected that any significant amount of load will be shared between the two structures by transmitting through the passageway. However, damage could occur in the passageway due to excessive differential displacement should the two structures sway out of sync with each other.

8 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

8.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSW's were identified in this building during the analysis.

8.2 Seismic Coefficient Parameters

Seismic Coefficient Parameters The seismic design parameters based on current design requirements from NZS1170.5:2004 and the NZBC clause B1 for this building are:

- Site soil class C, clause 3.1.3 NZS 1170.5:2004;
- Site hazard factor, $Z=0.3$, B1/VM1 clause 2.2.14B;
- Return period factor $R_u = 1.0$ from Table 3.5, NZS 1170.5:2004, for an Importance Level 2 structure with a 50 year design life;

8.3 Expected Ductility Factors

From a newspaper article posted on the wall of the community building we understand that the adjacent church building was constructed in 1879. This community building has been built in a similar style to the church, but of more recent origin, most likely pre-1978. Timber buildings of this age are expected to perform with only limited ductility. Therefore a structural ductility factor of 1.25 for wall bracing elements has been used in this seismic assessment.

8.4 Detailed Seismic Assessment Results

A summary of the structural performance of the building is shown in the following table. Note that the values given represent the worst performing elements in the building, as these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

Table 2: Summary of Seismic Performance

Structural Element/System	Failure mode and description of limiting criteria	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Walls – Long Direction	In-plane shear	No	>100
Walls – Short Direction	In-plane shear	No	94
Footing tie-down	Overturning	No	>100
Footing tie-down	Sliding	No	84
Roof trusses supporting water tanks	In-plane bending	No	>100

8.5 Discussion of Results

The building has a calculated seismic capacity of 84% NBS, as limited by the lack of tie-down between the bearers and footings. The structure is therefore classified as a low seismic risk building in accordance with NZSEE guidelines.

8.6 Limitations and Assumptions in Results

The observed level of damage suffered by the building was deemed low enough to not affect the seismic capacity. Therefore the analysis and assessment of the building was based on it being in an undamaged state. There may be damage to the building that was unable to be observed that could cause the capacity of the building to be reduced. Therefore, the capacity of the building may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- a. Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- b. Assessments of material strengths based on limited drawings, specifications and site inspections
- c. The normal variation in material properties which change from batch to batch.
- d. Approximations made in the assessment of the capacity of each element.

9 Summary of Geotechnical Appraisal

Due to a lack of observed ground damage, no specific geotechnical assessment has been undertaken. The seismic site parameter used for the structural analysis was Soil Class Type C, based on geotechnical advice from Opus.

10 Conclusions

This building has been assessed to have a seismic capacity of 84% NBS, limited by lack of footing tie down, and therefore is not classed as an earthquake prone building. The key seismic strength deficiency is the lack of tie-down of floor bearers to footings.

11 Recommendations

The following recommendations have been made for the building:

- (a) If improved performance is required then install hold-down connections between the timber bearers and piles in accordance with NZS 3604.
- (b) Repair wall lining cracks.

12 Limitations

- (a) This report is based on an inspection of the structure with a focus on the damage sustained from the September 2010 Canterbury Earthquake and aftershocks only. Some non-structural damage is mentioned but this is not intended to be a comprehensive list of non-structural items.
- (b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at the time.
- (c) This report is prepared for the CCC to assist with assessing remedial works required for council buildings and facilities. It is not intended for any other party or purpose.

13 References

- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] DBH (2012), Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch, Department of Building and Housing, June 2012.

Appendix 1 - Photographs

Little River Cemetery Community Building – Detailed Engineering Evaluation

Little River Cemetery Community Building		
No.	Item description	Photo
1.	Western wall	
2.	Southern end wall	

Little River Cemetery Community Building – Detailed Engineering Evaluation

<p>3.</p>	<p>Northern end wall and kitchen (refer beam over kitchen)</p>	 A photograph showing the northern end wall and kitchen area. The room features a vaulted ceiling, light-colored walls, and wood-paneled lower walls. A wooden counter with a blue top runs along the wall. To the left, there are large windows. In the center, there is a doorway leading to another room. A blue door is visible on the right side.
<p>4.</p>	<p>Passageway to church</p>	 A photograph showing a passageway leading to a church. The area is carpeted and has light-colored walls. There are two wooden chairs with white seats on either side of a central doorway. The doorway leads to a darker area, likely the church interior. There are decorative stained-glass windows above the doorway.
<p>5.</p>	<p>Southern end wall</p>	 A photograph showing the southern end wall of the room. The room has a vaulted ceiling and light-colored walls. There is a wooden table in the center, a wooden chair, and a sofa covered with a striped cloth on the right. A doorway is visible on the left side. There are decorative stained-glass windows on the wall.

Little River Cemetery Community Building – Detailed Engineering Evaluation

<p>6.</p>	<p>Western wall</p>	 A photograph showing the interior of a room. On the right, there is a large window with a decorative, multi-paned glass section at the top. A sofa covered in a striped cloth is positioned in front of the window. To the left, there is a wooden table and some equipment on a desk.
<p>7.</p>	<p>Gib board cracks between glazing frames</p>	 A close-up photograph of a wall. A horizontal crack runs across the wall between two vertical wooden frames. A yellow measuring tape is placed at the bottom of the image for scale, showing the crack is approximately 100 cm long.
<p>8.</p>	<p>Gib board cracks around door frame</p>	 A close-up photograph of a wall. A vertical crack runs down the wall, starting from the top and extending towards a wooden door frame at the bottom. The crack is irregular and appears to be in the plaster or drywall.

Little River Cemetery Community Building – Detailed Engineering Evaluation

<p>9.</p>	<p>Gib board cracks over passageway</p>	 A photograph showing a vertical crack in a white wall. The crack runs from the top of the frame down to a horizontal ledge or passageway. The wall is otherwise plain and white.
<p>10.</p>	<p>Gib board cracks over window frames in western wall</p>	 A photograph showing a vertical crack in a white wall. The crack runs from the top of the frame down to a window frame. The window is partially visible at the bottom left, showing a view of greenery outside. The wall is otherwise plain and white.

Little River Cemetery Community Building – Detailed Engineering Evaluation

11.	Gib board cracks over window frames in western wall	
12.	Separation of lining around beam from western wall in kitchen	
13.	Roof trusses	

Little River Cemetery Community Building – Detailed Engineering Evaluation

14.	Water tanks in roof space	
15.	Water tank in roof space	
16.	Sub-floor supports – mix of timber or concrete piles and timber blocking	

Little River Cemetery Community Building – Detailed Engineering Evaluation

17.	Joist-bearer-pile. Note: No apparent tie-down between any members	
18.	Timber pile	

Appendix 2 – CERA DEE Spreadsheet

Location		Building Name: Little River Cemetery Community Building	Reviewer: Paul Campbell
Building Address: 32 Upper Church Rd	Unit No: Street	CPEng No: 197688	Company: Opus International Consultants
Legal Description:		Company project number: 6-QUCC1.51	Company phone number: 03 363 5400
GPS south: 43 45 31.00	Degrees Min Sec	Date of submission: 19-Mar-13	Inspection Date: 14/06/2012 and 25/01/2013
GPS east: 172 48 25.00		Revision: Final	Is there a full report with this summary? yes
Building Unique Identifier (CCC): PRK_3668_BLDG_001_EQ2			

Site	Site slope: slope < 1 in 10	Max retaining height (m):
Soil type:	Site Class (to NZS1170.5): C	Soil Profile (if available):
Proximity to waterway (m, if <100m):	Proximity to cliff top (m, if < 100m):	If Ground improvement on site, describe:
Proximity to cliff base (m, if <100m):		Approx site elevation (m):

Building	No. of storeys above ground: 1	single storey = 1	Ground floor elevation (Absolute) (m):
Ground floor split? no	Storeys below ground: 0	Foundation type: other (describe)	Ground floor elevation above ground (m):
Building height (m): 2.20	Floor footprint area (approx): 64	Age of Building (years): 60	if Foundation type is other, describe: mixture of timber and concrete piles
Strengthening present? no	Use (ground floor): other (specify)	Use (upper floors): meeting room	height from ground to level of uppermost seismic mass (for IEP only) (m):
Use notes (if required): meeting room	Importance level (to NZS1170.5): IL2		Date of design:
			If so, when (year)?
			And what load level (%g)?
			Brief strengthening description:

Gravity Structure	Gravity System: load bearing walls	truss depth, purlin type and cladding: corrugated steel
Roof: timber truss	Floors: timber	joist depth and spacing (mm):
Beams: timber	Columns:	type:
Walls:		

Lateral load resisting structure	Lateral system along: lightweight timber framed walls	Note: Define along and across in detailed report!	note typical wall length (m):
Ductility assumed, μ: 1.25	Period along: 0.11		estimate or calculation? calculated
Total deflection (ULS) (mm):	maximum interstorey deflection (ULS) (mm):		estimate or calculation?
Lateral system across: lightweight timber framed walls	Ductility assumed, μ: 1.25	Period across: 0.11	note typical wall length (m):
Total deflection (ULS) (mm):	maximum interstorey deflection (ULS) (mm):	estimate or calculation? calculated	estimate or calculation?

Separations:	north (mm):	east (mm):	south (mm):	west (mm):	leave blank if not relevant
---------------------	-------------	------------	-------------	------------	-----------------------------

Non-structural elements	Stairs:	describe: Timber
Wall cladding: other light	Roof Cladding: Metal	describe: Corrugated iron
Glazing: timber frames	Ceilings: fibrous plaster, fixed	
Services(list):		

Available documentation	Architectural: none	original designer name/date:
Structural: none	Mechanical: none	original designer name/date:
Electrical: none	Geotech report: none	original designer name/date:
		original designer name/date:

Damage	Site performance:	Describe damage:
Site: (refer DEE Table 4-2)	Settlement: none observed	notes (if applicable):
Differential settlement: none observed	Liquefaction: none apparent	notes (if applicable):
Lateral Spread: none apparent	Differential lateral spread: none apparent	notes (if applicable):
Ground cracks: none apparent	Damage to area: none apparent	notes (if applicable):

Building:	Current Placard Status:	Describe how damage ratio arrived at:
Along	Damage ratio: 0%	$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
Describe (summary):	Damage ratio: 0%	
Across	Damage?: no	Describe:
Diaphragms	Damage?: no	Describe:
CSWs:	Damage?: no	Describe:
Pounding:	Damage?: no	Describe:
Non-structural:	Damage?: no	Describe:

Recommendations	Level of repair/strengthening required: none	Describe: floorboards to be removed to install	
Building Consent required: no	Interim occupancy recommendations: full occupancy	Describe: bearer to pier connections if 100%NBS	
		Describe: is desired. (Significant Structural)	
Along	Assessed %NBS before: 84%	Assessed %NBS after: 84%	#### %NBS from IEP below
Across	Assessed %NBS before: 84%	Assessed %NBS after: 84%	#### %NBS from IEP below
			If IEP not used, please detail assessment methodology: Quantitative



Opus International Consultants Ltd

20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400
f: +64 3 365 7858
w: www.opus.co.nz