



CLIENTS | PEOPLE | PERFORMANCE

**Papanui Memorial Reserve Toilet**  
**PRK 0586 BLDG 001 EQ2**  
Detailed Engineering Evaluation  
Qualitative Report  
Version Final

500 Papanui Road  
Papanui

**Papanui Memorial Reserve  
PRK 0586 BLDG 001 EQ2**

Detailed Engineering Evaluation  
Qualitative Report  
Version Final

500 Papanui Road, Papanui

Christchurch City Council

**Prepared By**  
Chris Wells

**Reviewed By**  
Razel Ramilo

**Date**  
18<sup>th</sup> September 2012

# Contents

Qualitative Report Summary	5
1. Background	7
2. Compliance	8
2.1 Canterbury Earthquake Recovery Authority (CERA)	8
2.2 Building Act	9
2.3 Christchurch City Council Policy	10
2.4 Building Code	10
3. Earthquake Resistance Standards	11
4. Building Description	13
4.1 General	13
4.2 Gravity Load Resisting System	13
4.3 Lateral Load Resisting System	14
5. Assessment	15
6. Damage Assessment	16
6.1 Surrounding Buildings	16
6.2 Residual Displacements and General Observations	16
6.3 Ground Damage	16
7. Critical Structural Weakness	17
7.1 Short Columns	17
7.2 Lift Shaft	17
7.3 Roof/Plan Irregularity	17
7.4 Staircases	17
7.5 Site Characteristics	17
7.6 Pounding effect	17
8. Geotechnical Consideration	18
8.1 Site Description	18
8.2 Published Information on Ground Conditions	18
8.3 Seismicity	21
8.4 Slope Failure and/or Rockfall Potential	22

8.5	Liquefaction Potential	22
8.6	Conclusions & Recommendations	22
9.	Survey	23
10.	Initial Capacity Assessment	24
10.1	% NBS Assessment	24
10.2	Seismic Parameters	24
10.3	Expected Structural Ductility Factor	24
10.4	Discussion of Results	24
11.	Initial Conclusions	25
12.	Recommendations	26
13.	Limitations	27
13.1	General	27
13.2	Geotechnical Limitations	27

## Table Index

Table 1	%NBS compared to relative risk of failure	12
Table 2	ECan Borehole Summary	18
Table 3	EQC Geotechnical Investigation Summary Table	19
Table 4	Summary of Known Active Faults	21

## Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	11
Figure 2	Plan Sketch Showing Key Structural Elements	13
Figure 3	Post February 2011 Earthquake Aerial Photography	20

## Appendices

- A Photographs
- B Building Sketch Showing Key Structural Elements
- C CERA Building Evaluation Form

# Qualitative Report Summary

**Papanui Memorial Reserve Toilet**

**PRK 0586 BLDG 001 EQ2**

**Detailed Engineering Evaluation**

**Qualitative Report - SUMMARY**

**Version Final**

**500 Papanui Road, Papanui**

## **Background**

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 19<sup>th</sup> July 2012.

## **Building Description**

The single story public toilet building is located at 500 Papanui Road within the northeast corner of the Papanui Memorial Reserve, with a two story neighbouring structure.

The original construction is estimated to be between 1965 and 1976; no structural alterations appear to have been made to the building.

The foundations are likely to be strip footings. The floor is formed by a concrete ground slab on grade. The building's exterior walls are constructed from 20 series masonry block with internal partitions being 10 series masonry block with a plastered finish to the internal wall faces. The roof has approximately a 3 degree mono-pitch, constructed from in-situ concrete with a proprietary waterproof membrane on top and exposed ceiling beneath.

## **Key Damage Observed**

No major damage was observed to the structure.

## **Critical Structural Weaknesses**

No Significant critical structural weakness has been identified.

## **Indicative Building Strength (from IEP and CSW assessment)**

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the original capacity of the building has been assessed to be in the order of 21% NBS and post-earthquake capacity also in the order of 21% NBS. The buildings post-earthquake capacity excluding critical structural weaknesses is in the order of 21% NBS.

The building has been assessed to have a seismic capacity in the order of 21% NBS and is therefore a potentially Earthquake Prone Building.

## **Recommendations**

The building has achieved less than 34% NBS seismic capacity according to the initial IEP assessment and as a result is classified as potentially an Earthquake Prone building in accordance with the NZSEE guidelines. Therefore it is recommended that further detailed assessment be carried out on the structure to more accurately assess the buildings %NBS.

# 1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Papanui Memorial Reserve Toilet.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. As there are no available drawings, the building's evaluation is based on the visual inspection carried out on site. The date of construction of the building is unknown and therefore estimated for the purpose of this assessment. The results of the evaluation, however, may change should the exact construction date is made known.

## 2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage

## **2.2 Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

### **Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

#### **2.2.1 Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## **2.4 Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

### 3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

**Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE**

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times


**Table 1 %NBS compared to relative risk of failure**

## 4. Building Description

### 4.1 General

The single story public toilet is located within Papanui Memorial Reserve at 500 Papanui Road. The Building is estimated to have been constructed in 1970. It appears that no alterations have been made to the building since construction. The nearest structure is a 2-storey building located 230mm northeast.

The foundations are likely to be strip footings. The floor slab is formed by a concrete ground slab on grade. The building's exterior walls are constructed from 20 series masonry block with internal partitions being 10 series masonry block with a plastered finish to the internal wall faces. From the visual inspection it cannot be confirmed if the blocks are reinforced or filled. The roof has approximately a 3 degree mono-pitch, constructed from in-situ concrete with a proprietary waterproof membrane on top and exposed ceiling beneath.



**Figure 2 Plan Sketch Showing Key Structural Elements**

The building is approximately 8.5m in length by 2.2m in width, with a height of 2.2m. The building occupies an area of 18.7m<sup>2</sup> approximately. The site for the building is level. The building is located adjacent to a two storey structure with a separation distance of 230mm.

No plans were available for the structure reviewed.

### 4.2 Gravity Load Resisting System

Gravity roof loads are transferred via the in-situ roof to the perimeter load bearing masonry walls down to the foundations and into the ground.

### **4.3 Lateral Load Resisting System**

In both the longitudinal and transverse direction, seismic loads are transferred via diaphragm action of the in-situ roof to the concrete masonry walls by panel action. From the walls, the seismic loads are then transferred to the foundations and into the ground.

## 5. Assessment

An inspection of the building was undertaken on the 19<sup>th</sup> July 2012. Both the interior and exterior of the building were inspected.

The inspection consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for this building has been based on the IEP procedure described by the NZSEE and based on the information obtained from visual inspection of the building. As there are no available drawings, the year of construction of the building was estimated for the purpose of this assessment.

## 6. Damage Assessment

### 6.1 Surrounding Buildings

The adjacent building appears to have suffered some damage as cracks were found on the northwest panels.

### 6.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during our inspection of the building. Minor cracking was observed along walls at the bottom edge of top row blocks.

### 6.3 Ground Damage

There was no evidence of ground damage on the property or surrounding neighbour's land.

## **7. Critical Structural Weakness**

### **7.1 Short Columns**

No significant short columns are present in the structure.

### **7.2 Lift Shaft**

The building does not contain a lift shaft.

### **7.3 Roof/Plan Irregularity**

The roof structure is constructed of in-situ concrete which provides a diaphragm action stiffening the structure. Although some plan irregularity exists due to the stiffness of the roof, we do not believe this is significant.

### **7.4 Staircases**

The building does not contain a staircase.

### **7.5 Site Characteristics**

Following the geotechnical appraisal it was found that the site is moderately susceptible to liquefaction. For the purposes of the IEP assessment and determination of the %NBS score of the building, the effects of soil liquefaction on the performance of the building has been assessed as 'insignificant' site characteristic in accordance with the NZSEE guidelines.

### **7.6 Pounding effect**

The nearest structure is a 2-story building to the Northeast. There is an acceptable 230mm separation between the two buildings, thus pounding is not a concern.

## 8. Geotechnical Consideration

### 8.1 Site Description

The site is situated in the suburb of Papanui, in northern Christchurch. It is relatively flat at approximately 12m above mean sea level. It is approximately 200m east of northern rail line, 3.5km north of the Avon River, 4.5km south of the Styx River, and 10km west of the coast (Pegasus Bay).

### 8.2 Published Information on Ground Conditions

#### 8.2.1 Published Geology

The geological map of the area<sup>1</sup> indicates that the site is underlain by the following units:

- Dominantly sand and silt overbank deposits, being alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, Holocene in age.

Figure 72 from Brown & Weeber indicates that groundwater is likely 2m to 3m below ground level (bgl).

#### 8.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that twenty one boreholes with lithographic logs are located within 200m of the site (see Table 1).

These indicate the area is underlain by sands and silts with one borehole encountering sandy gravel below 10m bgl. Varying amounts of clay and peat are also indicated with a notable peat horizon typically encountered around 2.0 m bgl.

Groundwater has been indicated typically between 1.1m and 2.7m bgl.

**Table 2 ECan Borehole Summary**

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35-11513-WC	6.0m	1.1m bgl	~120m N
M35-11514-WC	6.0m	1.1m bgl	~120m N
M35-11515-WC	6.0m	1.1m bgl	~120m N
M35-11516-WC	6.0m	-	~120m N
M35-11517-WC	6.0m	1.2m bgl	~120m N
M35-13363-WC	2.94m	-	~150m SE
M35-13364-WC	2.99m	-	~200m SE
M35-13803-WC	2.59m	-	~100m SE
M35-13804-WC	2.44m	-	~20m S

<sup>1</sup> Brown, L. J. & Weeber, J.H. (1992): *Geology of the Christchurch Urban Area*. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. IGNS Limited: Lower Hutt.

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35-13805-WC	2.28m	-	~10m E
M35-13806-WC	2.28m	-	~ 40m N
M35-13807-WC	2.28m	-	~60m N
M35-13808-WC	2.28m	-	~90m N
M35-13813-WC	2.13m	-	~200m E
M35-13814-WC	2.28m	-	~180m ENE
M35-13817-WC	1.99m	-	~100m ENE
M35-13830-WC*	2.59m	-	~100m WNW
M35-13831-WC	2.89m	-	~200m WNW
M35-13845-WC	1.98m	-	~140m ESE
M35-16251-WC	1.30m	-	~90m WSW
M35-6090-WC	15.0m	2.70m bgl	~180m NNW

It should be noted that the boreholes were sunk for groundwater extraction and not for geotechnical purposes. Therefore, the amount of material recovered and available for interpretation and recording will have been variable at best and may not be representative. The logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

### 8.2.3 EQC Geotechnical Investigations

The Earthquake Commission has undertaken geotechnical testing in the area of the site. Information pertaining to this investigation is included in the Tonkin & Taylor Report for Papanui<sup>2</sup>. One investigation point was undertaken within 200m of the site, as summarised below in Table 2.

**Table 3 EQC Geotechnical Investigation Summary Table**

Bore Name	Orientation from Site	Depth (m bgl)	Log Summary
CPT-PAI-02	180m S	0 – 0.5	Pre-drilled
		0.5 – 2	Loose sands
		2.0 – 6.5	Firm silts
		6.5 – 8.25	Loose to medium dense sands
		8.25 – 9.25	Dense sands (GWT at 0.6m bgl)

Initial observations of the CPT results indicate the soils are firm silts and loose to medium dense sands with dense sands intersected at 8.25 m bgl.

Groundwater has been indicated at approximately 0.6m bgl.

<sup>2</sup> Tonkin & Taylor Ltd., 2011: Christchurch Earthquake Recovery, *Geotechnical Factual Report, Papanui*.

### 8.2.4 CERA Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has indicated the site is situated within the Green Zone, indicating that repair and rebuild may take place.

Land in the CERA green zone has been divided into three technical categories. These categories describe how the land is expected to perform in future earthquakes.

The site is indicated as being within the TC2 (yellow) zone<sup>3</sup>. This means that minor to moderate land damage from liquefaction is possible in future significant earthquakes.

### 8.2.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows no signs of liquefaction outside the building footprint or adjacent to the site, as shown in Figure 1.

**Figure 3 Post February 2011 Earthquake Aerial Photography<sup>4</sup>**



### 8.2.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to comprise multiple strata of sand, with varying amounts of silt and organic horizons. Gravel and sandy gravel are anticipated at depth.

Based on the geology map, high groundwater levels of approximately 1.0m bgl are anticipated for the area. Nearby ECan and EQC intrusive investigations have confirmed high groundwater levels typically between 2.7m bgl and 0.6 bgl. The groundwater levels may be subjected to seasonal and climatic variation.

<sup>3</sup> CERA Landcheck website, <http://cera.govt.nz/my-property>

<sup>4</sup> Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>

## 8.3 Seismicity

### 8.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

**Table 4 Summary of Known Active Faults<sup>5,6</sup>**

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	130km	NW	~8.3	~300 years
Ashley Fault	25km	N	7.2	~2000 years
Greendale (2010) Fault	22km	SW	7.1	~15,000 years
Hope Fault	100km	N	7.2~7.5	120~200 years
Kelly Fault	110km	NW	7.2	~150 years
Porters Pass Fault	60km	NW	7.0	~1100 years
Cust Fault	37km	NW	-	>2000 years
Esk Fault	70km	NW	7.0	7500 years
Lees Valley Fault	50km	NW	6.7	7000 years

The recent earthquakes since 4 September 2010 have identified the presence of a previously unmapped active fault system underneath the Canterbury Plains, including Christchurch City, and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

### 8.3.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

The recent seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

<sup>5</sup> Stirling, M.W., McVerry, G.H, and Berryman K.R. (2002): "A New Seismic Hazard Model for New Zealand", *Bulletin of the Seismological Society of America*, Vol. 92 No. 5, June 2002, pp. 1878-1903.

<sup>6</sup> GNS Active Faults Database, <http://maps.gns.cri.nz/website/af/viewer>

#### **8.4 Slope Failure and/or Rockfall Potential**

The topography surrounding the site suggests that rockfall is not a potential hazard. In addition, any retaining structures or embankments nearby should be further investigated to determine the site-specific local slope instability potential.

#### **8.5 Liquefaction Potential**

The site is considered to have a minor susceptibility to liquefaction, due to the following reasons:

- Although no or limited liquefaction was observed in this area resulting from the recent Christchurch earthquake events, the presence of firm silts and loose saturated sands in conjunction with the high water table provide conditions that may produce liquefaction during a significant future seismic events; and
- The area in which the site is located is situated within the Green Zone and has been classified TC2 (yellow) suggesting that the site may be subjected to minor to moderate land damage from liquefaction is possible in future significant earthquakes.

#### **8.6 Conclusions & Recommendations**

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on stratified alluvial deposits, comprising, sand and silt with gravel likely at depth. Associated with this the site also has a moderate liquefaction potential, in particular where sands and/or silts are present.

A soil class of D (in accordance with NZS 1170.5:2004) should be adopted for the site. Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that intrusive investigation be conducted.

## 9. Survey

No level or verticality surveys have been undertaken for this building at this stage as indicated by Christchurch City Council guidelines.

## 10. Initial Capacity Assessment

### 10.1 % NBS Assessment

The building's capacity was assessed using the Initial Evaluation Procedure based on the information available. The building's capacity is expressed as a percentage of New Building Standard (% NBS) as shown below. This capacity is subjected to confirmation by a more detailed quantitative analysis.

Item	% NBS
Building's seismic capacity (No CSW observed)	21

Table 5. Indicative Building's Capacity based on the NZSEE Initial Evaluation Procedure

Following an IEP assessment, the building has been assessed as achieving 21% NBS. Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered Earthquake Prone as it achieves less than 34% NBS. This score has been adjusted for damage consideration.

### 10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class: D , NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- ▶ Site hazard factor,  $Z = 0.3$ , NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- ▶ Return period factor  $R_u = 1.0$ , NZS 1170.5:2004, Table 3.5, Importance level 2 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

### 10.3 Expected Structural Ductility Factor

A structural ductility factor of 1.25 has been assumed based on the structural system observed and the date of construction.

### 10.4 Discussion of Results

Although the toilet's construction date is unknown, comparisons were made with similarly constructed buildings and an engineering judgment was made that the building was constructed in or around 1970. The building was likely designed to the loading standard current at that time, NZS 1900: 1965. The design loads used in accordance with this standard are likely to have been less than those required by the current loads standard. When combined with the increase in the hazard factor for Christchurch 0.3, it would be expected that the building would not achieve 100% NBS.

There was no damage nor critical structural weakness identified in our visual inspection; consequently the %NBS has not reduced the baseline percentage of NBS as 21%.

## 11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 21% NBS and is therefore regarded as potentially Earthquake Prone building.

## 12. Recommendations

The building has achieved less than 34% NBS seismic capacity according to the initial IEP assessment and as a result is classified as potentially an Earthquake Prone building in accordance with the NZSEE guidelines. Therefore it is recommended that further detailed assessment be carried out on the structure to more accurately assess the buildings %NBS.

## 13. Limitations

### 13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report. A specific limitations section.

### 13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.


The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.

Appendix A  
Photographs



**Photograph 1 Southwest elevation.**



**Photograph 2 Northwest Elevation.**



**Photograph 3 Southeast Elevation.**



**Photograph 4 Perspective view from West corner.**



**Photograph 5 Horizontal cracking along the top row of blocks.**



**Photograph 6 Detail view showing cracking at wall to roof connection.**



**Photograph 7 Horizontal cracking along the top and lower row of blocks.**



**Photograph 8 Foundations on Southeast side of building also showing Separation between neighbouring structure.**



**Photograph 9 Window openings.**



**Photograph 10 Horizontal cracking along the top row of blocks.**


Appendix B

## Building Sketch Showing Key Structural Elements

LEGEND

20 SERIES

10 SERIES



Appendix C

## CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location	
Building Name:	Papanui Memorial Reserve Toilet
Building Address:	Unit No: Street 500 Papanui Road
Legal Description:	
GPS south:	Degrees Min Sec
GPS east:	
Building Unique Identifier (CCC):	PRK_0586_BLDG_001_EQ2
Reviewer:	Stephen Lee
CPEng No:	1006840
Company:	GHD
Company project number:	51309242
Company phone number:	04 472 0799
Date of submission:	
Inspection Date:	19-Jul-12
Revision:	
Is there a full report with this summary?	yes

Site	
Site slope:	flat
Soil type:	mixed
Site Class (to NZS1170.5):	D
Proximity to waterway (m, if <100m):	
Proximity to clifftop (m, if < 100m):	
Proximity to cliff base (m, if <100m):	
Max retaining height (m):	
Soil Profile (if available):	
If Ground improvement on site, describe:	
Approx site elevation (m):	12.00

Building				
No. of storeys above ground:	1	single storey = 1	Ground floor elevation (Absolute) (m):	12.00
Ground floor split?	no		Ground floor elevation above ground (m):	12.00
Storeys below ground:	0		if Foundation type is other, describe:	
Foundation type:	strip footings		height from ground to level of uppermost seismic mass (for IEP only) (m):	3.5
Building height (m):	3.50		Date of design:	1965-1976
Floor footprint area (approx):	18.70		Strengthening present?	no
Age of Building (years):	42		Use (ground floor):	public
			Use (upper floors):	
			Use notes (if required):	
			Importance level (to NZS1170.5):	IL2
			If so, when (year)?	
			And what load level (%g)?	
			Brief strengthening description:	

Gravity Structure			
Gravity System:	load bearing walls	slab thickness (mm)	100
Roof:	concrete	slab thickness (mm)	100
Floors:	concrete flat slab	overall depth x width (mm x mm)	
Beams:	none	thickness (mm)	200
Columns:			
Walls:	partially filled concrete masonry		



**Building:** Current Placard Status:

Along Damage ratio:  Describe how damage ratio arrived at:

Describe (summary):

Across Damage ratio:   $Damage\_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$

Describe (summary):

Diaphragms Damage?:  Describe:

CSWs: Damage?:  Describe:

Pounding: Damage?:  Describe:

Non-structural: Damage?:  Describe:

**Recommendations**

Level of repair/strengthening required:  Describe:

Building Consent required:  Describe:

Interim occupancy recommendations:  Describe:

Along Assessed %NBS before:  21% %NBS from IEP below If IEP not used, please detail assessment methodology:

Assessed %NBS after:

Across Assessed %NBS before:  21% %NBS from IEP below

Assessed %NBS after:

**IEP** Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1965-1976  $h_n$  from above: 3.5m

Seismic Zone, if designed between 1965 and 1992:  not required for this age of building

not required for this age of building

Period (from above): 

along	0.4	across	0.4
(%NBS) <sub>nom</sub> from Fig 3.3:	<input type="text" value="5%"/>	<input type="text" value="5%"/>	<input type="text" value="5%"/>

Note 1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0

Note 2: for RC buildings designed between 1976-1984, use 1.2

Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)

Final (%NBS)<sub>nom</sub>: 

along	<input type="text" value="5%"/>	across	<input type="text" value="5%"/>
-------	---------------------------------	--------	---------------------------------

**2.2 Near Fault Scaling Factor** Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

Near Fault scaling factor (1/N(T,D), **Factor A**): 

along	<input type="text" value="1"/>	across	<input type="text" value="1"/>
-------	--------------------------------	--------	--------------------------------

**2.3 Hazard Scaling Factor** Hazard factor Z for site from AS1170.5, Table 3.3:

Z<sub>1992</sub>, from NZS4203:1992

Hazard scaling factor, **Factor B**:

**2.4 Return Period Scaling Factor**

Building Importance level (from above):   
 Return Period Scaling factor from Table 3.1, **Factor C**:

**2.5 Ductility Scaling Factor**

Assessed ductility (less than max in Table 3.2)  along  across  
 Ductility scaling factor: =1 from 1976 onwards; or = $k_{\mu}$ , if pre-1976, from Table 3.3:    
 Ductility Scaling Factor, **Factor D**:

**2.6 Structural Performance Scaling Factor:**

Sp:    
 Structural Performance Scaling Factor **Factor E**:

**2.7 Baseline %NBS, (NBS%)<sub>b</sub> = (%NBS)<sub>nom</sub> x A x B x C x D x E**

%NBS<sub>b</sub>:

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

3.2. Vertical irregularity, Factor B:

3.3. Short columns, Factor C:

3.4. Pounding potential  
 Pounding effect D1, from Table to right   
 Height Difference effect D2, from Table to right

Therefore, Factor D:

3.5. Site Characteristics

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	<b>0.7</b>	<b>0.8</b>	<b>1</b>
Alignment of floors not within 20% of H	<b>0.4</b>	<b>0.7</b>	<b>0.8</b>

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

**3.6. Other factors, Factor F**

For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum    
 Rationale for choice of F factor, if not 1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any:  Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

**3.7. Overall Performance Achievement ratio (PAR)**

**4.3 PAR x (%NBS)<sub>b</sub>:**

PAR x Baseline %NBS:

**4.4 Percentage New Building Standard (%NBS), (before)**

**GHD**

Level 11, Guardian Trust House  
15 Willeston street, Wellington 6011  
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

© GHD Limited 2012

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

**Document Status**

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	C. Wells	R. Ramilo		S. Lee		18/09/12