



Christchurch City Council

Reg Stillwell Place PRO 1320

**Detailed Engineering Evaluation
Quantitative Assessment Report**



Christchurch City Council

Reg Stillwell Place

Quantitative Assessment Report

189 Palmers Road, New Brighton

Prepared By Kenneth T. Tam
Structural Engineer, SE CA 4559


Opus International Consultants Ltd
Christchurch Office
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail
Centre, Christchurch 8140
New Zealand

Original
Version
Reviewed By Alistair Boyce
Senior Structural Engineer

Telephone: +64 3 363 5400

Facsimile: +64 3 365 7858

Date: October 2013
Reference: 6-QUCCC.84
Status: Final V4

Current
Version
Approved By 
Mary Ann Halliday
Senior Structural Engineer

Summary

Reg Stilwell Place
PRO 1320-001 to PRO 1320-008

Detailed Engineering Evaluation
Quantitative Report - SUMMARY
Final – Version Four

189 Palmers Road, New Brighton, Christchurch

Background

This is a summary of the quantitative report for the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections, and available drawings.

This report has been altered and reissued for the following reasons;

1. Drawings for the resident's lounge and garages were requested from Christchurch City Council and did not become available until after the release of the first version of this document.
2. Blocks C, D and E were initially classed as being identical, however further investigation has determined blocks D and E have significantly more capacity than block C due to existing damage and plan irregularity.
3. A non-intrusive method was devised and used by Opus International Consultants to check GIB nail spacing in the units. This allowed engineers to confirm the use of an increased level of ductility and strength in the analysis of these units.
4. Drawings were found that showed that unit 24 was strengthened in 2009 with Braceline GIB board.

Key Damage Observed

All block had cracking to plasterboard linings. Other damage observed includes:

General

- a. Liquefaction induced differential movement is evident at the site surrounding the buildings.

Block A

- b. Severe cracking of exterior concrete block veneer. Damage is most severe outside of unit 5. Noticeable settlement and rotation of the building. Cracking of the sides of concrete ground beam.

Block B

- c. Severe cracking of exterior concrete block veneer. Damage is most severe outside of units 11 and 12. Some veneer block is out of plumb. Horizontal cracking of exterior block work propagates through interior gib lining. Noticeable settlement and rotation of the building. Cracking of perimeter ground beam.

Block C

- d. Severe cracking of exterior concrete block veneer. Damage is most severe at the connection between the 2 halves of the building. Lateral separation between units 18 and 19. Gap at ground floor slab between units 18 and 19 indicative of ground movement. Longitudinal cracking along concrete footing to units 19 and 20.

Block F

- e. Moderate cracking at exterior block veneer. Moderate cracking at interior lining.

Resident's Lounge

- f. Minor to moderate cracking at exterior block veneer.

Critical Structural Weaknesses**Blocks A and B**

- a) Torsion: Ground floor concrete block wall between kitchen and bathroom is not connected to the first floor slab. As a result, the only lateral load resistance in the east-west direction comes from the wall piers along the south elevation resulting in a torsional response.
- b) Pounding and separation between single-storey and two-storey portions: The two-storey portion and the single-storey portion are not structurally tied for lateral loading because the roof of the one-storey building does not align with the first floor of the two-storey building. As a result, they behave as separate structures and pounding can occur at the interface. Additionally, the roof of the single-storey structure relies on the two-storey building for gravity load support. Thus differential lateral movement from earthquake shaking could potentially lead to local loss of gravity support of the roof of the single storey portion.

Block C

- a) Pounding and separation between eastern and western halves: There is a lateral offset at the midpoint of Block C. The roof diaphragm is not aligned at this offset thus the eastern half and the western half of the building behaves as two separate structures for seismic loading. Pounding can occur at the interface. Additionally, the roof structure of the two halves relies on the common wall for gravity support. Thus differential lateral movement from earthquake shaking of the two halves could potentially lead to local loss of gravity support.

Block F

- a) Torsion: Ground floor concrete block wall between kitchen and bathroom is not connected to the first floor slab. As a result, the only lateral load resistance in the east-west direction comes from the wall piers along the south elevation resulting in a torsional response.

Indicative Building Strength (from quantitative assessment)

Based on the information available, and from undertaking a quantitative assessment, the indicative building strength is summarized in the table below:

Block	Indicative building strength	Comment
Blocks A and B	10% NBS	The buildings are considered earthquake prone
Blocks C and F	10 to 15% NBS	The buildings are considered earthquake prone

Block D	58% NBS	The building is considered to be moderate earthquake risk
Block E	68%NBS	The building is considered to be low earthquake risk
Resident's Lounge	46% NBS	The building is considered to be low to moderate earthquake risk
Garage (Block H)	65% NBS	The building is considered to be low or moderate earthquake risk.

Recommendations

- a) Develop a strengthening works scheme to increase the seismic capacity of Blocks A through D, Block F and the residents lounge to at least 67%NBS; this will need to consider compliance with accessibility and fire requirements.
- b) A quantity surveyor is engaged to determine the costs for strengthening the building.
- c) It is recommended that Blocks D, E, H (Garage) and the Resident's Lounge can be occupied, given their low to moderate risk.
- d) Due to potential falling hazard of the exterior block veneer, barricades are recommended or veneer be braced to protect pedestrians from falling hazards.

Contents

1	Introduction.....	1
2	Compliance	1
3	Earthquake Resistance Standards.....	4
4	Background Information.....	1
5	Survey	4
6	General Observations.....	5
7	Detailed Seismic Assessment	6
8	Summary of Geotechnical Appraisal	15
9	Remedial Options.....	18
10	Conclusions.....	18
11	Recommendations	20
12	Limitations.....	20
13	References	20

Appendix 1 – Photographs

Appendix 2 – Quantitative Assessment Methodology and Assumptions

Appendix 3 – Geotechnical Appraisal

Appendix 4 – Drawings

Appendix 5 – CERA DEE Data Sheets

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council (CCC) to undertake a detailed seismic assessment of the Reg Stilwell Place, located at 189 Palmers Road, New Brighton, Christchurch following the M6.3 Christchurch earthquake on 22 February 2011.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011.

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or

5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.

- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the DBH guidance document dated 12 June 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

4 Background Information

4.1 Building Description

The Reg Stilwell Place Residential Housing Units are situated approximately 7km north east of Christchurch City at 189 Palmers Road, New Brighton. The housing development was constructed in the 1970's and comprises 34 units of single and double storey configuration. The units are arranged into six blocks (Block A through F). There is also a single storey residents lounge and a single storey garage (Block H). Refer to the site plan in Figure 2 below.




Figure 2: Site Plan (Source: Google Maps)

4.2 Residential Units (Blocks A through F)

The construction of the residential units (Block A through F) is similar with minor variation in terms of number of stories and units. Block A is double-storey at western half and single-storey at the eastern half and consists of 6 units. Block B consists of a single storey central portion sandwiched between two double storey portions and consists of 10 units. Block C is a single storey building with four units. Blocks D and E are identical single-storey buildings with three units each. Block F consists of two double-storey halves with total of 8 units.

All units within single-storey blocks (or single-storey portions of a block) have identical plans. All double-storey blocks (or double-storey portion of a block) have identical plans.

The roof framing of building Blocks A – E consist of 10mm thick plywood sarking on 50mm by 100mm timber purlins which are supported by gang nailed timber trusses. The trusses are supported by timber load bearing walls. For the two-storey buildings, the 1st floor slab consists of 100mm thick precast concrete rib slab with 64mm thick concrete topping. The

topping is reinforced with 665 steel mesh. The 1st floor slab is supported by concrete masonry block walls.

The ground floors of all buildings consist of 100mm thick concrete slab on grade. The foundations typically consist of 700mm deep reinforced concrete ground beams under bearing walls and shear walls.

The exterior walls of all the buildings are cavity walls consisting of a 100 mm thick concrete block veneer. The veneer is backed by timber framed walls at the ground floor of single-storey buildings and 1st floor of 2-storey buildings. Whereas the backing for the veneer at ground floor of 2-storey buildings consists of partially filled concrete block walls.

There is no explicitly detailed roof diaphragm. The 10mm plywood sarking and 10mm gib board ceiling provides some diaphragm action to distribute the loads to the vertical lateral load resisting system. The 1st floor diaphragms for two-storey buildings consist of the concrete-topped precast concrete rib slab.

The lateral load resisting system for the single-storey buildings and the 1st floor of 2-storey buildings consist of a combination of concrete block walls and timber walls sheathed with 10mm “gib foil”. The lateral load resisting system at the ground floor of two-storey buildings consists primarily of concrete block walls. The block walls are either 150mm or 200mm thick and are typically reinforced with 12.7mm diameter vertical bars at 800mm centres. The drawings do not show any horizontal reinforcements except below window openings. The cells of the block walls are typically filled only where reinforcement steel is present, except that the walls between units are fully filled. Concrete bond beams occur at the floor and roof levels of the block walls.

The E-W lateral load resisting system for the single-storey buildings Blocks D & E consists primarily of the concrete block party walls. The block walls are 200mm thick and are typically reinforced with 12.7mm diameter vertical bars at 600mm centres. The drawings only show any horizontal reinforcements in the bond beam at the top of the party wall. The cells of the block walls are only filled only where reinforcement steel is present, at 600mm centres. Concrete bond beams occur at the roof levels of the party block walls.

4.3 Resident's Lounge

The Resident's Lounge is a single storey building. The roof framing consists of timber rafters and beams supported on timber bearing walls. The walls are lined with Gib board with braces within the wall and some plywood panels. The exterior walls are similar to the residential units and are 90mm concrete block veneer.

4.4 Garage (Block H)

The garage (Block H) is a single storey concrete block wall structure that consists of six identical spaces separated by interior concrete block walls. The roof consists of timber purlins supported on the block walls. The lateral system consists of a long concrete block wall along the back of the garages, in between each garage, and 590mm wide concrete block piers between each garage roll-up door along the front elevation. Based on cover metre survey, the block walls are reinforced with 16mm diameter vertical bars at 600mm centres and 16mm horizontal bars at 1200mm centres.

A summary of the buildings within the site is provided in Table 2 below:

Table 2: Summary of Buildings

Block	# of Stories	# of Units	Approx. overall dim.	Plan area	Notes
Block A	1 and 2	Ground floor: 4; 1 st floor: 2	6.9m by 25.4m	100 m ²	The eastern portion of Block A is single storey and is identical to central portion of Block B. The western portion of building A is two-storey and is identical to east and west portions of Block B.
Block B	1 and 2	Ground floor: 6; 1 st floor: 4	6.9m by 39m	269 m ²	The eastern portion of Block A is single storey and is identical to central portion of Block B. The western portion of building A is two-storey and is identical to east and west portions of Block B.
Block C	1	Ground floor: 4	6.7m by 23.4m	157 m ²	Layout of each individual units are same as Block D and E
Block D	1	Ground floor: 3	6.7m by 17.6m	118 m ²	Blocks D is similar to E
Block E	1	Ground floor: 3	6.7m by 17.6m	118 m ²	Block E similar to D but unit 24 was rebuilt in 2009 due to fire damage
Block F	2	Ground floor: 4; 1 st floor: 4	6.9m by 28m	193 m ²	
Residents Lounge	1	NA	10m by 11.1m	111 m ²	
Garage (Block H)	1	NA	6m by 20m	120 m ²	

5 Survey

5.1 Post 22 February 2011 Rapid Assessment

Opus International Consultants completed a Level 1 (external) Building Safety Evaluation on behalf of Civil Defence on 3 February 2011.

Opus International Consultants undertook a Level 2 (internal) inspection on 23 December 2011 on behalf of the Christchurch City Council.

We recommended barricades to be set up or veneer be braced to protect pedestrians from falling hazards.

5.2 Further Inspections

Additional site visits were undertaken by Opus International Consultants on 17 April 2012 and 30 April 2012.

Inspections included field measurements to determine existing construction of the residents lounge and garages.

Floor level surveys were performed on the ground floor and 1st floors of Blocks A, B and F. Additionally floor level survey was performed on the ground floor of Block C. The result of the survey is summarized in the geotechnical report included in Appendix 2. Verticality survey was performed at Blocks A, B and F. The results of the survey are included in Appendix 4.

5.3 Original Documentation

Copies of the following drawings were provided by CCC:

- June 1973 stamped consent drawings: Architectural drawings sheet 1 through 18
- 7 June 1973 stamped consent drawings: Structural sheet 1 through 4
- 8 April 1992 new resident's lounge drawings sheet 1 through 3
- March 2009 full drawings and bracing schedule was available for unit 24 which was rebuilt due to fire damage

Please note that we were NOT able to locate structural drawings for Block H (garage). Field investigation was performed to document the existing construction.

The drawings have been used to confirm the structural systems, investigate potential critical structural weaknesses (CSW's) and identify details which required particular attention.

No calculations were available for review.

6 General Observations

The buildings at Reg Stilwell Place have sustained moderate damage to structural elements, as well as some moderate to severe damage to non-structural elements. Following a review of the structural drawings and site investigations, the observed damage is generally consistent with the expected building performance, although some of the buildings have performed better than expected.

Key damage observed to structural and non-structural elements includes:

General

Liquefaction induced differential movement is evident at the site surrounding the buildings.

Block A

- a) Severe cracking of exterior concrete block veneer. Damage is most severe outside of unit 5.
- b) Cracking of interior lining.
- c) Noticeable settlement and rotation of the building.
- d) Cracking of the sides of concrete ground beam.

Block B

- a) Severe cracking of exterior concrete block veneer. Damage is most severe outside of units 11 and 12.
- b) Some veneer block is out of plumb.
- c) Minor cracking of interior lining.
- d) Horizontal cracking of exterior block work propagates through interior gib lining.
- e) Noticeable settlement and rotation of the building.
- f) Cracking of perimeter ground beam.

Block C

- a) Severe cracking of exterior concrete block veneer. Damage is most severe at the connection between the 2 halves of the building.
- b) Lateral separation between units 18 and 19.
- c) Gap at ground floor slab between units 18 and 19 indicative of ground movement
- d) Longitudinal cracking along concrete footing to Units 19 and 20.

Block D

- a) Minor cracking at interior lining.
- b) Visible ground movement and settlement.

Block E

- a) Minor cracking at interior lining.
- b) Visible ground movement and settlement.

Block F

- a) Moderate cracking at exterior block veneer
- b) Moderate cracking at interior lining.

Residents Lounge

- a) Minor to moderate cracking at exterior block veneer.

Garage (Block H)

- a) No damage was observed.

7 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” issued on 21 December 2011.

An initial qualitative assessment as outlined in the DEEP guidelines was not undertaken on this building prior to completing a detailed quantitative analysis. Identification of load paths, critical structural weaknesses and collapse hazards has been completed as part of the detailed quantitative analysis.

7.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building. The following potential CSW's have been identified for the building and have been considered in the analysis.

Blocks A and B

- a) Torsion: Ground floor concrete block wall between kitchen and bathroom is not connected to the first floor slab. As a result, the main lateral load resistance in the east-west direction comes from the wall piers along the south elevation resulting in a torsional response.
- b) Pounding and separation between single-storey and two-storey portions: The two-storey portion and the single-storey portion are not structurally tied together for lateral loading because the roof of the one-storey portion is not aligned with the first floor of the two-storey building.. As a result, they behave as separate structures and pounding can occur at the interface. Additionally, the roof of the single-storey structure relies on the wall at the interface for gravity load support. Thus differential lateral movement from earthquake shaking could potentially lead to local loss of gravity support of the roof of the single storey portion.

Block C

- a) Pounding and separation between eastern and western halves: There is a plan offset between the eastern and western halves of Block C. The roof diaphragm is not aligned at this offset thus the eastern half and the western half of the building behaves as two separate structures for seismic loading. Pounding can occur at the interface. Additionally, the roof structure of the two halves relies on the common wall for gravity support. Thus differential lateral movement from earthquake shaking of the two halves could potentially lead to local loss of gravity support.

Block F

- c) Torsion: Ground floor concrete block wall between kitchen and bathroom is not connected to the first floor slab. As a result, the only lateral load resistance in the east-west direction comes from the wall piers along the south elevation resulting in a torsional response.

7.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix 3 of the report due to the technical nature of the content. A brief summary follows:

- A 3D model of the 2-storey buildings (2-storey portion of Blocks A, B and F) was created in ETABS, which is a finite element structural analysis programme.
- The single-storey buildings were checked by hand calculations.
- An equivalent static force analysis was carried out using the spectral values established from NZS1170.5, with an updated Z factor of 0.3 (B1/VM1). This analysis was used to establish the actions on the structural elements.
- The building was assessed as Importance Level 2.
- Based on the actions determined from the analysis, demand to capacity ratios (DCR's) were determined for each component in question. The highest DCR was then converted to a %NBS for the structure.

7.3 Limitations and Assumptions in Results

Our analysis and assessment is based on an assessment of the building in its undamaged state. Therefore the current capacity of the building may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on drawings and site inspections
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element.

7.4 Quantitative Assessment

A summary of the structural performance of the building is shown in the tables below. Note that the values given represent the critical elements in the building, as these effectively define the building's capacity. As noted in Appendix A2.2 (Analysis Parameters), the building was analysed using a ductility factor (μ) equal to 1.25 due to partially reinforced block walls and timber walls that relies on gib sheathing to resist lateral load.

Modes of failure that do not govern the building's performance are not included in the table except as noted for cases where higher ductility factors have led to the component being classified as non-critical.

Table 3: Summary of Seismic Performance for Block A and B – $\mu = 1.25$ (unless noted otherwise)

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Primary Components at 2-story portion (those that are required parts of the lateral resisting system)			
1 st floor concrete block walls in north-south direction	Concrete block wall is adequate to resist code level forces in north-south direction loading	No	100%
1 st floor timber walls (sheathed with gib foil) in north-south direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	Yes	10% - 20%
1 st floor timber walls (sheathed with gib foil) in east-west direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	Yes	< 10%

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Ground floor concrete block wall in the north-south direction	Concrete block wall is adequate to resist code level forces in north-south direction loading	No	100%
Ground floor concrete block wall in the east-west direction	Concrete block wall pier along south elevation is not capable to resist code level forces. Failure mode is in flexure.	Yes	25%
Topping slab at 1 st floor (diaphragm)	Diaphragm is consists of 64mm thick concrete topping reinforced with 665 mesh. Maximum diaphragm shear occurs along the southern edge of the diaphragm where the concrete block wall along the south elevation provide majority of lateral load resistance for east west direction seismic load.	No	40%
Primary Components at 1-story portion (those that are required parts of the lateral resisting system)			
Concrete block wall in single-storey portion along north-south direction	Concrete block walls are adequate to resist code level forces	No	100%
Ground floor timber walls in single-storey portion in north-south direction	Timber walls sheathing with 10mm gib foil fails in shear.	No	40%
Ground floor timber walls in single-storey portion in east-west direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	Yes	10 - 15%
Ceiling diaphragm of single story portion	10mm gib ceiling diaphragm does not have shear capacity to act as diaphragm to resist code lateral forces	No	40 - 50%
Secondary Components (those that are not required parts of the lateral load resisting system but which must be able to maintain their gravity load capacity while the building under goes deformation due to earthquake loading)			
Interface between 2-storey and 1-storey portions	The two-storey portion and the single-storey portion are not structurally tied for lateral loading because the roof of the one-storey building does not align with the first floor of the two-storey building.. As a result, they behave as separate structures and pounding can occur at the interface. Additionally, the roof of the single-storey structure relies on the two-storey building for gravity load support. Thus differential lateral movement from earthquake shaking could potentially lead to local loss of gravity support of the roof of the single storey portion.	Yes; potential local loss of gravity support	NA
Staircase	Stair case is in-situ concrete that is dowelled into 1 st floor topping and slab intermediate landing. The staircase occurs between two relatively long concrete block walls. The inter-storey drift is expected to be low and the stair is expected to behave adequately	No	NA

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Out-of-plane support of ground floor block wall between kitchen and bathroom	Top of block wall is not connected to concrete slab above. Out of plane loading is resisted by block wall cantilever from foundation.	No	40 - 50%
Exterior block veneer	Connection between exterior block veneer and back-up wall is unknown. Whether the block veneer is reinforced is unknown. Based on observations from the field, the amount of damage to the veneer indicates that they are likely not reinforced and poorly tied to the back-up wall. Potential falling hazard exists.	Yes	NA

Table 4: Summary of Seismic Performance for Block C – $\mu = 1.25$ (unless noted otherwise)

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Primary Components (those that are required parts of the lateral resisting system)			
Concrete block wall in single-storey portion along north-south direction	Concrete block walls are adequate to resist code level forces	No	100%
Ground floor timber walls in single-storey portion along the north-south direction	Timber walls sheathing with 10mm gib foil fails in shear.	No	40%
Ground floor timber walls in single-storey portion along the east-west direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	Yes	10 - 15%
Ceiling diaphragm of single story portion	10mm gib ceiling diaphragm does not have shear capacity to act as diaphragm to resist code lateral forces	No	40 - 50%
Secondary Components (those that are not required parts of the lateral load resisting system but which must be able to maintain their gravity load capacity while the building under goes deformation due to earthquake loading)			

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Interface between eastern and western halves	There is a plan offset at the midpoint of Block C. The roof diaphragm is not aligned at this offset thus the eastern half and the western half of the building behaves as two separate structures for seismic loading. Separation and pounding can occur at the interface. This is evident from the damage to the exterior veneer adjacent to this interface. Additionally, the roof structure of the two halves relies on the common wall for gravity support. Thus differential lateral movement from earthquake shaking of the two halves could potentially lead to local loss of gravity support.	Yes; potential local loss of gravity support	NA
Exterior block veneer	Connection between exterior block veneer and back-up wall is unknown. Whether the block veneer is reinforced is unknown. Based on observations from the field, the amount of damage to the veneer indicates that they are likely not reinforced and poorly tied to the back-up wall. Potential falling hazard exists.	Yes	NA

Table 5: Summary of Seismic Performance for Block D – $\mu = 1.25$ (unless noted otherwise)

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Primary Components (those that are required parts of the lateral resisting system)			
Concrete block along east west direction	Concrete block walls are adequate to resist code level forces	No	100%
Along the north-south direction	Timber walls sheathing with 10mm gib foil fails in shear.	No	58%
Along the east-west direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	No	58%
Secondary Components (those that are not required parts of the lateral load resisting system but which must be able to maintain their gravity load capacity while the building under goes deformation due to earthquake loading)			
Exterior block veneer	Connection between exterior block veneer and back-up wall is unknown. Whether the block veneer is reinforced is unknown. Based on observations from the field, the amount of damage to the veneer indicates that they are likely not reinforced and poorly tied to the back-up wall. Potential falling hazard exists.	Yes	NA

Table 6: Summary of Seismic Performance for Block E – $\mu = 1.25$ (unless noted otherwise)

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Primary Components (those that are required parts of the lateral resisting system)			
Concrete block along east west direction	Concrete block walls are adequate to resist code level forces	No	100%
Along the north-south direction	Timber walls sheathing with 10mm gib foil fails in shear.	No	68%
Along the east-west direction	Timber walls sheathing with 10mm gib foil and Braceline	No	100%
Secondary Components (those that are not required parts of the lateral load resisting system but which must be able to maintain their gravity load capacity while the building under goes deformation due to earthquake loading)			
Exterior block veneer	Connection between exterior block veneer and back-up wall is unknown. Whether the block veneer is reinforced is unknown. Based on observations from the field, the amount of damage to the veneer indicates that they are likely not reinforced and poorly tied to the back-up wall. Potential falling hazard exists.	Yes	NA

Table 7: Summary of Seismic Performance for Block F – $\mu = 1.25$ (unless noted otherwise)

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Primary Components (those that are required parts of the lateral resisting system)			
1 st floor concrete block walls in north-south direction	Concrete block wall is adequate to resist code level forces in north-south direction loading	No	100%
1 st floor timber walls (sheathed with gib foil) in north-south direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	Yes	10% - 20%
1 st floor timber walls (sheathed with gib foil) in east-west direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	Yes	< 10%
Ground floor concrete block wall in the north-south direction	Concrete block wall is adequate to resist code level forces in north-south direction loading	No	100%
Ground floor concrete block wall in the east-west direction	Concrete block wall pier along south elevation is not capable to resist code level forces. Failure mode is in flexure.	Yes	25%

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Topping slab at 1 st floor (diaphragm)	Diaphragm is consists of 64mm thick concrete topping reinforced with 665 mesh. Maximum diaphragm shear occurs along the southern edge of the diaphragm where the concrete block wall along the south elevation provide majority of lateral load resistance for east west direction seismic load.	No	40%
Secondary Components (those that are not required parts of the lateral load resisting system but which must be able to maintain their gravity load capacity while the building under goes deformation due to earthquake loading)			
Staircase	Stair case is in-situ concrete that is dowelled into 1 st floor topping and slab intermediate landing. The staircase occurs between two relatively long concrete block walls. The inter-storey drift is expected to be low and the stair is expected to behave adequately	No	NA
Out-of-plane support of ground floor block wall between kitchen and bathroom	Top of block wall is not connected to concrete slab above. Out of plane loading is resisted by block wall cantilever from foundation.	No	40 - 50%
Exterior block veneer	Connection between exterior block veneer and back-up wall is unknown. Whether the block veneer is reinforced is unknown. Based on observations from the field, the amount of damage to the veneer indicates that they are likely not reinforced and poorly tied to the back-up wall. Potential falling hazard exists.	Yes	NA

Table 8: Summary of Seismic Performance for Residents Lounge – $\mu = 1.25$ (unless noted otherwise)

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Primary Components (those that are required parts of the lateral resisting system)			
Timber walls (sheathed in gib foil) in the north-south direction	Timber walls sheathing with 10mm gib foil. Shear capacity is limited. Additionally, holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	No	70%
Timber walls (sheathed in gib foil) in the east west direction	Timber walls sheathing with 10mm gib foil. Holdowns are not present at end of walls thus their capacity to resist overturning is limited. Controlling mode of failure is overturning.	No	46%
Ceiling Diaphragm	Gib ceiling diaphragm does not have shear capacity to act as diaphragm to resist code lateral forces	No	50 - 60%

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Secondary Components (those that are not required parts of the lateral load resisting system but which must be able to maintain their gravity load capacity while the building under goes deformation due to earthquake loading)			
Exterior block veneer	Connection between exterior block veneer and back-up wall is unknown. Whether the block veneer is reinforced is unknown. Based on observations from the field, the amount of damage to the veneer indicates that they are likely not reinforced and poorly tied to the back-up wall. Potential falling hazard exists.	Yes	46%

Table 9: Summary of Seismic Performance for the Garage (Block H) – $\mu = 1.25$ (unless noted otherwise)

Structural Element/System	Failure mode or description of limiting criteria based on displacement capacity of critical element.	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Primary Components (those that are required parts of the lateral resisting system)			
Transverse block walls	Concrete block walls are adequate to resist code level forces. The stresses in the walls are low.	No	100%
Longitudinal block walls at back of garage	Concrete block walls are adequate to resist code level forces. The stresses in the wall are low.	No	100%
Block wall piers at the front of the garage	Flexural failure of block wall piers.	No	65%
Roof Diaphragm	The construction of the roof diaphragm is unknown. However, spans between block walls are relatively small, the diaphragm is expected to perform adequately	No	NA

7.5 Discussion

Based on our quantitative assessment, Blocks A, B, C and F have computed strength of less than 33% NBS. This is primarily due to limited overturning capacity of the gib-sheathed timber shear walls which do not have holddowns to resist overturning forces. The calculated overturning capacity of these walls are approximately 10-20% NBS for the residential units. Ground floor concrete block wall piers for block A, B, and F have capacities of approximately 25% NBS for east-west direction loading. There are also signs of separation and pounding for blocks A, B, and C where the interfaces between different portions of the buildings are not tied together. As highlighted in Tables 3 to 7 above, a number of other elements also have seismic capacities less than 33% NBS, and the buildings are therefore defined as being earthquake prone in accordance with the Building Act.

The lateral support for the exterior block veneers is unknown. Based on damage observed, the amount of damage to the block veneer indicates that they are likely not reinforced and poorly tied to the backup walls. Potential falling hazard exists thus barricades are recommended or veneer be braced to protect pedestrians from falling hazards.

The Garage (Block H) has a computed strength of 65%NBS and is considered to be low or moderate earthquake risk.

The single storey Blocks D, E, H (garage) and the residents lounge are considered safe to occupy, with capacities over 33% NBS.

8 Summary of Geotechnical Appraisal

8.1 General

Christchurch City Council commissioned Opus International Consultants to undertake a desktop study of the ground conditions beneath the buildings at Reg Stilwell Place. Geotechnical information herein is based on the findings of that study.

The buildings foundations are reinforced concrete perimeter strip footings founded 600mm to 900mm below the finished floor slab level. These foundations have settled differentially because of either densification of the underlying soil or liquefaction that has occurred at depth. A Site investigation was undertaken and a report written dated 7 March 2013. A summary of the main findings follow.

8.2 Liquefaction Potential

The ECan liquefaction study indicated the Reg Stilwell Place site possessed a high liquefaction ground damage potential during future seismic events. Post-earthquake aeriels and observations have confirmed that significant volumes of liquefied soils were ejected at the site during the 4 September 2010, 22 February 2011 and 13 June 2011 earthquake events.

Residential properties on the southern boundary have been zoned “Red”, indicating that the land is not practical to rebuild, repair or reoccupy, as the required improvements would be too difficult or costly to implement.

Observations of damage to the Reg Stilwell Residential Housing Units confirmed that liquefaction induced differential settlement has occurred at the site. The extent of settlement was quantified in a levels survey by OPUS which indicated between 40 and 120mm of differential settlement has occurred in the concrete floor slabs of the units in Blocks A, B, C & F.

Due to the proximity of the Avon River to Reg Stilwell Place and the height difference from floor level to river invert level, the site is considered to have lateral spreading potential. A detailed investigation and assessment of the lateral spreading potential for this site is recommended.

The buildings at the site are a similar structural form to a residential structure. Accordingly, recommendations in the Department of Building and Housing New Zealand guidance documents for repairing and rebuilding foundations in Technical Category 3 (DBH, 2012) are considered applicable for the buildings at this site. The guidance document indicates that for foundations comprising a reinforced concrete perimeter footing with a concrete floor slab which are out of level between 50mm to 150mm with cracks in the floor slab less than 3mm, a foundation re-level is required.

8.3 Summary

Reg Stillwell suffered moderate to major ground damage due to the recent seismic events. Surface evidence of liquefaction including sand boils and differential subsidence was observed around the site, with lateral spreading being observed south and west of the site towards the Avon River.

Differential settlement has caused significant damage to the majority of the structures at Reg Stillwell. All buildings are founded on concrete perimeter strip footings with slab on-grade floors that have not been tied together.

The foundations of the buildings at Reg Stillwell Residential Complex are not considered appropriate for this site based on the MBIE guidance document.

A liquefaction assessment predicts this building is likely to experience up to 200 mm of total free-field subsidence in a future ULS seismic event, where the expected differential settlements of approximately 100 to 150 mm can be expected in a ULS event and up to 70 mm in a SLS event.

Lateral spreading analysis suggests that there may be up to 300 mm of horizontal deformation towards the Avon River in a ULS event and up to 100 mm of lateral stretch of buildings, although this level of lateral spreading did not occur in the recent seismic events.

The expected future ground performance of Reg Stillwell is likely to perform similar to MBIE TC3, with moderate land deformations possible in a future small to medium sized (SLS) earthquake, and significant land deformations in a future moderate to large (ULS) earthquake.

A number of remedial options have been outlined based on whether the buildings are to remain or be rebuilt. Options include; re-levelling the existing foundations or rebuilding on enhanced foundations with consideration of lateral spreading potential and mitigation. Replacement of the concrete floor slabs is likely, following a re-level of the buildings.

Further site investigations and engineering evaluation would be required in the detailed design phase to determine the most appropriate liquefaction mitigation and foundation options, and the cost associated with these options.

The floor levels of some of the blocks are below the recommended interim floor level by the CCC but are above the 200 year Flood Level. This would need to be considered in the future remediation and utilization of this site.

8.4 Geotechnical Recommendations

For the Reg Stillwell site it is recommended that:

- a) The selection of the most appropriate foundation option should consider the risks and long term exposure of this site to liquefaction induced subsidence and lateral spreading risk outlined in this assessment, comparing this with expected performance criteria.
- b) Shallow re-levelling and repairing remedial schemes (Option L1) is not considered acceptable in a ULS seismic event without considering lateral spread remediation.

- c) Underpinning the existing structure (Option L2) with piles or compacting grouting could provide an adequate low to moderate risk solution but may not be cost effective.
- d) If replacement of the building on site is being considered, then low risk options including deep piled foundations or ground improvement (Options R1 and R2) and if possible location of the buildings in the north side of the site. This should provide a low risk/resilient structure but is likely to be relatively expensive.
- e) Alternatively CCC could consider easily re-levellable foundation on a stabilised crust (Option R4).
- f) In the long term, CCC should consider whether rebuilding on an alternative site may be more effective.
- g) Allowance for significantly enhanced foundations and potentially lateral spreading mitigation should be made for any buildings that may be constructed on this site.
- h) Further site investigation and specific analysis of the foundations would be required in the detailed design phase.
- i) The final floor level of the re-levelled or re-built structure with respect to flood levels will need to be agreed with the CCC building consent team during the detailed design phase.

9 Remedial Options

The buildings requires repair and strengthening, with a target of increasing the seismic performance to as near as practicable to 100%NBS, and at least 67%NBS. A possible strengthening scheme to achieve this would include:

- Replace and/or strengthen gib sheathing at selected timber walls (applicable to Blocks A through F and residents lounge).
- Install hold-down anchors and strengthen timber members at ends of plywood shear walls. (Applicable to Blocks A through F and residents lounge).
- Install veneer ties to all exterior block veneers. (Applicable to Blocks A through F and residents lounge).
- Connect ground floor concrete block walls between kitchen and bathroom to 1st floor concrete slab above. (Applicable to Blocks A, B and F)
- Install secondary bearing wall to support roof framing along interface between single-storey and two-storey portions of Block A and B. Similarly, install secondary bearing wall to support roof framing along plan offset between eastern and western halves of Block C.
- Remove and replace selected block walls in east-west direction at ground level of Blocks A, B, and F with fully filled block walls with horizontal reinforcement or equivalent alternative.
- If the site is assessed to be the equivalent to the Department of Building and Housing New Zealand Technical Category 3 (DBH, 2011), then in accordance with the interim guidance document (DBH, 2012), a foundation re-level is recommended for the units at Reg Stilwell Place. However, more damage to the existing concrete slab foundations is likely in a future seismic event. Rebuilding with enhanced foundations (e.g. ribraft or piles) is considered more likely to be reinsurable and achieve building consent compliance.

10 Conclusions

Based on our quantitative assessment, Blocks A, B, C and F are considered earthquake prone. This is primarily due to the gib-sheathed timber shear walls having capacities of less than 33%NBS. Ground floor concrete block wall piers for block A, B, and F also have capacities less than 33%NBS for east-west direction loading. The single storey Blocks D and E, and the residents lounge are consider to be low or moderate earthquake risk, with capacities over 33% NBS. The Garage (Block H) has a computed strength of 65%NBS and is consider to be low or moderate earthquake risk. Factors limiting the %NBS of the buildings are summarized below:

- a. The seismic performance of the primary components (those that are required parts of the lateral resisting system) are governed by:
 - The lateral system for single-storey buildings consist primarily of timber walls sheathed with 10mm gib foil. No hold-downs were provided at the end of the shear walls to resist overturning. The walls in the north-south direction of block D and E have computed strength of 58% NBS. The walls in the east-west direction of block C also have computed

strength of 10 to 15% NBS. The walls in the east-west direction of the residents lounge have computed strength over 46% NBS.

- Similar to item “a” above, the lateral system for first floor of the two-storey buildings (Block A, B, and F) consists primarily of timber walls sheathed with 10mm gib foil. No hold-downs were provided at the end of the shear walls to resist overturning. The walls in the north-south direction have a computed strength of 10 to 20% NBS and the walls in the east-west direction have a computed strength of less than 10% NBS.
- The ground floor concrete block walls along the south elevations of Blocks A, B, and F are partially filled with no shear reinforcement and minimal reinforcement for flexure. These walls have computed strength of approximately 25% NBS.

b. The seismic performance of the secondary components (those that are not required parts of the lateral load resisting system but which must be able to maintain their gravity load capacity while the building undergoes deformation due to earthquake loading) are governed by:

- Exterior block veneer: connection between exterior block veneer and back-up wall is unknown. Whether the block veneer is reinforced is unknown. Based on observations from the field, the amount of damage to the veneer indicates that they are likely not reinforced and poorly tied to the back-up wall. Potential falling hazard exists.
- The two-storey portion and the single-storey portion of Blocks A and B are not tied together. The roof of the one-storey building does not align with the first floor of the two-storey building. As a result, they behave as separate structures and pounding can occur at the interface. Additionally, the roof of the single-storey structure relies on the two-storey building for gravity load support. Thus differential lateral movement from earthquake shaking could potentially lead to local loss of gravity support of the roof of the single storey portion.
- Similar to item “b” above, there is a lateral offset between the western and eastern halves of Block C. The roof diaphragm is not aligned at this offset thus the two halves behave as two separate structures for seismic loading. Pounding can occur at the interface. Additionally, the roof structure of the two halves relies on the common wall for gravity support. Thus differential lateral movement from earthquake shaking of the two halves could potentially lead to local loss of gravity support.

The buildings have a seismic capacity less than 34% NBS and are therefore defined as being earthquake prone in accordance with the Building Act. It is recommended that the buildings not be occupied given their earthquake prone building status.

The lateral support for the exterior block veneers is unknown. Based on damage observed, the amount of damage to the block veneer indicates that they are likely not reinforced and poorly tied to the backup walls. Potential falling hazard exists thus barricades are recommended or veneer be braced to protect pedestrians from falling hazards.

The ECan liquefaction study indicated the Reg Stilwell Place site possessed a high liquefaction ground damage potential during future seismic events. If the existing shallow foundations are retained, it is likely that in a future Serviceability Limit State (SLS) and Ultimate Limit State (ULS) earthquake, liquefaction induced settlement similar to that which has occurred at the site is likely. Additionally, due to the proximity of the Avon River to Reg Stilwell Place and the height difference from floor level to river invert level, the site is considered to have lateral spreading potential.

11 Recommendations

- a) Develop a strengthening works scheme to increase the seismic capacity of the Blocks A through D, Block F and the residents lounge to at least 67%NBS; this will need to consider compliance with accessibility and fire requirements.
- b) A quantity surveyor is engaged to determine the costs for strengthening the building.
- c) It is recommended that Blocks D, E, H (garage) and the Resident's Lounge can be occupied, given their low to moderate risk.
- d) Due to potential falling hazard of the exterior block veneer, barricades are recommended or veneer be braced to protect pedestrians from falling hazards.



12 Limitations



- a) This report is based on an inspection of the structure of the buildings and focuses on the structural damage resulting from the 4 September 2010 Darfield Earthquake and the 22 February 2011 Canterbury Earthquake and aftershocks. Some non-structural damage is described but this is not intended to be a complete list of damage to non-structural items.
- b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- c) We were not able to locate structural drawings for the third floor addition thus we assumed the construction is similar to the original construction.
- d) This report is prepared for CCC to assist with assessing the remedial works required for council buildings and facilities. It is not intended for any other party or purpose.



13 References



- [1] NZS 1170.5: 2004, *Structural design actions, Part 5 Earthquake actions*, Standards New Zealand.
- [2] NZSEE: 2006, *Assessment and improvement of the structural performance of buildings in earthquakes*, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC, *Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes*, Structural Engineering Society of New Zealand, 21 December 2011.



Appendix 1 – Photographs



Reg Stilwell Place – 189 Palmers Road		
No.	Item description	Photo
<u>Block A</u>		
1.	North elevation of Block A showing the two-storey portion	 <p>A photograph of the north elevation of Block A, a two-storey residential building. The building features a light-colored facade on the ground floor and a darker, possibly metal-clad, upper floor. A prominent balcony with a dark metal railing runs across the upper floor. The ground floor has large windows and a central entrance. The building is surrounded by some landscaping, including bushes and a paved area in the foreground.</p>
2.	South elevation of Block A. Note the ejecta due to liquefaction at the pavement	 <p>A photograph of the south elevation of Block A, showing a side view of the building. The building is a two-storey structure with a light-colored facade. The ground floor has several windows, and the upper floor is visible. The building is situated next to a paved road. There is a significant amount of ejecta (loose soil and debris) visible on the pavement, indicating liquefaction. A green fence is visible in the foreground on the left.</p>



3.	Crack in gib board wall at unit 3	
4.	Separation between the 2-storey portion and the 1-storey portion	



5.	Severe cracking in block veneer outside of Unit 5	
6.	Vertical crack at sides of concrete ground beam	



Block B		
7.	North elevation of 2-storey portion of Block B. Identical to Block A	
8.	Temporary bracing for exterior block veneer at gables	



9.	Step cracking at veneer of single-storey portion. Veneer is leaning toward the interior of the unit	
10.	Vertical crack and out-of-plane offset in block veneer	



11.	15mm crack at veneer joints	
12.	Veneer leaning toward the interior of single story unit as evident in gap between soffit and face of veneer	



13.	Vertical crack of block veneer	
14.	Horizontal cracking in exterior blockwall propagates through into interior lining	



15.	Horizontal crack at top of lining	 A photograph showing a horizontal crack in a white concrete or plaster surface. The crack is located near the top of the wall, just below a wooden frame. A red arrow points to the crack, and the date '2/11' is written in red ink next to it.
16.	Vertical crack at sides of perimeter ground beam	 A photograph showing a vertical crack in a concrete wall. A hand is holding a ruler against the wall to measure the crack. The crack is located at the base of the wall, near the ground. The ground is covered with dry grass and soil.



Block C		
17.	South elevation of block C	
18.	Severe step cracking of block veneer at Unit 18	



19.	Cracking of interior lining at Unit 18	
20.	Gap at slab on grade along base of partial wall between Unit 18 and 19	

21.	Temporary bracing of exterior block veneer in front of Unit 19	 A photograph showing the exterior of a building unit. The wall is made of light-colored concrete blocks. A window is visible, and a door is to the right. Temporary wooden bracing is installed around the window and door area. A white caution tape is strung across the lower part of the wall.
22.	Separation between two halves of block C (between units 18 and 19)	 A close-up photograph of the exterior wall, showing a significant vertical crack and separation between two halves of a concrete block. The crack runs through the mortar joint and the block itself. A white caution tape is visible on the left side of the crack.



23.	Separation of block veneer around window at Unit 20	
24.	Horizontal offset of exterior block veneer at Unit 20	

Block D		
25.	Minor cracking of interior linings at Unit 21	
26.	Minor cracking of interior linings at Unit 22	

<u>Block E</u>		
27.	Gap between footing and soil	
<u>Block F</u>		
28.	North elevation of Block F (identical to 2-storey portions of Block A and B)	

29.	Step cracking at exterior block veneer ground floor pier	
30.	Cracking of interior lining	

31.	Cracking of interior lining	 A photograph of an interior wall corner. The wall is covered in a light-colored, possibly plastered, lining. There is a prominent vertical crack running down the wall, starting from the ceiling and extending towards the bottom. The crack is slightly wider at the top and tapers off. To the right, a portion of a window with dark green curtains is visible.
32.	Temporary bracing of exterior block veneer at gable	 A photograph of the exterior of a building, specifically a gable end. The wall is constructed of light-colored concrete blocks. Two vertical wooden posts are attached to the wall with metal brackets, providing temporary bracing. The posts run from the ground level up to the roofline. A window is visible on the upper part of the wall, and a small rectangular opening is visible on the lower part. The roof is visible at the top, and some trees are visible in the background.

Resident's Lounge		
33.	Front elevation of Residents Lounge	
34.	Step cracking at exterior block work	

35.		
Garage (Block H)		
36.		

37.		
-----	--	--

Appendix 2 – Quantitative Assessment Methodology and Assumptions

A3.1. Referenced Documents

- AS/NZS 1170.0:2002, *Structural design actions, Part 0: General principles*, Standards New Zealand.
- AS/NZS 1170.1:2002, *Structural design actions, Part 1: Permanent, imposed and other actions*, Standards New Zealand.
- NZS 1170.5:2004, *Structural design actions, Part 5: Earthquake actions – New Zealand*, Standards New Zealand.
- NZS 3101: Part 1: 2006, *Concrete Structures Standard, The Design of Concrete Structures*, Standards New Zealand.
- NZS 3101: Part 2: 2006, *Concrete Structures Standard, Commentary on the Design of Concrete Structures*, Standards New Zealand.
- NZBC, *Clause B1 Structure, Verification Method B1/VM1*, Department of Building and Housing.
- NZSEE: 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, New Zealand Society for Earthquake Engineering.
- Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- ASCE/SEI 41-06, *Seismic Rehabilitation of Existing Buildings*, Structural Engineering Institute of the American Society of Civil Engineers, 2007.

A3.2. Analysis Parameters

The following parameters are used for the seismic analysis:

- Site soil category
D (deep or soft soil) Cl. 3.1.3, NZS1170.5
- Seismic hazard factor
 $Z = 0.30$ Cl. 2.2.14B, B1/VM1
- Return period factor
 $R_u = 1.0$ (Importance Level 2 structure, 50 year design life) Table 3.5, NZS1170.5
- Ductility factor
 $\mu = 2.0$ for blocks D, E and Resident's Lounge
 $\mu = 1.25$ (nominally ductile) for all other blocks Cl. 2.6.1.2, NZS3101:2006
- Structural performance factor
 $S_p = 0.925$ Cl. 2.6.2.2, NZS3101:2006

- Material properties

Table A1: Analysis Material Properties

Masonry nominal compressive strength, f_m (MPa) ⁽¹⁾	10
Mild reinforcing nominal yield strength, f_y (MPa) ⁽²⁾	300
Timber wall sheathed with gib, fVn (kN/m)	2.1 per side

Notes:

- Based on guidance from NZSEE 2006, probable reinforcement yield strength is based on a value of 1.08 times the nominal yield strength (Cl. 7.1.1)

- Effective section properties

Table A2: Effective section properties from NZS3101:2006

Table C6.6 – Effective section properties, I_e

Type of member	Ultimate limit state		Serviceability limit state		
	$f_y = 300 \text{ MPa}$	$f_y = 500 \text{ MPa}$	$\mu = 1.25$	$\mu = 3$	$\mu = 6$
1 Beams					
(a) Rectangular [¶]	$0.40 I_g$ (use with E_{40}) [§]	$0.32 I_g$ (use with E_{40}) [§]	I_g	$0.7 I_g$	$0.40 I_g$ (use with E_{40}) [§]
(b) T and L beams [¶]	$0.35 I_g$ (use with E_{40}) [§]	$0.27 I_g$ (use with E_{40}) [§]	I_g	$0.6 I_g$	$0.35 I_g$ (use with E_{40}) [§]
2 Columns					
(a) $N^*/A_g f'_c > 0.5$	$0.80 I_g$ ($1.0 I_g$) [‡]	$0.80 I_g$ ($1.0 I_g$) [‡]	I_g	$1.0 I_g$	As for the ultimate limit state values in brackets
(b) $N^*/A_g f'_c = 0.2$	$0.55 I_g$ ($0.66 I_g$) [‡]	$0.50 I_g$ ($0.66 I_g$) [‡]	I_g	$0.8 I_g$	
(c) $N^*/A_g f'_c = 0.0$	$0.40 I_g$ ($0.45 I_g$) [‡]	$0.30 I_g$ ($0.35 I_g$) [‡]	I_g	$0.7 I_g$	
3 Walls [¶]					
(a) $N^*/A_g f'_c = 0.2$	$0.48 I_g$	$0.42 I_g$	I_g	$0.7 I_g$	As for the ultimate limit state values
(b) $N^*/A_g f'_c = 0.1$	$0.40 I_g$	$0.33 I_g$	I_g	$0.6 I_g$	
(c) $N^*/A_g f'_c = 0.0$	$0.32 I_g$	$0.25 I_g$	I_g	$0.5 I_g$	
4 Diagonally reinforced coupling beams	$0.6 I_g$ for flexure Shear area, A_{shear} , as in text		I_g $1.5 A_{\text{shear}}$ for ULS	$0.75 I_g$ $1.25 A_{\text{shear}}$ for ULS	As for ultimate limit state
NOTES – (§) With these values the E value should be the elastic modulus for concrete with a strength of 40 MPa regardless of the actual concrete strength. (‡) The values in brackets apply to columns which have a high level of protection against plastic hinge formation in the ultimate limit state. (¶) For additional flexibility, within joint zones and for conventionally reinforced coupling beams refer to the text.					

- Earthquake load combination

$$G + E_u + \Psi_E Q$$

Cl. 4.2.2, AS/NZS1170.0

- Floor live loading

$$Q = 1.5 \text{ kPa} - \text{General Areas}$$

Table 3.1 Part G, AS/NZS1170.1

- Earthquake combination factor

$$\Psi_E = 0.3$$

Table 4.1, AS/NZS1170.0

- Building seismic weight

Cl. 4.2, NZS1170.5

$$W_t = G + \Psi_E Q$$

$$W_t = 944 \text{ kN}$$

A3.3. Assessment Methodology

Static Analysis

The seismic assessment was undertaken by completing static analysis for the building in accordance with NZS 1170.5:2004.

2-Story Buildings – Block A, B, and F

A 3D model was set up using the structural analysis program ETABS, and effective section properties for structural members were taken from Table A2 above. The floor diaphragms were modelled as flexible diaphragms.




Figure A1: ETABS model of the 2-storey building

The fundamental building periods is based on T used = 0.24 sec. This

The base shears resulting from the equivalent static method are:

- $V = 668 \text{ kN}$ (E/W and N/S direction)

The building was analysed as having limited ductility ($\mu = 1.25$) and the design actions were applied separately in each perpendicular direction, with 100% for the first axis plus 30% on the second

axis, and then 30% on the first axis and 100% on the second axis, as required by NZS1170.5, Clause 5.3.1.2.

Single-storey buildings, Blocks A, B, C, D, E, Residents lounge, and Garage (Block H)

The single storey buildings were analysed by hand calculations

Element Demand to Capacity

Element force demands were extracted from the MRS analysis and compared to calculated capacities based on the material properties assumed in Table A1. The results of these demand to capacity checks are summarized in further detail in the report and reported as %NBS.

Appendix 3 – Geotechnical Appraisal

29 May 2012

Michael Sheffield
Christchurch City Council
PO Box 2522
Addington
CHRISTCHURCH 8140



6-QUCCC.84/85SC REV 1

Dear Michael

Reg Stillwell Place - Geotechnical Desktop Study

1. Introduction

The Christchurch City Council (CCC) has requested OPUS International Consultants (OPUS) provide a geotechnical desktop study and walkover inspection of the Reg Stillwell Place Residential Housing Units following the Canterbury Earthquake Sequence initiated by the 4 September 2010 earthquake.

The purpose of the desktop study is to collate existing subsoil information to assess the current ground conditions, the potential geotechnical hazards that may be present at the site, and determine whether further subsurface geotechnical investigations are necessary.

The Geotechnical Desktop Study forms part of a Detailed Engineering Evaluation prepared by OPUS. The Geotechnical Desk Study has been undertaken without the benefit of any site specific investigations and is therefore preliminary in its nature.

2. Desktop Study

2.1 Site Description

The Reg Stillwell Place Residential Housing Units are situated approximately 7km north east of Christchurch City at 189 Palmers Road, New Brighton. It is a relatively flat site, approximately 180m north of the Avon River (refer Appendix A).

The housing development was constructed in the 1970's and comprises 34 units of single and double storey configuration.

2.2 Available Building Drawings

Construction drawings prepared by the Christchurch City Council of the Housing Development were sourced from the CCC property file (refer to Appendix B).

The drawings indicate the buildings are of timber framed construction, clad in concrete block veneer, with a corrugated iron roof. The buildings foundations are reinforced concrete perimeter strip footings founded 600mm to 900mm below the finished floor slab level, with a 100mm thick concrete floor slab reinforced with 1 layer of 668 mesh laid centrally on compacted hardfill.

2.3 Regional Geology

The published geological map of the area, (Brown et al, 1992) indicates the site is underlain predominantly by sand of fixed and semi-fixed dunes and beaches belonging to

the Christchurch Formation. A groundwater table depth of approximately 1m has been shown on the published map (Brown et al, 1992).

2.4 Earthquake Commission Subsurface Investigations

Four Cone Penetrometer Tests (CPT's) have been completed within 200m of the site by Tonkin and Taylor, on behalf of the Earthquake Commission (EQC). The CPT's indicate soils comprise silty to clayey SAND/SILT from 0m to 1.4m, underlain by interbedded SAND and SILT layers down to 3.8m to 5.8m, before transitioning into clean sand to the end of the test at approximately 14m depth (Refer Appendix C).

2.5 Expected Ground Conditions

A review of the Environmental Canterbury Wells database (ECan, 2012) showed four wells located within approximately 50m of the property boundary (on the neighbouring property - refer to Appendix D). Material logs available from these wells in addition to the EQC CPT's have been used to infer the ground conditions at the site as shown in table 1 below.

Table 1: Inferred Ground Conditions

Stratigraphy	Thickness (m)	Depth Encountered from (m) below ground
silty SAND/sandy SILT $q_{cave} = 0.5 \text{ MPa}$ (0 to 1.0 MPa)	1.2-1.8	0
clayey SILT $q_{cave} = 1.0 \text{ MPa}$, (0.2 to 2.2 MPa)	1.8-4.4	1.2-1.4
SAND $q_{cave} = 12 \text{ MPa}$, (10 to 20 MPa)	28.6-29.7	3.0-5.8
PEAT/clayey SILT $q_{cave} = 2.0 \text{ MPa}$, (0.5 to 5 MPa)	4.2-6.7	31.6-35.5
GRAVELS (RICCARTON)	-	37.4-39.7

The groundwater level was recorded as 0.8m to 1.0m below ground in the borehole records.

2.6 Liquefaction Hazard

The Environment Canterbury Solid Facts Liquefaction Study (ECan, 2004) indicates the site is in an area designated as having 'High liquefaction ground damage potential'. According to this study, based on a low groundwater table, ground damage from liquefaction is expected to be significant and is likely to be affected by greater than 300mm of ground subsidence.

Examination of post-earthquake aerial photos taken by New Zealand Aerial Mapping (Project Orbit, 2012) identified evidence of significant quantities of liquefied soils ejected at the ground surface of the site after the 4 September 2010, 22 February 2011 and 13 June 2011 events.

The Tonkin and Taylor Reconnaissance (Project Orbit, 2012) also indicated evidence of liquefaction was observed at the site after the 4 September 2010, 22 February 2011 and 13 June 2011 events.

Following the recent strong earthquakes in Canterbury, the Canterbury Earthquake Recovery Authority (CERA, 2012) has zoned land in the Greater Christchurch area according to its ground performance in future large earthquakes (refer Appendix E).

The Department of Building and Housing has sub-divided the CERA “Green” residential recovery zone land on the flat in Christchurch into technical categories. The three technical categories are summarised in Table 2 which has been adapted from the Department of Building and Housing guidance document (DBH, 2011).

Table 2: Technical Categories based on Expected Land Performance

Foundation Technical Category	Future land performance expected from liquefaction	Expected SLS land settlement	Expected ULS land settlement
TC 1	Negligible land deformations expected in a future small to medium sized earthquake and up to minor land deformations in a future moderate to large earthquake.	0-15 mm	0-25 mm
TC 2	Minor land deformations possible in a future small to medium sized earthquake and up to moderate land deformations in a future moderate to large earthquake.	0-50 mm	0-100 mm
TC 3	Moderate land deformations possible in a future small to medium sized earthquake and significant land deformations in a future moderate to large earthquake.	>50 mm	>100 mm

The property at Reg Stigwell Place has been zoned as N/A-Urban Non-residential, as it is not a residential dwelling. However, the neighbouring residential properties to the south of the site have been zoned as “Red” which is evaluated as not being practical to rebuild, repair or reoccupy. Properties to the north and east of the site have been zoned as Green-TC3 “blue zone”, which is determined to have a moderate to significant risk of land damage due to liquefaction in future significant earthquakes.

The Avon River is approximately 180m south-east of the site and its invert is approximately 3m to 4m below the floor level of the residential Units at Reg Stillwell Place. The proximity of the Avon River and presence of liquefiable soils may result in lateral spread occurring at the site.

3. Site Walkover Inspection

A walkover inspection of the exterior of the building and surrounding land was carried out by an Opus Geotechnical Engineer on 30 April 2012. The following observations were made (refer to Site Photographs and Appendix F):

- Ejected sand due to liquefaction located throughout the entire site (refer photographs 3,4 & 10);
- Up to 20mm stepped cracking of concrete block work cladding in numerous units with partial instability of the block work (refer photographs 5 & 8);
- 1mm to 3mm cracks in concrete slab footing to numerous units (refer photographs 2 & 6);
- 20mm to 300mm depressions in asphalt access way and in lawn areas (refer photograph 4);
- Manhole floated by 40mm relative to the surrounding ground;
- Approximately 80mm of heave in the asphalt path in front of Block F (refer photograph 9);
- Numerous cracks in asphalt areas throughout the site;
- Undulating asphalt surface in car park area (refer photograph 3);
- Numerous cracks in concrete kerb to northern access way;

- Numerous cracks in asphalt surfacing to southern access way;
- Longitudinal cracking along concrete footing to Units 19 & 20, Block C (refer photograph 7).

4. Level Survey

A level survey was carried out by OPUS on 30 April 2012. The maximum differential settlement is summarised in Table 3 (refer Appendix G).

Table 3: Variation in Floor Slab Levels

Block	Unit	Differential Settlement (mm) ^{1,2}
A	1	90 (south)
A	3	80 (south)
B	7	100 (south-east)
B	9	110 (south-east)
B	13	40 (south-east)
B	15	40 (south-east)
C	17	40 (south)
C	18	80 (south-west)
C	19	90 (south-west)
C	20	50 (south-west)
F	27	120 (north-west)
F	29	90 (north-west)
F	31	120 (north)
F	33	90 (north-east)
<p>Notes: (1) Floor slab levels rounded to nearest 10mm</p> <p>(2) Direction of fall indicated in brackets</p> <p>(3) Only units listed were surveyed.</p>		

5. Discussion

The ECan liquefaction study indicated the Reg Stillwell Place site possessed a high liquefaction ground damage potential during future seismic events. Post earthquake aerals and observations have confirmed that significant volumes of liquefied soils were ejected at the site during the 4 September 2010, 22 February 2011 and 13 June 2011 earthquake events.

Residential properties on the southern boundary have been zoned “Red”, indicating that the land is not practical to rebuild, repair or reoccupy, as the required improvements would be too difficult or costly to implement.

Observations of damage to the Reg Stillwell Residential Housing Units confirmed that liquefaction induced differential settlement has occurred at the site. The extent of settlement was quantified in a levels survey by OPUS which indicated between 40 and 120mm of differential settlement has occurred in the concrete floor slabs of the units in Blocks a, B, C & F.

Observed cracking of the concrete kerbs and asphalt surfaces throughout the site are predominantly perpendicular to the Avon River. Lateral spread ground cracking would be

expected to be parallel to the Avon River. Significant ground heave has occurred, which is inferred to result from liquefied ejected soils accumulating under an impermeable surface, such as asphalt.

Due to the proximity of the Avon River to Reg Stillwell Place, the site is considered to have lateral spreading potential. A detailed investigation and assessment of the lateral spreading potential for this site is recommended. The site may also be at risk from flooding of the Avon River.

The buildings at the site are a similar structural form to a residential structure. Accordingly, recommendations in the Department of Building and Housing New Zealand guidance documents for repairing and rebuilding foundations in Technical Category 3 (DBH, 2012) are likely to be applicable for the buildings at this site. The guidance document indicates that for foundations comprising reinforced concrete perimeter footing and a concrete floor slab which are out of level between 50mm to 150mm, with cracks in the floor slab less than 3mm width; a foundation re-level is required.

GNS Science indicates an elevated risk of seismic activity is expected in the Canterbury region as a result of the earthquake sequence following the 4 September 2010 earthquake. Recent advice (Geonet, 2012) indicates there is a 15% probability of another Magnitude 6 or greater earthquake occurring in the next 12 months in the Canterbury region. This event may cause liquefaction induced land damage at the site similar to that experienced; dependent on the location of the earthquakes epicentre. This confirms that there is currently a significant risk of liquefaction and ground settlements occurring at the site. It is expected that the probability of occurrence is likely to decrease with time following periods of reduced seismic activity

If the existing shallow foundations are retained, it is likely that in a future Serviceability Limit State (SLS) and Ultimate Limit State (ULS) earthquake, liquefaction induced settlement similar to that which has been reported at the site may occur.

If the existing units are to be retained, a building consent will be necessary for remedial works. Deep investigations comprising at least 6 Cone Penetrometer Tests (CPT's) to a depth of 20m are recommended to be undertaken to enable a site wide liquefaction and lateral spreading assessment (refer Appendix H).

6. Recommendations

- Review of the flood risk to the site based on updated topographic surveys of the area and predicted flooding river levels is recommended;
- It is recommended that deep investigations comprising at least 6 Cone Penetrometer Tests to a depth of 20m be undertaken to enable a site wide liquefaction and lateral spread potential assessment;
- If the site is assessed to be the equivalent to the DBH Technical Category 3, in accordance with the interim guidance document, a foundation re-level is recommended for the units at Reg Stillwell Place. However, more damage to the existing concrete slab foundations is likely in a future seismic event. Rebuilding with enhanced foundations (e.g. ribraft or piles) is considered more likely to be re-insurable and achieve building consent compliance.

7. Limitation

This report has been prepared solely for the benefit of the Christchurch City Council as our client with respect to the brief. The reliance by other parties on the information or opinions

contained in the report shall, without our prior review and agreement in writing, be at such parties' sole risk.

It is recognised that the passage of time affects the information and assessment provided in this Document. The recommendations formed in this report are based upon information that existed at the time of production of the Desk top Study. It is understood that the services provided allowed OPUS to form no more than an opinion on the actual conditions of the site at the time the site was visited and cannot be used to assess the effect of any subsequent changes in the quality of the site, or its surroundings or any laws or regulations.

8. References

Brown, LJ; Webber, JH (1992). Geology of the Christchurch Urban Area. Scale 1:25,000. Institute of Geological and Nuclear Sciences geological map 1.

Canterbury Earthquake Recovery Authority (CERA). *Land Zone Map*. (2012-last update). [Online]. Available: <http://www.rebuildchristchurch.co.nz/content/land-zone-map> [2012, April 23]

Department of Building and Housing New Zealand (2011) *Revised guidance on repairing and rebuilding houses affected by the Canterbury earthquake sequence*.

Department of Building and Housing New Zealand (2012) *Appendix C: Interim guidance for repairing and rebuilding foundations in Technical Category 3*.

Environment Canterbury (ECan), Canterbury Regional Council (2004) *The Solid Facts on Christchurch Liquefaction*.

Environment Canterbury (ECan), Canterbury Regional Council, *Well Card Search* [Online], Available: <http://ecan.govt.nz/services/online-services/tools-calculators/Pages/well-card.aspx> [2012, May 10]

Geonet. *Canterbury region long-term probabilities* (30 April 2012-last update). [Online], Available: <http://www.geonet.org.nz/canterbury-quakes/aftershocks/> [2012, May 02]

Project Orbit, *interagency/organisation collaboration portal for Christchurch recovery effort* (2012-last update) [Online] Available: <https://canterburyrecovery.projectorbit.com/SitePages/Home.aspx> [2012, May 15]

Figures:

Site Photographs

List of Appendices:

Appendix A: Site Location Plan

Appendix B: CCC Construction Drawings

Appendix C: Earthquake Commission Cone Penetrometer Test Results

Appendix D: Environment Canterbury Borehole Logs

Appendix E: Land Recovery Zones

Appendix F: Site Walkover Inspection Plan

Appendix G: OPUS Verticality Survey

Appendix H: Proposed CPT Site Plan

Appendix A: Site Location Plan



Key:



EQC CPT



Ecan Borehole

SOURCE: 1) canterburyrecovery.projectorbit.com (Accessed on 15/05/12)
2) <http://arcims.ecan.govt.nz/ecanmapping/> (Accessed on 15/05/12)



Opus International Consultants Ltd

Christchurch Office

20 Moorhouse Ave

PO Box 1482

Christchurch, New Zealand

Tel: +64 3 363 5400 Fax: +64 3 365 7857

Project:

Reg Stillwell Place

Geotechnical Desktop Study

Project No:

6-QUCCC.84 85SC

Client:









Christchurch City Council

Site Location Plan

Drawn:

15/05/2012

Appendix B:
CCC Construction Drawings



SECTIONAL ELEVATION

SECTIONAL ELEVATION

SECTIONAL ELEVATION

SECTIONAL ELEVATION



27-1 AND 27-2 JUNIOR

CHRISTCHURCH CITY COUNCIL

SECTIONAL ELEVATION

SECTIONAL ELEVATION

27-1 AND 27-2 JUNIOR

CHRISTCHURCH CITY COUNCIL

SECTIONAL ELEVATION


SECTIONAL ELEVATION

27-1 AND 27-2 JUNIOR

CHRISTCHURCH CITY COUNCIL


SECTIONAL ELEVATION

SECTIONAL ELEVATION






Notes and dimensions for the section drawing.



Notes and dimensions for the section drawing.




Notes and dimensions for the section drawing.




Notes and dimensions for the section drawing.




Notes and dimensions for the section drawing.



Notes and dimensions for the plan drawing.



Notes and dimensions for the section drawing.



PLAN OF FOUNDATION BLOCK A

PART PLAN OF FOUNDATION BLOCK B.

PART FOUNDATION PLAN BLOCK E



SECTION 1

SECTION 2

SECTION 3

SECTION 4

SECTION 5

SECTION 6

SECTION 7

1. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.

2. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.


3. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.

4. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.

5. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.

6. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.

7. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.



SECTION 1

SECTION 2


SECTION 3

TYPICAL PLAN OF REINFORCING AT CORNER

1. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.


PALMERS ROAD PENSIONERS COTTAGES - DOUBLE STOREY UNITS										D.1746	
FOUNDATION DETAILS											
CONSTRUCTION WITH CONCRETE - CITY ENGINEER'S DRAWINGS											
1. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.											
2. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.											
3. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.											
4. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.											
5. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.											
6. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.											
7. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.											
8. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.											
9. 12'-0" x 12'-0" x 12'-0" concrete block with 4#4 bars at 12" o.c.											
10. 12'-6" x 12'-6" x 12'-6" concrete block with 4#6 bars at 12" o.c.											

2' distance between the center of the door and the center of the window




SECTION 1
Door and window in wall

Scale: 1/4" = 1'-0"




SECTION 2
Door and window in wall

Scale: 1/4" = 1'-0"



SECTION 3
Door and window in wall

Scale: 1/4" = 1'-0"



SECTION 4
Door and window in wall

Scale: 1/4" = 1'-0"

Scale: 1/4" = 1'-0"

Scale: 1/4" = 1'-0"



SECTION 5
Door and window in wall

Scale: 1/4" = 1'-0"





SECTION 6
Door and window in wall


Scale: 1/4" = 1'-0"






GROTHENBERG CITY COUNCIL - CITY ENGINEER'S DEPARTMENT									
PALMERS ROAD PENSIONERS COTTAGES - DOUBLE STOREY UNITS									
SECTIONS									
1	2	3	4	5	6	7	8	9	10
11	12	13	14	15	16	17	18	19	20
21	22	23	24	25	26	27	28	29	30
31	32	33	34	35	36	37	38	39	40
41	42	43	44	45	46	47	48	49	50
51	52	53	54	55	56	57	58	59	60
61	62	63	64	65	66	67	68	69	70
71	72	73	74	75	76	77	78	79	80
81	82	83	84	85	86	87	88	89	90
91	92	93	94	95	96	97	98	99	100
101	102	103	104	105	106	107	108	109	110
111	112	113	114	115	116	117	118	119	120
121	122	123	124	125	126	127	128	129	130
131	132	133	134	135	136	137	138	139	140
141	142	143	144	145	146	147	148	149	150
151	152	153	154	155	156	157	158	159	160
161	162	163	164	165	166	167	168	169	170
171	172	173	174	175	176	177	178	179	180
181	182	183	184	185	186	187	188	189	190
191	192	193	194	195	196	197	198	199	200
201	202	203	204	205	206	207	208	209	210
211	212	213	214	215	216	217	218	219	220
221	222	223	224	225	226	227	228	229	230
231	232	233	234	235	236	237	238	239	240
241	242	243	244	245	246	247	248	249	250
251	252	253	254	255	256	257	258	259	260
261	262	263	264	265	266	267	268	269	270
271	272	273	274	275	276	277	278	279	280
281	282	283	284	285	286	287	288	289	290
291	292	293	294	295	296	297	298	299	300
301	302	303	304	305	306	307	308	309	310
311	312	313	314	315	316	317	318	319	320
321	322	323	324	325	326	327	328	329	330
331	332	333	334	335	336	337	338	339	340
341	342	343	344	345	346	347	348	349	350
351	352	353	354	355	356	357	358	359	360
361	362	363	364	365	366	367	368	369	370
371	372	373	374	375	376	377	378	379	380
381	382	383	384	385	386	387	388	389	390
391	392	393	394	395	396	397	398	399	400
401	402	403	404	405	406	407	408	409	410
411	412	413	414	415	416	417	418	419	420
421	422	423	424	425	426	427	428	429	430
431	432	433	434	435	436	437	438	439	440
441	442	443	444	445	446	447	448	449	450
451	452	453	454	455	456	457	458	459	460
461	462	463	464	465	466	467	468	469	470
471	472	473	474	475	476	477	478	479	480
481	482	483	484	485	486	487	488	489	490
491	492	493	494	495	496	497	498	499	500
501	502	503	504	505	506	507	508	509	510
511	512	513	514	515	516	517	518	519	520
521	522	523	524	525	526	527	528	529	530
531	532	533	534	535	536	537	538	539	540
541	542	543	544	545	546	547	548	549	550
551	552	553	554	555	556	557	558	559	560
561	562	563	564	565	566	567	568	569	570
571	572	573	574	575	576	577	578	579	580
581	582	583	584	585	586	587	588	589	590
591	592	593	594	595	596	597	598	599	600
601	602	603	604	605	606	607	608	609	610
611	612	613	614	615	616	617	618	619	620
621	622	623	624	625	626	627	628	629	630
631	632	633	634	635	636	637	638	639	640
641	642	643	644	645	646	647	648	649	650
651	652	653	654	655	656	657	658	659	660
661	662	663	664	665	666	667	668	669	670
671	672	673	674	675	676	677	678	679	680
681	682	683	684	685	686	687	688	689	690
691	692	693	694	695	696	697	698	699	700
701	702	703	704	705	706	707	708	709	710
711	712	713	714	715	716	717	718	719	720
721	722	723	724	725	726	727	728	729	730
731	732	733	734	735	736	737	738	739	740
741	742	743	744	745	746	747	748	749	750
751	752	753	754	755	756	757	758	759	760
761	762	763	764	765	766	767	768	769	770
771	772	773	774	775	776	777	778	779	780
781	782	783	784	785	786	787	788	789	790
791	792	793	794	795	796	797	798	799	800
801	802	803	804	805	806	807	808	809	810
811	812	813	814	815	816	817	818	819	820
821	822	823	824	825	826	827	828	829	830
831	832	833	834	835	836	837	838	839	840
841	842	843	844	845	846	847	848	849	850
851	852	853	854	855	856	857	858	859	860
861	862	863	864	865	866	867	868	869	870
871	872	873	874	875	876	877	878	879	880
881	882	883	884	885	886	887	888	889	890
891	892	893	894	895	896	897	898	899	900
901	902	903	904	905	906	907	908	909	910
911	912	913	914	915	916	917	918	919	920
921	922	923	924	925	926	927	928	929	930
931	932	933	934	935	936	937	938	939	940
941	942	943	944	945	946	947	948	949	950
951	952	953	954	955	956	957	958	959	960
961	962	963	964	965	966	967	968	969	970
971	972	973	974	975	976	977	978	979	980
981	982	983	984	985	986	987	988	989	990
991	992	993	994	995	996	997	998	999	1000



Appendix C:
Earthquake Commission Cone Penetrometer Test Results


Project: Darfield 2010 Earthquake - EQC Ground Investigations				Page: 1 of 1		CPT-NBT-07	
Test Date: 27-Nov-2010		Location: New Brighton		Operator: McMillan		 	
Pre-Drill: 1.2m		Assumed GWL: 3.1mBGL		Located By: Survey GPS			
Position: 2486769.7mE		5744668.4mN		1.59mRL			
				Coord. System: NZMG & MSL			
Other Tests:				Comments:			






Project: Darfield 2010 Earthquake - EQC Ground Investigations				Page: 1 of 1		CPT-NBT-08	
Test Date: 27-Nov-2010		Location: New Brighton		Operator: McMillan		 	
Pre-Drill: 1.2m		Assumed GWL: 1.5mBGL		Located By: Survey GPS			
Position: 2486821.6mE		5744921.7mN		2.26mRL			
				Coord. System: NZMG & MSL			
Other Tests:				Comments:			






Project: Christchurch 2011 Earthquake - EQC Ground Investigations				Page: 1 of 2		CPT-NBT-28	
Test Date: 4-Aug-2011		Location: New Brighton		Operator: Opus		 	
Pre-Drill: 1.2m		Assumed GWL: 5.2mBGL		Located By: Survey GPS			
Position: 2487002.3mE		5744574.2mN		1.46mRL			
				Coord. System: NZMG & MSL			
Other Tests:				Comments:			



Project: Christchurch 2011 Earthquake - EQC Ground Investigations				Page: 2 of 2		CPT-NBT-28	
Test Date: 4-Aug-2011		Location: New Brighton		Operator: Opus		 	
Pre-Drill: 1.2m		Assumed GWL: 5.2mBGL		Located By: Survey GPS			
Position: 2487002.3mE		5744574.2mN 1.46mRL		Coord. System: NZMG & MSL			
Other Tests:				Comments:			



Project: Christchurch 2011 Earthquake - EQC Ground Investigations				Page: 1 of 1		CPT-NBT-30	
Test Date: 10-Jun-2011		Location: New Brighton		Operator: Geotech		 	
Pre-Drill: 1.2m		Assumed GWL: 1.2mBGL		Located By: Survey GPS			
Position: 2487025.5mE		5744805.2mN 2.2mRL		Coord. System: NZMG & MSL			
Other Tests:				Comments:			



Appendix D:
Environment Canterbury Borehole Logs

Borelog for well M35/1871 page 1 of 2


Gridref: M35 86855-44667 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 2.39 +MSD

Driller : Stewart R H

Drill Method : Driven Pipe

Drill Depth : -103m Drill Date : 14/01/1952



Borelog for well M35/1871 page 2 of 2


Gridref: M35.86855-44667 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 2.39 +MSD

Driller : Stewart R H

Drill Method : Driven Pipe

Drill Depth : -103m Drill Date : 14/01/1952



Borelog for well M35/2132 page 1 of 3


Gridref: M35 86857-44695 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 3.95 +MSD

Driller : Stewart R H

Drill Method : Cable Tool

Drill Depth : -152.5m Drill Date : 21/10/1949



Borelog for well M35/2132 page 2 of 3


Gridref: M35 86857-44695 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 3.95 +MSD

Driller : Stewart R H

Drill Method : Cable Tool

Drill Depth : -152.5m Drill Date : 21/10/1949



Borelog for well M35/2132 page 3 of 3

Gridref: M35.86857-44695 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 3.95 +MSD

Driller : Stewart R H

Drill Method : Cable Tool

Drill Depth : -152.5m Drill Date : 21/10/1949



Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
		- 103.6m	Brown gravel & sand	li-3
			Brown sand & gravel	
		- 109.7m		he
			Brown sand with some gravel and clay (Tight)	
		- 113.0m		he
			Sandy clay (Hard)	he
		- 114.3m		he
			Yellow clay	he
		- 115.5m		
			Brown gravel & sand	
		- 121.3m		bu
			Sand, gravel & clay mixture	bu
		- 122.5m		
			Yellow clay & sand	sh
		- 124.0m		
			Blue clay & sand	
		- 127.4m		sh
			Blue clay & sand	
		- 132.8m		sh
			Brown sandy clay	
		- 135.3m		sh
			Blue clay	
		- 138.3m		sh
			Blue clay & fine Blue gravel	sh
		- 138.9m		
			Yellow clay	
		- 141.1m		sh
			Brown silty clay	
		- 142.9m		sh
			Clay, sand & Brown gravel (Tight)	wa
		- 143.5m		
			Brown gravel	
		- 152.4m		wa
			Yellow clay	aq5
		- 153.7m		

Borelog for well M35/2276 page 1 of 2


Gridref: M35.86858-44671 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 2.35 +MSD

Driller : Owner

Drill Method : Cable Tool

Drill Depth : -89.3m Drill Date : 6/06/1958



Borelog for well M35/2276 page 2 of 2


Gridref: M35.86858-44671 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 2.35 +MSD

Driller : Owner

Drill Method : Cable Tool

Drill Depth : -89.3m Drill Date : 6/06/1958



Borelog for well M35/2884 page 1 of 2


Gridref: M35:869-447 Accuracy : 4 (1=best, 4=worst)

Ground Level Altitude : 2.14 +MSD

Driller : A M Bisley & Co

Drill Method : Cable Tool

Drill Depth : -102.5m Drill Date : 26/10/1983



Borelog for well M35/2884 page 2 of 2


Gridref: M35:869-447 Accuracy : 4 (1=best, 4=worst)

Ground Level Altitude : 2.14 +MSD

Driller : A M Bisley & Co

Drill Method : Cable Tool

Drill Depth : -102.5m Drill Date : 26/10/1983



Borelog for well M35/4925 page 1 of 2


Gridref: M35:8679-4466 Accuracy : 4 (1=best, 4=worst)

Ground Level Altitude : 2.1 +MSD

Driller : McMillan Water Wells Ltd

Drill Method : Cable Tool

Drill Depth : -97m Drill Date : 28/11/1986



Borelog for well M35/4925 page 2 of 2

Gridref: M35:8679-4466 Accuracy : 4 (1=best, 4=worst)

Ground Level Altitude : 2.1 +MSD

Driller : McMillan Water Wells Ltd


Drill Method : Cable Tool

Drill Depth : -97m Drill Date : 28/11/1986




Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
	Artesian	49.0m	Grey sand & some gravel	br
-50		- 50.5m	Fine Blue & Grey sands	br
		- 52.0m	Fine Brown sand	br
		- 54.0m	Fine Brown sand & some clay	br
-55		- 56.0m	Yellow clay	br
		- 61.0m	Small gravels & sand	br
-60		- 64.0m	Blue pug & Blue sand	br
		- 65.0m	Blue pug	br
-65		- 65.5m	Yellow silt	br
			Brown stained shingle & sand	
-70		- 74.0m		li-1
-75		- 77.5m	Grey pug	li-2
		- 80.5m	Claybound gravels	li-2
-80			Rusty Brown stained gravels & sand	li-2
-85		- 87.8m		li-2
		- 88.5m	Yellow clay	li-2
-90		- 90.7m	Grey pug, some organic material	li-2
		- 91.3m	(Hard) Yellow clay	li-2
			Brown gravels	
-95		- 94.4m		li-3
		- 97.0m	Free Brown gravels	li-3


Appendix E: Land Recovery Zones




Appendix F:
Site Walkover Inspection Plan



Appendix G:
OPUS Verticality Survey





GROUND FLOOR PLAN - BLOCK A.

[illegible]

Christchurch Office
P O Box 1482
Christchurch 8142, New Zealand
+64 3 333 5119

Reg Stillwell Level Survey
Block A (Ground Floor)

Block A (Ground Floor)

State	
-------	--

1

Ques	Design	Answer	Revised Data
------	--------	--------	--------------


J. Morrow	© Baker
-----------	---------

Period (s)	Scale
------------	-------

GQUCCC.84	N.T.S
-----------	-------

Drawing by


6/1366/247/2604



FIRST FLOOR PLAN - BLOCK A


<div> <div>OPUS</div> <div> <div>Christchurch Office</div> <div>P.O. Box 1447</div> <div>Christchurch 8140, New Zealand</div> <div>+64 3 355 5400</div> </div> </div>		<div> <div>Reg Stillwell Level Survey</div> <div>Block A (First Floor)</div> </div>	
<div> <div>Drawn</div> <div>J. H. H. H.</div> </div>	<div> <div>Designed</div> <div></div> </div>	<div> <div>Approved</div> <div>S. T. C.</div> </div>	<div> <div>Checked</div> <div></div> </div>
<div> <div>Project No.</div> <div>60UCCC.84</div> </div>	<div> <div>Date</div> <div>N.T.S.</div> </div>	<div> <div>Sheet No.</div> <div>6/1366/247/2604</div> </div>	<div> <div>Scale</div> <div>3/10</div> </div>
<div> <div>Revised</div> <div></div> </div>		<div> <div>Revised</div> <div></div> </div>	

30 m
20
10
0



Rev	Description	Rev	Description

		Christchurch Office P.O. Box 1429 Christchurch 8140, New Zealand Tel: 03 336 5000		Project Reg Stillwell Level Survey Block B1 (First floor)	
Drawn J. Horner	Output S. Baker	Checked S. Baker	Approved S. Baker	Date 	
Project No. 80UCCC-64	Scale N.T.S.	Drawing No. 6/1366/247/2604		Check No. 5/10	Revision R0



FLOOR PLAN BLOCK C.

Revised	Revised	Revised	Revised

		Christchurch Office P.O. Box 1402 Christchurch 8140, New Zealand +64 3 363 5401	Project: Rogg Stillwell Level Survey Block C
Date: J. Moxley	Checked: S. B. B.	Approved: S. B. B.	Scale: 1:100
Project No: 6020000.04	Title: N.T.S.	Drawing No: 6/1366/247/2604	Date: 8/10 R0

FOUNDATION PLAN BLOCK F

GROUND FLOOR PLAN BLOCK F

Revision	Description	Approved	Revised



Christchurch Office
P.O. Box 1140
Christchurch 8140, New Zealand
+64 (0)3 366 5400


Reg Siltwell Level Survey
Block F (Ground floor)

Client: J. Murray
Design: S. Barker
Project: 6/1366/247/2604

Scale: N.T.S.

6/1366/247/2604

9/10 R0



Revised	Approved	Revised	Approved



Christchurch Office
PO Box 185
Christchurch 8140, New Zealand
+64 3 351 5100

Project
Reg Stillwell Level Survey
Block F (First floor)

Client

Drawn	Checked	Approved	Revised
J. Martin			
Revised			
6/20/2004			


Project No.
6/1366/247/2604

Sheet No.
10/10

Revision
R0

Appendix H:
Proposed CPT Site Plan



Key:  Cone Penetrometer Test Location






Opus International Consultants Ltd
Christchurch Office
20 Moorhouse Ave
PO Box 1482
Christchurch, New Zealand
Tel: +64 3 363 5400 Fax: +64 3 365 7857


Project: Reg Stillwell Place
Geotechnical Desktop Study
Project No: 6-QUCCC.84 85SC
Client: Christchurch City Council

Proposed CPT Site Plan

Drawn: 28/05/2012

Appendix 4 – Drawings










CHRISTCHURCH CITY COUNCIL

FRANKS ROAD PENS DENS CO-OP


5



- 1. 1/2" x 4" STUDS AT 16" O.C.
- 2. 1/2" x 4" STUDS AT 16" O.C.
- 3. 1/2" x 4" STUDS AT 16" O.C.
- 4. 1/2" x 4" STUDS AT 16" O.C.
- 5. 1/2" x 4" STUDS AT 16" O.C.
- 6. 1/2" x 4" STUDS AT 16" O.C.
- 7. 1/2" x 4" STUDS AT 16" O.C.
- 8. 1/2" x 4" STUDS AT 16" O.C.
- 9. 1/2" x 4" STUDS AT 16" O.C.
- 10. 1/2" x 4" STUDS AT 16" O.C.




SECTION 15
SECTION 16




SECTION 17
SECTION 18


UNIVERSITY OF CHURCH
ARCHITECTURAL
7 JUN 1965




PLAN OF FOUNDATION BLOCK A.
Scale: 1/4" = 1'-0"




PART PLAN OF FOUNDATION BLOCK B.
Scale: 1/4" = 1'-0"



PART FOUNDATION PLAN BLOCK F.
Scale: 1/4" = 1'-0"



SECTION 1 SECTION 2 SECTION 3 SECTION 4 SECTION 5 SECTION 6 SECTION 7








SECTION 8 SECTION 9 SECTION 10 SECTION 11



TYPICAL PLAN OF
REINFORCING AT CORNER


CHRISTCHURCH CITY COUNCIL - CIVIL AND NEER'S DEPARTMENT				PALMERS ROAD PENSIONERS COTTAGES - DOUBLE STOREY UNITS		0.1746
FOUNDATION DETAILS						



Source: *Survey of companies in 2014* shows
of *technology* *used* *in* *2014* *by* *companies*
101 Mean to the program 101


1 JUN 1973

CHRISTENBACH CITY COUNCIL - CITY ENGINEER'S DEPARTMENT PALMERS ROAD PENSIONERS COTTAGES - DOUBLE STOREY UNITS SECTIONS				D.1746
--	--	--	--	--------



CITY		DESIGN		NAME		SIGN.	DATE	APPROVED		JOB TITLE		DRAWING TITLE		SCALES		C.N. 98/99-359	
	CHRISTCHURCH THE GARDEN CITY <i>The city that shines</i>	DESIGNED	SDS / MK	18/5/99	18/5/99				18/5/99		REG STILLWELL PLACE SIX NEW GARAGES		SITE PLAN, PLAN, ELEVATIONS AND CROSS SECTION	1:50 1:20		D7501	
		DES REVIEW	D. CLARK	18/5/99	18/5/99				DATE								
		DRAWN	M. KITT	18/5/99	18/5/99												
		DRAW CHK.	SD. SMITH	18/5/99	18/5/99												
		INDEXED	AD008891/DON	MAR 99	18/5/99												D.E. Street
																	SHEET 1 OF 3

922 8525 Sheet 3



	CHRISTCHURCH CITY COUNCIL TECHNICAL SERVICES GROUP - DESIGN SERVICES UNIT - ARCHITECTS	NEW RESIDENTS LOUNGE AT BEE STILLWELL COURT	Date: 10/10/10	SCALE: 1:50 DRAWN: [Name] CHECKED: [Name]	CONTRACT: [Name] SHEET: 3 OF 3
--	--	---	----------------	---	-----------------------------------

Appendix 5 – CERA DEE Data Sheets

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Block A	Unit	No:	Street
Building Address:	Reg Stillwell Place			
Legal Description:				
		Degrees	Min	Sec
GPS south:				
GPS east:				
Building Unique Identifier (CCC):	PRO 1320-001			

Reviewer:	Alistair Boyce
CPEng No:	209860
Company:	Opus International
Company project number:	6-OUCCC.84
Company phone number:	03 3635400
Date of submission:	25/10/2013
Inspection Date:	23/12/2011
Revision:	Final V4
Is there a full report with this summary?	yes

Site

Site slope:	flat
Soil type:	silty sand
Site Class (to NZS1170.5):	D
Proximity to waterway (m, if <100m):	
Proximity to clifftop (m, if < 100m):	
Proximity to cliff base (m,if <100m):	

Max retaining height (m):	
Soil Profile (if available):	
If Ground improvement on site, describe:	
Approx site elevation (m):	

Building

No. of storeys above ground:	2
Ground floor split?	no
Storeys below ground:	0
Foundation type:	strip footings
Building height (m):	6.00
Floor footprint area (approx):	165
Age of Building (years):	39

single storey = 1

Ground floor elevation (Absolute) (m):	0.00
Ground floor elevation above ground (m):	
if Foundation type is other, describe:	
height from ground to level of uppermost seismic mass (for IEP only) (m):	6
Date of design:	1965-1976

Strengthening present?	no
Use (ground floor):	multi-unit residential
Use (upper floors):	multi-unit residential
Use notes (if required):	
Importance level (to NZS1170.5):	IL2

If so, when (year)?	
And what load level (%g)?	
Brief strengthening description:	

Gravity Structure

Gravity System:	load bearing walls
Roof:	timber framed
Floors:	precast concrete with topping
Beams:	none
Columns:	other (note)
Walls:	load bearing concrete

rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
unit type and depth (mm), topping	64mm topping, 100mm PC rib slab
overall depth x width (mm x mm)	
typical dimensions (mm x mm)	
#N/A	

Lateral load resisting structure

Lateral system along:	concrete shear wall
Ductility assumed, μ :	1.25
Period along:	0.24
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	

Note: Define along and across in detailed report!
0.02 from parameters in sheet

note total length of wall at ground (m):	4
wall thickness (m):	150
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	

Lateral system across:	concrete shear wall
Ductility assumed, μ :	1.25
Period across:	0.24
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	

0.00 from parameters in sheet

note total length of wall at ground (m):	24
wall thickness (m):	150
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	

Separations:

north (mm):	
east (mm):	
south (mm):	
west (mm):	

leave blank if not relevant

Non-structural elements

Stairs:	cast insitu
Wall cladding:	other heavy
Roof Cladding:	Metal
Glazing:	aluminium frames
Ceilings:	strapped or direct fixed
Services(list):	

notes	
describe	Concrete block veneer
describe	
gib ceiling	

Available documentation

Architectural	full
Structural	full
Mechanical	none
Electrical	none
Geotech report	none

original designer name/date	Christchurch City Council
original designer name/date	Christchurch City Council
original designer name/date	
original designer name/date	
original designer name/date	

Damage

Site:
(refer DEE Table 4-2)

Site performance:	Poor
Settlement:	0-25mm
Differential settlement:	1:150 or more
Liquefaction:	2-5 m ² /100m ³
Lateral Spread:	none apparent
Differential lateral spread:	none apparent
Ground cracks:	20-100mm/20m
Damage to area:	moderate to substantial (1 in 5)

Describe damage:	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	

Building:

Current Placard Status:	red
-------------------------	-----

Along

Damage ratio:	
Describe (summary):	

Describe how damage ratio arrived at: Moderate to severe damage observed

Across

Damage ratio:	#DIV/0!
Describe (summary):	

$$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms

Damage?:	no
----------	----

Describe:

CSWs:

Damage?:	yes
----------	-----

Describe: torsion, lack of load transfer, pounding

Pounding:

Damage?:	yes
----------	-----

Describe:

Non-structural:

Damage?:	no
----------	----

Describe:

Recommendations

Level of repair/strengthening required:	significant structural and strengthening
Building Consent required:	yes
Interim occupancy recommendations:	do not occupy

Describe:	as described in report
Describe:	
Describe:	

Along

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

If IEP not used, please detail assessment methodology: Quantitative

Across

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Block B	Unit No:	Street
Building Address:	Reg Stillwell Place		
Legal Description:			
	Degrees	Min	Sec
GPS south:			
GPS east:			
Building Unique Identifier (CCC):	PRO 1320-003		

Reviewer:	Alistair Boyce
CPEng No:	209860
Company:	Opus International
Company project number:	6-QUCCC.84
Company phone number:	03 3635400
Date of submission:	25/10/2013
Inspection Date:	6/01/2012
Revision:	Final V4
Is there a full report with this summary?	yes

Site

Site slope:	flat
Soil type:	silty sand
Site Class (to NZS1170.5):	D
Proximity to waterway (m, if <100m):	
Proximity to clifftop (m, if < 100m):	
Proximity to cliff base (m,if <100m):	

Max retaining height (m):	
Soil Profile (if available):	
If Ground improvement on site, describe:	
Approx site elevation (m):	

Building

No. of storeys above ground:	2
Ground floor split?	no
Storeys below ground:	0
Foundation type:	strip footings
Building height (m):	6.00
Floor footprint area (approx):	165
Age of Building (years):	39
Strengthening present?	no
Use (ground floor):	multi-unit residential
Use (upper floors):	multi-unit residential
Use notes (if required):	
Importance level (to NZS1170.5):	IL2

single storey = 1	Ground floor elevation (Absolute) (m):	0.00
	Ground floor elevation above ground (m):	
	if Foundation type is other, describe:	
	height from ground to level of uppermost seismic mass (for IEP only) (m):	6
	Date of design:	1965-1976

Gravity Structure

Gravity System:	load bearing walls
Roof:	timber framed
Floors:	precast concrete with topping
Beams:	none
Columns:	other (note)
Walls:	load bearing concrete

rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
unit type and depth (mm), topping	64mm topping, 100mm PC rib slab
overall depth x width (mm x mm)	
typical dimensions (mm x mm)	
#N/A	

Lateral load resisting structure

Lateral system along:	concrete shear wall
Ductility assumed, μ :	1.25
Period along:	0.24
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	
Lateral system across:	concrete shear wall
Ductility assumed, μ :	1.25
Period across:	0.24
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	

Note: Define along and across in detailed report!

0.02 from parameters in sheet

note total length of wall at ground (m):	4
wall thickness (m):	150
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	

note total length of wall at ground (m):	24
wall thickness (m):	150
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	

Separations:

north (mm):	
east (mm):	
south (mm):	
west (mm):	

leave blank if not relevant

Non-structural elements

Stairs:	cast insitu
Wall cladding:	other heavy
Roof Cladding:	Metal
Glazing:	aluminium frames
Ceilings:	strapped or direct fixed
Services(list):	

notes	
describe	Concrete block veneer
describe	
	gib ceiling

Available documentation

Architectural	full
Structural	full
Mechanical	none
Electrical	none
Geotech report	none

original designer name/date	Christchurch City Council
original designer name/date	Christchurch City Council
original designer name/date	
original designer name/date	
original designer name/date	

Damage

Site:
(refer DEE Table 4-2)

Site performance:	Poor
Settlement:	0-25mm
Differential settlement:	1:150 or more
Liquefaction:	2-5 m ² /100m ³
Lateral Spread:	none apparent
Differential lateral spread:	none apparent
Ground cracks:	20-100mm/20m
Damage to area:	moderate to substantial (1 in 5)

Describe damage:	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	

Building:

Current Placard Status:	red
-------------------------	-----

Along

Damage ratio:	
Describe (summary):	

Describe how damage ratio arrived at: Moderate to severe damage observed

Across

Damage ratio:	#DIV/0!
Describe (summary):	

$$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms

Damage?:	no
----------	----

Describe:

CSWs:

Damage?:	yes
----------	-----

Describe: torsion, lack of load transfer, pounding

Pounding:

Damage?:	yes
----------	-----

Describe:

Non-structural:

Damage?:	no
----------	----

Describe:

Recommendations

Level of repair/strengthening required:	significant structural and strengthening
Building Consent required:	yes
Interim occupancy recommendations:	do not occupy

Describe:	as described in report
Describe:	
Describe:	

Along

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

If IEP not used, please detail assessment methodology: Quantitative

Across

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Block C	Unit	No:	Street
Building Address:	Reg Stillwell Place			
Legal Description:				
		Degrees	Min	Sec
GPS south:				
GPS east:				
Building Unique Identifier (CCC):	PRO 1320-004			

Reviewer:	Alistair Boyce
CPEng No:	209860
Company:	Opus International
Company project number:	6-OUCCC.84
Company phone number:	03 3635400
Date of submission:	25/10/2013
Inspection Date:	23/12/2011
Revision:	Final V4
Is there a full report with this summary?	yes

Site

Site slope:	flat
Soil type:	silty sand
Site Class (to NZS1170.5):	D
Proximity to waterway (m, if <100m):	
Proximity to clifftop (m, if < 100m):	
Proximity to cliff base (m,if <100m):	

Max retaining height (m):	
Soil Profile (if available):	
If Ground improvement on site, describe:	
Approx site elevation (m):	

Building

No. of storeys above ground:	1
Ground floor split?	no
Storeys below ground:	0
Foundation type:	strip footings
Building height (m):	3.00
Floor footprint area (approx):	141
Age of Building (years):	39
Strengthening present?	no
Use (ground floor):	multi-unit residential
Use (upper floors):	multi-unit residential
Use notes (if required):	
Importance level (to NZS1170.5):	IL2

single storey = 1	Ground floor elevation (Absolute) (m):	0.00
	Ground floor elevation above ground (m):	
	if Foundation type is other, describe:	
	height from ground to level of uppermost seismic mass (for IEP only) (m):	3
	Date of design:	1965-1976

Gravity Structure

Gravity System:	load bearing walls
Roof:	timber framed
Floors:	other (note)
Beams:	cast-insitu concrete
Columns:	other (note)
Walls:	partially filled concrete masonry

rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
describe sytem	
overall depth x width (mm x mm)	
typical dimensions (mm x mm)	
thickness (mm)	

Lateral load resisting structure

Lateral system along:	lightweight timber framed walls	0.00
Ductility assumed, μ :	1.25	
Period along:		
Total deflection (ULS) (mm):		
maximum interstorey deflection (ULS) (mm):		
Lateral system across:	lightweight timber framed walls	0.00
Ductility assumed, μ :	1.25	
Period across:		
Total deflection (ULS) (mm):		
maximum interstorey deflection (ULS) (mm):		

Note: Define along and across in detailed report!

note typical wall length (m)	
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	
note typical wall length (m)	
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	

Separations:

north (mm):	
east (mm):	
south (mm):	
west (mm):	

leave blank if not relevant

Non-structural elements

Stairs:	other (specify)
Wall cladding:	other heavy
Roof Cladding:	Metal
Glazing:	aluminium frames
Ceilings:	strapped or direct fixed
Services(list):	

describe	None
describe	Concrete block veneer
describe	
	gib ceiling

Available documentation

Architectural	full
Structural	full
Mechanical	none
Electrical	none
Geotech report	none

original designer name/date	Christchurch City Council
original designer name/date	Christchurch City Council
original designer name/date	
original designer name/date	
original designer name/date	

Damage

Site:
(refer DEE Table 4-2)

Site performance:	Poor
Settlement:	0-25mm
Differential settlement:	1:150 or more
Liquefaction:	2-5 m ² /100m ³
Lateral Spread:	none apparent
Differential lateral spread:	none apparent
Ground cracks:	20-100mm/20m
Damage to area:	moderate to substantial (1 in 5)

Describe damage:	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	

Building:

Current Placard Status:	red
-------------------------	-----

Along

Damage ratio:	
Describe (summary):	

Describe how damage ratio arrived at: Moderate to severe damage observed

Across

Damage ratio:	#DIV/0!
Describe (summary):	

$$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms

Damage?:	no
----------	----

Describe:

CSWs:

Damage?:	yes
----------	-----

Describe: pounding

Pounding:

Damage?:	yes
----------	-----

Describe:

Non-structural:

Damage?:	no
----------	----

Describe:

Recommendations

Level of repair/strengthening required:	significant structural and strengthening
Building Consent required:	yes
Interim occupancy recommendations:	do not occupy

Describe:	as described in report
Describe:	
Describe:	

Along

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

If IEP not used, please detail Quantitative

Across

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

assessment methodology:

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Block D	Unit:	No:	Street:	Reviewer:	Alistair Boyce
Building Address:	Reg Stillwell Place				CPEng No:	209860
Legal Description:					Company:	Opus International
					Company project number:	6-OUCCC.84
					Company phone number:	03 3635400
		Degrees	Min	Sec	Date of submission:	25/10/2013
GPS south:					Inspection Date:	23/12/2011
GPS east:					Revision:	Final V4
Building Unique Identifier (CCC):	PRO 1320-005				Is there a full report with this summary?	yes

Site

Site slope:	flat	Max retaining height (m):	
Soil type:	silty sand	Soil Profile (if available):	
Site Class (to NZS1170.5):	D	If Ground improvement on site, describe:	
Proximity to waterway (m, if <100m):			
Proximity to clifftop (m, if < 100m):		Approx site elevation (m):	
Proximity to cliff base (m,if <100m):			

Building

No. of storeys above ground:	1	single storey = 1	Ground floor elevation (Absolute) (m):	0.00
Ground floor split?	no		Ground floor elevation above ground (m):	
Storeys below ground:	0		if Foundation type is other, describe:	
Foundation type:	strip footings	height from ground to level of uppermost seismic mass (for IEP only) (m):	6	
Building height (m):	3.00		Date of design:	1965-1976
Floor footprint area (approx):	108			
Age of Building (years):	39			
Strengthening present?	no		If so, when (year)?	
Use (ground floor):	multi-unit residential		And what load level (%g)?	
Use (upper floors):	multi-unit residential		Brief strengthening description:	
Use notes (if required):				
Importance level (to NZS1170.5):	IL2			

Gravity Structure

Gravity System:	load bearing walls	rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
Roof:	timber framed	describe sytem	64mm topping, 100mm PC rib slab
Floors:	other (note)	overall depth x width (mm x mm)	
Beams:	cast-insitu concrete	typical dimensions (mm x mm)	
Columns:	other (note)	thickness (mm)	
Walls:	partially filled concrete masonry		

Lateral load resisting structure

Lateral system along:	lightweight timber framed walls	Note: Define along and across in detailed report!	note typical wall length (m)	
Ductility assumed, μ :	1.25		estimate or calculation?	
Period along:			estimate or calculation?	
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):				
Lateral system across:	lightweight timber framed walls		note typical wall length (m)	
Ductility assumed, μ :	1.25		estimate or calculation?	
Period across:			estimate or calculation?	
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):				

Separations:

north (mm):		leave blank if not relevant
east (mm):		
south (mm):		
west (mm):		

Non-structural elements

Stairs:	other (specify)	describe:	None
Wall cladding:	other heavy	describe:	Concrete block veneer
Roof Cladding:	Metal	describe:	
Glazing:	aluminium frames		
Ceilings:	strapped or direct fixed		gib ceiling
Services(list):			

Available documentation

Architectural:	full	original designer name/date:	Christchurch City Council
Structural:	full	original designer name/date:	Christchurch City Council
Mechanical:	none	original designer name/date:	
Electrical:	none	original designer name/date:	
Geotech report:	none	original designer name/date:	

Damage

Site: (refer DEE Table 4-2)	Site performance:	Poor	Describe damage:	
	Settlement:	0-25mm	notes (if applicable):	
	Differential settlement:	1:150 or more	notes (if applicable):	
	Liquefaction:	2-5 m ² /100m ³	notes (if applicable):	
	Lateral Spread:	none apparent	notes (if applicable):	
	Differential lateral spread:	none apparent	notes (if applicable):	
	Ground cracks:	20-100mm/20m	notes (if applicable):	
	Damage to area:	moderate to substantial (1 in 5)	notes (if applicable):	

Building:

Current Placard Status:	green			
Along	Damage ratio:		Describe how damage ratio arrived at:	Moderate to severe damage observed
	Describe (summary):			
Across	Damage ratio:	#DIV/0!	$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$	
	Describe (summary):			
Diaphragms	Damage?:	no	Describe:	
CSWs:	Damage?:	no	Describe:	torsion, lack of load transfer, pounding
Pounding:	Damage?:	no	Describe:	
Non-structural:	Damage?:	no	Describe:	

Recommendations

Level of repair/strengthening required:	minor non-structural	Describe:	as described in report
Building Consent required:	no	Describe:	
Interim occupancy recommendations:	full occupancy	Describe:	
Along	Assessed %NBS before:		#### %NBS from IEP below
	Assessed %NBS after:	58%	If IEP not used, please detail assessment methodology:
Across	Assessed %NBS before:		#### %NBS from IEP below
	Assessed %NBS after:	58%	

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Block E	Unit:	No:	Street:
Building Address:	Reg Stillwell Place			
Legal Description:				
		Degrees	Min	Sec
GPS south:				
GPS east:				
Building Unique Identifier (CCC):	PRO 1320-006			

Reviewer:	Alistair Boyce
CPEng No:	209860
Company:	Opus International
Company project number:	6-QUCCC.84
Company phone number:	03 3635400
Date of submission:	25/10/2013
Inspection Date:	23/12/2011
Revision:	Final V4
Is there a full report with this summary?	yes

Site

Site slope:	flat
Soil type:	silty sand
Site Class (to NZS1170.5):	D
Proximity to waterway (m, if <100m):	
Proximity to clifftop (m, if < 100m):	
Proximity to cliff base (m,if <100m):	

Max retaining height (m):	
Soil Profile (if available):	
If Ground improvement on site, describe:	
Approx site elevation (m):	

Building

No. of storeys above ground:	1
Ground floor split?	no
Storeys below ground:	0
Foundation type:	strip footings
Building height (m):	3.00
Floor footprint area (approx):	108
Age of Building (years):	39
Strengthening present?	no
Use (ground floor):	multi-unit residential
Use (upper floors):	multi-unit residential
Use notes (if required):	
Importance level (to NZS1170.5):	IL2

single storey = 1	Ground floor elevation (Absolute) (m):	0.00
	Ground floor elevation above ground (m):	
	if Foundation type is other, describe:	
	height from ground to level of uppermost seismic mass (for IEP only) (m):	6
	Date of design:	1965-1976

Gravity Structure

Gravity System:	load bearing walls
Roof:	timber framed
Floors:	other (note)
Beams:	cast-insitu concrete
Columns:	other (note)
Walls:	partially filled concrete masonry

rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
describe sytem	64mm topping, 100mm PC rib slab
overall depth x width (mm x mm)	
typical dimensions (mm x mm)	
thickness (mm)	

Lateral load resisting structure

Lateral system along:	lightweight timber framed walls	0.00
Ductility assumed, μ :	1.25	
Period along:		
Total deflection (ULS) (mm):		
maximum interstorey deflection (ULS) (mm):		
Lateral system across:	lightweight timber framed walls	0.00
Ductility assumed, μ :	1.25	
Period across:		
Total deflection (ULS) (mm):		
maximum interstorey deflection (ULS) (mm):		

Note: Define along and across in detailed report!	note typical wall length (m)	
	estimate or calculation?	
	estimate or calculation?	
	estimate or calculation?	
	note typical wall length (m)	
	estimate or calculation?	
	estimate or calculation?	
	estimate or calculation?	

Separations:

north (mm):	
east (mm):	
south (mm):	
west (mm):	

leave blank if not relevant

Non-structural elements

Stairs:	other (specify)
Wall cladding:	other heavy
Roof Cladding:	Metal
Glazing:	aluminium frames
Ceilings:	strapped or direct fixed
Services(list):	

describe:	None
describe:	Concrete block veneer
describe:	
describe:	gib ceiling

Available documentation

Architectural:	full
Structural:	full
Mechanical:	none
Electrical:	none
Geotech report:	none

original designer name/date:	Christchurch City Council
original designer name/date:	Christchurch City Council
original designer name/date:	
original designer name/date:	
original designer name/date:	

Damage

Site:
(refer DEE Table 4-2)

Site performance:	Poor
Settlement:	0-25mm
Differential settlement:	1:150 or more
Liquefaction:	2-5 m ² /100m ³
Lateral Spread:	none apparent
Differential lateral spread:	none apparent
Ground cracks:	20-100mm/20m
Damage to area:	moderate to substantial (1 in 5)

Describe damage:	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	

Building:

Current Placard Status:	green
-------------------------	-------

Along	Damage ratio:		Describe how damage ratio arrived at: Moderate to severe damage observed
	Describe (summary):		
Across	Damage ratio:	#DIV/0!	$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
	Describe (summary):		
Diaphragms	Damage?:	no	Describe:
CSWs:	Damage?:	no	Describe: torsion, lack of load transfer, pounding
Pounding:	Damage?:	no	Describe:
Non-structural:	Damage?:	no	Describe:

Recommendations

Level of repair/strengthening required:	minor non-structural
Building Consent required:	no
Interim occupancy recommendations:	full occupancy

Describe:	as described in report
Describe:	
Describe:	

Along	Assessed %NBS before:		##### %NBS from IEP below	If IEP not used, please detail assessment methodology: Quantitative
	Assessed %NBS after:	68%		
Across	Assessed %NBS before:		##### %NBS from IEP below	
	Assessed %NBS after:	100%		

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Block F	Unit No:	Street
Building Address:	Reg Stillwell Place		
Legal Description:			
	Degrees	Min	Sec
GPS south:			
GPS east:			
Building Unique Identifier (CCC):	PRO 1320-007		

Reviewer:	Alistair Boyce
CPEng No:	209860
Company:	Opus International
Company project number:	6-QUCCC.84
Company phone number:	03 3635400
Date of submission:	25/10/2013
Inspection Date:	23/12/2011
Revision:	Final V4
Is there a full report with this summary?	yes

Site

Site slope:	flat
Soil type:	silty sand
Site Class (to NZS1170.5):	D
Proximity to waterway (m, if <100m):	
Proximity to clifftop (m, if < 100m):	
Proximity to cliff base (m,if <100m):	

Max retaining height (m):	
Soil Profile (if available):	
If Ground improvement on site, describe:	
Approx site elevation (m):	

Building

No. of storeys above ground:	2
Ground floor split?	no
Storeys below ground:	0
Foundation type:	strip footings
Building height (m):	6.00
Floor footprint area (approx):	185
Age of Building (years):	39
Strengthening present?	no
Use (ground floor):	multi-unit residential
Use (upper floors):	multi-unit residential
Use notes (if required):	
Importance level (to NZS1170.5):	IL2

single storey = 1	Ground floor elevation (Absolute) (m):	0.00
	Ground floor elevation above ground (m):	
	if Foundation type is other, describe:	
	height from ground to level of uppermost seismic mass (for IEP only) (m):	6
	Date of design:	1965-1976

Gravity Structure

Gravity System:	load bearing walls
Roof:	timber framed
Floors:	precast concrete with topping
Beams:	none
Columns:	other (note)
Walls:	load bearing concrete

rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
unit type and depth (mm), topping	64mm topping, 100mm PC rib slab
overall depth x width (mm x mm)	
typical dimensions (mm x mm)	
#N/A	

Lateral load resisting structure

Lateral system along:	concrete shear wall
Ductility assumed, μ :	1.25
Period along:	0.24
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	
Lateral system across:	concrete shear wall
Ductility assumed, μ :	1.25
Period across:	0.24
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	

Note: Define along and across in detailed report!
0.01 from parameters in sheet

0.00 from parameters in sheet

note total length of wall at ground (m):	8
wall thickness (m):	150
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	
note total length of wall at ground (m):	48
wall thickness (m):	150
estimate or calculation?	
estimate or calculation?	
estimate or calculation?	

Separations:

north (mm):	
east (mm):	
south (mm):	
west (mm):	

leave blank if not relevant

Non-structural elements

Stairs:	cast insitu
Wall cladding:	other heavy
Roof Cladding:	Metal
Glazing:	aluminium frames
Ceilings:	strapped or direct fixed
Services(list):	

notes	
describe	Concrete block veneer
describe	
gib ceiling	

Available documentation

Architectural	full
Structural	full
Mechanical	none
Electrical	none
Geotech report	none

original designer name/date	Christchurch City Council
original designer name/date	Christchurch City Council
original designer name/date	
original designer name/date	
original designer name/date	

Damage

Site:
(refer DEE Table 4-2)

Site performance:	Poor
Settlement:	0-25mm
Differential settlement:	1:150 or more
Liquefaction:	2-5 m ² /100m ³
Lateral Spread:	none apparent
Differential lateral spread:	none apparent
Ground cracks:	20-100mm/20m
Damage to area:	moderate to substantial (1 in 5)

Describe damage:	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	

Building:

Current Placard Status:	green
-------------------------	-------

Along

Damage ratio:	
Describe (summary):	

Describe how damage ratio arrived at: Moderate to severe damage observed

Across

Damage ratio:	#DIV/0!
Describe (summary):	

$$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms

Damage?:	no
----------	----

Describe:

CSWs:

Damage?:	yes
----------	-----

Describe: torsion, lack of load transfer, pounding

Pounding:

Damage?:	yes
----------	-----

Describe:

Non-structural:

Damage?:	no
----------	----

Describe:

Recommendations

Level of repair/strengthening required:	significant structural and strengthening
Building Consent required:	yes
Interim occupancy recommendations:	do not occupy

Describe:	as described in report
Describe:	
Describe:	

Along

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

If IEP not used, please detail assessment methodology: Quantitative

Across

Assessed %NBS before:	
Assessed %NBS after:	10%

%NBS from IEP below

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Garage	Unit:	No:	Street:	Reviewer:	Alistair Boyce
Building Address:	Reg Stillwell Place				CPEng No:	209860
Legal Description:					Company:	Opus International
					Company project number:	6-OUCCC.84
					Company phone number:	03 3635400
		Degrees	Min	Sec	Date of submission:	25/10/2013
GPS south:					Inspection Date:	23/12/2011
GPS east:					Revision:	Final V4
Building Unique Identifier (CCC):	PRO 1320-008				Is there a full report with this summary?	yes

Site

Site slope:	flat	Max retaining height (m):	
Soil type:	silty sand	Soil Profile (if available):	
Site Class (to NZS1170.5):	D	If Ground improvement on site, describe:	
Proximity to waterway (m, if <100m):			
Proximity to clifftop (m, if < 100m):		Approx site elevation (m):	
Proximity to cliff base (m,if <100m):			

Building

No. of storeys above ground:	1	single storey = 1	Ground floor elevation (Absolute) (m):	0.00
Ground floor split?	no		Ground floor elevation above ground (m):	
Storeys below ground:	0		if Foundation type is other, describe:	
Foundation type:	strip footings	height from ground to level of uppermost seismic mass (for IEP only) (m):	6	
Building height (m):	6.00		Date of design:	1965-1976
Floor footprint area (approx):	165			
Age of Building (years):	39			
Strengthening present?	no		If so, when (year)?	
Use (ground floor):	multi-unit residential		And what load level (%g)?	
Use (upper floors):	multi-unit residential		Brief strengthening description:	
Use notes (if required):				
Importance level (to NZS1170.5):	IL2			

Gravity Structure

Gravity System:	load bearing walls	rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
Roof:	timber framed	describe sytem	64mm topping, 100mm PC rib slab
Floors:	other (note)	overall depth x width (mm x mm)	
Beams:	cast-insitu concrete	typical dimensions (mm x mm)	
Columns:	other (note)	thickness (mm)	
Walls:	partially filled concrete masonry		

Lateral load resisting structure

Lateral system along:	lightweight timber framed walls	Note: Define along and across in detailed report!	note typical wall length (m)	
Ductility assumed, μ :	1.25		estimate or calculation?	
Period along:	0.24		estimate or calculation?	
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):				
Lateral system across:	lightweight timber framed walls		note typical wall length (m)	
Ductility assumed, μ :	1.25		estimate or calculation?	
Period across:	0.24		estimate or calculation?	
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):				

Separations:

north (mm):		leave blank if not relevant
east (mm):		
south (mm):		
west (mm):		

Non-structural elements

Stairs:	other (specify)	describe:	None
Wall cladding:	other heavy	describe:	Concrete block veneer
Roof Cladding:	Metal	describe:	
Glazing:	aluminium frames		
Ceilings:	strapped or direct fixed		gib ceiling
Services(list):			

Available documentation

Architectural:	full	original designer name/date:	Christchurch City Council
Structural:	full	original designer name/date:	Christchurch City Council
Mechanical:	none	original designer name/date:	
Electrical:	none	original designer name/date:	
Geotech report:	none	original designer name/date:	

Damage

Site: (refer DEE Table 4-2)	Site performance:	Poor	Describe damage:	
	Settlement:	0-25mm	notes (if applicable):	
	Differential settlement:	1:150 or more	notes (if applicable):	
	Liquefaction:	2-5 m ² /100m ³	notes (if applicable):	
	Lateral Spread:	none apparent	notes (if applicable):	
	Differential lateral spread:	none apparent	notes (if applicable):	
	Ground cracks:	20-100mm/20m	notes (if applicable):	
	Damage to area:	moderate to substantial (1 in 5)	notes (if applicable):	

Building:

Current Placard Status:	green			
Along	Damage ratio:		Describe how damage ratio arrived at:	Moderate to severe damage observed
	Describe (summary):			
Across	Damage ratio:	#DIV/0!	$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$	
	Describe (summary):			
Diaphragms	Damage?:	no	Describe:	
CSWs:	Damage?:	no	Describe:	
Pounding:	Damage?:	no	Describe:	
Non-structural:	Damage?:	no	Describe:	

Recommendations

Level of repair/strengthening required:	minor structural	Describe:	as described in report	
Building Consent required:	no	Describe:		
Interim occupancy recommendations:	full occupancy	Describe:		
Along	Assessed %NBS before:		#### %NBS from IEP below	
	Assessed %NBS after:	65%	If IEP not used, please detail assessment methodology:	Quantitative
Across	Assessed %NBS before:		#### %NBS from IEP below	
	Assessed %NBS after:	65%		

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	Reg Stillwell - Residents lounge	Unit:	No:	Street:	Reviewer:	Alistair Boyce
Building Address:	Reg Stillwell Place				CPEng No:	209860
Legal Description:					Company:	Opus International
					Company project number:	6-OUCCC.84
					Company phone number:	03 3635400
		Degrees	Min	Sec	Date of submission:	25/10/2013
GPS south:					Inspection Date:	23/12/2011
GPS east:					Revision:	Final V4
Building Unique Identifier (CCC):	PRO 1320-002				Is there a full report with this summary?	yes

Site

Site slope:	flat	Max retaining height (m):	
Soil type:	silty sand	Soil Profile (if available):	
Site Class (to NZS1170.5):	D	If Ground improvement on site, describe:	
Proximity to waterway (m, if <100m):			
Proximity to clifftop (m, if < 100m):		Approx site elevation (m):	
Proximity to cliff base (m,if <100m):			

Building

No. of storeys above ground:	1	single storey = 1	Ground floor elevation (Absolute) (m):	0.00
Ground floor split?	no		Ground floor elevation above ground (m):	
Storeys below ground:	0		if Foundation type is other, describe:	
Foundation type:	strip footings	height from ground to level of uppermost seismic mass (for IEP only) (m):	3	
Building height (m):	3.00		Date of design:	1965-1976
Floor footprint area (approx):				
Age of Building (years):	39			
Strengthening present?	no		If so, when (year)?	
Use (ground floor):	multi-unit residential		And what load level (%g)?	
Use (upper floors):	multi-unit residential		Brief strengthening description:	
Use notes (if required):				
Importance level (to NZS1170.5):	IL2			

Gravity Structure

Gravity System:	load bearing walls	rafter type, purlin type and cladding	Timber purlins over gang nailed trusses
Roof:	timber framed	describe sytem	
Floors:	other (note)	overall depth x width (mm x mm)	
Beams:	cast-insitu concrete	typical dimensions (mm x mm)	
Columns:	other (note)	thickness (mm)	
Walls:	partially filled concrete masonry		

Lateral load resisting structure

Lateral system along:	lightweight timber framed walls	Note: Define along and across in detailed report!	note typical wall length (m)	
Ductility assumed, μ :	1.25		estimate or calculation?	
Period along:	0.24		estimate or calculation?	
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):				
Lateral system across:	lightweight timber framed walls		note typical wall length (m)	
Ductility assumed, μ :	1.25		estimate or calculation?	
Period across:	0.24		estimate or calculation?	
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):				

Separations:

north (mm):		leave blank if not relevant
east (mm):		
south (mm):		
west (mm):		

Non-structural elements

Stairs:	other (specify)	describe:	None
Wall cladding:	other heavy	describe:	Concrete block veneer
Roof Cladding:	Metal	describe:	
Glazing:	aluminium frames		
Ceilings:	strapped or direct fixed		gib ceiling
Services(list):			

Available documentation

Architectural:	full	original designer name/date:	Christchurch City Council
Structural:	full	original designer name/date:	Christchurch City Council
Mechanical:	none	original designer name/date:	
Electrical:	none	original designer name/date:	
Geotech report:	none	original designer name/date:	

Damage

Site: (refer DEE Table 4-2)	Site performance:	Poor	Describe damage:	
	Settlement:	0-25mm	notes (if applicable):	
	Differential settlement:	1:150 or more	notes (if applicable):	
	Liquefaction:	2-5 m ² /100m ³	notes (if applicable):	
	Lateral Spread:	none apparent	notes (if applicable):	
	Differential lateral spread:	none apparent	notes (if applicable):	
	Ground cracks:	20-100mm/20m	notes (if applicable):	
	Damage to area:	moderate to substantial (1 in 5)	notes (if applicable):	

Building:

Current Placard Status:	green		
Along	Damage ratio:		Describe how damage ratio arrived at:
	Describe (summary):		
Across	Damage ratio:	#DIV/0!	$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
	Describe (summary):		
Diaphragms	Damage?:	no	Describe:
CSWs:	Damage?:	no	Describe:
Pounding:	Damage?:	no	Describe:
Non-structural:	Damage?:	no	Describe:

Recommendations

Level of repair/strengthening required:	minor structural	Describe:	as described in report
Building Consent required:	no	Describe:	
Interim occupancy recommendations:	full occupancy	Describe:	
Along	Assessed %NBS before:		#### %NBS from IEP below
	Assessed %NBS after:	46%	If IEP not used, please detail assessment methodology:
Across	Assessed %NBS before:		#### %NBS from IEP below
	Assessed %NBS after:	46%	



Opus International Consultants Ltd
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400
f: +64 3 365 7858
w: www.opus.co.nz