

## CHRISTCHURCH CITY COUNCIL

PRK\_1099\_BLDG\_007 EQ2

Spreydon Domain – Pavilion & Toilets

33 Domain Terrace, Spreydon



### QUALITATIVE ASSESSMENT REPORT FINAL

- Rev B
- 27 September 2012



**CHRISTCHURCH CITY COUNCIL**  
PRK\_1099\_BLDG\_007 EQ2  
Spreydon Domain – Pavilion and Toilet  
33 Domain Tce, Spreydon

- Rev B
- 27 September 2012

---

Sinclair Knight Merz  
142 Sherborne Street  
Saint Albans  
PO Box 21011, Edgeware  
Christchurch, New Zealand  
Tel: +64 3 940 4900  
Fax: +64 3 940 4901  
Web: [www.skmconsulting.com](http://www.skmconsulting.com)

**COPYRIGHT:** The concepts and information contained in this document are the property of Sinclair Knight Merz Limited. Use or copying of this document in whole or in part without the written permission of Sinclair Knight Merz constitutes an infringement of copyright.

**LIMITATION:** This report has been prepared on behalf of and for the exclusive use of Sinclair Knight Merz Limited's Client, and is subject to and issued in connection with the provisions of the agreement between Sinclair Knight Merz and its Client. Sinclair Knight Merz accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.



## Contents

<b>1. Executive Summary</b>	<b>1</b>
1.1. Background	1
1.2. Key Damage Observed	1
1.3. Critical Structural Weaknesses	2
1.4. Indicative Building Strength (from IEP and CSW assessment)	2
1.5. Recommendations	2
<b>2. Introduction</b>	<b>3</b>
<b>3. Compliance</b>	<b>4</b>
3.1. Canterbury Earthquake Recovery Authority (CERA)	4
3.2. Building Act	5
3.3. Christchurch City Council Policy	6
3.4. Building Code	7
<b>4. Earthquake Resistance Standards</b>	<b>8</b>
<b>5. Building Details</b>	<b>10</b>
5.1. Building description	10
5.2. Gravity Load Resisting system	10
5.3. Seismic Load Resisting system	10
5.4. Geotechnical Conditions	10
<b>6. Damage Summary</b>	<b>12</b>
<b>7. Initial Seismic Evaluation</b>	<b>13</b>
7.1. The Initial Evaluation Procedure Process	13
7.2. Design Criteria and Limitations	15
7.3. Survey	15
7.4. Critical Structural Weaknesses	15
7.5. Qualitative Assessment Results	16
<b>8. Further Investigation</b>	<b>17</b>
<b>9. Conclusion</b>	<b>18</b>
<b>10. Limitation Statement</b>	<b>19</b>
<b>11. Appendix 1 – Photos</b>	<b>20</b>
<b>12. Appendix 2 – IEP Reports</b>	<b>25</b>
<b>13. Appendix 3 – CERA Standardised Report Form</b>	<b>32</b>
<b>14. Appendix 4 – Geotechnical Desktop Study</b>	<b>34</b>



## Document history and status

Revision	Date issued	Reviewed by	Approved by	Date approved	Revision type
A	28/08/2012	James Carter	N Calvert	28/08/2012	Draft for Client Approval
B	27/09/2012	N Calvert	N Calvert	25/09/2012	Final Issue

## Distribution of copies

Revision	Copy no	Quantity	Issued to
A	1	1	CCC
B	1	1	CCC

<b>Printed:</b>	27 September 2012
<b>Last saved:</b>	27 September 2012 03:08 PM
<b>File name:</b>	ZB01276.111.PRK_1099_BLDG_007 EQ2.Qualitative.Assmt.B.docx
<b>Author:</b>	Oliver Kingsnorth
<b>Project manager:</b>	Nick Calvert
<b>Name of organisation:</b>	Christchurch City Council
<b>Name of project:</b>	Christchurch City Council Structures Panel
<b>Name of document:</b>	PRK_1099_BLDG_007 EQ2 – Spreydon Domain – BLD 7 Toilets and Pavilion
<b>Document version:</b>	B
<b>Project number:</b>	ZB01276.111

# 1. Executive Summary

## 1.1. Background

A Qualitative Assessment was carried out on Building 7, Pavilion and Toilets, located at Spreydon Domain. The building is a masonry structure with a timber framed roof. An aerial photograph illustrating the location of Building 7 is shown below in Figure 1. A detailed description outlining the building age and construction type is given in Section 5 of this report.



### ■ Figure 1 Aerial Photograph of Spreydon Domain showing the location of Building 7

The qualitative assessment includes a summary of the building damage as well as an initial assessment of the current Seismic Capacity compared with current seismic code loads using the Initial Evaluation Procedure (IEP).

This Qualitative report for the building structure is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspection on 22 May 2012 and structural drawings.

## 1.2. Key Damage Observed

Key damage observed includes:-

- Minor cracking to the masonry walls, particularly adjacent to windows and doorways



- Separation between original structure and extensions to the west

### **1.3. Critical Structural Weaknesses**

No critical structural weaknesses have been identified.

### **1.4. Indicative Building Strength (from IEP and CSW assessment)**

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the building's original capacity has been assessed to be in the order of 76%NBS. Damage to the structure does not significantly alter the strength of the building and therefore the post earthquake capacity remains the same.

The building has been assessed to have a seismic capacity in the order of 76% NBS and is therefore not earthquake prone.

### **1.5. Recommendations**

No further investigation work is deemed necessary.

- a) The current placard status of the building should remain as green 1. Since there was no placard visible on the building it is assumed that the placard status was green
- b) We consider that barriers around the building are not necessary.

## 2. Introduction

Sinclair Knight Merz was engaged by Christchurch City Council to prepare a qualitative assessment report for the building located at 33 Domain Terrace, Spreydon following the magnitude 6.3 earthquake which occurred in the afternoon of the 22nd of February 2011 and the subsequent aftershocks.

The Qualitative Assessment uses the methodology recommended in the Engineering Advisory Group document “Guidance on Detailed Engineering Evaluation of Earthquake affected Non-residential Buildings in Canterbury”. The qualitative assessment broadly includes a summary of the building damage as well as an initial assessment of the likely current Seismic Capacity compared with current seismic code requirements.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

This report describes the structural damage observed during our inspection and indicates suggested remediation measures. The inspection was undertaken from floor levels and was a visual inspection only. Our report reflects the situation at the time of the inspection and does not take account of changes caused by any events following our inspection. A full description of the basis on which we have undertaken our visual inspection is set out in Section 7.2.

The NZ Society for Earthquake Engineering (NZSEE) Initial Evaluation Procedure (IEP) was used to assess the likely performance of the building in a seismic event relative to the New Building Standard (NBS). 100% NBS is equivalent to the strength of a building that fully complies with current codes. This includes a recent increase of the Christchurch seismic hazard factor from 0.22 to 0.3<sup>1</sup>.

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Some construction drawings were made available, and these have been considered in our evaluation of the building. The building description below is based on a review of the drawings and our visual inspections.

---

<sup>1</sup> <http://www.dbh.govt.nz/seismicity-info>





### **3. Compliance**

This section contains a summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

#### **3.1. Canterbury Earthquake Recovery Authority (CERA)**

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

##### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

##### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses





- The extent of any earthquake damage

### **3.2. Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

#### **3.2.1. Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

#### **3.2.2. Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’. Regarding seismic capacity ‘as near as reasonably practicable’ has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

#### **3.2.3. Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

#### **3.2.4. Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.



### **3.2.5. Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **3.2.6. Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

### **3.3. Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4<sup>th</sup> September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone. Council recognises that it may not be practicable for some repairs to meet that target. The council will work closely with building owners to achieve sensible, safe outcomes;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 34%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.



### **3.4. Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a) Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b) Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

## 4. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 2 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

■ **Figure 2: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below provides an indication of the risk of failure for an existing building with a given percentage NBS, relative to the risk of failure for a new building that has been designed to meet current Building Code criteria (the annual probability of exceedance specified by current earthquake design standards for a building of 'normal' importance is 1/500, or 0.2% in the next year, which is equivalent to 10% probability of exceedance in the next 50 years).



■ **Table 1: %NBS compared to relative risk of failure**

<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

## **5. Building Details**

### **5.1. Building description**

Building 7 is a concrete block structure with a timber framed roof and corrugated steel sheeting. The building houses toilets, a shower room and two changing rooms. The masonry walls are founded on a strip footing and the building has an internal concrete floor slab. The building has internal concrete block and timber framed walls. An internal ceiling is present on the east side of the structure and underside of the purlins is lined with plywood at the west end of the building.

It appears as though the building was constructed in three phases. The east half looks to be the oldest with two extensions added to the west end of the building at different times.

A water tank was located on the apex of roof half way along the length of the building. The water tank is held in place with timber framing.

The age of the building is unknown. Drawings received from the Christchurch City Council indicate that a block wall extension was added to the west side of the building in October 1999.

Photos of the structure can be found in Appendix 1 – Photos.

### **5.2. Gravity Load Resisting system**

The timber roof framing spans between masonry walls which transmit gravity load to ground in bearing.

### **5.3. Seismic Load Resisting system**

Lateral load in the roof is transmitted to the masonry walls which resist in plane seismic loading in shear and span between perpendicular walls in out-of-plane loading. It is anticipated that some out of plane loading will be resisted through cantilever action in the walls. The roof appears to have limited diaphragm capacity.

### **5.4. Geotechnical Conditions**

A geotechnical desktop study was carried out for this site. The main conclusions from this report are:

- The site has been assessed as NZS1170.5 Class D (deep or soft soil) from adjacent borehole logs.
- It is expected that the ultimate bearing capacity of a shallow square pad footing to be in the order of 300 kPa. However, these may be revised by a site specific investigation.
- Liquefaction risk is low to moderate at this site.



Unless a change of use is intended for the site we do not believe that any further geotechnical investigations are required. Specific ground investigation should be undertaken if significant alterations or new structures are proposed. If any excavations are required on the site further investigation of the potential for contamination should be undertaken. The full geotechnical desktop study can be found in Appendix 4.





## 6. Damage Summary

SKM undertook an inspection of the building from floor level on 23 May 2012.

The following areas of damage were observed at the time of the inspection:

- 1) Vertical hairline cracking was observed in the mortar at either end of the lintel over window and door openings in the south and west walls of the building. (see Photo 3)
  - 2) Hairline separation was noted between the internal and perimeter masonry walls. (see Photo 4)
  - 3) Hairline cracking was observed in the window sill and wall beneath the window at the centre of the southern wall. (see Photo 5 and Photo 6)
  - 4) Hairline cracking was observed adjacent to the windows and doors in the eastern half of the structure. This cracking looks to be existing. (see Photo 7)
  - 5) Approximately 0.8mm separation was noted on the exterior of the southern wall at the junction between the eastern structure and the extension to the west. The junction is located at the centre of the building. Separation extends the full height of the wall and in to the footing (see Photo 8, Photo 9 and Photo 10). Separation was also observed between the internal floor slab of the shower room and the footing for the wall dividing the shower room and adjacent change room at this location (see Photo 11 and Photo 12). Separation between sections of the wall had been filled with a sealant on the interior of the building and on the exterior of the northern wall (see Photo 13 and Photo 14).
  - 6) Separation was noted between the most recent extension at the west end of the building and the adjacent structure. Separation was recorded at 0.5mm in width and the top of the walls and hairline in width at the base. (see Photo 15 and Photo 16)
  - 7) The timber framed structure supporting the water tank on the roof of the building appeared to be leaning to the west. One panel at the base of the north side of the structure had been dislodged. (see Photo 17)
  - 8) Some damage to paint and minor separation was observed where the internal timber framing meets the perimeter masonry walls. This damage is non-structural. (see Photo 18)
- 1)

## 7. Initial Seismic Evaluation

### 7.1. The Initial Evaluation Procedure Process

This section covers the initial seismic evaluation of the building as detailed in the NZSEE 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes'. The IEP grades buildings according to their likely performance in a seismic event. The procedure is not yet recognised by the NZ Building Code but is widely used and recognised by the Christchurch City Council as the preferred method for preliminary seismic investigations of buildings<sup>2</sup>.

The IEP is a coarse screening process designed to identify buildings that are likely to be earthquake prone. The IEP process ranks buildings according to how well they are likely to perform relative to a new building designed to current earthquake standards, as shown in **Error! Reference source not found.** The building grade is indicated by the percent of the required New Building Standard (%NBS) strength that the building is considered to have. A building is earthquake prone for the purposes of this Act if, having regard to its condition and to the ground on which it is built, and because of its construction, the building—

- a) will have its ultimate capacity exceeded in a moderate earthquake (as defined in the regulations); and
- b) would be likely to collapse causing—
  - i. injury or death to persons in the building or to persons on any other property; or
  - ii. damage to any other property.

A moderate earthquake is defined as 'in relation to a building, an earthquake that would generate shaking at the site of the building that is of the same duration as, but that is one-third as strong as, the earthquake shaking (determined by normal measures of acceleration, velocity and displacement) that would be used to design a new building at the site.'

An earthquake prone building will have an increased risk that its strength will be exceeded due to earthquake actions of approximately 10 times (or more) than that of a building having a capacity in excess of 100% NBS (refer Table 1)<sup>3</sup>. Buildings in Christchurch City that are identified as being earthquake prone are required by law to be followed up with a detailed assessment and strengthening work within 30 years of the owner being notified that the building is potentially earthquake prone<sup>4</sup>.

---

<sup>2</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

<sup>3</sup> NZSEE June 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p 2-13

<sup>4</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

**Table 2: IEP Risk classifications**

Description	Grade	Risk	%NBS	Structural performance
Low risk building	A+	Low	> 100	Acceptable. Improvement may be desirable.
	A		100 to 80	
	B		80 to 67	
Moderate risk building	C	Moderate	67 to 33	Acceptable legally. Improvement recommended.
High risk building	D	High	33 to 20	Unacceptable. Improvement required.
	E		< 20	

The IEP is a simple desktop study that is useful for risk management. No detailed calculations are done and so it relies on an inspection of the building and its plans to identify the structural members and describe the likely performance of the building in a seismic event. A review of the plans is also likely to identify any critical structural weaknesses. The IEP assumes that the building was properly designed and built according to the relevant codes at the time of construction. The IEP method rates buildings based on the code used at the time of construction and some more subjective parameters associated with how the building is detailed and so it is possible that %NBS derived from different engineers may differ.

This assessment describes only the likely seismic Ultimate Limit State (ULS) performance of the building. The ULS is the level of earthquake that can be resisted by the building without collapse or other forms of failure. The IEP does not attempt to estimate Serviceability Limit State (SLS) performance of the building, or the level of earthquake that would start to cause damage to the building<sup>5</sup>. This assessment concentrates on matters relating to life safety as damage to the building is a secondary consideration.

The NZ Building Code describes that the relevant codes for determining %NBS are primarily:

- AS/NZS 1170 Structural Design Actions
- NZS 3101:2006 Concrete Structures Standard
- NZS 3404:1997 Steel Structures Standard
- NZS4230:2004 Design of Reinforced Concrete Masonry Structures
- NZS 3603:1993 Timber Structures Standard

NZS 3604:2011 Timber Framed Buildings

<sup>5</sup> NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p2-9



## **7.2. Design Criteria and Limitations**

Following our inspection on the 22 May 2012, SKM carried out a preliminary structural review. The structural review was undertaken using the available information which was as follows:

- SKM site measurements and inspection findings of the building. Please note no intrusive investigations were undertaken.
- Architectural drawings of an extension to the west side of the building were made available

The design criteria used to undertake the assessment include:

- Standard design assumptions for typical office and factory buildings as described in AS/NZS1170.0:2002
  - 50 year design life, which is the default NZ Building Code design life.
  - Structure importance level 2. This level of importance is described as 'normal' with medium or considerable consequence of failure.
  - Ductility level of 1.25, based on our assessment and code requirements at the time of design. The structure primarily relies on masonry walls which are expected to be at least partially reinforced due to the age of construction.
  - Site hazard factor,  $Z = 0.3$ , NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011.

This IEP was based on our visual inspection of the building. Since it is not a full design and construction review, it has the following limitations:

- It is not likely to pick up on any original design or construction errors (if they exist)
- Other possible issues that could affect the performance of the building such as corrosion and modifications to the building will not be identified
- The IEP deals only with the structural aspects of the building. Other aspects such as building services are not covered.
- The IEP does not involve a detailed analysis or an element by element code compliance check.

## **7.3. Survey**

There was no visible settlement of the structure, nor was there any significant ground movement issues around the building. The building is adjacent to land which is zoned TC2 under the CERA Residential Technical Categories Map. The combination of these factors means that we do not recommend that any survey be undertaken at this point.

## **7.4. Critical Structural Weaknesses**

No critical structural weaknesses for the building were observed during our visual inspection.

## 7.5. Qualitative Assessment Results

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The building's capacity, expressed as a percentage of new building standard (%NBS), are in the order of that shown below in Table 3. This capacity is subject to confirmation by a quantitative analysis.

**Table 3: Qualitative Assessment Summary**

<u>Item</u>	<u>%NBS</u>
Toilets	76

Our qualitative assessment found that the building is likely to be classed as a 'Low Risk Building' (capacity greater than 67% of NBS). The full IEP assessment form is detailed in Appendix 2 – IEP Reports.



## **8. Further Investigation**

No further investigation is deemed necessary for this building.



## 9. Conclusion

A qualitative assessment was carried out for Building 7 located at Spreydon Domain. Some minor cracking was noted to the structure together with separation between where extensions to the building have been added. The building has been assessed to have a seismic capacity in the order of 76% NBS and is therefore not earthquake prone and is likely to be classified as a 'Low Risk Building' (capacity greater than 67% of NBS).

No further investigation work is deemed necessary.

- a) The current placard status of the building should remain as Green 1. Since there was no placard visible on the building it is assumed that the placard status was Green.
- b) We consider that barriers around the building are not necessary.





## 10. Limitation Statement

This report has been prepared on behalf of, and for the exclusive use of, SKM's client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and the Client. It is not possible to make a proper assessment of this report without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to, and the assumptions made by, SKM. The report may not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, in the event of any liability, SKM's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited in as set out in the terms of the engagement with the Client.

It is not within SKM's scope or responsibility to identify the presence of asbestos, nor the responsibility of SKM to identify possible sources of asbestos. Therefore for any property pre-dating 1989, the presence of asbestos materials should be considered when costing remedial measures or possible demolition.

There is a risk of further movement and increased cracking due to subsequent aftershocks or settlement.

Should there be any further significant earthquake event, of a magnitude 5 or greater, it will be necessary to conduct a follow-up investigation, as the observations, conclusions and recommendations of this report may no longer apply. Earthquake of a lower magnitude may also cause damage, and SKM should be advised immediately if further damage is visible or suspected.

## 11. Appendix 1 – Photos



Photo 1: The east and south elevations of the building



Photo 2: The north and east elevations of the building



Photo 3: Typical vertical cracking in the mortar at each end of the lintels of door and window openings



Photo 4: Typical separation between internal and perimeter masonry walls



Photo 5: Elevation on the window at the centre of the southern wall



Photo 6: Cracking in the window sill and wall beneath the central window




Photo 7: Typical cracking found adjacent to windows and doors in the eastern half of the building



Photo 8: Elevation on the junction between the original structure and the extensions to the west



Photo 9: Detail of the junction showing separation between structures



Photo 10: Detail of the footing at the junction showing separation



Photo 11: Separation between the internal floor slab in the shower room and the footing the masonry wall to the east



Photo 12: Cracking in the internal floor slab over the footing to the east of the shower room



Photo 13: Typical detail of sealant used on the interior of the building at the central junction between structures



Photo 14: Detail of the sealant on the exterior of the north wall at the central junction between structures



Photo 15: Elevation on the junction between the western most extension and the adjacent structure



Photo 16: Detail of the separation between the westernmost extension and the adjacent structure



Photo 17: Timber framing for the water tank fixed to the roof of the building. Note damage to lower plank and lean in the structure



Photo 18: Typical damage to the paint at the junction between internal timber framing and the perimeter masonry walls



## **12. Appendix 2 – IEP Reports**




Building Name:	Spreydon Domain - Building 7 - Pavilion and Toilets	Ref.	ZB01276.111
Location:	33 Domain Tce, Spreydon, Christchurch	By	OAK
		Date	28/08/2012

## Step 1 - General Information

### 1.1 Photos (attach sufficient to describe building)



### 1.2 Sketch of building plan



Only masonry walls shown

### 1.3 List relevant features

Building 2 is a concrete block structure with a timber framed roof and corrugated steel sheeting. The building houses toilets, a shower room and two changing rooms. The masonry walls are founded on a strip footing and the building has an internal concrete floor slab. The building has internal concrete block and timber framed walls. An internal ceiling is present on the east side of the structure and underside of the purlins is lined with plywood at the west end of the building. Reinforcement is not shown on the drawings made available, however it is anticipated that the walls are reinforced and partially filled.

It appears as though the building was constructed in three phases. The east half looks to be the oldest with two extensions added to the west end of the building at different times.

A water tank was located on the apex of roof half way along the length of the building. The water tank is held in place with timber framing.

The age of the building is unknown. Drawings received from the Christchurch City Council indicate that a block wall extension was added to the west side of the building in October 1999.

### 1.4 Note information sources

Tick as appropriate

- Visual Inspection of Exterior
- Visual Inspection of Interior
- Drawings (note type)
- Specifications
- Geotechnical Reports
- Other (list)

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

Architectural

--

**Table IEP-2 Initial Evaluation Procedure – Step 2**  
(Refer Table IEP - 1 for Step 1; Table IEP - 3 for Step 3, Table IEP - 4 for Steps 4, 5 and 6)

Building Name:	<u>Spreydon Domain - Building 7 - Pavilion and Toilets</u>	Ref.	<u>ZB01276.111</u>
Location:	<u>33 Domain Tce, Spreydon, Christchurch</u>	By	<u>OAK</u>
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	<u>28/08/2012</u>
( Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

### Step 2 - Determination of (%NBS)<sub>b</sub>

### 2.1 Determine nominal (%NBS) = (%NBS)<sub>nom</sub>

Seismic Zone;			
Pre 1935			See also notes 1, 3
1935-1965			
1965-1976	A		
	B		
	C		See also note 2
1976-1992	A		
	B		
	C		
1992-2004			

### b) Soil Type

From NZS1170.5:2004, Cl 3.1.3

A or B Rock  
C Shallow Soil  
D Soft Soil  
E Very Soft Soil

<input type="radio"/>
<input type="radio"/>
<input checked="" type="radio"/>
<input type="radio"/>

From NZS4203:1992, Cl 4.6.2.2  
(for 1992 to 2004 only and only if known)

a) Rigid  
b) Intermediate

A diagram showing a vertical stack of four rectangular boxes. The second box from the top contains a solid black dot. To the right of the stack, the text "N-A" is written.

**c) Estimate Period, T**

building Ht =	3	meters
---------------	---	--------

Can use following:

$T = 0.09h_n^{0.75}$	for moment-resisting concrete frames
$T = 0.14h_n^{0.75}$	for moment-resisting steel frames
$T = 0.08h_n^{0.75}$	for eccentrically braced steel frames
$T = 0.06h_n^{0.75}$	for all other frame structures
$T = 0.09h_n^{0.75}/A_c^{0.5}$	for concrete shear walls
$T \leq 0.4\text{sec}$	for masonry shear walls

Where

$h_n$  = height in m from the base of the structure to the uppermost seismic weight or mass.

$A_c = \sum A_i (0.2 + L_{wi}/h_n)^2$

$A_i$  = cross-sectional shear area of shear wall  $i$  in the first storey of the building, in  $m^2$

$L_{wi}$  = length of shear wall  $i$  in the first storey in the direction parallel to the applied forces, in m

with the restriction that  $L_{wi}/h_n$  shall not exceed 0.9

	Longitudinal	Transverse
Ac =		m2
	○ MRCF	○ MRCF
	○ MRSF	○ MRSF
	○ EBSF	○ EBSF
	○ Others	○ Others
	○ CSW	○ CSW
	● MSW	● MSW

Longitudinal	Transverse
0.4	0.4

Seconds

d) (%NBS )nom determined from Figure 3.3

**Note 1:** For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.25.

For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.33 - Zone A or 1.2 - Zone B

**Note 2:** For reinforced concrete buildings designed between 1976 -1984  
(%NBS )nom by 1.2

**Note 3:** For buildings designed prior to 1935 multiply (%NBS)nom by 0.8 except for Wellington where the factor may be taken as 1.

		Factor
No	<input type="checkbox"/>	1
No	<input type="checkbox"/>	1
No	<input type="checkbox"/>	1
No	<input type="checkbox"/>	1
No	<input type="checkbox"/>	1

<b>Longitudinal</b>	<b>16.5</b>	(%NBS) <sub>nom</sub>
<b>Transverse</b>	<b>16.5</b>	(%NBS) <sub>nom</sub>

Longitudinal	16.5	(%NBS) <sub>nom</sub>
Transverse	16.5	(%NBS) <sub>nom</sub>

Continued over page

Building Name: Spreydon Domain - Building 7 - Pavilion and Toilets  
 Location: 33 Domain Tce, Spreydon, Christchurch  
 Direction Considered: **Longitudinal & Transverse**  
 (Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)

Ref. ZB01276.111  
 By OAK  
 Date 28/08/2012

## 2.2 Near Fault Scaling Factor, Factor A

If  $T < 1.5\text{sec}$ , Factor A = 1

### a) Near Fault Factor, $N(T,D)$

(from NZS1170.5:2004, Cl 3.1.6)

1

### b) Near Fault Scaling Factor

=  $1/N(T,D)$ 

Factor A	1.00
----------	------

## 2.3 Hazard Scaling Factor, Factor B

Select Location Christchurch

### a) Hazard Factor, $Z$ , for site

(from NZS1170.5:2004, Table 3.3)

Z = 0.3

Z 1992 = 0.8

Auckland 0.6 Palm Nth 1.2

Wellington 1.2 Dunedin 0.6

Christchurch 0.8 Hamilton 0.67

### b) Hazard Scaling Factor

For pre 1992 =  $1/Z$ For 1992 onwards =  $Z 1992/Z$ 

#

(Where Z 1992 is the NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Factor B	3.33
----------	------

## 2.4 Return Period Scaling Factor, Factor C

### a) Building Importance Level

(from NZS1170.0:2004, Table 3.1 and 3.2)

2

### b) Return Period Scaling Factor from accompanying Table 3.1

Factor C	1.00
----------	------

## 2.5 Ductility Scaling Factor, D

### a) Assessed Ductility of Existing Structure, $\mu$

(shall be less than maximum given in accompanying Table 3.2)

Longitudinal 1.25

 $\mu$  Maximum = 6

Transverse 1.25

 $\mu$  Maximum = 6

### b) Ductility Scaling Factor

For pre 1976

=  $k_{\mu}$ 

For 1976 onwards

= 1

(where  $k_{\mu}$  is NZS1170.5:2005 Ductility Factor, from accompanying Table 3.3)

Longitudinal	Factor D	1.00
Transverse	Factor D	1.00

## 2.6 Structural Performance Scaling Factor, Factor E

Select Material of Lateral Load Resisting System

Longitudinal

Transverse

Masonry Block	▼
Masonry Block	▼

### a) Structural Performance Factor, $S_p$

from accompanying Figure 3.4

Longitudinal

 $S_p$ 

0.90

Transverse

 $S_p$ 

0.90

### b) Structural Performance Scaling Factor

Longitudinal

 $1/S_p$ 

Factor E

1.11

Transverse

 $1/S_p$ 

Factor E

1.11

## 2.7 Baseline %NBS for Building, $(\%NBS)_b$

(equals  $(\%NBS)_{nom} \times A \times B \times C \times D \times E$ )

Longitudinal	61.1	$(\%NBS)_b$
Transverse	61.1	$(\%NBS)_b$

Table IEP-3 Initial Evaluation Procedure – Step 3

(Refer Table IEP - 1 for Step 1; Table IEP - 2 for Step 2, Table IEP - 4 for Steps 4, 5 and 6)

Building Name: Spreydon Domain - Building 7 - Pavilion and Toilets	Ref. ZB01276.111
Location: 33 Domain Tce, Spreydon, Christchurch	By OAK
Direction Considered: <b>a) Longitudinal</b>	Date 28/08/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)	

**Step 3 - Assessment of Performance Achievement Ratio (PAR)**

(Refer Appendix B - Section B3.2)

**Critical Structural Weakness****Effect on Structural Performance**

(Choose a value - Do not interpolate)

**Building Score****3.1 Plan Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A **3.2 Vertical Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B **3.3 Short Columns**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C **3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

		Factor D1 <input type="text" value="1"/>		
		Severe	Significant	Insignificant
Table for Selection of Factor D1		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	Separation	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

		Factor D2 <input type="text" value="1"/>		
		Severe	Significant	Insignificant
Table for Selection of Factor D2		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	Separation	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1
Height Difference 2 to 4 Storeys		<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys		<input type="radio"/> 1	<input type="radio"/> 1	<input type="radio"/> 1

Factor D 

(Set D = lesser of D1 and D2 or..)

set D = 1.0 if no prospect of pounding)

**3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)**

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E **3.6 Other Factors**

For &lt; 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F 

Record rationale for choice of Factor F:

The building is a single storey structure with regular internal masonry walls.

**3.7 Performance Achievement Ratio (PAR)**  
 (equals A x B x C x D x E x F)
PAR

Table IEP-3

## Initial Evaluation Procedure – Step 3

(Refer Table IEP - 1 for Step 1; Table IEP - 2 for Step 2, Table IEP - 4 for Steps 4, 5 and 6)

Building Name:	Spreydon Domain - Building 7 - Pavilion and Toilets	Ref.	ZB01276.111
Location:	33 Domain Tce, Spreydon, Christchurch	By	OAK
Direction Considered:	<b>b) Transverse</b>	Date	28/08/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

## Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

## Critical Structural Weakness

Effect on Structural Performance  
(Choose a value - Do not interpolate)Building  
Score

## 3.1 Plan Irregularity

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A 

## 3.2 Vertical Irregularity

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B 

## 3.3 Short Columns

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C 

## 3.4 Pounding Potential

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

Factor D1 

Table for Selection of Factor D1

	Severe	Significant	Insignificant
Separation	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2 

Table for Selection of Factor D2

	Severe	Significant	Insignificant
Separation	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input type="radio"/> 1

Factor D (Set D = lesser of D1 and D2 or..  
set D = 1.0 if no prospect of pounding)

## 3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E 

## 3.6 Other Factors

For &lt; 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F 

Record rationale for choice of Factor F:

The building is a single storey structure with regular internal masonry walls.

## 3.7 Performance Achievement Ratio (PAR)

(equals A x B x C x D x E x F)

PAR

Building Name:	Spreydon Domain - Building 7 - Pavilion and Toilets	Ref.	ZB01276.111
Location:	33 Domain Tce, Spreydon, Christchurch	By	OAK
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	28/08/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 4 - Percentage of New Building Standard (%NBS)**

	Longitudinal	Transverse
<b>4.1 Assessed Baseline (%NBS)<sub>b</sub></b> (from Table IEP - 1)	<b>61</b>	<b>61</b>
<b>4.2 Performance Achievement Ratio (PAR)</b> (from Table IEP - 2)	<b>1.25</b>	<b>1.25</b>
<b>4.3 PAR x Baseline (%NBS)<sub>b</sub></b>	<b>76</b>	<b>76</b>
<b>4.4 Percentage New Building Standard (%NBS)</b> (Use lower of two values from Step 4.3)		<b>76</b>

**Step 5 - Potentially Earthquake Prone?**

(Mark as appropriate)

%NBS ≤ 33

**NO****Step 6 - Potentially Earthquake Risk?**


%NBS &lt; 67

**NO****Step 7 - Provisional Grading for Seismic Risk based on IEP**

Seismic Grade

**B**

Evaluation Confirmed by



Signature

James Carter

Name

1017618

CPEng. No

**Relationship between Seismic Grade and % NBS :**

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	80 to 67	67 to 33	33 to 20	< 20



## **13. Appendix 3 – CERA Standardised Report Form**



<b>Location</b>	
Building Name: PRK 1099 BLDG 007 EQ2	Unit No: Street
Building Address: Building 7 - Pavilion and Toilet	33 Domain Tce, Spreydon
Legal Description:	
GPS south:	Degrees Min Sec
GPS east:	
Building Unique Identifier (CCC):	
Reviewer: James Carter	CPEng No: 1017618
Company: SKM	Company project number: ZB01276.111
Company phone number: +64 3 940 4900	
Date of submission:	
Inspection Date: 23/05/2012	
Revision:	
Is there a full report with this summary?	

<b>Site</b>	Site slope: flat	Max retaining height (m):
	Soil type:	Soil Profile (if available):
Site Class (to NZS1170.5): D		
Proximity to waterway (m, if <100m):		If Ground improvement on site, describe:
Proximity to cliff top (m, if < 100m):		
Proximity to cliff base (m, if <100m):		Approx site elevation (m):

<b>Building</b>	No. of storeys above ground: 1	single storey = 1	Ground floor elevation (Absolute) (m):
	Ground floor split? no		Ground floor elevation above ground (m):
	Storeys below ground: 0		
	Foundation type: strip footings		if Foundation type is other, describe:
	Building height (m): 3.00	height from ground to level of uppermost seismic mass (for IEP only) (m): 3	
	Floor footprint area (approx):		Date of design: 1976-1992
	Age of Building (years): 30		
	Strengthening present? no		If so, when (year)?
	Use (ground floor): other (specify)		And what load level (%)?
	Use (upper floors):		Brief strengthening description:
	Use notes (if required): Amenities		
	Importance level (to NZS1170.5): IL2		

<b>Gravity Structure</b>	Gravity System: load bearing walls		
	Roof: timber framed	rafter type, purlin type and cladding:	Timber rafters, timber purlins, and corrugated steel roof sheeting
	Floors: concrete flat slab	slab thickness (mm):	
	Beams:		
	Columns:		
	Walls: partially filled concrete masonry	thickness (mm):	200

<b>Lateral load resisting structure</b>	Lateral system along: partially filled CMU	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): 22
	Ductility assumed, $\mu$ : 1.25	0.40 from parameters in sheet	wall thickness (m): 0.2
	Period along:		estimate or calculation?
	Total deflection (ULS) (mm):		estimate or calculation?
	maximum interstorey deflection (ULS) (mm):		estimate or calculation?
	Lateral system across: partially filled CMU		note total length of wall at ground (m): 4
	Ductility assumed, $\mu$ : 1.25	0.40 from parameters in sheet	wall thickness (m): 0.2
	Period across:		estimate or calculation?
	Total deflection (ULS) (mm):		estimate or calculation?
	maximum interstorey deflection (ULS) (mm):		estimate or calculation?

<b>Separations:</b>	north (mm):	leave blank if not relevant
	east (mm):	
	south (mm):	
	west (mm):	

<b>Non-structural elements</b>	Stairs:	
	Wall cladding:	
	Roof Cladding: Metal	describe: Corrugated steel sheeting
	Glazing:	
	Ceilings: plaster, fixed	Ceiling present over eastern 3/4 of building only
	Services(list):	

<b>Available documentation</b>	Architectural: partial	original designer name/date:
	Structural: none	original designer name/date:
	Mechanical: none	original designer name/date:
	Electrical: none	original designer name/date:
	Geotech report: none	original designer name/date:

<b>Damage</b>	Site performance: 1	Describe damage:
Site: (refer DEE Table 4-2)		
Settlement: none observed		notes (if applicable):
Differential settlement: none observed		notes (if applicable):
Liquefaction: none apparent		notes (if applicable):
Lateral Spread: none apparent		notes (if applicable):
Differential lateral spread: none apparent		notes (if applicable):
Ground cracks: none apparent		notes (if applicable):
Damage to area: none apparent		notes (if applicable):

<b>Building:</b>	Current Placard Status: green	
Along	Damage ratio: 0%	Describe how damage ratio arrived at:
	Describe (summary): Damage to building has not significantly altered the strength	
Across	Damage ratio: 0%	
	Describe (summary): Damage to building has not significantly altered the strength	
Diaphragms	Damage?: no	Describe:
CSWs:	Damage?: no	Describe:
Pounding:	Damage?: no	Describe:
Non-structural:	Damage?: no	Describe:

<b>Recommendations</b>	Level of repair/strengthening required: minor non-structural	Describe: Minor cracking and separation to be sealed to prevent water ingress
	Building Consent required: no	Describe:
	Interim occupancy recommendations: full occupancy	Describe:
Along	Assessed %NBS before: 76%	%NBS from IEP below
	Assessed %NBS after: 76%	If IEP not used, please detail assessment methodology:
Across	Assessed %NBS before: 76%	%NBS from IEP below
	Assessed %NBS after: 76%	



## **14. Appendix 4 – Geotechnical Desktop Study**



## **Christchurch City Council - Structural Engineering Service**

### **Geotechnical Desk Study**

SKM project number	ZB01276
SKM project site number	111
Address	33 Domain Terrace
Report date	July 2012
Author	Chris Ritchie
Reviewer	Leah Bateman / Ross Roberts
Approved for issue	Yes

### **1. Introduction**

This report outlines the geotechnical information that Sinclair Knight Merz (SKM) has been able to source from our database and other sources in relation to the property listed above. We understand that this information will be used as part of an initial qualitative Detailed Engineering Evaluation (DEE), and will be supplemented by more detailed information and investigations to allow detailed scoping of the repair or rebuild of the building.

### **2. Scope**

This geotechnical desk top study incorporates information sourced from:

- Published geology
- Publically available borehole records
- Liquefaction records
- Aerial photography
- A preliminary site walkover

### **3. Limitations**


This report was prepared to address geotechnical issues relating to the specific site in accordance with the scope of works as defined in the contract between SKM and our Client. This report has been prepared on behalf of, and for the exclusive use of, our Client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and our Client. The findings presented in this report should not be applied to another site or another development within the same site without consulting SKM.

The assessment undertaken by SKM was limited to a desktop review of the data described in this report. SKM has not undertaken any subsurface investigations, measurement or testing of materials from the site. In preparing this report, SKM has relied upon, and presumed accurate, any information (or confirmation of the absence thereof) provided by our Client, and from other sources as described in the report. Except as otherwise stated in this report, SKM has not attempted to verify the accuracy or completeness of any such information.



This report should be read in full and no excerpts are to be taken as representative of the findings. It must not be copied in parts, have parts removed, redrawn or otherwise altered without the written consent of SKM.

#### 4. Site location




■ **Figure 1 – Site location (courtesy of LINZ <http://viewers.geospatial.govt.nz>)**

The structure is located at 33 Domain Terrace, Spreydon. Grid reference 1567863 E, 5177343 N (NZTM).




## 5. Review of available information

### 5.1 Geological maps



■ Figure 2 – Regional geological map (Forsyth et al, 2008). Site marked in red.





■ Figure 3 – Local geological map (Brown et al, 1992). Site marked in red.

The site is shown to be located on a geological boundary. The site is predominantly underlain by alluvial gravel and silt deposits from historic river flood channels. The north east of the site is underlain by alluvial sand and silts. Both deposits are part of the Springston Formation.



## 5.2 Liquefaction map



■ **Figure 4 – Liquefaction map (Cubrinovski & Taylor, 2011). Site marked in red.**

Following the 22 February 2011 event drive through reconnaissance was undertaken from 23 February until 1 March by M Cubrinovski and M Taylor of Canterbury University. Their findings show moderate to severe liquefaction on Domain Terrace. However, this observation may be an over-estimate, given the comments made by local residents (see section 5.8).



### 5.3 Aerial photography



- **Figure 5 – Aerial photography from 24 Feb 2011 (<http://viewers.geospatial.govt.nz/>)**

Aerial photography shows moderate liquefaction after the 22 Feb 2011 event, particularly on the road to the north. The absence of liquefaction to the south west (on the field) appears to correspond with the change to alluvial gravel identified in the geological maps.

### 5.4 CERA classification

A review of the LINZ website (<http://viewers.geospatial.govt.nz/>) shows that the site is:

- Zone: Green
- DBH Technical Category TC2





## 5.5 Historical land use

In reference to historical documents (e.g. Appendix A) shows that the site lies approximately 100 m south and east of land that was recorded as marshland or swamp in 1856. It is therefore possible that soft or liquefiable ground would be present near the site. However, the geological mapping (supported by absence of evidence of liquefaction on the field) suggests that any swamp deposits are likely to be to the north and east of the site.

## 5.6 Existing ground investigation data



■ **Figure 6 – Local boreholes from Project Orbit and SKM files**  
(<https://canterburyrecovery.projectorbit.com/>)

Where available logs from these investigation locations are attached to this report (Appendix B), and the results are summarised in Appendix C.



## 5.7 Council property files

Council files were not available at the time of writing this report.

## 5.8 Site walkover

An engineer from SKM undertook a site walkover on 20 May 2012.

Spreydon Domain is a flat site bound north and south by slightly elevated terraces.

The toilet block/pavilion is a masonry block building with corrugated iron roof and has a concrete slab on grade foundation. Only minor damage to land and building was observed. Paving slabs at the front of the building did exhibit minor tilting probably due to settlement of fill. In addition minor damage due to shaking was observed which included isolated hairline cracks in the masonry walls and minor oscillation gaps between the building and concrete paving.

There was no evidence of land damage at the domain site where the toilet block is situated. However there was evidence of liquefaction on Domain Terrace immediately north of the park which is slightly elevated. This was mainly settlement of fill associated with service trenches; otherwise the road was in generally undamaged condition. A nearby resident indicated only isolated instances of minor sand and silt appeared on properties along Domain Terrace as a result of earthquake events.



■ **Figure 7** Toilet and Pavilion block at Spreydon Domain.





- **Figure 8** Area of depressed asphalt along Domain Terrace due to liquefaction.

## 6. Conclusions and recommendations

### 6.1 Site geology

The Spreydon Domain is situated within a river channel which comprises alluvial gravel, sand and silt. It is bounded north and south by slightly elevated ground of alluvial sand and silt overbank deposits.

An interpretation of the most relevant local investigation suggests that the site is underlain by:

Depth range (mBLG)	Soil type
0 - 9	Interbedded gravels with sand and silt.

### 6.2 Seismic site subsoil class

The site has been assessed as NZS1170.5 Class D (deep or soft soil) from adjacent borehole logs.

As described in NZS1170, the preferred site classification method is from site periods based on four times the shear wave travel time through material from the surface to the underlying rock. The next preferred methods are from borelogs including measurement of geotechnical properties or by evaluation of site periods from Nakamura ratios or from recorded earthquake motions. Lacking this information, classification may be based on boreholes with descriptors but no geotechnical measurements. The least preferred method is from surface geology and estimates of the depth to underlying rock.

In this case the absence of deep boreholes near the site has resulted in the use of the least preferred method. It is therefore possible that site specific investigation could revise the site class.



### 6.3 Building Performance

Although detailed records of the existing foundations are not available, the performance to date suggests that they are adequate for their current purpose.

### 6.4 Ground performance and properties

Liquefaction risk is low to moderate at this site. Although minor to moderate liquefaction occurred in the adjacent road no liquefaction was observed on Spreydon Domain where the toilets/pavilion is located. This is likely to be due to the domain being situated within a historic channel where the deposits are predominantly gravels with some silts and sands (see Figure 3). This geology exhibited in shallow boreholes along this channel to the northwest and southeast.

Due to the buildings location within a historical river channel we can infer the site's underlying geology based on data from boreholes located down channel of the site. Both locations share the same depositional environment and are likely to comprise underlying deposits of gravels with sand and silt.

Therefore the following parameters are recommended in order to perform a quantitative DEE. It should be noted that these parameters should not be used for design or consent purposes without confirming the properties through site specific investigation.

Parameter	Estimated value
Effective angle of friction	35 degrees
Apparent cohesion	0 kPa
Unit weight	19 kPa
Ultimate bearing capacity of a shallow square pad footing	*300 kPa

\*likely minimum ultimate bearing capacity which may increase following a site specific geotechnical investigation.

### 6.5 Further investigations

If consent is required for the structure or significant alterations to the structure are proposed, additional tests on site is likely to be required to confirm recommended properties:

- One borehole to a depth of 25 m below ground level including SPTs to obtain geotechnical parameters and ground conditions, and to identify if the site class can be improved to Seismic Class C.

## 7. References

Brown LJ, Weeber JH, 1992. Geology of the Christchurch urban area. Scale 1:25,000. Institute of Geological & Nuclear Sciences geological map 1.

Cubrinovski & Taylor, 2011. Liquefaction map summarising preliminary assessment of liquefaction in urban areas following the 2010 Darfield Earthquake.


Forsyth PJ, Barrell DJA, Jongens R, 2008. Geology of the Christchurch area. Institute of Geological & Nuclear Sciences geological map 16.

Land Information New Zealand (LINZ) geospatial viewer (<http://viewers.geospatial.govt.nz/>)

EQC Project Orbit geotechnical viewer (<https://canterburyrecovery.projectorbit.com/>)



## Appendix A – Christchurch 1856 land use





The swamps and previous creeks/ivers from 1856 have been overlayed onto a map of Christchurch in 2012


- Key**
- Previous creeks/ivers
  - Existing creeks/ivers
  - New creeks/ivers
  - Swamp/Marshland






## **Appendix B – Existing ground investigation logs**



<b>Project:</b> Christchurch 2011 Earthquake - EQC Ground Investigations				<b>Page:</b> 1 of 1		<b>CPT-HNH-11</b>	
<b>Test Date:</b> 16-May-2011		<b>Location:</b> Hoon Hay		<b>Operator:</b> McMillan			
<b>Pre-Drill:</b> 1.2m		<b>Assumed GWL:</b> 2mBGL		<b>Located By:</b> Survey GPS			
<b>Position:</b> 2477662.4mE		5738750.4mN		13.848mRL			
				<b>Coord. System:</b> NZMG & MSL			
<b>Other Tests:</b>				<b>Comments:</b>			



<b>Project:</b> Christchurch 2011 Earthquake - EQC Ground Investigations			<b>Page:</b> 1 of 1		<b>CPT-SPN-13</b>	
<b>Test Date:</b> 2-May-2011	<b>Location:</b> Spreydon		<b>Operator:</b> Geotech		 	
<b>Pre-Drill:</b> 1.2m	<b>Assumed GWL:</b> 2.3mBGL		<b>Located By:</b> Survey GPS			
<b>Position:</b> 2478172.5mE	5738810.6mN	12.917mRL	<b>Coord. System:</b> NZMG & MSL			
<b>Other Tests:</b>			<b>Comments:</b>			







## **Appendix C – Geotechnical Investigation Summary**



■ **Table 1 Summary of most relevant investigation data**

ID	1	2
Type *	CPT	CPT
Ref	SPN-13	HNH-11
Depth (m)	8.9	9.3
Distance from site (m)	327	290
Ground water level (mBGL)	2.3	2
0	N/A	N/A
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
Greater depths		

\*BH: Borehole, HA: Hand Auger, WW: Water Well, CPT: Cone Penetration Test

Sensitive or organic clay/silt	Clay to silty clay	Clayey silt to silt	Silty sand to silt
Clayey sand	Sand	Gravelly sand or gravel	

VL = very loose, L = loose, MD = medium dense, D = dense, VD = very dense

VS = very soft, So = soft, F = firm, St = stiff, VS = very stiff, H = hard