

Christchurch City Council

**St Johns Courts
Housing Complex
PRO 0853**

**Detailed Engineering Evaluation
Quantitative Assessment Report**



Christchurch City Council

Courts Housing Complex

Quantitative Assessment Report

**20 St Johns Street, Woolston,
Christchurch 8062**




Prepared By

.....
Chris Gilbert
Graduate Structural Engineer

Opus International Consultants Ltd
Christchurch Office
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail
Centre, Christchurch 8140
New Zealand


Reviewed By

.....

Lachlan Howat
Structural Engineer

Telephone: +64 3 363 5400
Facsimile: +64 3 365 7858

Date: January 2014
Reference: 6-QC403.00
Status: Final

Approved for
Release By

.....

Mary Ann Halliday
Senior Structural Engineer

Summary

St Johns Courts Housing Complex
PRO 0853

Detailed Engineering Evaluation
Quantitative Report - Summary
Final

Background

This is a summary of the quantitative report for the St Johns Courts Housing Complex, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This assessment covers the 13 residential units on the site.

Key Damage Observed

The residential units have suffered minor damage to non-structural elements and damage to the roof framing.

Non structural damage included cracking of the brick veneer cladding due to settlement of the concrete pad foundations and shear cracking.

Structural damage to the roofs include broken members within the roof space and visible sagging of the rooflines. Minor plasterboard cracking was observed in all units. This damage was deemed low enough to not affect the capacities of the buildings however, the damage to the roofs may pose a fall hazard should it remain unrepaired.

Level Survey

All accessible floor slopes were assessed in a laser level survey. Slopes in Blocks C and D are greater than the 5mm/m limitation set out in the MBIE guidelines [6], as shown below.

Internal Lining Nail Spacings

The internal lining nail spacings were measured on site to vary between 450-550mm.

Critical Structural Weaknesses

No critical structural weaknesses were found in any of the buildings.

Indicative Building Strength

Table A: Summary of Seismic Performance by Blocks

Block	NBS%	Floor Levels	Nail Spacings
PRO 0853 B001 (Block A)	46%	Pass	Fail
PRO 0853 B002 (Block B)	46%	Pass	Fail
PRO 0853 B003 (Block C)	46%	Fail	Fail
PRO 0853 B004 (Block D)	81%	Fail	Fail

No buildings on the site are considered to be earthquake prone.

Blocks A-C have capacities of 46% NBS as limited by the in-plane shear capacity of the timber-framed walls in the longitudinal direction. They are deemed to be a 'moderate risk' in a design seismic event according to NZSEE guidelines.

Block D has a capacity of 81% NBS as limited by the in-plane shear capacity of the timber-framed walls in the longitudinal direction. It is are deemed to be a 'low risk' in a design seismic event according to NZSEE guidelines

The %NBS has been calculated using the strength of the braces within the wall. The nail spacing does not comply with the minimum fixing requirements for plasterboard. An increase in the number of fixings would enhance the performance of the structure.

Recommendations

It is recommended that;

- Blocks A-C be strengthened to at least 67%NBS.
- Veneer at height (gable ends) have the veneer ties checked.
- Cosmetic repairs be undertaken as required.
- The timber roof framing requires repair in Unit 4. Other roof spaces should be fully inspected to confirm no further damage has occurred.

Contents

Summary	i
1 Introduction.....	1
2 Compliance	1
3 Earthquake Resistance Standards.....	5
4 Background Information.....	7
5 Damage	11
6 Detailed Seismic Assessment	12
7 Geotechnical Summary	16
8 Conclusions.....	16
9 Recommendations	17
10 Limitations.....	17
11 References	17
Appendix A – Photographs	
Appendix B – Level Survey	
Appendix C – Methodology and Assumptions	
Appendix D – CERA DEE Spreadsheet	

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the St Johns Courts Housing Complex, located at 20 St Johns Street, Woolston, Christchurch 8062 following the Canterbury earthquake sequence since September 2010. The site was visited by Opus International Consultants on 12 November 2013.

The purpose of the assessment is to determine if the buildings in the complex are classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [2] [3] [4] [5].

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in October 2011 following the Darfield Earthquake on 4 September 2010.

The policy includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure, was amended to include increased seismic design requirements for Canterbury as follows:

- Increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use). This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines [2]

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the MBIE guidance document dated December 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority.

4 Background Information

4.1 Building Descriptions

The site contains 13 residential units which were constructed in 1977. A site plan showing the location of the units, numbered 1 to 13, is shown in Figure 2. Figure 3 shows the location of the site in Christchurch City. The units are grouped together to form four blocks of either three or four units.




Figure 2: Site plan of St Johns Courts Housing Complex.




Figure 3: Location of St Johns Courts (circled) relative to Christchurch City CBD (Source: Google Earth).

The residential units are timber-framed buildings with diagonal timber braces. The roof structure comprises of timber roof framing supporting heavy, concrete tile roofs. The walls and ceilings are lined with plasterboard. External walls are clad with concrete block veneer. Foundations are strip footings under fire walls and around the perimeter of reinforced concrete slabs.

The units are separated by 190mm block masonry fire walls which are reinforced by 12mm bars to the perimeter.

Units in Blocks A, B and C have the same floor plan, as shown in Figure 4. Units in Block D have an alternative floor layout, as shown in Figure 5. These measurement were verified on site by Opus. Figure 6 shows a typical cross section used in calculations, from original documentation.




Figure 4: Typical partial floor plan of residential unit (Blocks A – C).




Figure 5: Typical partial floor plan of residential unit (Block D).




Figure 6: Cross section of St Johns Courts.

4.2 Survey

4.2.1 Post 22 February 2011 Rapid Assessment

A structural (Level 2) assessment of the buildings/property was undertaken on 7 March and 11 March 2011 by Opus International Consultants.

4.2.2 Level Survey

A full level survey was not deemed to be necessary at St Johns Courts as it is located in a TC2 zone. Properties in TC2 zones suffered minor to moderate damage due to liquefaction and/or settlement. In lieu of a full level survey, a laser level was placed in each unit so that differentials in vertical levels could be measured at the extreme ends of the unit. These values could then be used to determine the floor slope of the entire unit. For this site, the maximum slope in a unit was 8mm/m (which exceeds the 5mm/m limitation imposed by MBIE guidelines), the general slopes across all units was approximately 4mm/m.

Table 2: Summary of the level survey

Block	Unit No.	Comment	Maximum Fall*
A	1	Pass	-
	2	Pass	-
	3	Pass	-
B	4	Pass	-
	5	Pass	-
	6	Pass	-
C	7	Fail	7mm/m
	8	Pass	-
	9	No Access	-
	10	Fail	8 mm/m
D	11	Fail	8 mm/m
	12	Fail	7 mm/m
	13	Fail	7 mm/m

* Values are only recorded if greater than 5mm/m

Orange results represent floor levels which fall outside the MBIE guidelines when using the laser level but may comply when surveyed using more accurate equipment.

4.2.3 Nail Spacings

The internal lining nail spacings were measured on site to vary between 450-550mm.

4.3 Original Documentation

The following documentation was provided by the Christchurch City Council:

- 868 BU/1/2 – Christchurch City Council – Elderly Persons Housing – St Johns Street – Site plan, Floor Plans and Elevations – 1976.

In addition, a typical floor plan has been produced by Opus to help confirm as-built measurements.

Copies of the design calculations were not provided.

5 Damage

This section outlines the damage to the buildings that was observed during site visits. It is not intended to be a complete summary of the damage sustained by the buildings due to the earthquakes. Some forms of damage may not be able to be identified with a visual inspection only.

It is noticeable that some residential unit blocks, and individual units, have suffered more damage than others. Overall, Blocks C and D suffered more damage.

5.1 Residual Displacements

Blocks A and B suffered very little residual displacement. Residual displacement was observed in Block C where the maximum slope was observed in Unit 10. These slopes were observed to be toward the nearby creek. Residual displacement was observed in Block D where the maximum slope is 8 mm/m, in Unit 11. Despite the proximity of Block D to the creek, the residual displacements slope away from the creek.

5.2 Foundations

No foundation damage was observed.

5.3 Primary Gravity Structure

The roof structure at this site has not performed well, some structural members have broken or buckled in Unit 4 (photo 12), and some other units as well. Sagging of the rooflines is visually evident externally and requires repair.

5.4 Primary Lateral-Resistance Structure

Minor plasterboard cracking was observed in most units, typically above doorways, windows and at the roofline. Cracking in the ceiling diaphragms was observed in a number of units.

5.5 Non Structural Elements

Hairline cracking of the block veneer was observed, typically under windows or at the corner of buildings. A 1mm stepped crack was observed in the veneer at the back of Unit 10. A large crack of approximately 2-3mm was observed between Units 6 and 7, and a similarly large

crack between Units 8 and 9, between the veneer and firewall. Cracking was observed in the entrance patios and ramps.

5.6 General Observations

The buildings appeared to have performed reasonably well, as would be expected for buildings of this type, during the earthquakes. They have suffered distributed amounts of damage which is typical of the construction type and age of construction.

6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

As the residential units have the same floor plan, the analysis was simplified by conducting the analysis of one multi-unit block with similar cladding and using this for all multi-unit blocks.

6.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSWs were identified in the buildings.

6.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix C. A brief summary follows:

Hand calculations were performed to determine seismic forces from the current building codes. These forces were applied globally to the structure and the capacities of the walls were calculated and used to estimate the %NBS. The walls, highlighted in Figure 7 and Figure 8, were used for bracing in their respective directions.




Figure 7: Walls used for bracing in the longitudinal direction, Blocks A-C.




Figure 8: Walls used for bracing in the transverse direction, Blocks A-C.




Figure 9: Walls used for bracing in the longitudinal direction, Block D.




Figure 10: Walls used for bracing in the transverse direction, Block D.

6.3 Limitations and Assumptions in Results

The observed level of damage suffered by the buildings was deemed low enough to not affect their capacity. Therefore the analysis and assessment of the buildings was based on them being in an undamaged state. There may have been damage to the buildings that was unable to be observed that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections.
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.
- Construction is consistent with normal practise of the era in which constructed.

6.4 Assessment

A summary of the structural performance of the buildings is shown in Table 3. Note that the values given represent the worst performing elements in the building, where these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

Table 3: Summary of Seismic Performance

Building Description	Critical element	% NBS based on calculated capacity in longitudinal direction	% NBS based on calculated capacity in transverse direction.
Blocks A-C	Timber Framed Shear Walls – In Plane	46%	100%
Block D	Timber Framed Shear Walls – In Plane	81%	94%

7 Geotechnical Summary

CERA indicates that St Johns Courts is located in a TC2 zone (as shown in Figure 11). This classification suggests future significant earthquakes will cause minor to moderate land damage due to liquefaction and settlement.



Figure 11: CERA Technical Categories map (loc. starred).

An old stream runs along the south side of block D. It appears that this block has generally rotated down, potentially due to movement within the infill material of the stream. This suggests that further geotechnical investigation may be warranted for future development of the site.

8 Conclusions

- None of the buildings on site are considered to be Earthquake Prone.
- Blocks A-C have capacities of 46% NBS as limited by the in-plane shear capacity of the timber-framed walls in the longitudinal direction. They are deemed to be a 'moderate risk' in a design seismic event according to NZSEE guidelines. Their level of risk is 5-10 times that of a 100%NBS building (Figure 1).
- Block D has a capacity of 81% NBS as limited by the in-plane shear capacity of the timber-framed walls in the longitudinal direction. It is are deemed to be a 'low risk' in a design seismic event according to NZSEE guidelines. The level of risk is 1-2 times that of a 100%NBS building (Figure 1).
- The nail spacing does not comply with the minimum fixing requirements for plasterboard. An increase in the number of fixings would enhance the performance of the structure.
- Evidence of damage to the roofs was apparent internally within the roof space (broken members) and externally (visible sagging). This evidence suggests further problems may be apparent and should be fully inspected.
- Based on the geotechnical appraisal, differential settlement as a result of liquefaction could result in further damage, similar in nature to that which has occurred in the recent earthquake sequence. However, based on the nature of construction, this is unlikely to result in the collapse of concrete ground beams beneath the masonry walls.

9 Recommendations

It is recommended that;

- Blocks A-C be strengthened to at least 67%NBS.
- Veneer at height (gable ends) have the veneer ties checked.
- Cosmetic repairs be undertaken as required.
- The timber roof framing requires repair in Unit 4. Other roof spaces should be fully inspected to confirm no further damage has occurred.

10 Limitations

- This report is based on an inspection of the buildings and focuses on the structural damage resulting from the Canterbury Earthquake sequence since September 2010. Some non-structural damage may be described but this is not intended to be a complete list of damage to non-structural items.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- This report is prepared for the Christchurch City Council to assist in the assessment of any remedial works required for the St Johns Courts Housing Complex. It is not intended for any other party or purpose.

11 References

- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] MBIE (2012), Repairing and rebuilding houses affected by the Canterbury earthquakes, Ministry of Building, Innovation and Employment, December 2012.

Appendix A – Photographs

St Johns Courts Housing Complex – Detailed Engineering Evaluation

St Johns Courts Housing Complex		
No.	Item description	Photo
Residential Units Layout		
1.	Typical rear elevation (Block A)	 A photograph showing the rear elevation of a single-story residential unit. The building has a dark brown tiled roof and light-colored walls. A paved driveway leads to a red car parked on the right. The sky is overcast.
2.	Typical front elevation (Block B)	 A photograph showing the front elevation of a residential unit. The building has a dark brown tiled roof and light-colored walls with a teal door. A red car is parked in the foreground. A blue sign in the driveway reads 'THURSDAY ONLY NO PARKING'. The sky is overcast.

St Johns Courts Housing Complex – Detailed Engineering Evaluation

<p>3.</p>	<p>Typical front elevation (Block B)</p>	
<p>4.</p>	<p>Typical front elevation (Block C)</p>	
<p>5.</p>	<p>Typical front elevation (Block C)</p>	

St Johns Courts Housing Complex – Detailed Engineering Evaluation

<p>6.</p>	<p>Typical end elevation (Block A)</p>	
<p>7.</p>	<p>Typical front elevation (Block A)</p>	
<p>8.</p>	<p>Typical end elevation (Block D)</p>	

St Johns Courts Housing Complex – Detailed Engineering Evaluation

<p>9.</p>	<p>Typical rear elevation (Block C)</p>	
<p>10.</p>	<p>Typical rear elevation (Block C)</p>	
<p>11.</p>	<p>Typical roof void (Unit 4)</p>	

St Johns Courts Housing Complex – Detailed Engineering Evaluation

12.	Typical roof void (Unit 4) showing broken member.	 A photograph of a roof void in Unit 4. The image shows a network of wooden rafters and joists. A red arrow points to a horizontal wooden member that appears to be broken or severely damaged. Below the rafters, there is a layer of pink insulation and a white vapor barrier.
13.	Typical roof void (Unit 11)	 A photograph of a roof void in Unit 11. The image shows wooden rafters and joists. A horizontal wooden member is visible, which appears to be damaged or broken. There is a white vapor barrier and some debris on the floor of the void.
14.	Typical roof void (Unit 11)	 A photograph of a roof void in Unit 11. The image shows wooden rafters and joists. A horizontal wooden member is visible, which appears to be damaged or broken. There is a white vapor barrier and some debris on the floor of the void.

St Johns Courts Housing Complex – Detailed Engineering Evaluation

<p>15.</p>	<p>Typical lounge view (Unit 4)</p>	
<p>16.</p>	<p>Typical lounge view (Unit 4)</p>	
<p>17.</p>	<p>Typical hall view (Unit 4)</p>	

<p>18.</p>	<p>Typical kitchen view (Unit 4)</p>	
<p>19.</p>	<p>Typical bathroom view (Unit 4)</p>	


St Johns Courts Housing Complex – Detailed Engineering Evaluation

20.	Typical bathroom view (Unit 4)	 A photograph of a typical bathroom in Unit 4. It features a white sink on a light-colored vanity unit. Above the sink is a window with white lace curtains. To the left of the sink, there is a white wall-mounted unit, possibly a heater or a light fixture. A green toilet is partially visible in the foreground.
21.	Typical bedroom view (Unit 4)	 A photograph of a typical bedroom in Unit 4. The room contains a bed with blue and white patterned bedding. A window with light-colored curtains is on the right wall. A door is visible on the left, and a small table with a chair is near the door. A picture of a sunset is hanging on the wall.
22.	Typical nail spacings	 A close-up photograph showing a measuring tape held against a ceiling. The tape is yellow and black, and it is being used to measure the spacing between nails. The ceiling is white and has a dark trim around a recessed area. A doorway is visible in the background.

St Johns Courts Housing Complex – Detailed Engineering Evaluation


23.	Typical cracking at roofline	 A photograph showing the top edge of a wall where it meets the ceiling. There is a visible horizontal crack running across the wall, with some discoloration and peeling paint around the crack line.
24.	Typical cracking above windows	 A photograph showing a window frame with a white sill. Above the window, there is a vertical crack in the wall that extends upwards towards the ceiling. The wall is painted a light beige color.
25.	Typical cracking of the ceiling diaphragm	 A photograph showing a close-up of a ceiling. There is a horizontal crack running across the ceiling surface, which appears to be a joint or a crack in the concrete or plaster.

St Johns Courts Housing Complex – Detailed Engineering Evaluation

26.	Typical lounge view (Unit 11)	 A photograph of a typical lounge view in Unit 11. The room features a red sofa with a white fur throw and a blue and red patterned rug. A wooden cabinet and a glass display cabinet are visible in the background. A person in a high-visibility vest is standing near a table on the left.
27.	Typical lounge through bedroom (Unit 11)	 A photograph showing a typical lounge view through a bedroom in Unit 11. The view is from a doorway, looking into a room with a television on a wooden stand, a chair, and a doorway leading to another room. A person in a high-visibility vest is visible in the background.
28.	Typical kitchen view (Unit 11)	 A photograph of a typical kitchen view in Unit 11. The kitchen features a white stove, a sink, and a window with a view of the outdoors. A person in a high-visibility vest is standing near the sink. A refrigerator and a microwave are also visible.

<p>29.</p>	<p>Typical kitchen through bathroom view (Unit 11)</p>	
<p>30.</p>	<p>Typical bathroom view (Unit 11)</p>	

St Johns Courts Housing Complex – Detailed Engineering Evaluation


31.	Typical bedroom view (Unit 11)	
32.	Typical stepped cracking around corners	
33.	Cracking of ramp to entrance of unit	

St Johns Courts Housing Complex – Detailed Engineering Evaluation


<p>34.</p>	<p>Cracking between veneer and firewall between Units 6 and 7</p>	
<p>35.</p>	<p>Stepped cracking on Unit 10</p>	

Appendix B – Level Survey

Block C (Units 7-10)



Block D (Units 11-13)



Appendix C – Methodology and Assumptions

Seismic Parameters

As per NZS 1170.5:

- $T < 0.4s$ (assumed)
- Soil: Category D
- $Z = 0.3$
- $R = 1.0$ (IL2, 50 year)
- $N(T,D) = 1.0$

For the analyses, a μ of 2 was assumed for the residential units.

Analysis Procedure

As the units are small and have a number of closely spaced walls in both directions, the fibrous plaster board ceilings are assumed to be capable of transferring loads to all walls. It was therefore assumed that a global method could be used to carry the forces down to ground level in each direction. Bracing capacities were found by assuming a certain kN/m rating for the walls along each line. Due to the relatively unknown nature of the walls, the kN/m rating was taken as 3 kN/m for all timber walls with an aspect ratio (height: length) of less than 2:1. This was scaled down to zero kN/m at an aspect ratio of 3.5:1 as per NZSEE guidelines. %NBS values were then found through the ratio of bracing demand to bracing capacity for all walls in each direction.

Additional Assumptions

Further assumptions about the seismic performance of the buildings were:

- Foundations and foundation connections had adequate capacity to resist and transfer earthquake loads.
- Connections between all elements of the lateral load resisting systems are detailed to adequately transfer their loads sufficiently and are strong enough so as to not fail before the lateral load resisting elements.

Appendix D – CERA DEE Spreadsheet

Location		Building Name: <input type="text" value="St Johns Street Housing Complex"/>	Unit No: <input type="text" value="20"/>	Street: <input type="text" value="St Johns"/>	Reviewer: <input type="text" value="Mary Ann Halliday"/>
Building Address: <input type="text"/>	Legal Description: <input type="text"/>				CPEng No: <input type="text" value="67073"/>
			Company: <input type="text" value="Opus International Consultants"/>		
			Company project number: <input type="text" value="6-CC403.00"/>		
			Company phone number: <input type="text" value="64-3-363-5400"/>		
GPS south: <input type="text" value="43 32 57.59"/>		Degrees		Min	Sec
GPS east: <input type="text" value="172 41 7.62"/>					
Building Unique Identifier (CCC): <input type="text" value="PRO0853"/>			Date of submission: <input type="text" value="24-Jan-14"/>		
			Inspection Date: <input type="text" value="12/11/2013"/>		
			Revision: <input type="text" value="1"/>		
			Is there a full report with this summary? <input type="text" value="yes"/>		

Site		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
Soil type: <input type="text"/>		Soil Profile (if available): <input type="text"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>		If Ground improvement on site, describe: <input type="text"/>	
Proximity to waterway (m, if <100m): <input type="text"/>		Approx site elevation (m): <input type="text"/>	
Proximity to cliff top (m, if <100m): <input type="text"/>			
Proximity to cliff base (m, if <100m): <input type="text"/>			

Building		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split? <input type="text" value="no"/>		Storeys below ground: <input type="text" value="0"/>		Ground floor elevation above ground (m): <input type="text"/>
Foundation type: <input type="text" value="strip footings"/>		Building height (m): <input type="text" value="3.00"/>		if Foundation type is other, describe: <input type="text"/>
Floor footprint area (approx): <input type="text" value="192"/>		Age of Building (years): <input type="text" value="36"/>		height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>
Strengthening present? <input type="text" value="no"/>		Date of design: <input type="text" value="1965-1976"/>		
Use (ground floor): <input type="text" value="multi-unit residential"/>		If so, when (year)? <input type="text"/>		
Use (upper floors): <input type="text"/>		And what load level (%g)? <input type="text"/>		
Use notes (if required): <input type="text"/>		Brief strengthening description: <input type="text"/>		
Importance level (to NZS1170.5): <input type="text" value="IL2"/>				

Gravity Structure		Gravity System: <input type="text" value="frame system"/>	rafter type, purlin type and cladding: <input type="text" value="No sarking"/>
Roof: <input type="text" value="timber framed"/>		slab thickness (mm): <input type="text"/>	
Floors: <input type="text" value="concrete flat slab"/>		overall depth x width (mm x mm): <input type="text"/>	
Beams: <input type="text" value="none"/>		typical dimensions (mm x mm): <input type="text"/>	
Columns: <input type="text" value="timber"/>			
Walls: <input type="text" value="non-load bearing"/>			

Lateral load resisting structure		Lateral system along: <input type="text" value="lightweight timber framed walls"/>	Note: Define along and across in detailed report!	note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>		0.00		estimate or calculation? <input type="text" value="estimated"/>
Period along: <input type="text" value="0.10"/>				estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>				estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>				
Lateral system across: <input type="text" value="lightweight timber framed walls"/>		0.00		note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>				estimate or calculation? <input type="text" value="estimated"/>
Period across: <input type="text" value="0.10"/>				estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>				estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>				

Separations:		north (mm): <input type="text"/>	leave blank if not relevant
east (mm): <input type="text"/>			
south (mm): <input type="text"/>			
west (mm): <input type="text"/>			

Non-structural elements		Stairs: <input type="text"/>	describe: <input type="text" value="Concrete Block"/>
Wall cladding: <input type="text" value="other heavy"/>		Roof Cladding: <input type="text" value="Heavy tiles"/>	describe: <input type="text" value="Concrete"/>
Glazing: <input type="text" value="aluminium frames"/>		Ceilings: <input type="text" value="strapped or direct fixed"/>	
Services(list): <input type="text"/>			

Available documentation		Architectural: <input type="text" value="partial"/>	original designer name/date: <input type="text" value="CCC, 1976"/>
Structural: <input type="text" value="partial"/>		Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text" value="CCC, 1976"/>
Electrical: <input type="text" value="none"/>		Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text"/>
			original designer name/date: <input type="text"/>

Damage		Site performance: <input type="text" value="Good"/>	Describe damage: <input type="text"/>
Site: (refer DEE Table 4-2)		Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>
Differential settlement: <input type="text" value="1:250-1:150"/>		Liquefaction: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Lateral Spread: <input type="text" value="none apparent"/>		Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Ground cracks: <input type="text" value="none apparent"/>		Damage to area: <input type="text" value="slight"/>	notes (if applicable): <input type="text"/>

Building:		Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	Describe how damage ratio arrived at: <input type="text"/>
Across	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$			
Diaphragms	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>	
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>	
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>	
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>	

Recommendations		Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text"/>
Building Consent required: <input type="text" value="no"/>		Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before e'quakes: <input type="text" value="46%"/>	Assessed %NBS after e'quakes: <input type="text" value="46%"/>	#### %NBS from IEP below
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	Assessed %NBS after e'quakes: <input type="text" value="100%"/>	#### %NBS from IEP below
			If IEP not used, please detail assessment methodology: <input type="text" value="Equivalent Static"/>

Location		Building Name: <input type="text" value="St Johns Street Housing Complex"/>	Unit No: <input type="text" value="20"/>	Street: <input type="text" value="St Johns"/>	Reviewer: <input type="text" value="Mary Ann Halliday"/>
Building Address: <input type="text"/>	Legal Description: <input type="text"/>				CPEng No: <input type="text" value="67073"/>
			Company: <input type="text" value="Opus International Consultants"/>		
			Company project number: <input type="text" value="6-CC403.00"/>		
			Company phone number: <input type="text" value="64-3-363-5400"/>		
			Date of submission: <input type="text" value="24-Jan-14"/>		
			Inspection Date: <input type="text" value="12/11/2013"/>		
			Revision: <input type="text" value="1"/>		
Building Unique Identifier (CCC): <input type="text" value="PRO0853"/>			Is there a full report with this summary? <input type="text" value="yes"/>		

Site	Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
Soil type: <input type="text"/>	Soil Profile (if available): <input type="text"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>		
Proximity to waterway (m, if <100m): <input type="text"/>	If Ground improvement on site, describe: <input type="text"/>	
Proximity to cliff top (m, if <100m): <input type="text"/>		
Proximity to cliff base (m, if <100m): <input type="text"/>	Approx site elevation (m): <input type="text"/>	

Building	No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split?: <input type="text" value="no"/>			Ground floor elevation above ground (m): <input type="text"/>
Storeys below ground: <input type="text" value="0"/>			
Foundation type: <input type="text" value="strip footings"/>			if Foundation type is other, describe: <input type="text"/>
Building height (m): <input type="text" value="3.00"/>		height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>	
Floor footprint area (approx): <input type="text" value="192"/>			Date of design: <input type="text" value="1965-1976"/>
Age of Building (years): <input type="text" value="36"/>			
Strengthening present?: <input type="text" value="no"/>			If so, when (year)? <input type="text"/>
Use (ground floor): <input type="text" value="multi-unit residential"/>			And what load level (%g)? <input type="text"/>
Use (upper floors): <input type="text"/>			Brief strengthening description: <input type="text"/>
Use notes (if required): <input type="text"/>			
Importance level (to NZS1170.5): <input type="text" value="IL2"/>			

Gravity Structure	Gravity System: <input type="text" value="frame system"/>	rafter type, purlin type and cladding: <input type="text" value="No sarking"/>
Roof: <input type="text" value="timber framed"/>		slab thickness (mm): <input type="text"/>
Floors: <input type="text" value="concrete flat slab"/>		overall depth x width (mm x mm): <input type="text"/>
Beams: <input type="text" value="none"/>		typical dimensions (mm x mm): <input type="text"/>
Columns: <input type="text" value="timber"/>		
Walls: <input type="text" value="non-load bearing"/>		

Lateral load resisting structure	Lateral system along: <input type="text" value="lightweight timber framed walls"/>	Note: Define along and across in detailed report!	note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>	0.00		estimate or calculation? <input type="text" value="estimated"/>
Period along: <input type="text" value="0.10"/>			estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>			estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>			
Lateral system across: <input type="text" value="lightweight timber framed walls"/>			note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>	0.00		estimate or calculation? <input type="text" value="estimated"/>
Period across: <input type="text" value="0.10"/>			estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>			estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>			

Separations:	north (mm): <input type="text"/>	leave blank if not relevant
east (mm): <input type="text"/>		
south (mm): <input type="text"/>		
west (mm): <input type="text"/>		

Non-structural elements	Stairs: <input type="text"/>	describe: <input type="text" value="Concrete Block"/>
Wall cladding: <input type="text" value="other heavy"/>		describe: <input type="text" value="Concrete"/>
Roof Cladding: <input type="text" value="Heavy tiles"/>		
Glazing: <input type="text" value="aluminium frames"/>		
Ceilings: <input type="text" value="strapped or direct fixed"/>		
Services(list): <input type="text"/>		

Available documentation	Architectural: <input type="text" value="partial"/>	original designer name/date: <input type="text" value="CCC, 1976"/>
Structural: <input type="text" value="partial"/>		original designer name/date: <input type="text" value="CCC, 1976"/>
Mechanical: <input type="text" value="none"/>		original designer name/date: <input type="text"/>
Electrical: <input type="text" value="none"/>		original designer name/date: <input type="text"/>
Geotech report: <input type="text" value="none"/>		original designer name/date: <input type="text"/>

Damage Site:	Site performance: <input type="text" value="Good"/>	Describe damage: <input type="text"/>
(refer DEE Table 4-2)	Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>
Differential settlement: <input type="text" value="1:250-1:150"/>		notes (if applicable): <input type="text"/>
Liquefaction: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>
Lateral Spread: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>
Differential lateral spread: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>
Ground cracks: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text"/>
Damage to area: <input type="text" value="slight"/>		notes (if applicable): <input type="text"/>

Building:	Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio: <input type="text" value="0%"/>	Describe how damage ratio arrived at: <input type="text"/>
	Describe (summary): <input type="text"/>	
Across	Damage ratio: <input type="text" value="0%"/>	$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
	Describe (summary): <input type="text"/>	
Diaphragms	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>

Recommendations	Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text"/>
Building Consent required: <input type="text" value="no"/>		Describe: <input type="text"/>
Interim occupancy recommendations: <input type="text" value="full occupancy"/>		Describe: <input type="text"/>
Along	Assessed %NBS before e'quakes: <input type="text" value="46%"/>	##### %NBS from IEP below If IEP not used, please detail assessment methodology: <input type="text" value="Equivalent Static"/>
	Assessed %NBS after e'quakes: <input type="text" value="46%"/>	
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	##### %NBS from IEP below
	Assessed %NBS after e'quakes: <input type="text" value="100%"/>	

Location		Building Name: <input type="text" value="St Johns Street Housing Complex"/>	Unit No: <input type="text" value="20"/>	Street: <input type="text" value="St Johns"/>	Reviewer: <input type="text" value="Mary Ann Halliday"/>
Building Address: <input type="text"/>	Legal Description: <input type="text"/>				CPEng No: <input type="text" value="67073"/>
			Company: <input type="text" value="Opus International Consultants"/>		
			Company project number: <input type="text" value="6-CC403.00"/>		
			Company phone number: <input type="text" value="64-3-363-5400"/>		
GPS south: <input type="text" value="43 32 57.59"/>		Degrees		Min	Sec
GPS east: <input type="text" value="172 41 7.62"/>					
Building Unique Identifier (CCC): <input type="text" value="PRO0853"/>			Date of submission: <input type="text" value="24-Jan-14"/>		
			Inspection Date: <input type="text" value="12/11/2013"/>		
			Revision: <input type="text" value="1"/>		
			Is there a full report with this summary? <input type="text" value="yes"/>		

Site		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
Soil type: <input type="text"/>		Soil Profile (if available): <input type="text"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>		If Ground improvement on site, describe: <input type="text"/>	
Proximity to waterway (m, if <100m): <input type="text"/>		Approx site elevation (m): <input type="text"/>	
Proximity to cliff top (m, if <100m): <input type="text"/>			
Proximity to cliff base (m, if <100m): <input type="text"/>			

Building		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split?: <input type="text" value="no"/>		Storeys below ground: <input type="text" value="0"/>		Ground floor elevation above ground (m): <input type="text"/>
Foundation type: <input type="text" value="strip footings"/>		if Foundation type is other, describe: <input type="text"/>		
Building height (m): <input type="text" value="3.00"/>		height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>		
Floor footprint area (approx): <input type="text" value="143"/>		Date of design: <input type="text" value="1965-1976"/>		
Age of Building (years): <input type="text" value="36"/>				
Strengthening present?: <input type="text" value="no"/>		If so, when (year)? <input type="text"/>		
Use (ground floor): <input type="text" value="multi-unit residential"/>		And what load level (%g)? <input type="text"/>		
Use (upper floors): <input type="text"/>		Brief strengthening description: <input type="text"/>		
Use notes (if required): <input type="text"/>				
Importance level (to NZS1170.5): <input type="text" value="IL2"/>				

Gravity Structure		Gravity System: <input type="text" value="frame system"/>	rafter type, purlin type and cladding: <input type="text" value="No sarking"/>
Roof: <input type="text" value="timber framed"/>		slab thickness (mm): <input type="text"/>	
Floors: <input type="text" value="concrete flat slab"/>		overall depth x width (mm x mm): <input type="text"/>	
Beams: <input type="text" value="none"/>		typical dimensions (mm x mm): <input type="text"/>	
Columns: <input type="text" value="timber"/>			
Walls: <input type="text" value="non-load bearing"/>			

Lateral load resisting structure		Lateral system along: <input type="text" value="lightweight timber framed walls"/>	Note: Define along and across in detailed report!	note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>		0.00		estimate or calculation? <input type="text" value="estimated"/>
Period along: <input type="text" value="0.10"/>				estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>				estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>				
Lateral system across: <input type="text" value="lightweight timber framed walls"/>		0.00		note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>				estimate or calculation? <input type="text" value="estimated"/>
Period across: <input type="text" value="0.10"/>				estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>				estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>				

Separations:		north (mm): <input type="text"/>	leave blank if not relevant
east (mm): <input type="text"/>			
south (mm): <input type="text"/>			
west (mm): <input type="text"/>			

Non-structural elements		Stairs: <input type="text"/>	describe: <input type="text" value="Concrete Block"/>
Wall cladding: <input type="text" value="other heavy"/>		Roof Cladding: <input type="text" value="Heavy tiles"/>	describe: <input type="text" value="Concrete"/>
Glazing: <input type="text" value="aluminium frames"/>		Ceilings: <input type="text" value="strapped or direct fixed"/>	
Services(list): <input type="text"/>			

Available documentation		Architectural: <input type="text" value="partial"/>	original designer name/date: <input type="text" value="CCC, 1976"/>
Structural: <input type="text" value="partial"/>		Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text" value="CCC, 1976"/>
Electrical: <input type="text" value="none"/>		Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text"/>
			original designer name/date: <input type="text"/>

Damage Site:		Site performance: <input type="text" value="Good"/>	Describe damage: <input type="text"/>
(refer DEE Table 4-2)		Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>
Differential settlement: <input type="text" value="1:250-1:150"/>		Liquefaction: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Lateral Spread: <input type="text" value="none apparent"/>		Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Ground cracks: <input type="text" value="none apparent"/>		Damage to area: <input type="text" value="slight"/>	notes (if applicable): <input type="text"/>

Building:		Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	Describe how damage ratio arrived at: <input type="text"/>
Across	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$			
Diaphragms	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>	
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>	
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>	
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>	

Recommendations		Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text"/>
Building Consent required: <input type="text" value="no"/>		Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before e'quakes: <input type="text" value="81%"/>	Assessed %NBS after e'quakes: <input type="text" value="81%"/>	#### %NBS from IEP below
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	Assessed %NBS after e'quakes: <input type="text" value="100%"/>	#### %NBS from IEP below
			If IEP not used, please detail assessment methodology: <input type="text" value="Equivalent Static"/>



Opus International Consultants Ltd

20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400

f: +64 3 365 7858

w: www.opus.co.nz