



NOTES:

1. If existing metalcourses are still present below the berm subgrade inform the Engineer.