

Discharge began (2024)	Discharge ceased	ID	Overflow location	Receiving waterway	Cause
31 December 1pm	31 December 2:30pm	540	PS20/2 Waltham Road / Eastern Terrace	Heathcote River	Wet Weather
31 December 7am	31 December 10am	538	PS43/1 Cashmere Road	Heathcote River	Wet Weather
2 October 6.30pm	3 October 4.30pm	533	Harbour View Terrace, Cass Bay	Lyttelton Harbour	Broken pipe
2 October 9.30am	2 October 4pm	532	Park Terrace, Lyttelton	Lyttelton Harbour	Burst pipe
10 August 1.30pm	10 August 3.30pm	530	McCormack Road, Redcliffs	Ihutai Estuary	Pipe blockage
1 August 10.40am	1 August 4.06pm	529	Cashin Quay	Lyttelton Harbour	Pump station fault
10 July 10pm	11 July 2pm	520	Koromiko Cres, Diamond Harbour	Lyttelton Harbour	Root blockage
8 July 11am	11 July 4.50pm	519	Cressy Terrace, Lyttelton	Lyttelton Harbour	Pipe collapse
22 June 4pm	22 June 5pm	518	Wainui Road, Riccarton	Avon River	Fat blockage
9 June 4.20pm	9 June 6.30pm	515	Hoon Hay Road, Hoon Hay	Heathcote River	Fat blockage
2 June 7.30pm	2 June 11pm	513	Purau Bay, Diamond Harbour	Lyttelton Harbour	Root blockage
13 April 6am	15 April 11.30am	482	McCormacks Bay Road, Redcliffs	Ihutai Estuary	Blockage
17 March 8pm	18 March 3pm	481	Balguerie Stream, Akaroa	Akaroa Harbour	Broken pipe
6 March 12am	6 March 12.55pm	480	Hollis Avenue, Cashmere	Heathcote River	Root intrusion
25 February 12.30am	25 February 1.30am	479	270 Sparks Road, Halswell	Heathcote River	Electrical failure