Level 2, 134 Oxford Terrace

Christchurch Central, Christchurch 8011 PO Box 389, Christchurch 8140, New Zealand Tel +64 3 345 7100 Web www.pdp.co.nz Auckland Tauranga Hamilton Wellington Christchurch Invercargill





12 April 2023

Mark Johnston Project Manager - Land, Compliance, & Delivery Calder Stewart Development Limited PO Box 8356 Riccarton **CHRISTCHURCH 8440** 

Dear Mark,

# PRELIMINARY SITE INVESTIGATION – CORNER OF MARSHS ROAD AND MAIN SOUTH ROAD (STATE HIGHWAY 1), HORNBY, CHRISTCHURCH

#### 1.0 Introduction

Pattle Delamore Partners Limited (PDP) has been engaged by Calder Stewart Development Limited (Calder Stewart) to undertake a Preliminary Site Investigation (PSI; desktop site history review) for the properties located within an approximate 23 ha area of land located at the corner or Marshs Road and Main South Road (State Highway 1), Hornby, Christchurch (i.e., the site).

The objective of the investigation is to identify any potential sources of contamination from past and/or present land use activities at the site, which could be listed on the HAIL1 (Ministry for the Environment; MfE, 2011). The PSI has been prepared to assist Calder Stewart in relation to the proposed district plan change application from Rural Urban Fringe Zone and Open Space Community Parks Zone to an industrial zone for the approximate 23 ha site. A plan showing the site location is attached as Figure 1.

Due to access constraints and taking into account the objectives of the investigation, the investigation comprised a review of the site history including Christchurch City Council (CCC) property files, interviews with selected landowners and site inspections for the six largest land parcels associated with the proposed plan change area, as well as a review of historical aerial photographs, the Environment Canterbury (ECan) LLUR<sup>2</sup> and CCC HSNO<sup>3</sup> information for the entire approximate 23 ha site.







<sup>&</sup>lt;sup>1</sup> The Hazardous Activities and Industries List (HAIL; MfE, 2011) is a compilation of activities and industries that are considered likely to cause land contamination resulting from hazardous substance use, storage or disposal. The HAIL is intended to identify most situations in New Zealand where hazardous substances could cause, and in many cases have caused, land contamination.

<sup>&</sup>lt;sup>2</sup> Environment Canterbury Listed Land Use Register.

<sup>&</sup>lt;sup>3</sup> HSNO - Hazardous Substances and New Organisms Act.



The PSI has been prepared in general accordance with the Ministry for the Environment (MfE)

Contaminated Land Management Guidelines No. 1: Reporting on Contaminated Sites in New Zealand

(Revised 2021) (MfE, 2021) and has been certified by a Suitably Qualified and Experienced Practitioner

(SQEP) as outlined by the NESCS<sup>4</sup>. A certifying statement to this effect is attached.

#### 2.0 Site Details

The site details and description for the six largest land parcels associated with the proposed plan change are summarised below in Table 1, while an aerial photograph showing the overall current site layout (Figure 1) is attached.

Photographs of the site are also attached.

| Table 1: Site Identification   |   |
|--------------------------------|---|
| Table 1. Site identification   |   |
| Address                        | 1.673A Main South Road, Christchurch                                    |
|                                | 2. 689 Main South Road, Christchurch                                    |
|                                | 3. 27 Marshs Road, Christchurch   |
|                                | 4. 29 Marshs Road, Christchurch   |
|                                | 5. 41 Marshs Road, Christchurch   |
|                                | 6. 53 Marshs Road, Christchurch   |
| Legal Descriptions             | 1. Res 4707   |
|                                | 2. Lot 44 Deposited Plan 16696  |
|                                | 3. Lot 1 Deposited Plan 447493  |
|                                | 4. Lot 2 Deposited Plan 447493  |
|                                | 5. Lot 2 Deposited Plan 74746   |
|                                | 6. Lot 1 Deposited Plan 74746   |
| Site Owner                     | 1. No owners detailed   |
|                                | 2. John Choong Chet Law   |
|                                | 3. John Choong Chet Law and Karen Ann Law                               |
|                                | 4. Joy Elizabeth Murcott and Michael Ernest Murcott                     |
|                                | 5. Denis Ivan Powell and Marian Ivy Powell                              |
|                                | 6. Lynette Faye Stirling, Warren Ian Stirling and Warren Lee Stirling   |
| Grid Reference- Centre of Site | BX23:5896-7783  |
| Land Area                      | 1. 0.4148 ha  |
|                                | 2. 4.7227 ha  |
|                                | 3. 4.0967 ha  |
|                                | 4. 4.0002 ha  |
|                                | 5. 4.0230 ha  |
|                                | 6. 2.6750 ha  |
|                                | Total including all land parcels included in the proposed plan change = |
|                                | approximately 23 ha   |

C04702100L001.docx, 12/04/2023

<sup>&</sup>lt;sup>4</sup> Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soils to Protect Human Health) Regulations 2011 (referred to as the NESCS).



| Zoning               | Rural Urban Fringe Zone and Open Space Community Parks Zone  |
|----------------------|--|
| Land Use             | Excluding Islington Reserve, the remaining five largest properties associated with the proposed plan change are used for rural residential purposes and each contain at least one dwelling and paddocks used for grazing livestock. A horse training track is located across the 27 and 29 Marshs Road properties. The smaller properties around the perimete of the site are used for residential purposes. |
| Surrounding Land Use | The overall site is surrounded by paddocks used for agricultural activities immediately east and south of the site. Retail shops are located directly north of the site (north-western corner) and residential and rural residential properties are present west of the site.  |

## 3.0 Environmental Setting

The geological map for the area (Forsyth, P.J., Barrell, D.J.A., Jongens, R., 2008; 1:250,000) reports that the site is underlain by 'grey river alluvium beneath plains or low-level terraces'.

According to the Canterbury *Land and Water Regional Plan (LWRP)*, the site is located within the Christchurch Groundwater Protection Zone.

Based on the ECan GIS database, the nearest natural surface water body to the site is Dawson Creek, located approximately 4 km to the south-east of the site at its nearest point. An unnamed drain extends along the western site boundary along Marshs Road.

The ECan GIS database indicates that the depth to groundwater in the area is reported to be greater than approximately 10 m bgl. The regional groundwater flow direction is expected to be in a general southeasterly direction within the site vicinity.

According to the ECan GIS database, there are two groundwater bores within the site boundary. Of these, only one (M36/5580) was recorded as being 'active (exist, present)' and is used for a domestic supply for 41 Marshs Road. A bore plot and accompanying spreadsheet of bore details is attached.

A plan showing the location of the bores within the site boundary and accompanying data are attached.

## 4.0 Desktop Review of Site History

A desktop assessment was undertaken to provide an overview of any potential contaminants of concern that may be present within the site as a result of any documented past and present activities. The following information was sourced in order to establish the history of the site:

- : Historical aerial photographs;
- : Environment Canterbury (ECan) information;
- : Christchurch City Council (CCC) information; and
- Site inspection and interviews.



Due to access constraints, and the scope of this investigation, CCC property files and site inspections of the residential properties fronting Main South Road and northern portion of Marshs Road were not obtained or undertaken. It is expected that once these properties have been vacated site inspections can be undertaken at this time and any land contaminated issues evaluated. The exclusion of physical site inspections and reviewing of property files for these standard residential properties are not expected to impact the decision making for the proposed district plan change.

## 4.1 Historical Aerial Photographs

Historical aerial photographs from between 1941 and 2021 have been reviewed for the overall site. These photographs have been sourced from Canterbury Map Partners administered by ECan. Note that the review of the aerial photographs was carried out on the electronic versions, which provides a higher resolution compared with the printed versions attached.

| Table 2: Historical Aerial Photography |  |  |
|--|--|--|
| 1941                                   | The 1941 aerial photograph shows majority of the site being largely undeveloped, possibly used for stock grazing and/or pasture. A paleo river channel is situated on the eastern portion of the site. A dwelling is present midway along Marshs Road (27 Marshs Road) along with sheds and other unidentifiable objects/structures. A pile of hay is present in the land parcel located in the southern part of the site (53 Marshs Road) and a structure, potentially a shed/garage, is present halfway along the land fronting Main South Road. Tree plantings are present along the eastern and western boundaries of the site. Marshs Road and Main South Road are present in their current footprint and the site is surrounded by rural residential and rural land, likely used for grazing or pasture. |  |
| 1955                                   | The 1955 aerial photograph clearly shows a dwelling and eight buildings/sheds located at 27 Marshs Road. Eight additional dwellings or large sheds have been constructed along the land fronting Marshs Road and Main South Road. The remaining land appears to be used for grazing, pasture or cropping purposes. No other notable changes have occurred within the site.   |  |
| 1961                                   | The 1961 aerial photograph does not show imagery over the entire site but shows notable development along Marshs Road and Main South Road with a total of 22 houses and associated sheds/structures present. Three additional sheds have been constructed at 27 Marshs Road, which appear to be configured around a yard, potentially to store equipment and machinery associated with onsite farming activities. The remaining land within the site appears to be used for cropping or grazing.  The surrounding land has undergone further development with additional residential properties to the west, residential and commercial to the north, while east and south of the site remains undeveloped.  |  |
| 1965                                   | The 1965 aerial photograph shows additional development along the fringe of the site with a total of 29 residential properties fronting Marshs Road and Main South Road. Commercial buildings, located outside of the site, on the corner of Marshs Road and Main South Road have been constructed. The configuration of sheds at 27 Marshs Road has changed slightly with the removal and addition of two sheds. Trees have been planted along the boundary between the 27 Marshs Road and 689 Main South Road properties. No other notable changes are evident.  |  |



| Table 2: Historical Aerial Photography |  |  |
|--|--|--|
| 1974                                   | The 1974 aerial photography shows the construction of a dwelling and four sheds within the north-eastern corner of the site, at 689 Main South Road. Two sheds have been constructed along the southern boundary of the 689 Main South Road property and hay bales are present within the 689 Main South Road paddocks, indicating this land is being used to graze livestock. The shed configuration at 27 Marshs Road has undergone minor changes with the removal of one shed and construction of another two sheds. What was referred to as a "yard" in previous aerials appears to be tidied up/removed. There are now 33 houses and various sheds/garages fronting Marshs Road and Main South Road. An irrigation line is present in the southern portion of the site, confirming this land is likely being used for cropping. Commercial development continues directly north-east of the site. No other notable changes have occurred within the site. |  |
| 1975 and<br>1984                       | The paleo river channel sited in previous aerials has gradually been filled or the land reworked and is no longer noticeable in the 1975 and 1984 aerial photography. The 1984 aerial photography shows the removal of two sheds at the 27 Marshs Road property. No other notable changes are evident within the site.   |  |
| 1994                                   | The 1994 aerial photography shows the development of a horse training track across 27 and 29 Marshs Road and the removal of one shed at the 27 Marsh Road property. A dwelling, detached garage and a shed have been constructed within the southernmost part of the site at 53 Marshs Road, while planting around this property has been developed. A shelter belter splitting the land into sections has been planted across 27, 29 and 41 Marshs Road.  |  |
| 1995                                   | There are no significant changes compared with the earlier 1994 aerial image.  |  |
| 2000                                   | The 2000 aerial photography shows two additional dwellings fronting Main South Road, taking the total to 35 residential dwellings with associated sheds and garages fronting Marshs Road and Main South Road. The 2000 aerial photography shows the construction of a house with an attached garage, additional garage, shed and a suspected haybarn at the 41 Marshs Road property, located along the site's southern boundary.   |  |
| 2004                                   | Small sheds have been constructed within the inside of the horse training track. No other notable changes have occurred within the site.   |  |
| 2011                                   | The 2011 aerial photography shows the construction of a garage next to the dwelling and additional building at 53 Marshs Road. The suspected haybarn at 41 Marshs Road has been subject to an extension and an additional shed within the inside of the horse training track at 29 Marshs Road has been erected.   |  |
| 2018                                   | The 2018 aerial photography shows the construction of a dwelling with an attached garage and an implement shed, likely a haybarn, at 29 Marshs Road, located midway along Marshs Road.   |  |
| Latest<br>Imagery<br>(2021)            | Shows the land in its current layout. No notable changes are evident from the 2018 aerial photography.   |  |



#### 4.2 Environment Canterbury Information

#### 4.2.1 Listed Land Use Register

An online search was made via ECan for information from their Listed Land Use Register (LLUR). The ECan LLUR is used to hold information about sites that have used, stored or disposed of hazardous substances, based on activities detailed on the HAIL (MfE, 2011). It should be noted that the LLUR is not complete and new sites are regularly being added as ECan receives information or conduct their own investigations into current and historical land uses.

The entire approximate 23 ha site is not listed on LLUR.

A copy of the LLUR is attached.

#### 4.2.2 Resource Consents

The ECan GIS database was reviewed for recorded resource consents within the site boundary. There were 11 resource consents located within the site boundary, the status of all these consents was 'terminated.' Historically, when these consents were active, they permitted the take of groundwater, the installation of a bore or the discharge of a contaminated into land to water.

A plot showing the resource consents and accompanying spreadsheet of details is attached.

## 4.3 Christchurch City Council Information

#### 4.3.1 HSNO Information

HSNO information held in the CCC database was also provided to PDP for review of the entire site. The HSNO information includes various documents related to hazardous good storage, which is summarised below.

- A pit containing waste was located in the backyard of 681 Main South Road during an inspection undertaken by CCC on 8 April 2021. On closer inspection of historical aerials, the correct address of the waste pit is 679 Main South Road. The pit has an approximate diameter of 2-3 m.
- 693 Main South Road was used to store multiple vehicles for restoration purposes during an inspection by the CCC enforcement team on 10 July 2013.
- 689 Main South Road contains a pocket of uncontrolled fill related to a swimming pool removal; associated date not provided. The exact location of the fill/historical swimming pool is undetermined.

The email correspondence with CCC is attached.

### 4.3.2 Landfill Records

The site is not recorded as being located within an area identified on the CCC *Old Landfills Within Christchurch City* (1993) plan. The site is not recorded as being part of a known landfill. The nearest landfills on the map are located approximately 1 km north and 1.4 km east of the centre of the site and are listed as "Landfill (Rubbish)."

#### 4.3.3 Review of Christchurch City Council Property Files Documents

Property files provided by CCC for the six largest land parcels associated with the proposed plan change were reviewed for any specific site history information and/or potential contamination sources. The property files included documents related to the following.



#### 673a Main South Road Property Files:

CCC confirmed that they held no information on this address.

#### 689 Main South Road Property Files:

The property files for 689 Main South Road contained multiple building and resource consents related to a pig sty, bach, extended haybarn, dwelling with garage, fowl house, implement shed, store shed, shed and a hay shed. The property files also note a supply well being onsite but the location is not provided. Of interest, these files included a design plan for the fowl house, which detailed the material used for the wall covering to be polite, given the time period (i.e. 1970s) it is possible that this is asbestos containing material.

#### 27 Marshs Road Property Files:

The property files for 27 Marshs Road include multiple building and resource consents related to the construction of a detached dwelling, single story dwelling with an attached garage, with an amendment to the kitchen windows, a haybarn, the installation of a solid fuel heater (woodfire) and space heater, connection to a sewar lateral and a subdivision from 1989. These files included an historical Certificate of Title, which details the mortgage invoiced to Wattie Industries Limited (Wattie's) on 19 June 1989.

#### 29 Marshs Road Property Files:

The property files for 29 Marshs Road all relate to building consent BCN20182200, which consented the construction of a haybarn.

## 41 Marshs Road Property Files:

The property files for 41 Marshs Road include multiple building and resource consents related to the construction, renovations or relocation of dwellings, an office/clinic, garages and/or sheds and the change of use from a packing shed to a family flat. The files also contained documents associated with reductions in boundary set back distances, the management of a veterinary clinic and an artificial breeding centre for horses and subdivision of the land. These files included an historical Certificate of Title (reference 330/166), which details the title was transferred to Wattie Industries Limited in 1969.

## 53 Marshs Road Property Files:

The property files for 53 Marshs Road include multiple building and resource consents related to the relocation and renovation of a building, foundation and alterations to a relocated office/clinic, erection of an implement shed/haybarn, construction of a garage/sleep out, extension of a downstairs bedroom/ensuite, erection of a marquee, two subdivisions, which took place in 1996, boundary setbacks for a dwelling and garage, street number allocation, a consent to establish a veterinary artificial breeding centre for horses in Marshs Road, construction of a dwelling, dwelling alterations and additions to an existing two storey dwelling, including the installation of a fire place as well as the enlargement of a kitchen and dining room, and to alter cladding.

These property files contained a consent for a water connection, which includes a site plan detailing a veterinary office and clinic, outdoor lily bed and a small glasshouse. These files also noted the land was used for grazing up to 15 bobby calves, and contained an historical Certificate of Title detailing a name change of the registered to Wattie Industries Limited on 6 December 1976 and an historical Certificate of Title, which details the mortgagee as Wattie Industries Limited on 19 June 1989. The files also detail a supply well located onsite, but no specific location is detailed.



## 4.4 Site Inspection

An inspection of the site was carried out by a PDP environmental geologist/scientist on 7 March 2023. During this site inspection the six largest land parcels associated with the proposed plan change were inspected (i.e. 27, 29, 41 and 53 Marshs Road, 673a and 689 Main South Road) and an interview was conducted if the land owner was present during the time of inspection to provide information on the past and present land use activities. The main findings from the site inspection and interviews are summarised below. Photographs taken during the site inspection are attached.

#### 673a Main South Road:

During the time of the inspection, 673a Main South Road was Islington Reserve and was accessed through an alleyway off Main South Road. The reserve contained a grassed area with tree plantings and no structures. No person(s) were present during the time of inspection to undertake an interview.

#### 689 Main South Road:

During the time of the inspection, 689 Main South Road contained a two-storey dwelling with an attached garage and multiple storage sheds, with the remaining land comprised of paddocks used for grazing horses. An implement shed/haybarn was present in a paddock along the southern boundary. The dwelling was separated from the paddocks by tree plantings and a shelter belt was present along the southern boundary. The roof, soffits and gable of the dwelling looked like they may contain asbestos containing material, although this would require testing to confirm. During the inspection it was noted that a neighbouring property fronting Main South Road (693 Main South Road) contained tyres stacked up along the boundary, and multiple storage containers and cars is varying states of condition. No person(s) were present during the time of inspection to undertake an interview.

#### 27 Marshs Road:

During the time of the inspection, 27 Marshs Road contained a dwelling, various storage sheds, derelict stables, a horse yard and half a horse training track, which also extends over 29 Marshs Road. The central portion of the horse training track was used to graze horses and empty sheds were present within the centre of the horse training track and used as shelter for the horses. Shelter belts were present in the central portion of the horse training track and around the perimeter of the property, excluding the southern boundary. There was a residential style glasshouse in the backyard of the property.

Parts of the land was overgrown, and the buildings and sheds showed signs of deterioration. The gable ends, soffits and cladding may contain asbestos given the appearance of the material and the paint on the exterior of the dwelling was in poor condition, given the age it may be lead-based paint, although this would need to be confirmed with analytical testing.

Although a resident who rented the property was present during the time of inspection, Mr Michael Murcott, who currently resides at 29 Marshs road, was interviewed and disclosed he previously resided at 27 Marshs Road. Mr Murcott provided information on 27 Marshs Road including the locations of the redundant supply well and septic tank and confirmed that the dwelling is now connected to the council water and sewer reticulated systems. Mr Murcott noted that imported crusher dust was used for the horse training track and that ash was previously used for the horse yard to prevent the ground becoming muddy.



## 29 Marshs Road:

During the time of the inspection 29 Marshs Road contained a dwelling with an attached garage, a woodshed, an implement shed/haybarn, paddocks and the southern half of a horse training track. The paddock south-east of the dwelling contained horses and a haybarn, which was used to store hay and a tractor. The central portion of the horse training track was used to graze horses and contained shelter belts and empty sheds that were used as shelter for the horses. Shelter belts were planted around the perimeter of the property, excluding the northern boundary. All building structures were in good condition and showed no obvious sign of deterioration, excluding the sheds in the middle of the horse training track, which showed signs of deterioration.

Mr Murcott, the owner of the land confirmed that Wattie's had previously owned his property and the surrounding land. While owning the land, Wattie's reportedly filled in a paleo stream to enable them to use the land for cropping. The land was reportedly previously used for growing potatoes and for supporting dairy cows. Mr Murcott confirmed the dwelling with attached garage at 29 Marshs Road was constructed approximately nine years ago and is connected to the council reticulated system and therefore does not have a septic tank or supply well on site. Mr Murcott confirmed that imported crusher dust is used for the horse training track.

#### 41 Marshs Road:

During the time of the inspection, 41 Marshs Road contained a dwelling with an attached garage, a detached garage/hobby workshop, a guest house, two storage sheds, a shed used for growing plants and a haybarn. Vegetables were grown in raised planter boxes directly east of the dwelling next to a storage shed. This area also contained a compost heap, small residential style glasshouses and a water tank. The haybarn east of the dwelling on the property boundary contained hay, various storage items and drums used to store synthetic passenger car oil. There were no obvious spills or surficial staining on the surrounding land from these drums during the time of inspection. Due to the small quantity of car oil stored onsite it is considered that this does not constitute a HAIL activity.

A chicken coop was present in front of the haybarn and chickens were present in this south-eastern paddock. A small crop was fenced off in the northern most portion of the site along with a pile of hay under a tarpaulin. West of the crop a pile of garden clippings and a stock loading ramp Were present. The two western paddocks, one located adjacent to the driveway, were used to graze sheep or cows. West of the dwelling was a garage used as a small hobby workshop, and attached to the workshop was a guest house and what appeared to be horse stables, which were used for storage. It should be noted that the garage, used as a hobby workshop, had a concrete floor and was maintained in a tidy condition. Based on this, this would not constitute a HAIL activity.

South-east of this workshop was a storage shed and directly in front of the workshop was a small pile of timber poles. A septic tank was located within the circular island of the driveway and a small glasshouse used to grow swan plants was present in the south-western paddock.

Tree plantings lined the driveway and the gardens around the dwelling. All building structures were in good condition and showed no sign of deterioration. The owners of the property, Mr Denis and Mrs Powell gave details on how their property and surrounding land was previously owned by Wattie's in approximately the 1980s. Mrs Powell confirmed the location of the supply well onsite and noted that Wattie's would have had irrigation pipes through the land to irrigate their crops. Mrs Powell also noted that during her time of residing at 41 Marshs Road she noticed that certain plants did not grow in her gardens.



#### 53 Marshs Road:

During the time of the inspection 53 Marshs Road contained a two-storey dwelling with an attached garage, a smaller cottage style building, a garage used for general storage, a shed/barn near one of the paddocks used to store a caravan and various items, and a small garden shed by the main dwelling. A rubbish pile was present in the northernmost paddock at the time of inspection, which contained cardboard, garden clippings and a redundant computer hard drive. The two paddocks adjacent to the driveway were used for grazing sheep and there were also chickens, including a chicken coop, in the southernmost paddock. Vegetable gardens in raised planter boxes and small domestic glasshouses were present by the main dwelling.

Multiple caravans were parked around the property. Trees and gardens separated the dwelling from the surrounding paddocks while tree plantings lined the driveway and the north-western boundary. Shelter belts were also planted along the southern and western boundaries. All building structures were in good condition and showed no obvious sign of deterioration. Mr Warren Stirling, the property owner was unaware of any potentially contaminating activities being undertaken on his land.

## 5.0 Summary of Site History

The available historical information for the overall site shows that it was in pasture or used for cropping activities from at least 1941 (earliest aerial image). Residential development progressively occurred along the northern site boundary (Main South Road) and along the northern part of Marshs Road.

the six largest properties associated with the proposed plan change (occupying approximately 19.5 ha), predominantly comprised a reserve or paddocks used for grazing livestock (sheep, cows, horses and chickens). Historically a large percentage of this land<sup>5</sup> was owned by Wattie's. During the time of the inspection there were five dwellings, various storage sheds, a horse training track and a reserve across the six main properties. Dwellings and associated buildings located at 689 Main South Road, 27 and 53 Marshs Road may have been constructed with asbestos containing material and/or lead based paint given the age of the buildings (i.e. pre-2000).

Based on the available information, the potential contamination sources from past and present land use activities are restricted to the following for the overall site:

- 'Waste disposal to Land (excluding where biosolids have been used as soil conditioners)' (HAIL Reference G5) - Waste pits/rubbish piles located at 679 Main South Road and 53 Marshs Road, the uncontrolled fill associated with the removal of a swimming pool at 689 Main South Road (i.e. exact location undetermined);
- 'Waste disposal to Land (excluding where biosolids have been used as soil conditioners)' (HAIL Reference G5) - Imported fill and ash used for the horse training track and horse yard at 27 and 29 Marshs Road;
- 'Scrap yards including automotive dismantling, wrecking or scrap metal yards' (HAIL Reference G4)
   Tyres, multiple storage containers and cars is varying states of condition at 693 Main South Road;
   and

C04702100L001.docx, 12/04/2023

<sup>&</sup>lt;sup>5</sup> Including at least 27, 41 and 53 Marshs Road.



'Any other land that has been subject to the intentional or accidental release of a hazardous substance in sufficient quantity that it could be a risk to human health or the environment' (HAIL Reference I) - Associated with asbestos containing materials or lead-based paint potentially used in the construction of dwellings, garages, sheds or other structures on the site. Asbestos containing material and lead based paint would be determined by a pre-demolition survey for any buildings/structures constructed prior to 2000.

The site history information has shown that a large percentage of the site was in the ownership of Wattie's and used for general cropping purposes. It is important to note that general cropping is not classified as a HAIL activity (i.e. HAIL reference A10<sup>6</sup>) and there is no evidence to indicate that intensive cropping occurred that required the application of persistent pesticides. Furthermore, previous investigations undertaken by PDP on similar cropping land has shown heavy metals and organochlorine pesticide (OCP) concentrations (i.e. the likely persistent contaminants of concern) at or around the typical background soil concentrations of the local area.

In addition, due to the small 'residential' size of the glasshouses (i.e., not larger commercial scale) located at 27, 41 and 53 Marshs Road, these are not considered to constitute a HAIL activity (i.e. HAIL reference A10.

The primary contaminants of concern associated with the identified HAIL activities over the site include (but not necessarily limited to) heavy metals, petroleum hydrocarbons, asbestos and persistent pesticides (e.g. OCP compounds).

A plan showing the identified HAIL areas is attached as Figure 2. HAIL reference I has not been included in Figure 2 as pre-demolition surveys will be undertaken to determine which structures and buildings contain asbestos and/or lead based paint. In addition, HAIL reference A10 has not been included in Figure 2 at this stage based on the currently available information not confirming that intensive cropping/application of persistent pesticides occurred over the site.

#### 6.0 Consideration of the NESCS

#### 6.1 Provisions of the NESCS

The NESCS seeks to control activities on contaminated land so as to protect human health. The regulations apply to land which is described as having, has had or is more likely than not to have had an activity or industry described in the HAIL undertaken on it (i.e. the 'piece of land'). As discussed in Section 5.0, HAIL activities from past and present land use activities have been identified over parts of the site.

Therefore, under regulation 5(7), the NESCS regulations must be taken into consideration for any future change in land use<sup>7</sup>, subdivision or earthworks that result following any successful plan change application for the site.

It should be noted that a change of land use and/or subdivision are a permitted activity (i.e. no resource consent required under the NESCS) under regulation 8(4) if it can be demonstrated through the review of the site history (i.e. PSI) that it is *highly unlikely* that there will be a risk to human health.

#### 6.2 Applicability of the NESCS

As noted above, based on the identification of HAIL activities over parts of the site, the NESCS regulations need to be taken into consideration for any future change in land use, subdivision or earthworks that

<sup>&</sup>lt;sup>6</sup> A10 – Persistent pesticide bulk storage or use including sports turfs, market gardens, orchards, glass houses or spray sheds.

<sup>&</sup>lt;sup>7</sup> It is acknowledged that the proposed land change is from residential/agricultural to 'less sensitive' commercial/industrial land use, however the NESCS for the change in land use still needs to be considered.



result following any successful plan change application for the site. Based on a review of the available site history information, due to the presence of identified HAIL activities over parts of the site, a potential risk exists to human health (albeit a low risk noting the proposed change in land use to commercial/industrial). As such, resource consent will be required following the completion of the plan change process and for activities covered by the NESCS.

In particular, any land use change, subdivision and soil disturbance (i.e. excavations) in areas of the site where any of the current HAIL activities (i.e., G5, G4 and I) have been identified (i.e. the 'piece of land' where the two waste pits, uncontrolled fill associated with the removal of a swimming pool, imported for the horse training track, ash for the horse yard, bulk car storage and selected buildings built prior to 2000, which could comprise asbestos containing material and/or lead based paint are located), then the NESCS will be applicable and further investigations would be required (i.e. soil sampling as part of a Detailed Site Investigation).

Whilst noting the above, and the requirement to consider the NESCS, there is no reason why the proposed plan change cannot proceed.

#### 7.0 Conclusions

PDP has reviewed site history information for the land associated with the proposed plan change at Hornby, Christchurch, which is proposed to change the zoning from Rural Urban Fringe Zone and Open Space Community Parks Zone to an industrial zone. The objective of the investigation was to identify any potential HAIL activities/sources of contamination from past and/or present land use activities at the site and to assess compliance with the NESCS for the proposed district plan change for the land.

The investigation was limited to a review of the site history including property files, a site inspection and interviews with the selected property owners for the six largest properties (occupying approximately 85% of the overall site) as well as a review of the historical aerial photography, LLUR and HSNO information for all properties, including the residential properties fronting Main South Road and Marshs Road, associated with the proposed plan change.

In summary, the available historical information for the overall site shows that it was in pasture or used for cropping activities from at least 1941 (earliest aerial image). Residential development progressively occurred along the northern site boundary (Main South Road) and along the northern part of Marshs Road. The six largest properties associated with the proposed plan change (occupying approximately 19.5 ha), predominantly comprised paddocks used for grazing livestock, a horse training track, a reserve, and rural residential properties.

Through the process of this review, HAIL activities have been identified to have occurred within parts of the overall site, as follows:

- : HAIL reference G5 Waste disposal and uncontrolled or imported fill (i.e. located at 679 Main South Road, 53 Marshs Road, 689 Main South Road and 27 Marshs Road).
- HAIL reference G4 Tyres, multiple storage containers and cars is varying states of condition at 693 Main South Road.
- Hail reference I The potential of asbestos containing building materials and/or lead-based paint used for any structures (i.e. dwellings, garages or sheds) constructed prior to 2000 (i.e. this is to be determined via post demolition surveys).



The site history information has shown that a large percentage of the site was in the ownership of Wattie's and used for general cropping purposes. It is important to note that general cropping is not classified as a HAIL activity (i.e. HAIL reference A10) and there is no evidence to indicate that intensive cropping occurred that required the application of persistent pesticides. Likewise, the presence of 'residential' scale glasshouses identified at some of the properties do not constitute a HAIL activity (i.e. HAIL reference A10).

Based on a review of the available site history information, due to the presence of identified HAIL activities over parts of the site, a potential risk exists to human health (albeit a low risk noting the proposed change in land use to commercial/industrial). As such, resource consent will be required following the completion of the plan change process and for activities covered by the NESCS (i.e. land use change, subdivision and/or soil disturbance).

It is important to note that, in particular, if a land use change, subdivision and/or soil disturbance is proposed for the areas of the site where HAIL activities have been identified or likely to occur, then in accordance with the NESCS further investigations would likely be required (i.e. soil sampling forming part of a Detailed Site Investigation).

Whilst noting the above applicability of the NESCS, there is no reason from a site contamination perspective why the proposed plan change from Rural Urban Fringe Zone and Open Space Community Parks Zone to an industrial zone for the approximate 23 ha site cannot proceed.

#### 8.0 References

- Forsyth, P.J., Barrell, D.J.A., Jongens, R., 2008. Geology of the Christchurch Area. Institute of Geological & Nuclear Sciences 1:250,000, geological map 16. Lower Hutt, New Zealand. GNS Science.
- Ministry for the Environment, 2011. *Hazardous Activities and Industries List*. Ministry for the Environment, Wellington.
- Ministry for the Environment, 2021. *Contaminated Land Management Guidelines No. 1: Reporting on Contaminated Sites in New Zealand (Revised 2021)*. Ministry for the Environment, Wellington.
- Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011.



#### 9.0 Limitations

This letter has been prepared on the basis of information provided by Calder Stewart Development Limited and others (not directly contracted by PDP for the work), including Environment Canterbury and Christchurch City Council. PDP has not independently verified the provided information and has relied upon it being accurate and sufficient for use by PDP in preparing the letter. PDP accepts no responsibility for errors or omissions in, or the currency or sufficiency of, the provided information.

This letter has been prepared by PDP on the specific instructions of Calder Stewart Development Limited for the limited purposes described in the letter. PDP accepts no liability to any other person for their use of or reliance on this letter, and any such use or reliance will be solely at their own risk.

Owing to the limited nature of this assessment (as described in Section 1.0), there could be conditions at the site that have not been identified and which have not been considered in this letter. Although the assessment has shown the possible source of soil contamination from the identify HAIL activities, there is a risk that sources of soil contamination could exist that have not been identified by the assessment. This risk could be reduced by undertaking further research or subsoil investigation.

© 2023 Pattle Delamore Partners Limited.

Yours faithfully

PATTLE DELAMORE PARTNERS LIMITED

Prepared by

**Chanelle Seabrook** 

**Environmental Geologist/Scientist** 

Reviewed and Approved by

**Guy Knoyle** 

Technical Director - Contaminated Land



## **Certifying Statements**

I, Guy Knoyle of Pattle Delamore Partners Limited, certify that:

- This preliminary site investigation meets the requirements of the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011 (the NESCS) because it has been:
  - a. done by a suitably qualified and experienced practitioner, and
  - b. reported on in accordance with the current edition of *Contaminated land management* quidelines No 1 Reporting on contaminated sites in New Zealand, and
  - c. the report is certified by a suitably qualified and experienced practitioner.
- 2. This preliminary site investigation concludes that the NESCS regulations are considered to be applicable for the activities covered by the NESCS following any proposed plan change at the site.

Evidence of the qualifications and experience of the suitably qualified and experienced practitioner who has done this investigation and certified this report is provided below.

This certification applies to the date of this report.

Signed

Guy Knoyle

Technical Director - Contaminated Land



#### Guy Knoyle - Project Director

Guy is an environmental scientist with over 26 years of experience in undertaking environmental and contaminated land assessments. He has a BSc (Joint Honours) in Environmental Science and Zoology, and a MSc in Applied Hydrobiology, both from the University of Wales, College of Cardiff. Guy currently project manages contaminated land assessments and monitoring programmes for a diverse range of sites including commercial/industrial and largescale residential developments, former market gardens, horticultural and timber treatment sites, pesticide storage depots, landfills, the petroleum industry, former gas works sites and illicit methamphetamine laboratories, with experience attained over several hundred sites.

Guy has experience involved in a wide range of environmental issues, across a broad range of media including soil, sediment, surface water, groundwater, and ground gas; and for a wide range of contaminants including heavy metals, petroleum hydrocarbons, and asbestos.

Guy's knowledge has also allowed him to present technical evidence on behalf of various clients, as part of a multi-disciplinary team, at District Court, High Court and Environment Court mediation and at numerous joint territorial and regional authority hearings.

Guy has familiarity with and understanding of the current contaminated land regulation and practice in New Zealand including assessments against the NESCS, and in the consenting of contaminated sites.



# **Figures**



- PATTLE DELAMORE PARTNERS LTD



FIGURE 2: HAIL CATERGORIES



# **Site Photographs**



Photograph 1: Storage shed near western paddock. Image taken facing west.



Photograph 2: Image of western paddock, image taken in top corner of paddock facing east.



Photograph 3: Rubbish pile at 53 Marshs Road in the middle of the northern paddock.



Photograph 4: Back of garage, used for general storage. Image taken facing south.



Photograph 5: Cottage style building. Image taken facing east.



Photograph 6: Main dwelling, image taken facing south-east.



Photograph 7: Raised vegetable gardens, domestic glasshouses and garden shed north east dwelling.



Photograph 8: Chickens in the southern paddock. Image taken facing south-east.



Photograph 9: Sheep in southern paddock, image taken facing north.



Photograph 10: Front of garage. Image taken facing north-west.



Photograph 11: location of raised planter boxes with vegetable gardens, a water tank, domestic glasshouse and compost directly east of the dwelling.



Photograph 12: Haybarn east of the dwelling. Image taken facing east.



Photograph 13: Drums located in haybarn containing car motor oil.



Photograph 14: Grass crop located at the top of the northern paddock. Image taken facing south-west.



Photograph 15: Stock loading ramp.



Photograph 16: Pile of garden clippings. Image taken facing south.



Photograph 17: Cattle in western paddock. Image taken facing west.



Photograph 18: Small domestic glasshouse in southern paddock. Image taken facing south-east.



Photograph 19: Guest house and horse stables used for storage. Image taken facing south.



Photograph 20: Image of storage shed next to garage/hobby workshop. Image taken facing south-west.



Photograph 21: Image of dwelling at 41 Marshs Road. Image taken facing south-east.



Photograph 22: Image of garage/hobby workshop. Image taken facing south-west.



Photograph 23: Image inside garage/hobby workshop.



Photograph 23: Image of dwelling at 29 Marshs Road. Image taken facing south.



Photograph 24: Image of haybarn containing hay and a tractor. Image facing south-east.



Photograph 25: Image of horse training track. Image taken facing east.



Photograph 26: Image of shed in middle of the horse training track. Image taken south-west.



Photograph 27: Image of dwelling at 27 Marshs Road. Image taken facing south-west.



Photograph 28: Image of storage shed in backyard of 27 Marshs Road. Image taken facing north-east.



Photograph 29: Image of domestic glasshouse in backyard of 27 Marshs Road. Image taken facing north.



Photograph 29: Image of horse training track. Image taken facing south-west.



Photograph 30: Image of storage shed. Image taken facing north-west.



Photograph 31: Image of derelict horse stables. Image taken facing south-west.



Photograph 32: Image of storage shed. Image taken facing south-west.



Photograph 33: Image of horse yard. Image taken facing west.

## 698 Main South Road Photographs



Photograph 34: Image of dwelling at 689 Main South Road. Image taken facing east.



Photograph 35: Storage shed. Image taken facing north-west.



Photograph 36: Storage shed in south-west corner of residential property. Image taken facing north-west.



Photograph 37: Small storage sheds, image taken facing south.



Photograph 38: Storage shed, image taken facing north-east.



Photograph 39: Haybarn in paddock on southern boundary. Image taken facing south-east.



Photograph 40: Image of paddock used for horse grazing. Image taken in north-eastern corner of paddocks facing south-west.



Photograph 41: Image of the back of 693 Main South Road.

### 673a Main South Road (Islington Reserve) Photographs



Photograph 42: Image of walkway to Islington Reserve. Image taken facing south-east.



Photograph 43: Image of Islington Reserve. Image taken in the north-eastern corner facing south-west.



CALDER STEWART DEVELOPMENT LIMITED - PRELIMINARY SITE INVESTIGATION - CORNER OF MARSHS ROAD AND MAIN SOUTH ROAD (STATE HIGHWAY 1), HORNBY, CHRISTCHURCH

## **Historical Aerial Photographs**







C04702100Z002\_AERIALS.mxd 28/03/2023 ISSUE 1

1965 AERIAL PHOTOGRAPHY



1974 AERIAL PHOTOGRAPHY



- PATTLE DELAMORE PARTNERS LTD



- PATTLE DELAMORE PARTNERS LTD



1994 AERIAL PHOTOGRAPHY





— PATTLE DELAMORE PARTNERS LTD -







2018 AERIAL PHOTOGRAPHY





CALDER STEWART DEVELOPMENT LIMITED - PRELIMINARY SITE INVESTIGATION - CORNER OF MARSHS ROAD AND MAIN SOUTH ROAD (STATE HIGHWAY 1), HORNBY, CHRISTCHURCH

## **Environment Canterbury Information**

(SOURCED FROM ECAN GIS DATABASE APRIL 2023)

- PATTLE DELAMORE PARTNERS LTD

### Bores located within the Site Boundary (Sourced from Ecan GIS database in April 2023).

|   | Well No.   | Well Status             | Depth | Diameter | Use Codes       | Grid East | Grid North | Well Owner      | Well Type    | Well Location    | Top Screen | Bottom Screen | Initial SWL | Approx. Distance from centre of Site (m) |
|---|------------|-------------------------|-------|----------|-----------------|-----------|------------|-----------------|--------------|------------------|------------|---------------|-------------|--|
| 1 | M36/5580   | Active (exist, present) | 35.5  | 150      | Domestic Supply | 1559104   | 5177648    | COLLINS. GF & J | Bore or Well | 41 MARSHS ROAD   | 33.5       | 25.5          | -16         | 240                                      |
| 1 | 10130/3360 | Active (exist, present) | 33.3  | 130      | Domestic Supply | 1333104   | 3177046    | COLLINS, GF & J | Bore or Well | 41 IVIANSHS NOAD | 33.3       | 35.5          | -10         | 240                                      |
| 2 | M36/0194   | Not Used                | 23.2  | 152      | Irrigation      | 1558694   | 5177858    | RIDDEN L.R.     | Bore or Well | MARSHES ROAD     |            |               | -14         | 270                                      |



Customer Services
P. 03 353 9007 or 0800 324 636

PO Box 345 Christchurch 8140

P. 03 365 3828 F. 03 365 3194 E. ecinfo@ecan.govt.nz

www.ecan.govt.nz

### Dear Sir/Madam

Thank you for submitting your property enquiry from our Listed Land Use Register (LLUR). The LLUR holds information about sites that have been used or are currently used for activities which have the potential to cause contamination.

The LLUR statement shows the land parcel(s) you enquired about and provides information regarding any potential LLUR sites within a specified radius.

Please note that if a property is not currently registered on the LLUR, it does not mean that an activity with the potential to cause contamination has never occurred, or is not currently occurring there. The LLUR database is not complete, and new sites are regularly being added as we receive information and conduct our own investigations into current and historic land uses.

The LLUR only contains information held by Environment Canterbury in relation to contaminated or potentially contaminated land; additional relevant information may be held in other files (for example consent and enforcement files).

Please contact Environment Canterbury if you wish to discuss the contents of this property statement.

Yours sincerely

**Contaminated Sites Team** 

# **Property Statement from the Listed Land Use Register**



Visit ecan.govt.nz/HAIL for more information or contact Customer Services at ecan.govt.nz/contact/ and quote ENQ339222


Date generated: 28 February 2023 Land parcels: Lot 40 DP 16696

Lot 27 DP 16696 Lot 39 DP 16696 Lot 36 DP 16696 Lot 22 DP 16696 Lot 9 DP 16696 Lot 35 DP 16696 Lot 23 DP 16696 Lot 14 DP 16696 Lot 7 DP 16696 Lot 20 DP 16696 Lot 2 DP 16696 Lot 1 DP 16696 Lot 12 DP 16696 Lot 15 DP 16696 Lot 10 DP 16696 Lot 21 DP 16696 Lot 24 DP 16696 Lot 2 DP 76458

Lot 1 DP 74746 Lot 26 DP 16696 Lot 19 DP 16696 Lot 2 DP 74746 Lot 17 DP 16696 Lot 13 DP 16696 Lot 41 DP 16696 RES 4707 Lot 1 DP 76458 Lot 38 DP 16696

Lot 1 DP 76458 Lot 38 DP 16696 Lot 37 DP 16696 Lot 16 DP 16696 Lot 2 DP 447493 Lot 4 DP 76458 Lot 11 DP 16696 Lot 33 DP 16696 Lot 34 DP 16696 Lot 44 DP 16696 Lot 1 DP 447493 Lot 8 DP 16696

Lot 32 DP 16696 Lot 25 DP 16696 Lot 3 DP 76458 Lot 18 DP 16696



Ν



The information presented in this map is specific to the property you have selected. Information on nearby properties may not be shown on this map, even if the property is visible.

## Sites at a glance



Sites within enquiry area

There are no sites associated with the area of enquiry.

## More detail about the sites

There are no sites associated with the area of enquiry.

### Disclaimer

The enclosed information is derived from Environment Canterbury's Listed Land Use Register and is made available to you under the Local Government Official Information and Meetings Act 1987.

The information contained in this report reflects the current records held by Environment Canterbury regarding the activities undertaken on the site, its possible contamination and based on that information, the categorisation of the site. Environment Canterbury has not verified the accuracy or completeness of this information. It is released only as a copy of Environment Canterbury's records and is not intended to provide a full, complete or totally accurate assessment of the site. It is provided on the basis that Environment Canterbury makes no warranty or representation regarding the reliability, accuracy or completeness of the information provided or the level of contamination (if any) at the relevant site or that the site is suitable or otherwise for any particular purpose. Environment Canterbury accepts no responsibility for any loss, cost, damage or expense any person may incur as a result of the use, reference to or reliance on the information contained in this report.

Any person receiving and using this information is bound by the provisions of the Privacy Act 1993.



## Listed Land Use Register

What you need to know



## Everything is connected

## What is the Listed Land Use Register (LLUR)?

The LLUR is a database that Environment Canterbury uses to manage information about land that is, or has been, associated with the use, storage or disposal of hazardous substances.

## Why do we need the LLUR?

Some activities and industries are hazardous and can potentially contaminate land or water. We need the LLUR to help us manage information about land which could pose a risk to your health and the environment because of its current or former land use.

Section 30 of the Resource Management Act (RMA, 1991) requires Environment Canterbury to investigate, identify and monitor contaminated land. To do this we follow national guidelines and use the LLUR to help us manage the information.

The information we collect also helps your local district or city council to fulfil its functions under the RMA. One of these is implementing the National Environmental Standard (NES) for Assessing and Managing Contaminants in Soil, which came into effect on 1 January 2012. For information on the NES, contact your city or district council.

## How does Environment Canterbury identify sites to be included on the LLUR?

We identify sites to be included on the LLUR based on a list of land uses produced by the Ministry for the Environment (MfE). This is called the Hazardous Activities and Industries List (HAIL)<sup>1</sup>. The HAIL has 53 different activities, and includes land uses such as fuel storage sites, orchards, timber treatment yards, landfills, sheep dips and any other activities where hazardous substances could cause land and water contamination.

### We have two main ways of identifying HAIL sites:

- We are actively identifying sites in each district using historic records and aerial photographs. This project started in 2008 and is ongoing.
- We also receive information from other sources, such as environmental site investigation reports submitted to us as a requirement of the Regional Plan, and in resource consent applications.

<sup>1</sup>The Hazardous Activities and Industries List (HAIL) can be downloaded from MfE's website www.mfe.govt.nz, keyword search HAIL

## How does Environment Canterbury classify sites on the LLUR?

Where we have identified a HAIL land use, we review all the available information, which may include investigation reports if we have them. We then assign the site a category on the LLUR. The category is intended to best describe what we know about the land use and potential contamination at the site and is signed off by a senior staff member.


Please refer to the Site Categories and Definitions factsheet for further information.

## What does Environment Canterbury do with the information on the LLUR?

The LLUR is available online at <a href="www.llur.ecan.govt.nz">www.llur.ecan.govt.nz</a>. We mainly receive enquiries from potential property buyers and environmental consultants or engineers working on sites. An inquirer would typically receive a summary of any information we hold, including the category assigned to the site and a list of any investigation reports.


We may also use the information to prioritise sites for further investigation, remediation and management, to aid with planning, and to help assess resource consent applications. These are some of our other responsibilities under the RMA.

If you are conducting an environmental investigation or removing an underground storage tank at your property, you will need to comply with the rules in the Regional Plan and send us a copy of the report. This means we can keep our records accurate and up-to-date, and we can assign your property an appropriate category on the LLUR. To find out more, visit www.ecan.govt.nz/HAIL.



## **IMPORTANT!**

The LLUR is an online database which we are continually updating. A property may not currently be registered on the LLUR, but this does not necessarily mean that it hasn't had a HAIL use in the past.



Sheep dipping (ABOVE) and gas works (TOP) are among the former land uses that have been identified as potentially hazardous. (Photo above by Wheeler & Son in 1987, courtesy of Canterbury Museum.)

## My land is on the LLUR – what should I do now?

**IMPORTANT!** Just because your property has a land use that is deemed hazardous or is on the LLUR, it doesn't necessarily mean it's contaminated. The only way to know if land is contaminated is by carrying out a detailed site investigation, which involves collecting and testing soil samples.

You do not need to do anything if your land is on the LLUR and you have no plans to alter it in any way. It is important that you let a tenant or buyer know your land is on the Listed Land Use Register if you intend to rent or sell your property. If you are not sure what you need to tell the other party, you should seek legal advice.

You may choose to have your property further investigated for your own peace of mind, or because you want to do one of

the activities covered by the National **Environmental Standard for Assessing** and Managing Contaminants in Soil. Your district or city council will provide further information.

If you wish to engage a suitably qualified experienced practitioner to undertake a detailed site investigation, there are criteria for choosing a practitioner on www.ecan.govt.nz/HAIL.



## I think my site category is incorrect – how can I change it?

If you have an environmental investigation undertaken at your site, you must send us the report and we will review the LLUR category based on the information you provide. Similarly, if you have information that clearly shows your site has not been associated with HAIL activities (eg. a preliminary site investigation), or if other HAIL activities have occurred which we have not listed, we need to know about it so that our records are accurate.

If we have incorrectly identified that a HAIL activity has occurred at a site, it will be not be removed from the LLUR but categorised as Verified Non-HAIL. This helps us to ensure that the same site is not re-identified in the future.

## **Contact us**

Property owners have the right to look at all the information Environment Canterbury holds about their properties.

It is free to check the information on the LLUR, online at www.llur.ecan.govt.nz.

If you don't have access to the internet, you can enquire about a specific site by phoning us on (03) 353 9007 or toll free on 0800 EC INFO (32 4636) during business hours.

**Contact Environment Canterbury:** 

Email: ecinfo@ecan.govt.nz

Phone:

Calling from Christchurch: (03) 353 9007

Calling from any other area: 0800 EC INFO (32 4636)



Everything is connected

Promoting quality of life through balanced resource management.

## Listed Land Use Register

## Site categories and definitions

When Environment Canterbury identifies a Hazardous Activities and Industries List (HAIL) land use, we review the available information and assign the site a category on the Listed Land Use Register. The category is intended to best describe what we know about the land use.

If a site is categorised as **Unverified** it means it has been reported or identified as one that appears on the HAIL, but the land use has not been confirmed with the property owner.

If the land use has been confirmed but analytical information from the collection of samples is not available, and the presence or absence of contamination has therefore not been determined, the site is registered as:

#### Not investigated:

- A site whose past or present use has been reported and verified as one that appears on the HAIL.
- The site has not been investigated, which might typically include sampling and analysis of site soil, water and/or ambient air, and assessment of the associated analytical data.
- There is insufficient information to characterise any risks to human health or the environment from those activities undertaken on the site. Contamination may have occurred, but should not be assumed to have occurred.

If analytical information from the collection of samples is available, the site can be registered in one of six ways:

#### At or below background concentrations:

The site has been investigated or remediated. The investigation or post remediation validation results confirm there are no hazardous substances above local background concentrations other than those that occur naturally in the area. The investigation or validation sampling has been sufficiently detailed to characterise the site.

#### Below guideline values for:

The site has been investigated. Results show that there are hazardous substances present at the site but indicate that any adverse effects or risks to people and/or the environment are considered to be so low as to be acceptable. The site may have been remediated to reduce contamination to this level, and samples taken after remediation confirm this.



#### Managed for:

The site has been investigated. Results show that there are hazardous substances present at the site in concentrations that have the potential to cause adverse effects or risks to people and/or the environment. However, those risks are considered managed because:

- the nature of the use of the site prevents human and/or ecological exposure to the risks; and/or
- the land has been altered in some way and/or restrictions have been placed on the way it is used which prevent human and/or ecological exposure to the risks.

#### Partially investigated:

The site has been partially investigated. Results:

- demonstrate there are hazardous substances present at the site; however, there is insufficient information to quantify any adverse effects or risks to people or the environment; or
- do not adequately verify the presence or absence of contamination associated with all HAIL activities that are and/or have been undertaken on the site.

#### Significant adverse environmental effects:

The site has been investigated. Results show that sediment, groundwater or surface water contains hazardous substances that:

- · have significant adverse effects on the environment; or
- are reasonably likely to have significant adverse effects on the environment.

#### Contaminated:

The site has been investigated. Results show that the land has a hazardous substance in or on it that:

- has significant adverse effects on human health and/or the environment; and/or
- is reasonably likely to have significant adverse effects on human health and/or the environment.

If a site has been included incorrectly on the Listed Land Use Register as having a HAIL, it will not be removed but will be registered as:

#### Verified non-HAIL:

Information shows that this site has never been associated with any of the specific activities or industries on the HAIL.

Please contact Environment
Canterbury for further information:



PATTLE DELAMORE PARTNERS LTD

#### Resource Consents within the Site Boundary (Sourced from Ecan GIS Database in April 2023).

|    | Consent No. | Consent Type           | Consent Status        | Feature Type    | Activity Text                            | Activity Text                            | Holder Name              | From Date        | To Date          |
|----|-------------|------------------------|-----------------------|-----------------|--|--|--------------------------|------------------|------------------|
| 1  | CRC981533   | Land Use Consent (s9)  | Terminated - Expired  | Bore Gallery    | Install a Bore                           | Install a Bore                           | Mr & Mrs G F & J Collins | March 25, 1998   | March 24, 2001   |
| 2  | CRC920604   | Water Permit (s14)     | Terminated - Replaced | Water Take/Use  | Take Groundwater                         | Take Groundwater                         | Lawrence Rex Ridden      | June 5, 1992     | April 12, 2000   |
| 3  | NCY820178   | Water Permit (s14)     | Terminated - Expired  | Irrigation Area | Take Groundwater                         | Take Groundwater                         | Lawrence Rex Ridden      | August 1, 1982   | April 30, 1992   |
| 4  | CRC961426.1 | Discharge Permit (s15) | Terminated - Annulled | Human Effluent  | Discharge Contaminant into Land to Water | Discharge Contaminant into Land to Water | Mr & Mrs B V & K J Clark |                  | January 24, 2031 |
| 5  | CRC920604.1 | Water Permit (s14)     | Terminated - Expired  | Irrigation Area | Take Groundwater                         | Take Groundwater                         | John Choong Chet Law     | April 12, 2000   | April 30, 2001   |
| 6  | CRC961426   | Discharge Permit (s15) | Terminated - Lapsed   | Human Effluent  | Discharge Contaminant into Land to Water | Discharge Contaminant into Land to Water | Richard John Irvine      | January 31, 1996 | January 31, 1998 |
| 7  | CRC961246   | Discharge Permit (s15) | Terminated - Lapsed   | Human Effluent  | Discharge Contaminant into Land to Water | Discharge Contaminant into Land to Water | Richard John Irvine      | January 31, 1996 | January 31, 1998 |
| 8  | CRC961422   | Discharge Permit (s15) | Terminated - Lapsed   | Human Effluent  | Discharge Contaminant into Land to Water | Discharge Contaminant into Land to Water | Richard John Irvine      | January 31, 1996 | January 31, 1998 |
| 9  | CRC920604   | Water Permit (s14)     | Terminated - Replaced | Irrigation Area | Take Groundwater                         | Take Groundwater                         | Lawrence Rex Ridden      | June 5, 1992     | April 12, 2000   |
| 10 | NCY820178   | Water Permit (s14)     | Terminated - Expired  | Water Take/Use  | Take Groundwater                         | Take Groundwater                         | Lawrence Rex Ridden      | August 1, 1982   | April 30, 1992   |
| 11 | CRC920604.1 | Water Permit (s14)     | Terminated - Expired  | Water Take/Use  | Take Groundwater                         | Take Groundwater                         | John Choong Chet Law     | April 12, 2000   | April 30, 2001   |



CALDER STEWART DEVELOPMENT LIMITED - PRELIMINARY SITE INVESTIGATION - CORNER OF MARSHS ROAD AND MAIN SOUTH ROAD (STATE HIGHWAY 1), HORNBY, CHRISTCHURCH

## **Christchurch City Council Information**

## **Chanelle Seabrook**

From: van der Erf, Agnes <Agnes.vanderErf@ccc.govt.nz>

Sent: Thursday, 2 March 2023 1:53 pm

**To:** Chanelle Seabrook

**Subject:** RE: HSNO database information request

Attachments: TimePhoto\_20210408\_110639.jpg; TimePhoto\_20210408\_110901.jpg; TimePhoto\_


20210408\_111048.jpg; CRS91640394 - Enforcement - Completed Working File.PDF

#### Hi Chanelle

No real HSNO files for these properties and just a couple of notes about the surrounding residential properties which I have attached.

679 Main South Road - Photo of home occupation (container freight) and pit as seen in photos 693 Main South Road - Enforcement file on car storage

689 Main South Road has a small pockets of uncontrolled fill related to a swimming pool removal, in pink shown below.



Thanks Agnes

From: Chanelle Seabrook < Chanelle. Seabrook@pdp.co.nz>

Sent: Tuesday, 28 February 2023 4:43 pm

To: van der Erf, Agnes < Agnes.vander Erf@ccc.govt.nz >

Subject: HSNO database information request

Good afternoon Agnes,

I am hoping to request any HSNO info CCC has for the properties outline in the attached figure.

# Thu, Apr 08 2021, 11:10:48.8 681 Main South Road, Islington, Christchurch 8042, New Zealand





ENFORCEMENT TEAM
FILE CLOSURE FORM

ENF 3

Date:

10/07/2013

Team Leader Enforcement Team Christchurch City Council



The investigation into this matter has been completed. PRUPI: 750627

| CSR     | 91640394                                  | Date Opened | 09/07/2013 |
|---------|---|-------------|------------|
| Address | 693 Main South Road: Hornby: Christchurch | Date Closed | 10/07/2013 |

|                      | I .        |
|----------------------|------------|
| Yes                  |            |
| Vec                  | 10/07/2013 |
|                      | 10/07/2013 |
| Yes                  | 10/07/2013 |
|                      | 1 1        |
|                      | 1 1        |
|                      | 1 1        |
|                      | 1 1        |
|                      | 1 1        |
|                      | Date       |
|                      |            |
|                      |            |
|                      | 1 1        |
| en                   | 1 1        |
| - Fire Hazard Notice | 1 1        |
|                      |            |
|                      |            |
|                      |            |
|                      |            |
|                      |            |
|                      | Yes        |



ENF 2

# ENFORCEMENT TEAM INVESTIGATION ACTIVITY JOB SHEET

| Subject: 693 Main South Road: Hornby : Christchurch  |  |  |  |
|--|--|--|--|
| Receive complaint via CSR91638429 – Illegal Use of Land  |  |  |  |
| Site Visit: Establish address of 671 Main South Road is not property indicated by complainant. Check area in an attempt to locate property:  Contact complainant after some discussion establish he has provided Call centre with wrong address:  Establish address where activity is believed to be is now 693 Main South Road.                     |  |  |  |
| Check Trim and Web map: 693 Main South Road is designated Rural 2. Owners are Mark and Shelley Burrows:  |  |  |  |
| Site Visit: Speak to property owner Mark Burrows: Advises that he owns the property and is a classic vehicle enthusiast: Several vehicles which include a 1970 American muscle car and English Fords on site are collectable but are in various stages of restoration: His son is also an enthusiast and restores mid 1980 Toyota push rod vehicles: |  |  |  |
| There are four adults living in the dwelling: Each person owns a vehicle and also girl friends of his son visit the address and own their own vehicles: He was employed until recently by a scrap metal merchant and at times parked his employers truck out side the address which was carrying a load of crushed vehicles:                         |  |  |  |
| He is not a car wrecker and does not operate a business from the address: Mr Burrows is staring a new job with Jeff's Vehicle Transport next week. There is on vehicle for sale on the property which is a blue Ford falcon which he owns:  He has recently had a clean up and dumped parts used in the restorations;                                |  |  |  |
| <b>File Note</b> : In the next few weeks EQC are completing repairs at the property: A forty foot container will be placed on the driveway and also a caravan: Mr Burrows will live in the caravan for security of the property while the repairs are underway.  |  |  |  |
| Small Scale Home Based Business Investigation Check Sheet completed.   |  |  |  |
| Established not a Small Scale Home Based Business: NFA   |  |  |  |
| COMPLETED  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |



**ENF** 34

#### **ENFORCEMENT TEAM**

# **Small Scale Home Based Employment**

Investigation Check Sheet

Please note there may be different rules for the zone the property is located in e.g. Living 4A, B and C
Not all rules will apply to every business activity. This list is not exhaustive – consult a planner

| COD                               | 04040204               | <i>j</i>                 | Add                 | 200 11 :       | O di D  |
|-----------------------------------|------------------------|--------------------------|---------------------|----------------|---|
| CSR                               | 91640394               |                          | Address             |                | South Road  |
| Date of                           | 10.07.2013             |                          | Time                | 11.17am        |   |
| attendance:                       |                        |                          |                     |                |   |
| Desk top                          | City Plan Zone: R      | ural 2                   | Relevant Byla       | aws:           |   |
| enquiry                           |                        |                          |                     |                |   |
| EO in                             | Neale NR1              |                          |                     |                |   |
| attendance at                     |                        |                          |                     |                |   |
| Site                              | Eg: Brothel ,SOOB, Til | or Trailor Eabri         | cator               |                |   |
| Nature or                         | Lg. Brother,300B, Th   | er, Trailer Fabri        | Cator               |                |   |
| type of business                  | Home car enthusi       | ast                      |                     |                |   |
| activity                          |                        |                          |                     |                |   |
| Name of                           | N/A                    |                          |                     |                |   |
| business                          | IV/A                   |                          |                     |                |   |
| activity                          |                        |                          |                     |                |   |
| Business                          | Name: Mark Burre       | ows                      |                     |                |   |
| owners                            | Trainer Mark Barr      |                          |                     |                |   |
| personal                          | Address: 693 Mai       | n South Roa              | d                   |                |   |
| details                           |                        |                          |                     |                |   |
|                                   | Phone No's: 03 34      | 4 3475 Er                | nail:               |                | Business card obtained: [Yes/No]                  |
| If building                       | Operators Details:     | Workin                   | ng names of         |                | m number of employees on site at                  |
| used for                          |                        | employ                   | yees:               | any time       | e:  |
| purposes of                       |                        |                          |                     |                |   |
| prostitution:                     | N/A                    | N/A                      |                     |                | ees living on site:                               |
| brothel or                        |                        |                          |                     |                | e worker must live on site)                       |
| SOOB                              |                        |                          |                     |                | ees living off site: e worker must live off site) |
| Brothel                           | [Yes/No]               | Certificate              | Number              | (CCCB OIII     | e worker must live on site                        |
| Owners                            |                        |                          |                     |                |   |
| Certificate                       |                        |                          |                     |                |   |
| Multi Unit                        | [Yes/No]               | Brothels ar              | nd SOOB can n       | ot operate     | in a multi unit residential complex               |
| Residential                       |                        | (Letter to Ceas          | se Business Activit | y or follow up | Abatement Notice)                                 |
| Complex                           |                        |                          |                     |                |   |
| Size of Area                      | 40m2 or 30%            | Total busin              | ess activity are    | ea measure     | ment:   |
| Used for                          | gross floor area       |                          |                     |                |   |
| Business                          |                        |                          | rooms used in       |                | N/A   |
| Activity                          |                        |                          | or plan on back for |                |   |
| Business                          | Maximum of 50 ho       |                          |                     | N/A            |   |
| hours of                          | Mon/Fri 8am- 11pn      | n Sat/Sun &              | Holidays)           |                |   |
| operation                         |                        | NUA                      |                     |                |   |
| How many hou                      |                        | N/A                      |                     |                |   |
| employee work<br>Clients visiting |                        | Mumbarna                 | r day: N/A          |                |   |
| Chents visiting                   | the business           | Number per<br>Number per |                     |                |   |
| Traffic                           | A maximum of           |                          | trips per day:      | NI/A           |   |
| generation                        | 16-50 vehicle          | (a) Busines              |                     | IN/A           |   |
| generation                        | trips per day          | (b) Service              |                     |                | Para  |
|                                   | including trips        | (c) Couriers             |                     |                |   |
|                                   | by people living       | (3) 53411316             | <del>.</del>        |                | COMPLETED   |
|                                   | on site.               |                          |                     |                |   |
| Parking (on                       | Two car parks for dw   |                          |                     | Dwelling:      | 4   |
| site)                             | One visitor car park   |                          | loor area used      | Visitors:      |   |
|                                   | as part of business    |                          |                     |                |   |
|                                   | One car park for any   | worker                   | 1                   | Workers:       |   |
|                                   |                        |                          |                     |                |   |





#### Neale, Richard

From:

Mather, Graham

Sent:

Tuesday, 9 July 2013 8:55 AM

To:

Neale, Richard

Subject:

CSR91638429

<ToName: Neale, Richard>

<ToFaxnum: >

CHRISTCHURCH CITY COUNCIL REQUEST FOR SERVICE (RFS).

RFS Number

91640394

Priority

: COMPLEX

Location

: Caller knows ppty as 673 Main South Rd

: 671 MAIN SOUTH ROAD, HORNBY, CHRISTCHURCH 8004

Request Type

: ENF - Enforcement

: ILLUSE - Illegal use - land or building Request

Details

: Caller states that his neighbour's residential ppty is being used as a wrecking

There are about 30 wrecked cars in back yard, 10 in front yard and 2 trailers. Selling of parts goes on night and day. The ground is being poisoned with oil and hazardous waste. Last straw is that neighbour is now building another "illegal building on his

He said it was an add on to an add on. Please investigate. Thanks.

Customer1 Details

: MATTHEW 🤝

: CELL # GIVEN 021 251 00000

GAVE HIS ADDRESS AS 665 MAIN SOUTH RD

HORNBY

Customer Phone(s)

Ph(h)

Ph(w)

Ph(m)

: 021 251 0407

Customer2 Details

Forwarded to Forwarded by Forwarded on : Neale, Richard : Scanlan, Sara : 08/07/2013

Received on : 08/07/2013 , 10:26:00

Oppisite Islination Taveur.

Shelley - Mark Burrows =

673 6675

693 Roval 2



#### Resource Management Act 1991/Building Act 1991

Hazards or Special Site Characteristics

#### **SOCKBURN SERVICE CENTRE**

# HAZARD DATA INFORMATION SEPTIC TANKS - SOAK PITS

|        | Location Main South Road Number 689  |
|--------|--|
|        | Legal Description: Lot .44D.P. /6696 Ward:   |
|        | Recorded 8: 8: 8: Severity Accuracy Depth George Marsh Entry 3:12:99.                                  |
|        | Septic Tank - Soakpite - Swimming Pool - Well - Waterway Setback                                       |
|        | LOCATION OF INFORMATION: SOCKBURN SERVICE CENTRE /589  |
|        | File No. or Source of Information P.C.C. DRAINAGE # 603  |
|        | Further Details: Site is now/not connected to the sewage system  |
|        | System not available   |
|        | Hazards referring to septic tanks, catch pits, soak pits, soak holes, grease traps are a warning not   |
|        | to locate structures over these areas without adequate reinforcing or filling and compacting the void. |
|        | ("Catch pit" refers to a soak hole used for drainage of effluent).                                     |
| MARSHS | MAIN SOUTH ROAD  |
|        |  |
| RO     |  |
| AD     | 5-0  |
|        |  |
|        | 7 1997   |
|        |  |
|        | Scale 1-2500 - See page 3  |
|        | KEY Severity 1 Low 2 Moderate 3 Extreme 4 Unknown  |
|        | Accuracy A Confirmed B Unconfirmed C Personal Observation  |

Page 1 of 3

SCANNED: 02/03/2023 15:58:11 BATCH: 27658 DOC: CCCAYGLA Box: 115 PAPARUA COUNTY COUNCIL PROPOSED Fow House for Mr./Mrs. L. Ridden TO BE ERECTED AT 689 Main South Road. Front Elevation Floor Plan Please show site plan overleaf. **SPECIFICATIONS:** Foundation Reinforcing (required for concrete block buildings) centres centres **Purlins** Trimmer Roof Covering ... Polite Wall Covering MINIMUM DISTANCE FROM NEAREST BUILDINGS AND BOUNDARIES FOR GARAGES AND SHEDS 10 Feet from any dwelling or garage over 450 square feet (including the neighbours) and two feet from the Under 450 Square Feet side boundary. Over 450 Square Feet The same as above but with a minimum distance of five feet from the side boundary. NOTE: (a) Garages can only be erected closer to buildings or boundaries if a Fire-Proof Wall with an 18-inch parapet is erected. Such wall may be erected on boundary with the written consent of the neighbour. (b) Any two Buildings under 450 square feet must be at least four feet apart unless a fireproof wall is provided. subject to con-(c) Any building with a Fireplace is classed as being over 450 square feet (ii) Where the siting of the house makes it impossible to do otherwise NTY COUNCIL natal Coverage of outbuildings shall not exceed 600. (d) Garages can only be permitted forward of a house in the following cases:

(i) Corner sections (8 feet back from side boundary).

Out on P (e) The total Coverage of outbuildings shall not exceed 600 square feet on any section of 24 perches.

This may be increased by 10 square feet for each perch in excess of 24 to a total of 900 equare feet.

(f) Packing or Car Cases are not permitted.

The builder shall be responsible to footpath of the builder shall be responsible to footpath. (g) Spouting, Downpipes and satisfactory stormwater disposal to be provided uring construction.

Vehicle entranced.



#### CERTIFICATE OF TITLE UNDER LAND TRANSFER ACT

This Certificate dated the 12th day of June one thousand nine hundred and eighty nine under the seal of the District Land Registrar of the Land Registration District of CANTERBURY

WITNESSETH that BRIAN DESMOND WEST of Christchurch, Company Director ---

is seised of an estate in fee-simple (subject to such reservations, restrictions, encumbrances, liens, and interests as are notified by memorial underwritten or endorsed hereon) in the land heremafter described, delineated with bold black lines on the plan hereon, be the several admeasurements a little more or less, that is to say: All that parcel of land containing 8.0942

hectares or thereabouts being Lot 1 Deposited Plan 54482 ---

DISTRICT LALD REGISTRAR

CAN ERSURY N.Z.

ASSISTANT LAND REGISTRAR

Subject to:


Mortgage 809222/226 Warkie
Industries Limited produced
9.6.1989 at 11.41am and entered
19.6.1989 at 12.00 noon

Mortgage 809222/3 to Christopher James Ryder and Mico 3 Jane Abrams produced 9.6.1869 to 41am and entered 19.6.4989 to 13.00 noon

Transfer 835006/2 to Michael Ernest Murcott of Christchurch, Hydatids Officer and Joy Elizabeth Murcott his wife - 30.10.1989 at 9.32am

for A.L.R.

ZA/1329




NEW ZEALAND

Pol. Folia
Transfer No.
Reference :
Application No. IZ8IT
Order for N/O No.



egister-book, Vol 330. folio 166

CERTIFICATE OF TITLE UNDER LAND TRANSFER ACT.



330/166 amfer 160 s. a. 5 of hurlyage 12000 in further land of the little as to & 230 cm like as to & 230 cm bick to millan as to Exp. Variation of the tenge Willie freduced in By School 1924 1. 1 Application 19 800 pt 11:15: as STECHARGETTE Managhand 300060 findence Harrison F Cloudte May Colellet to their bathly Glad Lilly & Fall 30 May 1958 at 150 Michelle Baillie Reese -30007 - rampe of the interest in the strange 180004 as expensed to the standard of the standa Lawat 210Withdrawn. R. Cherry, Pople. mans fer 772482 45 J. Warre C. at Ilh strings - 5/8/1969 at 145 851240 Charge of name registered firstrictor to Industries himited 6.12 p of the Taxation of the term produced Alst Tolo 12,1971 at 12.05 p.m. ofen 228784 for Mortgage 851241 85 Yealand Inourage himited - 6.12 84 84 atarbem elden freet landerson milet in charles ge 183602 to to Bessie! 11: Care WKR. THIS REPRODUCTION ON A SERUCED SCALES, CHARLES OF OR A THUR OFF OF THE ORIGINAL REGISTER FOR THE PORTORES OF SECTION 275A LABOR THANKFER ALT 1952. ..... 1:

30/166





#### **APPLICATION FOR BUILDING CONSENT**

FORM: BA3 PROJECT NO: Z00892

#### PLEASE COMPLETE ALL SECTIONS OF THIS FORM (IF APPLICABLE TO YOUR APPLICATION)

| Has a Project Information Memorandum been issued by the Council for this project?        | Yes | DNO      |
|--|-----|----------|
| If YES, add the Project Information Memorandum number to the box above marked PROJECT NO | ,   | <i>-</i> |


| APPLICATION DETAILS  | PROJECT  |
|--|--|
| OWNER (as defined by the Building Act 1991)                          | LOCATION   |
| Name: G FOIJ COLLINS   | Street Address: 41 MARSHES ROM                               |
| Mailing Address: PO-BOX 23 C24 CHCH                                  | CHRISTCHURCH   |
| Street Address: Su Royann Dr CHCH                                    | Lot: 2 DP: 74746   |
| Phone: <u>3494 743</u> Fax: <u>3494 743</u>                          | Other:   |
| APPLICANT (Must be authorised by the owner to make this application) | DESCRIPTION OF WORK:   |
| Name:  |  |
| Company:   | Water Connection   |
| Mailing Address:   |  |
| Street Address:  | INTENDED USE:  |
| Phone: Fax:  |  |
| Estimated Value of proposed work (inclusive of GST)                  | Will the building undergo a change of use?                   |
| \$   | ☐ Yes ☐ No   |
| Building Consent to be uplifted from:                                |  |
| Service Centre   | Intended Life if less than 50 years:years                    |
| If prepaid post to Owner / Applicant (delete one)                    | Being stage of an intended stages                            |
| Water Supply   | FLOOR AREA   |
| Is a new supply required?  | Ground Floor: Existingm² Addm²                               |
| Residential / Commercial (DELETE ONE)                                | Other Floor: Existing Add m²                                 |
| If commercial, has estimate been obtained from the                   | Accessory Building Area:                                     |
| Council? Yes No  | m² Add m²  |
| Distance from LEARH boundary (looking from street)                   | Planning - Site Coverage                                     |
| metres of Row.   | Total area of all buildings over foundation at ground level. |
| Nominate street if a corner site:                                    |  |
|  | Existingm² Proposedm²  |
| Road Opening / Footpath Opening                                      | Vehicle Crossing (in connection with this Building           |
| Is an opening required?  | Consent)   |
| Type of service:   | Is a vehicle crossing required? Yes No                       |
| Sewer / Stormwater (DELETE AS NECESSARY)                             | New / Extension / Residential / Commercial                   |
|  | (DELETE AS NECESSARY)  |
| FOR COUNCIL  |  |
| Invalid Owner Recorded:  | DRAINAGE INFORMATION   |
| Date Received: 28 · 10 · 97 ·  | Not Required Block Plan Only                                 |
| Prepaid Fee: \$ <u>Z40.00</u> .                                      | Full PIM Date Requested//                                    |
| Receipt No: 229   166  |  |
| Receiving Officer's Name:  | Hazard Yes No  |
|  |  |

Date of Issue: April 1997

confunction

will

PLEASE TURN OVER WAR



# SITE PLAN P. J. GILLESPIE, J.M. TRENGROVE & G.F. & J. COLLINS

B. 2263

Annexure C

with the owners grazing bobby calves on the site. The vet clinic buildings have been used by the current owners for a study/office and storage. This application seeks to allow the dwelling to remain on the undersized site.

When considering an application for a resource consent the consent authority shall have regard to Section 104 (1) of the Resource Management Act 1991.

What are the actual and potential effects on the environment of allowing the activity?

I consider that the actual and potential effects of the proposal on the environment relate to loss of potential rural land use and rural character. These effects are discussed below.

#### Loss of potential for rural land use and rural character

The application site is 2.675ha, which falls short of the permitted standard for a dwelling of 40ha under the Transitional District Plan and 4ha under the Proposed City Plan.

As the dwelling has been located on this site since approximately 1990, and was provided for again in 1996 at the time of subdivision, it is my opinion that the only effects to consider are the loss of potential for rural land use and rural character resulting from the discontinuation of the vet clinic operation. I consider that as the dwelling and other buildings have been located on the site for over 10 years, and no new buildings are proposed in this application, there is no further loss of rural land that would potentially be used for primary production or intensive farming. I also consider that the potential for intensive farming is limited by the size of the site. The applicants state that they have grazed up to 15 bobby calves on the site which is the maximum that the site can handle in terms of grazing and feed availability.

The site has been extensively landscaped with a number of trees along the driveway and amongst the buildings. Several shelter belts also exist along the boundary of the site. The dwelling and buildings on the site are in keeping with the character of the surrounding area.

For the reasons discussed above, I consider the effects on the potential for rural land use and rural character to be insignificant. In any event, the applicant has obtained the written consent of the owners/occupiers of the properties at 27, 41 and 55 Marshs Road and two properties located on the south side of Marshs Road on the corner of Marshs Road and Meadowlands Road (located in the Selwyn District). Therefore, pursuant to section 104(3)(b) of the Act, the effects on these properties cannot be taken into account.

#### Other effects

As the proposal is a non-complying activity, the Council can give consideration to any other actual or potential effects as a result of the proposal. I do not consider there to be any other effects arising from this application.

How do any relevant objectives, policies, rules or other provisions of the Transitional or Proposed Plan relate to the proposal?

The relevant objectives and policies of the Transitional District Plan essentially seek to protect land having a high actual or potential value for the production of food, and to prevent sporadic and unnecessary urban development in rural areas while providing for rural-residential and other dwellers who seek to locate in rural areas. For the reasons discussed above, I consider that the proposal is not contrary to the relevant objectives and policies of the Transitional District Plan.

The relevant objectives and policies of the Proposed City Plan essentially seeks to maintain future potential for rural productivity and to maintain or enhance rural amenity values (Policy 13.1.6 and Objective 13.4). For the reasons discussed above, I consider that the proposal is not contrary to the relevant objectives and policies of the Proposed City Plan.

Are there any other matters which are relevant and reasonably necessary to determine the application (including Part II matters)?


NEW ZEALAND

Pol. Folia
Transfer No.
Reference :
Application No. IZ8IT
Order for N/O No.



egister-book, Vol 330. folio 166

CERTIFICATE OF TITLE UNDER LAND TRANSFER ACT.



330/166 amfer 160 5:05 of hurlyage 12000 for helptember 19 er af fell Im Almany to Jay SCH Well as to k 2200 ces bick to millan as to kypo Variation of the tenge Willie freduced in By School 1924 1. 1 Application 19 800 pt 11:15: as STECHARGETTE Managhand 300060 findence Harrison F Cloudte May Colellet to their bathly Glad Lilly & Fall 30 May 1958 at 150 Michelle Baillie Reese -30007 - rampe of the interest in the strange 180004 as expensed to the standard of the standa Lawat 210Withdrawn. R. Cherry, Pople. mans few 772482 45 J. Watter Could Illistings - 5/8/1969 at 145 851240 Charge of name registered firstrictor to Industries himited 6.12 p of the Taxation of the term produced Alst Tolo 12,1971 at 12.05 p.m. ofen 228784 for Mortgage 851241 85 Yealand Inourage himited - 6.12 84 84 atarbem elden freet landerson milet in charles ge 183602 to to Bessie! 11: Care WKR. THIS REPRODUCTION ON A SERUCED SCALES, CHARLES OF OR A THUR OFF OF THE ORIGINAL REGISTER FOR THE PORTORES OF SECTION 275A LABOR THANKFER ALT 1952. ..... 1:


30/166



Subject to:

(B)

ASSISTANT LAND REGISTRAR



LAS DETICA

SCANNED: 10/04/2013 3:49:40 p.m. BOX: 284 BATCH: 18100 DOC: CCCADRNL

APPLICATION FOR DISPENSATION

Date 27/4/81

County Engineer,
Paparua County Council,
P.O. Box 11011,
SOCKBURN.

Address of Proposed Work 57 Morsh's

Dispensation No. 3%

Road

Dear Sir,

Legal Description

I wish to apply for a dispensation from the provisions of the Paparua County - Council District Planning Scheme.

|  | s of Applica   | nt 6/0 7   | 1.7     | 1  | 4 0   | 5  |
|--|--|--|---------|--|---|--|
|  |  |  | 4) 115  | in Sout  | h Koed  | g  |
|  | one Humber   | ,  | 7 592   |  | 4.  |  |
| The Di   | spensation i   | s required for   | Future  | Proposed   | garag   | е то   |
| be.  | 31/09  | 705 MeTae  | s From  | Road B   | oundry  | er farringsman, in a to septement the state appropriate forces with the septement to the section of the septement to the section of the secti |
| tarer graenaven en etteret ett och |  | toring a realigness generalization and president specification of the specific and the spec |         |  |   |  |
|  |  | sation is nece   |         | . Why the re   | quirements of   | the District   |
| SiTies   | OF EXIS  | ting Deep well   | 12 Pump | Jast NLOW  | Energh Rec  | m To Pet So  |
|  |  | es book From   |         |  |   |  |
|  |  | se from b  |         |  | 1.50 miles  |  |
|  |  | The Sarage   |         |  |   |  |
|  |  | orning Sun   |         | -  |   |  |
|  |  | nd View.   |         |  |   |  |
|  |  | Tion which F   |         |  |   |  |
|  |  | and draineg  |         |  | C. C. fine  | 10 3 4 50 3 4 5 1  |
|  |  |  |         |  | Angles and providing the strong over \$100,000 and an account of the strong of the strong of                    | egentraginal strong gyala dig and menengan yan yan dan sem gandan semilin selektrisi ya kenjana  |
|  |  | s of adjoining   |         |  | ected Ni  |  |
| Ben  | ce hand  | on all   | Bounday | (5   |   |  |
| and the second second second second                                    | and a special to the special control of the s |  |         | The state of the s | ardý krali stra se stalego nakos med disku sudot nek disku disku disku disku se sa silede (100 mille). Na sudot | na 1910 may tanàna amin'ny amin'ny any ao amin'ny faritan'ny ao  |
|  |  |  |         |  |   |  |
|  | E CONTRACTOR CONTRACTO | The state of the s |         |  |   | A CONTRACTOR AND   |
|  | THE CHARLES SHOW I SHAW THE PROPERTY AND ADDRESS OF THE PROPERTY AND ADDRESS OF THE PARTY AND AD | Contribution (Contribution on Spring rapides algorithm of Contribution of Cont |         | THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE OW |   | A THE STREET CONTRACTOR OF THE SECOND CONTRACT |

In support of my application I submit a detailed site plan showing all buildings

on my property and a cross section of the proposed structure clearly dimensioned.

Yours faithfully,

99 Newell